



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<b>AT09-OPA1F1Z</b> <b>12361-74531</b> Toyota OPA [2000-2005] = ZCT1#, ACT1# Insulator Engine [FR]	TN-2012-August-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-OPA1E1Z</b> <b>12371-22150</b> Toyota OPA [2000-2005] = ZCT1# Insulator Engine [RE]	TN-2012-August-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-OPA1E2Z</b> <b>12371-74570</b> Toyota OPA [2000-2005] = ACT1# Insulator Engine [RE]	TN-2012-August-06 Tenacity Product, HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-OPA1L1Z</b> <b>12372-22072</b> Toyota OPA [2000-2005] = ZCT1# Insulator Engine [LH]	TN-2012-August-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-OPA1L2Z</b> <b>12306-28051</b> Toyota OPA [2000-2005] = ACT1# Insulator Engine [LH]	TN-2012-August-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-OPA1R1Z</b> <b>12362-22010</b> Toyota OPA [2000-2005] = ZCT1# Insulator Engine [RH]	Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-OPA1R2Z</b> <b>12305-28130</b> Toyota OPA [2000-2005] = ACT1# Insulator Engine [RH]	Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-J122FRZ</b> <b>12361-87403</b></p> <p>Toyota Cami / Daihatsu Terios [1997-2006] = J100, J102, J111, J122</p> <p>Insulator Engine [FR, RH] [1.3]</p> <p>TN-2012-August-06 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT09-J122FLZ</b> <b>12362-87403</b></p> <p>Toyota Cami / Daihatsu Terios [1997-2006] = J100, J102, J111, J122</p> <p>Insulator Engine [FR, LH] [1.3]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-J122FR2B</b> <b>12361-87401</b></p> <p>Toyota Cami / Daihatsu Terios [1997-2006] = J100, J102, J111, J122</p> <p>Insulator Engine [FR, RH]</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT09-J122FL2B</b> <b>12362-87401</b></p> <p>Toyota Cami / Daihatsu Terios [1997-2006] = J100, J102, J111, J122</p> <p>Insulator Engine Insulator Engine[FR, LH]</p> <p>PFT-2014-May-25 Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-J122E1Z</b> <b>12306-87402</b></p> <p>Toyota Cami / Daihatsu Terios [1997-2006] = J100, J102, J111, J122</p> <p>Insulator Engine [RE] [1.3]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	
<p><b>AT10-JZA8EZ</b> <b>12371-46090</b></p> <p>Supra [1993-1996] = JZA80</p> <p>Insulator Engine [RE, M/T]</p> <p>Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	<p><b>AT10-JZA8FZ</b> <b>12360-46070</b></p> <p>Supra [1993-1995] = JZA80</p> <p>Insulator Engine [FR, M/T, A/T]</p> <p>Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p><b>AT09-CHA86RZ</b> <b>12372-87703</b></p> <p>Daihatsu CHARADE 1.0 [1986-1994]</p> <p>Insulator Engine [RH]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	














# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-M101EZ</b> <b>12306-97210</b> Duet [1998-2004] = M100A, M101A, M110A, M111A..K3VE, EJVE   Daihatsu Storia [1998-2004] = M100S Insulator Engine [RE, A/T] [1.0, 1.3] 	<b>AT09-M100E1Z</b> <b>12306-97215</b> Daihatsu Sirion [1998-2000] = M100   Toyota Duet [1998-2000] = EJDE..M110..5F Insulator Engine [RE, 1.0] 
<b>AT09-M100R3Z</b> <b>12305-97203</b> Duet [1998-2004] = M100A, M101A, M110A, M111A..   Toyota Duet [1998-2004] = M110A.. [4WD]   Daihatsu Insulator Engine [RH, A/T] [1.0] 	<b>AT09-M100R4Z</b> <b>12305-97211</b> Daihatsu Sirion [1997-2000] = M100 Insulator Engine [RH, M/T] 
<b>AT09-M101LZ</b> <b>12373-97402</b> Duet [1998-2004] = M100A, M101A, M110A, M111A..EJVE   Daihatsu Storia [1998-2004] = M100S Insulator Engine [LH, A/T] [1.0] 	
<b>AT09-M100L1Z</b> <b>12373-97202</b> Daihatsu Sirion [1997-1998] = M100 Insulator Engine [LH, 1.0] 	<b>AT09-M100L2Z</b> <b>12373-97401</b> Daihatsu Sirion [1997-2000] = M100 Insulator Engine [LH, 1.3] 
<b>AT09-M100R1Z</b> <b>12305-97406</b> Daihatsu Sirion [1999-2000] = M100 Insulator Engine [RH, 1.0] 	<b>AT09-M100R2Z</b> <b>12305-97401</b> Daihatsu Sirion [1997-2000] = M100 Insulator Engine [RH, 1.3] 















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-SOC90FLAZ</b> <b>12307-87707</b>  Daihatsu SOCIAL 1.3 [1990-1995] Insulator Engine  <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.alafuae.com</small>	<b>AT09-SOC90FLMZ</b> <b>12307-87706</b>  Daihatsu SOCIAL 1.3 [1990-1995] Insulator Engine [FR, LH, M/T]  <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.alafuae.com</small>
<b>AT09-SOC90FR1Z</b> <b>12305-87706</b>  Daihatsu SOCIAL 1.3 [1990-1995] Insulator Engine  <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.alafuae.com</small>	<b>AT09-SOC90FR2Z</b> <b>12305-87Z01</b>  Daihatsu SOCIAL 1.3 [1990-1995] Insulator Engine  <small>HFC-2014-November-20 HFC Product www.rbi.ae</small>
<b>AT09-SOC90R1Z</b> <b>12306-87704</b>  Daihatsu SOCIAL 1.3 [1990-1995] Insulator Engine [RH]  <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.alafuae.com</small>	
<b>ADH10-M010</b> <b>12361-87206</b>  DAIHUTSU = MIRA Insulator Engine [FR, RE]  <small>RBI-OLD RBI Product shabbirh@eim.ae www.alafuae.com</small>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-KGC10LZ</b> <b>12306-B1020</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Passo [2004-2010] = KGC1#, QNC10   Daihatsu Boon [2004-2010] = M300   Daihatsu Sirion [2004-2</p> <p>Insulator Engine [LH] [1KRFE, K3VE] [1.0, 1.3]</p>	<p><b>AT09-KGC10L2Z</b> <b>12306-BZ010</b></p> <p>HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Toyota Passo [2004-2010] = KGC1#, QNC10   Daihatsu Boon [2004-2010] = M300   Daihatsu Sirion [2004-2</p> <p>Insulator Engine</p>
	<p><b>AT09-QNC10PZ</b> <b>12309-B1030</b></p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Passo [2004-2010] = KGC1#, QNC10   Daihatsu Boon [2004-2010] = M300   Daihatsu Sirion [2004-2</p> <p>Insulator Engine [Torq] [K3VE] [1.3]</p>
<p><b>AT09-QNC10R0</b> <b>12305-B1020</b></p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Passo [2004-2010] = KGC1#, QNC10   Daihatsu Boon [2004-2010] = M300   Daihatsu Sirion [2004-2</p> <p>Insulator Engine [RH] [K3VE] [1.3]</p>	
<p><b>AT09-QNC10RZ</b> <b>12305-B1020</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Passo [2004-2010] = KGC1#, QNC10   Daihatsu Boon [2004-2010] = M300   Daihatsu Sirion [2004-2</p> <p>Insulator Engine [RH] [K3VE] [1.3]</p>	<p><b>AT09-PAS04R3Z</b> <b>12305-BZ030</b></p> <p>HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Toyota Passo [2004-2010] = KGC1#, QNC10   Daihatsu Boon [2004-2010] = M300   Daihatsu Sirion [2004-2</p> <p>Insulator Engine</p>
<p><b>AT09-PAS04R4Z</b> <b>12305-BZ050</b></p> <p>HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Toyota Passo [2004-2010] = KGC1#, QNC10   Daihatsu Boon [2004-2010] = M300   Daihatsu Sirion [2004-2</p> <p>Insulator Engine</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-F60FR</b> <b>12361-BZ030</b>  <b>AVanza [2003] = F601, F602 [USA]</b>  <b>Insulator Engine [FR, RH] [1.3 = K33, K3VE]</b>	<b>AT10-F60FL</b> <b>12362-BZ020</b>  <b>AVanza [2003] = F601, F602 [USA]</b> <b>Insulator Engine [FR, LH] [1.3 = K33, K3VE]</b>
	<b>AT10-F62FL</b> <b>12362-BZ060</b>  <b>AVanza [2003] = F601, F602 [USA]</b> <b>Insulator Engine [FR, LH] [1.5 = 3SZVE]</b>
<b>AT10-F61FR</b> <b>12361-BZ040</b>  <b>AVanza [2003] = F602 [USA]</b> <b>Insulator Engine [FR, RH] [1.5 = 3SZVE]</b>	<b>AT10-F61FL</b> <b>12362-BZ010</b>  <b>AVanza [2003] = F602 [USA]</b> <b>Insulator Engine [FR, LH] [1.5 = 3SZVE]</b>
<b>AT10-F63FR</b> <b>12361-BZ070</b>  <b>AVanza [2003] = F602 [USA]</b> <b>Insulator Engine [FR, RH] [1.5 = 3SZVE]</b>	<b>AT10-F63FL</b> <b>12362-BZ070</b>  <b>AVanza [2003] = F602 [USA]</b> <b>Insulator Engine [FR, LH] [1.5 = 3SZVE]</b>
<b>AT11-F60EZ</b> <b>12371-BZ010</b>  <b>AVanza [2003] = F601 [USA]</b>  <b>Insulator Engine [RE] [1.3]</b>	<b>AT11-F62EZ</b> <b>12371-BZ050</b>  <b>AVanza [2003] = F601, F602 [USA]</b> <b>Insulator Engine [RE] [1.3, 1.5]</b>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-C01EAZ</b> <b>12371-74150</b></p> <p>Camry Vista [1986-1991] = SV2#, CV20, VZV20</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p><b>AT09-C01EMZ</b> <b>12371-64100</b></p> <p>Camry Vista [1986-1991] = SV2#, CV20, VZV20</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p><b>AT09-C01FZ</b> <b>12361-64120</b></p> <p>Camry Vista [1986-1991] = 3S..SV2#, CV20, VZV20..4FC [2.0]</p> <p>Insulator Engine [FR, A/T]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p><b>AT09-C01FAZ</b> <b>12361-62020</b></p> <p>Camry Vista [1986-1991] = 3S..SV2#, CV20, VZV20..4FC [2.0, 2.5]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2011-June-03 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p><b>AT09-C01FSZ</b> <b>12361-74100</b></p> <p>Camry Vista [1986-1991] = 4S..SV2#, ..5F [2.5]</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2011-June-03 Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p><b>AT09-C01FMZ</b> <b>12361-74020</b></p> <p>Camry Vista [1986-1991] = 4S..SV2#, ..5F [2.0]</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2011-June-03 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-C01RB</b> <b>12362-74030</b></p>  <p>Camry Vista [1986-1991] = SV2#</p> <p>Engine Bushing [RH]</p>	<p>RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-C01RS</b> <b>12362-74100</b></p>  <p>Camry Vista [1986-1991] = SV2#</p> <p>Engine Bushing [Small]</p>	<p>RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-C01L1</b> <b>12372-74170</b></p>  <p>Camry Vista [1986-1991] = SV2#</p> <p>Engine Bushing [LH, A/T]</p>	<p><b>AT09-C01LAZ</b> <b>12372-74170</b></p>  <p>Camry Vista [1986-1991] = SV2#</p> <p>Insulator Engine [LH, A/T]</p>
	<p><b>AT09-C01LMZ</b> <b>12372-74160</b></p>  <p>Camry Vista [1986-1991] = SV2#</p> <p>Insulator Engine [LH, M/T]</p>
	<p><b>AT09-C01PZ</b> <b>12363-74030</b></p>  <p>Camry Vista [1986-1991] = SV2#</p> <p>Insulator Engine [RE, Center]</p>
	<p><b>AT09-C01RH1Z</b> <b>12362-74110</b></p> <p>Camry Vista [1986-1991] = SV2#</p> <p>Insulator Engine [RH]</p>
	<p><b>AT09-C01RH2Z</b> <b>12362-62020</b></p> <p>Camry Vista [1986-1991] = VZV2#</p> <p>Insulator Engine [RH]</p>








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-SV40FMZ</b> <b>12361-74200</b></p> <p>Camry Vista [1990-1998] = 3SFE, 4SFE, 2CT, 3CT..SV3#, SV4#, CV3#, CV4#</p> <p>Insulator Engine [FR]</p> <p>ASH-2012-December-25 Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-SV40FAZ</b> <b>12361-62060</b></p> <p>Camry Vista [1990-1998] = 3SFE, 4SFE, 1VZFE, 4VZFE..SV3#, SV4#, VZV3#</p> <p>Insulator Engine [FR]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-SV40EAZ</b> <b>12371-74480</b></p> <p>Camry Vista [1990-1998] = 3SFE, 4SFE, 2CT, 3CT..SV3#, SV4#, CV3#, CV4#</p> <p>Insulator Engine [RE]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-SV40R1Z</b> <b>12362-74260</b></p> <p>Camry Vista [1990-1998] = SV3#, SV4#</p> <p>Insulator Engine [RH]</p>	<p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01

AT09-C00E  
12371-74130

Camry Vista [1988-1994] = SV25

Engine Bushing [RE]



RBI-2008-February-19  
RBI Product  
[shabbirh@eim.ae](mailto:shabbirh@eim.ae)  
[www.rbi.ae](http://www.rbi.ae)  
[www.alafuae.com](http://www.alafuae.com)







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA








Revision : 2014-November-01

<p><b>AT09-C02FMZ</b> <b>12361-74241</b></p> <p>Camry [1991-2001] = SXV1#, SXV20</p> <p>Insulator Engine [FR, M/T] [2.0, 2.2]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT09-C02EMZ</b> <b>12371-74301</b></p> <p>Camry [1991-2001] = SXV1#, SXV20</p> <p>Insulator Engine [RE, M/T] [2.0, 2.2]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT09-C02FAZ</b> <b>12361-74251</b></p> <p>Camry [1991-1996] = SXV1#</p> <p>Insulator Engine [FR, A/T] [2.0, 2.2]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT09-C02EAZ</b> <b>12371-74312</b></p> <p>Camry [1991-1996] = SXV1#</p> <p>Insulator Engine [RE, A/T] [2.0, 2.2]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT09-C03FAZ</b> <b>12361-03060</b></p> <p>Camry [1996-2001] = SXV1#, SXV2#</p> <p>Insulator Engine [FR, A/T] [2.0, 2.2]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT09-C03EAZ</b> <b>12371-74530</b></p> <p>Camry [1996-2001] = SXV1#, SXV2#</p> <p>Insulator Engine [RE, A/T] [2.0, 2.2]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



**TOYOTA**

Revision : 2014-November-01

<p><b>AT09-VCV10FAZ</b>  <b>12360-62020</b>  Camry [1991-2001] = VCV10   Lexus ES300 1992-1996] = VCV10  Insulator Engine [FR, A/T] [3.0]</p>	<p>TN-2010-December-01  Tenacity Product, HFC Product    www.rbi.ae  www.alafuae.com</p>
<p><b>AT09-MCV10FZ</b>  <b>12360-20020</b>  Camry [1991-2001] = MCV10, MCV20  Insulator Engine [FR, A/T] [3.0]</p>	<p><b>AT09-MCV10FMZ</b>  <b>12361-0A020</b>  Camry [1991-2006] = MCV10, MCV20, MCV36  Insulator Engine [FR, M/T] [3.0]</p> <p>HFC-2014-November-20  HFC Product    www.rbi.ae  www.alafuae.com</p>
<p><b>AT09-MCV10FAZ</b>  <b>12361-20040</b>  Camry [1997-2001] = MCV10  Insulator Engine [FR, A/T] [3.0]</p>	<p><b>AT09-MCV20F2Z</b>  <b>12361-20070</b>  Toyota Windom [1998-2001] = 1MZFE..MCV20    Toyota Lexus ES300 [1998-2001] = 1MZFE..MCV20   Toyota Ma  Insulator Engine [FR]</p> <p>HFC-2014-November-20  HFC Product    www.rbi.ae  www.alafuae.com</p>
<p><b>AT09-MCV36FZ</b>  <b>12361-20090</b>  Camry [2001-2006] = MCV36  Insulator Engine [FR, A/T] [3.0]</p>	<p>HFC-2014-November-20  HFC Product, Ashimori Product    www.rbi.ae  www.alafuae.com</p>
<p><b>AT09-C03E</b>  <b>12371-20030</b>  Camry [1991-2001] = MCV10, MCV20, VCV10    Camry Aus [2002-2006] = MCV36   Avalon [1996-2002] = MCX10  Engine Bushing [RE, A/T]</p>	<p>RBI-2011-September-24  RBI Product, Perfect Product    www.rbi.ae  www.alafuae.com</p>
<p><b>AT09-MCV10E</b>  <b>12371-62060</b>  Camry [1991-2001] = MCV10, MCV20, VCV10    Camry Aus [2002-2006] = MCV36   Avalon [1996-2002] = MCX10  Engine Bushing [RE, A/T]</p>	<p>PFT-2012-August-30  Perfect Product, Tenacity Product, HFC Product    www.rbi.ae  www.alafuae.com</p>
<p><b>AT09-MCV10EM</b>  <b>12371-20070</b>  Camry [1991-2001] = MCV10, MCV20, VCV10    Camry Aus [2002-2006] = MCV36  Engine Bushing [RE, M/T]</p>	<p>TN-2012-March-06  Tenacity Product    www.rbi.ae  www.alafuae.com</p>



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT11-C02M0</b> <b>12372-74370</b></p> <p>Camry [1991-2001] = SXV1#, SXV20</p> <p>Insulator Engine [LH, M/T] [2.0, 2.2]</p> <p>PFT-2014-March-25 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT11-C0200</b> <b>12372-03090</b></p> <p>Camry [1991-2001] = SXV1#, SXV20</p> <p>Insulator Engine [LH, A/T] [2.0, 2.2]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-VCV10LZ</b> <b>12372-62080</b></p> <p>Camry [1991-2001] = VCV10, MCV10, MCV20 [3000cc]   Camry Aus [2002-2006] = MCV36 [3000cc]</p> <p>Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-MCV10LMZ</b> <b>12372-62070</b></p> <p>Camry [1991-2001] = VCV10, MCV10, MCV20 [3000cc]   Camry Aus [2002-2006] = MCV36 [3000cc]</p> <p>Insulator Engine [LH, M/T]</p> <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-MCU10LZ</b> <b>12372-20030</b></p> <p>Toyota Lexus RX300 [1998-2003] = 1MZFE..MCU1#</p> <p>Insulator Engine [LH]</p> <p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	



**TOYOTA**

Revision : 2014-November-01

<b>AT09-C03B</b> <b>12363-74140</b>  Camry [1996-2001] = SXV2# Engine Bushing [Big] [2.0, 2.2]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT09-C02PZ</b> <b>12363-74140</b>  Camry [1991-2001] = SXV1#, SXV20 Insulator Engine [RH, Torq, M/T] [2.0, 2.2]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT09-C03S</b> <b>12363-74140</b>  Camry [1991-2001] = SXV1#, SXV2# Engine Bushing [Small] [2.0, 2.2]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT09-C02RB</b> <b>12363-74120</b>  Camry [1991-1996] = SXV1# Engine Bushing [Big] [2.0, 2.2]	RBI-2006-February-09 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT09-C02RBZ</b> <b>12363-74120</b>  Camry [1991-1996] = SXV1# Insulator Engine [RH, Torq, A/T] [2.0, 2.2]	RBI-2006-November-15 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT09-C03FB</b> <b>12363-74130</b>  Camry [1996-2001] = SXV2# Engine Bushing [Big] [2.0, 2.2]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT09-C03PZ</b> <b>12363-74130</b>  Camry [1996-2001] = SXV2# Insulator Engine [RH, Torq, A/T] [2.0, 2.2]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		<b>AT09-MCV10PMZ</b> <b>12363-62020</b>  Camry [1991-2006] = VCV10, MCV10, MCV20 [3000cc] Insulator Engine [RH, Torq, A/T, M/T]	TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		<b>AT09-C03Z</b> <b>12363-20020</b>  Camry [1991-2006] = MCV10, MCV20, MCV36   Camry Gracia [1996-2001] = MCV21   Avalon [1996-2000] = MC Insulator Engine [RH, Torq, A/T]	RBI-2011-February-24 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		<b>AT09-MCX20PZ</b> <b>12363-0A050</b>  AVALON = MCX20 Insulator Engine [RH, Torq]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-C04FAZ</b> <b>12361-28110</b></p> <p>Camry [2001-2006] = ACV3#   Solara [2003-2005] = ACV30</p> <p>Insulator Engine [FR, A/T] [2.0, 2.4 Petrol]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT09-MCV30FAZ</b> <b>12361-20120</b></p> <p>Camry [2001-2004] = 1MZFE..MCV30..4FC</p> <p>Insulator Engine [FR, 4 Speed, A/T] [3.0 Petrol]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT09-C04F2Z</b> <b>12361-0H060</b></p> <p>Camry [2001-2006] = ACV36</p> <p>Insulator Engine [FR, A/T] [2.0, 2.4 Petrol]</p> <p>TN-2012-March-06 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT09-MCV31FAZ</b> <b>12360-0A080</b></p> <p>Camry [2001-2006] = 1MZFE..MCV30..5FC</p> <p>Insulator Engine [FR, 5 Speed, A/T] [3.0 Petrol]</p> <p>Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT09-C05FAZ</b> <b>12361-28220</b></p> <p>Camry [2006-2010] = ACV4#</p> <p>Insulator Engine [FR, A/T] [2.0, 2.4 Petrol]</p> <p>TN-2011-August-27 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
	<p><b>AT09-ACR30FMZ</b> <b>12361-28090</b></p> <p>Previa [2000-2006] = 2AZFE, 1CDFTV..ACR30, CLR30</p> <p>Insulator Engine [FR, A/T, M/T] [2.4 Petrol] [2.0 Diesel]</p> <p>TN-2013-November-10 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p><b>AT09-ACR30FAZ</b> <b>12361-28100</b></p> <p>Toyota Alphard G, V [2002-2008] = ANH10, MNH10   Toyota Alphard G, V [2002-2008] = ANH15, MNH15.. [4</p> <p>Insulator Engine [FR]</p> <p>TN-2013-November-10 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p><b>AT09-AHR10FZ</b> <b>12361-28140</b></p> <p>Estima HYBRID [2001-2003] = 2AZFXE..AHR10,   Alphard HV [2003] = 2AZFXE..ATH10</p> <p>Insulator Engine [FR] [2.4]</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT09-C04E2Z</b> <b>12371-0H020</b></p> <p>Camry Aus [2002-2006] = ACV36</p> <p>Insulator Engine [RE, M/T, Torq]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01

<p>AT09-C06F1Z 12361-0V110 Camry [ARL] [2011] = ASV50 Insulator Engine [FR] [2.5] [2ARFE]</p>	<p>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AT09-C06F6Z 12361-36080 Camry Hybrid [ASIA] [2011] = ACV51, ASV50 Insulator Engine [FR] [2.0, 2.5] [TH] [1AZFE, 2ARFE]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-C04RAZ</b> <b>12362-28100</b></p> <p>Camry [2001-2010] = ACV3#, ACV36, ACV4#   ALPHARD [2002-2003] = ANH1#, ATH10   Estima Hybird [2001]</p> <p>Insulator Engine [RH, A/T, M/T] [2.0, 2.4 Petrol]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-C04R6Z</b> <b>12362-28020</b></p> <p>Toyota Estima T, L [1999-2006] = ACR30, MCR30   Toyota Estima T, L [1999-2006] = ACR40, MCR40.. [4WD]</p> <p>Insulator Engine [RH]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-C04R2AZ</b> <b>12362-28110</b></p> <p>Camry [ARL] [2002-2004] = 2AZFE..ACV36,   SolarA [2001-2002] = 2AZFE..ACV20</p> <p>Insulator Engine [RH] [2.4]</p> <p>TN-2013-July-16 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT09-C04R5Z</b> <b>12362-36030</b></p> <p>Toyota Camry [2009-2011] = 2ARFE..ASV40</p> <p>Insulator Engine [RH]</p> <p>HFC-2014-November-20 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT09-C04R8Z</b> <b>12362-28190</b></p> <p>Toyota Camry [2006-2009] = 2AZFE..ACV40</p> <p>Insulator Engine [RH]</p> <p>Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-C04R9Z</b> <b>12362-0H030</b></p> <p>Toyota Camry [2006-2009] = 2AZFXE..AHV40</p> <p>Insulator Engine [RH]</p> <p>Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-MCV30RAZ</b> <b>12362-20010</b></p> <p>Toyota Camry [2001-2003] = 1MZFE..MCV30</p> <p>Insulator Engine [RH, A/T, 3.0]</p> <p>TN-2014-May-05 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-MCV30R2Z</b> <b>12362-20070</b></p> <p>Toyota Camry [2004-2006] = 1MZFE..MCV30</p> <p>Insulator Engine Insulator Engine [RH, A/T, 3.0]</p> <p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-GSV40RAZ</b> <b>12362-31040</b></p> <p>Camry [2006-2010] = GSV4#, ..2GRFE [3.5]</p> <p>Insulator Engine [RH, A/T, 3.5]</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01

<p><b>AT09-C06R3Z</b> <b>12362-36050</b></p> <p>Camry Hybrid [ASIA] [2011] = ACV51, ASV50, AVV50</p> <p>Insulator Engine [RH] [2.0, 2.5] [TH] [1AZFE, 2AFRE, 2ARFXE]</p>	<p>TN-2013-November-20 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-C04LAZ</b> <b>12372-28020</b> Camry [2001-2006] = ACV3#, MCV3#, ACV36   Previa [2000-2006] = 2AZFE..ACR30..AT Insulator Engine [LH, A/T] [2.0, 2.4, 3.0 Petrol]	 TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-C05LAZ</b> <b>12372-28200</b> Toyota Camry / Aurion / Hybrid / HV [2006-2011] = ACV4# Insulator Engine [LH, A/T] [2.4 Petrol]	 TN-2010-December-01 Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-C04L2Z</b> <b>12372-0H060</b> Camry [2001-2006] = ACV3#, MCV3#, ACV36   Previa [2000-2006] = 2AZFE..ACR30..AT Insulator Engine [LH, A/T] [2.4 Petrol]	 TN-2011-August-27 Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT09-AHR10LZ</b> <b>12306-28060</b> Estima HYBRID [2001-2003] = 2AZFXE..AHR10,   Alphard HV [2003] = 2AZFXE..ATH10 Insulator Engine [LH] [2.4]	 Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-ACV40LMZ</b> <b>12372-0H100</b> Toyota Camry / Aurion / Hybrid / HV [2006-2011] = ACV4# Insulator Engine [LH, M/T] [2.4 Petrol]	 TN-2010-December-01 Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-GSV40LZ</b> <b>12372-31010</b> Toyota Camry / Aurion / Hybrid / HV [2006-2011] = GSV40 Insulator Engine [LH, A/T] [3.5 Petrol]	 TN-2010-December-01 Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-MCU30LAZ</b> <b>12372-20080</b> Toyota Lexus RX300, RX330, RX350, RX400 [2003-2009] = 1MZFE, 2GRFE, 3MZFE..MCU3#, GSU35 Insulator Engine [LH]	 TN-2010-December-01 Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>

















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-C04B</b> <b>12363-0H030</b></p> <p>Camry [2001-2006] = ACV30, ACV31, ACV3#, MCV30</p> <p>Engine Bushing [Big]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-C04S</b> <b>12363-0H030</b></p> <p>Camry [2001-2006] = ACV30, ACV31, ACV3#, MCV30</p> <p>Engine Bushing [Small]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-C04RZ</b> <b>12363-0H030</b></p> <p>Camry [2001-2006] = ACV30, ACV31   Solara [2003-2005] = ACV30</p> <p>Insulator Engine [RH, Torq] [With Out Top] [2.0, 2.4]</p>   <p>RBI-2005-January-27 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-C04RBZ</b> <b>12363-28060</b></p> <p>Camry [2001-2006] = ACV3#, ACV36</p> <p>Insulator Engine [RH, Torq] [With Top] [2.0, 2.4]</p>   <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-C04RLZ</b> <b>12364-28010</b></p> <p>Camry [2002-2010] = ACV30, ACV31, ACV3#, MCV30, ACV4#   Previa [2000-2006] = 2AZFE..ACR30..MT</p> <p>Insulator Engine [RE, M/T, Torq] [2.0, 2.4]</p>   <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-MCV30RBZ</b> <b>12363-20100</b></p> <p>Toyota Camry [2001-2006] = 1MZFE, 3MZFE..MCV30, MCV31   Toyota Windom [2001-2006] = 1MZFE..MCV30   T</p> <p>Insulator Engine [RH, Torq, 3.0]</p>   <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-C05R3B</b> <b>12309-28160B</b>  Camry [2006-2010] = ACV4#, ..1AZFE, 2AZFE [2.0, 2.4] Engine Bushing Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AT09-C05R3S</b> <b>12309-28160S</b>  Camry [2006-2010] = ACV4#, ..1AZFE, 2AZFE [2.0, 2.4] Engine Bushing PFT-2014-November-15 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-C05RZ</b> <b>12309-28160</b>  Camry [2006-2010] = ACV4#, ..1AZFE, 2AZFE [2.0, 2.4] Insulator Engine [RH, A/T, M/T, Torq] [2.0, 2.4] RBI-2012-July-14 RBI Product, Perfect Product, Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-C05RBZ</b> <b>12309-0H070</b>  Camry [2006-2010] = ACV4#, ..1AZFE, 2AZFE [2.0, 2.4] Insulator Engine [RH, A/T, M/T, Torq] [2.0, 2.4] TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-GSV4RB</b> <b>12363-31030</b>  Camry [2006-2010] = GSV4#, ..2GRFE [3.5] Engine Bushing [RH, A/T, M/T] ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-C05R2Z</b> <b>12309-0H041</b>  Camry [2006-2010] = ACV4# Insulator Engine [RH, A/T, M/T, Torq] [2.4] TN-2011-March-21 Perfect Product, Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-GSV4R2Z</b> <b>12363-31030</b>  Camry [2006-2010] = GSV4#, ..2GRFE [3.5] Insulator Engine [RH, A/T, M/T, Torq] [3.5] [With Head] TN-2011-November-14 Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-GSV4RBZ</b> <b>12363-31010</b>  Camry [2006-2010] = GSV4#, ..2GRFE [3.5] Insulator Engine [RH, A/T, M/T, Torq] [3.5] [Without Head] TN-2011-November-14 Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-GSX3RBZ</b> <b>12363-0P020</b>  Toyota Avalon [2005-2007] = 2GRFE..GSX30 Insulator Engine [RH, A/T, M/T, Torq] [3.5] [Short Body] TN-2011-November-14 Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-GSU30RBZ</b> <b>12363-31020</b>  Harrier [2006] = GSU3#   Lexus RX 300, 330, 350 [2006-] = GSU3#, GSU35 Insulator Engine [RH, A/T, Torq] [3.5] TN-2013-November-20 Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-GSU40RBZ</b> <b>12363-31040</b>  Highlander [2007] = GSU4# Insulator Engine [RH, A/T, Torq] [3.5] TN-2013-November-20 Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-GSX3PAZ</b> <b>12309-0P010</b>  Toyota Avalon [2007] = 2GRFE..GSX30  Insulator Engine [RH, A/T, M/T, Torq] [3.5] [Short Body]	 <small>TN-2011-November-14 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-C05P3Z</b> <b>12363-0V030</b>  Toyota Camry / Aurion / Hybrid / HV [2009-2010] = 2ARFE..ASV40  Insulator Engine [TORQ] [2.5] [2ARFE]	 <small>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-C06P1Z</b> <b>12309-0V090</b>  Toyota Camry [ARL] [2011] = ASV50  Insulator Engine [TORQ] [2.5] [2ARFE]	 <small>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
		<b>AT09-C06P5Z</b> <b>12363-0V140</b>  Toyota Camry Hybrid [ASIA] [2011] = ASV50  Insulator Engine [TORQ] [2.5] [2ARFE]	 <small>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-C06P3Z</b> <b>12309-0P032</b>  Camry [ARL] [2011] = GSV50  Insulator Engine [RH, A/T, M/T, Torq] [3.5] [With Head] [2GRFE]	 <small>TN-2011-November-14 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-C06P7Z</b> <b>12363-0V070</b>  Toyota Camry / Aurion / Hybrid / HV [2011] = 2ARFE..ASV50  Insulator Engine [TORQ] [2.5] [2ARFE]	 <small>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-C06P8Z</b> <b>12363-36040</b>  Toyota Camry / Aurion / Hybrid / HV [2011] = 2ARFE..ASV50  Insulator Engine [TORQ] [2.5] [2ARFE]	 <small>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-ACR30RBZ</b> <b>12363-28010</b>  Previa [2000-2006] = 2AZFE..ACR30  Insulator Engine [RH, A/T, Torq]	<b>AT09-AHR10PZ</b> <b>12363-28080</b>  Estima HYBRID [2001-2003] = 2AZFXE..AHR10  Insulator Engine [RH, TORQ] [2.4 Petrol]
<b>AT09-MCR30PZ</b> <b>12363-20060</b>  Estima [1999] = MCR30  Insulator Engine [RH, TORQ] [3.0] [1MZFE]	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-ACU10FZ</b> 12361-28120</p> <p>Harrier [1997-2003] = 2AZFE..ACU1#</p> <p>Insulator Engine [FR] [2.4 Petrol]</p> <p style="text-align: right;">Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-MCU10FZ</b> 12361-20060</p> <p>Harrier [1997-2003] = 1MZFE..MCU1#</p> <p>Insulator Engine [FR] [3.0 Petrol]</p> <p style="text-align: center;">HFC-2014-November-20 HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT09-MCU10EZ</b> 12371-20050</p> <p>Harrier [1997-2003] = 1MZFE..MCU10</p> <p>Insulator Engine [RE] [3.0 Petrol]</p> <p style="text-align: center;">Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-MCU15EZ</b> 12371-20060</p> <p>Harrier [1997-2003] = 1MZFE..MCU15</p> <p>Insulator Engine [RE] [3.0 Petrol]</p> <p style="text-align: right;">HFC-2014-November-20 HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p><b>AT09-ACU10LZ</b> 12372-28060</p> <p>Harrier [1997-2003] = 2AZFE..ACU10</p> <p>Insulator Engine [LH] [2.4 Petrol]</p> <p style="text-align: center;">Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT09-ACU10RHZ</b> 12362-28040</p> <p>Toyota Harrier [1997-2003] = 2AZFE..ACU1#</p> <p>Insulator Engine [RH]</p> <p style="text-align: center;">TN-2013-July-16 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<b>AT09-ACU20P1Z</b> <b>12363-28050</b> Highlander [2000-2003] = 2AZFE..ACU20 Insulator Engine [RH, TORQ]	TN-2012-March-06 Tenacity Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-ACU20P2Z</b> <b>12363-28120</b> Highlander [2003-2006] = 2AZFE..ACU20 Insulator Engine [RH, TORQ]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-ACU25P1Z</b> <b>12363-28020</b> Highlander [2000-2003] = 2AZFE..ACU25 Insulator Engine [RH, TORQ]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-ACU25P2Z</b> <b>12363-28130</b> Highlander [2003-2006] = 2AZFE..ACU25 Insulator Engine [RH, TORQ]	TN-2013-April-05 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-MCU20P1Z</b> <b>12363-20080</b> Highlander [2000-2003] = 1MZFE..MCU20 Insulator Engine [RH, TORQ]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-MCU25P1Z</b> <b>12363-20090</b> Highlander [2000-2003] = 1MZFE..MCU25 Insulator Engine [RH, TORQ]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-MCU30PZ</b> <b>12363-20111</b> Highlander [2003-2006] = 3MZFE..MCU2#   Lexus RX330, RX350 [2003-2006] = 3MZFE..MC3#   Harrier [2003] Insulator Engine [RH, TORQ] [3.0 Petrol]	TN-2012-March-06 Tenacity Product, HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-SXU10RZ</b> <b>12363-74160</b></p> <p>Harrier [1997-2003] = 5SFE..SXU1#</p> <p>Insulator Engine [RH, TORQ] [2.2 Petrol]</p> <p>TN-2013-April-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-ACU10RZ</b> <b>12363-28030</b></p> <p>Harrier [1997-2003] = 2AZFE..ACU10</p> <p>Insulator Engine [RH, TORQ] [2.4 Petrol]</p> <p>TN-2012-March-06 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-ACU15RZ</b> <b>12363-28040</b></p> <p>Harrier [1997-2003] = 2AZFE..ACU15</p> <p>Insulator Engine [RH, TORQ] [2.4 Petrol]</p> <p>TN-2012-March-06 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-MCU10PZ</b> <b>12363-20040</b></p> <p>Harrier [1997-2003] = 1MZFE..MCU1#</p> <p>Insulator Engine [RH, TORQ] [3.0 Petrol]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-ACU30RBZ</b> <b>12363-28140</b></p> <p>Harrier [2005] = ACU30</p> <p>Insulator Engine [RH, A/T, Torq] [2.4]</p> <p>TN-2013-April-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-ACU35RBZ</b> <b>12363-28150</b></p> <p>Harrier [2005] = ACU35</p> <p>Insulator Engine [RH, A/T, Torq] [2.4]</p> <p>TN-2013-April-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-MHU20PZ</b> <b>12363-20130</b></p> <p>Harrier / KLUGER [2005] = MHU2#, MHU28   Lexus RX400H [2005] = MHU3#, MHU38</p> <p>Insulator Engine [RH, TORQ] [3.3] [3MZFE]</p> <p>TN-2013-April-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-T11FR</b> <b>12361-76042</b></p> <p>PERFECT RUBBER PARTS</p> <p>Previa [1990-1996] = 2TZFE..TCR1#, TCR2#</p> <p>Insulator Engine [FR, RH] [2.4 Petrol]</p> <p>PFT-2014-January-14 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT10-T11FL</b> <b>12362-76012</b></p> <p>PERFECT RUBBER PARTS</p> <p>Previa [1990-1996] = 2TZFE..TCR1#, TCR2#</p> <p>Insulator Engine [FR, LH] [2.4 Petrol]</p> <p>PFT-2014-January-14 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT10-T12FR</b> <b>12361-76043</b></p> <p>PERFECT RUBBER PARTS</p> <p>Previa [1996-1999] = 2TZFE..TCR1#, TCR2#</p> <p>Insulator Engine [FR, RH] [2.4 Petrol]</p> <p>PFT-2014-January-14 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT10-T12FL</b> <b>12362-76013</b></p> <p>PERFECT RUBBER PARTS</p> <p>Previa [1996-1999] = 2TZFE..TCR1#, TCR2#</p> <p>Insulator Engine [FR, LH] [2.4 Petrol]</p> <p>PFT-2014-January-14 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT10-T11E3</b> <b>12371-76040</b></p> <p>PERFECT RUBBER PARTS</p> <p>Previa [1990-1999] = 2TZFE..TCR1#, TCR2#</p> <p>Insulator Engine [RE, LH, RH] [2.4 Petrol]</p> <p>Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT10-T11E4</b> <b>12371-64230</b></p> <p>PERFECT RUBBER PARTS</p> <p>Lucida, Estima, Emina, Previa [1990-1999] = CXR10, CXR20, TCR10, TCR20</p> <p>Insulator Engine [RE, LH, RH] [2.4 Petrol]</p> <p>Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT10-T11ER</b> <b>12371-76040</b></p> <p>PERFECT RUBBER PARTS</p> <p>Previa [1990-1999] = 2TZFE..TCR1#, TCR2#</p> <p>Insulator Engine [Bracket only] [RE, RH] [2.4 Petrol]</p> <p>PFT-2012-November-07 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT10-T11EL</b> <b>12372-76011</b></p> <p>PERFECT RUBBER PARTS</p> <p>Previa [1990-1999] = 2TZFE..TCR1#, TCR2#</p> <p>Insulator Engine [Bracket only] [RE, LH] [2.4 Petrol]</p> <p>Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT10-T11E0</b> <b>12380-76011</b></p> <p>PERFECT RUBBER PARTS</p> <p>Estima Previa [1994-1997] = 2TZFE.. TCR10, TCR20</p> <p>Engine Bushing [RE]</p> <p>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-07E</b> <b>12371-63030</b>  <b>ST150</b>  <b>Engine Bushing [RE, M/T]</b>	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-07EZ</b> <b>12371-63030</b>  <b>ST150</b>  <b>Insulator Engine [RE, M/T]</b>	RBI-2009-July-27 RBI Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-25E</b> <b>12371-11080</b>  <b>AE80</b>  <b>Engine Bushing [RE]</b>	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT09-ST165E</b> <b>12371-74060</b>  <b>ST165</b> <b>Engine Bushing [RE]</b>	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-ST165EZ</b> <b>12371-74060</b>  <b>ST165</b> <b>Insulator Engine [RE, A/T, M/T]</b>	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-ST184EZ</b> <b>12371-74200</b>  <b>ST184</b> <b>Insulator Engine [RE]</b>	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT10-ST162</b> <b>12361-63071</b>  <b>ST162, ST150</b> <b>Insulator Engine [A/T]</b>	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AT10-070</b> <b>12371-63071</b> <b>Corona &amp; Carina 2 [1983-1987] = ST150   Camry [1982-1986] = SV1#</b> <b>Insulator Engine [FR, RE, A/T]</b>	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT11-25E</b> <b>12371-15121</b>  <b>AE80</b>  <b>Insulator Engine [RE]</b>	RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-07F</b> <b>12361-74010</b></p> <p><b>ST150</b></p> <p>Engine Bushing [FR, M/T]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-07FZ</b> <b>12361-74150</b></p> <p><b>ST150</b></p> <p>Insulator Engine [FR, M/T]</p>   <p>RBI-2009-October-19 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-07FMZ</b> <b>12361-63030</b></p> <p>Corona &amp; Carina 2 [1983-1987] = ST150   Camry [1982-1986] = SV1#</p> <p>Insulator Engine [FR]</p>  <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-25F</b> <b>12361-11020</b></p> <p><b>AE80</b></p> <p>Engine Bushing [FR]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-25FZ</b> <b>12361-11020</b></p> <p><b>EE80</b></p> <p>Insulator Engine [FR, M/T]</p>   <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-25FAZ</b> <b>12361-15090</b></p> <p>AE80, EE80, AT151, AT160</p> <p>Insulator Engine [FR, A/T]</p>   <p>TN-2011-October-12 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-25FCZ</b> <b>12361-64100</b></p> <p>Corolla [1983-1988] = 1CL..CE80   Corona &amp; Carina 2 [1983-1987] = 2CL..CT150</p> <p>Insulator Engine [FR]</p>  <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-25F3Z</b> <b>12361-15140</b></p> <p>AE80, EE80, AT151, AT160</p> <p>Insulator Engine [FR]</p>   <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-07L</b> <b>12372-63011</b>  <b>ST150</b>  <b>Engine Bushing [LH]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-07LZ</b> <b>12372-63011</b>  <b>ST150</b>  <b>Insulator Engine [LH]</b>	  <small>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-25L</b> <b>12372-15051</b>  <b>AE80</b>  <b>Engine Bushing [LH]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-25LAZ</b> <b>12372-15051</b>  <b>AE80, AT151, AT160</b>  <b>Insulator Engine [LH]</b>	  <small>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-25LMZ</b> <b>12372-15061</b> <b>AE80, AT151, AT160   Celica [1985-1989] = AT160  </b> <b>Corolla [1983-1988] = AE8#   Corona &amp; Carina 2 [19</b>  <b>Insulator Engine [LH]</b>	  <small>PFT-2012-December-31 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-07R</b> <b>12362-63031</b>  <b>ST150</b>  <b>Engine Bushing [RH]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-07RZ</b> <b>12362-63031</b>  <b>ST150</b>  <b>Insulator Engine [RH]</b>	  <small>RBI-2008-September-02 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-25R</b> <b>12362-11010</b>  <b>Corolla [1984-1988] = EE80, AE80</b>  <b>Engine Bushing [RH]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-25RZ</b> <b>12362-11010</b>  <b>Corolla [1984-1988] = EE80, AE80</b>  <b>Insulator Engine [RH]</b>	  <small>ARD-2014-January-01 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-25RAZ</b> <b>12362-15030</b> <b>Celica [1987-1989] = AT160   Corolla [1983-1988] =</b> <b>AE8#   Corona &amp; Carina 2 [1983-1987] = AT151</b>  <b>Insulator Engine [RH]</b>	  <small>ARD-2014-January-01 Perfect Product, ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-08E</b> <b>12371-15170</b></p>  <p>Corona &amp; Carina [1987-1992] = AT17#, ST17#</p> <p>Engine Bushing [RE, A/T, M/T]</p>	<p><b>AT09-08EAZ</b> <b>12371-15220</b></p>  <p>Corona &amp; Carina [1987-1992] = AT17#</p> <p>Insulator Engine [RE, A/T]</p>
	<p><b>AT09-08EMZ</b> <b>12371-15170</b></p>  <p>Corona &amp; Carina [1987-1992] = AT17#</p> <p>Insulator Engine [RE, M/T] [1.6]</p>
	<p><b>AT09-09EAZ</b> <b>12371-74260</b></p>  <p>ST171</p> <p>Insulator Engine [RE, A/T]</p>
	<p><b>AT09-09EMZ</b> <b>12371-74250</b></p>  <p>ST171</p> <p>Insulator Engine [RE, M/T]</p>
	<p><b>AT09-ST180EMZ</b> <b>12371-16180</b></p>  <p>Toyota Celica [1989-1993] = 4AFE...AT180, ST180, ST185</p> <p>Insulator Engine [RE]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-08FAZ</b> <b>12361-16160</b></p> <p>Corona &amp; Carina [1987-1992] = AT17#</p> <p>Insulator Engine [FR, A/T] [1.5, 1.6, Petrol]</p> <p>TENACITY</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-08FMZ</b> <b>12361-15150</b></p> <p>Corona &amp; Carina [1987-1992] = AT17#</p> <p>Insulator Engine [FR, M/T] [1.5, 1.6, Petrol]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-09F</b> <b>12361-64120</b></p> <p>Corona &amp; Carina [1987-1992] = ST17#   Camry = SV30</p> <p>Engine Bushing [FR, A/T] [1.8, 2.0, Petrol]</p> <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT09-09FAZ</b> <b>12361-74080</b></p> <p>Corona &amp; Carina [1987-1992] = ST17#</p> <p>Insulator Engine [FR, A/T] [1.8, 2.0, Petrol]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-09FM</b> <b>12361-74100</b></p> <p>Corona &amp; Carina [1987-1992] = ST17#</p> <p>Engine Bushing [FR, M/T] [1.8, 2.0, Petrol]</p> <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT09-09FMZ</b> <b>12361-74070</b></p> <p>Corona &amp; Carina [1987-1992] = ST17#</p> <p>Insulator Engine [FR, M/T] [1.8, 2.0, Petrol]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-08L</b> <b>12372-16100</b></p>  <p>Corona &amp; Carina [1987-1992] = AT17#</p> <p>Engine Bushing [LH]</p>	<p>RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-09L</b> <b>12372-74120</b></p>  <p>ST171</p> <p>Engine Bushing [LH] [2.0]</p>	<p><b>AT09-09LAZ</b> <b>12372-74130</b></p>  <p>ST171</p> <p>Insulator Engine [LH, A/T] [2.0]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-09LZ</b> <b>12372-74120</b></p>  <p>ST171</p> <p>Insulator Engine [LH, M/T] [2.0]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-09R</b> <b>12362-74080</b></p>  <p>ST171</p> <p>Engine Bushing [RH] [2.0]</p>	<p><b>AT09-09RZ</b> <b>12362-74080</b></p>  <p>Toyota Carina 2 &amp; Corona [1987-1992] = ST171</p> <p>Insulator Engine [RH, A/T, M/T] [2.0]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-09R2Z</b> <b>12362-64080</b></p> <p>Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Caldina, Corona [1987-1992] = CT17#</p> <p>Insulator Engine [RH]</p>
	<p><b>AT11-090</b> <b>12363-74060</b></p>  <p>ST171</p> <p>Insulator Engine [RE]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-10E</b> <b>12371-16270</b>  Corona / Carina [1992-1998] = AT19#, ST19#, ST21#, ST22#  Engine Bushing [RE, A/T, M/T] [1.6]	 RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-10AEMZ</b> <b>12371-16270</b>  Corona / Carina [1992-1998] = AT190  Insulator Engine [RE, M/T] [1.6]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-11EA</b> <b>12371-74330</b>  Corona / Carina [1992-1998] = AT19#, ST19#, ST21#, ST22#  Engine Bushing [RE, A/T]	 RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-10SEMZ</b> <b>12371-74320</b>  Corona / Carina [1992-1998] = ST191  Insulator Engine [RE, M/T] [2.0]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-11SEMZ</b> <b>12371-74510</b>  Corona / Carina [1992-1998] = ST191, ST210, ST220  Insulator Engine [RE, M/T] [UK] [2.0]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-10AEAZ</b> <b>12371-16290</b>  Corona / Carina [1992-1998] = AT190  Insulator Engine [RE, A/T] [1.6]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-10SEAZ</b> <b>12371-74330</b>  Corona / Carina [1992-1998] = ST191  Insulator Engine [RE, A/T] [2.0]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-11SEAZ</b> <b>12371-74500</b>  Corona / Carina [1992-1998] = ST191, ST210, ST220  Insulator Engine [RE, A/T] [UK] [2.0]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-12SEAZ</b> <b>12371-16350</b>  Corona / Carina [1992-1998] = ST191, ST210, ST220  Insulator Engine [RE, A/T] [JP] [1.8]	 TN-2010-December-26 Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-10F2Z</b> <b>12361-16221</b></p> <p>Corona / Carina [1992-1998] = AT190</p> <p>Insulator Engine [FR, A/T] [1.6]</p> <p>TENACITY</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT09-10F</b> <b>12361-16210</b></p> <p>AT190</p> <p>Engine Bushing [FR, M/T]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT09-10FZ</b> <b>12361-16210</b></p> <p>Corona / Carina [1992-1998] = AT190</p> <p>Insulator Engine [FR, M/T] [1.6]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT09-10FA</b> <b>12361-74300</b></p> <p>ST190, ST191</p> <p>Engine Bushing [FR, A/T]</p> <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT09-10FAZ</b> <b>12361-74300</b></p> <p>Corona / Carina [1992-1998] = ST191</p> <p>Insulator Engine [FR, A/T] [2.0]</p> <p>RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p><b>AT09-10FMZ</b> <b>12361-74260</b></p> <p>Corona / Carina [1992-1998] = ST191</p> <p>Insulator Engine [FR, M/T] [2.0]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-11FA</b> <b>12361-16290</b>  <b>ST191 Exsior</b>  <b>Engine Bushing [FR, A/T]</b>	<b>AT09-11FAZ</b> <b>12361-16290</b>  <b>ST191 Exsior</b>  <b>Insulator Engine [FR, A/T] [1.6]</b>
<b>AT09-11FM</b> <b>12361-16280</b>  <b>ST191 Exsior</b>  <b>Engine Bushing [FR, M/T ID=10.40]</b>	<b>AT09-11FMZ</b> <b>12361-16280</b>  <b>ST191 Exsior</b>  <b>Insulator Engine [FR, M/T]</b>
<b>AT09-11FM12</b> <b>12361-16285</b>  <b>ST191 Exsior</b>  <b>Engine Bushing [FR, M/T, ID=12.40]</b>	
	<b>AT09-11F2Z</b> <b>12361-74460</b>  <b>ST191 Exsior</b>  <b>Insulator Engine [FR, A/T] [2.0]</b>
<b>AT09-12FM</b> <b>12361-16310</b>  <b>AT191 Exsior</b>  <b>Engine Bushing [FR, M/T] [1.6]</b>	<b>AT09-12FMZ</b> <b>12361-16310</b>  <b>AT191 Exsior</b>  <b>Insulator Engine [FR, M/T] [1.6]</b>
	<b>AT09-12FAZ</b> <b>12361-16300</b>  <b>AT191 Exsior</b>  <b>Insulator Engine [FR, A/T] [1.6]</b>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-10LMZ</b> <b>12372-16270</b></p>  <p>Corona / Carina [1992-1998] = AT190</p> <p>Insulator Engine [LH, M/T] [1.6]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-10LAZ</b> <b>12372-15190</b></p>  <p>Corona / Carina [1993-1998] = AT190</p> <p>Insulator Engine [LH, A/T] [1.6]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-10LM</b> <b>12372-74351</b></p>  <p>ST191</p> <p>Engine Bushing [LH]</p> <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-11LMZ</b> <b>12372-74351</b></p>  <p>Corona / Carina [1992-1998] = ST191</p> <p>Insulator Engine [LH, M/T] [2.0]</p> <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-11LAZ</b> <b>12372-74390</b></p>  <p>Corona / Carina [1992-1998] = ST191</p> <p>Insulator Engine [LH, A/T] [2.0]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT09-11L</b> <b>12372-16351</b></p>  <p>AE111, AE112   ST191 Exsior   Toyota Rav4 [1994-2000] = SXA1#</p> <p>Engine Bushing [LH, A/T, M/T]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-11LZ</b> <b>12372-16351</b></p>  <p>ST191 Exsior</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>RBI-2006-November-15 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-10R</b> <b>12362-16190</b></p> <p>AT190 [1.6], AT190 Exsior</p> <p>Engine Bushing [RH] [1.6]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-10RZ</b> <b>12305-16120</b></p> <p>Corona / Carina [1992-1998] = AT190</p> <p>Insulator Engine [RH] [1.6]</p>  <p>RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-10R2Z</b> <b>12362-64190</b></p> <p>Corona [1992-1996] = CT190..2C</p> <p>Insulator Engine [RH]</p> <p>Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>
	<p><b>AT09-10SRZ</b> <b>12305-74191</b></p> <p>Carina E [1996-1997] = ST191   Corona [1996-2003] = ST191, ST210, ST220   Caldina [1996-2002] = ST19</p> <p>Insulator Engine [RH, A/T, M/T]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-11RZ</b> <b>12362-74280</b></p> <p>Carina E / Corona / Caldina [1992-1994] = ST190, ST191</p> <p>Insulator Engine [RH, A/T, M/T] [2.0]</p>  <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-12RZ</b> <b>12362-74380</b></p> <p>Carina E / Corona / Caldina [1994-1998] = ST190, ST191</p> <p>Insulator Engine [RH, A/T, M/T] [2.0]</p>  <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-SXM10RZ</b> <b>12362-74480</b></p> <p>Picnic [1999-2001] = SXM10</p> <p>Insulator Engine [RH]</p>  <p>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-TE94E</b>  <b>12371-74420</b></p> <p>Celica = ST204</p> <p>Engine Bushing [RE]</p>   <p>RBI-OLD RBI Product, Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT09-TE94EZ</b>  <b>12371-74420</b></p> <p>Celica = ST204</p> <p>Insulator Engine [RE]</p>   <p>RBI-OLD RBI Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-CT21E1Z</b>  <b>12371-74350</b></p> <p>Caldina [1992-2002] = CT196, ET196, CT197    Caldina [1992-2002] = CT198, CT199, ST198..  [4WD]   Cald</p> <p>Insulator Engine [RE, A/T] [2.2 Diesel] [2.0 Petrol]</p>  <p>HFC-2014-November-20 HFC Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-TE94L</b> <b>12372-74450</b></p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Celica = ST204</p> <p>Engine Bushing [LH]</p>	<p><b>AT09-TE94LZ</b> <b>12372-74451</b></p>  <p>RBI-2005-January-27 RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Celica [1993-1999] = 3SFE, 5SFE..ST204..MTM</p> <p>Insulator Engine [LH, M/T]</p>
<p><b>AT09-TE94LA</b> <b>12372-74510</b></p>  <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Celica [1993-1999] = 3SFE, 5SFE..ST204..ATM</p> <p>Engine Bushing [LH, A/T]</p>	<p><b>AT09-TE94LAZ</b> <b>12372-74510</b></p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Celica [1993-1999] = 3SFE, 5SFE..ST204..ATM</p> <p>Insulator Engine [LH, A/T]</p>
	<p><b>AT09-CT21LMZ</b> <b>12372-64260</b></p> <p>Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Carina FF / Corona / Avensis [1996-2000] = CT210, CT211, CT215, CT220..2CT#, 3CTE   Caldina [1996-19]</p> <p>Insulator Engine [LH, M/T] [2.2 Diesel]</p>
	<p><b>AT09-ST215L2Z</b> <b>12372-74630</b></p>  <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Caldina [1997] = ST215..3SG#</p> <p>Insulator Engine [LH]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p>AT09-TE94ARZ 12362-74430</p> <p>Celica / Carina ED / Corona EXIV / Curren [1993-1998] = ST20#</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<b>AT09-AZT22FZ</b> <b>12361-0B011</b>  Avensis / Corona [1997-2003] = AT22#, AT220, AZT220, CDT220, CT220, ST220, ZZT22#  Insulator Engine [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
	<b>AT09-AZT22FAZ</b> <b>12361-02100</b>  Avensis / Corona [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT  Insulator Engine [FR, A/T]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
	<b>AT09-AZT22FMZ</b> <b>12361-02090</b>  Avensis / Corona [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT  Insulator Engine [FR, M/T]	ARP Product www.rbi.ae
	<b>AT09-SXM10FMZ</b> <b>12361-74500</b>  Toyota Picnic [1996-2001] = 3SFE..SXM10  Insulator Engine [FR, M/T]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-AZT22LZ</b> 12372-02140</p> <p>ARP Product</p> <p>Avensis / Corona [1997-2003] = AT22#, AT220, AZT220, CDT220, CT220, ST220, ZZT22#</p> <p>Insulator Engine [LH]</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p>
	<p><b>AT09-AZT22RZ</b> 12305-16160</p> <p>ARP Product</p> <p>Avensis / Corona [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Caldina [1992-1997] = A</p> <p>Insulator Engine [RH]</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p>
	<p><b>AT09-ACN10RZ</b> 12362-28080</p> <p>ARP Product</p> <p>Nadia [1998-2003] = ACN10, SXN10...1AZFSE</p> <p>Insulator Engine [RH][HYDRO]</p> <p><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-ZZT23RZZ</b> 12305-22290</p> <p>Ashimori Product</p> <p>Celica [1999-2003] = 1ZZFE..ZZT230..4FC</p> <p>Insulator Engine [RH, A/T]</p> <p><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT09-W110R4Z</b> 12362-28090</p> <p>TN-2010-December-01 Tenacity Product</p> <p>Toyota Ipsum [2001-2009] = ACM21   Toyota Ipsum [2001-2009] = ACM26.. [4WD]   Toyota Noah, Voxy [200</p> <p>Insulator Engine [RH]</p> <p><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>


















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-27E</b> <b>12371-15200</b> <b>AE92</b>  <b>Engine Bushing [RE, M/T]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-27EMZ</b> <b>12371-15200</b> <b>AE92</b>  <b>Insulator Engine [RE, M/T]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-27EA</b> <b>12371-64141</b> <b>AE92</b>  <b>Engine Bushing [RE, A/T]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-27EAZ</b> <b>12371-64141</b> <b>AE92</b>  <b>Insulator Engine [RE, A/T]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-27EZ</b> <b>12371-15230</b> <b>EE90, AE92</b>  <b>Insulator Engine [RE, M/T]</b>	<b>TN-2010-December-26</b> Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-28EAZ</b> <b>12371-64120</b> <b>EE90, AE92</b>  <b>Insulator Engine [RE, A/T]</b>	<b>PFT-2013-April-30</b> Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-28F</b> <b>12371-64120</b> <b>EE90</b>  <b>Engine Bushing [FR, RE]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-28EZ</b> <b>12371-11210</b> <b>EE90</b>  <b>Insulator Engine [RE, M/T]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product, Tenacity Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT11-270</b> <b>12363-15020</b> <b>AE92 [16V]</b>  <b>Insulator Engine [RE]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT11-280</b> <b>12363-11010</b> <b>EE90 12V</b>  <b>Insulator Engine [RE]</b>	<b>RBI-OLD</b> RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT09-08F 12361-16040</p>  <p>Corona &amp; Carina [1987-1992] = AT17#</p> <p>Engine Bushing [FR]</p>	<p>AT09-27FAZ 12361-16090</p>  <p>AE92</p> <p>Insulator Engine [FR, A/T]</p>
<p>AT09-27FMZ 12361-16040</p>  <p>EE90, AE92</p> <p>Insulator Engine [FR, M/T]</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-27R</b> <b>12362-15160</b>  Corolla / Sprinter [1987-1992] = AE92  Engine Bushing [RH]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-27RZ</b> <b>12362-15160</b>  Corolla / Sprinter [1987-1992] = AE92  Insulator Engine [RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-28R</b> <b>12362-15130</b>  Corolla / Sprinter [1987-1992] = EE90  Engine Bushing [RH]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-271RZ</b> <b>12362-15130</b>  Corolla / Sprinter [1987-1992] = AE92  Insulator Engine [RH]	PFT-2013-April-30 Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-30L</b> <b>12362-15120</b>  Corolla / Sprinter [1987-1997] = AE92, AE101, EE100   AT190, AT171  Engine Bushing [LH, RH]	RBI-OLD RBI Product, Perfect Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-272RZ</b> <b>12362-15120</b>  Corolla / Sprinter [1987-1992] = AE92  Insulator Engine [RH]	Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> 
		<b>AT09-28RZ</b> <b>12362-11070</b>  Corolla / Sprinter [1987-1992] = EE90, AE92  Insulator Engine [RH]	RBI-2007-October-22 RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-281R</b> <b>12362-11100</b>  Corolla / Sprinter [1987-1992] = EE90, EE92  Engine Bushing [RH]	PFT-2012-December-31 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-281RZ</b> <b>12362-11100</b>  Corolla / Sprinter [1987-1992] = EE90, EE92  Insulator Engine [RH]	RBI-2008-February-02 RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-27R1DZ</b> <b>12362-64060</b>  Corolla / Sprinter [1987-1989] = 1C..CE90  Insulator Engine [RH] [Diesel]	Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p>AT09-27LAZ 12372-15130</p> <p>AE92</p> <p>Insulator Engine [LH, A/T]</p>  <p>PFT-2013-October-10 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>
	<p>AT09-27LMZ 12372-15150</p> <p>AE92</p> <p>Insulator Engine [LH, M/T]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.alafuae.com</p>
<p>AT09-28L 12372-15120</p> <p>EE90, AE92</p> <p>Engine Bushing [LH]</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.alafuae.com</p>	<p>AT09-28LMZ 12372-15110</p> <p>AE92</p> <p>Insulator Engine [LH, M/T]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>



















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA



Revision : 2014-November-01

<b>AT09-29E</b> <b>12371-16280</b>  <b>AE101</b>  <b>Engine Bushing [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-29EZ</b> <b>12371-16280</b>  <b>AE101</b>  <b>Insulator Engine [RE]</b>	  <small>RBI-2005-August-19 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-30E</b> <b>12371-11430</b>  <b>EE100</b>  <b>Engine Bushing [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-30EZ</b> <b>12371-15240</b>  <b>EE100</b>  <b>Insulator Engine [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-31EA</b> <b>12371-64210</b>  <b>AE110, AE111</b>  <b>Engine Bushing [RE, A/T]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-31EAZ</b> <b>12371-64210</b>  <b>AE110, AE111</b>  <b>Insulator Engine [RE, A/T]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-31EM</b> <b>12371-15240</b>  <b>AE110, AE111</b>  <b>Engine Bushing [RE, M/T]</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-31EMZ</b> <b>12371-15241</b>  <b>AE110, AE111</b>  <b>Insulator Engine [RE, M/T]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>



## TOYOTA

Revision : 2014-November-01

<b>AT09-30F</b> <b>12361-11160</b>  <b>AE101, EE100</b>   Engine Bushing [FR]	RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-30FZ</b> <b>12361-11160</b>  <b>EE100, AE101</b>   Insulator Engine [FR]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-30FDZ</b> <b>12361-11170</b>  <b>EE100, CE100, CE110</b>   Insulator Engine [FR, Diesel]	PFT-2013-June-25 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT10-EE100FZ</b> <b>12361-11180</b>  <b>Corolla [1995-1996] = EE10#, EE11#..2E, 4EFE, 5EFE</b>   Insulator Engine [FR, MT]	PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT10-31F</b> <b>12361-15170</b>  <b>AE110, AE111, AE102</b>   Insulator Engine [FR, A/T]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-Z11FAZ</b> <b>12361-0D021</b>  <b>ZZE110</b>   Insulator Engine [FR, A/T]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-Z11FMZ</b> <b>12361-0D011</b>  <b>ZZE110</b>   Insulator Engine [FR, M/T]	TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-AE115FZ</b> <b>12361-16270</b>  <b>Corolla [1991-2000] = AE104, CE104.. [4WD]  </b> <b>Corolla [1991-2002] = AE10#, CE10#, EE10#  </b> <b>Corolla [19</b>   Insulator Engine [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		



**TOYOTA**

Revision : 2014-November-01

		<b>AT09-30LAZ</b> <b>12372-15160</b>  <b>AE100, AE101, AE102</b>  Insulator Engine [LH, M/T]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-31LA</b> <b>12372-15180</b>  <b>AE110, AE111</b>  Engine Bushing [LH, A/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-31LAZ</b> <b>12372-15181</b>  <b>AE110, AE111</b>  Insulator Engine [LH, A/T]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-31LM</b> <b>12372-11250</b>  <b>AE110, AE111</b>  Engine Bushing [LH, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-31LMZ</b> <b>12372-15171</b>  <b>AE110, AE111</b>  Insulator Engine [LH, M/T]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-31L3Z</b> <b>12372-11230</b>  <b>AE110, AE111</b>  Insulator Engine [LH, M/T]	PFT-2014-October-15 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-32LA</b> <b>12372-15200</b>  <b>AE111, AE112   ST191 Exsior   Toyota Rav4 [1994-2000] = SXA1#</b>  Engine Bushing [LH, A/T, M/T]	RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-32LAZ</b> <b>12372-15200</b>  <b>AE111 [HI-Torque]</b>  Insulator Engine [LH, A/T]	RBI-2006-May-25 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-32LMZ</b> <b>12372-15220</b>  <b>AE112, ZZE110, HI TORQUE</b>  Insulator Engine [LH, M/T]	RBI-2009-December-12 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-30R</b> <b>12305-11010</b>  <b>EE100, AE101</b>  Engine Bushing [RH]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-30RZ</b> <b>12305-11010</b>  <b>EE100, AE101</b>  Insulator Engine [RH]	 ASH-2012-December-25 Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-30R4Z</b> <b>12305-11020</b>  <b>EE100, AE101</b>  Insulator Engine [RH]	 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-32R00</b> <b>12305-15130</b>  <b>EE100, AE101</b>  Engine Bushing [RH]	 ARD-2014-January-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT09-31R</b> <b>12305-15040</b>  <b>AE110, AE111</b>  Engine Bushing [RH, A/T, M/T]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-31RZ</b> <b>12305-15040</b>  <b>AE110, AE111</b>  Insulator Engine [RH]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-31RZZ</b> <b>12305-15040</b>  <b>AE110, AE111</b>  Insulator Engine [RH, A/T, M/T]	 RBI-OLD RBI Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-31RAZ</b> <b>12305-16050</b>  <b>AE110, AE111</b>  Insulator Engine [RH]	 PFT-2012-December-31 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-31R4</b> <b>12305-16060</b>  <b>AE110, AE111</b>  Engine Bushing [RH]	 PFT-2012-December-31 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-31R4Z</b> <b>12305-16060</b>  <b>AE110, AE111</b>  Insulator Engine [RH]	 PFT-2012-December-31 Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT09-Z11RZ</b> <b>12305-0D010</b>  Corolla [1998-2002] = ZZ11#, [3ZZFE, 4ZZFE]  Insulator Engine [RH, A/T, M/T]	 TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-Z12EA</b> <b>12371-0D060</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Engine Bushing [RE, A/T]</p>	<p><b>AT09-Z12EAZ</b> <b>12371-0D060</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Insulator Engine [RE, A/T]</p>
	<p><b>AT09-Z12E3Z</b> <b>12371-0D040</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Insulator Engine [RE, A/T, M/T]</p>
<p><b>AT09-Z12EM</b> <b>12371-0D050</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Engine Bushing [RE, M/T]</p>	<p><b>AT09-Z12EMZ</b> <b>12371-0D050</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Insulator Engine [RE, M/T]</p>
	<p><b>AT09-Z12E5Z</b> <b>12371-64350</b></p>  <p>Toyota Corolla [2001-2011] = 2C..CE120, CE140</p> <p>Insulator Engine</p>
	<p><b>AT09-Z12E9Z</b> <b>12371-0D090</b></p>  <p>Toyota Corolla HB [2001-2004] = 2ZZGE, 3ZZFE, 4ZZFE..ZZE12#</p> <p>Insulator Engine [RE, M/T]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-Z12FM</b> <b>12361-0D030</b>  Corolla / Altis [2001-2007] = ZZE12# Engine Bushing [FR, M/T]	RBI-2008-January-13 RBI Product, Perfect Product shabbirh@eim.ae  <b>AT09-Z12FMZ</b> <b>12361-0D030</b> Corolla / Altis [2001-2007] = ZZE12# Insulator Engine [FR, M/T]
<b>AT09-Z12FA</b> <b>12361-0D040</b>  Corolla / Altis [2001-2007] = ZZE12# Engine Bushing [FR, A/T]	RBI-2008-January-13 RBI Product, Perfect Product shabbirh@eim.ae  <b>AT09-Z12FAZ</b> <b>12361-0D040</b> Corolla / Altis [2001-2007] = ZZE12# Insulator Engine [FR, A/T]
	RBI-2007-August-01 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  <b>AT09-ZRE12FAZ</b> <b>12361-0T040</b> Corolla [China] [2007] = IZRFE..ZRE120..4FC Insulator Engine [FR, A/T] [1.6]
	HFC-2014-November-20 HFC Product www.rbi.ae <b>AT09-ZRE12FMZ</b> <b>12361-0T030</b> Corolla [China] [2007] = IZRFE..ZRE120..5F Insulator Engine [FR, M/T] [1.6]
	TN-2012-March-06 Tenacity Product shabbirh@eim.ae  <b>AT09-Z12F3Z</b> <b>12361-0D150</b> Toyota Corolla HB / SED / WG [2002-2004] = 4ZZFE..ZZE120..UKP   Toyota Verso [2004-2007] = 1ZZFE, 3Z Insulator Engine [FR]
	TN-2011-October-12 Tenacity Product shabbirh@eim.ae  <b>AT09-ZZE112FAZ</b> <b>12361-22020</b> Toyota Corolla [1999-2002] = 3ZZFE..ZZE112..4FC Insulator Engine [FR, A/T]





# AL LAMSA AL FIDDIYA TRADING L.L.C.


**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-Z12L0</b> <b>12372-0D050</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Engine Bushing [LH, A/T, M/T]</p>	<p><b>AT09-Z12LZ</b> <b>12372-0D050</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Insulator Engine [LH, A/T, M/T]</p>
	<p><b>AT09-Z12L2Z</b> <b>12372-22060</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Insulator Engine [LH, A/T, M/T]</p>
	<p><b>AT09-Z12L3Z</b> <b>12372-0D080</b></p>  <p>Toyota Corolla HB / SED / WG [2001-2004] = 3ZZFE, 4ZZFE..ZZE120, ZZE12#, ZZE121.,UKP..5F</p> <p>Insulator Engine [LH, M/T]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-Z12R</b> <b>12305-0D061</b></p> <p>Corolla / Altis [2001-2007] = 1ZZFE, 3ZZFE..ZZE12#</p> <p>Engine Bushing [RH, A/T, M/T] [1.6, 1.8]</p>	<p><b>AT09-Z12RZ</b> <b>12305-0D061</b></p> <p>Corolla / Altis [2001-2007] = 1ZZFE, 3ZZFE..ZZE12#</p> <p>Insulator Engine [RH, A/T, M/T] [1.6, 1.8]</p>
	<p><b>AT09-Z12RZZ</b> <b>12362-22090</b></p> <p>Corolla / Altis [2001-2007] = 1ZZFE, 3ZZFE..ZZE12#</p> <p>Insulator Engine [RH, A/T, M/T] [1.6, 1.8]</p>
	<p><b>AT09-NZ12RZZ</b> <b>12305-21130</b></p> <p>Corolla / Altis [2001-2007] = 1NZFE, 2NZFE..NZE12#</p> <p>Insulator Engine [RH, A/T, M/T] [1.3, 1.5]</p>
	<p><b>AT09-Z12R6ZZ</b> <b>12305-0D051</b></p> <p>Toyota Corolla HB / SED / WG [2003-2007] = 3ZZFE, 4ZZFE..ZZE120, ZZE121..UKP   Toyota Corolla Verso</p> <p>Insulator Engine [RH]</p>











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-Z14EA</b> <b>12371-0D220</b></p>  <p>Corolla / Altis [2007] = ZZE14#</p> <p>Engine Bushing [RE, A/T]</p> <p><small>RBI-2010-May-22 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p><b>AT09-Z14EAZ</b> <b>12371-0D220</b></p>  <p>Corolla / Altis [2007] = ZZE14#</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p><small>RBI-2012-November-30 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p><b>AT09-Z14EMZ</b> <b>12371-0D210</b></p>  <p>Corolla / Altis [2007] = ZZE14#</p> <p>Insulator Engine [RE, M/T, M/T]</p> <p><small>PFT-2014-May-25 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p><b>AT09-Z14E3Z</b> <b>12371-22250</b></p>  <p>Toyota Corolla / SED / WG [2007] = ZZE14#</p> <p>Insulator Engine [Head Rubber]</p> <p><small>TN-2014-August-30 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p><b>AT09-Z14E4Z</b> <b>12371-37060</b></p>  <p>Corolla [2007] = ZRE142...2ZRFE</p> <p>Insulator Engine [RE]</p> <p><small>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p><b>AT09-Z14E5Z</b> <b>12371-37110</b></p>  <p>Toyota Corolla / SED / WG [2007] = ZRE14#</p> <p>Insulator Engine</p> <p><small>TN-2014-August-30 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-Z14FA</b> <b>12361-0D220</b></p> <p> <b>PERFECT</b> RUBBER PARTS</p> <p>Corolla / Altis [2007] = ZZE14#</p> <p>Engine Bushing [FR, A/T]</p>	<p><b>AT09-Z14FAZ</b> <b>12361-0D220</b></p> <p> <b>RBI</b></p> <p>Corolla / Altis [2007] = ZZE14#</p> <p>Insulator Engine [FR, A/T]</p> <p><small>RBI-2010-June-25 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small></p>
	<p><b>AT09-Z14FMZ</b> <b>12361-0D210</b></p> <p> <b>RBI</b></p> <p>Corolla / Altis [2007] = ZZE14#</p> <p>Insulator Engine [FR, M/T]</p> <p><small>RBI-2010-June-25 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small></p>
	<p><b>AT09-Z14F3Z</b> <b>12361-0T090</b></p> <p> <b>TENACITY</b></p> <p>Corolla Altis [2008] = ZRE143, GEP#KR.. [2.0]</p> <p>Insulator Engine [FR]</p> <p><small>TN-2013-November-20 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small></p>
	<p><b>AT09-Z14F4Z</b> <b>12361-37050</b></p> <p> <b>TENACITY</b></p> <p>Corolla [2007] = ZRE142..2ZRFE</p> <p>Insulator Engine [FR]</p> <p><small>TN-2013-November-20 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small></p>
	<p><b>AT09-Z14F5Z</b> <b>12361-64410</b></p> <p> <b>PERFECT</b> RUBBER PARTS</p> <p>Toyota Corolla [2007-2011] = 2C..CE140</p> <p>Insulator Engine [FR, M/T]</p> <p><small>PFT-2014-May-25 Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small></p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

		<b>AT09-Z14LAZ</b> <b>12372-0D190</b>  Corolla / Altis [2007] = ZZE14# Insulator Engine [LH, A/T]	RBI-2012-November-30 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-Z14LMZ</b> <b>12372-0D170</b>  Corolla / Altis [2007] = ZZE14# Insulator Engine [LH, M/T]	RBI-2012-November-30 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-Z14L2Z</b> <b>12372-22200</b>  Corolla / Altis [2007] = ZZE14# Insulator Engine [LH]	TN-2014-August-30 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-Z14L5Z</b> <b>12372-0T140</b>  Toyota Corolla / SED / WG [2007] = ZRE14# Insulator Engine LH	TN-2014-August-30 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-Z14RZZ</b> <b>12305-0D130</b>  Corolla / Altis [2007] = ZZE14# Insulator Engine [RH, A/T, M/T]	TN-2014-August-30 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-Z14R2ZZ</b> <b>12305-22380</b>  Corolla / Altis [2007] = ZZE14# Insulator Engine [RH, A/T, M/T]	TN-2014-August-30 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-Z14R3ZZ</b> <b>12305-37070</b>  Toyota Corolla JPP [2007-2013] = 2ZRF..ZRE142...JPP   Corolla S.America [2011- 2014] = 2ZR#..ZRE142 Insulator Engine [RH]	HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-Z14R5ZZ</b> <b>12305-37201</b>  Toyota Corolla [2007] = ZRE14# Insulator Engine [RH]	TN-2014-August-30 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-Z15FAZ</b> <b>12361-0T010</b></p> <p>Toyota Corolla [CHINA] [2007] = 1ZRFE,2ZRFE..ZRE15#..5F,6F   Toyota Rav4 / Vanguard [2009-2011] = 1A</p> <p>Insulator Engine [FR, 5 Speed, M/T] [2.0, 2.4 Petrol, GL]</p>	<p><b>AT09-RV30FZ</b> <b>12361-28230</b></p> <p>Toyota Rav4 / Vanguard [2005-2012] = 1AZFE, 2AZFE..ACA30, ACA33, ACA38..5F, /, 3ZRFAE..ZSA3#..6F</p> <p>Insulator Engine [FR, 5 Speed, M/T] [2.0, 2.4 Petrol, EL, GL, JP]</p>
<p><b>AT09-RV30F01Z</b> <b>12361-28250</b></p> <p>Toyota Rav4 / Vanguard [2005-2012] = 1AZFE, 2AZFE..ACA3#, ACA30, ACA31, ACA33, ACA38..4FC</p> <p>Insulator Engine [FR, 4 Speed, A/T] [2.0, 2.4 Petrol, EL, GL, US]</p>	
<p><b>AT09-RV30F04Z</b> <b>12361-28240</b></p> <p>Toyota Rav4 / Vanguard [2005-2010] = 1AZFE, 2AZFE..ACA31, ACA33, ACA36, ACA38, /, 3ZRFAE..ZSA30..CVF</p> <p>Insulator Engine [FR, 1] [2.0, 2.4 Petrol, EL, GL, JP]</p>	
<p><b>AT09-RV30F11Z</b> <b>12361-31160</b></p> <p>Toyota Rav4 / Vanguard [2006-2012] = 2GRFE..GSA3#</p> <p>Insulator Engine [FR] [3.5 Petrol, EL, GL, JP, US]</p>	








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-Z15EAZ</b> <b>12371-22220</b>  Corolla S.Africa & China [2007] = ZRE15#  Insulator Engine [RE, A/T]	HFC-2014-November-20 HFC Product, Ashimori Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-Z15EMZ</b> <b>12371-22240</b>  Corolla S.Africa & China [2007] = ZRE15#  Insulator Engine [RE, M/T]	HFC-2014-November-20 HFC Product, Ashimori Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-RV30EAZ</b> <b>12371-28210</b>  Toyota Rav4 / Vanguard [2005-2012] = 1AZFE, 2AZFE..ACA30, ACA31, ACA33..4FC  Insulator Engine [RE, 4 Speed, A/T] [2.0, 2.4 Petrol, EL, GL, US]	ARP Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
		<b>AT09-RV30E04Z</b> <b>12371-0H120</b>  Toyota Rav4 / Vanguard [2005-2012] = 1AZFE, 2AZFE..ACA38..5F, /, 3ZRFAE..ZSA35  Insulator Engine [RE, 5 Speed, M/T] [2.0, 2.4 Petrol, GL]	HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AT09-RV30E05Z</b> <b>12371-0H100</b>  Toyota Rav4 / Vanguard [2009-2011] = 1AZFE..ACA37..5F  Insulator Engine [RE, 5 Speed, M/T] [2.0 Petrol, GL]	HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-Z15LAZ</b> <b>12372-22150</b>  Corolla S.Africa & China [2007] = ZRE15#  Insulator Engine [LH, A/T]	HFC-2014-November-20 HFC Product, Ashimori Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-Z15LMZ</b> <b>12372-22180</b>  Corolla S.Africa & China [2007] = ZRE15#  Insulator Engine [LH, M/T]	HFC-2014-November-20 HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-RV30LAZ</b> <b>12372-28220</b>  Toyota Rav4 / Vanguard [2005-2012] = 1AZFE, 2AZFE..ACA3#, ACA30, ACA31, ACA33, ACA38..4FC, /, 2ARFE.  Insulator Engine [LH, 4 Speed, A/T] [2.0, 2.4 Petrol, EL, GL, US]	ARP Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT09-RV30L01Z</b> <b>12372-0H190</b>  Toyota Rav4 / Vanguard [2009-2011] = 1AZFE, 2AZFE..ACA3#..4FC  Insulator Engine [LH, 4 Speed, A/T] [2.0, 2.4 Petrol, GL]	HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AT09-RV30L02Z</b> <b>12372-0H180</b>  Toyota Rav4 / Vanguard [2009-2011] = 1AZFE, 2AZFE..ACA3#..5F  Insulator Engine [LH, 5 Speed, M/T] [2.0, 2.4 Petrol, GL]	HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-Z15RZ</b> <b>12305-22360</b>  Corolla S.Africa & China [2007] = ZRE15#  Insulator Engine [RH, A/T, M/T]	HFC-2014-November-20 HFC Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AT09-RV30RAZZ</b> <b>12305-28240</b>  Toyota Rav4 / Vanguard [2005-2012] = 1AZFE, 2AZFE..ACA30, ACA31, ACA33..4FC  Insulator Engine [RH, 4 Speed, A/T] [2.0, 2.4 Petrol, EL, GL, US]	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AT09-RV30R03ZZ</b> <b>12305-0H040</b>  Toyota Rav4 / Vanguard [2009-2012] = 1AZFE, 2AZFE..ACA32, ACA33, ACA37..5F  Insulator Engine [RH, 5 Speed, M/T] [2.0, 2.4 Petrol, GL]	HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-AZR60FZ</b> <b>12361-28170</b></p> <p>Shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Noah / Voxy [2001-2002] = AZR60, AZR65</p> <p>Insulator Engine [FR] [2WD, 4WD]</p>	<p><b>AT09-AZR60F2Z</b> <b>12361-28171</b></p> <p>ARP Product Shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Noah / Voxy [2001-2002] = AZR60, AZR65</p> <p>Insulator Engine [FR] [2WD, 4WD]</p>
<p><b>AT09-W110E</b> <b>12371-28060</b></p> <p>RBI-2010-January-28 RBI Product Shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Wish [2003] = ANE1#   Picnic / Avensis Verso [2001-2005] = ACM20 Ipsum [2001-2003] = ACM21   Noah /</p> <p>Engine Bushing [RE] [2WD, 4WD]</p>	<p><b>AT09-W110EZ</b> <b>12371-28080</b></p> <p>RBI-2010-October-27 RBI Product, Tenacity Product, HFC Product, Ashimori Product Shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Wish [2003] = ANE1#   Picnic / Avensis Verso [2001-2005] = ACM20   Ipsum [2001-2003] = ACM21</p> <p>Insulator Engine [RE] [2WD]</p>
	<p><b>AT09-W110R3Z</b> <b>12362-28060</b></p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product Shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Ipsum [2001-2009] = ACM21   Toyota Ipsum [2001-2009] = ACM26.. [4WD]   Toyota Noah, Voxy [200</p> <p>Insulator Engine [RH]</p>
	<p><b>AT09-AZR60EZ</b> <b>12371-28060</b></p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product Shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Noah / Voxy [2001-2002] = AZR60</p> <p>Insulator Engine [RE]</p>
	<p><b>AT09-AZR65EZ</b> <b>12371-28100</b></p> <p>ARP Product Shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Noah / Voxy [2001-2002] = AZR65</p> <p>Insulator Engine [RE] [4WD]</p>











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-W110L</b> <b>12372-28110</b> Wish [2003] = ANE1#   Picnic / Avensis Verso [2001-2005] = ACM20   Noah / Voxy [2001-2002] = AZR60, Engine Bushing [LH]	RBI-2010-January-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT09-W110LZ</b> <b>12306-0H020</b> Wish [2003] = ANE1# Insulator Engine [LH]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT09-AZR65LZ</b> <b>12372-28190</b> Noah / Voxy [2001-2002] = AZR65 Insulator Engine [LH] [4WD]	TN-2013-March-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT09-W110L2Z</b> <b>12372-28150</b> Picnic / Avensis Veso [2001-2005] = ACM20 Insulator Engine [LH]	TN-2013-March-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT09-AZR60LZ</b> <b>12372-28100</b> Noah / Voxy [2001-2002] = AZR60 Insulator Engine [LH] [2WD]	TN-2013-March-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT09-W110RZ</b> <b>12305-28080</b> Wish [2003] = ANE1#   Noah / Voxy [2001-2002] = AZR60   Picnic / Avensis Verso [2001-2005] = ACM20 Insulator Engine [RH] [2WD]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT09-W110R2Z</b> <b>12305-28120</b> Wish [2003-2004] = 1AZFSE..ANE1#   Isis [2004] = 1AZFSE..ANM10   Permio/Allion [2001-2004] = 1AZFSE. Insulator Engine [RH]	RBI-2013-June-15 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

AT09-NHW1FZ 12363-21020  Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  Toyota Prius [2000-2003] = NZFXE...NHW11  Insulator Engine [FR, TORQ] [1.5 Petrol]	
AT09-NHW1RZ 12305-21120  Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  Toyota Prius [2000-2003] = NZFXE...NHW11  Insulator Engine [RH] [1.5 Petrol]	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-XT08EAZ</b>  <b>12371-15031</b></p> <p>TN-2012-March-06  Tenacity Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Corsa / Tercel [1982-1983] = 2A, 3AC..AL20, AL21..3FC</p> <p>Insulator Engine [RE, A/T]</p>	
<p><b>AT09-XT08FZ</b>  <b>12361-15130</b></p> <p>ARD-2014-January-01  ARD Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Corsa / Tercel [1984-1989] = EL21, EL25</p> <p>Insulator Engine [FR]</p>	<p><b>AT09-XT08F2Z</b>  <b>12361-15050</b></p> <p>Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Corsa/Tercel [1982-1989] = AL2#,   Sprinter Carib [1982-1988] = AL25</p> <p>Insulator Engine [FR]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p>AT09-XT09FMZ 12361-11050</p> <p>Tercel / Corsa / Corolla 2 [1986-1990] = EL3#</p> <p>Insulator Engine [FR]</p> <p>ARD-2014-January-01 Perfect Product, ARD Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
<p>AT09-EP71E 12371-10040</p> <p>Starlet [1984-1989] = EP7#</p> <p>Engine Bushing [RE]</p>  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p>AT09-EP71EZ 12371-10040</p> <p>Starlet [1984-1989] = EP7#</p> <p>Insulator Engine [RE]</p> <p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p>AT09-XT09EMZ 12371-11141</p> <p>Tercel / Corsa / Corolla 2 [1986-1990] = EL3#</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
<p>AT09-EP71L 12372-10020</p> <p>Starlet [1984-1989] = EP7#</p> <p>Engine Bushing [LH]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p>AT09-EP71LZ 12372-10020</p> <p>Starlet [1984-1989] = EP7#</p> <p>Insulator Engine [LH]</p> <p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p>AT09-XT09LMZ 12372-11070</p> <p>Tercel / Corsa / Corolla 2 [1986-1990] = EL3#</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
<p>AT09-EP71R 12362-10010</p> <p>Starlet [1984-1989] = EP7#</p> <p>Engine Bushing [RH]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p>AT09-EP71RZ 12362-10010</p> <p>Starlet [1984-1989] = EP7#</p> <p>Insulator Engine [RH]</p> <p>RBI-2008-July-21 RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-EP82E</b> <b>12371-11240</b>  <b>EP82</b>  <b>Engine Bushing [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-EP82EZ</b> <b>12371-11240</b>  <b>Starlet [1991-1999] = EP81, EP82, EP90</b>  <b>Insulator Engine [RE, M/T]</b>	  <small>RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-EP82EAZ</b> <b>12371-11420</b>  <b>Starlet [1991-1999] = EP81, EP82, EP90</b>  <b>Insulator Engine [RE, A/T]</b>	  <small>Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-XT10EM</b> <b>12371-11290</b>  <b>Tercel [1990-1994] = EL4#</b>  <b>Engine Bushing [RE, M/T]</b>	 <small>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-XT10EMZ</b> <b>12371-11291</b>  <b>Tercel [1990-1994] = EL4#</b>  <b>Insulator Engine [RE, M/T]</b>	  <small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-XT10E2Z</b> <b>12371-11290</b>  <b>Tercel [1990-1994] = EL4#</b>  <b>Insulator Engine [RE, M/T] [1.5]</b>	  <small>TN-2011-July-23 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-XT10EAZ</b> <b>12371-11300</b>  <b>Tercel [1990-1994] = EL4#   Paseo [1990-1995] = EL4#</b>  <b>Insulator Engine [RE, A/T]</b>	  <small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-XT11EMZ</b> <b>12371-11310</b>  <b>Tercel [1994-1999] = EL5#</b>  <b>Insulator Engine [RE, M/T]</b>	  <small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-XT11EAZ</b> <b>12371-11510</b>  <b>Tercel [1994-1999] = EL5#</b>  <b>Insulator Engine [RE, A/T]</b>	  <small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>



















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-EP82L</b> <b>12372-10040</b>  <b>EP82</b>  <b>Engine Bushing [LH]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-EP82LZ</b> <b>12372-10040</b>  <b>EP82</b>  <b>Insulator Engine [LH]</b>	  <small>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-XT10LM</b> <b>12372-11170</b>  <b>Tercel [1990-1994] = EL4#   Corolla 2 [1994-1999] = EL51   Corsa / Cynos [1990-1999] = EL4#, EL5#</b>  <b>Engine Bushing [LH, M/T]</b>	  <small>PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-XT10LMZ</b> <b>12372-11170</b>  <b>Tercel [1990-1994] = EL4#   Corolla 2 [1994-1999] = EL51   Corsa / Cynos [1990-1999] = EL4#, EL5#</b>  <b>Insulator Engine [LH, M/T]</b>	  <small>Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-XT10LAZ</b> <b>12372-11190</b>  <b>Tercel [1990-1994] = EL4#   Corolla 2 [1994-1999] = EL51   Corsa / Cynos [1990-1999] = EL4#, EL5#</b>  <b>Insulator Engine [LH]</b>	  <small>TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-XT11LMZ</b> <b>12372-11290</b>  <b>Tercel [1994-1999] = EL5#</b>  <b>Insulator Engine [LH, M/T]</b>	  <small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT09-XT11LAZ</b> <b>12372-11220</b>  <b>Tercel [1994-1999] = EL5#</b>  <b>Insulator Engine [LH, A/T]</b>	  <small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-EY10L</b> <b>12362-11110</b> EP82   EXY10, SERA   Tercel [1990-1999] = EL4#, EL5#   Corolla 2 [1994-1999] = EL51, EL53, EL55   Co Engine Bushing [RH, A/T, M/T]	<b>AT09-EY10RZ</b> <b>12362-11110</b> EP82   EXY10, SERA   Tercel [1990-1999] = EL4#, EL5#   Corolla 2 [1994-1995] = EL51 Insulator Engine [RH, A/T, M/T]
	<b>AT09-XT10RMZ</b> <b>12362-11300</b> Tercel [1990-1999] = EL4#, EL5#   Corolla 2 [1994-1999] = EL51, EL53, EL55   Corsa / Tercel [1990-19 Insulator Engine [RH, A/T, M/T]







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-S01EA</b> <b>12371-02120</b>  Soluna [1996-2003] = AL50 Engine Bushing [RE, A/T]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-S01EAZ</b> <b>12371-02120</b>  Soluna [1996-2003] = AL50 Insulator Engine [RE, A/T]	RBI-2006-March-15 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-S01EM</b> <b>12371-02110</b>  Soluna [1996-2003] = AL50 Engine Bushing [RE, M/T]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-S01EMZ</b> <b>12371-02110</b>  Soluna [1996-2003] = AL50 Insulator Engine [RE, M/T]	RBI-2006-February-09 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-S01LA</b> <b>12372-02120</b>  Soluna [1996-2003] = AL50 Engine Bushing [LH, A/T, 3 Speed]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-S01LAZ</b> <b>12372-02120</b>  Soluna [1996-2003] = AL50 Insulator Engine [LH, A/T, 3 Speed]	RBI-OLD RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-S01LM</b> <b>12372-02110</b>  Soluna [1996-2003] = AL50 Engine Bushing [LH, M/T]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-S01LMZ</b> <b>12372-02110</b>  Soluna [1996-2003] = AL50 Insulator Engine [LH, M/T]	RBI-OLD RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-S02LAZ</b> <b>12372-02150</b>  Soluna [1996-2003] = AL50 Insulator Engine [LH, A/T, 4 Speed]	RBI-2009-June-12 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT09-S01R</b> <b>12362-02050</b>  Soluna [1996-2003] = AL50 Engine Bushing [RH, A/T, 3 Speed, M/T]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-S01RZ</b> <b>12362-02050</b>  Soluna [1996-2003] = AL50 Insulator Engine [RH, A/T, 3 Speed, M/T]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-S02R0Z</b> <b>12362-02060</b>  Soluna [1996-2003] = AL50 Insulator Engine [RH, A/T, 4 Speed]	RBI-2010-June-25 RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-NC42EA</b> <b>12371-0M030</b></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Engine Bushing [RE, A/T]</p>	<p><b>AT09-NC4EAZ</b> <b>12371-0M030</b></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Insulator Engine [RE, A/T]</p>
<p><b>AT09-NC42EM</b> <b>12371-0M020</b></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Engine Bushing [RE, M/T]</p>	<p><b>AT09-NC4EMZ</b> <b>12371-0M020</b></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Insulator Engine [RE, M/T]</p>
	<p><b>AT09-NC4E3Z</b> <b>12371-21040</b></p> <p>Vitz / Platz [1999-2002] = NCP15, NCP16..2NZFE   Pro Box / Succeed / Fun Cargo / BB Open Deck / IST</p> <p>Insulator Engine [RE, A/T]</p>
	<p><b>AT09-NC4E4Z</b> <b>12371-23010</b></p> <p>Yaris / Echo [1999-2000] = 1SZFE, 1NZFE, 2NZFE..NCP10, SCP10</p> <p>Insulator Engine [RE, A/T]</p>
	<p><b>AT09-NC4E5Z</b> <b>12371-21020</b></p> <p>Yaris / Echo / Toyota XA [2000-2005] = 1NZFE, 2NZFE..NCP1#, NCP61..5F</p> <p>Insulator Engine [RE, M/T]</p>
<p><b>AT09-NC4E8Z</b> <b>12371-21140</b></p> <p>Probox / Succeed / Will Cypha [2002-2003] = NCP50, NCP51, NCP52, NCP58..1NZ#, 2NZFE   Raum [2003] =</p> <p>Insulator Engine [RE, A/T]</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-NC42L</b> <b>12372-0M030</b>  Vios / Soluna Vios [2002] = NCP4# Engine Bushing [LH, A/T, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT09-NC4LAZ</b> <b>12372-0M030</b>  Vios / Soluna Vios [2002] = NCP4# Insulator Engine [LH, A/T]	RBI-2007-August-20 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-NC4LMZ</b> <b>12372-0M040</b>  Vios / Soluna Vios [2002] = NCP4# Insulator Engine [LH, M/T]	RBI-2007-August-20 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-NC4LZ</b> <b>12372-21060</b>  Vios / Soluna Vios [2002] = NCP4# Insulator Engine [LH, M/T]	TN-2011-June-03 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-NC4RZ</b> <b>12305-0M020</b>  Vios / Soluna Vios [2002-2005] = 1NZFE..NCP4# Insulator Engine [RH] [With Top]	TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-NC4R2Z</b> <b>12305-21060</b>  Vios / Soluna Vios [2002] = NCP4#   Yaris / Echo / Toyota XA [1999-2005] = 1NZFE..2NZFE..NCP1# Insulator Engine [RH] [With Top]	TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-NC4R3Z</b> <b>12305-21020</b>  Fun Cargo / BB/Open Deck / Platz / Pro Box/Succeed [1999-2005] = 1NZFE..NCP12# Insulator Engine [RH] [With Out Top]	TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
		<b>AT09-NC4R4Z</b> <b>12305-02060</b>  Vios / Soluna Vios [2002-2005] = NCP4#..SAFE, 8AFE..AXP4# Insulator Engine [RH] [With Out Top]	TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-NC9ELAZ</b> <b>12363-21060</b></p> <p>TN-2010-December-01 Tenacity Product, HFC Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#   Yaris [2011] = NCP13#</p> <p>Insulator Engine [RE, LH, A/T]</p>
<p><b>AT09-NC9ERA</b> <b>12364-21020</b></p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#</p> <p>Engine Bushing [RE, RH, A/T]</p>	<p><b>AT09-NC9ERAZ</b> <b>12364-21020</b></p> <p>TN-2010-December-01 Tenacity Product, HFC Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#</p> <p>Insulator Engine [RE, RH, A/T]</p>
	<p><b>AT09-NC9EMZ</b> <b>12363-21040</b></p> <p>PFT-2014-August-31 Perfect Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#   Yaris [2011] = NCP13#</p> <p>Insulator Engine [RE, M/T]</p>
	<p><b>AT09-NC9E2Z</b> <b>12363-0M040</b></p> <p>TN-2012-August-06 Tenacity Product, HFC Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#   Yaris [2011] = NCP13#</p> <p>Insulator Engine [RE, M/T]</p>
	<p><b>AT09-NC9EL5Z</b> <b>12363-0T020</b></p> <p>HFC-2014-November-20 HFC Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Yaris [2008-2010] = 1ZRFE..ZSP91..4PC   Toyota Vios [2008-2013] = 1ZRFE..ZSP92..4FC</p> <p>Insulator Engine [RE, LH, A/T]</p>













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<b>AT09-NC9RZ</b> <b>12305-21340</b> Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#   Yaris [2011] = NCP13# Insulator Engine [RH, A/T, M/T]	TN-2014-May-05 Tenacity Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-Z14R6ZZ</b> <b>12305-0T020</b> Toyota Corolla [CHINA] [2007-] = 1ZRFE..ZRE120 Insulator Engine [RH]	HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>
	<b>AT09-NC9R2Z</b> <b>12305-0T030</b> Toyota Vios [2007] = 1ZRFE..ZSP92..5F Insulator Engine [RH]	Ashimori Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-NC9R3Z</b> <b>12305-21200</b> Yaris [2005-2008] = NCP91..1NZFE..5F Insulator Engine [RH, MT]	HFC-2014-November-20 HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-NC9R4Z</b> <b>12305-21220</b> Yaris / Vios [2006-2010] = 1NZFE..NCP91, NCP93 Insulator Engine [RH]	TN-2014-May-05 Tenacity Product, HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-NC9LZ</b> <b>12372-21150</b> Yaris / Echo / Vios / Soluna [2005-2010] = NCP9# Insulator Engine [LH, A/T, M/T]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-NC9L2Z</b> <b>12372-0M050</b> Yaris / Echo / Vios / Soluna [2005-2010] = NCP9# Insulator Engine [LH, A/T, M/T]	HFC-2014-November-20 HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
	<b>AT09-NC9L3Z</b> <b>12372-0T040</b> Toyota Vios [2007-2014] = 1ZRFE..ZSP92..4FC Insulator Engine [LH, A/T]	HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01










<b>AT09-RV1EM</b> <b>12371-74460</b>  Toyota Rav4 [1994-2000] = SXA1#  Engine Bushing [RE, M/T]	 RBI-2007-June-18 RB1 Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-RV1EMZ</b> <b>12371-74460</b>  Toyota Rav4 [1994-2000] = SXA1#  Insulator Engine [RE, M/T]	 RBI-2009-May-11 RB1 Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-RV1EA</b> <b>12371-74470</b>  Toyota Rav4 [1994-2000] = SXA1#  Engine Bushing [RE, A/T]	 RBI-2009-December-12 RB1 Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-RV1EAZ</b> <b>12371-74470</b>  Toyota Rav4 [1994-2000] = SXA1#  Insulator Engine [RE, A/T]	 RBI-2009-May-11 RB1 Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-RV1FM</b> <b>12361-74340</b>  Toyota Rav4 [1994-2000] = SXA1#  Engine Bushing [FR, M/T]	 RBI-2007-March-13 RB1 Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-RV1FMZ</b> <b>12361-74340</b>  Toyota Rav4 [1994-2000] = SXA1#  Insulator Engine [FR, M/T]	 RBI-2009-April-21 RB1 Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-RV1FA</b> <b>12361-74370</b>  Toyota Rav4 [1994-2000] = SXA1#  Engine Bushing [FR, A/T]	 RBI-2007-March-03 RB1 Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-RV1FAZ</b> <b>12361-74370</b>  Toyota Rav4 [1994-2000] = SXA1#  Insulator Engine [FR, A/T]	 RBI-2009-April-21 RB1 Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





**TOYOTA**

Revision : 2014-November-01

<b>AT09-RV1LA</b> <b>12372-74410</b>  Toyota Rav4 [1994-2000] = SXA1# Engine Bushing [LH, A/T]	RBI-2007-March-03 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-RV1LMZ</b> <b>12372-74400</b>  Toyota Rav4 [1994-1997] = SXA1# Insulator Engine [LH, M/T]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-RV1LAZ</b> <b>12372-74520</b>  Toyota Rav4 [1994-1997] = SXA1# Insulator Engine [LH, A/T]	RBI-2009-April-21 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT09-RV1L0</b> <b>12372-74610</b>  Toyota Rav4 [1994-2000] = SXA1#   AE111, AE112   ST191 Exsior Engine Bushing [LH, A/T, M/T]	PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT09-RV1LZ</b> <b>12372-11320</b>  Toyota Rav4 [1997-2000] = SXA1#   Caldina [1996] = 5EFE..ET196.3FC Insulator Engine [LH, A/T, M/T]	ARD-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-RV1L2Z</b> <b>12372-74550</b>  Toyota Rav4 [1994-1997] = SXA15, SXA16 Insulator Engine [LH, A/T]	Ashimori Product www.rbi.ae
		<b>AT09-RV1L3Z</b> <b>12372-74610</b>  Toyota Rav4 [1997] = 3S#..SXA1#..MTM Insulator Engine [LH] [MT]	PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-RV1L4Z</b> <b>12372-74620</b>  Toyota Rav4 [1997] = 3S#..SXA1#..ATM Insulator Engine [LH, A/T]	PFT-2014-January-14 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT09-RV1RZ</b> <b>12362-74391</b>  Toyota Rav4 [1994-2000] = SXA1# Insulator Engine [RH]	PFT-2014-May-25 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT09-RV21FMZ</b> <b>12361-21010</b></p> <p>Toyota Rav4 [2000-2005] = ZCA2#, ACA2#</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2012-March-06 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p><b>AT09-RV21FAZ</b> <b>12361-21020</b></p> <p>Toyota Rav4 [2000-2005] = 1AZFE, 2AZFE, 1ZZFE..ACA2#, ZCA2#..ATM</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2011-October-12 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
<p><b>AT09-RV21E</b> <b>12371-28020</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#</p> <p>Engine Bushing [RE, A/T, M/T]</p> <p>PFT-2012-November-07 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	<p><b>AT09-RV21EZ</b> <b>12371-28020</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p><b>AT09-RV21LZ</b> <b>12372-28030</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>HFC-2014-November-20 HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-RV21L2Z</b> <b>12372-28040</b></p> <p>Toyota Rav4 [2000-2003] = 1AZFE..ACA2#</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT09-RV21L3Z</b> <b>12372-22050</b></p> <p>Toyota Rav4 [2000-2003] = 1ZZFE..ZCA2#</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-RV21RZ</b> <b>12305-28060</b></p> <p>Toyota Rav4 [2000-2005] = 1AZFSE..ACA2#</p> <p>Insulator Engine [RH]</p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	<p><b>AT09-RV21RZZ</b> <b>12305-28060</b></p> <p>Toyota Rav4 [2000-2005] = 1AZFSE..ACA2#</p> <p>Insulator Engine [RH]</p> <p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-RV21R2Z</b> <b>12305-28151</b></p> <p>Toyota Rav4 [2001-2003] = 1AZFSE..ACA2#..J/L</p> <p>Insulator Engine [RH]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

AT09-SW21FZ

12361-74160

Toyota MR2 [1990-1995] = 5SFE..SW21..5F, 4FC

Insulator Engine [FR, A/T, M/T] [2.2]





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

AT09-ZZW30E1Z 12371-22080  Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  Toyota MR2 [1999-2005] = 1ZZFE..ZZW30  Insulator Engine [RE]	
AT09-ZZW30F1Z 12361-22050  Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  Toyota MR2 [1999-2005] = 1ZZFE..ZZW30  Insulator Engine [FR]	
AT09-ZZW30L1Z 12372-22040  Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  Toyota MR2 [1999-2005] = 1ZZFE..ZZW30  Insulator Engine [LH]	
AT09-ZZW30R1Z 12362-22040  Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  Toyota MR2 [1999-2005] = 1ZZFE..ZZW30  Insulator Engine [RH]	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-DA115F</b> <b>12361-76020</b> Heavy Duty Truck [1969-2001] = 2D..DA11#, DB10# Insulator Engine [FR]	<small>PFT-2013-April-30 Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small> 	<b>AT10-DA115E00</b> <b>12371-76030</b> Heavy Duty Truck [1969-2001] = 2D..DA11#, DB10# Insulator Engine [RE]	<small>PFT-2014-January-14 Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small> 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<div>AT10-010L</div> <div>12361-31010</div> <div><div>PERFECT RUBBER PARTS</div></div> <div>RT40</div> <div>Insulator Engine [FR, LH]</div>	<div>Perfect Product</div> <div>12361-31060</div> <div><div>PERFECT RUBBER PARTS</div></div> <div>RT40</div> <div>Insulator Engine [FR, RH]</div>	<div>Perfect Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>
<div>AT10-030</div> <div>12361-39018</div> <div></div> <div>RT80, RN25</div> <div>Insulator Engine</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>
<div>AT10-040</div> <div>12361-39105</div> <div></div> <div>RT100</div> <div>Insulator Engine</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>
<div>AT10-050</div> <div>12361-26041</div> <div></div> <div>TT130, 2T NEW</div> <div>Insulator Engine</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, HFC Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>
<div>AT10-900</div> <div>12361-25010</div> <div></div> <div>2T</div> <div>Insulator Engine</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>	
<div>AT10-CR27</div> <div>12361-64022</div> <div></div> <div>CR27 [1C]   Toyota DELIBOY [1989-1995]</div> <div>Insulator Engine</div>	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<div>PFT-2012-June-26</div> <div>Perfect Product, Tenacity Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>
<div>AT10-ST140F</div> <div>12361-63020</div> <div></div> <div>Mark II / Chaser / Cresta [1984-1988] = ISU..SX70   Corona [1982-1987] = ST140, ST141   Celica [1983]</div> <div>Insulator Engine [FR]</div>	<div>ARD-2014-January-01</div> <div>ARD Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT11-210</b> <b>12371-22010</b>  <b>KE10</b>   Insulator Engine [RE]	RBI-OLD RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a>	
<b>AT10-22L</b> <b>12302-22011</b>  <b>KE20</b>   Insulator Engine [LH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT10-22R</b> <b>12301-22011</b>  <b>KE20</b>   Insulator Engine [RH]
<b>AT10-23L</b> <b>12302-24010</b>  <b>KE30</b>   Insulator Engine [LH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT10-23R</b> <b>12301-24020</b>  <b>KE30</b>   Insulator Engine [RH]
<b>AT11-230</b> <b>12371-13010</b>  <b>KE20, KE30</b>   Insulator Engine [RE]	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AT10-24L</b> <b>12302-12013</b>  <b>KE70, KP60, KM20, KR12</b>   Insulator Engine [LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT10-24R</b> <b>12301-13020</b>  <b>KE70</b>   Insulator Engine [RH]
<b>AT10-25F</b> <b>12361-15040</b>  Corolla [1983-1987] = AE71, AE86   Insulator Engine	ARD-2014-January-01 ARD Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT11-240</b> <b>12371-13030</b>  Toyota Corolla [1979-1987] = 4K, 4K#..KE70   Insulator Engine [RE, A/T, M/T]
<b>AT10-KF40L</b> <b>12302-13012</b>  Toyota Corolla / Trueno [1974-1981] = 3K#, 4KC..KE3#, KE5#   Insulator Engine [LH]	RBI-2005-October-12 RBI Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT10-KI20L</b> <b>12302-13161</b>  Toyota T.U.V [1996-2007] = 7KE..KF60, KF72, KF8#   Insulator Engine [LH]





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01






<p><b>AT10-430</b> <b>12361-54020</b></p> <p>LN30, RN30</p> <p>Insulator Engine</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT11-430</b> <b>12371-31040</b></p> <p>RN30</p> <p>Insulator Engine [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-440</b> <b>12361-54140</b></p> <p>LN40   Dyna 100 [1985-1995] = LH80   Dyna 150 / Toyoace G15 [1985-2001] = LY20#, LY21#, LY6#   Hilux</p> <p>Insulator Engine</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT11-4X0</b> <b>12371-54050</b></p> <p>LN56, LN106</p> <p>Insulator Engine [RE, LH, A/T, M/T]</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT11-YN61E00</b> <b>12371-35041</b></p> <p>Hilux [1986-1989] = 3YEU..YN61..4FC</p> <p>Insulator Engine [RE, LH, A/T, M/T]</p>  <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-460</b> <b>12361-54110</b></p> <p>LN85</p> <p>Insulator Engine [FR]</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT11-460</b> <b>12371-34030</b></p> <p>LN85, RT104</p> <p>Insulator Engine [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-LN15E1Z</b> <b>12371-05030</b></p> <p>Hilux [2001-2004] = 1KDFTV, 2KDFTV, 2L..KDN145, KDN15#, LN150, LN155</p> <p>Insulator Engine [RE]</p>  <p>PFT-2014-May-25 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	





**TOYOTA**

Revision : 2014-November-01

<p><b>AT10-LJ70E00</b>  <b>12371-35030</b></p> <p>Toyota Land Cruiser [1984-1990] = RJ70, LJ70, 22R 2L</p> <p>Insulator Engine [RE]</p>	<p>ARD-2013-May-01  ARD Product, Ashimori Product    <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT11-YN61E2</b>  <b>12371-35050</b></p> <p>Hilux [1986-1989] = YN10#, YN6#</p> <p>Insulator Engine [RE]</p>
<p><b>AT10-VZN13F0</b>  <b>12361-65010</b></p> <p>Hilux [1988-2004] = VZN130 [3000cc]</p> <p>Insulator Engine [FR]</p>	<p>TN-2010-December-01  Tenacity Product, Ashimori Product    <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-RZN14E00</b>  <b>12371-75050</b></p> <p>Hilux [1997-2001] = RZN147 MT</p> <p>Insulator Engine [RE]</p>	<p>ARD-2013-May-01  ARD Product, Ashimori Product    <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-VJ95R</b>  <b>12361-62110</b></p> <p>Toyota Land Cruiser Prado [1996-1999] = 5VZFE..VZJ9#   Hilux Surf / 4Runner [1995-1998] = 5VZFE..VZN</p> <p>Insulator Engine [FR, LH, RH]</p>	<p>ARD-2013-May-01  ARD Product    <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-KZJ7EA</b>  <b>12371-67030</b></p> <p>Toyota Land Cruiser S/T, H/T [1993-1996] = 1KZTE..KZJ7#</p> <p>Insulator Engine [RE, A/T]</p>	<p>ARD-2013-May-01  ARD Product, HFC Product, Ashimori Product    <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT10-RJ70E00</b>  <b>12371-54100</b></p> <p>Toyota Land Cruiser [1990-1996] = 22R, 2LT, 3L..RJ7#, LJ7#</p> <p>Insulator Engine [RE]</p>
	<p><b>AT10-KZJ7EM</b>  <b>12371-67041</b></p> <p>Toyota Land Cruiser S/T, H/T [1993-1996] = 1KZTE..KZJ7#</p> <p>Insulator Engine [RE, M/T]</p>









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT11-610</b> <b>12371-40020</b></p> <p>Toyota Liteace [1971-1979] = KM1#   Toyota Stout [1979-2000] = RK11#, YK110   RH10, RH20</p> <p>Insulator Engine [RE]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT11-630</b> <b>12371-39025</b></p> <p>RH30</p> <p>Insulator Engine [RE]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT10-640</b> <b>12361-54030</b></p> <p>YH60, LH60</p> <p>Insulator Engine</p>   <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-Y510</b> <b>12361-35050</b>  <b>Y51, Y56, Y60</b>  <b>Insulator Engine [FR, LH, RH] [2.7 Petrol, 3.0 Diesel]</b>	  <small>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT10-Y511</b> <b>12361-54120</b>  <b>LN145 TIGER, LH80</b>  <b>Insulator Engine [FR, LH, RH]</b>	  <small>PFT-2012-June-26 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT11-47XS</b> <b>33183-34030</b>  <b>Toyota Hilux [1997-2005] = LN16#, LN17#, KDN165   Toyota Land Cruiser Prado 90 [1996-1996] = VZJ9#  </b>  <b>Insulator Engine [RE, 4WD]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT10-G10L</b> <b>12362-62050</b>  <b>Granvia / Grand Hiace [1997-2005] = 5VZFE..VCH1#, VCH2#</b>  <b>Insulator Engine [FR, LH] [3.4 Petrol]</b>	  <small>RBI-2012-December-25 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT10-G10R</b> <b>12361-62120</b>  <b>Granvia / Grand Hiace [1997-2005] = 5VZFE..VCH1#, VCH2#</b>  <b>Insulator Engine [FR, RH] [3.4 Petrol]</b>	  <small>RBI-2012-December-25 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT11-640E</b> <b>12303-72010</b>  <b>YH60, LH60</b>  <b>Engine Bushing [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT11-640</b> <b>12303-72010</b>  <b>YH60, LH60</b>  <b>Insulator Engine [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT11-640M</b> <b>12303-72010</b>  <b>YH60, LH60</b>  <b>Insulator Engine [Bracket only] [RE]</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT10-650</b> <b>12361-54143</b>  <b>LH112</b>  <b>Insulator Engine</b>	  <small>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT11-47X</b> <b>12371-YE021</b>  <b>LN111, LN156, TIGER [4WD]</b>  <b>Insulator Engine [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT11-650E</b> <b>12303-54020</b>  <b>YH112, LH112</b>  <b>Engine Bushing [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT11-650</b> <b>12303-54020</b>  <b>YH112, LH112</b>  <b>Insulator Engine [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>





## TOYOTA

Revision : 2014-November-01

<b>AT10-450</b> <b>12361-38060</b> Hiace [1995-2005] = RCH1#, RCH2#   LN50, LN56, YH60, YH50, RZH100, RZH110, RCH11, RX60, YX70, YT140 Insulator Engine [FR, LH, RH] [2.4, 2.7 Petrol]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-KD20D</b> <b>12361-30090</b> Hiace / Regiusace [2005-2010] = KLH1#, KDH2##, LH2## Insulator Engine [FR, LH, RH] [2.7 Petrol] [2.5, Diesel]	RBI-2010-May-10 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-KL10D</b> <b>12361-54220</b> Hiace [1995-2005] = LXH1#, LXH2# Insulator Engine [FR, LH, RH] [2.4, Diesel]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-KD20B</b> <b>12361-75080</b> Hiace [2005-2010] = TRH20#, TRH21#, TRH22# Insulator Engine [FR, LH, RH] [2.5, 3.0, Diesel]	RBI-2010-May-08 RBI Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT11-65D</b> <b>12303-67021</b> Hiace [1989-1995] = LH1##, [2L, 3L, 5L, 5LE] Insulator Engine [RE] [2.4, 2.8, 3.0, Diesel]	PFT-2012-March-28 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-65A</b> <b>12303-67031</b> Hiace [1989-1995] = LH1##, RZH10#, RZH11#, RZH125, RZH135, RZH15#, [2L, 3L, 5L, 5LE, 1RZ, 1RZE, 2RZ, Insulator Engine [RE, A/T] [2.4, 2.8, 3.0, Diesel] [2.0, 2.4, Petrol]	RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT11-65A5Z</b> <b>12303-54030</b> Hiace [1989-1995] = LH1##, RZH10#, RZH11#, RZH125, RZH135, RZH15#, [2L, 3L, 5L, 5LE, 1RZ, 1RZE, 2RZ, Insulator Engine [RE, A/T] [2.4, 2.8, 3.0, Diesel] [2.0, 2.4, Petrol]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-65BZ</b> <b>12303-18020</b> Hiace Van Comuter [1982-1987] = YH51, YH61, LH50, LH51, LH61..2Y, 3Y, 2L   Liteace / Towanace [1981- Insulator Engine [RE, A/T]	Ashimori Product www.rbi.ae
<b>AT11-65AZ</b> <b>12371-72151</b> Hiace [1995-2005] = KLH1#, LXH1#, LXH2#, RCH1#, RCH2# Insulator Engine [RE, A/T, Bracket] [2.4, 2.5 Diesel] [2.4, 2.7 Petrol]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-65MZ</b> <b>12303-54050</b> Hiace [1995-2005] = KLH1#, LXH1#, LXH2#, RCH1#, RCH2# Insulator Engine [RE, M/T, Bracket] [2.4, 2.5 Diesel] [2.4, 2.7 Petrol]	ASH-2014-May-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		<b>AT11-65DMZ</b> <b>12303-54041</b> Hiace [1995-2005] = LH10#, LH11#, LH12#, LH16#, LH17#, LH18#, KZH10#, KZH11#, KZH13# Insulator Engine [RE, M/T, Bracket] [3.0 Diesel]	PFT-2012-June-26 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT11-KD20E</b> <b>12360-75020</b> Toyota Hiace, Regiusace [2005-2013] = KDH20#, KDH21#, KDH22#, KDH2##, TRH20#, TRH21#, TRH22#, TRH2## Engine Bushing [RE] [3.0, Diesel]	RBI-2010-October-01 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-KD200</b> <b>12380-30010</b> Toyota Hiace, Regiusace [2005-2013] = KDH20#, KDH21#, KDH22#, KDH2##, TRH20#, TRH21#, TRH22#, TRH2## Insulator Engine [RE] [2.5, 3.0, Diesel] [2.7 Petrol]	RBI-2010-October-01 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT11-KD20AZ</b> <b>12380-30020</b> Hiace / Regiusace [2005-2010] = KDH205, KDH206, KDH225, KDH227 Insulator Engine [RE, A/T] [2.5, 3.0, Diesel]	PFT-2014-March-25 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-KD20MZ</b> <b>12380-30030</b> Hiace / Regiusace [2005-2010] = KDH205, KDH206 Insulator Engine [RE, M/T] [2.5, 3.0, Diesel]	HFC Product www.rbi.ae

## TOYOTA

Revision : 2014-November-01

<b>AT11-SR40FZ</b> <b>12361-64320</b> Townance/Liteace [1996-2004] = 2C..3CE..CR41, CR42  Insulator Engine [FR]	RBI-2013-October-14 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-SR40EMZ</b> <b>12303-64110</b> Liteace/Townance/Noah [1996-2001] = SR40, SR50  Insulator Engine [RE, M/T, Bracket]	ASH-2012-December-25 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-KM36FL</b> <b>12302-13091</b> Toyota Liteace Van & Wagon [1985-1998] = KM36  Insulator Engine [FR, LH]	Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-KM36FR</b> <b>12301-13090</b> Toyota Liteace Van & Wagon [1985-1998] = KM36  Insulator Engine [FR, RH]	PFT-2014-May-25 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-KR42FL</b> <b>12362-13011</b> Toyota Liteace, Townance Noah, Voxy [1996-1998] = 5K, 7K..KR41, KR42  Insulator Engine [FR, LH]	RBI-2013-July-19 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-KR42FR</b> <b>12361-13030</b> Toyota Liteace, Townance Noah, Voxy [1996-1998] = 5K, 7K..KR41, KR42  Insulator Engine [FR, RH]	RBI-2013-July-19 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-KM30FL</b> <b>12302-13150</b> Toyota Liteace Van & Wagon [1988-1992] = 5K..KM3#  Insulator Engine [FR, LH]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-KM30FR</b> <b>12301-13150</b> Toyota Liteace Van & Wagon [1988-1992] = 5K..KM3#  Insulator Engine [FR, RH]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-LS110FR</b> <b>12361-54012</b></p> <p>Crown [1980-1983] = LS110</p> <p>Insulator Engine [FR, RH]</p>   <p>ARD-2014-January-01 Perfect Product, ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-LS110FL</b> <b>12362-54012</b></p> <p>Crown [1980-1983] = LS110</p> <p>Insulator Engine [FR, LH]</p>   <p>Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-840</b> <b>12361-49026</b></p> <p>Toyota Crown [1974-1983] = 4M, 5M#..MS8#, MS95, MS11#</p> <p>Insulator Engine</p>   <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-880</b> <b>12361-43060</b></p> <p>Toyota Crown [1983-1987] = 5M#, 6MGE..MS12#</p> <p>Insulator Engine [FR]</p>   <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-860</b> <b>12361-41120</b></p> <p>Toyota Crown [1987-1991] = 5M#, 7MGE..MS13#</p> <p>Insulator Engine</p>   <p>RBI-OLD RBI Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT10-870</b> <b>12361-46030</b></p> <p>Toyota Crown [1987-2001] = 1JZGE, 2JZGE...JZS13#</p> <p>Insulator Engine [FR, RH]</p>   <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-870L</b> <b>12362-46020</b></p> <p>Toyota Crown [1987-2001] = 1JZGE, 2JZGE...JZS13#</p> <p>Insulator Engine [FR, LH]</p>   <p>RBI-2009-July-02 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-874RZ</b> <b>12361-46090</b></p> <p>JZS133</p> <p>Insulator Engine [FR, RH]</p>   <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-874LZ</b> <b>12362-46040</b></p> <p>JZS133</p> <p>Insulator Engine [FR, LH]</p>   <p>Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT11-RS80E</b> <b>12371-45011</b>  Crown [1974-1981] = RS80, RS110, MS111, LS110  Insulator Engine [RE]	ARD-2014-January-01 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-880E</b> <b>12371-41070</b>  Crown [83-89] = GS12#, GS13#, MS12#, MS13#  Insulator Engine [RE]	ARD-2014-January-01 ARD Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT11-860</b> <b>12371-70030</b>  Toyota Crown [1987-1991] = 1GFE, 1GG#, 5M#, 7MGE..MS13#, GS13#  Insulator Engine [RE]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-870</b> <b>12371-46011</b>  Toyota Crown, Crown Majesta [1987-2001] = 1JZGE, 2JZGE..JZS13#, JZS14#  Insulator Engine [RE]	RBI-2011-March-21 RBI Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-872F</b> <b>12361-73052</b>  Crown Comfort [1998-2002] = YXS1#, ..3YPE   Corona [1998-1999] = YT140  Insulator Engine [FR]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-872E</b> <b>12371-73021</b>  Crown Comfort [1998-2002] = YXS1#, ..3YPE  Insulator Engine [RE]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-GSX10F00</b> <b>12361-75121</b>  Toyota Crown Comfort [1995-2008] = GXS1#, LXS1#, SXS1#, YXS1#, GBS12, TSS1#..[SED]  Insulator Engine [FR]	TN-2014-May-05 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-GX71FOS</b> <b>12361-35070</b></p> <p>Perfect Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Toyota Mark 2, Chaser, Cresta, Cressida = GX71, Cressida [1989-1996] = MX75, MX8#</p> <p>Insulator Engine [FR, 3.0] [Without Steel]</p>	<p><b>AT10-GX71F</b> <b>12361-35070</b></p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Mark 2, Chaser, Cresta, Cressida = GX71, Cressida [1989-1996] = MX75, MX8#</p> <p>Insulator Engine [FR, 3.0] [Without Steel]</p>
	<p><b>AT10-GX70F2Z</b> <b>12361-70180</b></p> <p>PFT-2014-May-25 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Mark 2, Chaser, Cresta [1988-1989] = 1GFE, 1GGE, GX70, GX81</p> <p>Insulator Engine [FR]</p>
	<p><b>AT10-GX81F</b> <b>12361-35100</b></p> <p>RBI-2008-July-17 RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Cressida [1988-1996] = RX7#, RX8#, GX8#   Cressida Wagon [1988-1993] = RX72</p> <p>Insulator Engine [FR]</p>
<p><b>AT10-SX80F</b> <b>12361-74090</b></p> <p>RBI-2008-October-22 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Mark 2, Chaser, Cresta [1988-1992] = SX80   Crown Comfort / SED [1996] = SXS1#</p> <p>Insulator Engine [FR]</p>	<p><b>AT11-RX60</b> <b>12371-54040</b></p> <p>RBI-2010-December-31 RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Mark 2, Chaser, Cresta [1988-1992] = LX80, SX80   Cressida [1981-1993] = LX60, LX7#, LX80, RX</p> <p>Insulator Engine [RE, A/T]</p>






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-MK292F1Z</b> <b>12360-46050</b> Ashimori Product  Toyota Mark 2, Chaser, Cresta [1992-1996] = 1JZ#, 2JZGE...JZX9#   Toyota Mark 2, Chaser, Cresta [1996] Insulator Engine [FR, LH, RH]	<b>AT09-MK292F2Z</b> <b>12360-46080</b> ARP Product  Toyota Mark 2, Chaser, Cresta [1993-1996] = 1JZGE...JZX93   Toyota Mark 2, Chaser, Cresta [1996-2001] Insulator Engine [FR, LH, RH]
<b>AT09-MK292F3Z</b> <b>12360-70010</b> HFC Product  Toyota Mark 2, Chaser, Cresta [1992-1995] = 1GFE..GX90 Insulator Engine [FR, LH, RH]	<b>AT09-MK292F4Z</b> <b>12360-70030</b> ARP Product  Toyota Mark 2, Chaser, Cresta [1995-1996] = 1GFE..GX90   Toyota Mark 2, Chaser, Cresta [1996-2001] = Insulator Engine [FR, LH, RH]
<b>AT10-SX90FLZ</b> <b>12362-74301</b> Perfect Product  Toyota Mark 2, Chaser, Cresta [1997-2001] = 4SFE..SX100 Insulator Engine [FR, LH]	<b>AT10-SX90FRZ</b> <b>12361-74311</b> Perfect Product  Toyota Mark 2, Chaser, Cresta [1997-2001] = 4SFE..SX100 Insulator Engine [FR, RH]
<b>AT10-SX90FZ</b> <b>12361-74310</b> PFT-2014-October-15 Perfect Product  Toyota Mark 2, Chaser, Cresta [1997-2001] = 4SFE..SX100 Insulator Engine [FR, LH, RH]	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT11-GX100EZ</b> 12371-46070</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Mark 2, Chaser, Cresta [1992-1996] = 1JZ#, 2JZGE...JZX90, JZX91..ATM   Toyota Mark 2, Chaser,</p> <p>Insulator Engine [RE, A/T]</p>	<p><b>AT11-JZX90EMZ</b> 12371-46150</p> <p>PFT-2012-November-07 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Mark 2, Chaser, Cresta [1992-1996] = 1JZGTE...JZX90..MTM</p> <p>Insulator Engine [RE, M/T]</p>
<p><b>AT11-GS151</b> 12371-70050</p> <p>RBI-2011-February-02 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Mark 2, Chaser, Cresta [1992-1996] = 1GFE..GX90..ATM   Toyota Mark 2, Chaser, Cresta [1996-20</p> <p>Insulator Engine [RE, A/T]</p>	<p><b>AT10-GX90EMZ</b> 12371-70060</p> <p>ARD-2013-August-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Mark 2, Chaser, Cresta [1992-1996] = 1GFE..GX90..MTM   Toyota Mark 2, Chaser, Cresta [1996-20</p> <p>Insulator Engine [RE, M/T]</p>
<p><b>AT09-MK292E5AZ</b> 12371-74400</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Mark 2, Chaser, Cresta [1993-1996] = 4SFE..SX90..ATM   Toyota Mark 2, Chaser, Cresta [1997-20</p> <p>Insulator Engine [RE, A/T]</p>	
<p><b>AT11-JZX90EAZ</b> 12371-46140</p> <p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Mark 2, Chaser, Cresta [1992-2001] = JZX90   Crown [1995-2001] = 2JZGE...JZS155..4FC</p> <p>Insulator Engine [RE, A/T] [3.0]</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-MK200F3Z</b> <b>12360-70040</b> Toyota Mark 2, Mark 2 Blit, Verossa [2000-2007] = 1GFE..GX110   Toyota Lexus IS200, IS300 [1999-2005] Insulator Engine [FR] 	<b>AT09-MK200F4Z</b> <b>12361-70230</b> Toyota Mark 2, Mark 2 Blit, Verossa [2000-2007] = 1GFE..GX110   Toyota Lexus IS200, IS300 [1999-2005] Insulator Engine [FR, LH, RH] 












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-GS3093F1Z</b> <b>12360-46040</b>  Toyota Aristo [1991-1997] = 2JZ#...JZS147   Toyota Lexus GS300 [1993-1997] = 2JZGE...JZS147..RHD  Insulator Engine [FR, LH, RH]	HFC-2014-November-20 HFC Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-GS3093F2Z</b> <b>12360-46090</b>  Toyota Lexus GS300 [1993-1997] = 2JZGE...JZS147..LHD  Insulator Engine [FR, LH, RH]	HFC-2014-November-20 HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-GS3093F3Z</b> <b>12360-46130</b>  Toyota Aristo [1995-1997] = 2JZGTE...JZS147  Insulator Engine [FR, LH, RH]	HFC-2014-November-20 HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-GS3093F4Z</b> <b>12361-50050</b>  Toyota Aristo [1992-1997] = 1UZFE...UZS143  Insulator Engine [FR, LH, RH] [4.0 Petrol]	HFC-2014-November-20 HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT09-GS3093F5Z</b> <b>12361-50060</b>  Toyota Aristo [1992-1997] = 1UZFE...UZS143  Insulator Engine	HFC-2014-November-20 HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT09-GS3093E1Z</b> <b>12371-46050</b>  Toyota Aristo [1991-1997] = 2JZ#...JZS147   Toyota Lexus GS300 [1993-1997] = 2JZGE...JZS147   Toyota M  Insulator Engine [RE]	HFC-2014-November-20 ARD Product, HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT09-GS3093E2Z</b> <b>12371-50050</b>  Toyota Aristo [1992-1997] = 1UZFE...UZS143  Insulator Engine [RE] [4.0 Petrol]	ARD-2015-January-31 ARD Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT09-GS3097F1Z</b> <b>12361-46190</b> Toyota Aristo [1997-2005] = 2JZGE...JZS160, JZS161   Toyota Lexus GS300 / GS400 / GS430 [1997-2005] = Insulator Engine [FR, LH, RH]	 <small>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-GS3097F2Z</b> <b>12361-46200</b> Lexus GS300 [1997-2005] = 2JZGE...JZS160..GCC Insulator Engine [FR, LH, RH]	 <small>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT09-GS3097E2Z</b> <b>12371-50200</b> Toyota Lexus GS300 / GS400 / GS430 [1997-2000] = 1UZFE, 3UZFE..UZS16# Insulator Engine [RE] [4.3, 4.0 Petrol]	 <small>ARD-2015-January-31 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT09-GS3097E1Z</b> <b>12371-46160</b> Toyota Aristo [1997] = 2JZ#...JZS16#   Toyota Lexus GS300 / GS400 / GS430 [1997] = 2JZGE...JZS160 Insulator Engine [RE]	 <small>ARD-2015-January-31 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT09-GS3005F1Z</b> <b>12361-31100</b></p> <p>Toyota Lexus GS300 / GS350 / GS430 / GS460 [2005-2008] = 3GRFE, 3GRFSE..GRS190   Toyota Lexus GS450</p> <p>Insulator Engine [FR, LH, RH]</p>	<p>HFC-2014-November-20 HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-GS3005F3Z</b> <b>12361-31200</b></p> <p>Toyota Lexus GS300 / GS350 / GS430 / GS460 [2005-2011] = 2GRFSE, 3GRFE, 3GRFSE..GRS190, GRS191   Toy</p> <p>Insulator Engine [FR, LH, RH]</p>	<p>HFC-2014-November-20 HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-MK205F1Z</b> <b>12360-0P060</b></p> <p>Toyota Reiz [2005-2010] = 3GRFE, 5GRFE..GRX12#   Toyota Reiz [2010] = 3GRFE, 5GRFE..GRX13#   Toyota</p> <p>Insulator Engine [FR, LH, RH]</p>	<p><b>AT09-MK205F2Z</b> <b>12380-0P010</b></p> <p>HFC Product</p> <p>Toyota Reiz [2005-2010] = 3GRFE, 5GRFE..GRX12#   Toyota Reiz [2010] = 3GRFE, 5GRFE..GRX13#</p> <p>Insulator Engine [FR, LH, RH]</p> <p>HFC Product</p>
<p><b>AT09-MK205F3Z</b> <b>12380-0P050</b></p> <p>Toyota Reiz [2005-2010] = 3GRFE, 5GRFE..GRX12#   Toyota Reiz [2010] = 3GRFE, 5GRFE..GRX13#   Toyota C</p> <p>Insulator Engine [FR, LH, RH]</p>	<p>HFC Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p><b>AT09-GS3005E1Z</b> <b>12371-31070</b></p> <p>Toyota Lexus GS300 / GS350 / GS430 / GS460 [2005-2007] = 2GRFSE, 3GR#, 3UZFE..GRS190, GRS191, UZS190</p> <p>Insulator Engine [RE] [2GRFSE = 3.5] [3GRFSE = 3.0] [3UZFE = 4.3]</p>	<p>ARD-2015-January-31 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-GS3005E3Z</b> <b>12371-31210</b></p> <p>Toyota Lexus GS300 / GS350 / GS430 / GS460 [2007-2008] = 3UZFE..UZS190</p> <p>Insulator Engine [RE]</p>	<p>ARD-2015-January-31 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT09-MK205E1Z</b> <b>12371-0P090</b></p> <p>Toyota Reiz [2005-2010] = 3GRFE, 5GRFE..GRX12#   Toyota Reiz [2010] = 3GRFE, 5GRFE..GRX13#   Toyota</p> <p>Insulator Engine [RE]</p>	<p>HFC-2014-November-20 HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>




# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT09-GS3011E1Z 12371-31270</p> <p>Toyota Lexus GS250 / GS350 / GS450 [2011] = 2ARFSE, 2GRFSE, 4GRFSE.. AWL10, GRL10, GRL11</p> <p>Insulator Engine (RE)</p>	<p>ARD-2015-January-31 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-UCF10FZ</b> <b>12361-50020</b>  Toyota Celsior, Lexus LS400 [1989-2000] = 1UZFE..UCF10, UCF2#  Insulator Engine [FR, LH, RH] [4.0 Petrol]		<b>AT10-UCF10EZ</b> <b>12371-50010</b>  Toyota Celsior, Lexus LS400 [1989-1994] = 1UZFE..UCF1#  Insulator Engine [RE] [4.0 Petrol]	
		<b>AT10-UCF20EZ</b> <b>12371-50060</b>  Toyota Celsior, Lexus LS400 [1994-2000] = 1UZFE..UCF2#  Insulator Engine [RE] [4.0 Petrol]	
<b>AT10-UCF30FZ</b> <b>12361-50170</b>  Toyota Celsior, Lexus LS430 [2000-2003] = 3UZFE..UCF30  Insulator Engine [FR, LH, RH] [4.3 Petrol]			
<b>AT10-UCF30EZ</b> <b>12371-50140</b>  Toyota Celsior, Lexus LS430 [2000-2003] = 3UZFE..UCF3#  Insulator Engine [RE, 5 Speed, A/T] [4.3 Petrol]		<b>AT10-UCF30EZ</b> <b>12371-50170</b>  Toyota Celsior, Lexus LS430 [2003-2006] = 3UZFE..UCF3#  Insulator Engine [RE, 6 Speed, A/T] [4.3 Petrol]	








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-USF40FZ</b> <b>12361-38160</b>  Toyota Celsior, Lexus LS460 [2006-2010] = 1UR#..USF4#  Insulator Engine [FR, LH, RH] [4.6 Petrol]	ARD-2015-January-31 ARD Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT10-USF40F2Z</b> <b>12361-38280</b>  Toyota Celsior, Lexus LS460 [2010-2012] = 1UR#..USF40, USF41  Insulator Engine [FR, LH, RH]	ARD-2015-January-31 ARD Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT10-USF40EZ</b> <b>12371-38050</b>  Toyota Celsior, Lexus LS460 [2006-2009] = 1UR#..USF4#  Insulator Engine [RE] [4.6 Petrol]	ARD-2015-January-31 ARD Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-JZZ31EAZ</b> <b>12371-46020</b> Toyota Lexus SC300 / SC400 [1991-2000] = JZZ31   Supra [1993-1996] = JZA80 Insulator Engine [RE, A/T]	 <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<b>AT10-SXE10FR</b> <b>12360-74140</b> Toyota Altezza, Altezza Gita [1998-2005] = GXE10, SXE10 Insulator Engine [FR]	 <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-BJ40E1Z</b> <b>12371-58010</b></p> <p>Toyota Land Cruiser Van [1980-1984] = 2B, 3B..BJ4#, BJ6#</p> <p>Insulator Engine [RE]</p>  <p>ARD-2013-May-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-FJ55E</b> <b>12371-60071</b></p> <p>Toyota Land Cruiser [69-80] = FJ55</p> <p>Insulator Engine [RE]</p>  <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-L010</b> <b>12361-60022</b></p> <p>Toyota Land Cruiser = FJ40 -FJ42</p> <p>Insulator Engine</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT10-L030</b> <b>12361-61020</b></p> <p>Toyota Land Cruiser [1980-1987] = 2F..FJ40, FJ60</p> <p>Insulator Engine</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-L040</b> <b>12361-61031</b></p> <p>Toyota Land Cruiser [1984-1992] = 3F, 3FE..FJ62, FJ7#</p> <p>Insulator Engine</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-J740</b> <b>12361-58030</b></p> <p>Toyota Land Cruiser [1980-1994] = 13BT, 3B, 2H..BJ60, BJ7#, HJ75</p> <p>Insulator Engine [FR]</p>  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-J740Z</b> <b>12361-58030</b></p> <p>Toyota Land Cruiser = BJ74 -HJ75</p> <p>Insulator Engine [With Bracket, FR]</p>  <p>ARD-2014-January-01 ARD Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>





















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-LHJ40</b> <b>12361-68020</b>  Toyota Land Cruiser 40, 50 [1969-1984] = 2H..HJ47 Insulator Engine  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT10-LHJ70</b> <b>12361-68051</b>  Toyota Land Cruiser = FJ70 Insulator Engine  RBI-OLD RBI Product, Perfect Product, ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT10-HZJ7F</b> <b>12361-17020</b>  Toyota Land Cruiser [1990-2007] = HZJ7#, FZJ7#, HDJ7#, PZJ7# Insulator Engine [FR] [4.5 Petrol] [4.2 Diesel] [Bolt_height = 34mm]  ARD-2013-August-01 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT10-HZJ7E</b> <b>12371-17010</b>  Toyota Land Cruiser [1990-2000] = HZJ7# Insulator Engine [RE, M/T] [4.2 Diesel]  ARD-2013-August-01 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT10-FZJ7E</b> <b>12371-66020</b>  Toyota Land Cruiser [1990-1993] = 1FZF, 1FZFE..FZJ7# Insulator Engine [RE] [4.5 Petrol]  ARD-2013-May-01 ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AT10-HZJ7EMZ</b> <b>12371-17080</b>  Toyota Land Cruiser [1999-2004] = HJ7#..1HZ Insulator Engine [RE, M/T] [4.2 Diesel]  ARD-2015-January-31 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
	<b>AT10-HJ60EMZ</b> <b>12371-68041</b>  Toyota Land Cruiser [1987-1988] = HJ6# Insulator Engine [RE, M/T]  ARD-2013-May-01 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT10-HJ60E1Z</b> <b>12371-68010</b>  Toyota Land Cruiser [1980-1986] = 2H..HJ60 Insulator Engine  Perfect Product www.rbi.ae	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : http://www.rbi.ae http://www.alafuae.com

## TOYOTA

Revision : 2014-November-01

<b>AT10-FJ70FR</b> <b>12361-61050</b> <p style="text-align: right;"><small>Ashimori Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Toyota Land Cruiser [1990-1992] = 3F..FJ7#, FJ8#</p> <p>Insulator Engine [FR, RH] [4.0 Petrol]</p>	<b>AT10-FJ70FL</b> <b>12362-61010</b> <p style="text-align: right;"><small>Ashimori Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Toyota Land Cruiser [1990-1992] = 3F..FJ7#, FJ8#</p> <p>Insulator Engine [FR, LH] [4.0 Petrol]</p>
<b>AT10-FJ60E1Z</b> <b>12371-61020</b> <p style="text-align: right;"><small>PFT-2012-August-30 Perfect Product, Ashimori Product</small> <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Land Cruiser [1980-1986] = FJ60, HJ47, HJ60</p> <p>Insulator Engine [FR]</p>	
	<b>AT10-FJ70EMZ</b> <b>12371-61031</b> <p style="text-align: right;"><small>PFT-2012-August-30 Perfect Product, HFC Product, Ashimori Product</small> <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Land Cruiser [1988-1992] = 3F..FJ6#, FJ7#</p> <p>Insulator Engine [RE, M/T] [4.0 Petrol]</p>
<b>AT10-LJ70EAZ</b> <b>12371-54110</b> <p style="text-align: right;"><small>ARD-2014-May-05 ARD Product</small> <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Land Cruiser [1990-1993] = 2LTE..LJ7#..ATM</p> <p>Insulator Engine [RE, A/T] [3.0 Diesel]</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-HZJ8F</b> <b>12361-17010</b></p> <p>Toyota Land Cruiser [1998-2006] = 1HZ..HZJ105   Toyota Land Cruiser [1990-2006] = HZJ8#, HDJ8#, FZJ8</p> <p>Insulator Engine [FR] [4.2 Diesel]</p>	<p><b>AT10-HZJ8E</b> <b>12371-61050</b></p> <p>Toyota Land Cruiser [1990-2006] = HZJ80, FJ80, FZJ80, HDJ80   Toyota Land Cruiser 100 [1998-2006] =</p> <p>Insulator Engine [RE]</p>
<p><b>AT10-HDJ8F</b> <b>12361-17050</b></p> <p>Toyota Land Cruiser [1995-1998] = 1HDFT..HDJ80</p> <p>Insulator Engine [FR, LH, RH] [4.2 Diesel]</p>	
<p><b>AT10-VDJ7FZ</b> <b>12361-51020</b></p> <p>Toyota Land Cruiser [1998-2007] = 1VDFTV..VDJ7#</p> <p>Insulator Engine [FR] [4.7, 4.5 Petrol, Diesel]</p>	<p><b>AT10-VDJ7EZ</b> <b>12371-17120</b></p> <p>Toyota Land Cruiser [2001-2007] = 1VDFTV, 1HDFTE..VDJ7#, HDJ7#</p> <p>Insulator Engine [RE] [4.2, 4.5 Diesel]</p>








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-HDJ1FZ</b> <b>12361-17070</b> Toyota Land Cruiser [1998-2007] = 1HDT, 1HDFTE..HDJ100 Insulator Engine [FR] [4.7, 4.5 Petrol, Diesel]	 <small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT10-HDJ1EZ</b> <b>12371-66040</b> Toyota Land Cruiser [1998-2007] = 1HDFTE..HDJ100..5F Insulator Engine [RE, 4.2 Diesel]	 <small>ARD-2013-August-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT10-HDJ1E3Z</b> <b>12371-66050</b> Toyota Land Cruiser [1998-2007] = 1HDFTE..HDJ100..4FC Insulator Engine [RE, 4.2 Diesel]	 <small>ARD-2013-August-01 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT10-HDJ1E4Z</b> <b>12371-17140</b> Toyota Land Cruiser [1998-2007] = 1HDFTE..HDJ100..5FC Insulator Engine [RE, 4.2 Diesel]	 <small>ARD-2015-January-31 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT10-UZJ1FZ</b> <b>12361-50120</b> Toyota Land Cruiser [1998-2007] = 2UZFE..UZJ100 Insulator Engine [FR] [4.7, 4.5 Petrol, Diesel]	 <small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT10-UZJ1EZ</b> <b>12371-50081</b> Toyota Land Cruiser [1998-2007] = 2UZFE..UZJ100 Insulator Engine [RE] [4.7 Petrol]	 <small>ARD-2013-August-01 ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT10-FZJ1FZ</b> <b>12361-66040</b> Toyota Land Cruiser [1998-2007] = 1FZFE..FZJ100 Insulator Engine [FR] [4.7, 4.5 Petrol, Diesel]	 <small>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT10-FZJ1EZ</b> <b>12371-66060</b> Toyota Land Cruiser [1998-2007] = 1FZFE..FZJ100 Insulator Engine [RE] [4.5 Petrol]	 <small>ARD-2013-August-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT10-UZJ1E3Z</b> <b>12371-50180</b> Toyota Land Cruiser [1998-2007] = 2UZFE..UZJ100 Insulator Engine [RE, 4.7 Petrol]	 <small>ARD-2013-August-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-GRJ20E</b> <b>12371-31180</b>  Toyota Land Cruiser [2007-2016] = 1GRFE..GRJ200..5F  Insulator Engine [RE, 4.0 Petrol]	ARD-2013-August-01 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-GRJ20E2Z</b> <b>12371-31190</b>  Toyota Land Cruiser [2007-2016] = 1GRFE..GRJ200..5FC  Insulator Engine [RE, 4.0 Petrol]	ARD-2013-August-01 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-GRJ20FLZ</b> <b>12361-31240</b>  Toyota Land Cruiser [2007-2016] = 1GRFE..GRJ200  Insulator Engine [FR, LH, 4.0 Petrol]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-GRJ20FRZ</b> <b>12362-31070</b>  Toyota Land Cruiser [2007-2016] = 1GRFE..GRJ200  Insulator Engine [FR, RH, 4.0 Petrol]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-UZJ20FLZ</b> <b>12361-50250</b>  Toyota Land Cruiser [2007-2016] = 2UZFE..UZJ200  Insulator Engine [FR, LH, 4.7 Petrol]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-UZJ20FRZ</b> <b>12362-50030</b>  Toyota Land Cruiser [2007-2016] = 2UZFE..UZJ200  Insulator Engine [FR, RH, 4.7 Petrol]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-UZJ20E</b> <b>12371-50210</b>  Toyota Land Cruiser [2007-2016] = 2UZFE..UZJ200  Insulator Engine [RE, 4.7 Petrol]	ARD-2013-August-01 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-URJ20EZ</b> <b>12371-38060</b>  Toyota Land Cruiser [2007-2016] = 1URFE..URJ202  Insulator Engine [RE, 4.6 Petrol]	ARD-2015-January-31 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-URJ20FLZ</b> <b>12361-38190</b>  Toyota Land Cruiser [2007-2016] = 1URFE..URJ202  Insulator Engine [FR, LH, 4.6 Petrol]	Perfect Product www.rbi.ae 	<b>AT10-URJ20FRZ</b> <b>12362-38010</b>  Toyota Land Cruiser [2007-2016] = 3URFE..URJ201  Insulator Engine [FR, LH, 4.6 Petrol]	Perfect Product www.rbi.ae 
<b>AT10-VDJ20E1Z</b> <b>12371-51060</b>  Toyota Land Cruiser [2007-2016] = 1VDFTV..VDJ200..5F  Insulator Engine [RE, 4.5 Diesel]	ARD-2015-January-31 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-VDJ20E2Z</b> <b>12371-51070</b>  Toyota Land Cruiser [2007-2016] = 1VDFTV..VDJ200..5FC  Insulator Engine [RE, 4.5 Diesel]	ARD-2015-January-31 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-VDJ20FLZ</b> <b>12361-51030</b>  Toyota Land Cruiser [2007-2016] = 1VDFTV..VDJ200  Insulator Engine [FR, LH, 4.5 Diesel]	Perfect Product www.rbi.ae 	<b>AT10-VDJ20FRZ</b> <b>12362-51010</b>  Toyota Land Cruiser [2007-2016] = 1VDFTV..VDJ200  Insulator Engine [FR, RH, 4.5 Diesel]	Perfect Product www.rbi.ae 
		<b>AT10-VDJ20FR2Z</b> <b>12362-51020</b>  Toyota Land Cruiser [2007-2016] = 1VDFTV..VDJ200  Insulator Engine [FR, RH, 4.5 Diesel]	Perfect Product www.rbi.ae 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-KZH106FR</b> <b>12361-67020</b></p> <p>Hiace Regiusace [1993-2004] = 1KZTE..KZH106, KZH100, KZH110, KZH116, KZH120, KZH126, KZH132, KZH138</p> <p>Insulator Engine [FR, RH] [4WD]</p>	<p>PFT-2012-June-26 Perfect Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 	
<p><b>AT11-KZH10EZ</b> <b>12303-54010</b></p> <p>Liteace [1986-1988] = 3YC..YM4#   Model-F [1988- 1990] = 4YEC..YR31   Hiace Van / Commuter [1986-1987]</p> <p>Insulator Engine [RE]</p>	<p>PFT-2012-June-26 Perfect Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-KZJ9EMZ</b> <b>12371-67060</b>  Toyota Land Cruiser Prado [1996-2002] = 1KZT, 1KZTE..KZJ9#  Insulator Engine [RE, M/T] [3.0 Diesel]	 ARD-2014-May-05 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT10-KZJ9EAZ</b> <b>12371-67020</b>  Toyota Land Cruiser Prado [1996-2002] = 1KZT, 1KZTE..KZJ9#  Insulator Engine [RE, A/T] [3.0 Diesel]	 ARD-2014-May-05 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT10-RZJ9FZ</b> <b>12361-35090</b>  Toyota Land Cruiser Prado [1996-2002] = 3RZF, 3RZFE..RZJ9#  Insulator Engine [FR, LH, RH] [2.7 Petrol]	 PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT10-RZJ9EMZ</b> <b>12371-75030</b>  Toyota Land Cruiser Prado [1996-2002] = 3RZF, 3RZFE..RZJ9#  Insulator Engine [RE, M/T] [2.7 Petrol]	 ARD-2014-May-05 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT10-RZJ9EAZ</b> <b>12371-75040</b>  Toyota Land Cruiser Prado [1996-2002] = 3RZF, 3RZFE..RZJ9#  Insulator Engine [RE, A/T] [2.7 Petrol]	 ARD-2013-August-01 ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT10-VZJ9FZ</b> <b>12361-62160</b>  Toyota Land Cruiser Prado [1996-2002] = 5VZFE..VZJ9#  Insulator Engine [FR, LH, RH] [3.4 Petrol]	 RBI-2013-June-15 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT10-VZJ9EMZ</b> <b>12371-62110</b>  Toyota Land Cruiser Prado [1996-2002] = 5VZFE..VZJ9#  Insulator Engine [RE, M/T] [3.4 Petrol]	 ARD-2014-May-05 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT10-VZJ9EAZ</b> <b>12371-62120</b>  Toyota Land Cruiser Prado [1996-2002] = 5VZFE..VZJ9#  Insulator Engine [RE, A/T] [3.4 Petrol]	 ARD-2014-May-05 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT10-LJ90EZ</b> <b>12371-54160</b>  Toyota Land Cruiser Prado [1996-2002] = 3L..LJ9#  Insulator Engine [RE] [2.8 Diesel]	 ARD-2014-May-05 ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-VCK4EM1Z</b> 12371-62160</p> <p>Tundra [1999-2004] = VCK40</p> <p>Insulator Engine [RE, M/T] [3.4]</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT10-VZN16E1</b> 12371-62080</p> <p>Toyota Tacoma [1995-2004] = 5VZFE..VZN160, VZN170</p> <p>Insulator Engine [RE]</p> <p>ARD-2015-January-31 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT10-VZN16F</b> 12361-62090</p> <p>Toyota 4-Runner Tacoma [1995-1999] = VZN150, VZN160, VZN170</p> <p>Insulator Engine [FR] [3.4]</p> <p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	
<p><b>AT10-UZJ12EZ</b> 12371-50150</p> <p>Toyota 4-Runner [2002-2009] = 2UZFE..UZJ215   Toyota Lexus GX470 [2002-2009] = 2UZFE..UZJ120</p> <p>Insulator Engine [RE, A/T, 5Gear, 4.7 Petrol]</p> <p>ARD-2015-January-31 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-RZJ12FZ</b> <b>12361-75071</b></p> <p>Toyota Land Cruiser Prado [2002-2009] = 3RZFE, 2TRFE..RZJ12#, TRJ12#</p> <p>Insulator Engine [FR, LH, RH] [2.7 Petrol]</p>	<p><b>AT10-RZJ12EZ</b> <b>12371-75140</b></p> <p>Toyota Land Cruiser Prado [2002-2009] = 3RZFE, 2TRFE..RZJ12#, TRJ12#..5F</p> <p>Insulator Engine [RE, M/T] [2.7 Petrol]</p>
<p><b>AT10-RZJ12EAZ</b> <b>12371-75180</b></p> <p>Toyota Land Cruiser Prado [2002-2014] = 3RZFE, 2TRFE..RZJ12#, TRJ12#, TRJ150..4FC</p> <p>Insulator Engine [RE, A/T] [2.7 Petrol]</p>	<p><b>AT10-RZJ12E3Z</b> <b>12371-75160</b></p> <p>Toyota Land Cruiser Prado [2009-2014] = 3RZFE, 2TRFE..TRJ150..5F</p> <p>Insulator Engine [RE, M/T] [2.7 Petrol]</p>
<p><b>AT10-GRJ12FZ</b> <b>12361-31081</b></p> <p>Toyota Land Cruiser Prado [2002-2014] = 1GRFE..GRJ12#, GRJ15#</p> <p>Insulator Engine [FR, LH, RH] [4.0 Petrol]</p>	
<p><b>AT10-GRJ12EZ</b> <b>12371-31050</b></p> <p>Toyota Land Cruiser Prado [2002-2009] = 1GRFE..GRJ12#</p> <p>Insulator Engine [RE] [4.0 Petrol]</p>	<p><b>AT10-GRJ15EZ</b> <b>12371-0P140</b></p> <p>Toyota Land Cruiser Prado [2009-2014] = 1GRFE..GRJ15#</p> <p>Insulator Engine [RE] [4.0 Petrol]</p>











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT10-KDJ12FZ</b> <b>12361-30141</b>  Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2002-2009] = 1KDFTV..KDJ12# Insulator Engine [FR, LH, RH] [3.0 Diesel]	<b>AT10-KDJ12F2Z</b> <b>12361-30120</b>  Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2009-2014] = 1KFTV..KDJ150 Insulator Engine [FR, LH, RH] [3.0 Diesel]
<b>AT10-KZJ12FZ</b> <b>12361-67030</b>  PFT-2012-June-26 Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2002-2014] = 1KZTE..KZJ120 Insulator Engine [FR, LH, RH]	
<b>AT10-KDJ12EAZ</b> <b>12371-30080</b>  ARD-2014-May-05 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2002-2009] = 1KDFTV, 1KZTE..KDJ12#, KZJ12#..4FC Insulator Engine [RE, A/T] [3.0 Diesel]	<b>AT10-KDJ12EMZ</b> <b>12371-30090</b>  ARD-2014-May-05 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2002-2009] = 1KDFTV, 1KZTE..KDJ12#, KZJ12#..5FC Insulator Engine [RE, M/T] [3.0 Diesel]
<b>AT10-KDJ15EAZ</b> <b>12371-30060</b>  ARD-2014-May-05 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2009-2014] = 1KDFTV, 1KZTE..KDJ15#..4FC Insulator Engine [RE, A/T] [3.0 Diesel]	<b>AT10-KDJ15EMZ</b> <b>12371-30070</b>  ARD-2014-May-05 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2009-2014] = 1KDFTV, 1KZTE..KDJ15#..5FC Insulator Engine [RE, M/T] [3.0 Diesel]
	<b>AT10-LJ12EZ</b> <b>12371-54200</b>  ARD-2014-May-05 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Land Cruiser Prado [2002-2014] = 5LE..LJ12#, LJ15# Insulator Engine [RE] [3.0 Diesel]













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT10-VG020</b> <b>12361-0L030</b></p> <p>Toyota Hilux Vigo [2005] = LAN15, LAN25, LAN35</p> <p>Insulator Engine [FR, LH, RH] [2WD, 4WD] [With Clip]</p>   <p>RBI-2007-August-20 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT10-KUN15F0</b> <b>12361-30080</b></p> <p>Toyota Hilux Vigo [2005] = 1KDFTV, 2KDFTV..KUN15, KUN2#</p> <p>Insulator Engine [FR, LH, RH] [2WD, 4WD] [With Clip]</p>   <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT10-LAN15F0</b> <b>12361-54250</b></p> <p>Toyota Fortuner [2006] = LAN50..5LE</p> <p>Insulator Engine [FR, LH, RH] [2WD, 4WD] [With Out Clip]</p>   <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT10-VG02B</b> <b>12305-0C011</b></p> <p>Toyota Hilux Vigo [2005] = KUN1#, KUN26, KUN36..5LE</p> <p>Insulator Engine [FR, LH, RH] [2WD, 4WD] [With Out Clip]</p>   <p>RBI-2010-October-01 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT10-VG02BLZ</b> <b>12306-0C011</b></p> <p>Toyota Hilux Vigo [2005] = KUN1#, KUN26, KUN36..5LE</p> <p>Insulator Engine [FR, LH] [With Bracket]</p> <p>Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	<p><b>AT10-VG02BRZ</b> <b>12305-0C011</b></p> <p>Toyota Hilux Vigo [2005] = KUN1#, KUN26, KUN36..5LE</p> <p>Insulator Engine [FR, RH] [With Bracket]</p> <p>Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT11-VG020</b> <b>12371-0C120</b></p> <p>Toyota Hilux [2005-2011] = 2TRFE..TGN26..4FC</p> <p>Insulator Engine [RE, 2.7 Petrol, A/T, 4-Speed]</p>	<p>RBI-2008-August-23 RBI Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT11-VG030</b> <b>12371-0L030</b></p> <p>Toyota Hilux [2004-2013] = 1KDFTV, 2KDFTV..KUN16,15, 35, 36..5F, 5FC</p> <p>Insulator Engine [RE, 2.5, 3.0 Diesel, M/T, A/T, 5-Speed]</p>	<p>RBI-2008-April-02 RBI Product, Perfect Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p><b>AT11-VG032</b> <b>12371-05020</b></p> <p>Toyota Hilux Vigo [2005-2010] = 5LE..LAN15, LAN35..SA</p> <p>Insulator Engine [RE]</p> <p>Perfect Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT11-VG050</b> <b>12371-0L050</b></p> <p>Toyota Hilux [2004-2011] = 1KDFTV, 2KDFTV..KUN16..4FC, 5FC</p> <p>Insulator Engine [RE, 3.0, 2.0 Diesel, M/T, A/T 4, 5-Speed]</p>	<p>RBI-2008-April-02 RBI Product, Perfect Product, HFC Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p><b>AT11-VG070</b> <b>12371-0C070</b></p> <p>Toyota Hilux [2004-2012] = 2KDFTV, 1TRFE, 2TRFE..KUN10, TGN1#, 36..5F</p> <p>Insulator Engine [RE, 2.5 Diesel, 2.0, 2.7 Petrol, M/T, 5-Speed]</p> <p>RBI-2008-April-02 RBI Product, Perfect Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT11-VG080</b> <b>12371-0L080</b></p> <p>Toyota Hilux [2004-2012] = 1KDFTV, 2KDFTV..KUN2#..4FC, 5F</p> <p>Insulator Engine [RE, 2.5, 3.0 Diesel, A/T, M/T, 4, 5-Speed]</p>	<p>RBI-2008-August-23 RBI Product, Perfect Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p><b>AT11-VG090EZ</b> <b>12371-0C090</b></p> <p>Toyota Hilux [2005-2011] = 2TRFE..TGN16, 36..4FC</p> <p>Insulator Engine [RE, 2.7 Diesel, A/T, 4-Speed]</p> <p>Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<b>AT11-VGN25E2Z</b> <b>12371-0P080</b>  Toyota Hilux [2005-2011] = 1GRFE..GGN25..5FC  Insulator Engine [RE, 4.0 Petrol, A/T, 5-Speed]
<b>AT11-VGN25E3Z</b> <b>12371-0P071</b>  Toyota Hilux [2005-2013] = 1GRFE..GGN25..5F  Insulator Engine [RE, 4.0 Petrol, M/T, 5-Speed]	<b>AT11-VGN25E4Z</b> <b>12371-05040</b>  Toyota Hilux [2005-2013] = 5LE..LAN25  Insulator Engine [RE, 3.0 Diesel]
	<b>AT11-VGN26E4Z</b> <b>12371-0C111</b>  Toyota Hilux [2005-2015] = 2TRFE..TGN26..5F  Insulator Engine [RE, 2.7 Petrol, M/T, 5-Speed]





**TOYOTA**

Revision : 2014-November-01

<b>AT10-910</b> <b>12361-49036</b> Toyota Crown [1974-1979] = RS80, MS8#, MS95   Toyota Crown [1979-1983] = GS11#, LS11#, MS11#, RS110 Insulator Engine	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-910</b> <b>12371-44011</b> BU10, JU10 Insulator Engine [RE]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-920</b> <b>12361-59035</b> BU10 Insulator Engine	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-920</b> <b>12371-56010</b> BU10 Insulator Engine [RE]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-930</b> <b>12361-58010</b> Dyna Coaster [82-88] = BB2#, BB3#, [3B] Insulator Engine [FR]	ARD-2014-January-01 Perfect Product, ARD Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT11-930</b> <b>12371-59025</b> Toyota Coaster [1977-1982] = RB1#, BB1#   Toyota Coaster [1982-1993] = RB2#, BB2#, BB3#, HB3#, FB30, Insulator Engine [RE]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-B61L</b> <b>12362-56010</b> BU61 [13B] Insulator Engine [FR, LH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-B61R</b> <b>12361-56070</b> BU61 [13B] Insulator Engine [FR, RH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT11-B61Z</b> <b>12371-56041</b> BU16 Insulator Engine [RE]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT10-B75F</b> <b>12361-58040</b> Dyna [1984-1988] = BU75, BU76, BU85, BU86, WU9#, [14B]   Dyna 200 [1987-1997] = BU7#, BU8#, BU9#, BU Insulator Engine [FR, LH, RH]	PFT-2012-March-28 Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT10-B75E</b> <b>12371-58040</b> Dyna Coaster [1985-1993] = BU2#, BU3#, RB2#, [14B, 3B, 22R] Insulator Engine [RE]	ARD-2014-January-01 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT10-LH5F</b> <b>12361-71020</b> Dyna [1987-1995] = YH81   HIACE [1987-1995] = LH513R, YM30, YM31, YM40, YR31 Insulator Engine [FR]	Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT10-B40E</b> <b>12371-17040</b> Dyna Coaster [93-99] = BB4#, BB5#, [14B, 15BFT, 3B] Insulator Engine [RE]	Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA






Revision : 2014-November-01

<b>AT10-RYN0F</b> <b>12361-78110</b>  RYNO   Dyna [1999-2000] = XZU302  Insulator Engine	<small>RBI-2006-May-01 RBI Product, Ashimori Product</small> <small>shabbirh@eim.ae</small>  <small>www.rbi.ae</small> <small>www.alafuae.com</small>	<b>AT10-RYN0EZ</b> <b>12371-78010</b>  RYNO   Dyna [1999-2000] = XZU302  Insulator Engine [RE]	<small>HFC Product, Ashimori Product</small> <small>www.rbi.ae</small>



**TOYOTA**

Revision : 2014-November-01

<p><b>AT13-SV20F</b>  <b>48609-32030</b></p> <p>Camry Vista [1986-1991] = SV2#, CV2#, VZV2#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>TN-2010-December-01  Tenacity Product, HFC Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-SV20E</b>  <b>48750-32040</b></p> <p>Camry Vista [1986-1991] = SV2#, CV20, VZV21</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>	<p>TN-2010-December-01  Tenacity Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-SV30F</b>  <b>48609-32100</b></p> <p>Camry Vista [1991-1994] = CV30, SV3#, VZV3#   Mark II, Chaser = YX70, RX7#, GX71, MX7#, LX7#, LX80,</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-2008-February-02  RBI Product, Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-CV40F</b>  <b>48609-32150</b></p> <p>Camry Vista [1994-1998] = CV40, SV40, SV41, SV42</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-2009-January-27  RBI Product, Perfect Product, HFC Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-CV40ER</b>  <b>48750-32150</b></p> <p>Camry Vista [1994-1998] = CV4#, SV4#</p> <p>Shock Absorber Mounting [RE, RH]</p>	<p><b>AT13-CV40EL</b>  <b>48760-32150</b></p> <p>Camry Vista [1994-1998] = CV4#, SV4#</p> <p>Shock Absorber Mounting [RE, LH]</p>
<p><b>AT13-SV50F00</b>  <b>48609-32170</b></p> <p>Vista, Vista Ardeo [1998-2003] = AZV50, SV50, ZZV50</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>ARP Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-C02F</b> <b>48609-33011</b></p>  <p>Camry [1991-1996] = SXV1#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-C02FZ</b> <b>48609-33010</b></p>  <p>Toyota CAMRY 2.0, 3.0 [ASMT01017+ABRTO1001] [1992-1994]</p> <p>Shock Absorber Mounting + Bearing [SET]</p>
<p><b>AT13-C02F02</b> <b>48609-33050</b></p>  <p>Camry, Windom, Scepter [JPP/SED] [1992-1997] = SXV1#, VCV1#, SXV10, VCV10...JPP..RHD</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	
<p><b>AT13-MCV10F</b> <b>48609-07010</b></p>  <p>Camry [1991-1996] = MCV10, MCV20, VCV10 [3000cc]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-VCV10F</b> <b>48609-33070</b></p>  <p>Camry [JPP/SED/NAP/WG] [1994-1997] = SXV10, VCV10...JPP..LHD, MCV10, SXV1#, NAP..WG</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p><b>AT13-C02E00</b> <b>48750-32070</b></p>  <p>Camry [1991-1996] = SXV1#, MCV10, VCV10</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>	
<p><b>AT13-C02ER</b> <b>48750-06020</b></p>  <p>Camry [1991-1996] = SXV1#, MCV10, VCV10</p> <p>Shock Absorber Mounting [RE, RH]</p>	<p><b>AT13-C02EL</b> <b>48760-06020</b></p>  <p>Camry [1991-1996] = SXV1#, MCV10, VCV10</p> <p>Shock Absorber Mounting [RE, LH]</p>



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-C03R</b> <b>48603-06020</b>  Camry [1996-2001] = SXV2#  Shock Absorber Mounting [FR, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-C03L</b> <b>48609-06070</b>  Camry [1996-2001] = SXV2#  Shock Absorber Mounting [FR, LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-LE01L</b> <b>48609-33121</b>  Camry [1996-2001] = SXV2#, MCV20   Avalon [1996-2000] = MCX10, MCX20   Camry Gracia [1996-2001] = MC  Shock Absorber Mounting [FR, LH]	RBI-2009-February-03 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-LE01R</b> <b>48603-33021</b>  Camry [1996-2001] = SXV2#, MCV20   Avalon [1996-2000] = MCX10, MCX20   Camry Gracia [1996-2001] = MC  Shock Absorber Mounting [FR, RH]	RBI-2009-February-03 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-LE01LZ</b> <b>48609-33121</b>  Camry [1996-2001] = SXV2#, MCV20   Avalon [1996-2000] = MCX10, MCX20   Camry Gracia [1996-2001] = MC  Shock Absorber Mounting + Bearing [SET] [FR, LH]	Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-LE01RZ</b> <b>48603-33021</b>  Camry [1996-2001] = SXV2#, MCV20   Avalon [1996-2000] = MCX10, MCX20   Camry Gracia [1996-2001] = MC  Shock Absorber Mounting + Bearing [SET] [FR, RH]	Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-MCV20FR</b> <b>48603-33040</b>  Camry [1996-1999] = MCV20, SXV20  Shock Absorber Mounting [FR, RH]	PFT-2013-October-10 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-MCV20FL</b> <b>48609-33140</b>  Camry [1996-1999] = MCV20, SXV20  Shock Absorber Mounting [FR, LH]	PFT-2013-October-10 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-C03EZ</b> <b>48750-33020</b>  Camry [1996-2001] = SXV2#, MCV20  Shock Absorber Mounting [RE, LH, RH, With Out Lock] [Complete With Rubber]	TN-2010-December-26 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT13-C03ER</b> <b>48750-06040</b>  Camry [1996-2001] = SXV2#, MCV20  Shock Absorber Mounting [RE, RH, With Out Lock]	RBI-2009-December-14 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-C03EL</b> <b>48760-06040</b>  Camry [1996-2001] = SXV2#, MCV20  Shock Absorber Mounting [RE, LH, With Out Lock]	RBI-2009-December-14 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-RX303EL</b> <b>48760-48040</b>  Toyota Harrier, Lexus RX300, RX330, RX350, RX400H [2000-2008] = ACU3#, MCU3#, MHU38, GSU3#   Toyota  Shock Absorber Mounting [RE, LH] [Complete With Rubber]	PFT-2014-March-25 Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-RX303ER</b> <b>48750-48040</b>  Toyota Harrier, Lexus RX300, RX330, RX350, RX400H [2000-2008] = ACU3#, MCU3#, MHU38, GSU3#   Toyota  Shock Absorber Mounting [RE, RH] [Complete With Rubber]	PFT-2014-March-25 Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-C04F</b> <b>48609-33170</b></p>  <p>Toyota Camry [2001-2006] = ACV3#, MCV3#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-C04FB</b> <b>48158-06040</b></p>  <p>Toyota Camry [2001-2006] = ACV3#, MCV3#</p> <p>Shock Absorber Mounting Bearing Only [FR, LH, RH]</p>
<p><b>AT13-RX303F</b> <b>48609-48010</b></p>  <p>Toyota Harrier [2003-2012] = ACU3#, MCU3#, GSU3#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-RX304F</b> <b>48609-48020</b></p>  <p>Toyota Highlander, Kluger [2000-2007] = ACU2#, MCU2#, MHU2#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p><b>AT13-MCV30F00</b> <b>48609-06100</b></p>  <p>Toyota Avalon [2005-2012] = GSX30</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-MCV30FZ</b> <b>48609-06100</b></p>  <p>Toyota CAMRY 2.0, 3.0 [ASMT01023+ABRTO1002] [2000-2006]</p> <p>Shock Absorber Mounting + Bearing [SET]</p>
<p><b>AT13-C04EZ</b> <b>48750-06090</b></p>  <p>Camry [2002-2006] = ACV30, ACV31, MCV30</p> <p>Shock Absorber Mounting [RE, LH, RH, With Out Lock] [Complete With Rubber]</p>	
<p><b>AT13-C04ER</b> <b>48750-33100</b></p>  <p>Camry [2002-2006] = ACV30, ACV31, MCV30   Estima / Previa / Tarago [1999-2004] = ACR30, ACR40, CLR30</p> <p>Shock Absorber Mounting [RE, RH, With Out Lock]</p>	<p><b>AT13-C04EL</b> <b>48760-33100</b></p>  <p>Camry [2002-2006] = ACV30, ACV31, MCV30   Estima / Previa / Tarago [1999-2004] = ACR30, ACR40, CLR30</p> <p>Shock Absorber Mounting [RE, LH, With Out Lock]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-C05F</b> <b>48609-06230</b>  Camry / Aurion [2006-2010] = ACV4#, GSV40   Highlander [2007] = GSU4#  Shock Absorber Mounting [FR, LH, RH]	<b>AT13-C05F2</b> <b>48609-33210</b>  Camry [2006-2009] = ACV40  Shock Absorber Mounting [FR, LH, RH]
<b>AT13-C05F3</b> <b>48609-33190</b>  Camry [2006-2009] = ACV45  Shock Absorber Mounting [FR, LH, RH]	<b>AT13-C05FB</b> <b>90903-63002</b>  Toyota GOA CAMRY 2.2, 3.0 [1997]  Shock Absorber Mounting Bearing Only
<b>AT13-C05FZ</b> <b>48609-06230</b>  Camry / Aurion [2006-2010] = ACV4#, GSV40   Highlander [2007] = GSU4#  Shock Absorber Mounting + Bearing [SET]	
<b>AT13-C06F</b> <b>48609-06280</b>  Camry [2011] = ASV50, AVV50, GSV50  Shock Absorber Mounting [FR, LH, RH]	
<b>AT13-GSV40F00</b> <b>48609-48040</b>  HighLander [2007-2009] = GSU4#  Shock Absorber Mounting [FR, LH, RH]	<b>AT13-GSV50F00</b> <b>48609-06300</b>  Camry [2011] = GSV50  Shock Absorber Mounting [FR, LH, RH]
<b>AT13-GSX30F</b> <b>48609-07020</b>  Avalon [2005] = GSX30  Shock Absorber Mounting [FR, LH, RH]	
<b>AT13-C05ER</b> <b>48750-06120</b>  Camry / Aurion [2006-2010] = ACV4#, GSV40   Highlander [2007] = GSU4#  Shock Absorber Mounting [RE, RH, With Lock]	<b>AT13-C05EL</b> <b>48760-06120</b>  Camry / Aurion [2006-2010] = ACV4#, GSV40   Highlander [2007] = GSU4#  Shock Absorber Mounting [RE, LH, With Lock]














# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-90F</b> <b>48680-14010</b></p>  <p>Carina [1970-1975] = TA1#   TT131, 2T</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p><b>AT13-06F</b> <b>48609-14040</b></p>  <p>Toyota Carina [1970-1977] = TA1#   Toyota Carina [1977-1981] = TA4#   Toyota Celica [1977-1981] = TA</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p><b>AT13-08F</b> <b>48609-20220</b></p>  <p>Toyota Carina 2 &amp; Corona [1987-1992] = AT17#, ST17#, CT17#, ET176</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-08E</b> <b>48750-20050</b></p>  <p>Corona / Carina / Caldina [1987-1999] = ST171, AT190, CT190, ST19#, ST215</p> <p>Shock Absorber Mounting [RE, LH, RH] [Screw 24mm]</p>
	<p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 














# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-10F</b> <b>48609-20281</b></p>  <p>ST190, AT190</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-CT190E</b> <b>48750-21020</b></p>  <p>Corona / Carina / Caldina [1987-1999] = ST171, AT190, CT190, ST19#, ST215</p> <p>Shock Absorber Mounting [RE, LH, RH] [Screw 25mm]</p>
<p><b>AT13-CT196F00</b> <b>48609-20381</b></p>  <p>Toyota Caldina [1992-1996] = CT196, CT198, ET196</p> <p>Shock Absorber Mounting [FR, RH]</p>	<p><b>AT13-CT197F00</b> <b>48609-21010</b></p>  <p>Toyota Caldina [1996-2002] = CT196, CT197, CT198, CT199, ET196, ST198</p> <p>Shock Absorber Mounting [RH]</p>
<p><b>AT13-11F</b> <b>48609-20410</b></p>  <p>ST191 Exsior</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-11E</b> <b>48750-21040</b></p>  <p>Corona / Carina / Caldina [1987-1999] = ST171, AT190, CT190, ST19#, ST215</p> <p>Shock Absorber Mounting [RE, LH, RH] [Screw 30mm]</p>
<p><b>AT13-12F</b> <b>48609-20440</b></p>  <p>ST191 Exsior</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	
<p><b>AT13-10E2</b> <b>48750-20140</b></p>  <p>Carina FF [1992-1994] = AT19#, CT19#, ST19#</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>	<p><b>AT13-10E3</b> <b>48750-20100</b></p>  <p>Carina FF / Caldina / Corona [1992-1996] = AT19#, CT19#, ST195</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-TE94F</b> <b>48609-20401</b></p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Celica [1993-1998] = ST202, ST204, ST20#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-TE94F2</b> <b>48609-20240</b></p> <p>TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Toyota CELICA = 4AFE, 5SFE, 3SGTE, , AT180, ST18*, ST28* [1986-1993]   Celica [1990-1993] = ST183,</p> <p>Shock Absorber Mounting [FR]</p>
<p><b>AT13-TE94EL</b> <b>48072-20061</b></p> <p>TN-2011-August-27 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Celica [1993-1998] = ST202, ST204, ST20#</p> <p>Shock Absorber Mounting [RE, LH]</p>	<p><b>AT13-TE94ER</b> <b>48071-20151</b></p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Celica [1993-1998] = ST202, ST204, ST20#</p> <p>Shock Absorber Mounting [RE, RH]</p>
<p><b>AT13-TE94E1LZ</b> <b>48072-20040</b></p> <p>ARP Product www.rbi.ae</p> <p>Carina ED [1993-1999] = ST20#   Celica [1993-1999] = AT200, ST20#   Corona EXIV [1993-1998] = ST20#</p> <p>Shock Absorber Mounting [RE, LH]</p>	<p><b>AT13-TE94E1RZ</b> <b>48071-20140</b></p> <p>ARP Product www.rbi.ae</p> <p>Carina ED [1993-1999] = ST20#   Celica [1993-1999] = AT200, ST20#   Corona EXIV [1993-1998] = ST20#</p> <p>Shock Absorber Mounting [RE, RH]</p>
<p><b>AT13-TE94E2LZ</b> <b>48072-20020</b></p> <p>ARP Product www.rbi.ae</p> <p>Carina ED [1989-1993] = ST18#   Celica [1989-1993] = AT180, ST18#   Celica [1989-1993] = ST185.. [4W</p> <p>Shock Absorber Mounting [RE, LH]</p>	<p><b>AT13-TE94E2RZ</b> <b>48071-20080</b></p> <p>ARP Product www.rbi.ae</p> <p>Carina ED [1989-1993] = ST18#   Celica [1989-1993] = AT180, ST18#   Celica [1989-1993] = ST185.. [4W</p> <p>Shock Absorber Mounting [RE, RH]</p>












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-CXM1F00</b> <b>48609-44010</b> Ipsum [1996-1998] = CXM10, SXM1# Shock Absorber Mounting [FR, LH, RH]	PFT-2012-December-31 Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT13-ACM1F00</b> <b>48609-44020</b> Ipsum [1998] = CXM10, SXM1#   Nadia [1998] = ACN1#, SXN1#   Gaia [1998-2001] = ACM1#, CXM10, SXM15 Shock Absorber Mounting [FR, LH, RH]	PFT-2012-December-31 Perfect Product, HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT13-ACM2F00</b> <b>48609-44040</b> Ipsum [2001] = ACM2#   Noah / Voxy [2001-2004] = AZR6#   Picnic / Avensis Verso [2001-2005] = ACM2#, Shock Absorber Mounting [FR]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT13-AZT22F</b> <b>48609-05010</b> Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZYT22#   Corona [1997-2003] = AT220, CT22 Shock Absorber Mounting [FR, LH, RH]	Tenacity Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT13-AZT24F</b> <b>48609-21030</b> Caldina [2002-2005] = AZT24#, ST24#, ZYT24#   ISIS [2004-2009] = ANM1#, ZNM1#   Scion TC [2004] = AN Shock Absorber Mounting [FR, LH, RH]	TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT13-AZT25F</b> <b>48609-05040</b> Avensis [2003-2006] = AZT250, AZT251, AZT255, ADT250, ADT251, CDT250, ZYT25#   Corolla VERSO [2004] Shock Absorber Mounting [FR, LH, RH]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT13-ZYT25F</b> <b>48609-05030</b> Avensis [2003-2006] = AZT250, AZT251, AZT255, ADT250, ADT251, CDT250, ZYT25#   Corolla VERSO [2004] Shock Absorber Mounting [FR, LH, RH]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-21F</b> <b>48680-12011</b>  <b>KE10</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT13-22F</b> <b>48609-12030</b>  <b>KE20</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT13-23F</b> <b>48609-12050</b>  <b>KE30</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT13-24F</b> <b>48609-16010</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT13-24L</b> <b>48609-12100</b>  <b>KE70</b>  <b>Shock Absorber Mounting [FR, LH]</b>	 <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT13-24R</b> <b>48603-12010</b>  <b>Shock Absorber Mounting [FR, RH]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT13-24Z1</b> <b>48609-12010</b>  <b>KE70</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT13-24Z2</b> <b>48609-12130</b>  <b>KE70</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT13-25F</b> <b>48609-20060</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT13-25E</b> <b>48750-12020</b>  <b>Shock Absorber Mounting [RE, LH, RH]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT13-SV10E00</b> <b>48750-32010</b>  <b>Shock Absorber Mounting [RE]</b>	 <small>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT13-26F</b> <b>48609-12151</b>  <b>Shock Absorber Mounting [FR, LH, RH]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-28F</b> <b>48609-12190</b></p> <p>EE90, AE92</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT13-28E00</b> <b>48071-12030</b></p> <p>Toyota COROLLA [1988-2000] = EE92, AE92</p> <p>Shock Absorber Mounting</p>  <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT13-30F</b> <b>48609-12270</b></p> <p>AE101, EE100</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT13-31F</b> <b>48609-12330</b></p> <p>AE110, AE111</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT13-312F</b> <b>48609-12250</b></p> <p>AE110, AE111</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT13-313F</b> <b>48609-12350</b></p> <p>AE110, AE111</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT13-32F</b> <b>48609-12370</b></p> <p>AE112 [HI-Torque]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT13-30EL</b> <b>48072-12130</b></p> <p>EE90, AE92, EE100, AE101, AE111, AE112</p> <p>Shock Absorber Mounting [RE, LH]</p>  <p>RBI-2008-October-08 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT13-30ER</b> <b>48071-12130</b></p> <p>EE90, AE92, EE100, AE101, AE111, AE112</p> <p>Shock Absorber Mounting [RE, RH]</p>  <p>RBI-2008-October-08 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>



**TOYOTA**

Revision : 2014-November-01

<b>AT13-Z121F</b> <b>48609-12420</b>  Corolla / Altis [2001-2007] = ZZE12# Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-Z141F</b> <b>48609-02220</b>  Corolla / Altis [2007] = ZZE14# Shock Absorber Mounting [FR, LH, RH]	RBI-2009-October-03 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-Z142F</b> <b>48609-12520</b>  Corolla Axio / Fielder [2006-2010] = NZE14#, ZR14#..HTWC Shock Absorber Mounting [FR, LH, RH]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-Z143F</b> <b>48609-02210</b>  Corolla / Altis [2007] = ZZE14# Shock Absorber Mounting [FR, LH, RH]	TN-2013-September-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-Z151F00</b> <b>48609-12500</b>  Auris [2006] = NZE154, ZRE154.. [4WD]   Auris [2006] = ZZE150, NZE151   Blade [2006] = AZE154.. [4WD] Shock Absorber Mounting [FR, LH, RH]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-Z121E00</b> <b>48750-02050</b>  Toyota COROLLA [2003-2008] Shock Absorber Mounting	TN-2014-February-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-W11F</b> <b>48609-13010</b>  Toyota Wish [2003-2009] = ANE1#, ZNE1#   Toyota Wish [2003-2009] = ZNE14.. [4WD] Shock Absorber Mounting [FR, LH, RH]	RBI-2009-September-16 RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-W11E</b> <b>48750-68020</b>  Toyota Wish [2003-2009] = ANE1#, ZNE1#   Toyota Wish [2003-2009] = ZNE14.. [4WD] Shock Absorber Mounting [RE, LH, RH]	ARD-2014-January-01 ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-ZGE20F00</b> <b>48609-0M010</b>  Toyota Wish [2009] = ZGE2#   Toyota Wish [2009] = ZGE25.. [4WD] Shock Absorber Mounting [FR]	TN-2013-November-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT13-ZGE20EL</b> <b>48760-0M020</b>  Toyota Wish [2009] = ZGE2#   Toyota Wish [2009] = ZGE25.. [4WD] Shock Absorber Mounting [RE, LH]	TN-2013-November-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-ZGE20ER</b> <b>48750-0M020</b>  Toyota Wish [2009] = ZGE2#   Toyota Wish [2009] = ZGE25.. [4WD] Shock Absorber Mounting [RE, RH]	TN-2013-November-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-Z121EB</b> <b>48750-02020</b>  Corolla / Altis [2001-2007] = ZZE12# Shock Absorber Mounting Rubber [RE, Big]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-Z121ES</b> <b>48755-02020</b>  Corolla / Altis [2001-2007] = ZZE12# Shock Absorber Mounting Rubber [RE, Small]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT13-Z141ES</b> <b>48755-02030</b>  Corolla Altis [2001-2006] = ZZE122 Shock Absorber Mounting Rubber [RE, Small]	Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT13-Z121ELZ</b> <b>48403-32010</b>  Corolla / Altis [2001-2007] = ZZE12# Shock Absorber Mounting [RE, LH]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-Z121ERZ</b> <b>48401-32020</b>  Corolla / Altis [2001-2007] = ZZE12# Shock Absorber Mounting [RE, RH]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT13-Z14ELZ</b> <b>48403-02050</b>  Corolla / Altis [2007] = ZZE14# Shock Absorber Mounting [RE, LH]	ARD-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-Z14ERZ</b> <b>48401-02060</b>  Corolla / Altis [2007] = ZZE14# Shock Absorber Mounting [RE, RH]	ARD-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT13-Z14EL3Z</b> <b>48403-02060</b>  Corolla / Altis [2007] = ZZE14# Shock Absorber Mounting [RE, LH]	TN-2013-September-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-Z14ER3Z</b> <b>48401-02070</b>  Corolla / Altis [2007] = ZZE14# Shock Absorber Mounting [RE, RH]	TN-2013-September-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-OPAF00</b> <b>48609-63010</b>  Toyota OPA [2000-2005] = ZCT1#, ACT1# Shock Absorber Mounting [FR, LH, RH]	<b>AT13-RUM1F00</b> <b>48609-46010</b>  Raum [1997-2003] = EXZ10   Raum [1997-2003] = EXZ15.. [4WD] Shock Absorber Mounting [FR, LH, RH]
<b>AT13-J122F00</b> <b>48609-87707</b>  Toyota Cami [1999-2005] = J100E, J102E, J122E   Daihatsu Terios [1997-2006] = J100, J111 Shock Absorber Mounting [FR, LH, RH]	<b>AT13-J100F00</b> <b>48609-87403</b>  Toyota Cami [1999-2005] = J100E, J102E, J122E   Daihatsu Terios [1997-2006] = J100, J111   Daihatsu
<b>AT13-J102F00</b> <b>48609-87J12</b>  Toyota Cami [1999-2005] = J100E, J102E, J122E   Daihatsu Terios [1997-2006] = J100, J111 Shock Absorber Mounting [FR, LH, RH]	
<b>AT13-CHA86F00</b>  Daihatsu CHARADE 1.0 [1986-1994] Shock Absorber Mounting	
<b>AT13-SOC90E00</b>  Daihatsu SOCIAL 1.3 [1990-1995] Shock Absorber Mounting	<b>AT13-SOC90F00</b> <b>48609-87102</b>  Daihatsu Charade [1990-1995]   Daihatsu Social [1990-1995] Shock Absorber Mounting [FR, LH, RH, 1.3 Petrol]
<b>AT13-SOC90F02</b> <b>48609-87206</b>  Daihatsu Charade [1990-1995]   Daihatsu Social [1990-1995] Shock Absorber Mounting [FR, LH, RH, 1.3 Petrol]	
<b>AT13-M101FB</b> <b>48619-97201</b>  Daihatsu Boon [2004-2010] = M300   Daihatsu Boon [2004-2010] = M310.. [4WD]   Daihatsu Cuore [2005] Shock Absorber Mounting Bearing Only	
<b>AT13-F60F00</b> <b>48609-BZ010</b>  AVanza [2003] = F601, F602 [USA] Shock Absorber Mounting [FR, LH, RH]	











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-UCF10B00</b> <b>48674-50030</b>  HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Toyota Celsior, Lexus LS400 [1992-1994] = UCF1#   Century [1992-1997] = VG45..4HC Strut Bar Mounting	<b>AT13-UCF10B02</b> <b>48677-50030</b>  HFC Product www.rbi.ae Toyota Celsior, Lexus LS400 [1989-1994] = UCF1# Shock Absorber Mounting
<b>AT13-UCF10E00</b> <b>48755-50020</b>  ARP Product www.rbi.ae Toyota Celsior, Lexus LS400 [1989-1994] = UCF10 Shock Absorber Mounting [RE, LH, RH]	<b>AT13-UCF10F00</b> <b>48680-50040</b>  HFC-2014-November-20 HFC Product www.rbi.ae Toyota Celsior, Lexus LS400 [1989-1994] = UCF1# Shock Absorber Mounting [FR, LH, RH]
<b>AT13-UCF20E00</b> <b>48755-50080</b>  ARP Product www.rbi.ae Toyota Celsior, Lexus LS400 [1994-2000] = UCF20 Shock Absorber Mounting [RE, LH, RH]	<b>AT13-UCF20F00</b> <b>48680-50090</b>  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Toyota Celsior, Lexus LS400 [1994-2000] = UCF20 Shock Absorber Mounting [FR, LH, RH]





**TOYOTA**

Revision : 2014-November-01

<b>AT13-95F</b> <b>48609-10060</b>  Starlet [1984-1989] = EP70, EP7#, NP7# Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-EP80F</b> <b>48609-10090</b>  Starlet [1989-1998] = EP80, EP81, EP8#, NP80 Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT13-RP85F</b> <b>48609-18010</b> Starlet / Sera [1990-1995] = EP85, EXY10 Shock Absorber Mounting [FR, LH, RH]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT13-XT08F00</b> <b>48609-16040</b>  Tercel [1982-1988] = AL20 Shock Absorber Mounting [FR, LH, RH]	TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-EP81F</b> <b>48609-10080</b> Starlet [1989-1998] = EP80, EP81, EP8#, NP80 Shock Absorber Mounting [FR, LH, RH]	Ashimori Product www.rbi.ae
<b>AT13-XT09F00</b> <b>48609-16100</b>  Corsa / Tercel / Corolla 2 / Paseo [1988-1994] = EL3#, NL30, EL4#, NL40 Shock Absorber Mounting [FR]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-XT09F20</b> <b>48609-16090</b>  Corsa / Tercel / Corolla 2 / Paseo [1988-1994] = EL3#, NL30, EL4#, NL40 Shock Absorber Mounting [FR]	TN-2011-August-30 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT13-XT09F30</b> <b>48609-16060</b>  Corsa / Tercel / Corolla 2 / Paseo [1988-1994] = EL3#, NL30, EL4#, NL40 Shock Absorber Mounting [FR]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-XT09F40</b> <b>48609-16160</b>  Corsa / Tercel / Corolla 2 / Paseo [1988-1994] = EL3#, NL30, EL4#, NL40 Shock Absorber Mounting [FR]	TN-2012-March-06 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT13-95E</b> <b>48750-10010</b>  Starlet [1984-1989] = EP70, EP7#, NP7# Shock Absorber Mounting [RE, LH, RH]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT13-EP80E</b> <b>48750-10040</b> Starlet [1989-1998] = EP80, EP81, EP8#, NP80 Shock Absorber Mounting [RE, LH, RH]	ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT13-XT09E00</b> <b>48750-16040</b>  Corsa / Tercel / Corolla 2 / Paseo [1988-1994] = EL3#, NL30, EL4#, NL40   Starlet [1986-1989] = EP71 Shock Absorber Mounting [RE]	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		

**TOYOTA**

Revision : 2014-November-01

<p><b>AT13-S01F</b>  <b>48609-16220</b></p> <p>Soluna [1996-1997] = AL50   Starlet [1996-1999] = EP9#, NP90   TERCEL [1994-1996] = EL53   CORSA / T</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-OLD  RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-S01FR0</b>  <b>48609-16310</b></p> <p>Soluna [1997-1999] = AL50   TERCEL [1996-1999] = EL53, EL53   Corolla 2 [1996-1999] = EL53, NL50   C</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-OLD  RBI Product, Perfect Product, Tenacity Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p><b>AT13-S01FL0</b>  <b>48609-16280</b></p> <p>Soluna [1997-1999] = AL50   TERCEL [1996-1999] = EL53, EL53   Corolla 2 [1996-1999] = EL53, NL50   C</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p><b>AT13-S01E00</b>  <b>48750-16100</b></p> <p>Tercel [1994-1999] = EL5#</p> <p>Shock Absorber Mounting [RE]</p>	<p>TN-2010-December-01  Tenacity Product, HFC Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p><b>AT13-S01E</b>  <b>48750-0A020</b></p> <p>Soluna [1996] = AL50</p> <p>Shock Absorber Mounting [RE]</p>
<p><b>AT13-NC91E</b>  <b>48755-0D100</b></p> <p>Yaris / Echo / Vios / Soluna Vios [1999-2010] = NCP1#, NCP4#, NCP9#   Yaris [2011] = NCP13#</p> <p>Shock Absorber Mounting Rubber [RE, LH, RH]</p>	<p>RBI-2011-August-23  RBI Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-NC91EZ</b>  <b>48755-52010</b></p> <p>Yaris / Echo / Vios / Soluna Vios [1999-2010] = NCP1#, NCP4#, NCP9#   Yaris [2011] = NCP13#</p> <p>Shock Absorber Mounting Bush [Set] [RE, LH, RH] [SET 3Pcs]</p>	<p>TN-2011-June-03  Tenacity Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p><b>AT13-NC91E0</b>  <b>48752-0D020</b></p> <p>Yaris / Echo / Vios / Soluna Vios [1999-2010] = NCP1#, NCP4#, NCP9#</p> <p>Shock Absorber Mounting Bush [RE]</p>
<p><b>AT13-NC42F</b>  <b>48609-0D080</b></p> <p>Yaris / Echo / Vios / Soluna Vios [1999-2005] = NCP1#, NCP4#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-2005-October-26  RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-NC91F</b>  <b>48609-0D050</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-2012-August-06  RBI Product, Perfect Product, HFC Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT13-NC92F</b>  <b>48609-52100</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>TN-2013-July-16  Tenacity Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p><b>AT13-NC92FZ</b>  <b>48609-52100</b></p> <p>Toyota YARIS 1.5 [ASMT01032+ABRT01003] [2007]</p> <p>Shock Absorber Mounting + Bearing [SET]</p>



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-VG02</b> <b>48609-0K010</b></p> <p>Hilux Vigo [2WD]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2006-April-04 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT13-VG04</b> <b>48609-0K040</b></p> <p>Hilux Vigo [4WD]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2006-April-04 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT13-VZJ95F</b> <b>48609-35030</b></p> <p>Toyota Land Cruiser Prado [1996-2002] = KDJ9#, KZJ9#, RZJ9#, VZJ9#   4Runner [1995-2002] = KZN185, R</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2009-August-31 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT13-GRJ12F</b> <b>48609-60040</b></p> <p>Toyota Land Cruiser Prado [2002-2004] = GRJ120, KDJ120, KDJ121, KZJ120, VZJ121   Toyota Land Cruiser</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2009-August-31 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT13-KDJ12F02</b> <b>48609-60060</b></p> <p>Toyota Land Cruiser Prado [2004] = GRJ120, GRJ121, KZJ120, KDJ120, VZJ121..4FC, 5FC, 6F</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>PFT-2014-October-15 Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT13-KDJ12F00</b> <b>48609-60030</b></p> <p>FJ Cruiser / 4Runner [2002-2009] = GSJ15, KZN215, GRN21#, GRJ12#, KDJ120, LJ12#..5F</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT13-GRJ20F</b> <b>48609-60070</b></p> <p>Toyota Land Cruiser [2007] = GRJ200, UZJ200, VDJ200</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
	<p><b>AT13-KDJ15F02</b> <b>48609-60100</b></p> <p>FJ Cruiser / 4Runner [2009-2014] = GSJ15, GRN28#, GRJ150, KDJ150, LJ150, TRJ15#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT13-UCK3F00</b> <b>48609-0C021</b></p> <p>Tundra / Sequoia [2002-2004] = GSK30, UCK30, UCK35, UCK45, UCK40, VCK30, VCK40,</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>PFT-2014-October-15 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-RX60F</b> <b>48609-22010</b></p> <p>Toyota Mark 2, Chaser, Cresta, Cressida [1976-1985] = RX3#, MX3#, GX5#, GX6#, LX6#, MX51, MX6#, RX6#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-OLD RBI Product, Tenacity Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT13-GX81F</b> <b>48609-22070</b></p> <p>Mark II / Chaser / Cresta [1988-1992] = GX81, MA61, YX70   Crown Comfort [1996-2001] = LXS1#, YXS10</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-2007-October-29 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p><b>AT13-GX80F</b> <b>48609-22080</b></p> <p>Mark II / Chaser / Cresta [1988-1992] = GX8#, JZX8#, MX8#</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p><b>AT13-LXS1EL</b> <b>48750-22041</b></p> <p>Crown Comfort [1996-2001] = LXS1#, YXS10</p> <p>Shock Absorber Mounting [RE, LH]</p>	<p>ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p><b>AT13-LXS1ER</b> <b>48750-22031</b></p> <p>Crown Comfort [1996-2001] = LXS1#, YXS10</p> <p>Shock Absorber Mounting [RE, RH]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-GX90E</b> <b>48755-30040</b></p> <p>Chaser / Cresta / Mark II [1996-2001] = GX90, GX100, JZX100, JZX101, LX100, SX100</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>	<p><b>AT13-GX90F</b> <b>48680-22030</b></p> <p>Mark 2, Chaser, Cresta [1992-1998] = GX100, JZX90, JZX100   Altezza [1998-2000] = GXE10, SXE10</p> <p>Shock Absorber Mounting [FR, RH]</p>
<p><b>AT13-GS151E</b> <b>48755-22020</b></p> <p>Crown / Crown Majesta [1995-2001] = GS151, JZS15#, LS151</p> <p>Shock Absorber Mounting [RE]</p>	<p><b>AT13-GS151F</b> <b>48680-22020</b></p> <p>Chaser / Cresta / Mark II [1996-2001] = GX90, GX100, JZX100, LX100, SX100   Crown / Crown Majesta [1</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p><b>AT13-GS171F00</b> <b>48680-30150</b></p> <p>CROWN / CROWN MAJESTA [1999-2003] = JZS171, JZS175, GS171, JKS175   ORIGIN [2000] = JCG17</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-GX110F00</b> <b>48680-30160</b></p> <p>Brevis [2001-2004] = JCG10   Crown, Crown Majesta [1999-2004] = UZS17#, GS171, JKS175, JZS17#   Mark</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p><b>AT13-JZX110F00</b> <b>48680-22150</b></p> <p>Mark 2 / Mark 2 blit / Verossa [2001-2004] = GX110, JZX110..4WD   Altezza / Altezza Gita [2001] = GX</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	
<p><b>AT13-JZX930FL</b> <b>48680-22060</b></p> <p>Crown, Crown Majesta [1995-2001] = UZS155, JZS153, JZS157.. [4WD]   Mark 2, Chaser, Cresta [1992-199</p> <p>Shock Absorber Mounting [FR, LH] [4WD]</p>	<p><b>AT13-JZX930FR</b> <b>48680-22040</b></p> <p>Crown, Crown Majesta [1995-2001] = UZS155, JZS153, JZS157.. [4WD]   Mark 2, Chaser, Cresta [1992-199</p> <p>Shock Absorber Mounting [FR, RH] [4WD]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT13-GS300F</b> <b>48609-30020</b></p> <p>HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Lexus GS300, GS400, GS430, SC430</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	
<p><b>AT13-GS301F</b> <b>48609-30050</b></p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Lexus GS300, GS400, GS430, SC430</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-GS302F</b> <b>48609-24040</b></p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Lexus GS300, GS400, GS430, SC430</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p><b>AT13-GS303F00</b> <b>48609-30030</b></p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Aristo [1991-1997] = JZS147   Crown, Crown Majesta [1991-1995] = UZS14#, JZS14#, LS141, GS141   Lexu</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p><b>AT13-GS304F00</b> <b>48609-30061</b></p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Crown, Majesta [2003-2008] = GRS18#, UZS18#   Lexus GS430, GS350 [2005-2007] = GRS190   Mark X [2004</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>



**TOYOTA**

Revision : 2014-November-01

<b>AT13-T11F</b> <b>48609-28010</b>  Estima / Emina / Lucida / Previa [1990-1999] = CXR1#, CXR2#, TCR1#, TCR2# Shock Absorber Mounting Upper [FR, LH, RH] [Upper]	RBI-2009-February-18 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-T11F0B</b> <b>48044-28010</b>  Estima / Emina / Lucida / Previa [1990-1999] = CXR1#, CXR2#, TCR1#, TCR2# Shock Absorber Mounting Lower [FR, LH, RH] [Lower]	ARP Product shabbirh@eim.ae www.alafuae.com
<b>AT13-ACR30F00</b> <b>48609-28020</b>  Toyota Estima T, L, Previa, Tarago [1999-2006] = ACR30, ACR40, MCR30, MCR40, CLR30 Shock Absorber Mounting [FR, LH, RH]	PFT-2013-March-10 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-AH20F</b> <b>48609-28040</b>  Estima / Previa / Tarago [2006] = ACR5#, GSR5#   Estima Hybrid [2006] = AHR20 Shock Absorber Mounting [FR, LH, RH]	RBI-2010-June-09 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-RV1F</b> <b>48609-42010</b>  Toyota Rav4 [1994-2005] = SXA1#, ACA2#, CLA2#, ZCA2# Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT13-RV30F</b> <b>48609-42020</b>  Toyota Rav4 [2005-2006] = ACA3#, ALA30, GSA3# Shock Absorber Mounting [FR, LH, RH]	RBI-2010-May-19 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-RV31F</b> <b>48609-42030</b>  Toyota Rav4 [2005-2006] = ACA3#, ALA30, GSA3# Shock Absorber Mounting [FR, LH, RH]	TN-2015-January-15 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT13-RV30F03</b> <b>48609-0R020</b>  Toyota Rav4 / Vanguard [2005-2012] = ACA3#, ALA3#, ASA3#, GSA3#, ZSA3# Shock Absorber Mounting [FR, LH, RH]	HFC-2014-November-20 HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT13-RV30F04</b> <b>48609-0R010</b> HFC Product www.rbi.ae Toyota Rav4 [2005-2012] = ALA3#..China Shock Absorber Mounting [FR, LH, RH]	
<b>AT13-RV40F01</b> <b>48609-42040</b> HFC Product www.rbi.ae Toyota Rav4 [2013-2018] = ASA4#, ALA4#, ZSA4# Shock Absorber Mounting [FR, LH, RH]		<b>AT13-RV40F02</b> <b>48609-42060</b>  Toyota Rav4 [2013-2018] = ASA4#, ALA4#, ZSA4# Shock Absorber Mounting [FR, LH, RH]	HFC Product shabbirh@eim.ae www.alafuae.com
<b>AT13-RV40F03</b> <b>48609-0R030</b> HFC Product www.rbi.ae Toyota Rav4 [2013-2018] = ASA4#, ALA4#, ZSA4# Shock Absorber Mounting [FR, LH, RH]		<b>AT13-RV40F04</b> <b>48609-0R040</b> HFC Product www.rbi.ae Toyota Rav4 [2013-2018] = ASA4#, ALA4#, ZSA4# Shock Absorber Mounting [FR, LH, RH]	








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT13-SW20F</b> <b>48609-17030</b>  MR2 [1989-1993] = SW20  Shock Absorber Mounting [FR, LH, RH]		<b>AT13-SW22F</b> <b>48609-17040</b>  MR2 [1993-1999] = SW20  Shock Absorber Mounting [FR, LH, RH]	
<b>AT13-SW20E</b> <b>48750-17020</b>  MR2 [1989-1991] = SW20  Shock Absorber Mounting [RE, LH, RH]		<b>AT13-SW21E</b> <b>48750-17031</b>  MR2 [1991-1993] = SW20  Shock Absorber Mounting [RE, LH, RH]	
<b>AT13-SW22E</b> <b>48750-17040</b>  MR2 [1993-1999] = SW20  Shock Absorber Mounting [RE, LH, RH]			







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT14-J122F1</b> <b>48331-87402</b></p> <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Shock Absorber Dust Cover [FR]</p> <p>ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	
<p><b>AT14-M101F00</b> <b>48331-87204</b></p> <p>Duet [1998-2004] = M100A, M101A, M110A, M111A   Duet [1998-2004] = M110A.. [4WD]   Daihatsu YRV [200</p> <p>Shock Absorber Dust Cover</p> <p>ARP Product www.rbi.ae</p>	
<p><b>AT14-F60F00</b> <b>48331-BZ010</b></p> <p>Toyota Avanza [2003-2011] = F601, F602</p> <p>Shock Absorber Dust Cover</p> <p>RBI-2014-July-14 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT14-22F 48331-12010</p>  <p>KE20</p> <p>Shock Absorber Bumper [FR]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT14-23F 48331-12030</p>  <p>KE30</p> <p>Shock Absorber Bumper [FR]</p>	<p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT14-07F 48331-20040</p>  <p>ST150, ST171, ST172, ST190</p> <p>Shock Absorber Bumper [FR]</p>	<p>AT14-U07F 48331-20040</p>  <p>ST150, ST171, ST172, ST190</p> <p>MEP-Shock Absorber Bumper [FR]</p> <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT14-ST160E 48341-20090</p> <p>Carina ED / Corona FF COUPE [1987-1989] = ST16#   Celica [1985-1989] = AT160, ST16#, ST182   Corona</p> <p>Shock Absorber Bumper [RE]</p>	<p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT14-08E 48341-20120</p>  <p>ST171</p> <p>Shock Absorber Bumper [RE]</p>	<p>AT14-U08E 48341-20120</p>  <p>ST171</p> <p>MEP-Shock Absorber Bumper [RE]</p> <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT14-28E</b> <b>48341-12130</b>  <b>AE101, AE92, EE90</b>  <b>Shock Absorber Bumper [RE]</b>	 <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<b>AT14-U28E</b> <b>48341-12130</b>  <b>AE101, AE92, EE90</b>  <b>MEP-Shock Absorber Bumper [RE]</b>	 <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<b>AT14-28F</b> <b>48331-12100</b>  <b>EE90, AE80</b>  <b>Shock Absorber Bumper [FR]</b>	 <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 		
<b>AT14-29E</b> <b>48341-12120</b>  <b>AE101</b>  <b>Shock Absorber Bumper [RE]</b>	 <p>RBI-2006-March-15 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<b>AT14-U29E</b> <b>48341-12120</b>  <b>AE101</b>  <b>MEP-Shock Absorber Bumper [RE]</b>	 <p>RBI-2005-December-23 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<b>AT14-29F</b> <b>48331-12120</b>  <b>AE101, ST171, ST191, AT190</b>  <b>Shock Absorber Bumper [FR]</b>	 <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<b>AT14-U29F</b> <b>48331-12120</b>  <b>AE101, ST171, ST191, AT190</b>  <b>MEP-Shock Absorber Bumper [FR]</b>	 <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<b>AT14-11E</b> <b>48341-32052</b>  <b>ST191, ST190, Camry   Camry / Aurion [2006-2010] = ACV40, GSV40   Avalon [1997-2001] = MCX10, MCX20</b>  <b>Shock Absorber Bumper [RE]</b>	 <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<b>AT14-U11E</b> <b>48341-32052</b>  <b>ST191, ST190, Camry   Camry / Aurion [2006-2010] = ACV40, GSV40   Avalon [1997-2001] = MCX10, MCX20</b>  <b>MEP-Shock Absorber Bumper [RE]</b>	 <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : http://www.rbi.ae http://www.alafuae.com

## TOYOTA

Revision : 2014-November-01

<p><b>AT14-30E</b> <b>48550-12070</b></p> <p>AE9#, AE10#, AE10#, EE9#, EE10#, EE11#, CE9#, CE10#, CE11#   Celica [1993-1998] = ST202, ST204, ST20</p> <p>Shock Absorber Dust Cover [RE]</p>	<p>RBI-2008-August-15 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>
<p><b>AT14-30E2</b> <b>48558-12040</b></p> <p>AE9#, AE10#, AE10#, EE9#, EE10#, EE11#, CE9#, CE10#, CE11#   Celica [1993-1998] = ST202, ST204, ST20</p> <p>Shock Absorber Dust Cover [RE]</p>	<p><b>AT14-30E3</b> <b>48558-12080</b></p> <p>AE9#, AE10#, AE10#, EE9#, EE10#, EE11#, CE9#, CE10#, CE11#   Celica [1993-1998] = ST202, ST204, ST20</p> <p>Shock Absorber Dust Cover [RE]</p>
<p><b>AT14-10E0</b> <b>48559-20040</b></p> <p>Corona / Carina / Caldina [1992-1999] = AT19#, ST19#, CT19#, ET19#</p> <p>Shock Absorber Dust Cover [RE]</p>	<p><b>AT14-12E0</b> <b>48754-05010</b></p> <p>AT21#, AT22#, ST21#, ST22#, CT21#, CT22#</p> <p>Shock Absorber Dust Cover [RE]</p>
<p><b>AT14-10F0</b> <b>48157-20130</b></p> <p>Corona / Carina / Caldina [1992-2002] = AT19#, ST19#, ST21#, CT19#, ET19#</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>
<p><b>AT14-30F1</b> <b>48331-12150</b></p> <p>EE100</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>
<p><b>AT14-31F</b> <b>48331-12140</b></p> <p>AE111</p> <p>Shock Absorber Dust Cover [FR]</p>	<p><b>AT14-31E</b> <b>48341-12180</b></p> <p>AE111</p> <p>Shock Absorber Dust Cover [RE]</p>








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT14-ST190E0</b> <b>48341-20280</b></p> <p>Corona / Carina / Caldina [1996-2002] = ST19#, ST21#, AT19#, AT21#, CT19#, CT21#</p> <p>Shock Absorber Dust Cover [RE]</p>	<p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT14-SXM10F</b> <b>48304-44020</b></p> <p>Picnic / Ipsum / Nadia / Gaia [1996-2002] = SXM1#, CXM1#, ACM1#, ACN1#, SXN1#   Corolla / Spacio [19</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  <p><b>AT14-SXM11F</b> <b>48304-44010</b></p> <p>Ipsum [1996-2002] = SXM1#   Corolla / Spacio [1997-2001] = AE11#</p> <p>Shock Absorber Dust Cover [FR]</p>
<p><b>AT14-SXM12F</b> <b>48304-44040</b></p> <p>Toyota Nadia [1998-2003] = ACN10, SXN10   Toyota Nadia [1998-2003] = SXN15.. [4WD]</p> <p>Shock Absorber Dust Cover</p>	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT14-AZT22F01</b> <b>48331-05020</b></p> <p>Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Carina E [1992-1997] = AT19#, ST</p> <p>Shock Absorber Bumper [FR]</p>	<p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><b>AT14-AZT22F02</b> <b>48331-05030</b></p> <p>Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT220, CT22</p> <p>Shock Absorber Bumper [FR]</p>
<p><b>AT14-AZT25E01</b> <b>48341-05030</b></p> <p>Avensis [2003-2008] = ADT25#, AZT25#, CDT250, ZZT25#   Avensis [2003-2008] = AZT255.. [4WD]</p> <p>Shock Absorber Bumper [RE]</p>	<p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><b>AT14-AZT25F01</b> <b>48331-02050</b></p> <p>Avensis [2003-2008] = ADT25#, AZT25#, CDT250, ZZT25#   Avensis [2003-2008] = AZT255.. [4WD]   Coroll</p> <p>Shock Absorber Bumper [FR]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT14-Z121F1</b> <b>48157-02020</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#, ZRE12#, NZE12#, CE12#, CDE12#, NDE12#, ZZ14#, NZE14#, CE14#, Z</p> <p>Shock Absorber Dust Cover [FR, LH, RH]</p>	<p>ASH-2012-December-25 Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT14-ZE121F</b> <b>48331-12210</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Shock Absorber Bumper [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT14-W11F0</b> <b>48331-68020</b></p> <p>Wish [2003] = ANE1#</p> <p>Shock Absorber Bumper [FR]</p>	<p>RBI-OLD RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT14-Z121E0</b> <b>48341-47010</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Shock Absorber Dust Cover &amp; Bumper Set [RE, LH, RH]</p>	<p>RBI-2005-December-23 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT14-W11E1</b> <b>48257-68020</b></p> <p>Wish [2003] = ANE1#</p> <p>Shock Absorber Dust Cover [RE]</p>	<p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p><b>AT14-W11E0</b> <b>48341-32100</b></p> <p>Wish [2003] = ANE1#</p> <p>Shock Absorber Bumper [RE]</p>	<p>RBI-2005-December-03 RBI Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT14-SV41E</b> <b>48341-32090</b></p>  <p>Toyota Camry / Vista [1994-1998] = SV4#, CV4#</p> <p>Shock Absorber Dust Cover [RE, LH, RH]</p> <p>RBI-2008-January-13 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT14-SV41F1</b> <b>48157-32040</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Camry Vista = CV4#, SV4#</p> <p>Shock Absorber Dust Cover [FR, LH, RH]</p>
<p><b>AT14-VG02F00</b> <b>48157-0K010</b></p> <p>Hilux Vigo [2004-2008] = KUN10, KUN15, KUN16, LAN15, GGN15, TGN1#   Innova / Kijan [2005] = KUN40, T</p> <p>Shock Absorber Dust Cover [FR]</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT14-SV41F</b> <b>48331-32090</b></p>  <p>Toyota Camry / Vista [1994-1998] = SV4#, CV4#</p> <p>Shock Absorber Bumper [FR, LH, RH]</p> <p>RBI-2008-February-02 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT14-USV41F</b> <b>48331-32090</b></p>  <p>Toyota Camry / Vista [1994-1998] = SV4#, CV4#</p> <p>MEP-Shock Absorber Bumper [FR, LH, RH]</p> <p>RBI-2008-October-15 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>





**TOYOTA**

Revision : 2014-November-01

<p><b>AT14-C02F1</b>  <b>48157-33020</b></p> <p>Camry [1991-1996] = SXV1#, MCV1#</p> <p>Shock Absorber Dust Cover [FR, LH, RH]</p>	<p>ASH-2012-December-25  Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-C02E1</b>  <b>48257-32060</b></p> <p>Camry [1991-1996] = SXV1#, MCV1#, VCV1#    Camry, Vista [1990-1994] = SV3#, VZV3#, CV30,  SV35.. [4WD]</p> <p>Shock Absorber Dust Cover [RE, LH, RH]</p>	<p>TN-2012-May-14  Tenacity Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p><b>AT14-C02E2</b>  <b>48259-32010</b></p> <p>Camry [1991-1996] = SXV1#, MCV1#, VCV1#    Camry, Vista [1990-1994] = SV3#, VZV3#, CV30,  SV35.. [4WD]</p> <p>Shock Absorber Dust Cover [RE, LH, RH]</p>
<p><b>AT14-C03F1</b>  <b>48157-33030</b></p> <p>Camry [1996-2001] = SXV2#, MCV2#</p> <p>Shock Absorber Dust Cover [FR, LH, RH]</p>	<p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-C03F3</b>  <b>48157-06030</b></p> <p>Camry [1996-2001] SXV20, MCV20</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>ASH-2013-July-10  Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-C03F</b>  <b>48331-33020</b></p> <p>Camry [1996-2001] = SXV2#</p> <p>Shock Absorber Bumper [FR]</p>	<p>RBI-2005-April-22  RBI Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p><b>AT14-UC03F</b>  <b>48331-33020</b></p> <p>Camry [1996-2001] = SXV2#</p> <p>MEP-Shock Absorber Bumper [FR]</p>
<p><b>AT14-C04F0</b>  <b>48331-33031</b></p> <p>Camry [2002-2006] = ACV30, ACV31, MCV30</p> <p>Shock Absorber Bumper [FR]</p>	<p>RBI-2005-May-07  RBI Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p><b>AT14-UC04F</b>  <b>48331-33031</b></p> <p>Camry [2002-2006] = ACV30, ACV31, MCV30</p> <p>MEP-Shock Absorber Bumper [FR, LH, RH]</p>











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : http://www.rbi.ae http://www.alafuae.com

## TOYOTA

Revision : 2014-November-01

<b>AT14-C04F1</b> <b>48157-06060</b>  Camry [2001-2010] = ACV3#, MCV3#, ACV4#, GSV4# Shock Absorber Dust Cover [FR, LH, RH]	<small>ASH-2012-December-25 Tenacity Product, Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT14-C04E1</b> <b>48750-06140</b> Camry [2001-2010] = ACV3#, MCV3#, ACV4#, GSV4# Shock Absorber Dust Cover [RE, LH, RH] [With 15 Rings, Plain Head]	<small>ASH-2014-May-15 Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT14-RX303E00</b> <b>48750-48040</b> Toyota Harrier, Lexus RX300, RX330, RX350, RX400H [2000-2008] = ACU3#, MCU3#, MHU38, GSU3#   Toyota Shock Absorber Dust Cover [RE, LH, RH]	<small>ASH-2014-May-15 Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
<b>AT14-C04ER</b> <b>48750-06120</b> Camry [2001-2010] = ACV3#, MCV3#, ACV4#, GSV4# Shock Absorber Dust Cover [RE, RH] [With 15 Rings, Plain Head]	<small>ASH-2014-May-15 Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT14-C04EL</b> <b>48760-06120</b> Camry [2001-2010] = ACV3#, MCV3#, ACV4#, GSV4# Shock Absorber Dust Cover [RE, LH] [With 15 Rings, Plain Head]	<small>ASH-2014-May-15 Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT14-C06F</b> <b>48331-33070</b>  Toyota Camry / Aurion / Hybrid / HV [2011] = ACV51, ASV50, AVV50, GSV50 Shock Absorber Bumper Bound [FR]	<small>RBI-2014-September-04 RBI Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT14-T11F00</b> <b>48304-28010</b> Estima / Emina / Lucida / Previa [1990-1999] = CXR1#, CXR2#, TCR1#, TCR2# Shock Absorber Dust Cover [FR]	<small>Ashimori Product</small> <small>www.rbi.ae</small>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.




**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA


Revision : 2014-November-01

<p><b>AT14-S01E</b> <b>48341-0A010</b></p>  <p>Soluna   Tercel</p> <p>Shock Absorber Dust Cover [RE]</p>	<p><b>AT14-S01F</b> <b>48331-0A010</b></p>  <p>Soluna   Tercel</p> <p>Shock Absorber Dust Cover [FR]</p>
<p><b>AT14-S01EZ</b> <b>48341-0A010</b></p>  <p>Soluna   Tercel</p> <p>Shock Absorber Dust Cover &amp; Bumper Set [RE, Set, 95, mt cap]</p>	



**TOYOTA**

Revision : 2014-November-01

<p><b>AT14-NC42F1</b>  <b>48157-0D040</b></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>ARP Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-NC42F</b>  <b>48331-0D040</b></p> <p>Toyota Raum [2003-2011] = NCZ2#   Toyota Echo [1999-2005] = NCP12, NCP13   Toyota Platz [1999-2005]</p> <p>Shock Absorber Bumper [FR]</p>	<p>RBI-OLD  RBI Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-NC42E0</b>  <b>48341-0D040</b></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Shock Absorber Dust Cover [RE]</p>	<p>RBI-2008-September-26  RBI Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-NC9F1</b>  <b>48157-0D060</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Shock Absorber Dust Cover [FR]</p>	<p><b>AT14-NC9F2</b>  <b>48157-52010</b></p> <p>Vios [2004-2006] = NCP42</p> <p>Shock Absorber Dust Cover [FR]</p> <p>ASH-2013-November-15  Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-NC9F</b>  <b>48331-52080</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Shock Absorber Bumper [FR]</p>	<p><b>AT14-UNC9F</b>  <b>48331-52080</b></p> <p>Belta [2005] = KSP92, SCP92   Belta [2005] = NCP96.. [4WD]   Belta [2005] = SCP92   Ractis [2005-201</p> <p>MEP-Shock Absorber Bumper [FR]</p> <p>RBI-2013-June-19  RBI Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p>ARP Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT14-NC7E1</b>  <b>48750-52010</b></p> <p>BB, Open Deck [2000-2005] = NCP30   Echo [1999-2005] = NCP12, NCP13   Fun Cargo [1999-2005] = NCP2#</p> <p>Shock Absorber Dust Cover [RE]</p>	<p><b>AT14-NC9E1</b>  <b>48750-0D060</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Shock Absorber Dust Cover [RE]</p> <p>TN-2014-May-05  Tenacity Product, HFC Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  <p>RBI-2014-March-12  RBI Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT14-RV1F1</b> <b>48157-42010</b>  Toyota Rav4 [1994-2005] = SXA1#, ACA2#, CLA2#, ZCA2#  Shock Absorber Dust Cover [FR, LH, RH]	 <small>ASH-2014-May-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT14-RV1F0</b> <b>48331-42010</b>  Toyota Rav4 [1994-2000] = SXA1#  Shock Absorber Bumper [FR, LH, RH]	 <small>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT14-RV1E0</b> <b>48306-42040</b>  Toyota Rav4 [1994-2000] = SXA1#  Shock Absorber Bumper [RE, LH, RH]	 <small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
<b>AT14-RV3F1</b> <b>48157-42020</b>  Toyota Rav4 [2005-2010] = ACA3#, ALA3#, GSA3#  Shock Absorber Dust Cover [FR, LH, RH]	 <small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924  
E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT14-JZ90E</b> <b>48341-30060</b></p>  <p>Mark II, Chaser = JZX90, GX90, 100, SX90, 100, LX90, LX100, JZS15#, GS151</p> <p>Shock Absorber Bumper [RE, LH, RH]</p>	<p>RBI-2007-October-22 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT14-GX110F</b> <b>48331-51010</b></p> <p>Altezza / Altezza Gita [1998-2005] = GXE10, SXE10   Mark 2 / Mark 2 Blit [2000-2004] = GX110, JZX110</p> <p>Shock Absorber Bumper [FR]</p>	<p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p><b>AT14-JZS160E00</b> <b>48257-22070</b></p> <p>Lexus LS430 / Celsior [2000-2006] = UCF30   Mark 2, Chaser, Cresta [1992-2001] = GX90, GX93, GX100,</p> <p>Shock Absorber Dust Cover [FR, RE]</p>	<p>ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924  
E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT17-C02IZ</b> <b>43448-20020</b>  Camry [1991-2001] = SXV1#, SXV20  Drive Shaft Boot [Inner]	 RBI-OLD RBI Product, Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT17-C02UZ</b> <b>43447-20030</b>  Camry [1991-2001] = SXV1#, SXV20  Drive Shaft Boot [Outer]	 RBI-OLD RBI Product, Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT17-C04IZ</b> <b>43448-06120</b>  Camry [2002-2006] = ACV30, ACV31, MCV30  Drive Shaft Boot [Inner]	 RBI-OLD RBI Product, Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT17-C04UZ</b> <b>43447-06120</b>  Camry [2002-2006] = ACV30, ACV31, MCV30  Drive Shaft Boot [Outer]	 RBI-OLD RBI Product, Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT17-C05IZ</b> <b>43448-06350</b>  Camry [2006-2010] = ACV4#  Drive Shaft Boot [Inner]	 RBI-2008-June-05 RBI Product, Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT17-C05UZ</b> <b>43447-06350</b>  Camry [2006-2010] = ACV4#  Drive Shaft Boot [Outer]	 RBI-2008-June-05 RBI Product, Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT17-VZV30UZ</b> <b>04437-17040</b>  Mark II / Chaser [1992-1999] = JZX90, JZX93, JZX100, JZX105   Camry Vista [1990-1992] = VZV30, VZV31  Drive Shaft Boot [Outer]	 ARD-2014-January-01 ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT17-VZV31UZ</b> <b>04437-17030</b>  Mark II / Chaser [1992-1999] = JZX90, JZX93, JZX100, JZX105   Camry Vista [1990-1992] = VZV30, VZV31  Drive Shaft Boot [Outer]	 ARD-2014-January-01 ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT17-07IZ</b> <b>43448-32010</b>  <b>ST150, AT171</b>   <b>Drive Shaft Boot [Inner]</b>	 <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>	<b>AT17-07UZ</b> <b>43447-32021</b>  <b>ST150, AT171</b>   <b>Drive Shaft Boot [Outer]</b>	 <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>
<b>AT17-25IZ</b> <b>43448-12020</b>  <b>AE80</b>   <b>Drive Shaft Boot [Inner]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>	<b>AT17-25UZ</b> <b>43447-17020</b>  <b>Corolla [1983-1988] = EE80, AE8#, CE80   EP70</b>   <b>Drive Shaft Boot [Outer]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>
<b>AT17-08IZ</b> <b>43448-12040</b>  <b>Corona &amp; Carina [1987-1992] = AT17#, ST17#   EE90, AE101</b>   <b>Drive Shaft Boot [Inner]</b>	 <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>	<b>AT17-08UZ</b> <b>43447-17041</b>  <b>Corona &amp; Carina [1987-1992] = AT17#, ST17#   AE92, ST190, AE101</b>   <b>Drive Shaft Boot [Outer]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>
<b>AT17-ST202IZ</b> <b>04438-20160</b>  <b>Corona &amp; Carina &amp; Celica &amp; Curren [1993-1999] = ST202, ST206</b>   <b>Drive Shaft Boot [Inner]</b>	 <small>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>		
<b>AT17-ST205UZ</b> <b>04438-28011</b>  <b>Celica [1994-1999] = ST205   Previa [1990-1999] = TCR1#, TRC2#   Liteace [1986-1988] = YM4#   Model</b>   <b>Drive Shaft Boot [Outer]</b>	 <small>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.rbi.ae.com</small>		




















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT17-ZE121I</b> <b>43448-12120</b>  Corolla / Altis [2001-2007] = ZZE12# Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT17-ZE121U</b> <b>43447-28020</b>  Corolla / Altis [2001-2007] = ZZE12# Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT17-W11IZ</b> <b>43448-28051</b>  Wish [2003] = ANE1# Drive Shaft Boot [Inner]	RBI-2006-December-18 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT17-Z14UZ</b> <b>43447-12050</b>  Corolla / Altis [2007] = ZZE14# Drive Shaft Boot [Outer]	RBI-2011-August-23 RBI Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT17-Z14IZ</b> <b>43448-12130</b>  Corolla / Altis [2007] = ZZE14# Drive Shaft Boot [Inner]	RBI-2011-August-23 RBI Product, Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT17-Z15IZ</b> <b>04437-02290</b>  Auris [2006] = ZZE150, NZE151   Auris, Hybrid [2007] = ADE15#, NDE150, NRE150, ZRE15#, ZZE150, ZWE15 Drive Shaft Boot [Inner]	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT17-Z15UZ</b> <b>04428-02420</b>  Auris [2006] = ZZE150, NZE151   Auris, Hybrid [2007] = ADE15#, NDE150, NRE150, ZRE15#, ZZE150, ZWE15 Drive Shaft Boot [Outer]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>



**TOYOTA**

Revision : 2014-November-01

<b>AT17-4X3IZ</b> <b>43448-35020</b>  <b>LN111 [4WD]</b>  Drive Shaft Boot [Inner]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-4X3UZ</b> <b>43447-35021</b>  <b>LN111 [4WD]</b>  Drive Shaft Boot [Outer]	 RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT17-VG04IZ</b> <b>43448-0K020</b>  <b>Hilux Vigo, Fortuner [4WD]</b>  Drive Shaft Boot [Inner]	 RBI-2007-January-05 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-VG04UZ</b> <b>43447-0K020</b>  <b>Hilux Vigo, Fortuner [4WD]</b>  Drive Shaft Boot [Outer]	 RBI-2007-August-01 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT17-ZJ95IZ</b> <b>43448-35030</b>  <b>Toyota Land Cruiser Prado [1996] = KZJ9#, LJ9#, RZJ9#, VZJ9#   Hilux Tagoma [2004] = KUN25, KUN145</b>  Drive Shaft Boot [Inner]	 RBI-2009-December-12 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-ZJ95UZ</b> <b>43447-35040</b>  <b>Toyota Land Cruiser Prado [1996] = KZJ9#, LJ9#, RZJ9#, VZJ9#   Hilux Vigo [2004] = KUN25, KUN145</b>  Drive Shaft Boot [Outer]	 RBI-2008-June-14 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT17-GRJ12IZ</b> <b>43448-60040</b>  <b>Toyota Land Cruiser Prado [2002] = GRJ12#, KDJ120, KZJ120, LJ12#, RZJ12#, TRJ12#</b>  Drive Shaft Boot [Inner]	 PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-GRJ12UZ</b> <b>43447-60040</b>  <b>Toyota Land Cruiser Prado [2002-2008] = GRJ12#, KDJ120, KZJ120, LJ12#, RZJ12#, TRJ12#</b>  Drive Shaft Boot [Outer]	 PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT17-KDJ15IZ</b> <b>43448-60130</b>  <b>Toyota Land Cruiser Prado [2009-2014] = GRJ15#, KDJ15#, LJ15#, TRJ15#</b>  Drive Shaft Boot [Inner]	 PFT-2013-June-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-KDJ15UZ</b> <b>43447-60130</b>  <b>Toyota Land Cruiser Prado [2009-2014] = GRJ15#, KDJ15#, LJ15#, TRJ15#</b>  Drive Shaft Boot [Outer]	 PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT17-TA10IZ</b> <b>04438-04011</b>  <b>Tacoma [1999-2002] = RZN161, RZN171, VZN170</b>  Drive Shaft Boot [Inner]	 RBI-2010-July-03 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-TA10UZ</b> <b>04438-04021</b>  <b>Tacoma [1999-2002] = RZN161, RZN171, VZN170</b>  Drive Shaft Boot [Outer]	 RBI-2010-July-03 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT17-UZ10IZ</b> <b>43448-60030</b>  <b>Toyota Land Cruiser 100 / Lexus LX470 [1998-2007] = UZJ100, FZJ100, HDJ100</b>  Drive Shaft Boot [Inner]	 PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-UZ10UZ</b> <b>43447-60030</b>  <b>Toyota Land Cruiser 100 / Lexus LX470 [1998-2007] = UZJ100, FZJ100, HDJ100</b>  Drive Shaft Boot [Outer]	 PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT17-UZ20IZ</b> <b>43448-60090</b>  <b>Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200, GRJ200, URJ201</b>  Drive Shaft Boot [Inner]	 PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT17-UZ20UZ</b> <b>43447-60090</b>  <b>Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200, GRJ200, URJ201</b>  Drive Shaft Boot [Outer]	 PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT17-95IZ</b> <b>43448-10020</b>  EP70  Drive Shaft Boot [Inner]	<div><div>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>		
<b>AT17-XT10I</b> <b>43448-16060</b>  TERCEL  Drive Shaft Boot [Inner]	<div><div>RBI-2009-December-12 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>		
<b>AT17-S01IZ</b> <b>04438-0A020</b>  Soluna  Drive Shaft Boot [Inner]	<div><div>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>	<b>AT17-S01UZ</b> <b>04437-0A020</b>  Soluna  Drive Shaft Boot [Outer]	<div><div>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>
<b>AT17-NC42IZ</b> <b>43448-52020</b>  Vios / Soluna Vios [2002] = NCP4#  Drive Shaft Boot [Inner]	<div><div>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>	<b>AT17-NC42UZ</b> <b>43447-17011</b>  Vios / Soluna Vios [2002] = NCP4#  Drive Shaft Boot [Outer]	<div><div>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>
<b>AT17-YA91IZ</b> <b>43448-0D140</b>  Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#  Drive Shaft Boot [Inner]	<div><div>RBI-2008-June-14 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>	<b>AT17-YA91UZ</b> <b>43447-0D140</b>  Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#  Drive Shaft Boot [Outer]	<div><div>RBI-2008-July-29 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>
<b>AT17-U01UN</b> <b>04428-16010</b>  Honda Accord [1990-1993] = CB1, CB3, CB7   Honda Accord [1994-1998] = CC, CD, CE   Honda Accord [199  Drive Shaft Boot	<div><div>Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div><div></div></div>		





**TOYOTA**

Revision : 2014-November-01

<p><b>AT18-06LZ</b> 45535-22011</p> <p>TT141</p> <p>Steering Gear Boot [LH]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p><b>AT18-06PZ</b> 45535-20010</p> <p>Toyota Celica [1981-1985] = AA63, TA6#, SA6#, RA6#, GA61, MA6#   Toyota Corona [1982-1985] = TT14#,</p> <p>Steering Gear Boot [LH, RH, Power]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p><b>AT18-06RZ</b> 45536-14020</p> <p>Toyota Carina FR / Celica [1981-1988] = TA6#, AA6#, SA6#, RA6#, KA67, CA6#, GA61, MA6#   Toyota Coro</p> <p>Steering Gear Boot [RH]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p><b>AT18-07PZ</b> 45535-20040</p> <p>ST150, AT171</p> <p>Steering Gear Boot [LH, RH, Power]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p><b>AT18-100Z</b> 45535-33010</p> <p>AT190</p> <p>Steering Gear Boot [LH, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p><b>AT18-11PZ</b> 45535-20080</p> <p>ST191 POWER</p> <p>Steering Gear Boot [LH, RH, Power]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p><b>AT18-ACM10R</b> 45535-20170</p> <p>Carina/Corona/Caldina [1995-2001] = AT19#, AT190, AT191, AT210, AT211, AT212, ST190, ST191, ST210,  </p> <p>Steering Gear Boot [RH]</p>	<p>PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		
<p><b>AT18-ACM20LR</b> 45535-44010</p> <p>Ipsum [2001-2007] = ACM2#,   Noah/Voxy [2001-2004] = AZR2#</p> <p>Steering Gear Boot [LH, RH]</p>	<p>PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		
<p><b>AT18-SXM15LR</b> 45535-20290</p> <p>Carina/Corona/Caldina [1995-2001] = ST195, ST198, ST215, CT195, CT198, CT199, CT215, CT216   Ipsum/N</p> <p>Steering Gear Boot [LH, RH]</p>	<p>PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		
<p><b>AT18-AZT22LR0</b> 45535-05020</p> <p>Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT220, CT22</p> <p>Steering Gear Boot</p>	<p>ARP Product www.rbi.ae</p>		



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT18-24LBZ</b> <b>45536-12010</b>  <b>KE70</b>  <b>Steering Gear Boot [LH, Big Diameter]</b>	  <small>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT18-24RBZ</b> <b>45535-12010</b>  <b>KE70</b>  <b>Steering Gear Boot [RH, Big Diameter]</b>	  <small>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT18-24LSZ</b> <b>45536-12011</b>  <b>KE70</b>  <b>Steering Gear Boot [LH, Small Diameter]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT18-24RSZ</b> <b>45535-12011</b>  <b>KE70, AE80, EE90, AT171</b>  <b>Steering Gear Boot [RH, Small Diameter]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT18-25LZ</b> <b>45536-12030</b>  <b>AE80, EE90, AT171</b>  <b>Steering Gear Boot [LH]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT18-27PZ</b> <b>45535-12050</b>  <b>AE92</b>  <b>Steering Gear Boot [LH, RH, Power]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT18-28PZ</b> <b>45535-12040</b>  <b>EE90 POWER</b>  <b>Steering Gear Boot [Power]</b>	  <small>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT18-29PZ</b> <b>45535-12070</b>  <b>COROLLA / COROLLA SPRINTER [1991-2002] = AE10#, EE10#, CE10#, AE11#, EE11#, CE11#, ZZE11#   Rav 4 [1</b>  <b>Steering Gear Boot [LH, RH, Power]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT18-300Z</b> <b>45535-12060</b>  <b>EE100</b>  <b>Steering Gear Boot [LH, RH]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT18-ZE1210</b> <b>45535-52050</b></p> <p>Corolla Asia / S.Africa / S.America / Altis [2001-2007] = ZZE12#   Wish [2003] = ANE1#   Rav 4 [2003]</p> <p>Steering Gear Boot [LH, RH]</p> <p><small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p><b>AT18-ZE1212</b> <b>45535-09040</b></p> <p>Corolla [2000-2008] = CE120, NZE12#, ZZE12#   Corolla [2002-2006] = ZZE121.. [UKP]</p> <p>Steering Gear Boot [LH, RH]</p> <p><small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p><b>AT18-W11LR</b> <b>45535-13010</b></p> <p>Wish [2003] = ANE1#   Corolla Asia / S.Africa / S.AMERICA [2002-2008] = ZZE12#, CDE120   Rav 4 [2003-]</p> <p>Steering Gear Boot [LH, RH]</p> <p><small>RBI-2006-December-18 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	
<p><b>AT18-Z141LR</b> <b>45535-02200</b></p> <p>Corolla / Altis [2007] = ZZE14#</p> <p>Steering Gear Boot [LH, RH]</p> <p><small>ARD-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p><b>AT18-ZE1410</b> <b>45535-09110</b></p> <p>Corolla / Altis [2007] = ZZE14#</p> <p>Steering Gear Boot [LH, RH]</p> <p><small>RBI-2012-November-10 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p><b>AT18-Z142LR</b> <b>45535-29015</b></p> <p>Toyota Corolla / Altis [2007] = AZE14#, CE14#, NDE14#, NZE14#, ZRE14#, ZZE14#</p> <p>Steering Gear Boot [LH, RH]</p> <p><small>Perfect Product www.rbi.ae</small></p>	
<p><b>AT18-RV30LR</b> <b>45535-49025</b></p> <p>Rav 4 / Rav 4 China [2005-2011] = ACA3#, ALA3#, GSA33, ZSA3#</p> <p>Steering Gear Boot [LH, RH]</p> <p><small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT18-CV10Z</b> <b>45535-14011</b>  Camry = CV10 Steering Gear Boot  RBI-OLD RBI Product shabbirh@eim.ae www.alafuae.com	<b>AT18-C031Z</b> <b>45535-8Y001</b>  Camry = SXV20 Steering Gear Boot ARP Product shabbirh@eim.ae www.alafuae.com
<b>AT18-C040</b> <b>45535-06040</b>  Camry [2002-2006] = ACV30, ACV31, MCV30 Steering Gear Boot  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.alafuae.com	
<b>AT18-97Z</b> <b>45535-06080</b>  Camry [2006-2010] = ACV4# Steering Gear Boot [LH, RH, 2.2 Power]  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.alafuae.com	
<b>AT18-C050</b> <b>45535-09080</b>  Camry / Aurion / HV [ARL] [2006-2009] = ACV40, GSV40 Steering Gear Boot [LH, RH]  PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.alafuae.com	<b>AT18-C052</b> <b>45535-33050</b>  Camry [2006] = ACV40, GSV40   Lexus ES240, ES350 [2006] = ACV40, GSV40   Lexus ES350 [2006] = GSV40 Steering Gear Boot  PFT-2014-October-15 Perfect Product shabbirh@eim.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT18-65LZ</b> <b>45536-26010</b>  <b>LH112</b>   Steering Gear Boot [LH]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT18-65RZ</b> <b>45535-26020</b>  <b>LH112</b>   Steering Gear Boot [RH]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT18-VG0L0</b> <b>45536-0K010</b>  <b>Hilux Vigo</b>   Steering Gear Boot [LH]	RBI-2005-August-30 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT18-VG0R0</b> <b>45535-0K010</b>  <b>Hilux Vigo</b>   Steering Gear Boot [RH]	RBI-2005-August-30 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT18-L050</b> <b>45535-35030</b>  <b>Toyota Land Cruiser Prado [1996] = KZJ9#, LJ9#, RZJ9#, VZJ9#</b>   Steering Gear Boot [LH, RH]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT18-65PZ</b> <b>45535-26030</b>  <b>Toyota Land Cruiser Prado [2002] = GRJ12#, KDJ120, KZJ120, LJ12#, RZJ12#, TRJ12#</b>   Steering Gear Boot [LH, RH, Power]	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT18-KDJ15LR</b> <b>45535-69025</b>  <b>Toyota Land Cruiser Prado [2009-2014] = GRJ15#, KDJ15#, LJ15#, TRJ15#</b>   Steering Gear Boot [LH, RH]	PFT-2013-June-25 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT18-UZ10LR</b> <b>45535-60010</b>  <b>Toyota Land Cruiser 100 / Lexus LX470 [1998-2007] = UZJ100, HDJ100</b>   Steering Gear Boot [LH, RH]	PFT-2013-February-15 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT18-UZ20LR</b> <b>45535-60020</b>  <b>Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200, GRJ200, URJ201</b>   Steering Gear Boot [LH, RH]	PFT-2013-February-15 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT18-GX8LR</b> <b>45535-22080</b></p> <p>Lexus LS400 [1994-2000] = UCF20   Cressida [1988-1996] = GX81, LX80, MX8#, RX8#   Century [1998] = G</p> <p>Steering Gear Boot [LH, RH]</p>	<p><b>AT18-UZZ40LR</b> <b>45535-30010</b></p> <p>Lexus SC430 [2001-2005] = UZZ40   Lexus IS200 / IS300 [1999] = GXE10, JCE10   Lexus GS300 / GS430 [1]</p> <p>Steering Gear Boot [LH, RH]</p>
<p><b>AT18-CM30LR</b> <b>45535-27020</b></p> <p>Liteace Van, Wagon [1988-1992] = CM3#, KM3#   Model-F / Van [1988-1990] = YR2#</p> <p>Steering Gear Boot [LH, RH]</p>	
	<p><b>AT18-T11LR</b> <b>45535-28020</b></p> <p>Previa [1990-1999] = TCR1#, TCR2#   Liteace Van, Wagon [1992-2000] = CR2#, YR2#</p> <p>Steering Gear Boot [LH, RH]</p>
	<p><b>AT18-AC30LR</b> <b>45535-28030</b></p> <p>Estima / Previa / Tarago [1999-2005] = ACR30, CLR30   ALPHARD [2002-2005] = MNH10   HIACE [2005] = L</p> <p>Steering Gear Boot [LH, RH]</p>










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT18-95LZ</b> <b>45536-10060</b></p>  <p>Soluna [1996-2003] = AL50   EP71, EP82</p> <p>Steering Gear Boot [LH]</p> <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT18-95RZ</b> <b>45535-10021</b></p>  <p>Soluna [1996-2003] = AL50   EP71, EP82</p> <p>Steering Gear Boot [RH]</p> <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT18-S01PZ</b> <b>45535-10060</b></p>  <p>Toyota Starlet [1989-1999] = EP8#, NP80, EP9#, NP90   Toyota Soluna [1996-2003] = AL50</p> <p>Steering Gear Boot [LH, RH, Power]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT18-NC420</b> <b>45535-02030</b></p>  <p>Vios / Soluna Vios [2002] = NCP4#   Corolla Asia / S.Africa / Altis [2001-2007] = ZZE12#</p> <p>Steering Gear Boot</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT18-NCP35LR</b> <b>45535-52060</b></p>  <p>BB, Open Deck [2003-2005] = NCP35.. [4WD]   Corolla Runx, Allex [2001-2006] = NZE121, ZZE122, ZZE123</p> <p>Steering Gear Boot</p> <p>PFT-2012-November-07 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT20-01E</b> <b>90385-15039</b> Toyota Corona [1973-1998] = RT10#, RT11#, RT130, RT132, TT133, YT140   Toyota Crown [1975-1999] = MS Spring Shackle Rubber [RE]	 RBI-OLD RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-01F</b> <b>90385-13032</b> Toyota Corona [1973-1979] = RT104, RT105, RT116, RT117, RT118   Toyota Crown [1987-1999] = GS136, LS Spring Shackle Rubber [FR]	 RBI-OLD RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT20-04E</b> <b>90385-05001</b> Toyota Corona [1974-1998] = RT10#, RT11#, RT130, RT132, TT133, YT140 Spring Shackle Rubber [RE]	 RBI-OLD RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-04F</b> <b>90385-17069</b> RT100 Spring Shackle Rubber [FR]	 RBI-OLD RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT20-090</b> <b>90389-14035</b> Toyota Carina 2 & Corona [1987-1992] = AT17#, ST17#, CT17#, ET176   Toyota Caldina [1992-2002] = AT1 Spring Shackle Bush	 RBI-OLD RBI Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-ST198001</b> <b>90389-14042</b> Caldina [1992-2002] = CT198, CT199, ST198.. [4WD]   Corolla [1991-2002] = AE109, CE109.. [4WD]   Spr Spring Shackle Bush [RE]	 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT20-22E</b> <b>90385-10015</b> KE20   Toyota 1000 & Publica [1969-1988] = UP3#, KP3#, KP50   Toyota Land Cruiser [1980-1987-1990-19 Spring Shackle Rubber [RE]	 RBI-OLD RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-22F</b> <b>90385-10014</b> KE20   Toyota 1000 & Publica [1969-1988] = UP3#, KP3#, KP50 Spring Shackle Rubber [FR]	 RBI-OLD RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT20-23E</b> <b>90385-13071</b> Toyota Corolla / Trueno [1974-1981] = KE3#, KE5#, TE3#, TE47, TE51   Toyota Carina [1977-1981] = TA4 Spring Shackle Rubber [RE]	 RBI-OLD RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-23F</b> <b>90385-13065</b> Toyota Corolla / Trueno [1974-1981] = KE3#, KE5#, TE3#, TE47, TE51 Spring Shackle Rubber [FR]	 RBI-OLD RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT20-250</b> <b>90389-12001</b> Toyota Corolla [1979-1987] = AE71E, KE7#, AE7#, TE7#, CE7# Spring Shackle Bush	 RBI-OLD RBI Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT20-420</b> <b>90385-18046</b></p> <p>Hilux [1979-1999] = LN106, LN56, RN30, RN40, RN20, LN20   Dyna [1985-2001] = LH80, LY100   Deliboy [</p> <p>Spring Shackle Rubber</p>   <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT20-420U</b> <b>90385-18046</b></p> <p>Hilux [1979-1999] = LN106, LN56, RN30, RN40, RN20, LN20   Dyna [1985-2001] = LH80, LY100   Deliboy [</p> <p>Spring Shackle Rubber [RE]</p>   <p>www.rbi.ae</p>
<p><b>AT20-421</b> <b>90385-18002</b></p> <p>Town / MasterRace [1976-1979] = TR11, 15</p> <p>Spring Shackle Rubber [RE]</p>   <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT20-460</b> <b>90385-18013</b></p> <p>LN85</p> <p>Spring Shackle Rubber</p>   <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p><b>AT20-47XE</b> <b>90385-18020</b></p> <p>LN111, TIGER</p> <p>Spring Shackle Rubber [RE]</p>   <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT20-4X1E</b> <b>90385-18007</b></p> <p>LN106, LN65</p> <p>Spring Shackle Rubber</p>   <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT20-620</b> <b>90385-18058</b></p> <p>Toyota Hiace [1977-1985] = RH11, RH2#, RH3#, RH42, LH11, LH20, LH30</p> <p>Spring Shackle Rubber</p>   <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT20-650</b> <b>90389-14007</b>  <b>LH112, LH60, TIGER</b>   Spring Shackle Bush	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT20-65E</b> <b>90385-18008</b>  <b>LH112</b>   Spring Shackle Rubber [RE]	RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT20-92E</b> <b>90385-18025</b>  <b>Toyota Dyna, Toyoace [1977-1984] = BU2#, BU3#, BU4#, BU5#, RU2#, RU3#, JU20, HU26, HU30, HU40, HU50,</b> Spring Shackle Rubber [RE]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT20-92F</b> <b>90385-23037</b>  <b>BU</b>   Spring Shackle Rubber [FR]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT20-BU6FS</b> <b>90385-16005</b>  <b>Dyna / Dyna 150 [1985-1987-1995-2001-2006] = BU6#, BU7#, BU8#, LY6#, LY21#, YY5#, YY6#, YY21#</b> Spring Shackle Rubber [FR]	ARD-2014-January-01 Perfect Product, ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT20-B61F</b> <b>90389-16002</b>  <b>BU61, BU20</b>   Spring Shackle Bush [FR]	RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT20-B61E01</b> <b>90389-16013</b>  <b>Dyna 200 [1995-2002] = BU111, BU211   Dyna 200 [1988-1995] = BU61, BU84   Dyna 200 / Toyoace G25 [19</b> Spring Shackle Bush [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT20-BB40E01</b> <b>90389-16015</b>  <b>Toyota Coaster [1993-2004] = BB4#, BB5#, BB#, BZB40, BZB50, BZB#, HDB5#, HZB40, HZB50, HZB#, RZB40,</b> Spring Shackle Bush	PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT20-BU100F00</b> <b>90385-23002</b>  <b>Dyna 200, Toyoace G25 [1995-2000] = BU1##, 2##, RZU100, 140, XZU130, 140</b> Spring Shackle Bush	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT20-AE71</b> <b>90389-14034</b>  <b>Corolla [1991-2002] = AE71, AE10#, CE10#, EE10#, EE105.. [4WD]   Sprinter [1991-2002] = AE10#, CE10#</b> Spring Shackle Bush	RBI-OLD RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT20-BJ40F</b> <b>90385-15016</b>  Toyota Land Cruiser = BJ40 Spring Shackle Rubber [FR, RE]	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-AT196</b> <b>90385-15005</b>  Caldina = AT196 Spring Shackle Rubber	RBI-2009-December-12 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT20-L01B</b> <b>90385-18009</b>  Toyota Land Cruiser [1984-1990] = HJ75 Spring Shackle Rubber [Big]	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-L01BU</b> <b>90385-18009</b> Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> Toyota Land Cruiser [1984-1990] = HJ75 Spring Shackle Rubber [RE]	
<b>AT20-L01S</b> <b>90389-18002</b>  Toyota Land Cruiser [1980-1990] = HJ75, HJ47 Spring Shackle Rubber [FR, Small]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT20-L01SU</b> <b>90389-18002</b> Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> Toyota Land Cruiser [1980-1990] = HJ75, HJ47 Spring Shackle Rubber [FR, Small]	
<b>AT20-L01A1</b> <b>90385-18022</b>  Toyota Land Cruiser [1993-2004] = HZJ7#, PZJ70 Spring Shackle Rubber [RE]	RBI-2014-April-18 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT20-L01A2</b> <b>90385-18021</b>  Toyota Land Cruiser [1999-2004] = HZJ7# Spring Shackle Rubber [RE] [Short]	RBI-2014-April-18 RBI Product, HFC Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT20-VG02F</b> <b>90385-T0003</b></p> <p>Toyota Hilux [2004-2012] = GGN15, GGN25, GGN35, KUN1#, KUN2#, KUN3#, LAN15, LAN25, LAN35, TGN1#, TGN</p> <p>Spring Shackle Rubber [RE, Spring Pin]</p>	<p><b>AT20-VG04F</b> <b>90389-T0005</b></p> <p>Toyota Hilux [2004-2012] = GGN15, GGN25, GGN35, KUN1#, KUN2#, KUN3#, LAN15, LAN25, LAN35, TGN1#, TGN</p> <p>Spring Shackle Bush [RE, Leaf]</p>
<p><b>AT20-VG0EL</b> <b>90385-T0001</b></p> <p>Toyota Hilux [2004-2012] = GGN15, GGN25, GGN35, KUN1#, KUN2#, KUN3#, LAN15, LAN25, LAN35, TGN1#, TGN</p> <p>Spring Shackle Rubber [RE, Upper]</p>	<p><b>AT20-VG0ES</b> <b>90385-T0002</b></p> <p>Toyota Hilux [2004-2012] = GGN15, GGN25, GGN35, KUN1#, KUN2#, KUN3#, LAN15, LAN25, LAN35, TGN1#, TGN</p> <p>Spring Shackle Rubber [RE, Lower]</p>
<p><b>AT20-VG02</b> <b>90389-T0001</b></p> <p>Hilux Vigo [2WD, 4WD]</p> <p>Spring Shackle Bush [RE]</p>	<p><b>AT20-VG0EU</b> <b>90385-T0004</b></p> <p>Toyota Hilux [2011] = GGN15, GGN25, GGN35, KUN1#, KUN2#, KUN3#, LAN15, LAN25, LAN35, TGN1#, TGN26, T</p> <p>Spring Shackle Rubber [RE, Shock Bush]</p>
<p><b>AT20-VG0E002</b> <b>90385-19007</b></p> <p>Toyota Hilux [2011] = KUN25, KUN26, KUN35</p> <p>Spring Shackle Rubber</p>	
<p><b>AT20-VG05E00</b> <b>90389-T0009</b></p> <p>Toyota Hilux [2005] = GGN15, GGN25   Toyota Tacoma [2004] = GRN225, TRN220   Toyota Tacoma [2004] =</p> <p>Spring Shackle Bush</p>	
<p><b>AT20-NEW01B</b> <b>90385-NEW01</b></p> <p>ALL CARS</p> <p>Spring Shackle Rubber [ID=16.00   OD=27.00   IH=37.00   OH=25.00]</p>	











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-J122F00</b> <b>48815-87405</b></p> <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Stabilizer Shaft Rubber [FR]</p> 	
<p><b>AT21-M101F00</b> <b>48815-97401</b></p> <p>Duet [1998-2004] = M101A, M111A   Duet [1998-2004] = M110A [4WD]</p> <p>Stabilizer Shaft Rubber [FR]</p> 	
<p><b>AT21-DHSU00</b> <b>48815-87710</b></p> <p>DAIHATSU</p> <p>Stabilizer Shaft Rubber</p> 	
<p><b>AT21-J200F00</b> <b>48815-B4010</b></p> <p>Rush [2006] = J210E.. [4WD]   Daihatsu Terios [2006] = J200, J211</p> <p>Stabilizer Shaft Rubber [FR]</p> 	

**TOYOTA**

Revision : 2014-November-01

<b>AT21-C02E</b> <b>48818-06051</b>  Camry [1991-1996] = SXV1# Stabilizer Shaft Rubber [RE]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-C02F</b> <b>48815-06030</b>  Camry [1991-1996] = SXV1# Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT21-LE01E01</b> <b>48818-33011</b>  Camry [1991-1996] = SXV10 Stabilizer Shaft Rubber [RE]	PFT-2012-August-30 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-LE01F</b> <b>48815-33011</b>  Camry [1991-1996] = SXV1#, MCV10, VCV10   Lexus ES300 [1992-1996] = VCV10 Stabilizer Shaft Rubber [FR]	RBI-2010-January-28 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT21-MCV10E00</b> <b>48818-06020</b>  Toyota Camry [1992-1996] = MCV10 Stabilizer Shaft Rubber [RE]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT21-C03E</b> <b>48818-06100</b>  Camry [1996-2001] = SXV20, MCV20, SXV2# Stabilizer Shaft Rubber [RE]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-C03F</b> <b>48815-33040</b>  Camry [1996-2001] = SXV20, MCV20, SXV2# Stabilizer Shaft Rubber [FR]	RBI-2014-February-04 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT21-C033E</b> <b>48818-33040</b>  Camry [1996-2001] = SXV20, MCV20, SXV2# Stabilizer Shaft Rubber [RE]	HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT21-C003E</b> <b>48818-33060</b>  Camry [1999-2001] = MCV20, SXV20   Avalon [1999] = MCX20 Stabilizer Shaft Rubber [RE]	RBI-2010-February-08 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-C003F</b> <b>48815-33050</b>  Camry [1996-2001] = MCV20, SXV20, SXV23 Stabilizer Shaft Rubber [FR]	RBI-2006-October-07 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-C04E00</b> <b>48818-06180</b>  Camry [2002-2006] = ACV30, ACV31, MCV30 Stabilizer Shaft Rubber [RE]	RBI-2010-February-23 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-C04F00</b> <b>48815-33090</b>  Camry [2002-2006] = ACV30, ACV31, MCV30 Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-C004E0</b> <b>48818-06170</b>  Camry [2002-2004] = ACV3#, MCV30 Stabilizer Shaft Rubber [RE]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-C05F0</b> <b>48815-33100</b>  Camry [2002-2006] = ACV30, ACV31, ACV40, MCV3#, GSV40   AVALON [2005] = GSX30   Lexus ES300 / 330 [2 Stabilizer Shaft Rubber [FR]	RBI-2010-January-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-C04E01</b> <b>48818-21030</b>  Camry [2002-2006] = ACV3#, MCV30, MCV31   Caldina [1997-2002] = ST215   Lexus ES300 / 330 [2001-2004 Stabilizer Shaft Rubber [RE]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-C06F</b> <b>48815-33110</b>  Camry [2002-2006] = ACV35, ACV45 Stabilizer Shaft Rubber [FR]	RBI-2010-January-29 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-C031E</b> <b>48818-21050</b>  Camry [2004-2006] = ACV30, MCV31   Caldina [1992-2002] = ST195, ST215, CT216   Camry GRACIA [1997-20 Stabilizer Shaft Rubber [RE]	RBI-2010-March-18 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-C031F</b> <b>48815-33030</b>  Camry [1996-2001] = MCV10, SXV1#, VCV10 Stabilizer Shaft Rubber [FR]	HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-MCU15E00</b> <b>48818-32090</b>  Harrier [1997-2000] = MCU15, SXU15 Stabilizer Shaft Rubber [RE]	PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-ACU10F0</b> <b>48815-06060</b>  Harrier [1997-2003] = 2AZFE...ACU1# Stabilizer Shaft Rubber [FR]	ASH-2012-December-25 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT21-ACU20F0</b> <b>48815-48030</b>  Lexus RX330 / 350 / RX400H / Harrier / HIGHLANDER / Kluger [2000-2007] = ACU2#, MCU2#, ACU3#, MCU30, Stabilizer Shaft Rubber [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-ACU25E00</b> <b>48818-48020</b>  Highlander [2000-2007] = ACU25, MCU25, MCU28 Stabilizer Shaft Rubber [RE]	Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT21-MCV31E00</b> <b>48818-0E010</b>  Solara [2003-2008] = ACV30, MCV31 Stabilizer Shaft Rubber [RE]	PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-C05E</b> <b>48818-06220</b></p> <p>Camry [2006-2010] = ACV4#</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-2008-April-02 RBI Product, Tenacity Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	<p><b>AT21-C05F</b> <b>48815-06200</b></p> <p>Camry [2006-2010] = ACV4#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2008-July-11 RBI Product, Tenacity Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
		<p><b>AT21-GV40F</b> <b>48815-06180</b></p> <p>Camry / Aurion [2006-2010] = ACV40, GSV40</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2010-January-28 RBI Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
<p><b>AT21-AHV40E00</b> <b>48818-33090</b></p> <p>Toyota Camry HV [2006-2009] = AHV40...JPP</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>PFT-2014-October-01 Perfect Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	<p><b>AT21-AHV40E01</b> <b>48818-06270</b></p> <p>Toyota Camry HV [2006-2009] = AHV40...NAP</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>PFT-2014-October-01 Perfect Product</p> <p>shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-CV00E</b> <b>48818-21020</b></p> <p>Camry Vista = CV43, SV43   Camry Vista [1994-1998] = SV42   Camry Gracia [1998-2001] = SXV25   Harri</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-2007-December-18 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT21-SV30F</b> <b>48815-32090</b></p> <p>Camry Vista = CV30, SV3#, VZV31, VZV33, CV4#, SV4#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2005-March-31 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT21-C01E</b> <b>48815-32110</b></p> <p>Camry Vista [1986-1991] = SV2#, CV20, VZV21</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-CV40E</b> <b>48818-32120</b></p> <p>Camry Vista [1994-1998] = CV40, SV41</p> <p>Stabilizer Shaft Rubber [RE]</p>
<p><b>AT21-SV55E</b> <b>48818-32130</b></p> <p>Vista / Vista ARDEO [1998-2003] = AZV55, SV55   PREMIO / ALLION [2001] = ZZT245   OPA [2000] = ZCT15</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-2008-July-11 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-UCF10F00</b> <b>48815-50040</b>  Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Celsior, Lexus LS400 [1989-1994] = UCF1# Stabilizer Shaft Rubber [FR]	<b>AT21-UCF30F02</b> <b>48815-50010</b>  Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Celsior, Lexus LS400 [1989-1994] = UCF1#   Toyota Century [1997-2005] = GZG50 Stabilizer Shaft Rubber [FR]
<b>AT21-UCF20F01</b> <b>48815-50110</b>  Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Celsior, Lexus LS400 [1994-2000] = UCF2# Stabilizer Shaft Rubber [FR]	<b>AT21-UCF20F02</b> <b>48815-50150</b>  Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Celsior, Lexus LS400 [1994-2000] = UCF2# Stabilizer Shaft Rubber [FR]
<b>AT21-UCF20F00</b> <b>48815-50121</b>  ASH-2012-December-25 HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Celsior, Lexus LS430 [2000-2006] = UCF3# Stabilizer Shaft Rubber [FR]	<b>AT21-UCF30F01</b> <b>48815-50180</b>  Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Celsior, Lexus LS430 [2000-2006] = UCF3# Stabilizer Shaft Rubber [FR]





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-220</b> <b>48815-12010</b>  <b>KE20</b>  <b>Stabilizer Shaft Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT21-231</b> <b>48815-12050</b>  <b>KE30 [17MM]</b>  <b>Stabilizer Shaft Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT21-232</b> <b>48815-12080</b>  <b>KE36 [19MM]</b>  <b>Stabilizer Shaft Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT21-240</b> <b>48815-14020</b>  <b>Toyota Corolla [1979-1987] = AE71E, KE7#, AE7#, TE7#, CE7#   Toyota Celica [1977-1981] = TA40, RA4#,</b>  <b>Stabilizer Shaft Rubber [FR]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT21-250</b> <b>48815-24010</b>  <b>AE80</b>  <b>Stabilizer Shaft Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
<b>AT21-28E</b> <b>48818-12050</b>  <b>EE90, AE92</b>  <b>Stabilizer Shaft Rubber [RE]</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT21-28F</b> <b>48815-12160</b>  <b>EE90, AE92</b>  <b>Stabilizer Shaft Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT21-28E01</b> <b>48818-12070</b>  <b>Corolla / Levin / Sprinter / Trueno [1987-1993] = AE92, EE90</b>  <b>Stabilizer Shaft Rubber [RE]</b>	  <small>RBI-2013-December-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT21-28F01</b> <b>48815-12180</b>  <b>Corolla / Levin / Sprinter / Trueno [1988-1992] = AE92, AE95, CE95, EE90</b>  <b>Stabilizer Shaft Rubber [FR]</b>	  <small>RBI-2013-December-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT21-28E02</b> <b>48818-12080</b>  <b>Corolla / Sprinter [1987-1992] = CE90</b>  <b>Stabilizer Shaft Rubber [RE]</b>	  <small>RBI-2013-October-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-30E</b> <b>48818-20070</b>  <b>EE100, AE101, AE110, AE111   Camry [1986-1991]</b> <b>= SV2#, CV20, VZV21</b>  <b>Stabilizer Shaft Rubber [RE]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT21-30F</b> <b>48815-12220</b>  <b>EE100, AE101, AE111</b>  <b>Stabilizer Shaft Rubber [FR]</b>	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT21-30E01</b> <b>48818-12180</b>  <b>Corolla / Levin / Trueno / Sprinter [1991-2001] =</b> <b>AE101, AE11#, CDE110, ZZE11#   Camry / Vista</b> <b>[1988]</b>  <b>Stabilizer Shaft Rubber [RE]</b>	 <small>RBI-2013-December-16 RBI Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT21-30F01</b> <b>48815-12200</b>  <b>Corolla [1992-1995] = AE101</b>  <b>Stabilizer Shaft Rubber [FR]</b>	 <small>RBI-2013-July-19 RBI Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT21-30E02</b> <b>48818-12190</b>  <b>Corolla / Sprinter [1991-1995] = AE104..4FC</b>  <b>Stabilizer Shaft Rubber [RE]</b>	 <small>RBI-2013-October-14 RBI Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT21-30F02</b> <b>48815-12210</b>  <b>Corolla / Levin / Sprinter / Trueno [1991-1997] =</b> <b>AE101, AE111</b>  <b>Stabilizer Shaft Rubber [FR]</b>	 <small>RBI-2013-July-19 RBI Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT21-30E03</b> <b>48818-12200</b>  <b>Corolla / Sprinter [1991-1995] = AE104, CE104..5F</b>  <b>Stabilizer Shaft Rubber [RE]</b>	 <small>RBI-2013-October-14 RBI Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
		<b>AT21-31F</b> <b>48815-12280</b>  <b>AE110</b>  <b>Stabilizer Shaft Rubber [FR]</b>	 <small>RBI-2007-May-14 RBI Product, Perfect Product, Tenacity Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		<b>AT21-31F01</b> <b>48815-12300</b>  <b>Corolla / Levin / Trueno [1997-2000] = AE111</b>  <b>Stabilizer Shaft Rubber [FR]</b>	 <small>RBI-2013-July-19 RBI Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>



**TOYOTA**

Revision : 2014-November-01

<p><b>AT21-W11F0</b>  <b>48815-0M010</b></p> <p>Wish [2003-2007] = ANE1#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-W110F</b>  <b>48815-20290</b></p> <p>Toyota Wish [2003-2009] = ANE1#, ZNE1#</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p><b>AT21-W11E0</b>  <b>48818-20350</b></p> <p>Toyota Wish [2003-2009] = ANE1#, ZNE1#   Toyota Wish [2009] = ZGE2#   Toyota Celica [1999-2006] = ZZ</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p><b>AT21-W12E0</b>  <b>48818-63010</b></p> <p>Wish [2003-2005] = NZE14</p> <p>Stabilizer Shaft Rubber [RE]</p>
<p><b>AT21-ZE123F</b>  <b>48815-12310</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-ZE124F</b>  <b>48815-12320</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p><b>AT21-ZE121F</b>  <b>48815-02060</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-ZE120F</b>  <b>48815-13040</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Stabilizer Shaft Rubber [FR] [1.8]</p>
<p><b>AT21-Z141F0</b>  <b>48815-02230</b></p> <p>Corolla / Altis [2007] = ZZE14#, [24mm]</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-Z141F</b>  <b>48815-02240</b></p> <p>Corolla / Altis [2007] = ZZE14#</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p><b>AT21-Z124E</b>  <b>48818-12260</b></p> <p>Corolla / RUNX / ALLEX / SPACIO / FIELDER [2000-2002] = NZE124, ZZE124   WILL VS [2001-2004] = ZZE12</p> <p>Stabilizer Shaft Rubber [RE]</p>	
<p><b>AT21-Z143F00</b>  <b>48815-02250</b></p> <p>Toyota Corolla / Altis [2007] = AZE14#, CE14#, NDE14#, NZE14#, ZRE14#, ZZE14#</p> <p>Stabilizer Shaft Rubber</p>	

















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-Z150FL</b> <b>48815-12370</b>  <p>Toyota Auris / Corolla [2006-2012] = ADE150, NDE150, NRE150, NZE15#, ZRE15#, ZZE150</p> <p>Stabilizer Shaft Rubber [FR] [LH]</p>	<p>RBI-2014-September-04 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<b>AT21-Z150FR</b> <b>48815-12390</b>  <p>Toyota Auris / Corolla [2006-2012] = ADE150, NDE150, NRE150, NZE15#, ZRE15#, ZZE150</p> <p>Stabilizer Shaft Rubber [FR] [RH]</p>	<p>RBI-2014-September-04 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<b>AT21-Z151FL</b> <b>48815-02140</b>  <p>Auris [2006] = ZZE150, NZE151   Auris, Hybrid [2007] = ADE15#, NDE150, NRE150, ZRE15#, ZZE150, ZWE15</p> <p>Stabilizer Shaft Rubber [FR, LH]</p>	<p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<b>AT21-Z151FR</b> <b>48815-02150</b>  <p>Auris [2006] = ZZE150, NZE151   Auris, Hybrid [2007] = ADE15#, NDE150, NRE150, ZRE15#, ZZE150, ZWE15</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<b>AT21-AZT270FL</b> <b>48815-05170</b>  <p>Avensis [2008] = AZT270</p> <p>Stabilizer Shaft Rubber [FR, LH]</p>	<p>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<b>AT21-AZT270FR</b> <b>48815-05160</b>  <p>Avensis [2008] = AZT270</p> <p>Stabilizer Shaft Rubber [FR, RH]</p>	<p>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 



**TOYOTA**

Revision : 2014-November-01

<p><b>AT21-010</b>  <b>48815-20020</b></p> <p><b>RT40</b></p> <p>Stabilizer Shaft Rubber</p>	<p>RBI-OLD  RBI Product, Perfect Product,  Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  	<p><b>AT21-040</b>  <b>48815-20090</b></p> <p><b>RT100</b></p> <p>Stabilizer Shaft Rubber</p>	<p>RBI-OLD  RBI Product, Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  
<p><b>AT21-060</b>  <b>48815-14150</b></p> <p><b>TT141</b></p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD  RBI Product, Perfect Product,  Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  	<p><b>AT21-061</b>  <b>48815-24020</b></p> <p>Corona &amp; Carina &amp; Celica [1982-1992] = AT141,  AT175, RT141, TT142, CT150, ST150, ST162</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>ARD-2014-January-01  ARP Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  
<p><b>AT21-08E</b>  <b>48818-20080</b></p> <p>Corona &amp; Carina [1987-1992] = AT17#, ST17#</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-OLD  RBI Product, Perfect Product,  Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  	<p><b>AT21-08F</b>  <b>48815-30060</b></p> <p>Corona &amp; Carina [1987-1992] = AT17#, ST17#    KF40</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD  RBI Product, Perfect Product,  Tenacity Product, HFC  Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  
<p><b>AT21-ST182F</b>  <b>48815-20200</b></p> <p>ST182   Hilux [1993-1995] = KZN13#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2009-December-12  RBI Product, Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  	<p><b>AT21-KZN13F</b>  <b>48815-35080</b></p> <p>Hilux [1993-1995] = KZN13#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>PFT-2012-March-28  Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  
<p><b>AT21-09E</b>  <b>48818-20280</b></p> <p><b>AT191, ST191</b></p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-OLD  RBI Product, Perfect Product,  Tenacity Product, HFC  Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  	<p><b>AT21-09F</b>  <b>48815-30040</b></p> <p>AT191, ST191   Liteace [1992-2000] = CR27, KR2#,  YR2#, YR39 [RE]   Caldina [1995-1996] = ST195    Car</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD  RBI Product, Perfect Product,  Tenacity Product, HFC  Product, Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  
<p><b>AT21-11E</b>  <b>48818-21040</b></p> <p>Carina / Corona / Caldina [1992-2002] = ST191,  AT210, AT211, ST210</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>ARP Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  	<p><b>AT21-10F</b>  <b>48815-20220</b></p> <p>Carina E [1992-1996] = ST191</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2013-December-16  RBI Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>  











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-121E</b> <b>48818-20380</b> Celica / Carina / Corona / Curren [1993-1999] = AT200, ST200, ST202, ST204, ST206, ST208 Stabilizer Shaft Rubber [RE]	 RBI-2013-November-14 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-121F</b> <b>48815-20260</b> Carina ED / Celica / Corona EXIV / Curren [1993-1999] = ST202, ST205, ST206 Stabilizer Shaft Rubber [FR]	 RBI-2013-October-14 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-122E</b> <b>48818-20390</b> Celica / Carina / Corona / Curren [1993-1997] = AT200, ST20# Stabilizer Shaft Rubber [RE]	 RBI-2013-December-16 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-122F</b> <b>48815-21010</b> Caldina [1997-2002] = ST215, CT216 Stabilizer Shaft Rubber [FR]	 RBI-2013-December-16 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-AZT22E</b> <b>48818-05041</b> Avensis [1997-2003] = AZT22#, AT22#, CDT22, CT22#, ST220, ZZT22# Stabilizer Shaft Rubber [RE]	 RBI-2007-March-13 RBI Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-AZT22F</b> <b>48815-05050</b> Avensis [1997-2003] = AZT22#, AT22#, CDT22, CT22#, ST220, ZZT22# Stabilizer Shaft Rubber [FR]	 RBI-2006-December-18 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-AZT23E</b> <b>48818-05061</b> Avensis [1997-2003] = AZT22#, AT22#, CDT22, CT22#, ST220, ZZT22# Stabilizer Shaft Rubber [RE]	 ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-ZZT23F</b> <b>48815-20280</b> Celica [1999-2006] = ZZT230   Vista / Vista Ardeo [1998-2003] = AZV50, SV50 Stabilizer Shaft Rubber [FR]	 ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>

















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-AZT241E</b> <b>48818-21080</b></p> <p>Avensis / Caldina [2002-2005] = AZT241, AZT255, ZYT241   Scion TC [2004] = ANT10..4FC</p> <p>Stabilizer Shaft Rubber [RE]</p>   <p>RBI-2013-December-16 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-AZT241F</b> <b>48815-21020</b></p> <p>Caldina [2002-2005] = AZT241, ZYT241, ST246   Scion TC [2004] = ANT10</p> <p>Stabilizer Shaft Rubber [FR]</p>   <p>TN-2013-September-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT21-AZT250E</b> <b>48818-05080</b></p> <p>Avensis [2006] = AZT250, AZT251</p> <p>Stabilizer Shaft Rubber [RE]</p>   <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-AZT251E</b> <b>48818-05070</b></p> <p>Avensis [2003-2008] = AZT250, CDT250</p> <p>Stabilizer Shaft Rubber [RE]</p>   <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT21-AZT250F</b> <b>48815-05110</b></p> <p>Avensis [2003-2006] = AZT250, AZT251</p> <p>Stabilizer Shaft Rubber [FR]</p>   <p>ASH-2014-May-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-AZT250F02</b> <b>48815-02110</b></p> <p>Avensis [2003-2006] = AZT250, AZT251</p> <p>Stabilizer Shaft Rubber [FR]</p>   <p>ASH-2014-May-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-GY02F</b> <b>48815-44010</b></p> <p>Toyota Caldina [1997-2002] = AT21#, ST21#   Toyota Carina FF [1996-2001] = AT21#, CT21#, ST21#   Toy</p> <p>Stabilizer Shaft Rubber [FR, 2WD]</p>  <p>RBI-2009-December-12 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT21-GY04F</b> <b>48815-38010</b></p> <p>Ipsum, GAYA [4WD]</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-2006-October-07 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT21-ND02F</b> <b>48815-44020</b></p> <p>Nadia, Platz [2WD]</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT21-ND08F</b> <b>48815-28170</b></p> <p>Noah / Voxy [2001-2010] = ZRR7#, ZRR70, AZR6#   ISIS [2004-2009] = ANM15, ZGM15</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>TN-2011-August-30 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT21-ACM2F01</b> <b>48815-44030</b></p> <p>Ipsum [2001-2009] = ACM2#, ACM26   Picnic / Avensis Verso [2001-2005] = ACM20, ACM2#, CLM20</p> <p>Stabilizer Shaft Rubber [FR] [2WD, 4WD]</p>  <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT21-ACM2F02</b> <b>48815-44040</b></p> <p>Ipsum [2001-2009] = ACM21,</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-ZJ95F</b> <b>48815-60100</b>  Toyota Land Cruiser Prado [1996] = KZJ90, LJ90, RZJ90, VZJ90  Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-FJ95F</b> <b>48815-35100</b>  Toyota Land Cruiser Prado [1996] = KZJ95, LJ95, RZJ95, VZJ95  Stabilizer Shaft Rubber [FR]	RBI-2007-February-13 RBI Product, Perfect Product, HFC Product, shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-LJ90F</b> <b>48815-16170</b>  Toyota Land Cruiser Prado [1996-2004] = KZJ9#, KDJ9#, LJ9#, RZJ9#, VZJ9#   Toyota Land Cruiser Prado  Stabilizer Shaft Rubber [FR]	RBI-2009-February-16 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-LJ91F</b> <b>48815-16160</b>  Toyota Land Cruiser Prado [1996-2004] = KZJ9#, KDJ9#, LJ9#, RZJ9#, VZJ9#   Toyota Land Cruiser Prado  Stabilizer Shaft Rubber [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-L01E</b> <b>48815-60010</b>  Toyota Land Cruiser [1969-1986] = FJ43, FJ45, FJ55, HJ45, HJ47, BJ43, BJ45  Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT21-BJ70F</b> <b>48815-60040</b>  Toyota Land Cruiser [1991-2001] = BJ70, FJ80, FZJ71, 74, HDJ80, 81, HZJ7#, HZJ80, LJ7#, RJ7#, KZJ7#  Stabilizer Shaft Rubber [FR]	RBI-2007-October-11 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT21-FZ78F</b> <b>48815-60170</b>  Toyota Land Cruiser [1999-2007] = FZJ7#, HDJ7#, HZJ7#, VDJ7#  Stabilizer Shaft Rubber [FR]	RBI-2012-November-30 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-FZ80F</b> <b>48815-60070</b>  Toyota Land Cruiser [1992-1998] = FZJ80, HDJ80, HZJ80   Toyota Land Cruiser Van [1992-1998] = FZJ80,  Stabilizer Shaft Rubber [FR]	RBI-2009-March-27 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-LJ70F</b> <b>48815-60030</b>  Toyota Land Cruiser [1990-1996] = KZJ7#, LJ7#, RJ7#  Stabilizer Shaft Rubber [FR]	ARD-2014-January-01 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-FJ80F</b> <b>48815-60050</b>  Toyota Land Cruiser [1992] = FJ80, HDJ80, HDJ81, HZJ80, HZJ81  Stabilizer Shaft Rubber [FR]	RBI-2012-December-25 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-FJ81F</b> <b>48815-30090</b>  Toyota Land Cruiser [1990-1992] = FJ80, FZJ80, HDJ8#, HZJ80   Crown [1983-1987] = YS120, MS122, LS12  Stabilizer Shaft Rubber [FR]	PFT-2012-June-26 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-ZJ96F</b> <b>48815-10090</b>  Toyota Land Cruiser Prado [1996] = KZJ90, LJ90, RZJ90, VZJ90  Stabilizer Shaft Rubber [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-GRJ12F</b> <b>48815-60160</b> Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Stabilizer Shaft Rubber [FR]	RBI-2009-August-21 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT21-GR21F</b> <b>48815-14140</b> 4Runner [2002-2006] = GRN21#, KZN215, UZN21#   Carina [1981-1983] = CA60, TA6#   Celica [1981-1985] Stabilizer Shaft Rubber [FR]	RBI-2009-February-16 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT21-GRJ12E00</b> <b>48815-14130</b> Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Stabilizer Shaft Rubber [FR]	PFT-2014-October-01 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 		
<b>AT21-KDJ15F00</b> <b>48815-60380</b> Toyota Land Cruiser Prado [2009-2014] = GRJ15#, KDJ15#, LJ15#, TRJ15# Stabilizer Shaft Rubber [FR]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT21-GSJ15F00</b> <b>48815-60350</b> Toyota FJ Cruiser [2006] = GSJ1#, GSJ15 Stabilizer Shaft Bush [FR]	Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT21-KDJ15E00</b> <b>48818-60040</b> Toyota Land Cruiser Prado [2009-2014] = GRJ15#, KDJ15#, LJ15#, TRJ15# Stabilizer Shaft Rubber [RE]	RBI-2014-July-14 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT21-KDJ15E01</b> <b>48818-60030</b> Toyota FJ Cruiser [2006] = GSJ1#, GSJ15 Stabilizer Shaft Rubber [RE]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 



**TOYOTA**

Revision : 2014-November-01

<b>AT21-HD100F</b> <b>48815-26250</b> Toyota Land Cruiser 100 / Lexus LX470 [1998-2006] = HDJ10#, UZJ100   Regius / Touring Hiace [1997-20] Stabilizer Shaft Rubber [FR]	RBI-2012-September-22 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-HD101F</b> <b>48815-60121</b> Toyota Land Cruiser 100 / Lexus LX470 [1998-2006] = HDJ100, HDJ101 Stabilizer Shaft Rubber [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT21-HD102F</b> <b>48815-60140</b> Toyota Land Cruiser 100 / Lexus LX470 [1998-2006] = HDJ100, HDJ101, UZJ100 Stabilizer Shaft Rubber [FR]	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-UZ10F</b> <b>48815-60150</b> Toyota Land Cruiser 100 / Lexus LX470 [1998-2006] = HDJ100, HDJ101, UZJ100, FZJ100 Stabilizer Shaft Rubber [FR]	RBI-2012-September-22 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT21-HD104F</b> <b>48815-60111</b> Toyota Land Cruiser 100 / Lexus LX470 [1998-2006] = HDJ100, HDJ101, UZJ100, FZJ100 Stabilizer Shaft Rubber [FR]	ASH-2012-December-25 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT21-UZ120F</b> <b>48815-60200</b> Lexus GX470 [2003] = UZJ120 Stabilizer Shaft Rubber [FR]	RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-UZ120E</b> <b>48818-60010</b> Lexus GX470 [2003] = UZJ120 Stabilizer Shaft Rubber [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT21-FZ76F</b> <b>48815-60210</b> Toyota Land Cruiser [2007] = FZJ76, HZJ76 Stabilizer Shaft Rubber [FR]	RBI-2012-September-22 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT21-UZ20F</b> <b>48815-60250</b> Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200, GRJ200, URJ201 Stabilizer Shaft Rubber [FR]	RBI-2010-May-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-UZ201F</b> <b>48815-60240</b> Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200, GRJ200, URJ201 Stabilizer Shaft Rubber [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT21-UZ202F</b> <b>48815-60220</b> Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200 Stabilizer Shaft Rubber [FR]	RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT21-UZ203F</b> <b>48815-60260</b> Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200 Stabilizer Shaft Rubber [FR]	RBI-2013-October-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-640</b> <b>48815-26020</b></p> <p>Hiace [1982-1988] = LH5#, LH6#, LH7#, YH5#, YH6#, YH7#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-650</b> <b>48815-26060</b></p> <p>Hiace [1989-1996] = LH10#, LH11#, LH125, RZH10#, RZH11#, RZH125</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p><b>AT21-LH12F</b> <b>48815-26300</b></p> <p>Hiace / Van / Wagon / Comuter / Regiusace [1996-2005] = LH10#, LH11#, LH12#, LH16#, LH17#, LH184, RZ</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-652F</b> <b>48815-26120</b></p> <p>Toyota Hiace, Regiusace [1989-2005] = KCH40, KZH1##, LH1##, RCH40, RZH1##, TRH1##</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p><b>AT21-KC10F</b> <b>48815-26200</b></p> <p>Granvia / Grand Hiace / Hiace / Regius / Touring [1995-2006] = KCH10, KLH12, KLH22, LXH12, LXH22, RC</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-KC100F</b> <b>48815-26260</b></p> <p>Granvia / Grand Hiace / Hiace / Regius / Touring [1997-2006] = KCH10, KLH22, RCH1#, RCH2#, VCH10, VC</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p><b>AT21-657F</b> <b>48815-26230</b></p> <p>Granvia / Grand Hiace / Hiace / Regius / Touring [1995-1998] = KCH16, LXH18, LXH28, RCH18, RCH28</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-658F</b> <b>48815-26310</b></p> <p>Granvia / Grand Hiace / Hiace / Regius / Touring [1997-2006] = KCH16, KCH46, KLH18, KLH28, VCH16, VC</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p><b>AT21-KC16F</b> <b>48815-26340</b></p> <p>Granvia / Grand Hiace / Hiace / Regius / Touring [1999-2002] = KCH16, VCH16</p> <p>Stabilizer Shaft Rubber [FR]</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-66E</b> <b>48815-26140</b>  Hiace [1996-2005] = RZH15#, LH154 Stabilizer Shaft Rubber [RE] [LH]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-67E</b> <b>48815-26160</b>  Hiace [1996-2005] = RZH135 Stabilizer Shaft Rubber [RE]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-670F</b> <b>48815-26221</b>  Hiace [1996-2005] = RZH135, RZH15#, LH154 Stabilizer Shaft Rubber [FR]	RBI-2007-October-13 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT21-KD20F</b> <b>48815-26370</b>  Hiace / Regiusace [2005-2010] = KDH20#, KDH22#, LH20#, LH22#, TRH20#, TRH22# Stabilizer Shaft Rubber [FR]	RBI-2009-December-12 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT21-KC40F</b> <b>48815-26240</b>  Hiace / Regius / Touring [1997-2002] = KCH40, RCH41 Stabilizer Shaft Rubber [FR]	RBI-2012-September-22 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-KC400F</b> <b>48815-26270</b>  Hiace / Regius / Touring [1997-2002] = KCH40, RCH41   QUICK DELI / URBAN SUP [1999-2004] = BU28#, RZ Stabilizer Shaft Rubber [FR]	RBI-2012-November-10 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-LH176F00</b> <b>48815-26050</b>  Toyota Hiace Quick Delivery [1985-1995] = LH8#   Toyota Hiace Van, Comuter [1982-1989] = YH5#, YH6# Stabilizer Shaft Rubber [FR]	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT21-LY270F00</b> <b>48815-25040</b>  Toyota Dyna 150, Toyoace G15 [2001-2007] = KDY22#, KDY23#, KDY25#, KDY26#, KDY280, KDY2##, LY220, LY Stabilizer Shaft Rubber [FR]	HFC Product, Ashimori Product www.rbi.ae		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-CMYF</b> <b>48815-30100</b>  Liteace / Townace / Noah [1992-2000] = CR27, KR2#, YR2#, YR39, CM4#, YM40, CM6# Stabilizer Shaft Rubber [FR]	 RBI-2007-March-13 RBI Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-CM30F</b> <b>48815-30120</b>  Liteace / Townace / Noah [1988-1998] = CM3#, KM3#, YM3#, YM4# Stabilizer Shaft Rubber [FR]	 RBI-2007-July-16 RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-CR40F</b> <b>48815-30080</b>  Liteace / Townace / Noah [1996-1998] = CR4#, KR4#, SR4# Stabilizer Shaft Rubber [FR]	 TN-2013-March-31 Perfect Product, Tenacity Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-CR41F</b> <b>48815-28080</b>  Liteace / Townace / Noah [1998-2004] = CR4#, KR4#, SR4# Stabilizer Shaft Rubber [FR]	 TN-2013-March-31 Tenacity Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-CR40E</b> <b>48815-28120</b>  Liteace / Townace / Noah [1996-2004] = CR4#, KR4#, SR4# Stabilizer Shaft Rubber [RE]	 TN-2013-March-31 Tenacity Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-CR5F</b> <b>48815-28070</b>  Liteace / Townace / Noah [1998-2001] = CR5# Stabilizer Shaft Rubber [FR]	 RBI-2007-March-13 RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-CR50F</b> <b>48815-28090</b>  Liteace / Townace / Noah [1998-2001] = CR50, SR50 Stabilizer Shaft Rubber [FR]	 RBI-2012-August-25 RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-CR52F</b> <b>48815-28100</b>  Liteace / Townace / Noah [1999-2004] = SR50, CM75, CM8#, CR52, KM75, KM8#, KR52 Stabilizer Shaft Rubber [FR]	 RBI-2013-July-19 RBI Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-TCR11</b> <b>48815-28030</b>  Estima / Emina / Lucida / Previa [1991-1999] = TCR11   Liteace / Townace / Noah [1988-1998] = CM4# Stabilizer Shaft Rubber [FR]	 RBI-2006-April-04 RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-T11F</b> <b>48815-28040</b>  Estima / Emina / Lucida / Previa [1990-1991] = TCR1#, TCR2# Stabilizer Shaft Rubber [FR]	 RBI-2009-April-28 RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-CX10F</b> <b>48815-28061</b>  Estima / Emina / Lucida / Previa [1991-1999] = CXR1#, CXR20, TCR1#, TCR20 Stabilizer Shaft Rubber [FR]	 RBI-2009-March-09 RBI Product, Perfect Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-CX11F</b> <b>48815-28051</b>  Estima / Emina / Lucida / Previa [1992-1999] = CXR11, CXR2#, TCR11, TCR2# Stabilizer Shaft Rubber [FR]	 ASH-2013-July-10 HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-AC30F</b> <b>48815-28150</b>  Toyota Estima T, L, Previa, Tarago Hybird [1999-2006] = ACR30, ACR40, MCR30, MCR40, CLR30, AHR10   T Stabilizer Shaft Rubber [FR]	RBI-2009-November-28 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-AC31F</b> <b>48815-28130</b>  Estima / Previa / Tarago [1999-2003] = ACR30, MCR30   Lexus ES350 [2006] = GSV40 Stabilizer Shaft Rubber [FR]	ASH-2013-July-10 HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-AC40F</b> <b>48815-28140</b>  Estima / Previa / Tarago [1999-2003] = ACR40, MCR40 Stabilizer Shaft Rubber [FR]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT21-AGV10F00</b> <b>48815-0T010</b>  Toyota Venza [2008-2013] = AGV1#, GGV1# Stabilizer Shaft Rubber [FR]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>		
<b>AT21-AC50L</b> <b>48815-28180</b>  Estima / Previa / Tarago [2006] = ACR50 Stabilizer Shaft Rubber [FR] [LH]	RBI-2010-July-19 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-AC50R</b> <b>48815-28190</b>  Estima / Previa / Tarago [2006] = ACR50 Stabilizer Shaft Rubber [FR] [RH]	RBI-2010-July-19 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-AC55L</b> <b>48815-28200</b>  Estima / Previa / Tarago [2006] = ACR55, GSR5#   Estima Hybird [2006] = AHR20   Previa / Tarago [200 Stabilizer Shaft Rubber [FR, LH]	RBI-2010-July-19 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-AC55R</b> <b>48815-28210</b>  Estima / Previa / Tarago [2006] = ACR55, GSR5#   Estima Hybird [2006] = AHR20   Previa / Tarago [200 Stabilizer Shaft Rubber [FR, RH]	RBI-2010-July-19 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-AGL10F00</b> <b>48815-48070</b>  Toyota Lexus RX270, RX350, RX450 [2008] = AGL10, GGL1#, GYL1#   Toyota Highlander, Kluger [2007] = A Stabilizer Shaft Rubber [FR]	PFT-2013-April-30 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-ASL30F00</b> <b>48815-AE030</b>  Toyota Sienna [2003-2009] = GSL2#, MCL2#   Toyota Sienna [2010] = ASL30, GSL3# Stabilizer Shaft Bush [FR]	PFT-2013-April-30 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT21-AUR20FL</b> <b>48815-0F040</b>  Toyota Corolla Verso [2009] = AUR2#, ZGR2#, WAR20 Stabilizer Shaft Rubber [FR] [LH]	Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT21-AUR20FR</b> <b>48815-0F050</b>  Toyota Corolla Verso [2009] = AUR2#, ZGR2#, WAR20 Stabilizer Shaft Rubber [FR, RH]	Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT21-RV01F</b> <b>48815-42010</b>  Toyota Rav4 [1994-2000] = SXA1#  Stabilizer Shaft Rubber [FR]	<div>RBI-2006-November-15 RBI Product, Perfect Product, Ashimori Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  	<b>AT21-RV1F</b> <b>48815-42020</b>  Toyota Rav4 [1994-2000] = SXA1#  Stabilizer Shaft Rubber [FR]	<div>RBI-2007-November-06 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  
<b>AT21-RV02F</b> <b>48815-42030</b>  Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#  Stabilizer Shaft Rubber [RE]	<div>RBI-2009-February-16 RBI Product, Perfect Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  	<b>AT21-AC20F</b> <b>48815-42040</b>  Toyota Rav4 [2000-2005] = ACA2#, CLA21, ZCA26  Stabilizer Shaft Rubber [FR]	<div>RBI-2010-January-28 RBI Product, Perfect Product, HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  
<b>AT21-AC21F</b> <b>48815-42050</b>  Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#  Stabilizer Shaft Rubber [FR]	<div>RBI-2010-August-16 RBI Product, Perfect Product, HFC Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  	<b>AT21-AC22F</b> <b>48815-42060</b>  Toyota Rav4 [2000-2005] = ACA2#  Stabilizer Shaft Rubber [FR]	<div>ARP Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  
<b>AT21-AC30L</b> <b>48815-42090</b>  Toyota Rav4 [2005-2007] = ACA3#, ALA30, GSA3#  Stabilizer Shaft Rubber [FR, LH]	<div>RBI-2010-August-16 RBI Product, HFC Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  	<b>AT21-AC30R</b> <b>48815-42100</b>  Toyota Rav4 [2005-2007] = ACA3#, ALA30, GSA3#  Stabilizer Shaft Rubber [FR, RH]	<div>RBI-2010-July-19 RBI Product, HFC Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  
<b>AT21-AC38L</b> <b>48815-42070</b>  Toyota Rav4 [2005-2007] = ACA38  Stabilizer Shaft Rubber [FR] [LH]	<div>RBI-2010-August-16 RBI Product, Perfect Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  	<b>AT21-AC38R</b> <b>48815-42080</b>  Toyota Rav4 [2005-2007] = ACA38  Stabilizer Shaft Rubber [FR] [RH]	<div>RBI-2010-August-16 RBI Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  
<b>AT21-RV02E</b> <b>48818-42010</b>  Toyota Rav4 [2005-2010] = ACA3#, ALA30, GSA3#  Stabilizer Shaft Rubber [RE]	<div>RBI-2009-February-16 RBI Product, Perfect Product, HFC Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>  		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924  
E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-420</b> <b>48815-20030</b></p> <p>Hilux = RN20</p> <p>Stabilizer Shaft Rubber</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT21-421</b> <b>48815-35060</b></p> <p>Hilux [1985-1994] = RN5#, YN5#   TRUCK Toyota 4-Runner [1984-1988] = RN55, RN75</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT21-460</b> <b>48815-14160</b></p> <p>Hilux = LN85</p> <p>Stabilizer Shaft Rubber [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT21-TUVF00</b> <b>48815-38030</b></p> <p>T.U.V [1999-2006] = LF85, RZF85</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>PFT-2012-August-30 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT21-820</b> <b>48815-30050</b></p> <p>MS60, LN56</p> <p>Stabilizer Shaft Rubber</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT21-860</b> <b>48815-30171</b></p> <p>MS132</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT21-920</b> <b>48815-36012</b></p> <p>BU10   Toyota Stout [1979-2000] = RK11#, YK110   Toyota Coaster [1977-1982] = RB1#, BB1#</p> <p>Stabilizer Shaft Rubber</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT21-VG02C</b> <b>48815-0K070</b></p> <p>Hilux Vigo [2WD] [CAP4]</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-2005-August-19 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT21-VG02F</b> <b>48815-0K050</b></p> <p>Hilux Vigo [2WD]</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-2005-September-23 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT21-VG04F</b> <b>48815-0K010</b></p> <p>Hilux Vigo [4WD]</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-2005-August-19 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT21-RX0F</b> <b>48815-22040</b></p> <p>Mark II / Chaser / Cresta / Cressida [1984-1996] = RX70, RX81, LX70, GX81, SX80, MX83, SX70, YX7#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2007-April-23 RBI Product, Perfect Product, HFC Product, Ashimori Product</p> <p><a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT21-GX70E</b> <b>48815-22080</b></p> <p>Mark II / Chaser / Cresta / Cressida [1984-1992] = JZX8#, YX7#, LX7#, RX7#, GX7#, MX7#</p> <p>Stabilizer Shaft Rubber [RE]</p>
<p><b>AT21-GX80F</b> <b>48815-22120</b></p> <p>Mark II / Chaser / Cresta / Cressida [1988-1992] = GX8#, MX8#, JZX8#, YX7#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p><b>AT21-GX80E</b> <b>48818-17070</b></p> <p>Mark II / Chaser / Cresta / Cressida [1988-1992] = GX8#, MX8#, JZX8#, YX7#</p> <p>Stabilizer Shaft Rubber [RE]</p>



## TOYOTA

Revision : 2014-November-01

<b>AT21-GX90E</b> <b>48815-22140</b> <p>ARP Product  <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Mark 2, Chaser, Cresta [1992-1996] = GX90</p> <p>Stabilizer Shaft Rubber [RE]</p>	
<b>AT21-GX900</b> <b>48815-22150</b> <p>RBI-OLD  RBI Product, Perfect Product, Ashimori Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Mark II / Chaser / Cresta / Cressida [1992-2001] = GX90</p> <p>Stabilizer Shaft Rubber [FR]</p>	<b>AT21-GX930</b> <b>48815-22180</b> <p>PFT-2012-March-28  Perfect Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Mark II / Chaser / Cresta / Cressida [1996-2001] = GX105, JZX105, JZX93</p> <p>Stabilizer Shaft Rubber [FR] [4WD]</p>
<b>AT21-GX100</b> <b>48815-22190</b> <p>PFT-2012-March-28  Perfect Product, Ashimori Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Mark II / Chaser / Cresta / Cressida [1996-1998] = GX100, JZX100</p> <p>Stabilizer Shaft Rubber [FR]</p>	<b>AT21-GX101F</b> <b>48815-22210</b> <p>PFT-2012-March-28  Perfect Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Mark II / Chaser / Cresta / Cressida [1996-2001] = GX100, JZX100, JZX101, LX100, SX100</p> <p>Stabilizer Shaft Rubber [FR]</p>
<b>AT21-GX110F</b> <b>48815-22240</b> <p>ARP Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Mark II / Chaser / Cresta / Cressida [2001-2004] = GX110, JZX110</p> <p>Stabilizer Shaft Rubber [FR]</p>	
<b>AT21-GX115F</b> <b>48815-22250</b> <p>ARP Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Mark II / Chaser / Cresta / Cressida [2000-2004] = GX115, JZX115</p> <p>Stabilizer Shaft Rubber [FR]</p>	
<b>AT21-GXE10F0</b> <b>48815-51010</b> <p>TN-2012-March-06  Tenacity Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Altezza / Altezza Gita [2000] = GXE1#, SXE1#, JCE1#   Origin / Progress [1998] = JCG1#   Mark II [20</p> <p>Stabilizer Shaft Rubber [FR]</p>	<b>AT21-GXE10E0</b> <b>48818-53030</b> <p>TN-2012-March-06  Tenacity Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Altezza / Altezza Gita [2000] = GXE1#, SXE1#, JCE1#   Origin / Progress [1998] = JCG1#   Mark II [20</p> <p>Stabilizer Shaft Rubber [RE]</p>
<b>AT21-GX100E01</b> <b>48815-22200</b> <p>ARP Product  <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Mark 2, Chaser, Cresta [1996-2001] = GX100</p> <p>Stabilizer Shaft Rubber [RE]</p>	<b>AT21-GX100E02</b> <b>48815-22220</b> <p>ARP Product  <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Mark 2, Chaser, Cresta [1996-2001] = GX100</p> <p>Stabilizer Shaft Rubber [RE]</p>
<b>AT21-GX100E03</b> <b>48815-22230</b> <p>ARP Product  <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Mark 2, Chaser, Cresta [1996-2001] = GX100</p> <p>Stabilizer Shaft Rubber [RE]</p>	

**TOYOTA**

Revision : 2014-November-01

<p><b>AT21-GS131F00</b>  <b>48815-30180</b></p> <p>Crown / Crown Majesta [1987-1991] = GS131, MS135, JZS131</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-JZS133E00</b>  <b>48815-30300</b></p> <p>Toyota Crown [1991-2001] = JZS133, JZS135</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>HFC-2014-November-20 HFC Product www.rbi.ae</p>
<p><b>AT21-GS151</b>  <b>48815-30470</b></p> <p>Crown / Crown Majesta [1995-2003] = GS151, JZS155, LS15#, JZS175   Lexus IS200, 300 [99-2000] = GXE1</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>RBI-2012-July-14 RBI Product, ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>AT21-880F</b>  <b>48815-30400</b></p> <p>Crown / Crown Majesta [1995-2003] = GS151, JZS155, LS15#, JZS175</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>RBI-2013-February-09 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-880E</b>  <b>48818-30090</b></p> <p>Crown / Crown Majesta [1995-2003] = GS151, JZS155, LS15#, JZS175</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>RBI-2012-July-14 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT21-JZS160F0</b>  <b>48815-30540</b></p> <p>Toyota Lexus GS300, GS400, GS430 [2000] = JZS160, UZS161   Toyota Aristo [2000] = JZS16#</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-UZS175F0</b>  <b>48815-30520</b></p> <p>Crown / Crown Majesta [1999-2004] = UZS171, UZS175</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT21-GRS180F0</b>  <b>48815-30551</b></p> <p>Crown / Crown Majesta [2004-2009] = GRS18#, UZS18#   Mark X [2004-2009] = GRX12#   Lexus ISF [2007]</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>TN-2012-March-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-GRS180E0</b>  <b>48818-30180</b></p> <p>Crown / Crown Majesta [2004-2009] = GRS18#, UZS18#   Mark X [2004-2009] = GRX12#   Lexus ISF [2007]</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>TN-2012-March-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT21-GRS190F0</b>  <b>48815-30560</b></p> <p>Crown / Crown Majesta [2004-2009] = GRS19#</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT21-GRS190E0</b>  <b>48818-30160</b></p> <p>Crown / Crown Majesta [2004-2009] = GRS19#</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT21-GXE10E2</b>  <b>48818-30110</b></p> <p>Altezza, Altezza Gita [1998-2005] = GXE10, SXE10   Aristo [1997-2004] = JZS160, JZS161   Crown, Crow</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>AT21-UZS14E00</b>  <b>48818-30060</b></p> <p>Aristo [1991-1997] = JZS147   Aristo [1991-1997] = UZS143.. [4WD]   Crown, Crown Majesta [1991-1995]</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>HFC Product www.rbi.ae</p>	<p><b>AT21-UZS14F00</b>  <b>48815-30390</b></p> <p>Aristo [1991-1997] = JZS147   Aristo [1991-1997] = UZS143.. [4WD]   Crown, Crown Majesta [1991-1995]</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product www.rbi.ae</p>

**TOYOTA**

Revision : 2014-November-01

<b>AT21-VP02F</b> <b>48815-52030</b>  Echo, Yaris, Vits, Platz [2WD] Stabilizer Shaft Rubber [FR]	RBI-2007-April-20 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-NCP35E</b> <b>48815-52050</b>  Toyota BB, Open Deck [2003-2005] = NCP35.. [4WD]   Toyota Fun Cargo [1999-2005] = NCP25.. [4WD] Stabilizer Shaft Rubber [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-NCP55F</b> <b>48815-52070</b> Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD] Stabilizer Shaft Rubber [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-NCP55E</b> <b>48815-52060</b> Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD] Stabilizer Shaft Rubber [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-NCP55F01</b> <b>48815-52020</b> YARIS / ECHO [2000-2003] Stabilizer Shaft Rubber [FR]	ASH-2013-July-10 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT21-XT10F</b> <b>48815-10060</b>  Toyota Starlet [1978-1984] = KP6#   Toyota Corsa, Tercel [1982-1989] = AL2# Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-YA91F</b> <b>48815-0D110</b>  Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9# Stabilizer Shaft Rubber [FR]	RBI-2008-October-15 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT21-NCP93F00</b> <b>48815-52080</b>  YARIS [2007-2010] = NCP93 Stabilizer Shaft Rubber [FR]	ASH-2013-July-10 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT21-S01F</b> <b>48815-0A010</b>  Toyota Soluna [1996-2003] = AL50 Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT21-NC42F</b> <b>48815-0D040</b>  Vios / Soluna Vios [2002] = NCP4# Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT21-F60F00 48815-BZ010</p> <p>AVanza [2003] = F601, F602 [USA]</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2014-July-14 RBI Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p>AT21-KGJ10F00 48815-74030</p> <p>IQ [2008] = KGJ10, NGJ10</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>ARP Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p>	
<p>AT21-NHW1F 48815-47010</p> <p>PRIUS [1997-2003] = NHW1#</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>ARP Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p>	





**TOYOTA**

Revision : 2014-November-01

<b>AXX-100</b> <b>56112-94000</b>  D / S, S250 Stabilizer Link Grommet [Big]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AXX-101</b> <b>56112-09400</b>  D / S Stabilizer Link Grommet [Small]	RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AXX-101-8M</b> <b>56112-09408</b>  D / S, S250 Stabilizer Link Grommet [SMALL]
<b>AXX-109TX</b> <b>10301-90201</b>  TX Shock Absorber Grommet Rubber	RBI-2005-July-27 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT22-HZJ70001</b> <b>90948-01004</b>  Toyota Land Cruiser [1990-2004] = HZJ70, HZJ71, HZJ74, HZJ75, HZJ76   Toyota Land Cruiser 100 [1998- Shock Absorber Grommet Rubber [RE]
<b>AT19-VG02P</b> <b>90948-T1001</b>  Hilux Vigo Stabilizer Link Grommet [Upper]	RBI-2010-March-18 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AXX-107</b> <b>8-97236303-0</b>  D-Max Shock Absorber Grommet Rubber
<b>AT22-RCH41001</b> <b>90948-01061</b>  Dyna 150, Toyoace G15 [2001-2004] = LY220   Dyna 150, Toyoace G15 [2003-2007] = KDY220, KDY280   Dyn Stabilizer Link Grommet	PFT-2014-October-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT22-UZJ10F01</b> <b>90540-17006</b>  Toyota Land Cruiser 100 [1998-2007] = HDJ101, UZJ100 Stabilizer Link Grommet
<b>AT22-VZJ95001</b> <b>90948-01045</b>  Hilux [1988-1997] = KZN130, LN8#, LN10#, LN112, LN13#, VZN130, YN8#, YN10#, YN130   Hilux [1988-1999 Stabilizer Link Grommet	PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AN22-Y60E001</b> <b>56119-01J00</b>  Civilian [1982-1999] = W40   Civilian [2002] = W41   Patrol [1997-2010] = Y61L, [GR]   Patrol Safari Shock Absorber Grommet Rubber	PFT-2014-November-15 Perfect Product, ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT22-1235A00</b> <b>56119-1235A</b>  All Cars Shock Absorber Grommet Rubber



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT22-FJ62B00</b> <b>90948-01031</b></p> <p>Toyota Land Cruiser 60 [1987-1987] = BJ60, HJ6#, FJ62</p> <p>Shock Absorber Grommet Rubber [Big]</p>	<p><b>AT22-RV1B00</b> <b>90948-01018</b></p> <p>Toyota Rav4 [1994-2000] = SXA1#   Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Shock Absorber Grommet Rubber [Big]</p>
<p><b>AT22-UZJ10F02</b> <b>90948-01003</b></p> <p>Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100</p> <p>Shock Absorber Grommet Rubber [Big]</p>	
<p><b>AT22-RCH10F01</b> <b>48817-26010</b></p> <p>Granvia, Grand Hiace [1995-2005] = KCH1#, RCH11, VCH1#, VCH2#   Hiace, Hiace S.B.V [1995-2006] = KLH</p> <p>Shock Absorber Grommet Rubber</p>	
<p><b>AT22-ZJ95E00</b> <b>90385-19009</b></p> <p>Toyota Land Cruiser Prado 90 [1996-2002] = KDJ9#, KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Shock Absorber Grommet Rubber [RE]</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AN22-240</b> <b>56125-18100</b>  910, A31, C31, C32, C33, C34, C35, AWC34, B110, B310 Stabilizer Link Grommet	<b>AN22-242</b> <b>56127-50000</b>  Nissan Urvan, Urvan, King Van [1986-2010] = E23, E24, E25   AL NISSAN CARS Stabilizer Link Grommet
<b>AM22-K5400</b> <b>MB-633908</b>  Strada / G-Wagon [1996-2002] = K54, K57, K77 Stabilizer Link Grommet	
<b>AM22-CK200</b> <b>MR-241349</b>  Lancer / Cedia [1997-2001] = CK2, CK4, CK5, CS3, CS5 Stabilizer Link Grommet	<b>AM22-CK201</b> <b>4056A010</b>  Lancer / Cedia / Mirage [1995-2009] = CK2, CK4, CK5, CS3, CS5, CS, CJ, CK   Airtrek [2001-2005] = CU Stabilizer Link Grommet [With Metal Inside]
<b>AM22-CS9F</b> <b>MR-476595</b>  Lancer / Cedia [2000-2006] = CS3, CS9   OUTLANDER [2002-2006] = CU2W, CU5W   AIRTREK [2001-2005] = C Stabilizer Shaft Rubber	
<b>AM22-DG1E00</b> <b>MR-465000</b>  Mitsubishi Carisma [1995-2003] = DA   Mitsubishi Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A   V Stabilizer Link Grommet [RE, LH, RH]	
<b>AO22-AC90E01</b> <b>52316-692-010</b>  Accord [1990-1993] = CB1, CB3, CB7   Civic Shuttle [1987-1997] = EF   Civic, Civic CRX [1987-1998] = Shock Absorber Grommet Rubber	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT22-810</b> <b>48817-30010</b></p> <p>MS60   Camry [1982-1986] = CV1#, SV1#   Carina [1970-1973] = TA1#   CENTURY [1987-1997] = VG4#   Cor</p> <p>Stabilizer Link Grommet</p>	 <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT22-010</b> <b>48817-20010</b></p> <p>Toyota Hilux [1972-1978] = RN2#   RT40</p> <p>Stabilizer Link Grommet</p>	<p><b>AT22-220</b> <b>48817-12010</b></p> <p>KE20, KE30</p> <p>Stabilizer Link Grommet</p>  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT22-25E</b> <b>90385-11021</b>  AE80, AE92, LN106  Stabilizer Link Grommet [FR]	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT26-25E</b> <b>90385-11021</b>  AE80, AE92, LN106  Stabilizer Link Grommet [Metal Inside]	RBI-2010-December-31 RBI Product, Perfect Product, Tenacity Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT22-NCP3F01</b> <b>90385-11025</b> BB, Open Deck [2003-2005] = NCP35.. [4WD]   Fun Cargo [1999-2005] = NCP25.. [4WD]   Platz [1999- 2005 Shock Absorber Grommet Rubber	PFT-2014-October-15 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT22-NCP3F01Z</b> <b>90385-11025</b> BB, Open Deck [2003-2005] = NCP35.. [4WD]   Fun Cargo [1999-2005] = NCP25.. [4WD]   Platz [1999- 2005 Shock Absorber Grommet Rubber	PFT-2014-October-15 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT22-670</b> <b>90385-13008</b>  RZH135   ProBox/Succeed [2002] = NCP55, NCP59  Stabilizer Link Grommet [RE]	RBI-2006-April-04 RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT22-670Z</b> <b>90385-13008</b>  RZH135   ProBox/Succeed [2002] = NCP55, NCP59  Stabilizer Link Grommet [Metal Inside]	PFT-2013-April-30 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT22-675</b> <b>90385-13004</b>  RZH100  Stabilizer Link Grommet [FR]	PFT-2013-April-30 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT22-675Z</b> <b>90385-13004</b>  RZH100  Stabilizer Link Grommet [Metal Inside]	PFT-2013-April-30 Perfect Product, Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> 28.00 <a href="http://www.rbi.ae">www.rbi.ae</a> 10.20 <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT22-BU300F</b> <b>90385-13009</b> DYNA [2002-] = BU30#, 34#, WU30#, 34#, XZU305, 345..ARL, GCC, GEN, SA  Stabilizer Link Grommet	PFT-2013-April-30 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT22-BU300FZ</b> <b>90385-13009</b> DYNA [2002-] = BU30#, 34#, WU30#, 34#, XZU305, 345..ARL, GCC, GEN, SA  Stabilizer Link Grommet [Metal Inside]	PFT-2013-April-30 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT22-J200E01</b> <b>48849-B4010</b> Rush [2006] = J200E   Rush [2006] = J210E.. [4WD]   Daihatsu Be-Go [2006] = J200G   Daihatsu Be-Go [	PFT-2013-April-30 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT22-J200E01Z</b> <b>48849-B4010</b> Rush [2006] = J200E   Rush [2006] = J210E.. [4WD]   Daihatsu Be-Go [2006] = J200G   Daihatsu Be-Go [	PFT-2013-April-30 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AO22-0880</b> <b>52316-SA5-000</b>  Accord [1988-1997]   Civic [1988]  Stabilizer Link Grommet	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AO22-090</b> <b>90112-SM4-020</b>  Accord [1990]  Stabilizer Link Grommet	RBI-OLD RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT22-676 90385-1300A</p> <p>All Cars</p> <p>Stabilizer Link Grommet</p> <p>ARD-2013-May-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	
<p>AT22-UZ200F00 48817-60010</p> <p>Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200..VX</p> <p>Stabilizer Link Grommet</p> <p>PFT-2014-May-25 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p>AT22-UZ20F 48817-60020</p> <p>Toyota Land Cruiser / Lexus LX570 [2007] = GRJ200, UZJ200, VDJ200, URJ201..GX</p> <p>Stabilizer Link Grommet</p> <p>PFT-2014-May-25 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AN22-243 56217-EB70A</p> <p>All Cars</p> <p>Stabilizer Link Grommet</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p>AN22-244 56218-CA000</p> <p>All Cars</p> <p>Stabilizer Link Grommet</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AXX-103 47856-10021</p> <p>All Cars</p> <p>Stabilizer Link Grommet</p> <p>RBI-2012-March-12 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AXX-102</b> <b>56119-32201</b></p> <p>HILUX, STOUT, Toyota Land Cruiser, Carina, Crown, Liteace, Dyna</p> <p>Shock Absorber Grommet Rubber [30x15x18]</p>	<p><b>AXX-102-SH</b> <b>56119-32201</b></p> <p>HILUX, STOUT, Toyota Land Cruiser, Carina, Crown, Liteace, Dyna</p> <p>Shock Absorber Grommet Rubber</p>
<p><b>AT22-HZJ100E01</b> <b>90385-19003</b></p> <p>Toyota Land Cruiser [1984-1998] = BJ6#, FJ6#, HJ6#, HJ75, HZJ105, FZJ105</p> <p>Shock Absorber Grommet Rubber [RE]</p>	
<p><b>AT22-J122001</b> <b>48537-87401</b></p> <p>Cami [1999-2005] = J100E, J102E, J122E   Daihatsu Terios [1997-2006] = J100, J111</p> <p>Shock Absorber Grommet Rubber [RE]</p>	
<p><b>AXX-106</b> <b>56119-32000</b></p> <p>GR82</p> <p>Shock Absorber Grommet Rubber [35-10-15]</p>	<p><b>AXX-108</b> <b>13500-13510</b></p> <p>KM, KT925</p> <p>Shock Absorber Grommet Rubber</p>
<p><b>AN22-281</b> <b>53150-90001</b></p> <p>All Cars</p> <p>Shock Absorber Grommet Rubber</p>	<p><b>AN22-E24001</b> <b>55135-90R00</b></p> <p>Urvan / Urvan / King Van / Caravan / Homy [1986-2001] = E24, E25   Terrano 1 / Pathfinder [1986-1995]</p> <p>Shock Absorber Grommet Rubber</p>
<p><b>AXX-109BUS</b> <b>8-94235319-0</b></p> <p>BUS 206</p> <p>Shock Absorber Grommet Rubber</p>	<p><b>AXX-109KT7</b> <b>9-37518030-0</b></p> <p>KT725</p> <p>Shock Absorber Grommet Rubber</p>
<p><b>AXX-104</b> <b>8-94226577-3</b></p> <p>JEEP, KBZ   L200 / Triton</p> <p>Shock Absorber Grommet Rubber</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT22-M100E01</b> <b>90043-85102</b></p> <p>BB [2006] = QNC25.. [4WD]   Duet [1998-2004] = M100A, M101A, M110A, M111A   Duet [1998-2004] = M110A</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT22-RZH10E01</b> <b>90385-20005</b></p> <p>Hiace Van, Comuter [1989-2006] = LH1##, RZH10#, RZH11#, RZH125, RZH135, RZH15#   Hiace Van, Comuter</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p><b>AN22-S21E001</b> <b>56119-HA000</b></p> <p>Vanette [1999] = S21   E2000, E2200 [1997] = SD, SR   E2000, E2200 [1999] = SK, SL</p> <p>Shock Absorber Grommet Rubber</p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AN22-Y61E001</b> <b>56219-VB000</b></p> <p>Patrol [1997-2010] = Y61.. [GR]   Patrol Safari [1997-2006] = Y61</p> <p>Shock Absorber Grommet Rubber</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AN22-Z50E01</b> <b>56217-CA000</b></p> <p>Murano [2002-2007] = Z50   Presage [2003-2009] = NU31.. [4WD]   Presage [2003-2009] = U31   Quest [2</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AM22-V43000</b> <b>MB-584146</b></p> <p>Pajero [1991] = V43, V45</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AM22-V43001</b> <b>MR-132561</b></p> <p>Pajero [1991] = V43, V45</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AM22-T04001</b> <b>MR-992329</b></p> <p>Triton / L200 = KB4, KB8 [2.5, 3.2] [16V]</p> <p>Shock Absorber Grommet Rubber</p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AM22-T04002</b> <b>MR-992330</b></p> <p>Triton / L200 = KB4, KB8 [2.5, 3.2] [16V]</p> <p>Shock Absorber Grommet Rubber</p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AM22-A12100</b> <b>MB-108789</b></p> <p>Lancer [1978-1980] = A121</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	<p><b>AM22-E54001</b> <b>MB-910802</b></p> <p>Galant [1993] = E54, E55   Space Wagon [1992] = N31, N33</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AM22-CB1001</b> <b>MB-349789</b></p> <p>Lancer [1993] = CB1, CB2, CB4</p> <p>Shock Absorber Grommet Rubber</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT22-NC42</b> <b>48817-52010</b></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Stabilizer Link Grommet</p>   <p>www.rbi.ae www.alafuae.com</p>	<p><b>AO22-0920</b> <b>52314-SH3-000</b></p> <p>Civic [1988-1992]</p> <p>Stabilizer Link Grommet</p>   <p>www.rbi.ae www.alafuae.com</p>
<p><b>AT19-RI01</b> <b>90301-33001</b></p> <p>ALL CARS</p> <p>Exhaust / Silencer Pipe Ring</p>   <p>www.rbi.ae www.alafuae.com</p>	<p><b>AT19-RI02</b> <b>90301-34172</b></p> <p>ALL CARS</p> <p>Exhaust / Silencer Pipe Ring</p>   <p>www.rbi.ae www.alafuae.com</p>
<p><b>AT19-RI03</b> <b>20630-H5000</b></p> <p>ALL CARS</p> <p>Exhaust / Silencer Pipe Ring</p>  <p>www.rbi.ae www.alafuae.com</p>	
<p><b>AT13-U0001</b> <b>90303-22049</b></p> <p>Corolla / Altis [2001-2007] = ZZE12#   ST171, AT190, AE101</p> <p>Shock Absorber Mounting Seal Cover</p>   <p>www.rbi.ae www.alafuae.com</p>	
<p><b>AT22-0001</b> <b>90385-18068</b></p> <p>Corona [1982-1999] = TT140, CT140, CT140, RT140, TT14#, ST141, CT141, YT140   Carina [1981-1983] = T</p> <p>Idler Arm Bush</p>  <p>www.rbi.ae www.alafuae.com</p>	
<p><b>AT22-0003</b> <b>90386-18002</b></p> <p>Hilux/4Runner [4WD] [1988-1991] = LN111, 13#, RN110, 13#, VZN130, YN13#   Hilux2WD [1989-2001] = YN8</p> <p>Idler Arm Bush</p>  <p>www.rbi.ae www.alafuae.com</p>	
<p><b>AT22-SW05001</b> <b>41812-63J00</b></p> <p>Suzuki Swift [2003] = RS413, RS415, RS416   Suzuki SX4 [2006] = RW415, RW416, RW419, RW420</p> <p>Stabilizer Link Grommet</p>  <p>www.rbi.ae</p>	<p><b>AT22-SW93001</b> <b>09320-10024</b></p> <p>Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419   Suzuki Cultus [1995-2001] =</p> <p>Stabilizer Link Grommet</p>  <p>www.rbi.ae</p>
<p><b>AT19-ZE121</b> <b>90919-02239</b></p> <p>Toyota 4-Runner [2002-2009] = GRN21#, KZN215, UZN21#   Toyota Altezza, Altezza Gita [1998-2005] = GX</p> <p>Coil Spring Rubber</p>   <p>www.rbi.ae www.alafuae.com</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT23-021</b> <b>48675-22010</b>  <b>RT60</b>  <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-02Z</b> <b>48674-29015</b>  <b>RT60</b>  <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-022</b> <b>48674-22010</b>  <b>RT60</b>  <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-06Z</b> <b>48674-17065</b>  <b>TT141</b>  <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-22Y</b> <b>48674-12010</b>  <b>KE20</b>  <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-22Z</b> <b>48674-12010</b>  <b>KE20</b>  <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-23Y</b> <b>48674-12080</b>  <b>KE30</b>  <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-23Z</b> <b>48674-12080</b>  <b>KE30</b>  <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-24Y</b> <b>48674-14020</b>  <b>KE70</b>  <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-24Z</b> <b>48674-19095</b>  <b>KE70</b>  <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-0001</b> <b>90948-02036</b>  <b>FOR ALL CARS</b>  <b>Strut Bar Metal</b>	  <small>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT23-44Y</b> <b>48674-39045</b> <b>LN40   CROWN [1979-1983] = LS110, MS11#, RS110</b> <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-44Z</b> <b>48674-39045</b> <b>LN40</b> <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-46Y</b> <b>48674-22021</b> <b>LN85, TIGER   Corona [1985-1999] = RT142, ST141, CT141, YT140</b> <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-46Z</b> <b>48674-22021</b> <b>LN85</b> <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-65Y</b> <b>48674-26010</b> <b>LH112, LH60</b> <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-65Z</b> <b>48674-26010</b> <b>LH112, LH60</b> <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT23-67Y</b> <b>48674-26021</b> <b>RZH135</b> <b>Strut Bar Rubber</b>	  <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT23-67Z</b> <b>48674-26021</b> <b>RZH135</b> <b>Strut Bar Rubber Set [Set]</b>	  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT23-82Y</b> <b>48674-30020</b>  <b>MS50, MS60</b>  <b>Strut Bar Rubber</b>	  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT23-82Z</b> <b>48674-39025</b>  <b>MS50, MS60</b>  <b>Strut Bar Rubber Set [Set]</b>	  <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT23-84Y</b> <b>48674-30040</b>  <b>MS110</b>  <b>Strut Bar Rubber</b>	  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT23-84Z</b> <b>48674-30040</b>  <b>MS110</b>  <b>Strut Bar Rubber Set [Set]</b>	  <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT23-85Y</b> <b>48674-30031</b>  <b>MS120, MS132</b>  <b>Strut Bar Rubber [Bush 1]</b>	  <p>RBI-2006-February-09 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT23-85Z</b> <b>48674-30031</b>  <b>MS120, MS132</b>  <b>Strut Bar Rubber Set [Set]</b>	  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT23-85YS</b> <b>48674-30031</b>  <b>MS120, MS132</b>  <b>Strut Bar Rubber [Bush 2]</b>	  <p>RBI-2010-December-31 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>		
<b>AT23-85YY</b> <b>48674-30031</b>  <b>MS120, MS132</b>  <b>MEP-Strut Bar Rubber [Bush 3]</b>	  <p>RBI-2010-December-31 RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	<b>AT23-85ZY</b> <b>48674-30031</b>  <b>MS120, MS132</b>  <b>MEP-Strut Bar Rubber Set [Set]</b>	  <p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT23-UZS14FB</b> <b>48674-30070</b>  <p>Crown [1988-1995] = GS131   Crown, Crown Majesta [1991-1995] = UZS14#, JZS14#, LS141, GS141   Crown, <b>Strut Bar Rubber</b></p>	 <p>Perfect Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>		





## TOYOTA

Revision : 2014-November-01

<b>AT23-XT10</b> <b>48674-16030</b>  Corsa / Tercel [1982-1989] = AL2#  Strut Bar Rubber [FR]	 RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT23-XT11</b> <b>48675-16040</b>  Corsa / Tercel [1982-1989] = AL2#  Strut Bar Rubber [RE]	 RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT23-GX810</b> <b>48674-22141</b>  Mark II, Chaser, Cressida = GX81  Strut Bar Arm Bush	 RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT23-GX81R</b> <b>48667-22020</b>  Mark II, Chaser, Cressida = GX81  Strut Bar Retainer	 RBI-2009-December-12 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT23-CR27</b> <b>48674-28010</b>  CR27, KM36  Strut Bar Rubber	 RBI-2007-September-10 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT23-CV40</b> <b>48667-32020</b>  Camry Vista = CV40, SV40, SV41, SV42  Strut Bar Arm Bush [FR]	 RBI-2007-September-24 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT23-LJ7Y</b> <b>48674-60020</b>  Toyota Land Cruiser [84-90] = RJ70, LJ70  Strut Bar Rubber [RE]	 RBI-2008-January-13 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT23-KD200</b> <b>48674-26040</b>  Hiace / Regiusace [2005-2010] = KDH2##, TRH2##, LH2##  Strut Bar Rubber	 RBI-2008-August-19 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT23-KD20Z</b> <b>48674-26040</b>  Hiace / Regiusace [2005-2010] = KDH2##, TRH2##, LH2##  Strut Bar Rubber Set [Set]	 RBI-2011-August-23 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT23-SV20Y</b> <b>48674-22090</b>  Camry [1985-1991] = SV2#, VCV21   Mark II / Chaser / Cressida / Cresta [1984-1988] = RX7#, GX71, MX7  Strut Bar Arm Bush	 ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT23-M101F00</b> <b>48674-97202</b>  Duet [1998-2004] = M101A, M111A   Duet [1998-2004] = M110A [4WD]  Strut Bar Arm Bush	 TN-2013-March-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-C00W</b> <b>48654-32040</b>  Camry Vista [1982-1991] = SV1#, CV1#, SV2#, CV2#, VZV2# Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-96S</b> <b>48674-32030</b>  Camry Vista [1982-1986] = SV1#, CV1# Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
		<b>AT24-96B</b> <b>48674-32090</b>  Camry Vista [1986-1991] = SV2#, CV2#, VZV2# Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT24-C010</b> <b>48654-32020</b>  Camry Vista [1990-1998] = SV3#, VZV3#, CV3#, SV4#, CV4# Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT23-C01000</b> <b>48674-32110</b>  Camry Vista [1990-1998] = SV3#, VZV3#, CV3#, SV4#, CV4# Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-SV50E00</b> <b>48725-32280</b>  PREMIO / ALLION [2001] = AZT240, NZT240, ZZT240   VISTA / VISTA ARDEO [2000-2003] = AZV50, SV50, ZZV Rear Suspension Bush [RE]	RBI-2013-September-02 RBI Product, Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-SV50E01</b> <b>48705-32010</b>  Vista / Vista Ardeo [1998-2003] = AZV50, SV50 Rear Suspension Bush [RE]	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-ASL30E00</b> <b>48725-08020</b>  Sienna [2003-2010] = ASL30, GSL20, GSL25, GSL30, GSL35, MCL20, MCL25 Rear Suspension Bush [RE]	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-C02WB</b> <b>48655-33040</b></p>  <p>Camry [1991-1996] = SXV1#, MCV1#, VCV1#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-C02WS</b> <b>48654-33040</b></p>  <p>Camry [1991-2001] = SXV1#, MCV1#, VCV1#, SXV2#, MCV2#   Camry [2002-2006] = ACV36, MCV36</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-C03</b> <b>48655-06030</b></p>  <p>Camry [1996-2001] = SXV2#, MCV2#   Camry [2002-2006] = ACV36, MCV36</p> <p>Front Lower Arm Bush [FR, Big]</p>	
<p><b>AT24-C02LCRZ</b> <b>48068-33010</b></p>  <p>Camry [1991-2001] = SXV1#, MCV1#, VCV1#, SXV2#, MCV2#   Camry [2002-2006] = ACV36, MCV36</p> <p>Front Complete Lower Arm [FR, RH] [With 2 Bush]</p>	<p><b>AT24-C02LCLZ</b> <b>48069-33010</b></p>  <p>Camry [1991-2001] = SXV1#, MCV1#, VCV1#, SXV2#, MCV2#   Camry [2002-2006] = ACV36, MCV36</p> <p>Front Complete Lower Arm [FR, LH] [With 2 Bush]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-C04WB</b> <b>48655-28020</b></p> <p>Camry [2002-2011] = ACV3#, MCV3#, ACV4#, GSV4#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-C04WS</b> <b>48654-28060</b></p> <p>Camry [2002-2011] = ACV3#, MCV3#, ACV4#, GSV4#</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-C04WBLJ</b> <b>43340-39545</b></p> <p>Toyota Camry [2006] = ACV40, GSV40   Toyota Camry, Aurion [2006] = ACV40, GSV40.. [ARL]   Toyota Cam</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<p><b>AT24-C04WBRJ</b> <b>43330-39775</b></p> <p>Toyota Camry [2006] = ACV40, GSV40   Toyota Camry, Aurion [2006] = ACV40, GSV40.. [ARL]   Toyota Cam</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<p><b>AT24-GSV40WB</b> <b>48068-33060</b></p> <p>Lexus ES240, ES350 [2006] = ACV40, GSV40</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-GSV40WS</b> <b>48068-33060</b></p> <p>Lexus ES240, ES350 [2006] = ACV40, GSV40</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-GSV40WBLJ</b> <b>43340-09040</b></p> <p>Toyota Avalon [2005-2010] = GSX30   Toyota Camry [2006] = ACV40, GSV40   Toyota Camry HV [2006] = AH</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<p><b>AT24-GSV40WBRJ</b> <b>43330-09330</b></p> <p>Toyota Avalon [2005-2010] = GSX30   Toyota Camry [2006] = ACV40, GSV40   Toyota Camry HV [2006] = AH</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<p><b>AT24-MCV30WB</b> <b>48655-58011</b></p> <p>Toyota Solara [2003-2008] = MCV3#</p> <p>Front Lower Arm Rubber [FR, Big]</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-C05LCRZ</b> <b>48068-33060</b>  Camry [2007-2011] = ACV4#, GSV4# Front Complete Lower Arm [FR, RH] [With 2 Bush]	<b>AT24-C05LCLZ</b> <b>48069-33060</b>  Camry [2007-2011] = ACV4#, GSV4# Front Complete Lower Arm [FR, LH] [With 2 Bush]
<b>AT24-C06LCRZ</b> <b>48068-33050</b>  Camry [2007-2011] = ACV4#, GSV4# Front Complete Lower Arm [FR, RH] [With 2 Bush]	<b>AT24-C06LCLZ</b> <b>48069-33050</b>  Camry [2007-2011] = ACV4#, GSV4# Front Complete Lower Arm [FR, LH] [With 2 Bush]
<b>AT24-ACU3LCRZ</b> <b>48068-48020</b>  Kluger / Harrier / Lexus RX300, RX330, RX350 [2003-2007] = ACU3#, MCU28, MCU3#, GSU3# Front Complete Lower Arm [FR, RH] [With 2 Bush]	<b>AT24-ACU3LCLZ</b> <b>48069-48020</b>  Kluger / Harrier / Lexus RX300, RX330, RX350 [2003-2007] = ACU3#, MCU28, MCU3#, GSU3# Front Complete Lower Arm [FR, LH] [With 2 Bush]
<b>AT24-AGV10LCLZ</b> <b>48069-0T011</b>  Toyota Venza [2008] = AGV1#, GGV1# Front Complete Lower Arm [FR, LH] [With 2 Bush]	<b>AT24-AGV10LCRZ</b> <b>48068-0T011</b>  Toyota Venza [2008] = AGV1#, GGV1# Front Complete Lower Arm [FR, RH] [With 2 Bush]
<b>AT24-GSU40LCLZ</b> <b>48069-48040</b>  Toyota Highlander, Kluger [2007] = ASU40, GSU4#, GVU48, MHU48 Front Complete Lower Arm [FR, LH] [With 2 Bush]	<b>AT24-GSU40LCRZ</b> <b>48068-48040</b>  Toyota Highlander, Kluger [2007] = ASU40, GSU4#, GVU48, MHU48 Front Complete Lower Arm [FR, RH] [With 2 Bush]





# AL LAMSA AL FIDDIYA TRADING L.L.C.



ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01

<p>AT25-MCL10E1</p> <p>48725-08010</p> <p>Toyota Sienna [1997-2003] = MCL10</p> <p>Rear Suspension Bush [RE]</p>	<p>PFT-2014-October-01 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  <p><b>PERFECT</b> RUBBER PARTS</p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-C02S4</b> <b>48725-33025</b></p> <p>Camry [1991-1996] = SXV1#</p> <p>Rear Suspension Bush [RE, Small]</p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT25-C02S3</b> <b>48716-12040</b></p> <p>Camry [1991-1996] = SXV1#   AE92   Avalon [2005-2007] = GSX30   Camry / Vista [1990-1998] = SV30, SV</p> <p>Rear Suspension Bush [RE]</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-C02S2</b> <b>48716-12040</b></p> <p>Camry [1991-1996] = SXV1#   AE92   Avalon [2005-2007] = GSX30   Camry / Vista [1990-1998] = SV30, SV</p> <p>Rear Suspension Bush [RE]</p> <p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT25-C02S</b> <b>48716-12040</b></p> <p>Camry [1991-1996] = SXV1#   AE92   Avalon [2005-2007] = GSX30   Camry / Vista [1990-1998] = SV30, SV</p> <p>Rear Suspension Bush [RE]</p> <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-C010</b> <b>48725-32030</b></p> <p>Camry / Vista [1990-1998] = SV30, SV35, SV40, CV30, CV40, VZV30   Caldina [1997-2002] = ST215, CT216</p> <p>Rear Suspension Bush [RE]</p> <p>RBI-2005-May-23 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT25-C021L1RZ</b> <b>48730-33020</b></p> <p>Camry [1991-1996] = SXV1#, MCV1#, VCV1#</p> <p>Rear Complete Suspension Arm [RE, RH] No.1</p> <p>PFT-2012-March-28 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-C021L1LZ</b> <b>48740-33020</b></p> <p>Camry [1991-1996] = SXV1#, MCV1#, VCV1#</p> <p>Rear Complete Suspension Arm [RE, LH] No.1</p> <p>PFT-2012-March-28 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT25-C03R</b> <b>48730-33050</b></p> <p>Camry [1996-2001] = SXV2#, MCV2#</p> <p>Rear Complete Suspension Arm [RE, RH] No.1</p> <p>RBI-2012-May-31 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-C03L</b> <b>48740-33060</b></p> <p>Camry [1996-2001] = SXV2#, MCV2#</p> <p>Rear Complete Suspension Arm [RE, LH] No.1</p> <p>RBI-2012-May-31 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT25-C032L1Z</b> <b>48730-AA020</b></p> <p>Camry [1996-2001] = SXV2#, MCV2#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.1</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA





Revision : 2014-November-01

<p>AT25-C020 48725-03010</p>  <p>Camry [1991-2001] = SXV1#, SXV20</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product</p> <p><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a></p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p>AT25-C021L2Z 48710-33030</p>  <p>Camry [1991-1996] = SXV1#, MCV1#, VCV1#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.1</p>	<p>PFT-2012-March-28 Perfect Product, HFC Product, Ashimori Product</p> <p><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a></p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>AT25-C03E 48710-33050</p>  <p>Camry [1996-2001] = SXV2#, MCV2#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.1</p>
<p>AT25-C032L2Z 48710-33040</p> <p>Camry [1996-2001] = SXV2#, MCV2#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.1</p>	<p>HFC Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p>AT25-C021L3Z 48780-12010</p> <p>Camry [1991-1996] = SXV1#, MCV1#, VCV1#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.3</p>	<p>HFC Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>AT25-C031L3Z 48780-33010</p> <p>Camry [1996-2001] = SXV2#, MCV2#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.3</p>



**TOYOTA**

Revision : 2014-November-01

<p><b>AT25-C040</b>  <b>48725-12460</b></p>  <p>Toyota Camry [2001-2006] = ACV3#, MCV3#</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2008-July-11  RBI Product, Perfect Product,  Tenacity Product, HFC  Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
<p><b>AT25-C04B</b>  <b>48725-48020</b></p>  <p>Toyota Camry [2001-2006] = ACV3#, MCV3#</p> <p>Rear Suspension Bush [RE, Big]</p>	<p>RBI-2008-April-24  RBI Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
	<p><b>AT25-C04S</b>  <b>48725-48020</b></p>  <p>Toyota Camry [2001-2006] = ACV3#, MCV3#</p> <p>Rear Suspension Bush [RE, Small]</p>
	<p><b>AT25-C04E0Z</b>  <b>48780-12020</b></p> <p>Toyota Camry [2001-2006] = ACV3#, MCV3#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.3</p>
<p><b>AT25-C05E0</b>  <b>48780-06040</b></p>  <p>Toyota Camry / Aurion / Hybrid / HV [2006-2011]  = ACV4#, AHV4#, ASV40, GSV40..[Japan, ARL,  Asia]</p> <p>Rear Suspension Bush [RE, LH, RH]</p>	<p>RBI-2008-July-17  RBI Product, Tenacity  Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
	<p><b>AT25-C05E0Z</b>  <b>48780-06040</b></p> <p>Toyota Camry / Aurion / Hybrid / HV [2006-2011]  = ACV4#, AHV4#, ASV40, GSV40..[Japan, ARL,  Asia]</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.3</p>
	<p><b>AT25-C05E1Z</b>  <b>48710-06100</b></p> <p>Toyota Camry / Aurion / Hybrid / HV [2006-2011]  = ACV4#, AHV4#, ASV40, GSV40..[Japan, ARL,  Asia]</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.1</p>
<p><b>AT25-ACU10E0</b>  <b>48725-20370</b></p>  <p>Harrier [1997-2003] = ACU1#, MCU1#, SXU1#</p> <p>Rear Suspension Bush [RE, LH, RH]</p>	<p>TN-2014-February-10  Tenacity Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
	<p><b>AT25-ACU10EZ</b>  <b>48710-48020</b></p> <p>Harrier [1997-2003] = ACU1#, MCU1#, SXU1#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.1</p>

**TOYOTA**

Revision : 2014-November-01

<b>AT25-ACU35E01</b> <b>48725-48035</b> Harrier / Lexus RX300 / RX330 / RX350 / RX400H [2003-2005] = ACU35, MCU35, MHU38, GSU35   Highlander Rear Suspension Bush [RE]	PFT-2014-March-25 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-ACU35E02</b> <b>48725-48115</b> Harrier / Lexus RX300 / RX330 / RX350 / RX400H [2003-2006] = ACU35, MCU35, MHU38, GSU35   Highlander Rear Suspension Bush [RE]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-ACU35E03</b> <b>48725-48055</b> Harrier / Lexus RX300 / RX330 / RX350 / RX400H [2003-2006] = ACU35, MCU35, MHU38, GSU35   Highlander Rear Suspension Bush [RE]	PFT-2014-March-25 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT25-C04E</b> <b>48710-33070</b> Toyota Camry [2001-2006] = ACV3#, MCV3# Rear Suspension Bush [RE]	RBI-2008-February-28 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-C04EZ</b> <b>48710-33070</b> Toyota Camry [2001-2006] = ACV3#, MCV3# Rear Complete Suspension Arm [RE, LH, RH] No.1	HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-C04L00</b> <b>48740-33080</b> Toyota Camry [2001-2006] = ACV3#, MCV3# Rear Suspension Bush [RE, LH]	RBI-2008-April-02 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-C04R00</b> <b>48730-33080</b> Toyota Camry [2001-2006] = ACV3#, MCV3# Rear Suspension Bush [RE, RH]	RBI-2008-April-02 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-C04ELZ</b> <b>48740-33080</b> Toyota Camry [2001-2006] = ACV3#, MCV3# Rear Suspension Bush [RE, LH]	RBI-2014-July-14 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-C04ERZ</b> <b>48730-33080</b> Toyota Camry [2001-2006] = ACV3#, MCV3# Rear Complete Suspension Arm [RE, RH]	RBI-2014-July-14 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-C05ELZ</b> <b>48740-33100</b> Toyota Camry / Aurion / Hybrid / HV [2006-2011] = ACV4#, AHV4#, ASV40, GSV40..[Japan, ARL, Asia] Rear Complete Suspension Arm [RE, LH]	RBI-2014-July-14 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-C05ERZ</b> <b>48730-33150</b> Toyota Camry / Aurion / Hybrid / HV [2006-2011] = ACV4#, AHV4#, ASV40, GSV40..[Japan, ARL, Asia] Rear Complete Suspension Arm [RE, RH]	RBI-2014-July-14 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-C04ZZ2</b> <b>48740-48070</b> Toyota Highlander, Kluger [2000-2007] = ACU2#, MCU2#, MHU2# Rear Complete Suspension Arm [RE, LH, RH] No.1	ASH-2012-December-25 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-ACU25L1Z</b> <b>48710-48010</b>  ACU10, SXU10 [1997-2000]  Rear Complete Suspension Arm [RE, RH]	<small>ASH-2013-July-10 Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	
<b>AT25-ACU25L2Z</b> <b>48730-48050</b>  ACU10, SXU10 [1997-2000]  Rear Complete Suspension Arm [RE, LH]	<small>ASH-2013-July-10 Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT25-ACU25L3Z</b> <b>48780-48020</b>  Highlander [2000-2007] = ACU20, MCU20  Rear Complete Suspension Arm [RE]












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-J122WB</b> <b>48655-87401</b></p>  <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-J122WS</b> <b>48654-87402</b></p>  <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT25-J122C1</b> <b>48745-87602</b></p>  <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Rear Suspension Bush [RE, Big]</p>	
<p><b>AT25-J122E1B</b> <b>48725-87402</b></p>  <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Rear Suspension Bush [RE, Big]</p>	<p><b>AT25-J122E1S</b> <b>48727-87403</b></p>  <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Rear Suspension Bush [RE, Small]</p>
<p><b>AT25-J122LA1RZ</b> <b>48710-87402</b></p>  <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Rear Complete Suspension Arm [RE] [RH] No.1</p>	<p><b>AT25-J122LA1LZ</b> <b>48770-87402</b></p>  <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Rear Complete Lower Arm No.1 [RE] [LH]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-M101WS</b> <b>48654-87203</b></p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Duet [1998-2004] = M101A, M111A   Duet [1998-2004] = M110A [4WD]</p> <p>Front Lower Arm Bush [FR, Small]</p>	
<p><b>AT24-M101LCLZ</b> <b>48069-97201</b></p> <p>ARP Product www.rbi.ae</p> <p>Duet [1998-2004] = M100A, M101A, M110A, M111A   Duet [1998-2004] = M110A.. [4WD]   Daihatsu Storia [</p> <p>Front Complete Lower Arm [FR, LH]</p>	<p><b>AT24-M101LCRZ</b> <b>48068-97201</b></p> <p>ARP Product www.rbi.ae</p> <p>Duet [1998-2004] = M100A, M101A, M110A, M111A   Duet [1998-2004] = M110A.. [4WD]   Daihatsu Storia [</p> <p>Front Complete Lower Arm [FR, RH]</p>
<p><b>AT25-M101E01</b> <b>48725-97201</b></p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Duet [1998-2004] = M101A, M111A   Duet [1998-2004] = M110A [4WD]</p> <p>Rear Suspension Bush [RE]</p>	
<p><b>AT25-M101E02B</b> <b>48725-97202</b></p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Duet [1998-2004] = M101A, M111A   Duet [1998-2004] = M110A [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p><b>AT25-M101E02S</b> <b>48727-97401</b></p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Duet [1998-2004] = M101A, M111A   Duet [1998-2004] = M110A [4WD]</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-M101E04</b> <b>48537-97201</b></p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Duet [1998-2004] = M101A, M111A   Duet [1998-2004] = M110A [4WD]</p> <p>Rear Suspension Bush [RE]</p>	



## TOYOTA

Revision : 2014-November-01

<b>AT24-F60WB</b> <b>48655-BZ010</b>  A Vanza [2003-2009] = F601, F602 [USA] Front Lower Arm Bush [FR, Big]	RBI-2009-November-18 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT24-F60WS</b> <b>48654-BZ010</b>  A Vanza [2003-2009] = F601, F602 [USA] Front Lower Arm Bush [FR, Small]	RBI-2009-November-03 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT24-F60WBJ</b> <b>#48068-BZ010</b> ARP Product www.rbi.ae Toyota Avanza [2003] = F601, F602 Front Lower Arm Ball Joint [FR, LH, RH]			
<b>AT24-F61WB</b> <b>48655-B1010</b>  A Vanza [2003-2009] = F601, F602 [USA]   BB [2006] = QNC20, QNC25.. [4WD]   Passo [2004-2010] = KGC10 Front Lower Arm Bush [FR, Big]	TN-2013-September-10 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT24-F61WS</b> <b>48654-B2010</b>  A Vanza [2003-2009] = F601, F602 [USA]   BB [2006] = QNC20, QNC25.. [4WD]   Passo [2004-2010] = KGC10 Front Lower Arm Bush [FR, Small]	RBI-2013-September-02 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT24-F62WB</b> <b>48655-B1020</b>  Toyota BB [2006] = QNC2# Front Lower Arm Bush [FR, Big]	RBI-2013-December-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT24-J200WB</b> <b>48655-B4011</b>  Toyota Rush [2006-2012] = J200E, J210E, F700   Daihatsu Be-Go [2006] = J200G   Daihatsu Terios [2006] Front Lower Arm Bush [FR, Big]	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT24-J200WBJ</b> <b>#48068-B4010</b> ARP Product www.rbi.ae Daihatsu Be-Go [2006] = J200G   Daihatsu Be-Go [2006] = J210G.. [4WD]   Daihatsu Terios [2006] = J20 Front Lower Arm Ball Joint [FR, LH, RH]	
<b>AT24-F601LCRZZ</b> <b>48068-BZ010</b> Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com A Vanza [2003-2006] = F601 [USA] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]		<b>AT24-F601LCLZZ</b> <b>48069-BZ010</b> Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com A Vanza [2003-2006] = F601 [USA] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	
<b>AT25-F60E00</b> <b>48704-BZ010</b>  A Vanza [2003-2009] = F601, F602 [USA] Rear Suspension Bush [RE]	ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT26-F60E00</b> <b>90043-85149</b>  Avanza [2003] = F601, F602   CAMI [1999-2005] = J100E, J102E, J122E   Liteace / Townace [2008] = S40 Suspension Rubber [RE]	TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-21W</b> <b>48061-12010</b>  <b>KE10</b>   <b>Front Lower Arm Bush [FR, Big]</b>	<small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small>  <small><a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small>	<b>AT24-22W</b> <b>48654-12010</b>  <b>KE20, KE30, KE7#, TA1#, TA4#, MA4#, RA4#, TA6#, AA6#, SA6#, RA6#, KA6#, CA6#, M6#, RT14#, CT14#, ST1</b>   <b>Front Lower Arm Bush [FR, Small]</b>	<small>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small>  <small><a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small>




















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-241</b> <b>48706-14010</b>  <b>KE70, TT141</b>  Rear Suspension Bush [RE]	  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-242</b> <b>90385-20001</b>  <b>KE70</b>  Rear Suspension Bush [RE]	  RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-243</b> <b>12375-12072</b>  <b>KE70</b>  Rear Suspension Bush [RE]	  RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-244</b> <b>12375-12070</b>  <b>KE70</b>  Rear Suspension Bush [RE]	  RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-24GZ</b> <b>48702-12040</b>  <b>KE70</b>  Rear Complete Suspension Arm [RE] [Long]	  RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-24TZ</b> <b>48702-12020</b>  <b>KE70</b>  Rear Complete Suspension Arm [RE]	  RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-24GT</b> <b>48725-12020</b>  <b>KE70</b>  Rear Suspension Bush [RE]	  ARD-2014-January-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-24P</b> <b>48725-12030</b>  <b>KE70</b>  Rear Suspension Bush [RE]	  ARD-2014-January-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-25WB</b> <b>48655-20030</b></p> <p>AE80   Corona &amp; Carina [1983-1987] = AT15#, ST15#, CT15#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-25WS</b> <b>35654-20060</b></p> <p>AE80   Corona &amp; Carina [1983-1987] = AT15#, ST15#, CT15#</p> <p>Front Lower Arm Bush [FR, Small, ID=12.10mm]</p>
	<p><b>AT24-25WS2</b> <b>48654-20065</b></p> <p>AE80   Corona &amp; Carina [1983-1987] = AT15#, ST15#, CT15#</p> <p>Front Lower Arm Bush [FR, Small, ID=10.20mm]</p>
<p><b>AT24-ST160WB</b> <b>48655-20050</b></p> <p>Celica [1985-1989] = AT160, ST162, ST182</p> <p>Front Lower Arm Bush [FR, Big]</p>	
<p><b>AT24-28WB</b> <b>48655-12010</b></p> <p>EE90, AE92</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-28WS</b> <b>48654-12050</b></p> <p>EE90, AE92   Prius [1997-2003] = NHW1#   Vista / Vista Ardeo [1998-2003] = AZV5#, SV5#, ZZV50</p> <p>Front Lower Arm Bush [FR, Small]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-30WB</b> <b>48655-12050</b></p> <p>AE10#, EE10#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-30WS</b> <b>48654-12070</b></p> <p>EE10#, AE10#</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-EE104WB</b> <b>48655-12080</b></p> <p>Toyota Sprinter [1993-1995] = AE100, EE101, EE102, EE103, EE104</p> <p>Front Lower Arm Bush [FR, Big]</p>	
<p><b>AT24-29WL</b> <b>48076-12010</b></p> <p>EE10#, AE10#</p> <p>Front Lower Arm Bush [Bracket] [FR, Big, LH]</p>	<p><b>AT24-29WR</b> <b>48075-12010</b></p> <p>EE10#, AE10#</p> <p>Front Lower Arm Bush [Bracket] [FR, Big, RH]</p>









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-31WB</b> <b>48655-12120</b>  Toyota Corolla / HB / LB [1995-2001] = AE11#, CDE110, CE11#, EE11#, WZE110, ZZE11#  Front Lower Arm Bush [FR, Big]	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small> 	<b>AT24-31WS</b> <b>48654-12090</b>  Toyota Corolla / HB / LB [1995-2001] = AE11#, CDE110, CE11#, EE11#, WZE110, ZZE11#  Front Lower Arm Bush [FR, Small]	 <small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></small> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-25E</b> <b>48725-32070</b>  <b>ST150, AE80</b>  Rear Suspension Bush [RE]	  <p>RBI-OLD RBI Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<b>AT25-283</b> <b>48725-12290</b>  <b>EE90, AE92</b>  Rear Suspension Bush [RE]	  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT25-284</b> <b>48725-12110</b>  <b>EE90, AE92</b>  Rear Suspension Bush [RE]
<b>AT26-28E</b> <b>48725-12050</b>  <b>EE90, AE92</b>  Rear Suspension Bush [RE]	  <p>RBI-2005-January-11 RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT26-280</b> <b>48725-12300</b>  <b>EE90, AE92</b>  Rear Suspension Bush [RE]
<b>AT26-28B</b> <b>48725-12040</b>  <b>EE90, AE92, AE90</b>  Rear Suspension Bush [RE]	  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT26-28S</b> <b>48725-16080</b>  <b>EE90, AE92</b>  Rear Suspension Bush [RE]
<b>AT26-250</b> <b>43474-20050</b>  <b>AE80, AE92, AE101</b>  Rear Suspension Bush [RE]	  <p>RBI-OLD RBI Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<b>AT25-281</b> <b>48725-12150</b>  <b>EE90</b>  Rear Suspension Bush [RE]	  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT25-282</b> <b>48725-20380</b>  <b>AE92, AE101, ST171</b>  Rear Suspension Bush [RE]
		<b>AT25-282ZZ</b> <b>48780-20040</b>  <b>ST171, AT171</b>  Rear Complete Suspension Arm [RE]








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-301</b> <b>48725-12200</b></p> <p><b>EE100, AE101</b></p> <p>Rear Suspension Bush [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-302</b> <b>48725-12240</b></p> <p><b>EE100, AE101</b></p> <p>Rear Suspension Bush [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT25-31S</b> <b>48725-12370</b></p> <p>Camry Gracia [1996-2001] = MCV21, SXV20   Corolla / Spacio / Sprinter / Carib [1991-2002] = AE10#, A</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-309</b> <b>48725-32010</b></p> <p><b>EE100, AE101</b></p> <p>Rear Suspension Bush [RE]</p>  <p>ARD-2014-January-01 Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT25-3092</b> <b>48725-12440</b></p> <p>Corolla [1991-1997] = AE100, EE100, CE100   Corolla [1995-2001] = AE115 [4WD]   Corolla Spacio [1998]</p> <p>Rear Suspension Bush [RE]</p>  <p>Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-ZE121B</b> <b>48655-12170</b></p> <p>Corolla / Altis [2001-2011] = ZZE12#, ZRE120, NZE12#, CE120, ZZE14#, NZE141, CE140   Wish [2003] = A</p> <p>Front Lower Arm Bush [FR, Big] [Light Duty]</p>	<p><b>AT24-ZE121S</b> <b>48654-12120</b></p> <p>Corolla / Altis [2001-2011] = ZZE12#, ZRE120, NZE12#, CE120, ZZE14#, NZE141, CE140</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-ZE121T</b> <b>48655-12170T</b></p> <p>Corolla / Altis [2001-2011] = ZZE12#, ZRE120, NZE12#, CE120, ZZE14#, NZE141, CE140   Wish [2003] = A</p> <p>Front Lower Arm Bush [FR, Big] [Heavy Duty]</p>	<p><b>AT24-ZZE130WB</b> <b>48655-12180</b></p> <p>Toyota Corolla / Matrix [2002-2006] = ZZE130</p> <p>Front Lower Arm Bush [FR, Big, Light Duty]</p>
<p><b>AT24-W11WB</b> <b>48655-21010</b></p> <p>Corolla / Altis [2001-2011] = ZZE12#, ZRE120, NZE12#, CE120, ZZE14#, NZE141, CE140   Wish [2003] = A</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-W11WS</b> <b>48654-21010</b></p> <p>Wish [2003] = ANE1#</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-ZE121WBJ</b> <b>43330-09210</b></p> <p>Toyota Avensis [2003-2008] = ADT25#, AZT25#, CDT250, ZZT25#   Toyota Avensis [2003-2008] = AZT255..</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	
<p><b>AT24-ZE14LCRZZ</b> <b>48068-12290</b></p> <p>Corolla / Altis [2007-2011] = ZZE14#, NZE141, CE140</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint &amp; 2 Bush]</p>	<p><b>AT24-ZE14LCLZZ</b> <b>48069-12290</b></p> <p>Corolla / Altis [2007-2011] = ZZE14#, NZE141, CE140</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint &amp; 2 Bush]</p>










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT24-ZE151B</b>  <b>48655-12210</b></p> <p>Corolla / Altis [2006-2011] = ZZE150</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2012-June-26  Perfect Product, HFC Product,  Ashimori Product</p> <p><b>PERFECT</b>  RUBBER PARTS</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT24-ADT27WB</b>  <b>48655-02060</b></p> <p>Toyota Avensis [2008] = ADT27#, ZRT27#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2012-June-26  Perfect Product</p> <p><b>PERFECT</b>  RUBBER PARTS</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT24-AZE15WB</b>  <b>48655-02080</b></p> <p>Toyota Blade [2006] = AZE154.. [4WD]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2012-June-26  Perfect Product</p> <p><b>PERFECT</b>  RUBBER PARTS</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-ZE121E</b> <b>48725-02240</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Rear Suspension Bush [RE] [LH, RH]</p> <p>RBI-2007-March-24 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-Z122E</b> <b>48725-12550</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Rear Suspension Bush [RE] [LH, RH]</p> <p>TN-2012-March-06 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT25-ZE141E</b> <b>48725-02310</b></p>  <p>Corolla / Altis [2008-2013] = ZZE14#</p> <p>Rear Suspension Bush [RE] [LH, RH]</p> <p>RBI-2011-December-12 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT25-Z151E</b> <b>48725-12590</b></p>  <p>Corolla / Auris [2006] = ADE150, NDE150, ZRE151, ZRE152, ZZE150</p> <p>Rear Suspension Bush [RE] [LH, RH]</p> <p>RBI-2013-April-27 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT26-ZE121</b> <b>48537-02010</b></p>  <p>Corolla / Altis [2001-2007] = ZZE12#</p> <p>Front Shock Absorber Bush [RE]</p> <p>RBI-2007-October-22 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT25-NZE12E00</b> <b>48725-12560</b></p>  <p>Corolla / Fielder / Corolla Runx / Corolla Spacio [2000-2006] = CE121, NZE120, 121, ZZE122, 123   Co</p> <p>Rear Suspension Bush [RE, RH]</p> <p>PFT-2012-March-28 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT25-NZE15E001</b> <b>48725-12600</b></p>  <p>Toyota Auris [2006] = NZE154, ZRE154.. [4WD]   Toyota Auris, Hybrid [2007] = ADE15#, NDE150, NRE150,</p> <p>Rear Suspension Bush</p> <p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-W110E</b> <b>48725-32250</b>  Wish [2003] = ANE1# Rear Suspension Bush [RE]	RBI-2012-April-05 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-W111E</b> <b>48770-20020</b>  Wish [2003-2005] = ANE1#   Celica [1999-2005] = ZZT231   Wish [2003] = ZNE14   Corolla [2004-2006] = Rear Suspension Bush [RE]	RBI-2012-April-26 RBI Product, Tenacity Product shabbirh@eim.ae  35.00 www.rbi.ae www.alafuae.com 42.80 12.30
<b>AT25-W11E</b> <b>48070-68020</b>  Corolla / Altis [2001-2007] = ZZE12#   Wish [2003] = ANE1# Rear Suspension Bush [RE]	RBI-2010-May-19 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT25-W11ERZ</b> <b>48070-68020</b>  Wish [2003] = ANE1# Rear Suspension Bush [Bracket] [RE, LH]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-W11ELZ</b> <b>48060-68020</b>  Wish [2003] = ANE1# Rear Suspension Bush [Bracket] [RE, RH]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-ZGE20E00</b> <b>48725-12640</b>  Wish [2009] = ZGE20, ZGE21 Rear Suspension Bush [RE, RH]	PFT-2012-March-28 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT26-ZE141</b> <b>43474-12130</b>  Corolla / Altis [2008-2013] = ZZE14# Damper Drive Shaft Metal [RE]	RBI-2010-November-02 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT26-ZE141E</b> <b>48537-02080</b>  Toyota Corolla [2007] = ZZ141 Front Shock Absorber Bush [RE]	RBI-2013-June-15 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT24-02P 48632-22010</p> <p>RT60</p>  <p>Front Upper Arm Bush [FR, Small]</p>	<p>AT24-02W 48654-22010</p> <p>RT60, MX12</p>  <p>Front Lower Arm Bush [FR, Small]</p>
<p>AT24-04P 48091-12010</p> <p>Corona [1973-1979] = RT10#, RT11#</p>  <p>Front Upper Arm Bush [FR]</p>	
<p>AT24-04W 48061-20020</p> <p>Corona [1973-1979] = RT10#, RT11#</p>  <p>Front Lower Arm Bush [FR, Big]</p>	















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-08WB</b> <b>48655-20060</b>  Corona & Carina [1987-1992] = AT17#, ST17#, CT17# Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-08WS</b> <b>48068-20200</b>  Corona & Carina [1987-1992] = AT17#, ST17#, CT17# Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT24-08WLB</b> <b>48076-20010</b>  Corona & Carina [1987-1992] = AT17#, ST17#, CT17# Front Lower Arm Bush [Bracket] [FR, Big, LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-08WRB</b> <b>48075-20010</b>  Corona & Carina [1987-1992] = AT17#, ST17#, CT17# Front Lower Arm Bush [Bracket] [FR, Big, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT24-08LCR1</b> <b>48068-20200</b>  Corona & Carina [1987-1992] = AT17#, ST17#, CT17# Front Complete Lower Arm [FR, RH] [With 1 Bush]	ARP Product  <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		





**TOYOTA**

Revision : 2014-November-01

<p><b>AT24-09WB</b>  <b>48655-20140</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-09WBJ</b>  <b>43330-19095</b></p> <p>Tenacity Product  Toyota Caldina [1992-1997] = AT19#, ST19#, CT190   Toyota Caldina [1992-1997] = ST195.. [4WD]   Toyo</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<p><b>AT24-09WS</b>  <b>48654-20150</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p><b>AT24-09WS3</b>  <b>48654-20161</b></p> <p>TN-2012-March-06  Tenacity Product  Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-09WSB</b>  <b>48655-20140S</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Front Lower Arm Bush [FR, Big] [Small Hole, ID = 14.30]</p>	<p><b>AT24-09WS2</b>  <b>48654-05041</b></p> <p>PFT-2012-March-28  Perfect Product  Corona [1997-2003] = AT220, ST220   Avensis [1997-2003] = AT220, ZST220</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-11WB</b>  <b>48655-20221</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Front Lower Arm Bush [FR, Big, Light Duty]</p>	<p><b>AT24-11WS</b>  <b>48654-20190</b></p> <p>RBI-OLD  RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product  Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-11WT</b>  <b>48655-20221T</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#   Prius [1997-2003] = NHW1#  </p> <p>Front Lower Arm Bush [FR, Big] [Heavy Duty]</p>	
<p><b>AT24-11XB</b>  <b>48655-20260</b></p> <p>Toyota Caldina, Carina, Corona [1992-2002] = CT196, CT198, CT199, CT215, CT216, ST195, ST198, ST215</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-11XS</b>  <b>48654-20170</b></p> <p>PFT-2012-March-28  Perfect Product  Corona = AT195</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-CT190WB</b>  <b>48655-05011</b></p> <p>Corona [UK] [1992-1997] = AT190, CT190, ST191</p> <p>Front Lower Arm Bush [FR, Big]</p>	

## TOYOTA

Revision : 2014-November-01

<b>AT24-TE94WB</b> <b>48655-20210</b>  Toyota Celica [1993-1999] = AT200, ST20#, ST204 Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT24-TE94WS</b> <b>48654-20180</b>  Toyota Celica [1993-1999] = AT200, ST20#, ST204 Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT24-TE94WS2</b> <b>48068-20290</b>  Carina ED [1993-1999] = ST200   Celica [1993-1999] = ST200   Corona EXIV [1994-1998] = ST200   Curre Front Lower Arm Bush [FR, Small]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT24-TE94W</b> <b>48654-20100</b>  Toyota Celica [1989-1993] = AT180, ST18#, ST184 Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT24-ND04W</b> <b>48655-44020</b>  Ipsum, GAYA, Nadia [4WD] Front Lower Arm Bush [FR, Big]	RBI-2006-August-14 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT24-R01W0</b> <b>42304-12110</b>  Toyota Carina ED [1989-1999] = ST18#, ST20#   Toyota Corolla / Sprinter [1992-1997] = AE10#, CE10#, Front Lower Arm Bush [FR]	RBI-2006-May-01 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT24-X10W0</b> <b>48655-44010</b>  Toyota Gaia [1998-2004] = ACM1#, CXM10, SXM1#   Toyota Ipsum [1996-2001] = CXM10, SXM1#   Toyota Nad Front Lower Arm Bush [FR, Big]	RBI-2009-December-12 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT24-11WS2</b> <b>48654-44010</b>  Gaia [1998-2004] = ACM10, SXM10   Gaia [1998-2004] = ACM15, SXM15 [4WD]   Ipsum [1996-2001] = CXM10, Front Lower Arm Bush [FR, Small]	TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		<b>AT24-VP02WB</b> <b>48654-59035</b>  Ipsum, GAYA, Nadia Front Lower Arm Bush [FR, Big]	RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT24-ACM21WB</b> <b>48655-20310</b>  Toyota Ipsum [2001-2009] = ACM21 Front Lower Arm Bush [FR, Big]	PFT-2012-March-28 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT90-090</b> <b>90389-19002</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Cover Bush [FR, Metal]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT90-091</b> <b>90389-19003</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Cover Bush [FR, Metal]</p>  <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT90-092</b> <b>90389-21003</b></p> <p>Corona &amp; Carina [1996-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Cover Bush [FR, Metal]</p>  <p>PFT-2013-August-20 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>ARI90-NPRF</b> <b>8-94120021-0</b></p> <p>NPR</p> <p>Cover Bush</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AN24-H410</b> <b>54045-0T000</b></p> <p>H41</p> <p>Cover Bush [FR]</p>  <p>RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-AZT22WB</b> <b>48061-05010</b>  <p>Corona &amp; Carina [1997-2003] = AT22#, ST22#, CT22#   Avensis [1997-2003] = AZT22#, ZZT22#, CDT22#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2012-December-31 Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<b>AT24-ZZT23WB</b> <b>48655-20380</b>  <p>Celica [1999-2006] = ZZT23#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  <p><b>AT24-ZZT23WS</b>  <b>48654-20380</b>          ARP Product  <a href="http://www.rbi.ae">www.rbi.ae</a>          Celica [1999-2006] = ZZT23#</p> <p>Front Lower Arm Bush [FR, Small]</p>
<b>AT24-AZT25WBJ</b> <b>43330-09360</b> <p>Toyota Avensis [2003-2008] = ADT25#, AZT25#, CDT250, ZZT25#   Toyota Corolla Verso [2004-2009] = AUR</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>





## TOYOTA

Revision : 2014-November-01

<b>AT25-900</b> <b>48702-14010</b>  Celica = CT140, 2T, TT133, TT141   RT103  Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<b>AT25-050</b> <b>48702-22060</b>  Celica = CT140, 2T, TT133, TT141   RT103  Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<b>AT25-081</b> <b>48725-20070</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<b>AT25-082</b> <b>48725-32110</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<b>AT25-083</b> <b>48725-20050</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<b>AT25-084</b> <b>48725-20340</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<b>AT25-087</b> <b>48725-20140</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Rear Suspension Bush [RE, Big Hole]	<p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<b>AT25-088</b> <b>48725-20150</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Rear Suspension Bush [RE, Small Hole]	<p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<b>AT25-087Z</b> <b>48730-20030</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Rear Complete Suspension Arm [RE, LH, RH] No.1	<p>ARP Product www.rbi.ae</p>		
<b>AT25-ST1850Z</b> <b>48780-20060</b>  Celica [1991-1993] = ST185  Rear Complete Suspension Arm [RE, LH, RH] No.3	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>		
<b>AT25-08900</b> <b>48725-20149</b>  Toyota CORONA 1.6, 2.0 [1988-1992]  Rear Suspension Bush	<p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-1140</b> <b>48740-20080</b></p> <p>Corona &amp; Carina &amp; Caldina [1992-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Rear Suspension Bush [RE, Big] [LH, RH]</p>	<p><b>AT25-1125</b> <b>48725-20560</b></p> <p>Corona &amp; Carina &amp; Caldina [1992-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-1160</b> <b>48725-20590</b></p> <p>Corona &amp; Carina &amp; Caldina [1992-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Rear Suspension Bush [RE]</p>	<p><b>AT25-116Z</b> <b>48780-20080</b></p> <p>Corona &amp; Carina &amp; Caldina [1992-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] No.3</p>
<p><b>AT25-1126</b> <b>48725-20275</b></p> <p>Corona &amp; Carina &amp; Caldina [1992-2002] = AT19#, ST19#, CT19#, AT21#, ST21#, CT21#   Camry / Vista [19</p> <p>Rear Suspension Bush [RE]</p>	<p><b>AT25-1127</b> <b>48725-20390</b></p> <p>Toyota Caldina &amp; Carina &amp; Corona [1992-2002] = AT19#, ST19#, CT19#, ET196, AT21#, CT21#, ST21#   Toy</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-1128</b> <b>48725-20215</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994] = UCF1#   Caldina / Carina / Celica / Corona / Curren [1992-</p> <p>Rear Suspension Bush [RE]</p>	<p><b>AT25-1129</b> <b>48725-05065</b></p> <p>Avensis [1997-2003] = AT220, ZZT220   Corona [1997-2003] = AT220, ST220</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-1131</b> <b>48725-20460</b></p> <p>Carina ED [1993-1999] = ST200   Celica [1993-1999] = ST200   Corona EXIV [1994-1998] = ST200   Curre</p> <p>Rear Suspension Bush [RE]</p>	






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA



















Revision : 2014-November-01

<b>AT25-AZ250</b> <b>48725-05071</b>  Avensis [2003-2008] = AZT25#, ADT25#, CDT25#, ZZT25# Rear Suspension Bush [RE]	RBI-2012-May-31 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-AZ251</b> <b>48725-05141</b>  Avensis [2003-2008] = AZT25#, ADT25#, CDT25#, ZZT25# Rear Suspension Bush [RE]	RBI-2012-July-14 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-AZT25E3</b> <b>48725-05080</b>  Avensis [2003-2008] = AZT25#, ADT25#, CDT25#, ZZT25# Rear Suspension Bush [RE, Big]	RBI-2013-September-02 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-AZT25E4</b> <b>48725-21011</b>  Avensis [2003-2008] = AZT25#, ADT25#, CDT25#, ZZT25#   Caldina [2002-2007] = AZT240, ZZT240   Caldin Rear Suspension Bush [RE]	Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-AZT25E3LZ</b> <b>48704-05030</b>  Avensis [2003-2008] = AZT25#, ADT25#, CDT25#, ZZT25# Rear Complete Suspension Arm [RE, LH]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-AZT22E01Z</b> <b>48710-05050</b>  Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT220, CT22 Rear Complete Suspension Arm [RE]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-AZT22E02Z</b> <b>48780-05020</b>  Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT220, CT22 Rear Complete Suspension Arm [RE]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AT25-AZT22E03Z</b> <b>48730-05030</b>  Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT220, CT22 Rear Complete Suspension Arm [RE]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-AZT270E03</b> <b>48730-05070</b>  Avensis [2008] = AZT270 Rear Suspension Bush [RE, RH]	PFT-2012-December-31 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		



## TOYOTA

Revision : 2014-November-01

<b>AT25-ND024</b> <b>48725-44030</b>  Toyota Nadia [1998-2003] = ACN1#, SXN1# Rear Suspension Bush [RE]	RBI-2008-April-24 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT25-CXM10E1</b> <b>48725-44010</b>  Toyota Gaia [1998-2004] = ACM1#, CXM10, SXM1#   Toyota Ipsum [1996-2001] = CXM10, SXM1#   Toyota Pic Rear Suspension Bush [RE]	PFT-2014-October-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT25-ACM2E</b> <b>48725-44051</b>  Toyota Noah, Voxy [2001-2007] = AZR6#   Toyota Ipsum [2001-2009] = ACM2# Rear Suspension Bush [RE]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT25-ACM2E5</b> <b>48725-58010</b>  Toyota Isis [2004-2009] = ANM1#, ZGM1#, ZNM10   Toyota Alphard GV, HV [2002-2008] = ANH1#, MNH1#, AT Rear Suspension Bush [RE]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT25-ACM2E2</b> <b>48725-28050</b>  Toyota Estima T, L, Previa, Tarago [1999-2006] = ACR30, ACR40, MCR30, MCR40, CLR30   Toyota Estima H Rear Suspension Bush [RE]	RBI-2013-July-19 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT25-ACM2E3</b> <b>48725-28070</b>  Estima [2003] = ACR30, ACR40, MCR30, MCR40   Ipsum [2003] = ACM2#   Picnic / Avensis Verso [2003-200 Rear Suspension Bush [RE]	RBI-2014-February-04 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
<b>AT29-T11BS</b> <b>48725-28010</b>  Previo / Lucida [1990-1999] = TCR1#, TCR2# Rear Suspension Bush [RE] [B]	RBI-2005-May-07 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
<b>AT29-T11DB</b> <b>48725-28020</b>  Previo / Lucida [1990-1999] = TCR1#, TCR2# Rear Suspension Bush [RE] [D]	RBI-2005-May-07 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	<b>AT29-T11DBZ</b> <b>04374-28020</b>  Previo / Lucida [1990-1999] = TCR1#, TCR2# Rear Suspension Coupling Kit [RE] [D] [Bracket]	Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 














# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-RV1WB</b> <b>48075-42050</b>  Toyota Rav4 [1994-2000] = SXA1# Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-RV1WS</b> <b>48654-42020</b>  Toyota Rav4 [1994-2000] = SXA1# Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT24-RV1WRZ</b> <b>48075-42010</b>  Toyota Rav4 [1994-2000] = SXA1# Front Lower Arm Bush [Bracket] [FR, Big, RH]	TN-2012-March-06 Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-RV1WLZ</b> <b>48076-42010</b>  Toyota Rav4 [1994-2000] = SXA1# Front Lower Arm Bush [Bracket] [FR, Big, LH]	TN-2012-March-06 Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT24-RV1LCR1</b> <b>48068-42012</b>  Toyota Rav4 [1994-2000] = SXA1# Front Complete Lower Arm [FR, RH] [With 1 Bush]	Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-RV1LCL1</b> <b>48069-42012</b>  Toyota Rav4 [1994-2000] = SXA1# Front Complete Lower Arm [FR, LH] [With 1 Bush]	Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-RV10</b> <b>48725-42011</b></p>  <p>Toyota Rav4 [1994-2000] = SXA1#</p> <p>Rear Suspension Bush [RE]</p> <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>AT25-RV1E1</b> <b>48725-42030</b></p> <p>Toyota Rav4 [1994-2000] = SXA1#   Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Rear Suspension Bush [RE]</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT25-RV1E2</b> <b>48725-42020</b></p> <p>Toyota Rav4 [1994-2000] = SXA1#   Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Rear Suspension Bush [RE]</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT25-RV1LALZ</b> <b>48720-42010</b></p>  <p>Toyota Rav4 [1994-2000] = SXA1#</p> <p>Rear Complete Lower Arm [RE, RH]</p> <p>RBI-2014-July-14 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT25-RV1LARZ</b> <b>48730-42010</b></p> <p>Toyota Rav4 [1994-2000] = SXA1#</p> <p>Rear Complete Suspension Arm [RE, LH] No.1</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT25-RV1UALZ</b> <b>48770-42010</b></p>  <p>Toyota Rav4 [1994-2000] = SXA1#</p> <p>Rear Complete Upper Arm [RE, RH]</p> <p>RBI-2014-July-14 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT25-RV1UARZ</b> <b>48790-42010</b></p> <p>Toyota Rav4 [1994-2000] = SXA1#</p> <p>Rear Complete Suspension Arm [RE, LH] No.3</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>

















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-RV20WB</b> <b>48655-42040</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Front Lower Arm Bush [FR, Big]</p>  <p>RBI-2011-February-17 RBI Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT24-RV20WS</b> <b>48654-42030</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Front Lower Arm Bush [FR, Small]</p>  <p>RBI-2011-February-17 RBI Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-OPA1WB</b> <b>48655-32020</b></p> <p>Toyota OPA [2000-2005] = ZCT1#, ACT1#</p> <p>Front Lower Arm Bush [FR, Big]</p>  <p>TN-2013-March-31 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT24-OPA1WS</b> <b>48654-47020</b></p> <p>Toyota OPA [2000-2005] = ZCT1#, ACT1#</p> <p>Front Lower Arm Bush [FR, Small]</p>  <p>PFT-2012-August-30 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-RV2LCR1Z</b> <b>48068-42040</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Front Complete Lower Arm [FR, RH] [With 2 Bush]</p>  <p>HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-RV20E1</b> <b>48725-42080</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Rear Suspension Bush [RE]</p>  <p>RBI-2013-October-14 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	
	<p><b>AT25-RV20E2Z</b> <b>48770-42020</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Rear Complete Suspension Arm [RE, LH, RH] [Arm#, 2] [With 2 Bush]</p>  <p>RBI-2014-July-14 RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT25-RV20E3RZ</b> <b>48720-42020</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Rear Complete Suspension Arm [RE, RH] [Arm#, 3] [With 2 Bush]</p>  <p>RBI-2014-July-14 RBI Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT25-RV20E3LZ</b> <b>48730-42020</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Rear Complete Suspension Arm [RE, LH] [Arm#, 3] [With 2 Bush] No.1</p>  <p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-RV30WB</b> <b>48655-42060</b>  Toyota Rav4 [2005-2010] = ACA3#, ALA3#, GSA3# Front Lower Arm Bush [FR, Big]	RBI-2010-December-24 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-RV30WS</b> <b>48654-42040</b>  Toyota Rav4 [2005-2010] = ACA3#, ALA3#, GSA3# Front Lower Arm Bush [FR, Small]	RBI-2010-November-24 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-RV30WBJ</b> <b>43330-49095</b>  Toyota Alphard, Vellfire [2008] = ANH20, GGH20   Toyota Alphard, Vellfire [2008] = ANH25, GGH25.. [4] Front Lower Arm Ball Joint [FR, LH, RH]	Tenacity Product www.rbi.ae		
<b>AT24-ACA33WB</b> <b>48655-0R010</b>  Toyota Rav4 [2005-2010] = ACA33L Front Lower Arm Bush [FR, Big]	TN-2012-March-06 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-ACA33WS</b> <b>48654-0R010</b>  Toyota Rav4 [2005-2010] = ACA33L Front Lower Arm Bush [FR, Small]	TN-2012-March-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-RV3LCRZ</b> <b>48068-42050</b>  Toyota Rav4 [2005-2010] = ACA3#, ALA3#, GSA3# Front Complete Lower Arm [FR, RH] [With 2 Bush]	HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-RV3LCLZ</b> <b>48069-42050</b>  Toyota Rav4 [2005-2010] = ACA3#, ALA3#, GSA3# Front Complete Lower Arm [FR, LH] [With 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-RV30E02S</b> <b>48760-42010</b>  PFT-2012-November-07 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Suspension Bush [RE, Big]	<b>AT25-RV30E02B</b> <b>48760-42010</b>  PFT-2012-December-31 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Suspension Bush [RE, Small]
<b>AT25-RV30E03</b> <b>48730-42050</b>  PFT-2012-December-31 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Suspension Bush [RE]	
<b>AT25-RV30E041</b> <b>42304-42020</b>  ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Suspension Bush [RE]	<b>AT25-RV30E042</b> <b>42304-42020</b>  ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Suspension Bush [RE]
<b>AT25-RV30E043</b> <b>42304-42020</b>  ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Suspension Bush [RE]	
<b>AT25-RV305EB</b> <b>48770-42040</b>  ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Suspension Bush [RE]	
<b>AT25-RV305ELZ</b> <b>48790-42020</b>  ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Complete Suspension Arm [RE, LH]	<b>AT25-RV305ERZ</b> <b>48770-42040</b>  ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Complete Suspension Arm [RE, RH]
<b>AT25-RV306EZ</b> <b>48710-42020</b>  ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Toyota Rav4 [2005] = ACA3#, GSA3# Rear Complete Suspension Arm [RE]	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

AT24-RV40WB

48068-42060B

Toyota Rav4 [2013-2018] = ASA4#, ALA4#, ZSA4#

Front Lower Arm Bush [FR, Big]

PFT-2012-June-26  
Perfect Product  
shabbirh@eim.ae  
www.rbi.ae  
www.alafuae.com



AT24-RV40WS

48068-42060S

Toyota Rav4 [2013-2018] = ASA4#, ALA4#, ZSA4#

Front Lower Arm Bush [FR, Small]

TN-2012-March-06  
Tenacity Product  
shabbirh@eim.ae  
www.rbi.ae  
www.alafuae.com







# AL LAMSA AL FIDDIYA TRADING L.L.C.

**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-ZJ95P</b> <b>48632-35080</b></p> <p>Toyota Land Cruiser Prado 90 [1996-2002] = KDJ9#, KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Front Upper Arm Bush [FR, Small] [1 Car 4 Pcs]</p>	<p><b>AT24-ZJ95PBJ</b> <b>43310-39016</b></p> <p>Toyota Hilux Surf, Toyota 4-Runner [1995-2002] = RZN18#, VZN18#, KZN18#, KDN185   Toyota Land Cruise</p> <p>Front Upper Arm Ball Joint [FR, LH, RH]</p>
<p><b>AT24-ZJ95WB</b> <b>48061-35040</b></p> <p>Toyota Land Cruiser Prado 90 [1996-2002] = KDJ9#, KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Front Lower Arm Bush [FR, Big] [1 Car 4 Pcs]</p>	<p><b>AT24-ZJ96WB</b> <b>48061-35050</b></p> <p>4Runner / Tacoma [1995-2000] = RZN18#, RZN161, RZN171, VZN160, VZN195, VZN18#</p> <p>Front Lower Arm Bush [FR, Big] [1 Car 4 Pcs]</p>
<p><b>AT24-ZJ95WBLJ</b> <b>43340-39325</b></p> <p>Toyota Hilux Surf, Toyota 4-Runner [1995-2002] = RZN18#, VZN18#, KZN18#, KDN185   Toyota Land Cruise</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<p><b>AT24-ZJ95WBRJ</b> <b>43330-39415</b></p> <p>Toyota Land Cruiser Prado 90 [1996-2002] = KDJ9#, KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<p><b>AT24-ZJ95LCLZZ</b> <b>48068-35080</b></p> <p>Toyota Land Cruiser Prado 90 [1996-2002] = KDJ9#, KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Front Complete Lateral Arm [FR, RH] [With 2 Bush]</p>	<p><b>AT24-ZJ95LCRZZ</b> <b>48069-35080</b></p> <p>Toyota Land Cruiser Prado 90 [1996-2002] = KDJ9#, KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Front Complete Lower Arm [FR, RH] [With 2 Bush]</p>








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA















Revision : 2014-November-01

<b>AT24-RZN14PS</b> <b>48632-35070</b> Toyota Tacoma [1995-2004] = RZN140, RZN150, RZN160, RZN161, RZN171, RZN19#, VZN150, VZN160, VZN170, Front Upper Arm Bush [FR, Small]  TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AT24-RZN14WB</b> <b>48655-35085</b> Toyota Tacoma [1995-2004] = RZN140, RZN150, RZN160, RZN161, RZN171, RZN19#, VZN150, VZN160, VZN170, Front Lower Arm Bush [FR, Big]  Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-RZN14WS</b> <b>48654-35080</b> Toyota Tacoma [1995-2004] = RZN140, RZN150, RZN160, RZN161, RZN171, RZN19#, VZN150, VZN160, VZN170, Front Lower Arm Bush [FR, Small]  PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



**TOYOTA**

Revision : 2014-November-01

<b>AT24-GR21P</b> <b>48632-60020</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Upper Arm Bush [FR] [1 Car 4 Pcs]  RBI-2010-June-11 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AT24-GR21WB</b> <b>48655-60030</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Lower Arm Bush [FR, Big]  RBI-2013-June-15 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-GR21W</b> <b>48654-60030</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Lower Arm Bush [FR, Small]  RBI-2010-June-03 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-GR21WBJ</b> <b>#48068-60010</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Lower Arm Ball Joint [FR, LH, RH] ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AT24-GR21LCLZZ</b> <b>48069-60010</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Complete Lower Arm [FR, LH] ARP Product www.rbi.ae	<b>AT24-GR21LCRZZ</b> <b>48068-60010</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Complete Lower Arm [FR, RH] ARP Product www.rbi.ae
<b>AT24-GR21UCLZ</b> <b>48630-60020</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Complete Upper Arm [FR, LH] ARP Product www.rbi.ae	<b>AT24-GR21UCRZ</b> <b>48610-60050</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Front Complete Upper Arm [FR, RH] ARP Product www.rbi.ae
<b>AT25-GR21E01Z</b> <b>48720-35061</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Rear Complete Suspension Arm ARP Product www.rbi.ae	
<b>AT25-GR21E03LZ</b> <b>48710-35070</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Rear Complete Suspension Arm ARP Product www.rbi.ae	<b>AT25-GR21E03RZ</b> <b>48710-35060</b>  Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U Rear Complete Suspension Arm ARP Product www.rbi.ae






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-UCK3P</b>  <b>48632-34010</b>  Sequoia [2000-2007] = UCK35, UCK45   Tundra [1999-2006] = UCK3#, UCK4#, VCK30, VCK40, GSK30  Front Upper Arm Bush [FR] [1 Car 4 Pcs]</p>	<p>PFT-2012-August-30  Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT24-UCK3WB</b>  <b>48655-34010</b>  Sequoia [2000-2007] = UCK35, UCK45   Tundra [1999-2006] = UCK3#, UCK4#, VCK30, VCK40, GSK30  Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2013-May-28  RBI Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
	<p><b>AT24-UCK3WS</b>  <b>48654-34010</b>  Sequoia [2000-2007] = UCK35, UCK45   Tundra [1999-2006] = UCK3#, UCK4#, VCK30, VCK40, GSK30  Front Lower Arm Bush [FR, Small]</p>
	<p>RBI-2013-June-15  RBI Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-KDJ15P</b> <b>48632-60040</b></p> <p>PFT-2012-August-30 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Land Cruiser Prado 150 [2009-2015] = GRJ15#, KDJ15#, LJ150, TRJ15#, URJ150</p> <p>Front Upper Arm Bush [FR] [1 Car 4 Pcs]</p>	
<p><b>AT24-KDJ15WB</b> <b>48655-60050</b></p> <p>PFT-2012-August-30 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Land Cruiser Prado 150 [2009-2015] = GRJ15#, KDJ15#, LJ150, TRJ15#, URJ150</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-KDJ15WS</b> <b>48654-60050</b></p> <p>PFT-2012-November-07 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Land Cruiser Prado 150 [2009-2015] = GRJ15#, KDJ15#, LJ150, TRJ15#, URJ150</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-KDJ15WBJ</b> <b>#48068-60040</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Toyota Land Cruiser Prado 150 [2009-2015] = GRJ15#, KDJ15#, LJ150, TRJ15#, URJ150</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-FJ80W</b> <b>48061-60010</b></p>  <p>Toyota Land Cruiser 70 [1990-2004] = FJ80</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-LJ70WB</b> <b>48061-60020</b></p>  <p>Toyota Land Cruiser 70 [1990-2004] = LJ7#</p> <p>Front Lower Arm Bush [FR, Big]</p>
<p><b>AT24-FJ89W</b> <b>48061-60030</b></p>  <p>Toyota Land Cruiser 70 [1990-2004] = FJ80</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-KZJ70WB</b> <b>48061-60040</b></p>  <p>Toyota Land Cruiser 70 [1990-2004] = KZJ7#,RJ7#</p> <p>Front Lower Arm Bush [FR, Big]</p>
<p><b>AT24-FJ78WB</b> <b>48061-60050</b></p>  <p>Toyota Land Cruiser [1999] = FZJ78, FZJ79, HDJ7#, HZJ78, HZJ79, VDJ78, VDJ79</p> <p>Front Lower Arm Bush [FR, Big]</p>	

















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-UZ10P</b> <b>48632-60010</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Upper Arm Bush [FR, Small]	RBI-2010-May-28 RBI Product, Perfect Product, HFC Product, Ashimori Product  <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-UZ10PBJ</b> <b>48610-60030</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Upper Arm Ball Joint [FR, LH, RH]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT24-UZ10UCLZ</b> <b>48630-60010</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Complete Upper Arm [FR, LH]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AT24-UZ10ULRZ</b> <b>48610-60030</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Complete Upper Arm [FR, RH]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AT24-UZ10WB</b> <b>48655-60010</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Lower Arm Bush [FR, Big]	RBI-2010-June-18 RBI Product, Perfect Product, HFC Product, Ashimori Product  <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-UZ10W</b> <b>48654-60010</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Lower Arm Bush [FR, Small]	RBI-2010-April-24 RBI Product, Perfect Product, HFC Product, Ashimori Product  <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT24-UZ10WBJ</b> <b>48620-60010</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Lower Arm Ball Joint [FR, LH, RH]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>		
<b>AT24-UZ10LCLZZ</b> <b>48640-60010</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-UZ10LCRZZ</b> <b>48620-60010</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	ARP Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-UZ20P</b> <b>48632-60030</b></p> <p>Toyota Land Cruiser 200 [2007-2016] = GRJ200, URJ20#, UZJ200, VDJ200   Toyota Lexus LX460 / LX570 [2]</p> <p>Front Upper Arm Bush [FR, Small]</p>	<p><b>AT24-UZ20PBJ</b> <b>48610-60060</b></p> <p>Toyota Land Cruiser 200 [2007-2016] = GRJ200, URJ20#, UZJ200, VDJ200   Toyota Lexus LX460 / LX570 [2]</p> <p>Front Upper Arm Ball Joint [FR, LH, RH]</p>
<p><b>AT24-UZ20UCLZ</b> <b>48630-60030</b></p> <p>Toyota Land Cruiser 200 [2007-2016] = GRJ200, URJ20#, UZJ200, VDJ200   Toyota Lexus LX460 / LX570 [2]</p> <p>Front Complete Upper Arm [FR, LH]</p>	<p><b>AT24-UZ20UCRZ</b> <b>48610-60060</b></p> <p>Toyota Land Cruiser 200 [2007-2016] = GRJ200, URJ20#, UZJ200, VDJ200   Toyota Lexus LX460 / LX570 [2]</p> <p>Front Complete Upper Arm [FR, RH]</p>
<p><b>AT24-UZ20W</b> <b>48654-60040</b></p> <p>Toyota Land Cruiser 200 [2007-2016] = GRJ200, URJ20#, UZJ200, VDJ200   Toyota Lexus LX460 / LX570 [2]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p><b>AT24-UZ20WB</b> <b>48655-60040</b></p> <p>Toyota Land Cruiser 200 [2007-2016] = GRJ200, URJ20#, UZJ200, VDJ200   Toyota Lexus LX460 / LX570 [2]</p> <p>Front Lower Arm Bush [FR, Big]</p>
	<p><b>AT24-UZ20WBJ</b> <b>48068-60030</b></p> <p>Toyota Land Cruiser 200 [2007-2016] = GRJ200, URJ20#, UZJ200, VDJ200   Toyota Lexus LX460 / LX570 [2]</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-UCK5P</b>  <b>48632-0C010</b>            Toyota Sequoia [2007] = UCK6#, USK6#, UPK6#              Toyota Tundra [2006] = GSK5#, UCK5#, UPK5#, USK5#            Front Upper Arm Bush [FR, Small]</p>	<p>Perfect Product    <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT24-UCK5WS</b>  <b>48654-0C010</b>            Toyota Sequoia [2007] = UCK6#, USK6#, UPK6#              Toyota Tundra [2006] = GSK5#, UCK5#, UPK5#, USK5#            Front Lower Arm Bush [FR, Small]</p>	<p><b>AT24-UCK5WB</b>  <b>48655-0C010</b>            Toyota Sequoia [2007] = UCK6#, USK6#, UPK6#              Toyota Tundra [2006] = GSK5#, UCK5#, UPK5#, USK5#            Front Lower Arm Bush [FR, Big]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-ZJ95E4</b> <b>48706-35020</b></p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Rear Suspension Bush [RE]</p>	<p>PFT-2012-June-26 Perfect Product, HFC Product, Ashimori Product</p> <p><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT25-ZJ95E3</b> <b>48702-35050</b></p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2013-May-28 RBI Product, Perfect Product, HFC Product, Ashimori Product</p> <p><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT25-ZJ95E3Z</b> <b>48710-35040</b></p> <p>ARP Product</p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Rear Complete Suspension Arm [RE] No.1</p>	<p>HFC Product</p> <p><b>AT25-ZJ95EZ</b> <b>48710-35030</b></p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Rear Complete Suspension Arm [RE] No.1</p>
<p><b>AT25-ZJ95E1</b> <b>48702-35070</b></p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product</p> <p><b>AT25-ZJ95E2</b> <b>48702-35040</b></p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-DJ2150</b> <b>48706-60060</b></p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Land Cruiser Prado [2002-2008] = KDJ215, KZJ120, LJ120, RZJ120</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2006-February-09 RBI Product, Perfect Product, HFC Product, Ashimori Product</p> <p><b>AT25-DJ2152</b> <b>48725-35020</b></p> <p>Toyota Land Cruiser Prado [2002-2008] = KDJ215, KZJ120, LJ120, RZJ120</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-KJ215</b> <b>48714-35010</b></p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Land Cruiser Prado [2002-2008] = KDJ215, KZJ120, LJ120, RZJ120</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2006-August-14 RBI Product, Perfect Product, HFC Product, Ashimori Product</p> <p>RBI-2014-July-14 RBI Product, Perfect Product, HFC Product, Ashimori Product</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT26-ZJ950</b> <b>90389-14048</b></p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Front Shock Absorber Bush [FR]</p>	<p><b>AT26-ZJ959</b> <b>90903-89012</b></p> <p>Toyota Land Cruiser Prado [1996-2002] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Front Shock Absorber Bush [FR]</p>
<p><b>AT26-KDJ150</b> <b>48536-60010</b></p> <p>Toyota Land Cruiser Prado [2009-2014] = GRJ15#, KDJ15#, LJ15#, TRJ15#</p> <p>Front Shock Absorber Bush [FR]</p>	<p><b>AT26-UZ10E00</b> <b>90385-19010</b></p> <p>Toyota Land Cruiser / Lexus LX470 [1998-2006] = HDJ101, UZJ100, FZJ100, HDJ100, UZJ100   Toyota Land</p> <p>Rear Shock Absorber Bush [RE]</p>
<p><b>AT26-UZ10E02</b> <b>90903-89016</b></p> <p>Toyota Land Cruiser 100 [1998-2007] = HDJ101, UZJ100</p> <p>Front Shock Absorber Bush [RE]</p>	



## TOYOTA

Revision : 2014-November-01

<b>AT25-LJ701</b> <b>48702-60020</b> Toyota Land Cruiser [1984-1996] = KZJ7#, LJ7#, RJ7# Rear Suspension Bush [RE]	PFT-2012-November-07 Perfect Product, Ashimori Product  www.rbi.ae www.alafuae.com	<b>AT25-LJ702</b> <b>48702-60010</b> Toyota Land Cruiser [1984-1996] = KZJ7#, LJ7#, RJ7# Rear Suspension Bush [RE]	PFT-2012-November-07 Perfect Product  www.rbi.ae www.alafuae.com
<b>AT25-920</b> <b>48702-60050</b> Toyota Land Cruiser [1990-2002] = FJ80, FZJ80, FZJ105, HDJ80, HZJ80, HZJ105 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com	<b>AT25-9202</b> <b>48702-60011</b> Toyota Land Cruiser [1990-2002] = FJ80, FZJ80, FZJ105, HDJ80, HZJ80, HZJ105 Rear Suspension Bush [RE]	PFT-2012-June-26 Perfect Product, HFC Product  www.rbi.ae www.alafuae.com
<b>AT25-FJ801</b> <b>48702-60040</b> Toyota Land Cruiser [1990-2002] = FJ80, FZJ80, FZJ105, HDJ80, HZJ80, HZJ105 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com	<b>AT25-FJ802</b> <b>48702-60031</b> Toyota Land Cruiser [1990-2002] = FJ80, FZJ80, FZJ105, HDJ80, HZJ80, HZJ105 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com
<b>AT25-BJ7E</b> <b>48706-60011</b> Toyota Land Cruiser [1987-1996] = KZJ7#, LJ7#, RJ7# Rear Suspension Bush [RE]	RBI-2008-May-08 RBI Product, Perfect Product, Ashimori Product  www.rbi.ae www.alafuae.com	<b>AT25-LJ705</b> <b>48706-60020</b> Toyota Land Cruiser [1984-1990] = RJ70, LJ70 Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product, ARD Product, Ashimori Product  www.rbi.ae www.alafuae.com
<b>AT25-FJ803</b> <b>48706-60030</b> Toyota Land Cruiser [1990-2002] = FJ80, FZJ80, FZJ105, HDJ80, HZJ80, HZJ105 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com	<b>AT25-FJ804</b> <b>48706-60040</b> Toyota Land Cruiser [1990-2002] = FJ80, FZJ80, FZJ105, HDJ80, HZJ80, HZJ105 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com
<b>AT25-LJ706</b> <b>48706-60050</b> Toyota Land Cruiser [1984-1996] = KZJ70, RJ70, LJ70 Rear Suspension Bush [RE]	PFT-2012-December-31 Perfect Product, AKD Product, Ashimori Product  www.rbi.ae www.alafuae.com	<b>AT25-LJ703</b> <b>90389-20001</b> Toyota Land Cruiser [1987-1990] = RJ7#, LJ7# Suspension Rubber [RE]	PFT-2012-March-28 Perfect Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com
<b>AT25-FZJ7E01</b> <b>48706-60070</b> Toyota Land Cruiser [1999-2007] = FZJ71, FZJ74, FZJ78, FZJ79, GRJ7#, HZJ7# Rear Suspension Bush	PFT-2012-March-28 Perfect Product  www.rbi.ae www.alafuae.com		



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-UZ201</b> <b>48702-60100</b>  Toyota Land Cruiser / Lexus LX470 [1998-2006] = HDJ101, UZJ100, FZJ100, HDJ100, UZJ100   Toyota Land Rear Suspension Bush [RE]	RBI-2010-June-18 RBI Product, Perfect Product, Tenacity Product, HFC Product  <b>AT25-UZ202</b> <b>48702-60110</b>  Toyota Land Cruiser / Lexus LX470 [1998-2006] = HDJ101, UZJ100, FZJ100, HDJ100, UZJ100   Toyota Land Rear Suspension Bush [RE]
<b>AT25-UZ209</b> <b>48702-60090</b>  Toyota Land Cruiser / Lexus LX470 [1998-2006] = HDJ101, UZJ100, FZJ100, HDJ100, UZJ100   Toyota Land Rear Suspension Bush [RE]	RBI-2013-December-16 RBI Product, Perfect Product, HFC Product 
<b>AT27-LE00FB</b> <b>48849-60010</b>  Lexus LX470 [1998-2006] = UZJ100 Link Assy Bush [FR, LH, RH]	Perfect Product, HFC Product 
<b>AT25-UZ208B1</b> <b>48702-60130</b>  Toyota Land Cruiser [2007] = GRJ200, UZJ200, VDJ200 Rear Suspension Bush [RE]	RBI-2013-December-16 RBI Product 
<b>AT25-FZJ100E1</b> <b>48702-60120</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ100#, HZJ105, HDJ100, HDJ101, UZJ100   Toyota Lexus LX470 [1 Rear Suspension Bush [RE]	PFT-2012-June-26 Perfect Product 













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-UZ20E</b> <b>48849-60110</b>  Toyota Land Cruiser / Lexus LX570 [2007] = GRJ200, URJ201, UZJ200, VDJ200 Rear Suspension Bush [RE]	RBI-2010-June-11 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-UZ21E</b> <b>48849-60050</b>  Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200 Rear Suspension Bush [RE]	RBI-2014-February-04 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-UZ22E</b> <b>48849-60090</b>  Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200 Rear Suspension Bush [RE]	RBI-2014-February-04 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-UZ203E</b> <b>48702-60140</b>  Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200   Lexus LX570 [2007] = URJ201 Rear Suspension Bush [RE]	PFT-2013-August-20 Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-UZ204E</b> <b>48740-60150</b>  Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200   Lexus LX570 [2007] = URJ201 Rear Suspension Bush [RE]	Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-UZ20E5</b> <b>48725-60015</b>  Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200 Front Lower Arm Bush [FR]	ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-UZ20E8</b> <b>48810-60060</b>  Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200   Lexus LX570 [2007] = URJ201 Link Assy Bush [FR]	ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-UZ20E6</b> <b>48725-60125</b>  Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200 Rear Suspension Bush [RE]	Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-UZ20E7</b> <b>48725-60065</b>  Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200 Rear Suspension Bush [RE]	ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>





**TOYOTA**

Revision : 2014-November-01

<p><b>AT24-GX81W</b>  <b>48654-22030</b></p> <p>Toyota Mark 2, Chaser, Cresta, Cressida [1988-1992] = GX81, LX80, MX8#, RX8#, SX80, YX80, JZX81   To</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-OLD  RBI Product, Perfect Product, HFC Product, Ashimori Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
<p><b>AT24-GX90P</b>  <b>48610-39045</b></p> <p>Toyota Mark 2, Mark 2 Blit [2000-2004] = GX110, JZX110</p> <p>Front Upper Arm Bush [FR]</p>	<p>PFT-2012-August-30  Perfect Product, Tenacity Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
<p><b>AT24-GX900P</b>  <b>48632-22030</b></p> <p>Toyota Mark 2, Chaser, Cresta [1992-1996] = GX90, JZX9#, LX90, SX90   Toyota Mark 2, Chaser, Cresta</p> <p>Front Upper Arm Bush [FR, Small]</p>	<p>RBI-2009-January-16  RBI Product, Perfect Product, HFC Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
<p><b>AT24-GX901P</b>  <b>48632-30100</b></p> <p>Tyota Mark 2, Chaser, Cresta [1992-1996] = GX90</p> <p>Front Upper Arm Bush [FR, Small]</p>	<p>RBI-2005-March-25  RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
	<p><b>AT24-UZS15P1</b>  <b>48632-39013</b></p> <p>Toyota Aristo [1991-1997-2002] = JZS147, JZS16#   Toyota Lexus GS300, GS400, GS430 [1993-1997-2005]</p> <p>Front Upper Arm Bush [FR] [TYPE A]</p>
<p><b>AT24-UZS15P2</b>  <b>48632-39014</b></p> <p>Toyota Aristo [1991-1997-2002] = JZS147, JZS16#   Toyota Lexus GS300, GS400, GS430 [1993-1997-2005]</p> <p>Front Upper Arm Bush [FR] [TYPE B]</p>	<p>ARP Product</p>  <p>shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p>
<p><b>AT24-UZS151UCLZ</b>  <b>48630-39015</b></p> <p>Aristo [1991-1997] = JZS147   Aristo [1997-2004] = JZS160, JZS161   Crown, Crown Majesta [1991-1995]</p> <p>Front Complete Upper Arm [FR, LH] [With Ball Joint]</p>	<p><b>AT24-UZS151UCRZ</b>  <b>48610-39015</b></p> <p>Aristo [1991-1997] = JZS147   Aristo [1997-2004] = JZS160, JZS161   Crown, Crown Majesta [1991-1995]</p> <p>Front Complete Upper Arm [FR, LH] [With Ball Joint]</p>

## TOYOTA

Revision : 2014-November-01

<b>AT24-GXE10WB</b> <b>48660-53010</b>  Toyota Lexus IS200, IS300 [1999-2005] = GXE10, JCE10 Front Lower Arm Bush [FR, Big] PFT-2012-August-30 Perfect Product www.rbi.ae	<b>AT24-GX90WB</b> <b>48655-22010</b>  Mark 2, Chaser, Cresta [1992-2004] = GX90, GX100, GX110, JZX110 Front Lower Arm Bush [FR, Big] RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-GX901W</b> <b>48654-30070</b>  Toyota Mark 2, Chaser, Cresta [1992-1996] = GX90, JZX9#, LX90, SX90 Front Lower Arm Bush [FR, Small] RBI-2005-May-07 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-MA0W</b> <b>48655-22030</b>  Mark 2 [1994] Front Lower Arm Bush [FR, Big] RBI-2013-November-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-JZX93W</b> <b>48655-22041</b>  Mark II, Chaser = JZX93 [4WD] Front Lower Arm Bush [FR, Big] RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-GXE15WS</b> <b>48654-30060</b>  Toyota Altezza / Altezza Gita [1998-2005] = GXE1#, JCE1#, SXE10 Front Lower Arm Bush [FR, Small] PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-JZX95WS</b> <b>48654-22050</b>  Toyota Mark 2, Mark 2 Blit [2000-2007] = GX11#, JZX11# Front Lower Arm Bush [FR, Small] PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-JZX95WB</b> <b>48655-30100</b>  Toyota Altezza, Altezza Gita [1998-2005] = GXE15, JCE15.. [4WD]   Toyota Brevis [2001-2004] = JCG15. Front Lower Arm Bush [FR, Big] PFT-2012-November-07 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-UZS173WS</b> <b>48654-30080</b>  Toyota Crown, Crown Majesta [1999-2003] = GS171, JKS175, JZS17#, UZS17# Front Lower Arm Bush [FR, Small] PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-UZS173WB</b> <b>48655-30140</b>  Crown / Crown Majesta [1999-2004] = UZS173 Front Lower Arm Bush [FR, Big] PFT-2013-June-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-JZS143WL</b> <b>48653-30280</b>  Toyota Aristo [1991-1997] = JZS143, JZS147, UZS143   Toyota Crown, Crown Majesta [1999-2003] = GS171 Front Lower Arm Bush PFT-2014-October-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-JZS143WS</b> <b>48654-30280</b>  Toyota Aristo [1991-1997] = JZS143, JZS147, UZS143 Front Lower Arm Bush [FR, Small] PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-GX90WBLJ</b> <b>43340-29185</b> <div>ARP Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <p>Toyota Mark 2, Chaser, Cresta [1992-1996] = GX90</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<b>AT24-GX90WBRZ</b> <b>43330-29415</b> <div>ARP Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <p>Toyota Mark 2, Chaser, Cresta [1992-1996] = GX90</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<b>AT24-GX100WBLJ</b> <b>43340-59085</b> <div>Tenacity Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <p>Toyota Mark 2, Chaser, Cresta [1996-2001] = GX100   Toyota Origin [2000-2001] = JCG17   Toyota Progr</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<b>AT24-GX100WBRJ</b> <b>43330-59085</b> <div>Tenacity Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <p>Toyota Mark 2, Chaser, Cresta [1996-2001] = GX100   Toyota Origin [2000-2001] = JCG17   Toyota Progr</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<b>AT24-GX110WBLJ</b> <b>43340-59066</b> <div>Tenacity Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <p>Toyota Altezza, Altezza Gita [1998-2005] = GXE10, SXE10   Toyota Lexus IS200, IS300 [1999-2005] = GX</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<b>AT24-GX110WBRJ</b> <b>43330-59066</b> <div>Tenacity Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <p>Toyota Altezza, Altezza Gita [1998-2005] = GXE10, SXE10   Toyota Lexus IS200, IS300 [1999-2005] = GX</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<b>AT24-GRX12WBLJ</b> <b>43340-39505</b> <div>Tenacity Product</div> <div><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a></div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <div><a href="http://www.alafuae.com">www.alafuae.com</a></div> <p>Toyota Crown [2008] = GRS20#, GWS204   Toyota Crown Majesta [2009] = URS206, UZS207   Toyota Crown,</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<b>AT24-GRX12WBRJ</b> <b>43330-39625</b> <div>Tenacity Product</div> <div><a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a></div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <div><a href="http://www.alafuae.com">www.alafuae.com</a></div> <p>Toyota Crown [2008] = GRS20#, GWS204   Toyota Crown Majesta [2009] = URS206, UZS207   Toyota Crown,</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-UZS15WB</b> <b>48655-30090</b> Toyota Aristo [1992-1995] = UZS143   Toyota Crown, Crown Majesta [1992-2004] = UZS143, UZS145, UZS15 Front Lower Arm Bush [FR, Big]	RBI-2012-December-25 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-UZS15WS</b> <b>48654-30050</b> Crown / Majesta / Aristo / Lexus GS300 [1991-2004] = JZS147, JZS155, UZS15#, UZS173 Front Lower Arm Bush [FR, Small]	RBI-2013-May-28 RBI Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-UZS15WB2</b> <b>48655-30195</b> Toyota Lexus GS300 [1993-1997] = JZS147   Toyota Aristo [1991-1997] = JZS143, JZS147 Front Lower Arm Bush [FR, Big]	PFT-2013-March-10 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 		
<b>AT24-JZS160WS</b> <b>48654-30245</b> Lexus GS300, GS400, GS430 [1997-2005] = JZS160   Soarer, Lexus SC430 [2001-2010] = UZZ40   Aristo [1 Front Lower Arm Bush [FR, Small]	PFT-2013-August-20 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-JZS160WB1</b> <b>48655-30245</b> Toyota Lexus GS300, GS400, GS430 [1997-1999] = JZS160, UZS16#   Toyota Aristo [1997-1999] = JZS16# Front Lower Arm Bush [FR, Big]	PFT-2013-March-10 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-JZS160WB2</b> <b>48655-30170</b> Toyota Lexus GS300, GS400, GS430 [1999-2005] = JZS160, UZS16#   Toyota Aristo [1999-2005] = JZS16# Front Lower Arm Bush [FR, Big]	PFT-2013-February-15 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-JZS160WB3</b> <b>48655-30180</b> Toyota Lexus GS300 [2000] = JZS160 Front Lower Arm Bush [FR, Big]	PFT-2013-October-10 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-JZ160W</b> <b>48655-30181</b> Toyota Lexus GS300 [1999] = JZS160 Front Lower Arm Bush	RBI-2014-February-04 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 		

















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-82P</b> <b>48632-30020</b></p> <p>Crown = MS60   Hilux [1988-2001] = LN8#, LN9#, YN8#, YN9#   Liteace / Townace / Masterace [1988-2004]</p> <p>Front Upper Arm Bush [FR, Small]</p>   <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT24-82W</b> <b>48654-30020</b></p> <p>Crown = MS60</p> <p>Front Lower Arm Bush [FR, Small]</p>   <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT24-86P</b> <b>48632-30070</b></p> <p>Crown = MS132</p> <p>Front Upper Arm Bush [FR, Small]</p>   <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT24-86W</b> <b>48654-30030</b></p> <p>Crown = MS132</p> <p>Front Lower Arm Bush [FR, Small]</p>   <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT24-94P</b> <b>48632-22020</b></p> <p>Crown = MX12</p> <p>Front Upper Arm Bush [FR, Small]</p>   <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	





## TOYOTA

Revision : 2014-November-01

<b>AT24-GSR182P</b> <b>48610-39125</b> Lexus GS300 / GS350 / GS430 / GS460 [2005-2007] = GRS190   Crown / Majesta [2004-2009] = UZS186   Ma  PFT-2014-August-31 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Upper Arm Bush [FR]	<b>AT24-GSR182PBJ</b> <b>#48610-39125</b> ARP Product Toyota Crown, Majesta [2003-2008] = GRS18#, UZS18#   Toyota Crown, Majesta [2003-2008] = GRS183, GRS www.rbi.ae Front Upper Arm Ball Joint [FR, LH, RH]
<b>AT24-GSR182WB</b> <b>48075-30020</b> Crown [2004-2008] = GRS182   Crown / Majesta [2004-2009] = UZS186   Lexus GS430 / GS350 [2005-2007]  PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Big, LH, RH]	<b>AT24-GSR182WS</b> <b>48654-30295</b> PFT-2014-August-31 Perfect Product shabbirh@eim.ae Crown / Majesta [2004-2009] = UZS186   Lexus GS430 / GS350 [2005-2007] = GRS190   Mark X [2004-2009]  www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Small]
<b>AT24-GSR182WR</b> <b>48075-30020</b> Crown [2004-2008] = GRS182  TN-2012-August-06 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [Bracket] [FR, Big, RH]	<b>AT24-GSR182WL</b> <b>48076-30020</b> Crown [2004-2008] = GRS182  TN-2012-August-06 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [Bracket] [FR, Big, LH]
<b>AT24-GSR182WS2</b> <b>48654-30305</b> Crown, Majesta [2003-2008] = GRS18#, UZS187, UZS18#   Lexus GS300, GS350, GS430 [2005] = GRS195, GRS  PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Small]	<b>AT24-GSR182WM</b> <b>48653-30305</b> PFT-2014-October-15 Perfect Product shabbirh@eim.ae Crown, Majesta [2003-2008] = GRS18#, UZS187, UZS18#   Lexus GS300, GS350, GS430 [2005] = GRS195, GRS  www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Middle]
<b>AT24-JZZ31WS</b> <b>48654-24010</b> Lexus SC300 / SC400 [1991-1997] = JZZ31   Soarer [1991-2001] = JZZ31, UZZ31  PFT-2012-March-28 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Small]	<b>AT24-JZZ31WB</b> <b>48655-29166</b> PFT-2014-March-25 Perfect Product shabbirh@eim.ae Lexus SC300 / SC400 [1991-1997] = JZZ31   Soarer [1991-2001] = JZZ31, UZZ31  www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Big]






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-GX810</b> <b>48702-22090</b>  Mark II / Chaser / Cresta / Cressida [1988-1993] = LX8#, SX8#, YX8#, RX8# Rear Suspension Bush [RE]	<small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae</small>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GX819</b> <b>48702-22370</b>  Mark II / Chaser / Cresta / Cressida [1988-1993] = LX8#, SX8#, YX8#, RX8#   Crown Comfort / SED [199 <small>Perfect Product, Ashimori Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Suspension Bush [RE]



## TOYOTA

Revision : 2014-November-01

<b>AT25-GX90C</b> <b>TC55GX90B</b> Mark II / Chaser / Cresta / BLIT / Verossa [1992-2004] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX Rear Suspension Bush [RE]	PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT25-GX90E01</b> <b>42304-30070</b> Mark II / Chaser / Cresta / BLIT / Verossa [1992-2004] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX Rear Suspension Bush [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-GX90BBUS</b> <b>42304-30040</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   Crown Rear Suspension Bush [RE, Big]	ARP Product www.rbi.ae 	<b>AT25-GX90BRUB</b> <b>42304-30040</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   Crown Rear Suspension Bush [RE, Big]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-GX90B</b> <b>42304-30040</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   Crown Rear Suspension Bush [RE, Big]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT25-GX90S</b> <b>42304-22021</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE, Small]	RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-GX90SBUS</b> <b>42304-22021</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE, Small]	ARP Product www.rbi.ae 	<b>AT25-GX90SRUB</b> <b>42304-22021</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE, Small]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-GX90E</b> <b>48725-22150</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	RBI-2007-November-30 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT25-GX900</b> <b>48702-22410</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Upper Arm Bush [RE]	RBI-2009-November-23 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT25-GX900PBJ</b> <b>48770-22030</b> Toyota Crown [1995-2001] = JZS155.. [4WD]   Toyota Crown [1995-2001] = JZS155, GS151   Toyota Crown, Rear Upper Arm Ball Joint [RE, LH, RH]	ARP Product www.rbi.ae
<b>AT25-GX901</b> <b>48725-22180</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	RBI-2005-February-15 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT25-GX9070</b> <b>48725-22130</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	PFT-2012-March-28 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-GX90RB</b> <b>48725-22181</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		

**TOYOTA**

Revision : 2014-November-01

<b>AT25-GX9050</b> <b>48725-22170</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-GX905Z</b> <b>48710-22300</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Complete Suspension Arm [RE, LH, RH] No.1	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-GX9090</b> <b>90389-14028</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT25-GX9060</b> <b>48702-22380</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	PFT-2012-March-28 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-GX9080</b> <b>48706-22040</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Suspension Bush [RE]	PFT-2012-March-28 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-GX100E01</b> <b>48770-30052</b> Mark II / BLIT / Verossa [2000-2004] = GX110, GX115, JZX110, JZX115   Aristo / Lexus GS300 / GS400 / Rear Suspension Bush [RE, Big]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-GX100E02</b> <b>48770-39035</b> Mark II / BLIT / Verossa [2000-2004] = GX110, GX115, JZX110, JZX115   Crown / Crown Majesta [1999-20 Rear Suspension Bush [RE]	PFT-2013-April-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT25-GX100E03</b> <b>48705-30080</b> Mark II / BLIT / Verossa [2000-2004] = GX110, GX115, JZX110, JZX115   Progres / Brevis [1998-2007] = Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT25-GX110E01</b> <b>48725-53040</b> Mark II / BLIT [2000-2004] = GX110, JZX110   Verossa [2001-2004] = GX110, JZX110   Altezza / Altez Rear Suspension Bush [RE]	PFT-2013-April-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT25-GX110E02</b> <b>48730-51010</b> Mark II / BLIT / Verossa [2000-2004] = GX110, GX115, JZX110, JZX115   Crown / Crown Majesta [1999-20 Rear Suspension Bush [RE]	PFT-2013-February-15 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT25-GX110E03</b> <b>48725-30230</b> Aristo [1997-2004] = JZS160, JZS161   Lexus GS300, GS350, GS430, GS460 [2005] = GRS19#, URS190, UZS1 Rear Suspension Bush [RE]	PFT-2013-February-15 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-GX93E0</b> <b>52271-22090</b> Mark II / Chaser / Cresta [1992-1996] = GX90, GX93 [4WD] Rear Suspension Bush [RE]	Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GX105E0</b> <b>52271-22120</b> Mark II / Chaser / Cresta [1996-2001] = GX105, GX105 [4WD] Rear Suspension Bush [RE]	Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-GX93E1Z</b> <b>52205-22030</b> Mark II / Chaser / Cresta [1992-1996] = GX90, GX93 [4WD] Rear Suspension Bush [Bracket] [RE] [Bracket]	PFT-2012-December-31 Perfect Product, HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GX105E1Z</b> <b>52205-22090</b> Mark II / Chaser / Cresta [1996-2001] = GX105, GX105 [4WD] Rear Suspension Bush [Bracket] [RE] [Bracket]	PFT-2012-December-31 Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-GX105E2Z</b> <b>52205-30140</b> Crown / Crown Majesta [1995-1999] = UZS151   Crown / Crown Majesta [1995-1999] = UZS155 [4WD] Rear Suspension Bush [Bracket] [RE] [Bracket]	PFT-2012-December-31 Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-GX100E01S</b> <b>48790-30052</b> Aristo [1997-2004] = JZS160, JZS161   Toyota Lexus GS300, GS400, GS430 [1997-2005] = JZS160   Toyota Rear Suspension Bush [RE, Small, 2 Pcs]	Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GX9092</b> <b>48725-24050</b> Aristo [1991-1997] = JZS147   Aristo [1991-1997] = UZS143.. [4WD]   Crown [1995-2001] = JZS155.. [4W] Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-UZS14E04</b> <b>48702-24020</b> Aristo [1991-1997] = JZS147   Aristo [1991-1997] = UZS143.. [4WD]   Crown [1995-2001] = JZS155.. [4W] Front Upper Arm Bush [FR]	ARP Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-UZS14E05</b> <b>42304-30010</b> Aristo [1991-1997] = JZS143.. [4WD]   Aristo [1991-1997] = JZS147   Aristo [1991-1997] = UZS143.. [4W] Rear Suspension Bush [RE]	Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT26-GS00</b> <b>90389-14044</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Rear Shock Absorber Bush [RE]	RBI-2007-April-23 RBI Product, Perfect Product, HFC Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT26-GS01</b> <b>90389-12016</b> Mark II / Chaser / Cresta [1992-2001] = GX9#, GX10#, JZX9#, JZX10#, LX9#, LX10#, SX9#, SX10#   GS151 Front Shock Absorber Bush [FR]	RBI-2007-December-12 RBI Product, Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-820</b> <b>48702-30031</b>  Crown = MS60  Rear Suspension Bush [RE]	 	<b>AT25-860</b> <b>48702-30140</b>  Crown = MS132  Rear Suspension Bush [RE]	 
<b>AT25-870</b> <b>48725-30050</b>  Crown = MS133, JZS133  Rear Lower Arm Bush [RE]	 	<b>AT25-870B</b> <b>48725-30060</b>  Crown = MS133, JZS133  Rear Lower Arm Bush [RE]	 
<b>AT25-901</b> <b>48702-22010</b>  Crown [1973-1978] = RT102, RT104  Rear Suspension Bush [RE]	 	<b>AT26-85Z</b> <b>52201-30040</b>  Crown = MS120 [SET]  Suspension Rubber Set	 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-GSR182E01</b> <b>48725-30205</b> Lexus GS300 / GS350 / GS430 / GS450H / GS460 [2005-2006] = GRS190, GWS191   Lexus IS220D / IS250 / I Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product, HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GSR182E02</b> <b>48725-30105</b> Crown / Majesta [2004-2009] = UZS186, UZS187   Lexus GS300 / GS350 / GS430 / GS450H [2005] = GRS190, Rear Suspension Bush [RE, Small]	PFT-2012-December-31 Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-GSR182E03</b> <b>48725-30085</b> Lexus GS300 / GS350 / GS430 [2005] = GRS190, GRS196   Lexus IS250 / IS220 / IS300 / IS350 [2005] = G Rear Suspension Bush [RE]	PFT-2012-August-30 Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GSR182E04</b> <b>48725-30106</b> Lexus GS350 / GS430 / GS450 / GS460 [2004-2006] = GWS191   Lexus IS220 / IS250 / IS350 / IS300 [2005] Rear Suspension Bush [RE, Big]	Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-GSR182E051</b> <b>48725-30092</b> Toyota Lexus GS300, GS350, GS430, GS460 [2005-2011] = GRS19#, URS190, UZS190 Rear Suspension Bush [RE]	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GSR182E052</b> <b>48725-30093</b> Lexus GS430 / GS350 [2005-2007] = GRS190, GRS196   Crown / Majesta [2004-2009] = UZS186, UZS187 Rear Suspension Bush [RE]	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-GSR182E053</b> <b>48725-30094</b> Lexus GS430 / GS350 [2005-2007] = GRS190, GRS196   Crown / Majesta [2004-2009] = UZS186, UZS187 Rear Suspension Bush [RE]	ARP Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-GSR182E06</b> <b>48725-30095</b> Lexus GS430 / GS350 [2005-2007] = GRS190, GRS196   Crown / Majesta [2004-2009] = UZS186, UZS187 Rear Suspension Bush [RE]	PFT-2012-November-07 Perfect Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-GSR182E07</b> <b>48725-30096</b> Lexus GS430 / GS350 [2005-2007] = GRS190, GRS196   Crown / Majesta [2004-2009] = UZS186, UZS187 Rear Suspension Bush [RE]	PFT-2013-March-10 Perfect Product, HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-LS40WS</b> <b>48654-50010</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994-2000] = UCF1#, UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p><b>AT24-LS40W00</b> <b>48674-40051</b></p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Strut Bar Arm Bush [FR, LOWER]</p>
<p><b>AT24-LS40PA</b> <b>48632-5901A</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994-2000] = UCF1#, UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Front Upper Arm Bush [FR] [Type-A]</p>	<p><b>AT24-LS40PB</b> <b>48632-5901B</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994-2000] = UCF1#, UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Front Upper Arm Bush [FR] [Type-B]</p>
<p><b>AT24-LS40PC</b> <b>48632-59015</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994-2000] = UCF1#, UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Front Upper Arm Bush [FR] [Type-C]</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-LS401</b> <b>48725-22110</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994] = UCF1#   Cressida [88-96] = GX8#, MX8#, RX8#</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2005-April-27 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT25-LS40E6B</b> <b>48725-50030</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994] = UCF1#</p> <p>Rear Suspension Bush [RE, Big]</p>	<p>HFC-2014-November-20 HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT25-LS40E9A</b> <b>48725-50045</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994] = UCF1#</p> <p>Rear Suspension Bush [RE, Small]</p>	<p><b>AT25-LS40E9B</b> <b>48725-50040</b></p> <p>Toyota Celsior, Lexus LS400 [1989-1994] = UCF1#</p> <p>Rear Suspension Bush [RE, Big]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-LS40E0B</b> <b>48725-50070</b></p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#</p> <p>Rear Suspension Bush [RE]</p>	
<p><b>AT25-LS40E1B</b> <b>48725-50075</b></p> <p>ARP Product www.rbi.ae</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Rear Suspension Bush [RE]</p>	
<p><b>AT25-LS40E2B</b> <b>48725-50085</b></p> <p>ARP Product www.rbi.ae</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Rear Suspension Bush [RE]</p>	
<p><b>AT25-LS40E3A</b> <b>48702-5003A</b></p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Rear Upper Arm Bush [RE] [Type-A]</p>	<p><b>AT25-LS40E3B</b> <b>48702-5003B</b></p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Rear Upper Arm Bush [RE] [Type-B]</p>
<p><b>AT25-LS40E3C</b> <b>48702-50030</b></p> <p>Perfect Product www.rbi.ae</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#   Toyota Century [1997-2005] = GZG50</p> <p>Rear Upper Arm Bush [RE] [Type-C]</p>	
<p><b>AT25-LS40E4A</b> <b>48725-50095</b></p> <p>PFT-2012-June-26 Perfect Product www.rbi.ae</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#</p> <p>Rear Lower Arm Bush [RE]</p>	<p><b>AT25-LS40E4B</b> <b>48725-50090</b></p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Toyota Celsior, Lexus LS400 [1994-2000] = UCF2#</p> <p>Rear Suspension Bush [RE, Big]</p>










# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT24-LS43PB 48632-59045</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Front Upper Arm Bush [FR, Small]</p>	<p>PFT-2012-August-30 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT24-LS43WS 48654-50055</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT24-LS43WB 48655-50012</p> <p>RBI</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2012-November-30 RBI Product, Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT24-LS430BZZ LS430-AT24-SET</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Front Assy Arm Bush [SET]</p>	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-LS43E1A</b>  <b>48725-50140</b></p> <p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Rear Suspension Bush [RE, Upper, Small]</p>	<p><b>AT25-LS43E1B</b>  <b>48725-50145</b></p> <p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Rear Suspension Bush [RE, Upper, Big 2 Pcs]</p>
<p><b>AT25-LS43E2B</b>  <b>48725-50175</b></p> <p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Rear Suspension Bush [RE, NO.02]</p>	
<p><b>AT25-LS43E3B</b>  <b>48725-50170</b></p> <p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Rear Suspension Bush [RE, NO.03]</p>	
<p><b>AT25-LS43E4B</b>  <b>48725-50180</b></p> <p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p>Toyota Celsior, Lexus LS430 [2000-2006] = UCF3#</p> <p>Rear Suspension Bush [RE, NO.04]</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-USF40PB</b> <b>48632-5908B</b></p> <p><small>PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Front Upper Arm Bush [FR, Big]</p>	
<p><b>AT24-USF40CB</b> <b>48620-5007B</b></p> <p><small>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Front Lower Center Arm Bush [FR, Center, Big]</p>	<p><b>AT24-USF40CS</b> <b>48620-5007S</b></p> <p><small>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Front Lower Center Arm Bush [FR, Center, Small]</p>
<p><b>AT24-USF40WB</b> <b>48655-59015</b></p> <p><small>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Front Lower Arm Bush [FR, Big]</p>	
<p><b>AT24-USF40BZZ</b> <b>LS460-AT24-SET</b></p> <p><small>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Front Assy Arm Bush [Set 10Pcs]</p>	



**TOYOTA**

Revision : 2014-November-01

<p>AT25-USF40E1B 48725-50190</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Rear Lower Arm Bush</p>	
<p>AT25-USF40E2B 48725-50195</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Rear Suspension Bush [RE]</p>	
<p>AT25-USF40E3B 48725-50225</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Rear Suspension Bush [RE]</p>	
<p>AT25-USF40E4A 48725-50215</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Rear Suspension Bush</p>	<p>AT25-USF40E4B 48725-50216</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Rear Suspension Bush</p>
<p>AT25-USF40E4C 48725-50217</p> <p>Perfect Product www.rbi.ae</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Rear Suspension Bush [RE]</p>	<p>AT25-USF40E4Z 48730-50110</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PERFECT RUBBER PARTS</p> <p>Toyota Celsior, Lexus LS460 [2006-2012] = USF4#</p> <p>Rear Complete Arm [RE, LH, RH]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

AT25-USF40E5B

48725-50220

Toyota Celsior, Lexus LS460 [2006-2012] = USF4#

Rear Upper Arm Bush

Perfect Product

[shabbirh@eim.ae](mailto:shabbirh@eim.ae)

[www.rbi.ae](http://www.rbi.ae)

[www.alafuae.com](http://www.alafuae.com)



**TOYOTA**

Revision : 2014-November-01

<b>AT24-CR21PS</b> <b>48632-28030</b> Liteace / Townace / Masterace [1988-1992] = CR21, YR20, YR21, CM30, YM30 Front Upper Arm Bush [FR, Small] 	<b>AT24-CR21PB</b> <b>48635-28040</b> Liteace / Townace / Masterace [1988-1992] = CR21, YR20, YR21, CM30, YM30 Front Upper Arm Bush [FR, Big] 
<b>AT24-KM20PB</b> <b>48635-27010</b> Liteace / Townace / Masterace [1979-1985] = KM20 Front Upper Arm Bush [FR, Big] 	<b>AT24-CR27P</b> <b>48635-28010</b> Liteace / Townace / Masterace [1988-2004] = CR27, CM3#, KM3#, YM3#, YM4#, CR4#, KR4#, SR4# Front Upper Arm Bush [FR, Big] 
<b>AT24-CR27W</b> <b>48061-27011</b> Liteace / Townace / Masterace [1988-2004] = CR27, CM3#, KM3#, YM3#, YM4#, KR2#, YR2#, YR39, CR4#, KR Front Lower Arm Bush [FR, Big] 	<b>AT24-CR304W</b> <b>48061-28030</b> Liteace / Townace / Masterace [1988-1998] = CR3#, [4WD] Front Lower Arm Bush [FR, Big] 
<b>AT24-SR40PB</b> <b>48635-28060</b> Toyota Lite, Townace Noah, V [1996-2007] = CR4#, SR40, KR4#   Toyota Townace, Liteace [1996-2004] = Front Upper Arm Bush [FR, Big] 	<b>AT24-SR40PS</b> <b>48632-28050</b> Toyota Lite, Townace Noah, V [1996-2007] = CR4#, SR40, KR4#   Toyota Townace, Liteace [1996-2004] = Front Upper Arm Bush [FR, Small] 
<b>AT24-KR40PB</b> <b>48635-28030</b> Townace/Liteace [1998-2003] = KR42 Front Upper Arm Bush [FR, Big] 	
<b>AT24-SR50UCLZZ</b> <b>48067-29135</b> Lite, Townace [1999-2007] = CM7#, CM8#, KM7#, KM8#   Lite, Townace Noah, V [1996-2001] = SR40, SR50 Front Complete Upper Arm [FR, LH] [With Ball Joint] 	<b>AT24-SR50UCRZZ</b> <b>48066-29135</b> Lite, Townace [1999-2007] = CM7#, CM8#, KM7#, KM8#   Lite, Townace Noah, V [1996-2001] = SR40, SR50 Front Complete Upper Arm [FR, RH] [With Ball Joint] 
<b>AT24-CR5WB</b> <b>48061-28050</b> Liteace / Townace / Masterace [1988-1998] = CR5#, KR5#, SR5# Front Lower Arm Bush [FR, Big] 	<b>AT24-CR5WS</b> <b>48061-28040</b> Liteace / Townace / Masterace [1988-1998] = CR5#, KR5#, SR5# Front Lower Arm Bush [FR, Big] 



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT25-CR30E</b> <b>48704-28010</b></p> <p>Liteace / Townace / Masterace [1992-2000] = CR27, KR27#, YZ2#, YR39</p> <p>Rear Suspension Bush [RE]</p> <p><small>RBI-2007-September-24 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p><b>AT25-CM30E</b> <b>48702-27040</b></p> <p>Liteace / Townace / Masterace [1988-1998] = CM3#, KM3#, YM3#, YM4#</p> <p>Rear Suspension Bush [RE]</p> <p><small>RBI-2008-January-17 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p><b>AT25-RM3E</b> <b>48706-22030</b></p> <p>Liteace / Townace / Masterace [1988-1998] = CM3#, KM3#, YM3#, YM4#</p> <p>Rear Suspension Bush [RE]</p> <p><small>RBI-2008-March-17 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	
<p><b>AT25-SR40E1</b> <b>48706-28020</b></p> <p>Liteace / Townace / Masterace [1996-2001] = SR40, CR4#, KR4#</p> <p>Rear Suspension Bush [RE]</p> <p><small>ARD-2014-January-01 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p><b>AT25-CR4E</b> <b>48704-28040</b></p> <p>Liteace / Townace / Masterace [1996-2001] = SR40, CR4#, KR4#</p> <p>Rear Suspension Bush [RE]</p> <p><small>RBI-2012-August-06 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p><b>AT25-SR40E3</b> <b>48702-28130</b></p> <p>Liteace / Townace / Masterace [1996-2001] = SR40, CR4#, KR4#</p> <p>Rear Suspension Bush [RE]</p> <p><small>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p><b>AT25-SR40E4</b> <b>48710-28170</b></p> <p>Liteace / Townace / Masterace [1996-2001] = SR40, CR4#, KR4#</p> <p>Rear Suspension Bush [RE]</p> <p><small>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-64W</b> <b>48061-26010</b></p>  <p>Hiace = LH60, LH112, YH112, VZN130</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-64PS</b> <b>48632-26010</b></p>  <p>Hiace = LH60, LH112, YH112, VZN130</p> <p>Front Upper Arm Bush [FR, Small]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-G10PS</b> <b>48632-26050</b></p>  <p>Granvia / Grand Hiace / Hiace = VCH10</p> <p>Front Upper Arm Bush [FR, Small]</p>	<p>RBI-2009-March-11 RBI Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-KD201WB</b> <b>48061-26060</b></p>  <p>Hiace / Regiusace [2005-2010] = KDH205, KDH225, KDH227, TRH219, TRH226, TRH228, TRH229</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2013-June-19 RBI Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-KD202WB</b> <b>48061-25010</b></p>  <p>Hiace / Regiusace [2005-2010] = KDH205, KDH225, KDH227, TRH219, TRH226, TRH228, TRH229</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2012-December-25 RBI Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-BB20WB</b> <b>48061-36011</b></p>  <p>Coaster [1982-1993] = RB2#, BB2#, BB3#, FB30, HB3#, HDB20, HDB3#, HZB3#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2013-February-19 RBI Product, HFC Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-BB40WB</b> <b>48061-36020</b></p>  <p>Coaster [1993-2007] = BB4#, BB5#, BZB4#, BZB5#, HDB4#, HDB5#, HZB4#, HZB5#, RZB4#, RZB5#, TRB40, TRB</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2013-February-09 RBI Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-BB41WB</b> <b>48655-36010</b></p>  <p>Coaster [1993-2007] = BB4#, BB5#, BZB4#, BZB5#, HDB4#, HDB5#, HZB4#, HZB5#, RZB4#, RZB5#, TRB40, TRB</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2013-March-01 RBI Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-T11WB</b> <b>48655-28010</b>  Previa / Lucida [1990-1999] = TCR1#, TCR2# Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT24-T11WS</b> <b>48654-28030</b>  Previa / Lucida [1990-1999] = TCR1#, TCR2# Front Lower Arm Bush [FR, Small]	ASH-2012-December-25 HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-670</b> <b>48706-30020</b>  Hiace = RZH135 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-671</b> <b>48702-28080</b>  Hiace = RZH135   Previa / Lucida [1990-1999] = TCR1#, TCR2# Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT25-T11E01</b> <b>48726-28010</b>  Previa / Lucida [1990-1999] = TCR1#, TCR2# Rear Suspension Bush [RE, Big]	ASH-2012-December-25 Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-T11E02</b> <b>48725-28075</b>  Previa / Lucida [1990-1999] = TCR1#, TCR2# Rear Suspension Bush [RE, Small]	ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-6701</b> <b>48702-26051</b>  Hiace = RZH135 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-672</b> <b>48702-26041</b>  Hiace = RZH135 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT25-TG1020</b> <b>48725-26020</b>  Hiace = RCH10, RCH11, RCH16 Rear Suspension Bush [RE]	RBI-OLD RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT25-TG1030</b> <b>48725-26030</b>  Hiace = RCH10, RCH11, RCH16 Rear Suspension Bush [RE, Big Diameter]	RBI-OLD RBI Product, Ashimori Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-41P</b> <b>48632-30012</b>  Hilux [1972-2006] = LN30, LN40, LN5#, LN8#, LN14#, LN15#, RN2#, RN3#, RN4#, RN5#, RN8#, RZN14#, YN5#  Front Upper Arm Bolt [FR, Small]	<div>ARP Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> 		
<b>AT24-46P</b> <b>48632-35020</b>  Crown = MS60   Hilux [1988-2001] = LN8#, LN9#, YN8#, YN9#   Liteace / Townace / Masterace [1988-2004]  Front Upper Arm Bush [FR, Small]	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> 	<b>AT24-44W</b> <b>48654-35010</b>  Hilux [1978-2001] = LN3#, LN4#, LN5#, LN8#, LN9#, RN3#, RN4#, RN5#, RN8#, YN5#, YN8#   TIGER  Front Lower Arm Bush [FR, Small]	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> 
<b>AT24-S0AR91</b> <b>48632-14040</b>  Toyota Soarer, Lexus SC300, SC400 [1991-2000] = JZZ3#, UZZ3#  Front Upper Arm Bush [FR, Small]	<div>RBI-2005-April-27</div> <div>RBI Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> 	<b>AT24-Y5102W</b> <b>48654-04020</b>  TIGER [2WD]  Front Lower Arm Bush [FR, Small]	<div>RBI-OLD</div> <div>RBI Product, Perfect Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> 
<b>AT26-45001</b> <b>48500-35030</b>  Hilux = LN85   L200 / Triton  Front Shock Absorber Bush	<div>RBI-2005-September-23</div> <div>RBI Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> 		
<b>AT25-4X0E</b> <b>48725-35010</b>  Hilux = LN106  Rear Suspension Bush [RE]	<div>RBI-2008-March-11</div> <div>RBI Product, Ashimori Product</div> <div>shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> 		



## TOYOTA

Revision : 2014-November-01

<b>AT24-VG02P</b> <b>48632-0K010</b>  Hilux Vigo [2WD] Front Upper Arm Bush [FR, Small]	RBI-2006-May-25 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-VG04P</b> <b>48632-0K040</b>  Hilux Vigo [4WD]   4Runner [2002-2005] = GRN21#, KZN215, UZN21#   Hilux Surf [2002- 2005] = GRN215, K Front Upper Arm Bush [FR] [1 Car 4 Pcs]	RBI-2005-October-12 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-VG2WB</b> <b>48655-0K010</b>  Hilux Vigo [2WD] Front Lower Arm Bush [FR, Big]	RBI-2006-February-09 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-VG2WS</b> <b>48654-0K010</b>  Hilux Vigo [2WD] Front Lower Arm Bush [FR, Small]	RBI-2006-February-09 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT24-VG4WB</b> <b>48655-0K040</b>  Hilux Vigo [4WD]   Toyota Land Cruiser 120 [2002- 2004] = GRJ12#, KDJ12#   4Runner [2002-2005] = GRN2 Front Lower Arm Bush [FR, Big]	RBI-2006-February-09 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT24-VG4WS</b> <b>48654-0K040</b>  Hilux Vigo [4WD] Front Lower Arm Bush [FR, Small]	RBI-2006-February-09 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-VG041</b> <b>48706-0K030</b>  Hilux Vigo, Fortuner Rear Suspension Bush [RE]	RBI-2008-March-04 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT25-VG042</b> <b>48702-0K010</b>  Hilux Vigo, Fortuner Rear Suspension Bush [RE]	RBI-2008-June-14 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-VG043</b> <b>48702-0K080</b>  Hilux Vigo, Fortuner Rear Suspension Bush [RE]	RBI-2008-July-11 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT25-VG044</b> <b>48702-0K090</b>  Hilux Vigo, Fortuner Rear Suspension Bush [RE]	RBI-2008-July-29 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT25-KDN14E1Z</b> <b>45450-39295</b>  Hilux [2001-2004] = RZN147, RZN152, LN147 Rear Complete Suspension Strut Arm [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT26-VG04F9</b> <b>48510-09K06</b>  Hilux Vigo, Fortuner Front Shock Absorber Bush [FR] [4WD]	ARD-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT26-VG02F9</b> <b>48510-90J10</b>  Hilux Vigo, Fortuner Front Shock Absorber Bush [FR] [2WD]	ARD-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT26-VG04EB1</b> <b>52201-0K010</b>  Hilux Vigo [2004] = KUN25 Suspension Rubber Bush	Ashimori Product www.rbi.ae		



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-XT08W</b> <b>48654-16040</b></p> <p>Corsa / Tercel [1982-1989] = AL2#</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>ARD-2014-January-01 ARD Product, Ashimori Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-95WB</b> <b>48655-16010</b></p> <p>Toyota Starlet [1984-1989] = EP7#, NP7#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT24-95WS</b> <b>48654-16060</b></p> <p>Toyota Starlet [1984-1989] = EP7#, NP7#</p> <p>Front Lower Arm Bush [FR, Small]</p>
	<p><b>AT24-95WS2</b> <b>48654-16065</b></p> <p>Corolla 2 [1990-1994] = EL41   Corsa / Tercel [1990-1994] = EL40   Cynos [1990-1995] = EL44   Paseo</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-S01WB</b> <b>48655-10030</b></p> <p>Toyota Corsa, Tercel [1990-1994] = EL4#, NL40</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-S02WB</b> <b>48655-10050</b></p> <p>Toyota Soluna [1996-2003] = AL50</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT24-EL53WB</b> <b>48655-46010</b></p> <p>Toyota Tercel [1994-1999] = EL50, EL53</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2012-November-07 Perfect Product</p> <p><a href="http://www.rbi.ae">www.rbi.ae</a></p> <p><a href="http://www.alafuae.com">www.alafuae.com</a></p> 







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-NC42WB</b> <b>48655-0D060</b>  Toyota Yaris / Echo / Vios / Soluna [1999-2005] = NCP1#, NCP4# Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-NC42WS</b> <b>48654-0D040</b>  Toyota Yaris / Echo / Vios / Soluna [1999-2005] = NCP1#, NCP4# Front Lower Arm Bush [FR, Small]	RBI-2007-November-20 RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-NC51WB</b> <b>48655-17010</b>  Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD] Front Lower Arm Bush [FR, Big]	PFT-2012-March-28 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-NC51WS</b> <b>48654-17031</b>  Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD] Front Lower Arm Bush [FR, Small]	PFT-2012-June-26 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-NC40LCRZZ</b> <b>48068-59035</b>  Yaris / Echo / Vios / Soluna [1999-2005] = NCP1#, NCP4# Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-NC40LCLZZ</b> <b>48069-59035</b>  Yaris / Echo / Vios / Soluna [1999-2005] = NCP1#, NCP4# Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-NC41LCRZZ</b> <b>48068-09010</b>  Yaris / Echo / Vios / Soluna [1999-2005] = NCP1#, NCP4# Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-NC41LCLZZ</b> <b>48069-09010</b>  Yaris / Echo / Vios / Soluna [1999-2005] = NCP1#, NCP4# Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-KGB10WB</b> <b>48655-0H010</b>  Toyota Aygo [2005] = KGB10, WNB10 Front Lower Arm Bush [FR, Big]	PFT-2014-November-15 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 	<b>AT24-KGB10WS</b> <b>48654-0H010</b>  Toyota Aygo [2005-2012] = KGB10 Front Lower Arm Bush [FR, Small]	PFT-2012-June-26 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> 
<b>AT24-KGB10LCLZZ</b> <b>3520.Q2</b>  Toyota Aygo [2005] = KGB10   Citroen C1 [2006]   Peugeot 107 [2006] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AT24-KGB10LCRZZ</b> <b>3521.L3</b>  Toyota Aygo [2005] = KGB10   Citroen C1 [2006]   Peugeot 107 [2006] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT24-NC93WB</b> <b>48655-0D051</b></p> <p>Toyota Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p><b>AT24-NC93WS</b> <b>48654-0D060</b></p> <p>Toyota Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p><b>AT24-NC90LCRZZ</b> <b>48068-59095</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint &amp; 2 Bush]</p>	<p><b>AT24-NC90LCLZZ</b> <b>48069-59095</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint &amp; 2 Bush]</p>
<p><b>AT24-NC91LCRZZ</b> <b>48068-09071</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint &amp; 2 Bush]</p>	<p><b>AT24-NC91LCLZZ</b> <b>48069-09071</b></p> <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint &amp; 2 Bush]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT25-EL40E01B</b> <b>48725-16087</b> Toyota Corolla 2 [1994-1999] = EL5#, NL50   Toyota Corsa, Tercel [1994-1999] = EL5#, NL50   Toyota C Rear Suspension Bush [RE, Big]	<p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<b>AT25-EL40E01S</b> <b>48725-16086</b> Toyota Corolla 2 [1994-1999] = EL5#, NL50   Toyota Corsa, Tercel [1994-1999] = EL5#, NL50   Toyota C Rear Suspension Bush [RE, Small]	<p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<b>AT25-950</b> <b>48725-10010</b> Toyota Starlet [1984-1989] = EP7#, NP7# Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<b>AT25-ST93E</b> <b>48702-10020</b> Toyota Starlet [1978-1998] = KP6#, EP7#, NP7#, EP8#, NP80 Rear Suspension Bush [RE]	<p>RBI-2007-November-20 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<b>AT25-S011</b> <b>48725-0A010</b> Soluna   Tercel [1990-1999] = EL4#, EL5#, NL50   Corolla 2 [1994-1999] = EL51, EL53, NL50   Corsa / Rear Suspension Bush [RE]	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<b>AT25-EP80E01</b> <b>48725-16055</b> Corolla 2 [1990-1994] = EL45 [4WD]   Corolla 2 [1994-1999] = EL55 [4WD]   Corsa / Tercel [1990-1994] Rear Suspension Bush [RE]	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<b>AT25-KGB10E01</b> <b>48725-0H010</b> Toyota Aygo [2005] = KGB10   Toyota IQ [2008] = KGJ10, NGJ10 Rear Suspension Bush	<p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>		



**TOYOTA**

Revision : 2014-November-01

<p><b>AT25-NC42E</b>  <b>48725-0D040</b></p>  <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2007-December-18  RBI Product, Perfect Product,  Ashimori Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT25-NC12E</b>  <b>48725-52010</b></p>  <p>Echo / Platz / Vitz / Yaris / Echo [1999-2005] = NCP1#, NCP12, NCP13, SCP1#, SCP10, SCP11, NLP10   W</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2009-May-12  RBI Product, Perfect Product,  Tenacity Product, HFC  Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p><b>AT25-YA91E</b>  <b>48725-0D070</b></p>  <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-NC20E</b>  <b>48725-52030</b></p>  <p>Fun Cargo [1999-2005] = NCP20, NCP21</p> <p>Rear Suspension Bush [RE]</p>	<p>TN-2012-March-06  Tenacity Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> 
<p><b>AT25-NCP1E01</b>  <b>48725-46020</b></p>  <p>Yaris / Echo / Platz / Vitz [1999-2005] = NCP1#, SCP10, NLP10   IST / Scion / XA [2002-2007] = NCP6#</p> <p>Rear Suspension Bush [RE]</p>	<p>ARP Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p><b>AT25-NCP1E02</b>  <b>48706-52010</b></p>  <p>Vitz / Platz / Fun Cargo [1999-2005] = NCP15, NCP16, NCP25   BB / Open Deck [2003-2005] = NCP35   IS</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-NC51E01</b>  <b>48704-52010</b></p>  <p>Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p><b>AT25-NC51E02</b>  <b>48702-52060</b></p>  <p>Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD]</p> <p>Rear Suspension Bush [RE]</p>
<p><b>AT25-NC51E03B</b>  <b>48747-10010</b></p>  <p>Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD]</p> <p>Rear Suspension Bush [RE, Big]</p>	<p>Perfect Product  shabbirh@eim.ae  www.rbi.ae  www.alafuae.com</p> <p><b>AT25-NC51E03S</b>  <b>48706-10020</b></p>  <p>Probox, Succeed [2002-2007] = NCP51, NCP55.. [4WD]</p> <p>Rear Suspension Bush [RE, Small]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT24-KGJ10WB</b> <b>48655-79015</b>  <b>Perfect Product</b> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> <b>IQ [2008] = KGJ10, NGJ10</b> <b>Front Lower Arm Bush [FR, Big]</b>	<b>AT24-KGJ10WS</b> <b>48654-79015</b>  <b>PFT-2012-August-30</b> <b>Perfect Product</b> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> <b>IQ [2008] = KGJ10, NGJ10</b> <b>Front Lower Arm Bush [FR, Small]</b>
<b>AT24-KGJ10LCLZZ</b> <b>48069-79015</b>  <b>ARP Product</b> <a href="http://www.rbi.ae">www.rbi.ae</a> <b>Toyota IQ &amp; Scion IQ [2008-2011] = KGJ10, NGJ10, NUJ10</b> <b>Front Complete Lower Arm [FR, LH] [With 2 Bush]</b>	<b>AT24-KGJ10LCRZZ</b> <b>48068-79015</b>  <b>ARP Product</b> <a href="http://www.rbi.ae">www.rbi.ae</a> <b>Toyota IQ &amp; Scion IQ [2008-2011] = KGJ10, NGJ10, NUJ10</b> <b>Front Lower Arm Bush [FR, RH] [With 2 Bush]</b>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT27-040</b> <b>90101-08458</b>  Toyota Corona [1973-1979] = RT10#, RT11# Stabilizer Link	RBI-OLD RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-060</b> <b>48819-20010</b>  Toyota Corolla Coupe [1983-1987] = AE86   Toyota Carina [1977-1981] = TA4#   Toyota Celica [1977-1987] = AE Stabilizer Link	RBI-OLD RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-230</b> <b>90101-08274</b>  Toyota Corolla / Trueno [1974-1981] = KE3#, KE5#, TE3#, TE47, TE51   Toyota Carina [1970-1977] = TA1 Stabilizer Link	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-240</b> <b>48819-12010</b>  Toyota Corolla / Trueno [1974-1981] = KE3#, KE5#, TE3#, TE47, TE51   Toyota Corolla [1979-1987] = AE Stabilizer Link	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-250</b> <b>48819-20030</b>  AE80, AE92 Stabilizer Link	RBI-OLD RBI Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-410</b> <b>91111-70856</b>  RN25, RT80 Stabilizer Link	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-440</b> <b>90101-08038</b>  LN40, LN50 Stabilizer Link	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-460</b> <b>48819-35020</b>  LN85, TIGER Stabilizer Link	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-4X3</b> <b>90101-10140</b>  LN111, LN167 Stabilizer Link	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-620</b> <b>90101-10259</b>  Toyota Hiace [1977-1985] = RH11, RH2#, RH3#, RH42, LH11, LH20, LH30   Toyota Stout [1979-2000] = RK1 Stabilizer Link	RBI-OLD RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-650</b> <b>48819-26050</b>  Toyota Hiace Van, Comuter [1982-1989] = YH5#, YH6#, YH7#, LH5#, LH6#, LH7#   Toyota Hiace Van, Comut Stabilizer Link	RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-820</b> <b>90101-80206</b>  MS60 Stabilizer Link	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-910</b> <b>90101-10323</b>  JU, BU Stabilizer Link	RBI-OLD RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-S010</b> <b>48819-10010</b>  Toyota Soluna [1996-2003] = AL50 Stabilizer Link [FR, LH, RH]	RBI-OLD RBI Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-NC42</b> <b>48819-52010</b></p> <p></p> <p>Vios / Soluna Vios [2002] = NCP4#</p> <p>Stabilizer Link [FR, LH, RH]</p>	<p>RBI-2008-May-02 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com</p>
<p><b>AT27-NC5E01</b> <b>48802-52030</b></p> <p></p> <p>ProBox/Succeed [2002-2007] = NLP51..DXJ, NCP50, 51, 58</p> <p>Stabilizer Link [RE]</p>	<p><b>AT27-NC5E02</b> <b>48802-52050</b></p> <p></p> <p>Probox, Succeed [2002-2007] = NCP51, NCP55, NCP59.. [4WD]</p> <p>Stabilizer Link [RE] [4WD]</p>
<p><b>AT27-J122F</b> <b>48822-87401</b></p> <p></p> <p>Cami / Terios [1999-2005] = J10#, J111, J122</p> <p>Link Assy [FR, LH, RH]</p>	<p><b>AT27-J200F</b> <b>48822-97503</b></p> <p></p> <p>Rush [2006] = J200E   Sparky [2000-2003] = S221E, S231E</p> <p>Link Assy [FR, LH, RH]</p>





## TOYOTA

Revision : 2014-November-01

<b>AT27-09FL</b> <b>48810-20010</b> Corona & Carina2 [1987-1992] = AT17#, ST17#, CT17# Link Assy [FR, LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT27-09FR</b> <b>48820-20030</b> Corona & Carina2 [1987-1992] = AT17#, ST17#, CT17# Link Assy [FR, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT27-10FL</b> <b>48810-20020</b> Corona & Carina E [JP] [1991-1997] = AT19#, CT190, ST191 Link Assy [FR, LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT27-10FR</b> <b>48820-20040</b> Corona & Carina E [JP] [1991-1997] = AT19#, CT190, ST191 Link Assy [FR, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT27-11FL</b> <b>48810-20030</b> Corona & Carina E [UK] [1991-1997] = AT19#, CT190, ST191 Link Assy [FR, LH]	RBI-2013-February-08 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT27-11FR</b> <b>48820-20050</b> Corona & Carina E [UK] [1991-1997] = AT19#, CT190, ST191 Link Assy [FR, RH]	RBI-2013-February-08 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		<b>AT27-30E</b> <b>48830-20010</b> Corona & Carina [1987-1997] = AT17#, ST17#, AT19#, CT190, ST191   AE101   Camry = SV2# Link Assy [RE, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT27-CT190E</b> <b>48830-12050</b> Corona & Carina [1987-1997] = AT17#, ST17#, AT19#, CT190, ST191 Link Assy [RE, LH, RH]	RBI-2012-August-25 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT27-30F</b> <b>48820-33010</b> Camry = SXV10   AE101   Toyota Rav4 [1994-2000] = SXA10 Link Assy [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT27-AZT22F</b> <b>48650-20021</b> Toyota Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22#   Corona [1997-2003] = AT22 Link Assy [FR, LH, RH]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT27-AT22FL</b> <b>48810-05012</b> Toyota Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22# Link Assy [FR, LH]	ARP Product www.rbi.ae	<b>AT27-AT22FR</b> <b>48820-05012</b> Toyota Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22# Link Assy [FR, RH]	ARP Product www.rbi.ae
<b>AT27-AT22E00</b> <b>48830-05020</b> Toyota Avensis [1997-2003] = AT22#, AZT220, CDT220, CT220, ST220, ZZT22# Link Assy [RE, LH, RH]	Perfect Product www.rbi.ae		









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA




















Revision : 2014-November-01

<p><b>AT27-30CF</b> <b>48820-12010</b></p>  <p>AE101, AE111, Coupe Super Strut</p> <p>Link Assy [FR, LH, RH] [2 Heads]</p>	<p><b>AT27-180F</b> <b>48820-20010</b></p>  <p>AT180, AE92</p> <p>Link Assy [FR, LH, RH]</p>
<p><b>AT27-ST185F</b> <b>48820-20021</b></p>  <p>AE10#, CE100, EE101   Celica = ST185</p> <p>Link Assy [FR, LH, RH]</p>	<p><b>AT27-ST205F</b> <b>48820-20060</b></p>  <p>Toyota Carina ED [1993-1999] = ST20#   Toyota Celica [1993-1999] = AT200, ST20#   Toyota Corona EXIV</p> <p>Link Assy [FR, LH, RH]</p>
<p><b>AT27-AE100E00</b> <b>48830-12060</b></p>  <p>Toyota Corolla / HB / LB [1992-1997] = AE10#, CE10#, EE10#   Toyota LVN / CRE / TRN / MRN [1991-1998]</p> <p>Link Assy [RE, LH, RH]</p>	
<p><b>AT27-ZT231F</b> <b>48820-32010</b></p>  <p>Toyota Celica [1999-2006] = ZZT23#</p> <p>Link Assy [FR, LH, RH]</p>	



## TOYOTA

Revision : 2014-November-01

<b>AT27-W110F</b> <b>48820-02050</b>  Corolla / Altis [2001-2007] = ZZE12#   Wish [2003] = ANE1# Link Assy [FR, LH, RH] [2 Heads]	RBI-2005-December-03 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT27-W110E</b> <b>48820-24010</b>  Corolla / Altis [2001-2007] = ZZE12#   Wish [2003] = ANE1# Link Assy [RE, LH, RH]	RBI-2005-December-23 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT27-ZE121F</b> <b>48820-47010</b>  Corolla / Altis [2001-2007] = ZZE12# Link Assy [FR, LH, RH] [2 Heads]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT27-ZE124E</b> <b>48830-32050</b>  Corolla, AXIO, FIELDER, RUNX, ALLEX, SPACIO, WILL VS [2001-2007] = ZZE124, ZZE129, NZE124, NZE144   Link Assy [RE, LH, RH] [4WD]	RBI-2013-March-08 RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT27-ZE141F</b> <b>48820-02100</b>  Corolla / Altis [2007] = ZZE14# Link Assy [FR, LH, RH] [2 Heads]	RBI-2009-September-07 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT27-Z15E00</b> <b>48830-05030</b>  Auris [2007] = ADE157.. [UKP]   Auris, Hybrid [2007] = ADE15#, NDE150, NRE150, ZRE15#, ZZE150, ZWE15 Link Assy [RE]	ARP Product www.rbi.ae
<b>AT27-ZRR70F</b> <b>48820-44020</b>  Noah, Voxy [2001-2010] = ZRR70, AZR60   PICNIC, AVENSIS, VERSO, IPSUM [2001-2007] = ACM20, ACM21   I Link Assy [FR, LH, RH] [2 Heads] [4WD]	RBI-2013-July-19 RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT27-ANH10F</b> <b>48820-58010</b>  Alphard [2002-2005] = ANH10, ATH10, MNH10 Link Assy [FR, LH, RH] [2 Heads]	Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT27-AZT25EL</b> <b>48840-21010</b>  Avensis [2003-2008] = AZT250, AZT255, CDT250 [2WD, 4WD]   Caldina [2002-2007] = AZT240, AZT246, ST24 Link Assy [RE, LH]	RBI-2013-March-14 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT27-AZT25ER</b> <b>48830-21020</b>  Avensis [2003-2008] = AZT250, AZT255, CDT250 [2WD, 4WD]   Caldina [2002-2007] = AZT240, AZT246, ST24 Link Assy [RE, RH]	RBI-2013-March-08 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-C0091F</b> <b>48820-33000</b></p>  <p>Camry 91</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product, shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT27-SV32E</b> <b>48830-32030</b></p>  <p>Toyota Camry / Vista [1990-1994] = SV3#, VZV3#, CV30</p> <p>Link Assy [RE, LH, RH]</p>	<p><b>AT27-SV43E</b> <b>48830-32040</b></p>  <p>Camry Vista = SV43, CV43, SV35</p> <p>Link Assy [RE, LH, RH] [2 Heads]</p>
<p><b>AT27-96E</b> <b>48830-33010</b></p>  <p>Camry = SXV10, SXV20   Camry Vista = CV40, SV41, SV42   Ipsum [2001] = ACM21   ISIS [2004] = ANM1#,</p> <p>Link Assy [RE, LH, RH] [2 Heads]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT27-C03FL</b> <b>48810-33010</b></p>  <p>Camry [1996-2001] = SXV2#</p> <p>Link Assy [FR, LH] [2 Heads]</p>	<p><b>AT27-C03FR</b> <b>48820-33020</b></p>  <p>Camry [1996-2001] = SXV2#</p> <p>Link Assy [FR, RH] [2 Heads]</p>
<p><b>AT27-C031FL</b> <b>48810-33020</b></p>  <p>Camry [2001-2006] = ACV35</p> <p>Link Assy [FR, LH] [2 Heads]</p>	<p><b>AT27-C031FR</b> <b>48820-33030</b></p>  <p>Camry [2001-2006] = ACV35</p> <p>Link Assy [FR, RH] [2 Heads]</p>





**TOYOTA**

Revision : 2014-November-01

<p><b>AT27-C04E00</b>  <b>48830-48010</b></p> <p>Camry [2002-2006] = ACV30, ACV31, MCV30</p> <p>Link Assy [RE, LH, RH] [2 Heads]</p>	<p><b>AT27-C04F00</b>  <b>48820-28050</b></p> <p>Camry [2002-2006] = ACV30, ACV31, MCV30   Estima / Previa / Tarago [2000-2006] = ACR30, ACR40, MCR30</p> <p>Link Assy [FR, LH, RH]</p>
<p><b>AT27-MHU38E</b>  <b>48830-48030</b></p> <p>Lexus RX400H / Harrier HV [2005] = MHU38</p> <p>Link Assy [RE, LH, RH]</p>	<p><b>AT27-MHU38F</b>  <b>48820-08020</b></p> <p>Lexus RX400H / Harrier HV [2005] = MHU38   Sienna [2003-2006] = MCL2#, GSL2#</p> <p>Link Assy [FR, LH, RH]</p>
	<p><b>AT27-ACR3F00</b>  <b>48820-28060</b></p> <p>Estima / Previa / Tarago [2000-2006] = ACR30, ACR40, MCR30, MCR40, CLR30</p> <p>Link Assy [FR, LH, RH]</p>
<p><b>AT27-C05E00</b>  <b>48830-06070</b></p> <p>Camry [2006-2010] = ACV4#</p> <p>Link Assy [RE, LH, RH]</p>	<p><b>AT27-C05F00</b>  <b>48820-06070</b></p> <p>Camry [2006-2010] = ACV4#</p> <p>Link Assy [FR, LH, RH]</p>
<p><b>AT27-C06E00</b>  <b>48830-33040</b></p> <p>Camry [2006-2010] = ACV4#   Lexus ES350 [2006] = GSV40</p> <p>Link Assy [RE, LH, RH]</p>	<p><b>AT27-C06F00</b>  <b>48820-33060</b></p> <p>Camry [2006-2010] = ACV4#   Lexus ES350 [2006] = GSV40</p> <p>Link Assy [FR, LH, RH]</p>
<p><b>AT27-C061E00</b>  <b>48830-06050</b></p> <p>Camry [2006-2010] = ACV4#</p> <p>Link Assy [RE, LH, RH]</p>	
<p><b>AT27-RX35008EL</b>  <b>48803-48010</b></p> <p>Toyota Lexus RX270, RX350, RX450 [2008] = AGL10, GGL1#, GYL1#</p> <p>Link Assy [RE, LH]</p>	<p><b>AT27-RX35008ER</b>  <b>48802-48010</b></p> <p>Toyota Lexus RX270, RX350, RX450 [2008] = AGL10, GGL1#, GYL1#</p> <p>Link Assy [RE, RH]</p>

















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT27-GX81FL</b> <b>48810-22011</b>  Mark II, Chaser, Cressida = GX81 Link Assy [FR, LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT27-GX81FR</b> <b>48820-22011</b>  Mark II, Chaser, Cressida = GX81 Link Assy [FR, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT27-880F0</b> <b>48820-22041</b>  Mark II, Chaser = GX90, GX100, JZS155 Link Assy [FR, LH, RH]	RBI-2005-December-23 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT27-880E0</b> <b>48830-22041</b>  Mark II, Chaser = GX90, GX100, JZS155 Link Assy [RE, LH, RH]	RBI-2005-December-03 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT27-GX93FL</b> <b>48810-22041</b>  Mark II / BLIT / Chaser / CRESTA / VEROSSA [1992-2004] = GX93, GX105, GX115, JZX115 [4WD]   CROWN / Link Assy [FR, LH]	RBI-2013-October-14 RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT27-GX93FR</b> <b>48820-22051</b>  Mark II / BLIT / Chaser / CRESTA / VEROSSA [1992-2004] = GX93, GX105, GX115, JZX115 [4WD]   CROWN / Link Assy [FR, RH]	RBI-2013-October-14 RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-66FL</b> <b>48810-26010</b></p> <p>Toyota Hiace Van, Comuter [1989-2006] = LH10#, LH11#, LH1##, LH154, LH166, LH176, RZH10#, RZH11#, RZ</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-66FR</b> <b>48820-26010</b></p> <p>Toyota Hiace Van, Comuter [1989-2006] = LH10#, LH11#, LH1##, LH154, LH166, LH176, RZH10#, RZH11#, RZ</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-G10E</b> <b>48830-26030</b></p> <p>Grandvia = VCH10</p> <p>Link Assy [RE, LH, RH]</p>	
<p><b>AT27-G10FL</b> <b>48810-26020</b></p> <p>Grandvia = VCH10</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-G10FR</b> <b>48820-26020</b></p> <p>Grandvia = VCH10</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-RC11FL</b> <b>48810-26030</b></p> <p>LXH12, LXH22, RCH11, RCH12, RCH13, RCH22, RCH23, KLH12, KLH22, KCH10, KCH12 Hiace [1995-2001]</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-RC11FR</b> <b>48820-26030</b></p> <p>LXH12, LXH22, RCH11, RCH12, RCH13, RCH22, RCH23, KLH12, KLH22, KCH10, KCH12 Hiace [1995-2001]</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-RC135E</b> <b>48830-26011</b></p> <p>LXH12, LXH22, RCH11, RCH12, RCH13, RCH22, RCH23, KLH12, KLH22, KCH10, KCH12 Hiace [1995-2001]</p> <p>Link Assy [RE, LH, RH]</p>	
<p><b>AT27-KD20F</b> <b>48820-26050</b></p> <p>Hiace / Regiusace [2005-2010] = KDH20#</p> <p>Link Assy [FR, LH, RH]</p>	













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-RV1F</b> <b>48820-42010</b></p>  <p>Toyota Rav4 [1994-2000] = SXA1#</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT27-RV21F</b> <b>48820-42020</b></p>  <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2006-November-15 RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT27-RV21EL</b> <b>48840-42010</b></p>  <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Link Assy [RE, LH]</p>	<p><b>AT27-RV21ER</b> <b>48830-42010</b></p>  <p>Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#</p> <p>Link Assy [RE, RH]</p>
<p><b>AT27-RV10F</b> <b>48820-42030</b></p>  <p>Toyota Rav4 / Vanguard [2005-2012] = ACA3#, ALA3#, ASA3#, GSA3#, ZSA3#</p> <p>Link Assy [FR, LH, RH] [2 Heads]</p>	<p><b>AT27-RV10E</b> <b>48830-42020</b></p>  <p>Toyota Rav4 / Vanguard [2005-2012] = ACA3#, ALA3#, ASA3#, GSA3#, ZSA3#</p> <p>Link Assy [RE, LH, RH]</p>





















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT27-T11FL</b> <b>48810-28020</b>  Previa / Lucida [1990-1999] = TCR1#, TCR2# Link Assy [FR, LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-T11FR</b> <b>48820-28030</b>  Previa / Lucida [1990-1999] = TCR1#, TCR2# Link Assy [FR, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-CR27F</b> <b>48820-28020</b>  Townace / Liteace / Noah [1996-2004] = SR40, SR50, CR40, CR50   CR27 Link Assy [FR, LH, RH]	RBI-2008-April-24 RBI Product, Perfect Product, Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-SR40E</b> <b>48830-28010</b>  Townace / Liteace / Noah [1996-2004] = SR40, SR50, CR40, CR50 Link Assy [RE, LH, RH]	RBI-2013-December-16 RBI Product, Tenacity Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-SR40FL</b> <b>48810-28030</b>  Townace / Liteace / Noah [1996-2004] = SR40, SR50, CR40, CR50 Link Assy [FR, LH]	RBI-2014-March-12 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-SR40FR</b> <b>48820-28040</b>  Townace / Liteace / Noah [1996-2004] = SR40, SR50, CR40, CR50 Link Assy [FR, RH]	RBI-2014-March-12 RBI Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT27-4N130F</b> <b>48820-35010</b>  Toyota Hilux [2WD] [1988-2004] = RN8#, RN90, RN125, RN1##, RZN200, YN8#, YN9#, YN1##, LN8#, LN90, LN Link Assy [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT27-4N130E</b> <b>48830-35010</b>  Toyota Hilux [2WD] [1988-2004] = RN8#, RN90, RN125, RN1##, RZN200, YN8#, YN9#, YN1##, LN8#, LN90, LN Link Assy [RE, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-L05F00</b> <b>48820-35030</b></p> <p>Toyota Land Cruiser Prado [1996] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Link Assy [FR, LH, RH]</p>	<p><b>AT27-ZJ95E</b> <b>48830-35020</b></p> <p>Toyota Land Cruiser Prado [1996] = KZJ9#, LJ9#, RZJ9#, VZJ9#</p> <p>Link Assy [RE, LH, RH]</p>
<p><b>AT27-KZJ12FL</b> <b>48810-60040</b></p> <p>Toyota Land Cruiser Prado [2002-2005] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#   Lexu</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-KZJ12FR</b> <b>48820-60050</b></p> <p>Toyota Land Cruiser Prado [2002-2005] = KDJ12#, KZJ12#, TRJ12#, GRJ12#, RZJ12#, LJ12#, VZJ12#   Lexu</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-GRJ15E00</b> <b>48830-60030</b></p> <p>Toyota Land Cruiser Prado 120 [2002-2009] = GRJ12#, KDJ12#, KZJ120, LJ12#, RZJ12#, TRJ12#, VZJ12#, U</p> <p>Link Assy [RE, LH, RH]</p>	












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-VG02F</b> <b>48820-0K010</b></p>  <p>Hilux Vigo [2WD]</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2005-May-12 RBI Product, Perfect Product, Tenacity Product, Ashimori Product</p> <p>shabbirh@eim.ae</p>  <p><a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT27-VG04FL</b> <b>48810-0K010</b></p>  <p>Hilux Vigo [4WD]   4Runner [2002-2005] = GRN21#, KZN215, UZN21#   FJ Cruiser [2006- 2007] = GSJ1#   H</p> <p>Link Assy [FR, LH]</p>	<p>RBI-2007-June-04 RBI Product, Perfect Product, Tenacity Product, Ashimori Product</p> <p>shabbirh@eim.ae</p>  <p><a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p><b>AT27-VG04FR</b> <b>48820-0K030</b></p>  <p>Hilux Vigo [4WD]   4Runner [2002-2005] = GRN21#, KZN215, UZN21#   FJ Cruiser [2006- 2007] = GSJ1#   H</p> <p>Link Assy [FR, RH]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-RZN14F00</b> <b>48820-35020</b></p> <p>Toyota Tacoma [1995-2004] = RZN140, RZN150, RZN160, RZN161, RZN171, RZN19#, VZN150, VZN160, VZN170,</p> <p>Link Assy [FR]</p>	<p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	
<p><b>AT27-UCK30F00</b> <b>48820-34010</b></p> <p>Tundra / Sequoia [2000-2006] = GSK3#, UCK3#, UCK4#, VCK30, VCK40</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2013-May-28 RBI Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-KZ7FL</b> <b>48810-60010</b></p> <p>Toyota Land Cruiser [1990-1996] = KZJ7#, LJ7#, RJ7#, BJ7#</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-KZ7FR</b> <b>48820-60010</b></p> <p>Toyota Land Cruiser [1990-1996] = KZJ7#, LJ7#, RJ7#, BJ7#</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-KZ7E00</b> <b>48830-60010</b></p> <p>Toyota Land Cruiser [1990-1996] = KZJ7#, LJ7#, RJ7#, BJ7#</p> <p>Link Assy [RE, LH, RH]</p>	











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT27-FZJ80F</b> <b>48802-60050</b>  Toyota Land Cruiser 80 [1990-2001] = FJ80, FZJ80, HDJ80, HDJ81, HZJ80, HZJ81  Link Assy [FR, LH, RH]	<small>ASH-2013-November-15 HFC Product, Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT27-FZJ81F</b> <b>48802-60060</b>  Toyota Land Cruiser / Lexus LX450 [1990-2001] = FZJ80, HDJ81, HZJ80  Link Assy [FR, LH, RH]	<small>ASH-2013-November-15 HFC Product, Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT27-FZJ82F</b> <b>48802-60030</b>  Toyota Land Cruiser / Lexus LX450 [1990-2001] = FZJ80, HDJ81, HZJ80  Link Assy [FR, LH, RH]	<small>Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
<b>AT27-LE00E</b> <b>48802-60090</b>  Lexus LX470 [1998-2006] = UZJ100  Link Assy [RE, LH, RH]	<small>RBI-2008-February-19 RBI Product, Perfect Product, Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>AT27-LE00F</b> <b>48820-60032</b>  Lexus LX470 [1998-2006] = UZJ100  Link Assy [FR, LH, RH]	<small>RBI-2008-March-17 RBI Product, Perfect Product, Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>AT27-HZJ105F00</b> <b>48802-60120</b>  Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ101, UZJ100  Link Assy [FR, LH, RH]	<small>Ashimori Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		












# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-UZ200F00</b> <b>48802-60100</b></p> <p>Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200..VX</p> <p>Link Assy [FR, LH, RH]</p>  	<p><b>AT27-UZ20F</b> <b>48802-60110</b></p> <p>Toyota Land Cruiser / Lexus LX570 [2007] = GRJ200, UZJ200, VDJ200, URJ201..GX</p> <p>Link Assy [FR, LH, RH]</p>  
<p><b>AT27-UZ200FL</b> <b>48810-60060</b></p> <p>Toyota Land Cruiser / Lexus LX570 [2007] = UZJ200, VDJ200</p> <p>Link Assy [FR, LH]</p> 	
<p><b>AT27-UZ201FL</b> <b>48810-60051</b></p> <p>Toyota Land Cruiser / Lexus LX570 [2007] = GRJ200, UZJ200, VDJ200, URJ201</p> <p>Link Assy [FR, LH]</p> 	<p><b>AT27-UZ201FR</b> <b>48820-60071</b></p> <p>Toyota Land Cruiser / Lexus LX570 [2007] = GRJ200, UZJ200, VDJ200, URJ201</p> <p>Link Assy [FR, RH]</p> 














# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-EP91F</b> <b>48820-10010</b></p>  <p>Starlet [1996-1999] = EP91</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2013-November-14 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT27-YA91F</b> <b>48820-0D020</b></p>  <p>Yaris / Echo / Vios / Soluna [2005-2010] = NCP9#, ZSP9#   Yaris [2011] = NCP13#</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2008-November-12 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
	<p><b>AT27-NCP92F</b> <b>48820-52030</b></p>  <p>Yaris / Vios / Ractis [2005-2010] = NCP9#, SCP100</p> <p>Link Assy [FR, LH, RH]</p>
<p><b>AT27-F60F</b> <b>48820-B0010</b></p>  <p>AVanza [2003] = F601, F602 [USA]</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2010-February-18 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-UC10FL</b> <b>48810-50011</b></p>  <p>Lexus LS400 [1989-2000] = UCF10, UCF20   CENTURY [1998-] = GZG50</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-UC10FR</b> <b>48820-50011</b></p>  <p>Lexus LS400 [1989-2000] = UCF10, UCF20   CENTURY [1998-] = GZG50</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-LS40E</b> <b>48830-50020</b></p>  <p>Lexus LS400 [90-1994] = UCF10</p> <p>Link Assy [RE, LH, RH]</p>	
<p><b>AT27-UCF30F00</b> <b>48820-50020</b></p>  <p>Lexus LS430 / Celsior [2000-2006] = UCF3#</p> <p>Link Assy [FR, LH, RH]</p>	
<p><b>AT27-UCF30EL</b> <b>48840-50010</b></p>  <p>Lexus LS430 / Celsior [2000-2006] = UCF3#</p> <p>Link Assy [RE, LH]</p>	<p><b>AT27-UCF30ER</b> <b>48830-50030</b></p>  <p>Lexus LS430 / Celsior [2000-2006] = UCF3#</p> <p>Link Assy [RE, RH]</p>
<p><b>AT27-USF40FL</b> <b>48810-50020</b></p>  <p>Lexus LS460 [2006-2010] = USF4#</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-USF40FR</b> <b>48820-50030</b></p>  <p>Lexus LS460 [2006-2010] = USF4#</p> <p>Link Assy [FR, RH]</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT27-86FL</b> <b>48820-30020</b></p> <p>Crown / Crown Majesta [1993-1995] = UZS141   MS132, MS133   Crown [1987-1995] = GS131</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-86FR</b> <b>48820-30010</b></p> <p>Crown / Crown Majesta [1993-1995] = UZS141   MS132, MS133   Crown [1987-1995] = GS131</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-870E</b> <b>48830-30020</b></p> <p>Crown / Crown Majesta [1993-1995] = UZS141   MS132, MS133   Crown [1987-1995] = GS131   Mark II / Ch</p> <p>Link Assy [RE, LH, RH]</p>	
<p><b>AT27-86EL</b> <b>48706-30030</b></p> <p>Crown / Crown Majesta [1993-1995] = UZS141   MS132, MS133   Crown [1987-1995] = GS131</p> <p>Link Assy [RE, LH]</p>	<p><b>AT27-86ER</b> <b>48705-30060</b></p> <p>Crown / Crown Majesta [1993-1995] = UZS141   MS132, MS133   Crown [1987-1995] = GS131</p> <p>Link Assy [RE, RH]</p>
<p><b>AT27-JZ147FL</b> <b>48810-30010</b></p> <p>Crown / Crown Majesta [1995-2004] = UZS151, UZS171, UZS175   Aristo [1991-2005] = JZS147, JZS160, JZ</p> <p>Link Assy [FR, LH]</p>	<p><b>AT27-JZ147FR</b> <b>48820-30030</b></p> <p>Crown / Crown Majesta [1995-2004] = UZS151, UZS171, UZS175   Aristo [1991-2005] = JZS147, JZS160, JZ</p> <p>Link Assy [FR, RH]</p>
<p><b>AT27-JZ147E</b> <b>48830-30060</b></p> <p>Crown / Crown Majesta [1995-1999] = UZS151   Aristo [1991-1997] = JZS147   Lexus GS300 [1993-1997] =</p> <p>Link Assy [RE, LH, RH]</p>	<p><b>AT27-JZ148E</b> <b>48830-24010</b></p> <p>Crown / Crown Majesta [1995-1999] = UZS151   Aristo [1991-1997] = JZS147   Lexus GS300 [1993-1997] =</p> <p>Link Assy [RE, LH, RH]</p>
<p><b>AT27-UZ155EL</b> <b>48840-14030</b></p> <p>Crown / Crown Majesta [1995-1999] = UZS155   Supra [1993-2002] = JZA80</p> <p>Link Assy [RE, LH]</p>	<p><b>AT27-UZ155ER</b> <b>48830-14050</b></p> <p>Crown / Crown Majesta [1995-1999] = UZS155   Supra [1993-2002] = JZA80</p> <p>Link Assy [RE, RH]</p>



**TOYOTA**

Revision : 2014-November-01

<b>AT27-GR180FL</b> <b>48810-30070</b> Crown / Crown Majesta [2004-2008] = GRS180, GRS20#, GWS204, URS206, UZS207   Lexus GS300 / GS350 / G  Link Assy [FR, LH]	<b>AT27-GR180FR</b> <b>48820-30090</b> Crown / Crown Majesta [2004-2008] = GRS180, GRS20#, GWS204, URS206, UZS207   Lexus GS300 / GS350 / G  Link Assy [FR, RH]
<b>AT27-GR181FL</b> <b>48810-30080</b> Toyota Lexus GS300, GS350, GS430, GS460 [2005-2011] = GRS19#, URS190, UZS190   Toyota Mark X [2004-2  Link Assy [FR, LH]	<b>AT27-GR181FR</b> <b>48820-30100</b> Toyota Lexus GS300, GS350, GS430, GS460 [2005-2011] = GRS19#, URS190, UZS190   Toyota Mark X [2004-2  Link Assy [FR, RH]
<b>AT27-GSE2FL</b> <b>48810-53010</b> Lexus IS250 / IS220d / IS300 / IS350 [2005-2006] = ALE20, GSE2#  Link Assy [FR, LH]	<b>AT27-GSE2FR</b> <b>48820-53010</b> Lexus IS250 / IS220d / IS300 / IS350 [2005-2006] = ALE20, GSE2#  Link Assy [FR, RH]
<b>AT27-GR180E</b> <b>48830-30090</b> Crown / Crown Majesta [2004-2008] = GRS180, GRS20#, GWS204, URS206, UZS207   Lexus GS300 / GS350 / G  Link Assy [RE, LH, RH]	
<b>AT27-JZ160E</b> <b>48830-30080</b> Crown / Crown Majesta [1999-2004] = UZS171, UZS175, UZS173 [4WD]   Aristo [1997-2005] = JZS160, JZS1  Link Assy [RE, LH, RH]	<b>AT27-JZ175E</b> <b>48830-51010</b> Crown / Crown Majesta [1999-2003] = GS171, JKS175, JZS17#   Altezza / Altezza Gita [1998-2003] = GXE  Link Assy [RE, LH, RH]



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924  
E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01

<p>AT27-XB51F00 48820-36010</p> <p>Coaster [1993-2005] = HDB51, HZB41, XZB51</p> <p>Link Assy [FR, LH, RH]</p>  <p>RBI-2013-May-28 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01

AT27-BB55E00 48830-36020 Coaster [1993-2006] = BB4#, BB5#, BZB40, BZB50, HDB50, HZB40, HZB50, RZB40, RZB50, TRB40, TRB50, XZB Link Assy [RE, LH, RH]	 <p>RBI-2013-March-14 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT28-41E</b> <b>48306-35011</b>  Toyota Hilux [1972-1978] = RN20  Bumper Bound [RE]	<b>AT28-41W</b> <b>48304-39035</b>  Toyota Hilux [1972-1978] = RN25  Bumper Bound [Lower]
<b>AT28-42W</b> <b>48304-39045</b>  Hilux [1978-1984] = LN30, LN40, RN30, RN31, RN40, RN41  Bumper Bound [Lower]	
<b>AT28-44E</b> <b>48341-35020</b>  Toyota Hilux & Pickup [1978-1988] = RN3#, RN4#, LN3#, LN4#   Toyota Liteace, Townace Van & Wagon [19  Bumper Bound [RE]	<b>AT28-44P</b> <b>48332-35010</b>  Toyota Hilux & Pickup [1978-1988] = RN3#, RN4#, LN3#, LN4#  Bumper Bound [Upper]
<b>AT28-44W</b> <b>48304-35030</b>  Toyota Hilux & Pickup [1978-1988] = RN3#, RN4#, LN3#, LN4#  Bumper Bound [Lower]	<b>AT28-45E</b> <b>48341-35040</b>  Toyota Hilux [1983-1989] = LN5#, LN6#, YN5#, YN6#, RN5#, RN6#   Toyota 4-Runner Truck [1983-1989] =  Bumper Bound [RE]
<b>AT28-45P</b> <b>48332-35020</b>  Hilux = LN50, LN85  Bumper Bound [Upper]	<b>AT28-45W</b> <b>48304-35080</b>  Hilux = LN50, RN50 [83-88]  Bumper Bound [Lower]
<b>AT28-46E</b> <b>48341-35050</b>  Hilux = LN85  Bumper Bound [RE]	<b>AT28-46W</b> <b>48304-35130</b>  Hilux = LN80, YN80 [88-97]  Bumper Bound [Lower]





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT28-47X2E</b> <b>48341-04030</b>  Hilux [97-2006] = KDN150, KDN155, LN150   Tiger 2  RBI Product, Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound [RE, 2WD]	<b>AT28-47X2C</b> <b>48341-04040</b>  Hilux [97-2006] = KDN145, LN145   Tiger 4  RBI-2009-August-29 RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound [RE, 4WD]
<b>AT28-4X3PB</b> <b>48304-04060</b>  Hilux = LN111, LN145, TIGER  RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound	<b>AT28-4X3PS</b> <b>48305-04020</b>  Hilux = LN111, LN145, TIGER  RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound
<b>AT28-4X3W</b> <b>48304-04050</b>  Hilux = LN111, LN145, TIGER  RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound	<b>AT28-47XE</b> <b>48306-35190</b>  Hilux = LN111, LN145, TIGER  RBI-OLD RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound [Lower]
<b>AT28-4X20E</b> <b>48306-35110</b>  Hilux = LN10#  RBI-2007-August-15 RBI Product, ARD Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound [RE]	
<b>AT28-4X4W</b> <b>48304-35100</b>  Hilux = LN106, RN106, YN106 [4WD]  RBI-2007-May-14 RBI Product, Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound [FR, Lower, Small]	<b>AT28-4X4W2</b> <b>48304-35110</b>  Hilux = LN106, RN106, YN106 [4WD]  ARD-2013-May-01 Perfect Product, ARD Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Bumper Bound [FR, Lower, Big]






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT28-VG02W</b> <b>48304-0K010</b></p> <p>Hilux Vigo</p>  <p>Bumper Bound [2WD] [Lower]</p>	<p><b>AT28-VG02E</b> <b>48341-0K010</b></p> <p>Hilux Vigo [2004] = KUN10, KUN15, KUN16, GGN15, TGN15, TGN16, LAN15</p>  <p>Bumper Bound [2WD] [RE]</p>
<p><b>AT28-VG04W</b> <b>48304-0K040</b></p> <p>Hilux Vigo</p>  <p>Bumper Bound [4WD] [Lower]</p>	<p><b>AT28-VG04E</b> <b>48306-0K010</b></p> <p>Hilux Vigo [2004] = KUN2#, KUN3#, GGN25, TGN26, TGN36</p>  <p>Bumper Bound [4WD] [RE]</p>
<p><b>AT28-IN40E</b> <b>48341-0K030</b></p> <p>Hilux Vigo / Innova / Kijang [2004] = KUN40, TGN40, TGN41</p>  <p>Bumper Bound [RE]</p>	
<p><b>AT28-FR50E</b> <b>48341-0K050</b></p> <p>Hilux Vigo / Fortuner [2005] = KUN5#, KUN6#, TGN5#, TGN6#, GGN50, GGN60, LAN50</p>  <p>Bumper Bound [RE]</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT28-62P</b> <b>48305-26011</b>  Hiace = RH20, RH30 Bumper Bound [Upper]	<b>AT28-62W</b> <b>48304-26010</b>  Hiace = RH20, RH30 Bumper Bound [Lower]
<b>AT28-LH20F</b> <b>48305-29016</b>  Hiace [1977-1985] = LH11, LH2#, LH3#, RH11, RH2#, RH3#, RH42 Bumper Bound [FR]	
<b>AT28-KD20E</b> <b>48341-26240</b>  Hiace / Regiusace [2005-2010] = KDH20# Bumper Bound [RE]	<b>AT28-KD20W</b> <b>48331-26140</b>  Hiace / Regiusace [2005-2010] = KDH20# Bumper Bound [Lower]
<b>AT28-KD20S</b> <b>48252-28170</b>  Hiace / Regiusace [2005-2010] = KDH20# Bumper Bound	
	<b>AT28-SR40F</b> <b>48331-28020</b>  Lite, Townace [1999-2007] = CM7#, CM8#, KM7#, KM8#   Lite, Townace Noah, V [1996-2001] = SR40, SR50 Bumper Bound [FR]
<b>AT28-SR41F</b> <b>48332-28020</b>  Lite, Townace Noah, V [1996-2007] = CR5#, SR50, KR52.. [4WD] Bumper Bound	
<b>AT28-SHAP</b> <b>48332-35SHA</b>  ALL CARS Bumper Bound	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT28-920E</b> <b>48344-36190</b></p> <p>Dyna 200 [1982-2000] = BU10, BU14, BU21#, BU22#, AL Dyna</p> <p>Bumper Bound [RE]</p> <p>PFT-2013-June-25 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT28-921E</b> <b>48344-36180</b></p> <p>Dyna 200 [1982-2000] = BU10, BU14, BU21#, BU22#, AL Dyna</p> <p>Bumper Bound [RE]</p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT28-RN67W</b> <b>48304-36040</b></p> <p>Coaster [1982-1993] = RB2#, BB2#, BB3#, HB3#, FB30, HDB20, HDB3#, HZB3#   RN67, YN67</p> <p>Bumper Bound</p> <p>RBI-2010-May-28 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT28-BB4FR</b> <b>48304-36170</b></p> <p>Coaster [China] [1993-2007] = HZB50, BB42, 50, 53, 58, RZB40, 50, 53, XZB50, 53, BB58, TRB53</p> <p>Bumper Bound [FR, RH]</p> <p>ARD-2013-May-01 ARD Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT28-BU60E01</b> <b>48435-36050</b></p> <p>Toyota BU61, BU60</p> <p>Bumper Bound</p> <p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT28-BU65F01</b> <b>48304-36150</b></p> <p>Dyna [1988-1997] = BU65</p> <p>Bumper Bound [FR]</p> <p>PFT-2014-August-31 Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AT28-YY200E01</b> <b>48304-36021</b></p> <p>Toyota DYNA 150 / TOYOACE G15 [1985-2006] = LY6#, YY5#, YY6#, LY20#, LY21#, YY201, YY211, LY225, LY2</p> <p>Bumper Bound</p> <p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	
<p><b>AT28-65E</b> <b>48341-26150</b></p> <p>Hiace = LH112</p> <p>Bumper Bound [RE]</p> <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AT28-65W</b> <b>48331-26090</b></p> <p>Hiace = LH112</p> <p>Bumper Bound [Lower]</p> <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
	<p><b>AT28-LN65E00</b> <b>48306-35050</b></p> <p>Toyota Hilux [1983-1985] = LN6#, YN6#</p> <p>Bumper Bound [RE]</p> <p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT28-BJ40F</b> <b>48304-60010</b>  Toyota Land Cruiser [1969-1986] = BJ4#, HJ45, HJ47, FJ4#, FJ55 Bumper Bound [FR, LH, RH]	ARD-2014-January-01 Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AT28-FJ01FR</b> <b>48304-60041</b> Toyota Land Cruiser [1984-1987] = RJ7#, LJ7# Bumper Bound [FR, RH]	ARD-2013-August-01 ARD Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT28-FJ01FL</b> <b>48305-60011</b> Toyota Land Cruiser [1984-1987] = RJ7#, LJ7# Bumper Bound [FR, LH]
<b>AT28-FJ02E</b> <b>48306-60060</b> Toyota Land Cruiser [1984-1987] = RJ7#, LJ7# Bumper Bound [RE]	ARD-2014-January-01 ARD Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AT28-FJ00E</b> <b>48306-60080</b>  Toyota Land Cruiser = FJ7#, FZJ7#, HJ7#, HZJ7#, PZJ7#, [HEAVY-DUTY] Bumper Bound [RE]	RBI-2007-August-01 RBI Product, Ashimori Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT28-FJ01E</b> <b>48306-60050</b>  Toyota Land Cruiser = FJ7#, FZJ7#, HJ7#, HZJ7#, PZJ7# Bumper Bound [RE]
<b>AT28-FJ01WL</b> <b>48305-60020</b>  Toyota Land Cruiser [1984-1987] = BJ7#, FJ7#, HJ75 Bumper Bound [FR, LH, Lower]	RBI-2008-September-04 RBI Product, Perfect Product, Ashimori Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT28-FJ01WR</b> <b>48304-60050</b>  Toyota Land Cruiser [1984-1987] = BJ7#, FJ7#, HJ75 Bumper Bound [FR, RH, Lower]









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT28-FJ80F0</b> <b>48304-60080</b> Toyota Land Cruiser [1990-1998] = LJ7#, RJ7#, KZJ7#, FZJ80, HDJ80, HZJ80   Toyota Land Cruiser 100 [ Bumper Bound [FR, RH]	ARD-2014-January-01 ARD Product, HFC Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AT28-FJ80E0</b> <b>48306-60100</b> Toyota Land Cruiser [1990-1992] = FJ80, HDJ8#, HZJ80 Bumper Bound [RE]	ARD-2014-January-01 ARD Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT28-FZJ100E</b> <b>48306-60140</b> Toyota Land Cruiser [1998-2002] = HDJ101, UZJ100   Toyota Land Cruiser 100 [1998-2006] = FZJ100, HDJ Bumper Bound [RE]
<b>AT28-UZ10E</b> <b>48313-60050</b> Toyota Land Cruiser 100 [1998-2005] = UZ100, HDJ100 Bumper Bound [RE]	ARD-2015-January-31 ARD Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT28-HDJ100E</b> <b>48313-60010</b> Toyota Land Cruiser 100 [1990-2005] = FJ80, HZJ80, HDJ80, FZJ10#, HDJ100, UZJ100, FZJ105 Bumper Bound [RE]
<b>AT28-LC95001</b> <b>48302-60010</b> Toyota Land Cruiser [1995] Bumper Bound	ARD-2013-May-01 ARD Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT28-LC95002</b> <b>48302-60060</b> Toyota Land Cruiser [1995-2002] = 1HZ..FJ78 Bumper Bound








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT28-VZJ95E</b> <b>48306-60121</b>  4Runner / Toyota Land Cruiser 90 [1998-2002] = KZN185, RZN18#, VZJ18#, KZJ95, LJ9#  Bumper Bound [RE]	 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT28-ZJ95E0</b> <b>48306-60120</b>  Toyota Land Cruiser Prado [1996-1998] = KZJ95, LJ95, RZJ95, VZJ95  Bumper Bound [RE]	 ARD-2013-August-01 ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT28-VZN18E</b> <b>48306-35180</b>  Toyota Land Cruiser Prado [1996-2000] = LJ90  Bumper Bound [RE]	 ARD-2015-January-31 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
<b>AT28-GRJ12E</b> <b>48306-60180</b>  4Runner [2002-2005] = GRN21#, KZN215, UZN21#   FJ Cruiser [2006-2007] = GSJ1#   Toyota Land Cruiser  Bumper Bound [RE]	 ARD-2015-January-31 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT28-VZN13E</b> <b>48306-35140</b>  Hilux / 4Runner [1989-1995] = LN130, RN130, VZN130, YN130  Bumper Bound [RE]	 ARD-2013-May-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT28-DJ21EL</b> <b>48036-60010</b>  Toyota Land Cruiser Prado [2002] = KDJ215  Bumper Bound [RE, LH]	 RBI-2009-December-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT28-DJ21ER</b> <b>48306-60200</b>  Toyota Land Cruiser Prado [2002] = KDJ215  Bumper Bound [RE, RH]	 RBI-2008-June-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT28-00001</b> <b>48304-00000</b>  ALL CARS  Bumper Bound	 ARD-2013-May-01 ARD Product www.rbi.ae		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT29-050</b> <b>37230-14031</b>  <b>TT132</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT29-060</b> <b>37230-24010</b>  <b>Toyota Carina FR [1981-1988] = TA6#, AA6#, SA60, RA63, KA67, CA6#   Toyota Celica [1981-1985] = AA63</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT29-411</b> <b>37230-35013</b>  <b>Toyota Hilux [1972-1978] = RN20</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT29-412</b> <b>37230-40031</b>  <b>Toyota Hilux [1972-1978] = RN25</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT29-440</b> <b>37230-35030</b>  <b>Toyota Hilux &amp; Pickup [1978-1988] = RN3#, RN4#, LN3#, LN4#</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT29-441</b> <b>37230-35040</b>  <b>Stout [1979-1983] = RK110</b>  <b>Center Bearing</b>	  <p>Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT29-450</b> <b>37230-35050</b>  <b>LN50, LN85</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>		
<b>AT29-47X4</b> <b>37230-35130</b>  <b>LN145, TIGER</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT29-47X2</b> <b>37230-35120</b>  <b>Toyota Hilux [1997-2006] = KZN165, KZN190, KDN1##, LN147, LN16#, LN17#, LN1##, RZN147, RZN152, RZN16</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT29-4X10</b> <b>37230-35061</b>  <b>LN65</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<b>AT29-4X20</b> <b>37230-35080</b>  <b>LN106 [4WD]</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<b>AT29-650</b> <b>37230-26010</b>  <b>LH112</b>  <b>Center Bearing</b>	  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>		







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT29-830 37230-30022</p>  <p>Toyota Crown [1974-1979] = RS80, MS8#, MS95</p> <p>Center Bearing</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p>AT29-840 37230-30030</p>  <p>Toyota Crown [1979-1983] = GS11#, LS11#, MS11#, RS110</p> <p>Center Bearing</p>	<p>AT29-850 37230-30040</p>  <p>Toyota Crown [1983-1987] = GS12#, LS12#, MS12#, YS120   Toyota Crown [1987-1991] = GS13#, JZS13#, LS</p> <p>Center Bearing</p>
<p>AT29-KE7000 37230-12040</p>  <p>KE70</p> <p>Center Bearing</p>	<p>AT29-KR7100 37230-12050</p>  <p>KE70, AE80</p> <p>Center Bearing</p>
<p>AT29-AE104G01 37230-12120</p> <p>Corolla [1991-2000] = AE104, CE104.. [4WD]   Corolla [1991-2002] = AE109, CE109.. [4WD]   Corolla [1</p> <p>Center Bearing</p>	<p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT29-BU10 37230-36014</p> <p>Dyna / Coaster = BU10, RU30</p> <p>Center Bearing</p> <p>PFT-2012-August-30 Perfect Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	
<p>AT29-BU30 37230-36021</p> <p>Dyna / Coaster = BU20, BU30</p> <p>Center Bearing</p> <p>PFT-2012-March-28 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	<p>AT29-BU75 37230-36061</p> <p>Dyna / Coaster = BU61, BU80, BU90, RU30, WU90   Coaster [1983-1993] = BB2#, BB3#, HB3#, HDB3#, HZB3#</p> <p>Center Bearing</p> <p>PFT-2012-June-26 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
<p>AT29-BU60 37230-36070</p> <p>Dyna / Coaster = BU40, RU30, RU61   Dyna [1982-1983] = BU40, HU40, HU50, WU40</p> <p>Center Bearing</p> <p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  	<p>AT29-BU80 37230-36080</p> <p>Dyna / Coaster = BU61, BU80, BU90, RU30, WU90</p> <p>Center Bearing</p> <p>PFT-2012-March-28 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  
	<p>AT29-BB20G01 37207-35011</p> <p>Coaster [1982-1993] = RB2#, BB2#, BB3#, HB3#, FB30, HDB30, HZB30   Coaster [1993] = BB#, BZB#, HZB50</p> <p>Center Bearing</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT29-VG02</b> <b>37230-0K011</b> Toyota Hilux Vigo [2004-2012] = GGN15, GGN25, GGN35, KUN1#, KUN2#, KUN3#, LAN15, LAN25, LAN35, TGN1# Center Bearing [2WD]	RBI-2007-November-12 RBI Product, Perfect Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT29-VG04</b> <b>37230-0K021</b> Toyota Hilux [2004-2012] = GGN15, GGN25, GGN35, KUN1#, KUN2#, KUN3#, LAN15, LAN25, LAN35, TGN1#, TGN Center Bearing [4WD]	RBI-2007-November-12 RBI Product, Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT29-KD200</b> <b>37230-26030</b> Hiace / Regiusace [2005-2010] = KDH20#   Liteace / Townace / Noah / Voxy [1996-2004] = CR4#, CR5#, K Center Bearing	RBI-2009-January-07 RBI Product, Perfect Product, HFC Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT29-CR500</b> <b>37230-28020</b> Hiace / Regiusace [2005-2010] = KDH20#   Liteace / Townace / Noah / Voxy [1996-2004] = CR4#, CR5#, K Center Bearing	PFT-2013-June-25 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT29-AZR600</b> <b>37230-29015</b> Toyota Noah, Voxy [2001-2007] = AZR6#   Toyota Harrier [1997-2003] = MCU15, SXU15 Center Bearing	RBI-2014-September-04 RBI Product, Perfect Product, HFC Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT29-AZR601</b> <b>37230-48010</b> Liteace / Townace / Noah / Voxy [2001-2010] = AZR6#, ZRR7#   Harrier [1997-2003] = MCU15, SXU15 Center Bearing	PFT-2013-October-10 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT29-ACR300</b> <b>37230-21020</b> Toyota Estima T, L, Previa, Tarago [1999-2006] = ACR30, ACR40, MCR30, MCR40, CLR30 Center Bearing	PFT-2013-October-10 Perfect Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT29-UCF1001</b> <b>37230-30110</b> Aristo [1991-1997] = JZS147   Crown, Crown Majesta [1991-1995] = UZS14#, JZS14#, LS141, GS141   Crow Center Bearing	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AT29-JZA80</b> <b>37230-24090</b> Supra [1993-2002] = JZA80..[6F, 4FC]   Soarer [1991-1997] = UZZ3# Center Bearing	Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AT29-UCF1003</b> <b>37230-30090</b> Crown [1988-1995] = GS131   Crown, Crown Majesta [1991-1995] = UZS14#, JZS14#, LS141, GS141   Crown, Center Bearing	HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AT29-UCF2001</b> <b>37230-50030</b> Century [1997-2005] = GZG50   Lexus LS400, Celsior [1994-2000] = UCF20 Center Bearing	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>





**TOYOTA**

Revision : 2014-November-01

<b>AT29-GX60</b> <b>37230-22042</b> Cressida [1976-1985] = GX6#, LX60, RX3#, RX60, RX62, MX3#, MX63X, TX62 Center Bearing  	<b>AT29-GX10</b> <b>37230-22110</b> Cressida [1988-1996] = MX8#, RX81   GX100, GX105, JZS151   Mark 2 / Chaser [1988-1992] = GX81, MX83, Center Bearing 
<b>AT29-GX90</b> <b>37230-22190</b> Mark 2 / Chaser / Cresta [1992-1996] = GX90, GX93, JZX9#, JZX90, 91 Center Bearing [2WD, 4WD]  	
<b>AT29-RV10</b> <b>37230-42010</b> Toyota Rav4 [1994-2000] = SXA1# Center Bearing  	<b>AT29-RV21</b> <b>37230-20130</b> Toyota Rav4 [2000-2005] = ACA2#, CLA2# Center Bearing 
<b>AT29-Z124001</b> <b>37230-19015</b> Corolla Runx, Allex [2001-2006] = NZE124, ZZE124.. [4WD]   Corolla Spacio [2001-2007] = ZZE124.. [4W] Center Bearing 	
<b>AT29-T11000</b> <b>37230-28010</b> Estima / Emina / Lucida / Previa [1990-1999] = CXR1#, CXR2#, TCR1#, TCR2# Center Bearing  	
<b>AT29-F600</b> <b>37230-BZ010</b> AVanza [2003] = F601, F602 [USA] Center Bearing  	<b>AT29-JZS1600</b> <b>37230-30170</b> Aristo [1997-2004] = JZS160, JZS161   Crown, Crown Majesta [1999-2004] = UZS17#, GS171, JKS175, JZS1 Center Bearing 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT31-070</b> <b>17573-74020</b>  Corona & Carina [1987-1992] = AT17#, ST17#  Exhaust Pipe Support	  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-090</b> <b>17571-74333</b>  AT191, ST191  Exhaust Pipe Support	  RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT31-091</b> <b>17571-74430</b>  Corona Carina [1990-2003] = AT191, ST191  Exhaust Pipe Support	  TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-280</b> <b>17572-15050</b>  AE92  Exhaust Pipe Support	  RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT31-092</b> <b>17571-74450</b>  Nadia [1998-2003] = ACN10, SXN10   Gaia / Ipsun / Picnic [1998-2004] = ACM10, CXM10, SXM10  Exhaust Pipe Support	  HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-093</b> <b>17571-74340</b>  Caldina [1992-1997] = ST195.. [4WD]   Carina FF [1992-1996] = CT195, ST195.. [4WD]   Carina FF [1996]  Exhaust Pipe Support	  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT31-285</b> <b>17565-15070</b>  Toyota Rav4 [2000-2005] = ACA2#, CLA2#, ZCA2#   Corolla / Sprinter [1987-1992] = AE9#, CE9#, EE9#    Exhaust Pipe Support	  ARD-2014-January-01 Perfect Product, ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-310</b> <b>17506-15070</b>  EE101, AE111  Exhaust Pipe Support	  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT31-311Z</b> <b>17506-15080</b>  AE110  Exhaust Pipe Support [Bracket]	  RBI-2006-July-25 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-310Z</b> <b>17506-15070</b>  AE111, EE101  Exhaust Pipe Support [Bracket]	  RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT31-460</b> <b>17572-54080</b></p>  <p>LN85</p> <p>Exhaust Pipe Support [Bracket]</p>	<p><b>AT31-46BF</b> <b>17562-54190</b></p>  <p>LN107, LN111, LN13#</p> <p>Exhaust Pipe Support [Bracket]</p>
<p><b>AT31-462</b> <b>17563-35020</b></p>  <p>LN85</p> <p>Exhaust Pipe Support [2 Hole]</p>	<p><b>AT31-463</b> <b>17566-35010</b></p>  <p>LN85</p> <p>Exhaust Pipe Support</p>
<p><b>AT31-464</b> <b>17561-73020</b></p>  <p>Hilux Surf / Toyota 4-Runner [2002-2009]   Celica [1989-1999]   Corolla 2 [1994-1999]   Corsa / Terc</p> <p>Exhaust Pipe Support</p>	<p><b>AT31-465</b> <b>17565-46040</b></p>  <p>Toyota 4-Runner [2002-2009] = GRN21#, KZN215, UZN21#   Altezza, Altezza Gita [1998-2005] = GXE10, SX</p> <p>Exhaust Pipe Support</p>
<p><b>AT31-650</b> <b>17563-63020</b></p>  <p>LH112</p> <p>Exhaust Pipe Support</p>	<p><b>AT31-659</b> <b>17565-63020</b></p>  <p>Camry [1982-1986] = SV1#, CV1#   Chaser / Cressida / Cresta [1984-1996] = MX63, MX63X, MX7#, GX71, R</p> <p>Exhaust Pipe Support</p>
<p><b>AT31-65TCK</b> <b>20650-D0101</b></p>  <p>ALL CARS</p> <p>Exhaust Pipe Support [Thick]</p>	<p><b>AT31-65THN</b> <b>20650-D0101</b></p>  <p>ALL CARS</p> <p>Exhaust Pipe Support [Thin]</p>



**TOYOTA**

Revision : 2014-November-01

<b>AT31-BU610</b> <b>17567-61030</b>  <b>BU61, Toyota Land Cruiser</b> <b>Exhaust Pipe Support</b>	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AT31-C0301</b> <b>17572-74090</b> <b>Camry [1996-2001] = SXV1#, SXV2#</b> <b>Exhaust Pipe Support</b>	HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-C0302</b> <b>17572-60200</b> <b>Toyota</b> <b>Insulator Engine</b> HFC-2014-November-20 HFC Product www.rbi.ae
<b>AT31-C0203</b> <b>17572-07040</b> <b>Camry [2002-2006] = ACV30, ACV31, MCV30</b> <b>Exhaust Pipe Support</b>	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-C040</b> <b>17572-0H040</b> <b>Camry [2002-2010] = ACV30, ACV31, MCV30, ACV40</b> <b>Exhaust Pipe Support</b> RBI-2012-April-26 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
<b>AT31-MCV10E01</b> <b>17572-20020</b> <b>Toyota Camry [1991-1996] = 1MZFE..MCV10   Toyota Windom / Lexus ES300 [1991-1996] = 1MZFE..MCV10</b> <b>Insulator Engine</b>	HFC-2014-November-20 HFC Product www.rbi.ae	
<b>AT31-KD200</b> <b>17565-28010</b> <b>KD200</b> <b>Exhaust Pipe Support</b>	RBI-2010-July-03 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AT31-RV102</b> <b>17565-74420</b> <b>Toyota Rav4 [1994-2000] = SXA1#   Toyota Land Cruiser 100 [1998-2007] = FZJ10#, HZJ105, HDJ100, HDJ1</b> <b>Exhaust Pipe Support</b>	RBI-2014-July-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
<b>AT31-LH24001</b> <b>90917-08004</b> <b>Hiace Truck [1982-1985] = LH24, RH24</b> <b>Exhaust Pipe Support Rubber</b>	ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	<b>AT31-RH2F01</b> <b>17565-31010</b> <b>Hiace [1980-1982] = RH20, RH22, RH3#, RH42..12R, 18R</b> <b>Exhaust Pipe Support Rubber [RE]</b> ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT38-ST150L</b> <b>45517-12050</b></p> <p>Corona &amp; Carina 2 [1983-1987] = AT151, ST150   Celica [1985-1990] = AT160, AT180   Corolla [1983-198</p> <p>Grommet Steering Rack [LH]</p>	<p>Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT38-09LA</b> <b>45517-20050</b></p> <p>Corona &amp; Carina [1987-1992] = AT17#, ST17#</p> <p>Grommet Steering Rack [LH, Power]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  <p><b>AT38-09LM</b> <b>45517-20060</b></p> <p>Corona &amp; Carina [1987-1992] = AT17#, ST17#, CT17#</p> <p>Grommet Steering Rack [LH, M/T]</p>
<p><b>AT38-09R</b> <b>45516-20050</b></p> <p>Corona &amp; Carina [1987-1992] = AT17#, ST17#, CT17#</p> <p>Grommet Steering Rack [RH, A/T, M/T]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT38-10LZ</b> <b>45517-20160</b></p> <p>Corona &amp; Carina [1992] = AT190</p> <p>Grommet Steering Rack [LH]</p>	<p>ARP Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  <p><b>AT38-11LM</b> <b>45517-20150</b></p> <p>Corona &amp; Carina [1992] = ST191</p> <p>Grommet Steering Rack [LH, M/T]</p>
<p><b>AT38-11RM</b> <b>45516-20080</b></p> <p>Corona &amp; Carina [1992] = ST191</p> <p>Grommet Steering Rack Bush [RH, M/T]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>  <p><b>AT38-11RP</b> <b>44250-20392</b></p> <p>Corona &amp; Carina [1992] = ST191 Exsior [Power]</p> <p>Grommet Steering Rack Bush [RH]</p>







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT38-AT220LR</b> <b>45517-05030</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Corona [1997-2003] = AT220, ST220   Avensis [1997-2003] = AT220, ZZT220</p> <p>Grommet Steering Rack [LH, RH]</p>	<p><b>AT38-AZT250B</b> <b>45516-05030</b></p> <p>ARP Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Avensis [2003-2008] = AZT250, CDT250</p> <p>Grommet Steering Rack Bush [Big]</p>
<p><b>AT38-ACM201S</b> <b>44200-4414S</b></p> <p>TN-2014-May-05 Perfect Product, Tenacity Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Picnic / Avensis Verso [2001-2005] = ACM20   Ipsum [2001-2007] = ACM21</p> <p>Grommet Steering Rack Bush [Small]</p>	<p><b>AT38-ACM201B</b> <b>44200-4414B</b></p> <p>TN-2014-May-05 Perfect Product, Tenacity Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Picnic / Avensis Verso [2001-2005] = ACM20   Ipsum [2001-2007] = ACM21</p> <p>Grommet Steering Rack Bush [Big]</p>
<p><b>AT38-ACM200S</b> <b>45516-44041</b></p> <p>RBI-2014-March-12 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Ipsum [2001] = ACM2#</p> <p>Grommet Steering Rack Bush</p>	
<p><b>AT38-SXM15LR</b> <b>45517-20130</b></p> <p>RBI-2013-December-16 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Carina/Corona/Caldina [1992-2001] = ST195, ST198, ST215, CT195, CT198, CT199, CT215, CT216   Ipsum/N</p> <p>Grommet Steering Rack [LH, RH]</p>	<p><b>AT38-ACM10LR</b> <b>45517-44010</b></p> <p>RBI-2013-November-14 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Ipsum / Gaia / Picnic [1996-2003] = ACM10, CXM10, SXM10</p> <p>Grommet Steering Rack [LH, RH]</p>
<p><b>AT38-ANM10B01</b> <b>45516-44050</b></p> <p>Perfect Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Isis [2004-2009] = ANM10, ZGM10, ZGM11, ZNM10   Wish [2009] = ZGE2#</p> <p>Grommet Steering Rack Bush</p>	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT38-24L</b> <b>45517-12020</b>  Corolla = KE70  Grommet Steering Rack		<b>AT38-24R</b> <b>45516-12020</b>  Corolla = KE70  Grommet Steering Rack [RH]	
<b>AT38-25L</b> <b>45517-12120</b>  Corolla = AE80, EE90  Grommet Steering Rack [LH]		<b>AT38-25R</b> <b>45516-20010</b>  Corolla = AE80, EE90  Grommet Steering Rack [RH]	
<b>AT38-29L</b> <b>45517-12111</b>  Corolla = AE101, AE111  Grommet Steering Rack [LH]		<b>AT38-29R</b> <b>45516-12060</b>  Corolla = AE101, AE111  Grommet Steering Rack [RH]	
<b>AT38-Z121B</b> <b>45516-02090</b>  Corolla / Altis [2001-2007] = ZZE12#  Grommet Steering Rack Bush [Big]		<b>AT38-Z121S</b> <b>45516-02100</b>  Corolla / Altis [2001-2007] = ZZE12#  Grommet Steering Rack Bush [Small]	
<b>AT38-Z122B</b> <b>40120-12610</b>  Corolla / Altis [2001-2007] = NZE124  Grommet Steering Rack Bush [Big]		<b>AT38-Z121Q</b> <b>45516-12080</b>  Corolla / Runx / Alex / Spacio / Fielder / Matrix / Will VS [2000-2008] = ZZE12#, ZZE130, CE120, NZ  Grommet Steering Rack Bush [Square]	









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT38-RV1R00</b> <b>45516-42010</b></p> <p>Toyota Rav4 [1994-2000] = SXA11</p> <p>Grommet Steering Rack Bush [RH]</p> <p>ASH-2012-December-25 Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT38-RV1LR</b> <b>45517-42010</b></p> <p>Toyota Rav4 [1994-2000] = SXA1#</p> <p>Grommet Steering Rack [LH, RH]</p> <p>ASH-2012-December-25 Ashimori Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 
<p><b>AT38-ACA20L1</b> <b>45516-42020</b></p> <p>Toyota Rav4 [2000-2005] = ACA2#</p> <p>Grommet Steering Rack Bush [Long]</p> <p>RBI-2014-February-04 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 	<p><b>AT38-ACA20LR</b> <b>45517-42020</b></p> <p>Toyota Rav4 [2000-2003] = ACA2#, CLA2#, ZCA2#   Corona / Carina / Caldina [1992-1998] = AT19#, AT191</p> <p>Grommet Steering Rack [LH, RH]</p> <p>RBI-2013-December-16 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

	<p><b>AT38-GX71R</b>  <b>45516-22010</b></p> <p>Cressida / Cressida Wagon [1984-1992] = GX71, GX81, MX7#, MX8#, LX7#, LX80, RX60, RX7#, RX80, YX7#  </p> <p>Grommet Steering Rack [RH]</p> <p>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p><b>AT38-GX72R</b>  <b>45516-22011</b></p> <p>Cressida / Cressida Wagon [1984-1992] = GX71, GX81, MX7#, MX8#, LX7#, LX80, RX60, RX7#, RX80, YX7#  </p> <p>Grommet Steering Rack [RH]</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT38-GX901B</b>  <b>44250-22320</b></p> <p>Chaser / Cresta / Mark II [1992-1996] = GX90</p> <p>Grommet Steering Rack Bush [Big]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>AT38-GX901L</b>  <b>45517-22080</b></p> <p>Mark II / Chaser / Cresta / BLIT [1992-2004] = GX93, GX105, GX115, JZX115   Altezza / Altezza Gita [</p> <p>Grommet Steering Rack [LH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT38-GX901R</b>  <b>45516-22050</b></p> <p>Mark II / Chaser / Cresta / BLIT [1992-2004] = GX93, GX105, GX115, JZX115   Altezza / Altezza Gita [</p> <p>Grommet Steering Rack [RH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT38-GX100B</b>  <b>45516-30020</b></p> <p>Mark II / Chaser / Cresta [1996-2001] = GX100   Crown [1995-2001] = JZS155 [4WD]   Crown / Crown Maj</p> <p>Grommet Steering Rack Bush [Big]</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>AT38-GXS10L</b>  <b>45517-22031</b></p> <p>Crown Comfort [1995-2001] = GXS10, LXS11, LXS12, SXS11, YXS1#   Mark 2 &amp; Chaser &amp; Cresta [1990-1996]</p> <p>Grommet Steering Rack [LH]</p> <p>ASH-2012-December-25 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT38-GXS10R</b>  <b>45516-43010</b></p> <p>Crown Comfort [1995-2000] = GXS10, LXS11, SXS11, YXS1#</p> <p>Grommet Steering Rack [RH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p><b>AT38-GXS11R</b>  <b>45516-43030</b></p> <p>Crown Comfort [2000-2003] = LXS12, GXS10, GXS1#, SXS11, SXS13, YXS1#, GBS12</p> <p>Grommet Steering Rack [RH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT38-C02L</b> <b>45517-786RB</b></p>  <p>Camry [1991-2001] = SXV1#, SXV20</p> <p>Grommet Steering Rack [LH]</p>	<p><b>AT38-C02R</b> <b>45516-06080</b></p>  <p>Camry [1991-2001] = SXV1#, SXV20</p> <p>Grommet Steering Rack Bush [RH]</p>
<p><b>AT38-C05B01</b> <b>44200-33490</b></p>  <p>Camry [2001-2006] = ACV3#, MCV3#   Camry [2006] = ACV40, GSV40   Lexus ES300 [2001-2006] = MCV30   R</p> <p>Grommet Steering Rack Bush</p>	<p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PFT-2014-March-25 Perfect Product, Tenacity Product shabbirh@eim.ae 26.40 www.rbi.ae 34.00 www.alafuae.com</p>
<p><b>AT38-OPA1B</b> <b>40120-32290</b></p>  <p>Toyota OPA [2000-2005] = ACT1#, ZCT10</p> <p>Grommet Steering Rack Bush [Big]</p>	<p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT38-ACR30R</b> <b>45516-28050</b></p>  <p>Previa / Tarago [2000-2003] = ACR30, CLR30   Estima [1991-2003] = ACR30, ACR40, MCR30, MCR40</p> <p>Grommet Steering Rack Bush [Small]</p>	<p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT38-S01ML</b> <b>45517-0A010</b>  Soluna [1996-2003] = AL50  Grommet Steering Rack [LH, M/T]	<b>AT38-S01MR</b> <b>45516-0A010</b>  Soluna [1996-2003] = AL50  Grommet Steering Rack [RH, M/T]
<b>AT38-S01PL</b> <b>45517-10070</b>  Soluna [1996-2003] = AL50 Power  Grommet Steering Rack [LH]	<b>AT38-S01PR</b> <b>45516-16060</b>  Soluna [1996-2003] = AL50 Power  Grommet Steering Rack [RH]
<b>AT38-NC42L</b> <b>45517-0D040</b>  Vios / Soluna Vios [2002] = NCP4#  Grommet Steering Rack [LH]	
<b>AT38-NC10B</b> <b>40120-52080</b>  Yaris, Echo, Echo Verso [1999-2005] = NCP1#, NCP2#, NLP10, NLP2#, SCP10   Vitz [1999-2005] = NCP1#,  Grommet Steering Rack Bush [Big]	
<b>AT38-NC42B2</b> <b>45516-0D040</b>  Vios / Soluna Vios [2002-2006] = NCP4# Grommet Steering Rack Bush [RH]	











# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT38-UCF20L</b>  <b>45517-50020</b></p> <p> <b>PERFECT</b> <small>Perfect Product</small>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Lexus LS400 [1994-2000] = UCF20</p> <p>Grommet Steering Rack [LH]</p>	<p><b>AT38-UCF20R</b>  <b>45516-50020</b></p> <p> <b>PERFECT</b> <small>Perfect Product</small>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Lexus LS400 [1994-2000] = UCF20</p> <p>Grommet Steering Rack [RH]</p>
<p><b>AT38-JZS160E01</b>  <b>45517-30050</b></p> <p> <b>PERFECT</b> <small>PFT-2014-August-31 Perfect Product</small>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Aristo [1997-2004] = JZS160, JZS161    Toyota Lexus GS300, GS400, GS430 [1997-2005] = JZS160  </p> <p>Grommet Steering Rack</p>	<p><b>AT38-JZS160E02</b>  <b>45516-30050</b></p> <p> <b>PERFECT</b> <small>PFT-2014-November-15 Perfect Product</small>  <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Toyota Aristo [1997-2004] = JZS160, JZS161    Toyota Lexus GS300, GS400, GS430 [1997-2005] = JZS160  </p> <p>Grommet Steering Rack</p>















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT38-65L</b> <b>45517-26030</b>  Hiace = LH112 Grommet Steering Rack [LH]	RBI-OLD RBI Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT38-65LP</b> <b>45517-26020</b>  Hiace = LH112 [Power] Grommet Steering Rack [LH]	RBI-OLD RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AT38-65R</b> <b>45516-26010</b>  Hiace = LH112 [Power] Grommet Steering Rack [RH, M/T]	RBI-OLD RBI Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT38-KD20L</b> <b>45517-26060</b>  Hiace / Regiusace [2005-2010] = KDH20# Grommet Steering Rack Bush [LH]	RBI-2010-February-18 RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>		
<b>AT38-KCH10B</b> <b>44203-26180</b> Granvia / Grand Hiace [1995-2002] = KCH10, VCH10, KCH16, VCH16 Grommet Steering Rack Bush [Big]	ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a>		
<b>AT38-KR52</b> <b>44200-28380</b>  Liteace / Townace / Noah [1999-2004] = KR52 Grommet Steering Rack Bush [Big]	TN-2012-August-06 Tenacity Product, Ashimori Product <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a>  <a href="http://www.alafuae.com">www.alafuae.com</a>		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT38-ZJ95L</b> <b>45517-35010</b>  Toyota Land Cruiser Prado [1996-2001] = KZJ9#, LJ9#, RZJ9#, VZJ9#  RBI-2005-October-26 RBI Product, HFC Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack [LH]	<b>AT38-ZJ95B</b> <b>45522-35040</b>  Toyota Land Cruiser Prado [1996-2001] = KZJ9#, LJ9#, RZJ9#, VZJ9#  RBI-2007-December-20 RBI Product, HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush [Big]
<b>AT38-ZJ95S</b> <b>45516-35040</b>  Toyota Land Cruiser Prado [1996-2001] = KZJ9#, LJ9#, RZJ9#, VZJ9#  RBI-2008-April-02 RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush [Small]	<b>AT38-ZJ95S2</b> <b>45522-35020</b>  Toyota Land Cruiser Prado [1996-2001] = KZJ9#, LJ9#, RZJ9#, VZJ9#  Perfect Product, Ashimori Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush [Small]
<b>AT38-KZN2151B</b> <b>44200-3506B</b>  4Runner / Hilux Surf [2002-2005] = KZN215   Hilux / Surf / 4Runner [2002-2009] = RZN210   Toyota Lan  PFT-2014-August-31 Perfect Product, Tenacity Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush [Big]	<b>AT38-KZN2151S</b> <b>44200-3506S</b>  4Runner / Hilux Surf [2002-2005] = KZN215   Hilux / Surf / 4Runner [2002-2009] = RZN210   Toyota Lan  PFT-2014-May-25 Perfect Product, Tenacity Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush [Small]
<b>AT38-VG04B</b> <b>45522-0K040</b>  Hilux Vigo [2004]  ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush [Big]	<b>AT38-VG04S</b> <b>45522-0K100</b>  Hilux Vigo [2004]  ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush [Small]
<b>AT38-UCK60ZZ</b> <b>44250-0C120</b>  Toyota Sequoia [2007] = UCK6#, USK6#, UPK6#  Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Grommet Steering Rack Bush	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT38-HDJ101B</b> <b>45522-60010</b></p> <p>Toyota Land Cruiser 100 / Lexus LX470 [1998-2007] = UZJ100, FZJ100, HDJ100</p> <p>Grommet Steering Rack Bush [Big]</p> <p>PFT-2013-April-30 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT38-HDJ101LR</b> <b>45517-60010</b></p> <p>Toyota Land Cruiser 100 / Lexus LX470 [1998-2007] = UZJ100, FZJ100, HDJ100   DYNA / TOYOACE [1999-20]</p> <p>Grommet Steering Rack [LH, RH]</p> <p>PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT38-UZ20S01B</b> <b>45516-6017B</b></p> <p>Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200   Toyota Lexus LX570 [2007] = URJ201</p> <p>Grommet Steering Rack</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>AT38-UZ20S01M</b> <b>45516-6017M</b></p> <p>Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200   Toyota Lexus LX570 [2007] = URJ201</p> <p>Grommet Steering Rack</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>AT38-UZ20S01S</b> <b>45516-6017S</b></p> <p>Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200   Toyota Lexus LX570 [2007] = URJ201</p> <p>Grommet Steering Rack</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>AT38-UZ20S01Z</b> <b>45516-60170-SET</b></p> <p>Toyota Land Cruiser 200 [2007] = UZJ200, VDJ200   Toyota Lexus LX570 [2007] = URJ201</p> <p>Grommet Steering Rack Bush</p> <p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	



## TOYOTA

Revision : 2014-November-01

<b>AT26-RV1E2</b> <b>52380-42050</b>  Toyota Rav4 [1994-2000] = SXA1# Rear Differential Bushing [RE]	PFT-2013-October-10 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT26-RV1EZ</b> <b>52380-42082</b>  Toyota Rav4 [1994-2000] = SXA1# Rear Differential Mounting [RE]	TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT26-RV1E</b> <b>52380-42082</b>  Toyota Rav4 [1994-2000] = SXA1# Rear Differential Bushing [RE]	PFT-2013-October-10 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT26-RV1E2Z</b> <b>52380-42050</b>  Toyota Rav4 [1994-2000] = SXA1# Rear Differential Mounting [RE]	PFT-2013-October-10 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT26-RV1F</b> <b>52380-42071</b>  Toyota Rav4 [1994-2000] = SXA1# Rear Differential Bushing [FR]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT26-RV1FZ</b> <b>52380-42010</b>  Toyota Rav4 [1994-2000] = SXA1# Rear Differential Mounting [FR]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT26-31EZ</b> <b>52291-12010</b>  AE104, AE114, AE115 Rear Differential Mounting [RE] [4WD]	TN-2011-July-23 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	<b>AT26-ST205EZ</b> <b>52291-20010</b>  Celica [1989-1999] = ST165, ST185, ST205   Corona & Carina [1988-1992] = AT175   Camry Vista [1987-1 Rear Differential Mounting [RE] [4WD]	TN-2011-July-23 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		<b>AT26-ST215EZ</b> <b>41651-32030</b>  Corona & Carina & Caldina [1992-2002] = CT195, CT215, ST195, ST215   Camry Vista [1990-1998] = CV43, Rear Differential Mounting [RE] [4WD]	Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
<b>AT41-ST195001</b> <b>41651-32010</b>  Caldina [1992-1997] = ST195.. [4WD]   Camry, Vista [1990-1994] = SV35.. [4WD]   Camry, Vista [1994-1 Rear Differential Bushing [RE]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
<b>AT41-Z154B2</b> <b>41651-42130</b>  Auris [2006] = NZE154, ZRE154.. [4WD]   Blade [2006] = AZE154.. [4WD]   Corolla Rumion [2007] = ZRE1 Rear Differential Bushing [RE]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT26-RCH2F</b> <b>41851-26030</b></p> <p>PFT-2012-June-26 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Hiace [2004-2006] = RCH1#, RCH2#, KLH1#, KLH2#</p> <p>Rear Differential Bushing (FR)</p>	
<p><b>AT26-RCH1F</b> <b>41651-26070</b></p> <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Hiace [2004-2006] = RCH1#, RCH2#, KLH1#, KLH2#</p> <p>Rear Differential Bushing (FR)</p>	
<p><b>AT41-RCH1B3</b> <b>41651-26040</b></p> <p>ASH-2013-July-10 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Granvia / Grand Hiace [1995-2002] = KCH10, VCH10, KCH16, VCH16   Granvia / Grand Hiace [1999-2005] =</p> <p>Rear Differential Bushing</p>	<p><b>AT41-SR40B1</b> <b>41651-28050</b></p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Granvia / Grand / Hiace / Regius / Touring [1995-2006] = KCH10, VCH10, KCH16, VCH16, KLH12, LXH12, R</p> <p>Rear Differential Bushing</p>
<p><b>AT41-RCH1B4</b> <b>41653-26010</b></p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Hiace Van, Comuter [1989-2006] = LH1##, RZH10#, RZH11#, RZH125, RZH135, RZH15#   Hiace, Hiace S.B.V</p> <p>Front Differential Mounting</p>	<p><b>AT41-RZH1E01</b> <b>52380-26051</b></p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Hiace Van, Comuter [1989-2006] = LH1##, RZH10#, RZH11#, RZH125, RZH135, RZH15#   Hiace, Regiusace [1</p> <p>Rear Differential Bushing (RE)</p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT41-GX90B1</b> <b>41651-22030</b>  Chaser / Cresta / Mark II [1988-1993] = GX81, JZX81, MX83 Rear Differential Bushing	<b>AT41-GX90B4</b> <b>41654-22010</b>  Mark II / Chaser / Cresta / BLIT / Verossa [1992-2004] = GX90, GX100, GX110, GX115, JZX110   Altezza Rear Differential Bushing
<b>AT41-GX90B2</b> <b>41651-30060</b>  Chaser / Cresta / Mark II [1996-2001] = GX90, GX100, JZX100, JZX101, LX100, SX100 Rear Differential Bushing	<b>AT41-GX90B3</b> <b>41651-30070</b>  Chaser / Cresta / Mark II [1996-2001] = GX90, GX100, JZX100, JZX101, LX100, SX100 Rear Differential Bushing
<b>AT41-GX90B5</b> <b>52273-22050</b>  Mark II / Chaser / Cresta [1996-2001] = GX100   Mark II / Chaser / Cresta [1992-1996] = GX90   Mark Rear Differential Rubber	
<b>AT41-ACU25B1</b> <b>52380-48010</b>  Harrier / Lexus RX300 / RX330 / RX350 [1997-2006] = ACU15, ACU35, SXU15, MCU15, MCU35, GSU35   Highl Rear Differential Bushing [RE]	<b>AT41-ACU25B2</b> <b>41651-48030</b>  Harrier / Lexus RX300 / RX330 / RX350 [1997-2006] = ACU15, ACU35, SXU15, MCU15, MCU35, GSU35   Highl Rear Differential Bushing
<b>AT41-ACU25B3</b> <b>41651-48020</b>  Harrier / Lexus RX300 / RX330 / RX350 [1997-2007] = ACU15, ACU35, SXU15, MCU15, MCU35, GSU35   Highl Rear Differential Bushing	<b>AT41-SXM15F</b> <b>52380-28030</b>  Estima T, L [1999-2006] = ACR40, MCR40   Gaia / Ipsum [1998-2004] = ACM15, SXM15   Ipsum [2001-2009] Rear Differential Bushing [FR] [4WD]
<b>AT41-UZ10B1</b> <b>41651-60030</b>  Toyota Land Cruiser 100 [1998-2007] = HDJ101, UZJ100   Lexus LX470 [1998-2007] = UZJ100 Rear Differential Bushing [RE]	<b>AT41-Z154B1</b> <b>41651-42120</b>  Auris [2006] = NZE154, ZRE154 [4WD]   Blade [2006] = AZE154 [4WD]   Corolla Rumion [2007] = ZRE154 Rear Differential Bushing
<b>AT41-J200E01</b> <b>51205-B4010</b>  Rush [2006] = J210E.. [4WD]   Daihatsu Terios [2006] = J200, J211 Rear Differential Bushing [RE]	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p>AT41-UCF20E1 41651-50100</p> <p> <b>PERFECT</b> RUBBER PARTS</p> <p>Lexus LS400, Celsior [1994-2000] = UCF20</p> <p>Rear Differential Bushing [RE]</p>	<p>Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> 








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT90-4301</b> <b>17881-31020</b>  <b>Hilux [1978-1984] = RN30, RN40</b>  <b>Air Hose Pipe</b>	<small>ARD-2014-January-01 ARD Product</small> <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	
	<small>ARD-2014-January-01 ARD Product</small> <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT90-4401</b> <b>17881-54200</b>  <b>Hilux [1983-1995] = LN5#, LN6#</b>  <b>Air Hose Pipe</b>
<b>AT90-4402</b> <b>17881-54410</b>  <b>Hilux [1995-1998] = LN5#, LN67   Hilux / 4Runner [4WD] [1988-2001] = LN10#, 111, 13#   Hilux 2WD [19</b>  <b>Air Hose Pipe</b>	<small>ARD-2014-January-01 Ashimori Product</small> <a href="mailto:shabbirh@eim.ae">shabbirh@eim.ae</a>  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AT90-4403</b> <b>17881-73030</b>  <b>Hilux [1983-1998] = YN5#, YH6#   Hilux / 4Runner [4WD] [1988-1997] = YN106, YN135   Hilux 2WD [1988-</b>  <b>Air Hose Pipe</b>
<b>AT90-4404</b> <b>17881-54190</b>  <b>Hilux [1983-1995] = LN56</b>  <b>Air Hose Pipe</b>	<small>Ashimori Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a>	













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT90-4701</b> <b>17881-54820</b>  Hilux [1997-2005] = LN141, LN145, LN146, LN150, LN155, LN166, LN171, LN191  Air Hose Pipe	<p>ARD-2013-August-01 ARD Product, Ashimori Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<b>AT90-4702</b> <b>17881-54640</b>  Hilux [1997-2006] = LN14#, LN15#, LN16#, LN17#, LN192  Air Hose Pipe	<p>Ashimori Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>
<b>AT90-VG001</b> <b>17882-30050</b>  Hilux [2002-2004] = KDN151, KDN166  Air Hose Pipe	<p>ARP Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<b>AT90-VG002</b> <b>17882-30040</b>  Hilux [2001-2005] = KDN145, KDN150, KDN155, KDN165, KDN190  Air Hose Pipe	<p>Ashimori Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>
<b>AT90-VG003</b> <b>17881-54740</b>  Hilux [2000-2005] = LN147, LN152, LN157, LN167, LN172, LN192  Air Hose Pipe	<p>Ashimori Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<b>AT90-VG004</b> <b>17881-0L010</b>  Hilux [2000-2004] = LN145, LN150, LN155  Air Hose Pipe	<p>Ashimori Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>
<b>AT90-VG005</b> <b>17881-0L030</b>  Fortuner [2005-2007] = KUN51, KUN61   Hilux [2004-2007] = KUN16, KUN26, KUN36   Hilux [2004] = KUN15  Air Hose Pipe	<p>ARD-2014-January-01 ARP Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<b>AT90-VG006</b> <b>17881-0L050</b>  Fortuner [2005-2005] = KUN50, KUN60   Hilux [2004-2005] = KUN10, KUN15, KUN25, KUN35   Innova / Kija  Air Hose Pipe	<p>ARD-2014-January-01 ARP Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>
		<b>AT90-VG008</b> <b>17881-0L080</b>  Hilux [2005-2006] = KUN15, KUN25  Air Hose Pipe	<p>ARP Product</p> <p>shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>















# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<p><b>AT90-64001</b> <b>17881-72010</b></p> <p>Hiace Van, Comuter [1982-1993] = YH5#, YH6#, YH7#   Hiace Van, Wagon [1987-1989] = YH5#, YH6#, YH71</p> <p>Air Hose Pipe</p> <p>ARD-2014-January-01 ARD Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	<p><b>AT90-64002</b> <b>17882-54120</b></p> <p>Hiace Van Comuter / Wagon [1982-1989] = LH5#, LH6#, LH7#</p> <p>Air Hose Pipe</p> <p>ARP Product www.rbi.ae</p>
<p><b>AT90-65001</b> <b>17881-54420</b></p> <p>Hiace / Regiusace [1989-1993] = LH100, LH102, LH110, LH140   Hiace Van, Comuter [1989-2000] = LH10#,</p> <p>Air Hose Pipe</p> <p>ARD-2014-January-01 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	<p><b>AT90-65002</b> <b>17882-54400</b></p> <p>Hiace Van Comuter [1989-1998] = LH103, LH113, LH115, LH123, LH125</p> <p>Air Hose Pipe</p> <p>ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>
<p><b>AT90-65003</b> <b>17881-75010</b></p> <p>Hiace / Regiusace [1989-1994] = RZH10#, RZH11#, RZH12#   Hiace Van, Comuter [1989-1994] = RZH10#, RZ</p> <p>Air Hose Pipe</p> <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	<p><b>AT90-65004</b> <b>17881-75020</b></p> <p>Hiace / Regiusace [1989-2005] = RZH10#, RZH11, RZH112, RZH124, RZH125, RZH133, RZH183, TRH102, TRH1</p> <p>Air Hose Pipe</p> <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>
<p><b>AT90-FJ620</b> <b>17881-61061</b></p> <p>Toyota Land Cruiser [1984-1992] = FJ62, FJ7#</p> <p>Air Hose Pipe</p> <p>ARD-2014-January-01 ARD Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	<p><b>AT90-FZJ70</b> <b>17881-66020</b></p> <p>Toyota Land Cruiser [1992-1999] = FZJ7#</p> <p>Air Hose Pipe</p> <p>ARD-2013-August-01 ARD Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>
<p><b>AT90-HZJ80</b> <b>17881-17020</b></p> <p>Toyota Land Cruiser [1990-1998] = HZJ80, HZJ81   Toyota Land Cruiser Van [1990-1998] = HZJ80, HZJ81</p> <p>Air Hose Pipe</p> <p>ARD-2014-January-01 ARD Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT90-24001</b> <b>17881-12030</b>  Corolla [1981-1987] = KE70E, KE70  Air Hose Pipe	<div>ARP Product</div> <div>shabbirh@eim.ae</div>  <div>www.rbi.ae</div> <div>www.alafuae.com</div>	
<b>AT90-31001</b> <b>17881-15180</b>  Corolla [1991-1999] = AE10#, AE11#   Levin / CRE / Trueno / MRN [1991-1995] = AE10#   Sprinter [1991]  Air Hose Pipe	<div>ARP Product</div> <div>shabbirh@eim.ae</div>  <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<b>AT90-31002</b> <b>17881-15190</b>  Corolla [1995-1997] = AE10#, AE11#   Levin / CRE / Trueno / MRN [1995-1997] = AE10#   Sprinter [1995]  Air Hose Pipe
<b>AT90-Z12000</b> <b>17881-0D040</b>  Corolla / Altis [2001-2007] = ZZE12#  Air Hose Pipe	<div>ARD-2014-January-01</div> <div>ARP Product</div> <div>shabbirh@eim.ae</div>  <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<b>AT90-Z12100</b> <b>17881-0D050</b>  Corolla / Altis [2001-2007] = ZZE12#   Avensis [2003-2004] = ZZT251   Caldina [2002] = ZZT241   ISIS  Air Hose Pipe
<b>AT90-ST16201</b> <b>17881-74190</b>  Carina ED / Celica / Corona FF COUPE [1987-1989] = ST162   Corona & Carina 2 [1987-1992] = ST17#  Air Hose Pipe	<div>Ashimori Product</div> <div>shabbirh@eim.ae</div>  <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<b>AT90-10001</b> <b>17881-74450</b>  Caldina [1992-1996] = ST19#   Carina E [1992-1996] = ST191   Corona [1992-1998] = ST191  Air Hose Pipe
<b>AT90-12001</b> <b>17881-74710</b>  Corona [1996-1997] = ST210  Air Hose Pipe	<div>ARD-2014-January-01</div> <div>ARP Product</div> <div>shabbirh@eim.ae</div>  <div>www.rbi.ae</div> <div>www.alafuae.com</div>	
<b>AT90-S01001</b> <b>17881-02080</b>  Soluna [1996-2003] = AL50  Air Hose Pipe	<div>ARP Product</div> <div>shabbirh@eim.ae</div>  <div>www.rbi.ae</div> <div>www.alafuae.com</div>	<b>AT90-NCP401</b> <b>17880-0M040</b>  Vios / Soluna Vios [2002] = NCP4#  Air Hose Pipe









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## TOYOTA

Revision : 2014-November-01

<b>AT90-C02001</b> <b>17881-74390</b>  Camry [1991-1997] = SXV1#  Air Hose Pipe	 <small>Ashimori Product</small> <small>shabbirh@eim.ae</small> <small>www.alafuae.com</small>	<b>AT90-C02002</b> <b>17881-74840</b>  Camry [1997-2001] = SXV1#  Air Hose Pipe	 <small>ARD-2014-January-01</small> <small>ARP Product</small> <small>shabbirh@eim.ae</small> <small>www.alafuae.com</small>
		<b>AT90-C04002</b> <b>17881-28140</b>  Camry [2002-2006] = ACV3#   SOLARA [2003-2005] = ACV30  Air Hose Pipe	 <small>ARP Product</small> <small>shabbirh@eim.ae</small> <small>www.alafuae.com</small>
<b>AT90-TCR1000</b> <b>17881-76050</b>  Estima Previa [1990-1999] = TCR10 TCR20  Air Hose Pipe	 <small>Ashimori Product</small> <small>www.rbi.ae</small>		






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

**TOYOTA**

Revision : 2014-November-01

<p><b>AT90-BU6003</b> <b>17881-56110</b></p> <p>Dyna 200 [1988-1995] = BU61, BU66, BU84, BU87, BU101, BU102, BU141</p> <p>Air Hose Pipe</p> <p>Ashimori Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	

