

HYUNDAI

Revision : 2014-November-01

AHU09-X92FA 21840-24710  Excel [1990-1995] [1.5] Engine Bushing [FR, A/T]	RBI-2006-November-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU09-X92FAZ 21840-24710  Excel [1990-1995] [1.5] Insulator Engine [FR, A/T]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU09-X92FM 21846-24000  Excel [1990-1995] [1.5] Engine Bushing [FR, M/T]	RBI-2006-December-18 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU09-X92FMZ 21840-24010  Excel [1990-1995] [1.5] Insulator Engine [FR, M/T]	TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AHU09-X92EZ 21850-24710  Excel [1990-1995] [1.5] Insulator Engine [RE, A/T]	TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU09-X92E0 21851-24000  Excel [1990-1995] [1.5] Scoupe Engine Bushing [RE, M/T]	RBI-2009-December-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU09-X92EMZ 21850-24010  Excel [1990-1995] [1.5] Insulator Engine [RE, M/T]	TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU11-X92EA 21834-24800  Excel [1990-1995] [1.5] Scoupe Engine Bushing [RH, A/T]	RBI-2006-November-28 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU09-X92RAZ 21830-24810  Excel [1990-1995] [1.5] Insulator Engine [RH, A/T]	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU11-X92EM 21834-24000  Excel [1990-1995] [1.5] Scoupe Engine Bushing [RH, M/T]	RBI-2007-February-26 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU09-X92RMZ 21830-24010  Excel [1990-1995] [1.5] Insulator Engine [RH, M/T]	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AHU09-X92LZ 21810-24010  Excel [1990-1995] [1.5] Insulator Engine [LH, A/T, M/T]	TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-X92E0Z 21930-34200</p> <p>Excel</p> <p>Insulator Engine [RE, M/T]</p>   <p>Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-X00L0 21818-24000</p> <p>Excel Scoupe</p> <p>Engine Bushing [LH]</p>  <p>RBI-2007-January-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU09-X00L0Z 21810-24110</p> <p>Excel</p> <p>Insulator Engine [LH]</p>   <p>Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU09-E92FA 21910-28500</p>  <p>Elantra [1990-1995] [1.5, 1.6, 1.8] Scoupe</p> <p>Engine Bushing [FR, A/T]</p> <p><small>RBI-2006-December-01 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AHU09-E92FAZ 21910-28500</p>  <p>Elantra [1990-1995] [1.5, 1.6, 1.8] Scoupe</p> <p>Insulator Engine [FR, A/T]</p> <p><small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-E92FMZ 21910-28000</p>  <p>Elantra [1990-1995] [1.5, 1.6, 1.8] Scoupe</p> <p>Insulator Engine [FR, M/T]</p> <p><small>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-E96FAZ 21910-29051</p>  <p>Elantra [1996-1998] [1.6, 1.8] Scoupe</p> <p>Insulator Engine [FR, A/T]</p> <p><small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-E98FAZ 21910-29500</p>  <p>Elantra [1998-2000] [1.6, 1.8, 2.0] Scoupe</p> <p>Insulator Engine [FR, A/T]</p> <p><small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-E96FMZ 21910-29001</p>  <p>Elantra [1998-2000] [1.6, 1.8, 2.0] Scoupe Tiburon</p> <p>Insulator Engine [FR, M/T]</p> <p><small>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-E94EZ 21930-28500</p> <p>Elantra [1990-1995] [1.5, 1.6]</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU09-E92EA 21931-28500</p> <p>Elantra [1990-1995] [1.8] Tiburon</p> <p>Engine Bushing [RE, A/T]</p>  <p>RBI-2006-November-28 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AHU09-E92EM 21931-29000</p> <p>Elantra [1990-2000] [1.5, 1.6, 1.8, 2.0] Tiburon Scoupe</p> <p>Engine Bushing [RE, M/T]</p>  <p>RBI-2006-November-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU09-E94EMZ 21930-28001</p> <p>Elantra [1990-1995] [1.5, 1.6, 1.8]</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-E96EZ 21930-29051</p> <p>Elantra [1996-2000] [1.6, 1.8] Scoupe Tiburon</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-E96E2Z 21930-29000</p> <p>Elantra [1996-2000] [1.6, 1.8, 2.0] Scoupe</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-E96EMZ 21930-29001</p> <p>Elantra [1996-2000] [1.6, 1.8, 2.0] Scoupe</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU11-E92E0 21832-28700</p>  <p>Elantra [1990-1995]</p> <p>Engine Bushing [RH, A/T]</p> <p><small>RBI-2006-October-07 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AHU09-E92RAZ 21830-28700</p>  <p>Elantra [1990-1995] [1.6]</p> <p>Insulator Engine [RH, A/T]</p> <p><small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-E94RAZ 21830-28860</p> <p>Elantra [1994] [1.8]</p> <p>Insulator Engine [RH, A/T]</p> <p><small>Ashimori Product www.rbi.ae</small></p>
	<p>AHU09-E96RAZ 21830-29150</p>  <p>Elantra [1996-2000] [1.6, 1.8, 2.0] Scoupe</p> <p>Insulator Engine [RH, A/T]</p> <p><small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p>AHU11-E92EA 21832-28200</p>  <p>Elantra [1990-2000] [1.6, 1.8, 2.0] Scoupe</p> <p>Engine Bushing [RH, A/T, M/T]</p> <p><small>RBI-2007-January-29 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AHU09-E92RMZ 21830-28200</p>  <p>Elantra [1990-1995] [1.6]</p> <p>Insulator Engine [RH, M/T]</p> <p><small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-E92R2Z 21830-29000</p>  <p>Elantra [1990-1995] [1.8]</p> <p>Insulator Engine [RH, M/T]</p> <p><small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-E96RMZ 21830-29100</p>  <p>Elantra [1996-2000] [1.6, 1.8, 2.0] Scoupe</p> <p>Insulator Engine [RH, M/T]</p> <p><small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>



HYUNDAI

Revision : 2014-November-01

	<p>AHU09-E92L1Z 21810-28000 Elantra [1990-1993] [1.5] Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-E9600 21812-29150 Elantra [1990-1996] [1.6] Tiburon Engine Bushing [LH, A/T]</p> <p>RBI-2006-November-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU09-E92LAZ 21810-28200 Elantra [1990-1993] [1.6] Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-E94LAZ 21810-28260 Elantra [1993-1995] [1.6] Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-E92L0 21812-28200 Elantra [1990-1996] [1.6, 1.8] Engine Bushing [LH, A/T]</p> <p>RBI-2006-December-01 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
	<p>AHU09-E92LMZ 21810-28270 Elantra [1990-1995] [1.5, 1.6] Insulator Engine [LH, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-4LM 21812-28250 Elantra [1990-2000] [1.6, 1.8, 2.0] Tiburon Engine Bushing [RE, LH, M/T]</p> <p>RBI-2006-September-04 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
	<p>AHU09-E94LMZ 21810-29000 Elantra [1990-1995] Insulator Engine [LH, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-E96LAZ 21810-29130</p> <p>Elantra [1996-2000] [1.6, 1.8]</p> <p>Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-E96LZ 21810-29150</p> <p>Elantra [1996-2000] [2.0] Tiburon</p> <p>Insulator Engine [LH, A/T]</p> <p>Ashimori Product www.rbi.ae</p>
	<p>AHU09-E96LMZ 21810-29100</p> <p>Elantra [1996-2000] [1.6, 1.8, 2.0] Tiburon</p> <p>Insulator Engine [LH, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-E00FZ 21910-2D050</p> <p>Elantra [2000-2005] [1.6, 1.8, 2.0]</p> <p>Insulator Engine [FR, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-C01FZ 21910-2C050</p> <p>Scoupe [2000]</p> <p>Insulator Engine [FR, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-E00EZ 21930-2D151</p> <p>Elantra [2000-2005] [1.6, 1.8, 2.0]</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-C01EZ 21930-2C051</p> <p>Scoupe [2000]</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-E00LAZ 21830-2D050</p> <p>Elantra [2000-2005] [1.6, 1.8, 2.0]</p> <p>Insulator Engine [LH, A/T]</p> <p>   </p> <p> <small>TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product</small> www.alafuae.com </p>
	<p>AHU09-C01LAZ 21830-2C150</p> <p>Scoupe [2000]</p> <p>Insulator Engine [LH, A/T]</p> <p>   </p> <p> <small>TN-2010-December-01 Tenacity Product</small> www.alafuae.com </p>
	<p>AHU09-E00LMZ 21830-2D000</p> <p>Elantra [2000-2005] [1.6, 1.8, 2.0] Scoupe [2000]</p> <p>Insulator Engine [LH, M/T]</p> <p>   </p> <p> <small>TN-2010-December-01 Tenacity Product, Ashimori Product</small> www.alafuae.com </p>
	<p>AHU09-E00RZ 21810-2D050</p> <p>Elantra [2000-2003] [1.6, 1.8, 2.0] Scoupe [2000]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>   </p> <p> <small>TN-2010-December-26 Tenacity Product, Ashimori Product</small> www.alafuae.com </p>
	<p>AHU09-E03RZ 21810-2D200</p> <p>Elantra [2003-2005] [1.6, 1.8, 2.0]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>   </p> <p> <small>TN-2010-December-01 Tenacity Product</small> www.alafuae.com </p>













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-E08FZ 21910-1M000</p> <p>Elantra [2008]</p> <p>Insulator Engine [FR]</p> <p>TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-E08EDZ 21930-2H100</p> <p>Elantra [2008]</p> <p>Insulator Engine [RE, Diesel]</p> <p>TN-2012-March-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-E08EPZ 21930-1M100</p> <p>Elantra [2008]</p> <p>Insulator Engine [RE, Petrol]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-E08LZ 21830-1M000</p> <p>Elantra [2008]</p> <p>Insulator Engine [LH]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  





AL LAMSA AL FIDDIYA TRADING L.L.C.


ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-C00L0Z 21810-23630</p> <p>Scoupe</p> <p>Insulator Engine [LH]</p> <p> PERFECT RUBBER PARTS</p> <p>Perfect Product www.rbi.ae</p>






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

HYUNDAI

	<p>AHU09-A94FAZ 21840-22700</p> <p>Accent [1994-1995] [1.5]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>  
	<p>AHU09-A96FAZ 21840-22500</p> <p>Accent [1996] [1.5]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>  
<p>AHU09-A97FA 21911-22400</p> <p>Accent [1997-1999] [1.5] Elantra [1996] Tiburon</p> <p>Engine Bushing [FR, A/T]</p>  <p>RBI-2006-November-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AHU09-A97FAZ 21840-22400</p> <p>Accent [1997-1999] [1.5]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>  
<p>AHU09-A97FM 21911-22001</p> <p>Accent [1994-1995] [1.5] Elantra [1992-1994] Tiburon Scoupe</p> <p>Engine Bushing [FR, M/T]</p>  <p>RBI-2006-December-18 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AHU09-A94FMZ 21840-22000</p> <p>Accent [1994-1995] [1.5] Tiburon</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>  
	<p>AHU09-A96FMZ 21840-22600</p> <p>Accent [1996] [1.5] Tiburon</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>  
	<p>AHU09-A97FMZ 21840-22300</p> <p>Accent [1997-1999] [1.5] Tiburon</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p>  










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU09-A00E 21850-22702</p>  <p>Accent [1994-1996] [1.5] SOHC</p> <p>Engine Bushing [RE, A/T, M/T]</p> <p><small>RBI-2008-March-06 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AHU09-A94EZ 21850-22702</p>  <p>Accent [1994-1996] [1.5] SOHC</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p><small>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p>AHU09-A97E 21851-24700</p>  <p>Accent [1996-1999] [1.5] Excel Scoupe</p> <p>Engine Bushing [RE, A/T, M/T]</p> <p><small>RBI-2006-November-28 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AHU09-A96EZ 21850-22300</p>  <p>Accent [1996-1999] [1.5]</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p><small>TN-2010-December-26 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
	<p>AHU09-A94EAZ 21850-22701</p>  <p>Accent [1994-1996] [1.5] DOHC</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p><small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>



Revision : 2014-November-01

HYUNDAI

	<p>AHU09-A94RAZ 21830-22700</p> <p>Accent [1994-1996] [1.5]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-A96RAZ 21830-22400</p> <p>Accent [1996-1999] [1.5] SOHC</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-A96RZ 21830-22501</p> <p>Accent [1996-1999] [1.5] DOHC</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU11-A94R0 21834-22130</p> <p>Accent [1994-1996] [1.5]</p> <p>Engine Bushing [RH, M/T]</p> <p>RBI-2006-December-18 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU09-A94RMZ 21830-22020</p> <p>Accent [1994-1996] [1.5]</p> <p>Insulator Engine [RH, M/T]</p> <p>Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-A96RMZ 21830-22200</p> <p>Accent [1996-1999] [1.5] DOHC</p> <p>Insulator Engine [RH, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-A00R 21834-22030</p> <p>Accent [1994-1995] [1.5]</p> <p>Engine Bushing [RH, A/T, M/T]</p> <p>RBI-2006-December-01 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU09-A94LZ 21810-22040</p> <p>Accent [1994-1995] [1.5]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>Perfect Product, HFC Product www.rbi.ae</p>
	<p>AHU09-A95LZ 21810-22020</p> <p>Accent [1995-1996] [1.5]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-A96LZ 21810-22510</p> <p>Accent [1996-1999-2002] [1.5] DOHC</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-A99FAZ 21910-25110</p> <p>Accent [1999-2002] [1.5]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-A99FMZ 21910-25010</p> <p>Accent [1999-2002] [1.5]</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-A99EZ 21930-25010</p> <p>Accent [1999-2002] [1.5]</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-A99RAZ 21830-25100</p> <p>Accent [1999-2002] [1.5]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-A99RMZ 21830-25010</p> <p>Accent [1999-2002] [1.5]</p> <p>Insulator Engine [RH, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-A99LZ 21810-25010</p> <p>Accent [1999-2002] [1.5] SOHC</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  

















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	AHU09-A02FAZ 21910-25450 Accent [2002] [1.5] Insulator Engine [FR, A/T]	<small>TN-2010-December-01 Tenacity Product, Ashimori Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 
	AHU09-A02FMZ 21910-25400 Accent [2002] [1.5] Insulator Engine [FR, M/T]	<small>TN-2010-December-01 Tenacity Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 
	AHU09-A02EAZ 21930-25450 Accent [2002] [1.5] Insulator Engine [RE, A/T]	<small>TN-2010-December-26 Tenacity Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 
	AHU09-A02EMZ 21930-25400 Accent [2002] [1.5] Insulator Engine [RE, M/T]	<small>TN-2010-December-01 Tenacity Product, Ashimori Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 
	AHU09-A02RAZ 21830-25450 Accent [2002] [1.5] Insulator Engine [RH, A/T]	<small>TN-2010-December-26 Tenacity Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 
	AHU09-A02RMZ 21830-25400 Accent [2002] [1.5] Insulator Engine [RH, M/T]	<small>TN-2010-December-01 Tenacity Product, Ashimori Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 
	AHU09-A02LZ 21810-25020 Accent [2002] [1.5] SOHC Insulator Engine [LH, A/T, M/T]	<small>TN-2010-December-26 Tenacity Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 
	AHU09-A02L2Z 21810-25120 Accent [2002] [1.5] DOHC Insulator Engine [LH, A/T, M/T]	<small>TN-2010-December-26 Tenacity Product</small>  shabbirh@eim.ae www.rbi.ae www.alafuae.com 



HYUNDAI

Revision : 2014-November-01

<p>AHU09-E94FA 21641-33410</p>  <p>Sonata [1989-1994] [2.0] Elantra [1992-1994] [1.8]</p> <p>Engine Bushing [FR, A/T, M/T]</p> <p>RBI-2007-August-15 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU09-S89FAZ 21640-33410</p>  <p>Sonata [1989-1991] [2.0]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-S92FAZ 21640-33470</p>  <p>Sonata [1992-1994] [2.0]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-S89FMZ 21640-33010</p>  <p>Sonata [1989-1991] [2.0]</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-S92FMZ 21640-33170</p>  <p>Sonata [1992-1994] [2.0]</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-26 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-S92EA 21631-33410</p>  <p>Sonata [1989-1994] [2.0]</p> <p>Engine Bushing [RE, A/T]</p> <p>RBI-2006-December-18 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU09-S92EAZ 21630-33410</p>  <p>Sonata [1989-1994] [2.0]</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-S92EM 21631-36000</p>  <p>Sonata [1989-1994] [2.0]</p> <p>Engine Bushing [RE, M/T]</p> <p>RBI-2006-December-01 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI





Revision : 2014-November-01

	<p>AHU09-S89RAZ 21860-33410</p> <p>Sonata [1989-1994] [2.0]</p> <p>Insulator Engine [RH, A/T]</p> <p>TENACITY</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-S89RMZ 21860-33010</p> <p>Sonata [1989-1994] [2.0]</p> <p>Insulator Engine [RH, M/T]</p> <p>TENACITY</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU11-S920A 21872-33070</p> <p>Sonata [1992-1994] [16V]</p> <p>Engine Bushing [RH, A/T]</p> <p>RBI-2007-January-15 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>RBI</p>	
<p>AHU11-S920M 21860-33070</p> <p>Sonata [1992-1994] [16V]</p> <p>Engine Bushing [RH, M/T]</p> <p>RBI-2006-December-18 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>RBI</p>	<p>AHU09-S92RMZ 21860-33070</p> <p>Sonata [1992-1994] [16V]</p> <p>Insulator Engine [RH, M/T]</p> <p>Ashimori Product www.rbi.ae</p>
	<p>AHU09-S89LZ 21830-33010</p> <p>Sonata [1989-1991] [2.0]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TENACITY</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU09-S94L0 21852-33070</p> <p>Sonata [1992-1994] [2.0]</p> <p>Engine Bushing [LH, A/T]</p> <p>RBI-2007-January-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>RBI</p>	<p>AHU09-S92LAZ 21830-33470</p> <p>Sonata [1992-1994] [2.0]</p> <p>Insulator Engine [LH, A/T]</p> <p>PERFECT RUBBER PARTS</p> <p>Perfect Product www.rbi.ae</p>
	<p>AHU09-S92LMZ 21830-33070</p> <p>Sonata [1992-1994] [2.0]</p> <p>Insulator Engine [LH, M/T]</p> <p>TENACITY</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



HYUNDAI

Revision : 2014-November-01

<p>AHU09-S94FA 21911-34500</p>  <p>Sonata [1994-1996] [2.0]</p> <p>Engine Bushing [FR, A/T]</p>	<p>AHU09-S94FAZ 21910-34310</p> <p>Ashimori Product</p> <p>www.rbi.ae</p> <p>Sonata [1994-1996] [2.0]</p> <p>Insulator Engine [FR, A/T]</p>
<p>AHU09-S97FA 21911-34401</p>  <p>Sonata [1996-1998] [2.0]</p> <p>Engine Bushing [FR, A/T]</p>	<p>AHU09-S96FAZ 21910-34410</p> <p>TN-2010-December-26 Tenacity Product</p>  <p>www.rbi.ae</p> <p>Sonata [1996-1998] [2.0]</p> <p>Insulator Engine [FR, A/T]</p>
<p>AHU09-S97FM 21911-35010</p>  <p>Sonata [1994-1996] [2.0]</p> <p>Engine Bushing [FR, M/T]</p>	<p>AHU09-S94FMZ 21910-34020</p> <p>TN-2010-December-26 Tenacity Product</p>  <p>www.rbi.ae</p> <p>Sonata [1994-1996] [2.0]</p> <p>Insulator Engine [FR, M/T]</p>
	<p>AHU09-S96FMZ 21910-34210</p> <p>TN-2010-December-26 Tenacity Product</p>  <p>www.rbi.ae</p> <p>Sonata [1996-1998] [2.0]</p> <p>Insulator Engine [FR, M/T]</p>
<p>AHU09-S94EA 21931-34100</p>  <p>Sonata [1994-1997]</p> <p>Engine Bushing [RE, A/T]</p>	<p>AHU09-S94EAZ 21930-34300</p> <p>Perfect Product, Ashimori Product</p>  <p>www.rbi.ae</p> <p>Sonata [1994-1997]</p> <p>Insulator Engine [RE, A/T]</p>
<p>AHU09-S97EA 21931-35500</p>  <p>Sonata [1997-1998]</p> <p>Engine Bushing [RE, A/T]</p>	
<p>AHU09-S97EM 21931-35000</p>  <p>Sonata [1997-1998]</p> <p>Engine Bushing [RE, M/T]</p>	






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU11-S94E0 21832-34600</p>  <p>Sonata [1994-1997]</p> <p>Engine Bushing [RH, A/T, M/T]</p>	<p>AHU09-S94RZ 21830-34600</p> <p>Ashimori Product</p> <p>www.rbi.ae</p> <p>Sonata [1994-1997]</p> <p>Insulator Engine [RH, A/T, M/T]</p>
	<p>AHU09-S94RMZ 21830-34200</p> <p>Ashimori Product</p> <p>www.rbi.ae</p> <p>Sonata [1994-1997]</p> <p>Insulator Engine [RH, M/T]</p>
<p>AHU09-S94L1 21812-34600</p>  <p>Sonata [1994-1996] [16V]</p> <p>Engine Bushing [LH, A/T, M/T]</p>	<p>AHU09-S94L2Z 21810-34200</p> <p>Tenacity Product</p> <p>www.rbi.ae</p> <p>Sonata [1994-1996]</p> <p>Insulator Engine [LH, A/T, M/T]</p>
<p>AHU09-S97L0 21812-35140</p>  <p>Sonata [1994-1998]</p> <p>Engine Bushing [LH, A/T, M/T]</p>	<p>AHU09-S97LAZ 21810-34221</p> <p>Tenacity Product, Ashimori Product</p> <p>www.rbi.ae</p> <p>Sonata [1997-1998]</p> <p>Insulator Engine [LH, A/T]</p>
	<p>AHU09-S97LMZ 21810-35000</p> <p>Tenacity Product</p> <p>www.rbi.ae</p> <p>Sonata [1997-1998]</p> <p>Insulator Engine [LH, M/T]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-S99FAZ 21910-38600</p> <p>Sonata [1999-2001] [2.0, 2.5]</p> <p>Insulator Engine (FR, A/T)</p> <p>   </p> <p> <small>TN-2010-December-01 Perfect Product, Tenacity Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
	<p>AHU09-XG99FAZ 21910-39601</p> <p>XG [1999-2003] [2.0, 2.5]</p> <p>Insulator Engine (FR, A/T)</p> <p>   </p> <p> <small>TN-2010-December-26 Tenacity Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
	<p>AHU09-S99FMZ 21910-38100</p> <p>Sonata [1999-2001] [2.0, 2.5]</p> <p>Insulator Engine (FR, M/T)</p> <p>   </p> <p> <small>TN-2010-December-01 Tenacity Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
	<p>AHU09-XG99FMZ 21910-39101</p> <p>XG [1999-2003] [2.0, 2.5]</p> <p>Insulator Engine (FR, M/T)</p> <p>   </p> <p> <small>TN-2010-December-26 Tenacity Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
	<p>AHU09-XG99FZ 21910-39801</p> <p>XG [1999-2003] [3.0]</p> <p>Insulator Engine (FR, A/T, M/T)</p> <p>   </p> <p> <small>TN-2010-December-26 Tenacity Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-S99EAZ 21930-38850</p> <p>Sonata [1999-2001] [2.0, 2.5] XG [1999-2003] [2.0, 2.5]</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S99EMZ 21930-38100</p> <p>Sonata [1999-2001] XG [1999-2003] [2.0, 2.5]</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S99EZ 21930-38300</p> <p>Sonata [1999-2001] [2.0, CVT]</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-XG99EZ 21930-39800</p> <p>XG [1999-2003] [3.0]</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-S99R1Z 21830-38500</p> <p>Sonata [1999-2001] [2.0]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S99R2Z 21830-38550</p> <p>Sonata [1999-2001] [2.5]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashmori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S99RMZ 21830-38000</p> <p>Sonata [1999-2001] [2.0, 2.5] XG [1999-2003] [3.0]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashmori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S99R3Z 21830-38300</p> <p>Sonata [1999-2001] [2.0, CVT]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-XG99RAZ 21830-39510</p> <p>XG [1999-2003] [2.5]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-XG99RMZ 21830-39011</p> <p>XG [1999-2003] [2.0, 2.5]</p> <p>Insulator Engine [RH, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-S99L1Z 21810-38010</p> <p>Sonata [1999-2001] [2.0]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S99L2Z 21810-38710</p> <p>Sonata [1999-2001] [2.5, 2.7] XG [1999-2003] [2.0, 2.5]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-XG99L2Z 21810-39800</p> <p>XG [1999-2003] [3.0]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-XG03RAZ 21830-39513</p> <p>XG [2003] [2.0, 2.5]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-XG03RMZ 21830-39700</p> <p>XG [2003] [2.0, 2.5]</p> <p>Insulator Engine [RH, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-XG03RZ 21830-39801</p> <p>XG [2003] [3.0]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-S06FZ 21910-3K050</p> <p>Hyundai Sonata [2005-2010] = NF [2.0 Diesel, 2.4 Petrol]</p> <p>Insulator Engine [FR, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S06EZ 21930-3K800</p> <p>NF-Sonata [2006] [2.0 Diesel, 2.4 Petrol]</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S06E1Z 21930-3K050</p> <p>Hyundai Sonata [2005-2010] = NF</p> <p>Insulator Engine</p> <p>ARP Product www.rbi.ae</p>
	<p>AHU09-S06LDZ 21810-3K000</p> <p>NF-Sonata [2006] [2.0 Diesel]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S06LPZ 21810-3K850</p> <p>NF-Sonata [2006] [2.4 Petrol]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S06RDZ 21830-3K000</p> <p>Hyundai Sonata [2005-2010] = NF [2.0 Diesel]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-S06RPZ 21830-3K800</p> <p>NF-Sonata [2006] [2.4 Petrol]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-AT97FZ 21840-02000</p> <p>Atos [1997-2000]</p> <p>Insulator Engine [FR]</p> <p> PERFECT RUBBER PARTS</p> <p>TN-2010-December-26 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-AT97L1Z 21830-02100</p> <p>Atos [1997-2000]</p> <p>Insulator Engine [LH]</p> <p> TENACITY</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-AT97L2Z 21830-02050</p> <p>Atos [1997-2000]</p> <p>Insulator Engine [LH]</p> <p> TENACITY</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-AT97RZ 21850-02050</p> <p>Atos [1997-2000]</p> <p>Insulator Engine [RH]</p> <p> PERFECT RUBBER PARTS</p> <p>TN-2010-December-26 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-GE02FAZ 21930-1C230</p> <p>Getz [2002]</p> <p>Insulator Engine [FR, A/T]</p> <p> TENACITY</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-GE02FMZ 21930-1C130</p> <p>Getz [2002]</p> <p>Insulator Engine [FR, M/T]</p> <p> TENACITY</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-GE02LZ 21810-1C220</p> <p>Getz [2002]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p> TENACITY</p> <p>TN-2010-December-26 Tenacity Product, HFC Product, Ashmori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AHU09-GE02RZ 21830-1C270</p> <p>Getz [2002]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p> TENACITY</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-MA01FAZ 21910-17050</p> <p>Matrix [2001] [1.6]</p> <p>Insulator Engine [FR, A/T]</p>	<p>TN-2010-December-26 Tenacity Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-MA01FMZ 21910-17000</p> <p>Matrix [2001] [1.6, 1.8]</p> <p>Insulator Engine [FR, M/T]</p>	<p>TN-2010-December-26 Tenacity Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-MA01EAZ 21930-17050</p> <p>Matrix [2001] [1.6, 1.8]</p> <p>Insulator Engine [RE, A/T]</p>	<p>TN-2010-December-26 Tenacity Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-MA01EMZ 21930-17000</p> <p>Matrix [2001] [1.6, 1.8]</p> <p>Insulator Engine [RE, M/T]</p>	<p>TN-2010-December-26 Tenacity Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-MA01RAZ 21830-17150</p> <p>Matrix [2001] [1.6, 1.8]</p> <p>Insulator Engine [RH, A/T]</p>	<p>TN-2010-December-26 Tenacity Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-MA01RMZ 21830-17000</p> <p>Matrix [2001] [1.6, 1.8]</p> <p>Insulator Engine [RH, M/T]</p>	<p>TN-2010-December-26 Tenacity Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-MA01L1Z 21810-17000</p> <p>Matrix [2001] [1.6]</p> <p>Insulator Engine [LH, A/T, M/T]</p>	<p>TN-2010-December-26 Tenacity Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AHU09-MA01L2Z 21810-17200</p> <p>Matrix [2001] [1.8]</p> <p>Insulator Engine [LH, A/T, M/T]</p>	<p>TN-2010-December-26 Tenacity Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

AHU09-TU04EA 21930-2E100  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Engine Bushing [RE, A/T, 2.0]	AHU09-TU04EAZ 21930-2E100  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Insulator Engine [RE, A/T, 2.0]
AHU09-TU04EM 21930-2E300  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Engine Bushing [RE, M/T, 2.0]	AHU09-TU04EMZ 21930-2E300  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Insulator Engine [RE, M/T, 2.0]
AHU09-TU04FA 21910-2E300  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Engine Bushing [FR, A/T, 2.0]	AHU09-TU04FAZ 21910-2E300  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Insulator Engine [FR, A/T, 2.0]
AHU09-TU04FM 21911-2E100  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Engine Bushing [FR, M/T, 2.0]	AHU09-TU04FMZ 21910-2E100  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Insulator Engine [FR, M/T, 2.0]
AHU09-TU04FM2 21911-2E501  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Engine Bushing [FR, M/T, 2.0]	AHU09-TU04F2Z 21910-2E501  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Insulator Engine [FR]
	AHU09-TU04F3Z 21910-2E002  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Insulator Engine [FR, 2.0]
	AHU09-TU04FDZ 21910-2E650  Hyundai Tucson [2004-2010] Insulator Engine [FR, 2.0 Diesel]





AL LAMSA AL FIDDIYA TRADING L.L.C.



ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU09-TU04L0</p>  <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Engine Bushing [LH]</p>	<p>AHU09-TU04LAZ</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product</p> <p>21830-2E100</p> <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Insulator Engine [LH, A/T, 2WD, 2.0]</p>
	<p>AHU09-TU04LZ</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product</p> <p>21830-2E200</p> <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Insulator Engine [LH, A/T, 4WD, 2.0]</p>
	<p>AHU09-TU04LMZ</p> <p>TN-2010-December-26 Tenacity Product, HFC Product</p> <p>21830-2E000</p> <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Insulator Engine [LH, M/T, 2.0]</p>
<p>AHU09-TU04R0</p> <p>21812-2E000</p>  <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Engine Bushing [RH]</p>	<p>AHU09-TU04RZ</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product</p> <p>21810-2E100</p> <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Insulator Engine [RH, A/T, M/T] [2.0]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-TA00FAZ 21910-3A501</p> <p>Trajet [2000-2004] [2.0, 2.7]</p> <p>Insulator Engine [FR, A/T]</p>	<p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-TA00FMZ 21910-3A101</p> <p>Trajet [2000-2004] [2.0, 2.7]</p> <p>Insulator Engine [FR, M/T]</p>	<p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-SA00FAZ 21910-26200</p> <p>Santa-Fe [2000-2004]</p> <p>Insulator Engine [FR, A/T]</p>	<p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-SA00FMZ 21910-26000</p> <p>Santa-Fe [2000-2004]</p> <p>Insulator Engine [FR, M/T]</p>	<p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-TA00E1Z 21930-3A100</p> <p>Trajet [2000-2004] [2.0]</p> <p>Insulator Engine [RE, A/T, M/T]</p>	<p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-TA00E2Z 21930-3A300</p> <p>Trajet [2000-2004] [2.7]</p> <p>Insulator Engine [RE, A/T, M/T]</p>	<p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-SA00EZ 21930-26200</p> <p>Santa-Fe [2000-2004]</p> <p>Insulator Engine [RE, A/T, M/T]</p>	<p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

	<p>AHU09-TA00RZ 21830-3A001</p> <p>Trajat [2000-2004] [2.0, 2.7] Santa-Fe [2000-2004]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-TA00L1Z 21810-3A700</p> <p>Trajat [2000-2004] [2.0]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-TA00L2Z 21810-3A900</p> <p>Trajat [2000-2004] [2.7]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-SA00LZ 21810-26500</p> <p>Santa-Fe [2000-2004]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU09-SA00LDZ 21810-26750</p> <p>Santa-Fe [2000-2004] [Diesel]</p> <p>Insulator Engine [LH, A/T]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU09-H197FRL 21811-4B021</p> <p>H100 [1997]</p> <p>Insulator Engine [FR, LH, RH]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AHU09-H106FRL 21811-4A000</p> <p>H1 [2006]</p> <p>Insulator Engine [FR, LH, RH]</p> <p>PFT-2014-March-25 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU13-X87F 54610-21000 Excel [1987-1989] [1.5] Shock Absorber Mounting [FR, LH, RH]</p>	<p>TN-2011-August-30 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU13-X90F 54610-23000 Excel [1990-1994] [1.5] Shock Absorber Mounting [FR, LH, RH]</p>	<p>AHU13-X92F 54610-24001 Excel Scoupe Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2006-November-28 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU13-A00F 54610-22000 Accent Shock Absorber Mounting [FR, LH, RH]</p>	<p>AHU13-A95F 54610-25000 Accent [1995-2004] Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2007-January-18 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU13-A95E00 55310-22000 Accent [1995-2004] Shock Absorber Mounting [RE, LH, RH] [Lower 2Pcs In Car]</p>	<p>AHU13-A95E01 55311-22000 Accent [1995-2004] Shock Absorber Mounting Rubber [RE, LH, RH] [Upper 2Pcs In Car]</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 



HYUNDAI

Revision : 2014-November-01

<p>AHU13-E92F 54610-28000</p>  <p>Elantra [1992-1996] [1.6, 1.8]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2007-February-08 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU13-E96F0 54610-29000</p>  <p>Elantra [1996-2005] Matrix [2001]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2008-February-02 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU13-E96EL 55310-29000</p>  <p>Elantra [1996-2005] Matrix [2001]</p> <p>Shock Absorber Mounting [RE, LH]</p> <p>RBI-2009-March-24 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU13-E96ER 55320-29000</p>  <p>Elantra [1996-2005] Matrix [2001]</p> <p>Shock Absorber Mounting [RE, RH]</p> <p>RBI-2009-March-07 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU13-E00F00 54610-2D000</p>  <p>Hyundai Elantra, Lantra [2000-2006] = CA KIA Cerato I [2004-2009] KIA Spectra [2004]</p> <p>Shock Absorber Mounting</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AHU13-S89F 54610-36060</p>  <p>Sonata [1989-1994] [2.0]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU13-S92F 54610-36002</p>  <p>Sonata [1992-1994]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2009-December-12 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU13-S94F 54610-34010</p>  <p>Sonata [1994-1997]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2006-October-07 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU13-AT00F 54610-ATOS1</p>  <p>Atos [2000]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU13-TU04F 54610-2E100</p>  <p>Tuscon [2004] [2.0]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU13-SA00F 54610-26000</p>  <p>Santa-FE [2000]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>


















HYUNDAI

Revision : 2014-November-01

<p>AHU14-TU04F00 55325-2E000</p> <p>ARP Product www.rbi.ae</p> <p>Hyundai Tucson [2004-2010] Hyundai CM10 [2009] = CM KIA Sportage [2004-2010]</p> <p>Shock Absorber Dust Cover</p>	<p>AHU14-TU09F01 54626-2E000</p> <p>ARP Product www.rbi.ae</p> <p>Hyundai Ix35, Tucson 10my [2009] Hyundai Santa FE [2006] = CM Hyundai TM 10 [2009] = TM Hyunda</p> <p>MEP-Shock Absorber Bumper [FR]</p>
<p>AHU17-S06IZ 49506-3KA10</p> <p>RBI-2014-May-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Hyundai Sonata [2005-2010] = NF</p> <p>Drive Shaft Boot [Inner]</p>	<p>AHU17-S06UZ 49509-3KA10</p> <p>RBI-2014-May-28 RBI Product www.rbi.ae</p> <p>Hyundai Sonata [2005-2010] = NF</p> <p>Drive Shaft Boot [OUTER]</p>
<p>AHU17-TU04UZ #49500-2E800</p> <p>ARP Product www.rbi.ae</p> <p>Hyundai Tucson [2004-2010]</p> <p>Drive Shaft Boot [Outer]</p>	
<p>AHU18-S06FLR 57740-3K000</p> <p>RBI-2014-May-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Hyundai Sonata [2005-2010] = NF</p> <p>Steering Gear Boot [FR, LH, RH]</p>	

HYUNDAI

Revision : 2014-November-01

AHU21-A00E 55513-22010 Accent  Stabilizer Shaft Rubber [RE]	RBI-2006-September-04 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AHU21-A00F 54813-22200 Accent  Stabilizer Shaft Rubber [FR]	RBI-2006-September-04 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AHU21-E92F 54813-28001 Elantra [1992-1994]  Stabilizer Shaft Rubber [FR]	RBI-2007-June-18 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AHU21-E96E 55513-29100 Elantra [1996]  Stabilizer Shaft Rubber [RE]	RBI-2006-September-04 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AHU21-E96F 54813-29100 Elantra [1996]  Stabilizer Shaft Rubber [FR]	RBI-2007-March-24 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AHU21-S92F 54813-33022 Sonata [1992-1994]  Stabilizer Shaft Rubber [FR]	RBI-2006-October-07 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AHU21-S94E 55577-34000 Sonata [1994-1997]  Stabilizer Shaft Rubber [RE]	RBI-2006-September-04 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AHU21-S94F 54813-34000 Sonata [1994-1997]  Stabilizer Shaft Rubber [FR]	RBI-2006-December-18 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AHU21-S06E00 55513-3K000 Hyundai Sonata [2005-2010] = NF KIA Amanti [2006] = GH  Stabilizer Shaft Rubber [RE]	ARP Product www.rbi.ae	AHU21-S06E02 55513-3K100 Hyundai Grandeur [2005] = TG Hyundai Sonata [2005-2010] = NF  Stabilizer Shaft Rubber [RE]	ARP Product www.rbi.ae










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

AHU21-TU04E00 55513-1F000  Hyundai Tucson [2004-2010] Hyundai Tucson [2008] = JM KIA Sportage [2004-2010] KIA Sportage [2] Stabilizer Shaft Rubber [RE]	AHU21-TU04E01 55513-2E100  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Stabilizer Shaft Rubber [RE]
AHU21-TU04F00 54813-2E100  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Stabilizer Shaft Rubber [FR]	AHU21-TU04F01 54813-2S000  Hyundai Ix35, Tucson 10my [2009] Hyundai TM 10 [2009] = TM KIA Sportage [2010] = SL Stabilizer Shaft Rubber [FR]
AHU21-TU04F02 54813-2E000  Hyundai Tucson [2004-2010] KIA Sorento [2006] = BL KIA Sportage [2004-2010] Stabilizer Shaft Rubber [FR]	
AHU21-X00F 54813-24010  Excel Scoupe  Stabilizer Shaft Rubber [FR]	



HYUNDAI

Revision : 2014-November-01

AHU20-H101RS 55256-44000  Hyundai H1 Spring Shackle Rubber PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU20-H101RB 55257-44000  Hyundai H1 Spring Shackle Rubber PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU20-HD78001 54148-5H050 Hyundai HD-72, HD78 [2004] KIA Pamax Cargo [2000] Spring Shackle Bush [RE] ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU20-H101EB 55118-4A501 Hyundai H-1 [2001] Hyundai Libero [2000-2006] = HB Hyundai Porter H-100 [2004] KIA Bongo-3 [20] Spring Shackle Bush [RE] Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU21-H10E 55513-4H100 Hyundai H1 Stabilizer Shaft Rubber [RE] RBI-2012-May-09 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU21-H10F 54813-3K100 Hyundai H1 Hyundai Sonata [2005-2010] = NF Stabilizer Shaft Rubber [FR] RBI-2012-May-09 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU21-H100 54813-4A600 H100 Stabilizer Shaft Rubber [FR] RBI-2012-November-10 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
AHU21-TE1F00 54816-H1100 Hyundai Terracan [2001] Stabilizer Shaft Rubber [FR] Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU21-TE1E00 55816-H1000 Hyundai Terracan [2001] Stabilizer Shaft Rubber [RE] ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU23-H100 54751-4B002 H100 Strut Bar Rubber RBI-2008-June-17 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	



AL LAMSA AL FIDDIYA TRADING L.L.C.







ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU24-A00WS 54551-22000</p> <p>Accent</p>  <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-2007-January-29 RBI Product, Tenacity Product, Ashimori Product www.rbi.ae www.alafuae.com</p> 
<p>AHU24-A0WL 54555-22102</p> <p>Accent</p>  <p>Front Lower Arm Bush [FR, Big, LH]</p>	<p>AHU24-A0WR 54556-22102</p> <p>Accent</p>  <p>Front Lower Arm Bush [FR, Big, RH]</p>
<p>AHU24-A06WS 54551-1J000</p> <p>Hyundai Accent [2006-2010] = MC Hyundai Accent [2006-2010] = BZ Hyundai Elantra 11 [2010] = SD</p>  <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-2006-September-04 RBI Product, Perfect Product www.rbi.ae www.alafuae.com</p> 



HYUNDAI

Revision : 2014-November-01

<div><div>AHU24-E92WS</div><div>54551-28000</div><div></div><div>Elantra [1992-1994]</div><div>Front Lower Arm Bush [FR, Small]</div></div>	<div><div>RBI-2007-March-24 RBI Product, Perfect Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>		
<div><div>AHU24-E92WL</div><div>54555-28001</div><div></div><div>Elantra [1992]</div><div>Front Lower Arm Bush [FR, Big, LH]</div></div>	<div><div>RBI-2007-March-13 RBI Product, Perfect Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>	<div><div>AHU24-E92WR</div><div>54556-28001</div><div></div><div>Elantra [1992]</div><div>Front Lower Arm Bush [FR, Big, RH]</div></div>	<div><div>RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>
<div><div>AHU24-E94WL</div><div>54555-28071</div><div></div><div>Elantra [1994]</div><div>Front Lower Arm Bush [FR, Big, LH]</div></div>	<div><div>RBI-2006-October-07 RBI Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>	<div><div>AHU24-E94WR</div><div>54556-28071</div><div></div><div>Elantra [1994]</div><div>Front Lower Arm Bush [FR, Big, RH]</div></div>	<div><div>RBI-2006-October-07 RBI Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>
<div><div>AHU24-E95WL</div><div>54555-28070</div><div></div><div>Elantra [1995]</div><div>Front Lower Arm Bush [FR, Big, LH]</div></div>	<div><div>RBI-2007-March-13 RBI Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>	<div><div>AHU24-E95WR</div><div>54556-28070</div><div></div><div>Elantra [1995]</div><div>Front Lower Arm Bush [FR, Big, RH]</div></div>	<div><div>RBI-2007-March-13 RBI Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>
<div><div>AHU24-E96WB</div><div>54583-29000</div><div></div><div>Elantra [1996]</div><div>Front Lower Arm Bush [FR, Big]</div></div>	<div><div>RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>	<div><div>AHU24-E96WS</div><div>54551-29000</div><div></div><div>Elantra [1996]</div><div>Front Lower Arm Bush [FR, Small]</div></div>	<div><div>RBI-2007-February-13 RBI Product, Perfect Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>
<div><div>AHU24-ELA10WB</div><div>54584-4L000</div><div></div><div>Hyundai Elantra 11 [2010] = SD</div><div>Front Lower Arm Bush [FR, Big]</div></div>	<div><div>Tenacity Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>	<div><div>AHU24-ELA10WS</div><div>54551-3X000</div><div></div><div>Hyundai Elantra 11 [2010] = SD Hyundai Veloster [2011] = GS</div><div>Front Lower Arm Bush</div></div>	<div><div>PFT-2014-January-01 Perfect Product shabbirh@eim.ae</div><div></div><div>www.rbi.ae www.alafuae.com</div></div>













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU24-S92WS 54551-36000</p>  <p>Sonata [1992-1994]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-2006-October-07 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU24-S94W0 55116-37000</p>  <p>Sonata [1994-1997]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2006-October-07 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU24-S95WB 54580-35000</p>  <p>Sonata [1994-1997]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2006-October-07 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AHU24-S94WS 54551-37000</p>  <p>Sonata [1994-1997]</p> <p>Front Lower Arm Bush [FR, Small]</p>
	<p>AHU24-S95WS 54580-35000</p>  <p>Sonata [1994-1997]</p> <p>Front Lower Arm Bush [FR, Small]</p>
	<p>RBI-2007-January-18 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>RBI-2006-October-07 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

AHU25-S06PB 55342-2J000 Hyundai Santa FE [2006] = CM Front Upper Arm Bush	 <small>ARP Product</small> <small>shabbirh@eim.ae</small> <small>www.rbi.ae</small> <small>www.alafuae.com</small>	AHU24-S06PS 54443-3K000 Hyundai Sonata [2005-2010] = NF Hyundai Grandeur [2005] = TG Front Upper Arm Bush [FR, Upper]	 <small>RBI-2014-September-04</small> <small>RBI Product</small> <small>shabbirh@eim.ae</small> <small>www.rbi.ae</small> <small>www.alafuae.com</small>
AHU24-S06PBJ 54430-3F600 Hyundai Azera [2006] = TG Hyundai Grandeur [2005] = TG Hyundai Sonata [2005-2010] = NF KIA Ama Front Upper Arm Ball Joint [FR, LH, RH]	 <small>ARP Product</small> <small>www.rbi.ae</small>	AHU24-S06WBJ 51760-3K000 Hyundai Azera [2006] = TG Hyundai Grandeur [2005] = TG Hyundai Sonata [2005-2010] = NF KIA Ama Front Lower Arm Ball Joint [FR, LH, RH]	 <small>ARP Product</small> <small>shabbirh@eim.ae</small> <small>www.rbi.ae</small> <small>www.alafuae.com</small>
AHU24-S06WB 54584-3F600 Hyundai Sonata [2001-2005] = EF Hyundai Sonata [2005-2010] = NF Hyundai Coupe [2001] Hyundai E Front Lower Arm Bush [FR, Big]	 <small>RBI-2014-May-28</small> <small>RBI Product</small> <small>www.rbi.ae</small>	AHU24-S06WL 54552-3K000 Hyundai Sonata [2005-2010] = NF Hyundai Grandeur [2005] = TG Front Lower Arm Bush [FR, Midding]	 <small>RBI-2014-May-28</small> <small>RBI Product</small> <small>shabbirh@eim.ae</small> <small>www.rbi.ae</small> <small>www.alafuae.com</small>
AHU24-S06WS 54551-3L000 Hyundai Sonata [2005-2010] = NF Hyundai Grandeur [2005] = TG Front Lower Arm Bush [FR, Small]	 <small>RBI-2014-April-18</small> <small>RBI Product</small> <small>shabbirh@eim.ae</small> <small>www.rbi.ae</small> <small>www.alafuae.com</small>	AHU24-S06WS2 54551-2B000 Hyundai Santa FE [2006] = CM Front Lower Arm Bush [FR, Small]	 <small>PFT-2014-January-01</small> <small>Perfect Product</small> <small>shabbirh@eim.ae</small> <small>www.rbi.ae</small> <small>www.alafuae.com</small>
AHU25-S06E02 55218-2B000 Hyundai Santa FE [2006] = CM Rear Lower Arm Bush	 <small>ARP Product</small> <small>shabbirh@eim.ae</small> <small>www.rbi.ae</small> <small>www.alafuae.com</small>	AHU25-S06E03 55118-2B100 Hyundai Santa FE [2006] = CM Rear Suspension Bush	<small>ARP Product</small> <small>www.rbi.ae</small>
AHU25-S06E04 55118-2B000 Hyundai Santa FE [2006] = CM Rear Suspension Bush	<small>ARP Product</small> <small>www.rbi.ae</small>		
AHU25-S06E05A 55130-4D00L Hyundai Santa FE [2006] = CM Rear Suspension Bush	<small>ARP Product</small> <small>www.rbi.ae</small>	AHU25-S06E05M 55130-4D00M Hyundai Santa FE [2006] = CM Rear Suspension Bush	<small>ARP Product</small> <small>www.rbi.ae</small>



HYUNDAI

Revision : 2014-November-01

<p>AHU24-SA00PB 54443-38000</p> <p>SANTA FE [2000-2006] HYUNDAI XG/XG25/XG30/XG300 [1998] KIA OPTIMA/MAGENTIS [2000-2005]</p> <p>Front Upper Arm Bush [FR]</p>	<p>PFT-2012-November-07 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU24-SA00WB 54555-26000</p> <p>Hyundai Santa FE [2000-2006] = BB</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AHU24-SA00WS 54551-26000</p> <p>Hyundai Santa FE [2000-2006] = BB</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>AHU24-GE02WB 54584-1C300</p> <p>Hyundai Getz [2002-2011]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AHU24-GE02WS 54551-1C000</p> <p>Hyundai Getz [2002-2011] Hyundai Accent [2005] = MC Hyundai Accent 11, Blue [2011] .. [USA] Hy</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>AHU24-AZE06WB 54584-2S000</p> <p>Hyundai Azera [2006] = TG</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU24-X92W 54551-24001</p> <p>Excel Scoupe</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-2006-September-04 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU24-M00W 54551-25000</p> <p>Matrix</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2007-July-16 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AHU24-M01W 54584-17000</p> <p>Matrix</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>AHU24-T00WS 54551-3A000</p> <p>Hyundai Trajet [2000-2006]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-2009-February-18 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU24-TU05WB 54584-2E000</p> <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Front Lower Arm Bush [FR, Big]</p> <p>Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AHU24-TU05WS 54551-1D000</p> <p>Hyundai Elantra [2006] = HD Hyundai I30 [2007] Hyundai Tucson [2004-2010] Hyundai Azera [2011]</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AHU24-TU04FB01 62486-2E000</p> <p>Hyundai Tucson [2004-2010]</p> <p>Front Suspension Body Bush</p> <p>ARP Product www.rbi.ae</p>	<p>AHU24-TU04WBJ 51760-2E000</p> <p>Hyundai Tucson [2004-2010] KIA Sportage [2004-2010]</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p> <p>ARP Product www.rbi.ae</p>
<p>AHU24-TU09WS 54551-2S000</p> <p>Hyundai Ix35, Tucson 10my [2009] Hyundai TM 10 [2009] = TM KIA Sportage [2010] = SL</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>ARP Product www.rbi.ae</p>	
<p>AHU24-SOL10WB 54584-1G000</p> <p>Hyundai Solaris [2010] = SB</p> <p>Front Lower Arm Bush [FR, Big]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

AHU25-TU04E1Z 55210-2E500 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Complete Suspension Arm [RE]	
AHU25-TU04E2B 55215-2E500 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Suspension Bush	AHU25-TU04E2Z 55220-2E500 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Complete Suspension Arm [RE]
AHU25-TU04E3B 55116-2E001 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] Hyundai Tucson [2008] = JM KIA Sportage [2008] = FQ Rear Suspension Bush	AHU25-TU04E3Z 55110-2E002 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2008] = FQ Rear Complete Suspension Arm
AHU25-TU04E4Z 55220-2E010 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Complete Suspension Arm [RE]	AHU25-TU04E5Z 55210-2E000 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Complete Suspension Arm [RE]
AHU25-TU04E6B 55116-2E000 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Suspension Bush	
AHU25-TU04W1B #55210-2D000 <small>ARP Product</small> shabbirh@eim.ae  www.rbi.ae www.alafuae.com Hyundai Coupe [2001] Hyundai Elantra, Lantra [2000-2006] = CA Hyundai Matrix, Lavita [2001-2006] Rear Suspension Bush	AHU25-TU04W2B #55210-2E500 <small>ARP Product</small> www.rbi.ae Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Suspension Bush





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

<p>AHU25-E9201 54551-28310</p>  <p>Elantra [1992-1994]</p> <p>Rear Suspension Bush [RE]</p>	<p>AHU25-S9401 55543-37000</p>  <p>Sonata [1994-1997]</p> <p>Rear Suspension Bush [RE]</p>
<p>AHU25-S9402 55543-35000</p>  <p>Sonata [1994-1997]</p> <p>Rear Suspension Bush [RE]</p>	
<p>AHU25-T00E 54555-3A100</p>  <p>Trajet</p> <p>Rear Suspension Bush [RE]</p>	<p>AHU25-A00E 54555-25000</p>  <p>Accent [2000]</p> <p>Rear Suspension Bush [RE, Big]</p>
<p>AHU25-A99E01S 55116-25000</p>  <p>Hyundai Accent, Verna [1999-2002] Hyundai Coupe [2001] Hyundai Coupe, Tiburon [1996-2000] Hyun</p> <p>Rear Suspension Bush</p>	<p>AHU25-A99E01B 55119-25000</p>  <p>Hyundai Accent, Verna [1999-2002]</p> <p>Rear Suspension Bush</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

AHU24-H10WB 54584-4H000  Hyundai H-1 [2001] Hyundai H-1 [2007] = TQ Front Lower Arm Bush [FR, Big]	RBI-2011-November-11 RBI Product  www.rbi.ae www.alafuae.com	AHU24-H10WS 54551-4H000  Hyundai H-1 [2001] Hyundai H-1 [2007] = TQ Front Lower Arm Bush [FR, Small]	RBI-2012-January-06 RBI Product  www.rbi.ae www.alafuae.com
AHU24-H101WB 54522-4B010  Hyundai H-1 [2001] Hyundai H100 [1997] = AU Truck Hyundai Porter H-100 [2004] Front Lower Arm Bush [FR, Big]	Perfect Product  www.rbi.ae www.alafuae.com		
AHU25-H10E 55620-4H000  HYUNDAI H1 Rear Suspension Bush [RE]	RBI-2011-February-24 RBI Product  www.rbi.ae www.alafuae.com	AHU25-H100 55630-4H000  HYUNDAI H1 Rear Suspension Bush [RE]	RBI-2011-March-28 RBI Product  www.rbi.ae www.alafuae.com
AHU25-H101 55217-4H000  HYUNDAI H1 Rear Suspension Bush [RE]	RBI-2011-May-24 RBI Product  www.rbi.ae www.alafuae.com	AHU25-H103 55225-4H100  HYUNDAI H1 Rear Suspension Bush [RE]	RBI-2011-July-12 RBI Product  www.rbi.ae www.alafuae.com
AHU25-H104 55216-4H100  HYUNDAI H1 Rear Suspension Bush [RE]	RBI-2011-November-11 RBI Product  www.rbi.ae www.alafuae.com		
AHU25-EF2E01 52718-38000  Hyundai Sonata [1999-2001] = EF Hyundai XG, XG25, XG30, XG300 [1998] KIA Amanti [2003-2006] = EH Rear Suspension Bush	Perfect Product www.rbi.ae		



HYUNDAI

Revision : 2014-November-01

<p>AHU27-E920F 54830-37020</p>  <p>Elantra [1992-1994]</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2009-October-12 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AHU27-E960E 55530-29500</p>  <p>Elantra [1996]</p> <p>Link Assy [RE, LH, RH]</p>	<p>RBI-2009-October-07 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU27-S920F 54830-36101</p>  <p>Sonata [1992-1994]</p> <p>Link Assy [FR, LH, RH]</p>	<p>RBI-2009-October-03 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AHU27-S940E 55580-37030</p>  <p>Sonata [1994-1997]</p> <p>Link Assy [RE, LH, RH]</p>	<p>RBI-2009-October-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AHU27-S06E00 55530-3K002</p>  <p>Hyundai Sonata [2005-2010] = NF</p> <p>Link Assy [RE]</p>	<p>RBI-2013-December-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AHU27-S06F02 54830-3K000</p>  <p>Hyundai Grandeur [2005] = TG Hyundai Sonata [2005-2010] = NF</p> <p>Link Assy</p>	<p>PFT-2014-January-01 Perfect Product www.rbi.ae</p> 
<p>AHU27-S06F00 54830-3K010</p>  <p>Hyundai Sonata [2005-2010] = NF</p> <p>Link Assy [FR]</p>	<p>RBI-2013-December-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 		















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HYUNDAI

Revision : 2014-November-01

AHU27-H1FL 54830-4H000  Hyundai H1 [1997-2007] Link Assy [FR, LH] RBI-2010-December-24 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU27-H1FR 54840-4H000  Hyundai H1 [1997-2007] Link Assy [FR, RH] RBI-2010-December-24 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU27-H1EL 55530-4H000  Hyundai H1 [1997-2007] Link Assy [RE, LH] RBI-2010-December-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AHU27-H1ER 55540-4H000  Hyundai H1 [1997-2007] Link Assy [RE, RH] RBI-2010-December-09 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AHU27-TU04E00 55530-1F000  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Link Assy [RE] ARP Product www.rbi.ae	AHU27-TU04F00 54830-2E000  Hyundai Tucson [2004-2010] KIA Carens III [2006] KIA Rio [2005] Link Assy ARP Product www.rbi.ae
AHU29-TU04001 #49300-2E000  Hyundai Tucson [2004-2010] Hyundai Tucson [2008] = JM KIA Sportage [2004-2010] KIA Sportage [2] Center Bearing HFC Product www.rbi.ae	AHU29-TU09001 #49300-2P100  Hyundai Ix35, Tucson 10my [2009] Hyundai TM 10 [2009] = TM KIA Sorento [2009] = XM KIA Sportage Center Bearing ARP Product www.rbi.ae
AHU41-S06E01 53912-2E000  Hyundai Santa FE [2006] = CM Rear Differential Bushing [RE] ARP Product www.rbi.ae	AHU41-TU04E1B 55456-2E500  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Suspension Bush ARP Product www.rbi.ae
AHU41-TU04E1M 53912-2E100  Hyundai Santa FE [2006] = CM Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Differential Bushing [RE] ARP Product www.rbi.ae	AHU41-TU04E1S 55456-39000  Hyundai Tucson [2004-2010] KIA Sportage [2004-2010] Rear Suspension Bush ARP Product www.rbi.ae

