

## CHRYSLER

Revision : 2014-November-01

<p><b>ACH09-CAR96E1Z</b>  <b>5281314AB</b></p> <p>Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [1996-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>ACH09-CAR96F1Z</b>  <b>4612431</b></p> <p>Chrysler CARAVAN 2.2, 2.4 [1996-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>ACH09-CAR96F2Z</b>  <b>4612427</b></p> <p>Chrysler CARAVAN 3.0, 3.3 [1996-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>ACH09-CAR96L1Z</b>  <b>5012896AA</b></p> <p>Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [1996-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>ACH09-CAR96R1Z</b>  <b>4612367</b></p> <p>Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [1996-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>ACH09-CHE97E1Z</b>  <b>52001180</b></p> <p>Chrysler Jeep CHEROKEE [1984-2000]   Chrysler Jeep Grand Cherokee II [1997-2004]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>ACH09-CHE97E2Z</b>  <b>52003064</b></p> <p>Chrysler Jeep CHEROKEE</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>ACH09-CHE97F1Z</b>  <b>J3212711</b></p> <p>Chrysler Jeep CHEROKEE [1984-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>ACH09-CHE97F2Z</b>  <b>52019201</b></p> <p>Chrysler Jeep CHEROKEE [1984-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>ACH09-CHE97F3Z</b>  <b>52007394</b></p> <p>Chrysler Jeep CHEROKEE [1991-2000]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	

**CHRYSLER**

Revision : 2014-November-01

<div>ACH09-CON94EAZ</div> <div>4663228</div> <div>Chrysler CONCORD 3.3, 3.5 [1994]</div> <div>Insulator Engine</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>		
<div>ACH09-DYN00L1Z</div> <div>4471031</div> <div>Chrysler DYNASTY</div> <div>Insulator Engine</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>		
<div>ACH09-NEO93F1Z</div> <div>4668182</div> <div>Chrysler NEON 2.0 [1993-1998]</div> <div>Insulator Engine</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>	<div>ACH09-NEO93R1Z</div> <div>4668200</div> <div>Chrysler NEON 2.0 [1993-1998]</div> <div>Insulator Engine</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>
<div>ACH09-NEO93L1Z</div> <div>4668259</div> <div>Chrysler NEON 2.0 [1993-1998]</div> <div>Insulator Engine</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>	<div>ACH09-NEO93L2Z</div> <div>4668089</div> <div>Chrysler NEON 2.0 [1993-1998]</div> <div>Insulator Engine</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>
<div>ACH09-NEO00F1Z</div> <div>4668192</div> <div>Chrysler Neon II [2000-2005]</div> <div>Insulator Engine [FR, A/T, 2.0]</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>	<div>ACH09-NEO00L2Z</div> <div>4668527</div> <div>Chrysler Neon II [2000-2005]</div> <div>Insulator Engine [LH, A/T, 2.0]</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>
<div>ACH09-NEO00R1Z</div> <div>4668347</div> <div>Chrysler Neon II [2000-2005]</div> <div>Insulator Engine [RH, Buffer, 2.0]</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>	<div>ACH09-NEO00R2Z</div> <div>4668193</div> <div>Chrysler Neon II [2000-2005]</div> <div>Insulator Engine [RH, Buffer, 2.0]</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> <div></div>



# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHRYSLER

Revision : 2014-November-01

<p><b>ACH09-SPI89F1Z</b> <b>4612157</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler SPIRIT 2.5 [1989]</p> <p>Insulator Engine</p>	
<p><b>ACH09-SPI89FL1Z</b> <b>4471039</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler SPIRIT 2.5 [1989]</p> <p>Insulator Engine</p>	<p><b>ACH09-SPI89FR1Z</b> <b>4612093</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler SPIRIT 2.5 [1989]</p> <p>Insulator Engine</p>
<p><b>ACH09-STR95F1Z</b> <b>4593410</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]</p> <p>Insulator Engine</p>	
<p><b>ACH09-STR95L1Z</b> <b>4573775</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]</p> <p>Insulator Engine</p>	<p><b>ACH09-STR95R1Z</b> <b>4573773</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]</p> <p>Insulator Engine</p>
<p><b>ACH09-STR99E1Z</b> <b>4593397</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler STRATUS 2.0, 2.4, 2.5 [1999]</p> <p>Insulator Engine</p>	<p><b>ACH09-STR99F1Z</b> <b>4593338</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler STRATUS 2.0, 2.4, 2.5 [1999]</p> <p>Insulator Engine</p>
<p><b>ACH09-VOY01E1Z</b> <b>04861273AA</b></p> <p>HFC Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20]</p> <p>Insulator Engine</p>	<p><b>ACH09-VOY01F1Z</b> <b>04861430AB</b></p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20]</p> <p>Insulator Engine</p>



## CHRYSLER

Revision : 2014-November-01

<b>ACH13-CAR84F00</b> <b>4052850</b>  Chrysler CARAVAN [1984-1985] Shock Absorber Mounting	<b>ACH13-CAR85F00</b> <b>4684643</b>  Chrysler CARAVAN [1985-1993] Shock Absorber Mounting
<b>ACH13-CAR85FB</b>  Chrysler CARAVAN, SPIRIT 2.5 [1985-1993] Shock Absorber Mounting Bearing Only	<b>ACH13-CAR85FZ</b> <b>4684643</b>  Chrysler CARAVAN [ASMCH1011+ABRCH1003] [1985-1993] Shock Absorber Mounting + Bearing [SET]
<b>ACH13-CAR93F00</b> <b>4684129</b>  Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [1993-1997] Shock Absorber Mounting	<b>ACH13-CAR93FB</b>  Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [1993-1997] Shock Absorber Mounting Bearing Only
<b>ACH13-CAR93FZ</b> <b>4684129</b>  Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [ASMCH1001+ABRCH1001] [1993-1997] Shock Absorber Mounting + Bearing [SET]	
<b>ACH13-CAR01F00</b> <b>4743044AA</b>  Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [2001] Shock Absorber Mounting	<b>ACH13-CAR01F02</b> <b>4862027</b>  Chrysler . Shock Absorber Mounting
<b>ACH13-CAR01FB</b>  Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [2001] Shock Absorber Mounting Bearing Only	<b>ACH13-CAR01FZ</b> <b>4743044AAK</b>  Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [ASMCH1002+ABRCH1002] [2001] Shock Absorber Mounting + Bearing [SET]
<b>ACH13-CAR01FZ2</b> <b>4862027K</b>  Chrysler . [ASMCH1008+ABRCH1002] Shock Absorber Mounting + Bearing [SET]	
<b>ACH13-CIR95E00</b> <b>4616703</b>  Chrysler CIRRUS [1995-2000] Shock Absorber Mounting	<b>ACH13-CON94FB</b>  Chrysler CONCORD [1994-1997] Shock Absorber Mounting Bearing Only



## CHRYSLER

Revision : 2014-November-01

<b>ACH13-LIB00FL</b> <b>5212-8533-AA</b> Chrysler Jeep Liberty [2000-2007] Shock Absorber Mounting [FR, LH]	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>ACH13-LIB00FR</b> <b>5212-8532-AA</b> Chrysler Jeep Liberty [2000-2007] Shock Absorber Mounting [FR, RH]	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>ACH13-NEO93E00</b> <b>4626182</b> Chrysler NEON [1995-1999] Shock Absorber Mounting	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>ACH13-NEO93F00</b> <b>4626100</b> Chrysler NEON [1995-1999] Shock Absorber Mounting	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>ACH13-NEO93FB</b> Chrysler NEON [1995-1999] Shock Absorber Mounting Bearing Only	 <small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>ACH13-NEO93FZ</b> <b>4626100</b> Chrysler NEON [ASMCH1006+ABRCH1004] [1995-1999] Shock Absorber Mounting + Bearing [SET]	 <small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>ACH13-NEO00F00</b> <b>5272226</b> Chrysler Neon II [2000-2005] Shock Absorber Mounting [FR]	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>ACH13-NEO00FZ</b> <b>5272226K</b> Chrysler Neon II [2000-2005] Shock Absorber Mounting + Bearing [SET] [FR] [ASMCH1010+ABRCH1004]	 <small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>ACH13-VOY96FB</b> <b>4684418</b> Chrysler Voyager II [GS] [1995-2001]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan II [199 Shock Absorber Mounting Bearing Only	 <small>ARP Product www.rbi.ae</small>		
<b>ACH13-VOY01F00</b> <b>04766116AB</b> Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20 Shock Absorber Mounting	 <small>ARP Product www.rbi.ae</small>	<b>ACH13-VOY01FB</b> <b>04743044AA</b> Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20 Shock Absorber Mounting Bearing Only	 <small>ARP Product www.rbi.ae</small>
<b>ACH13-YOR94E00</b> <b>4601937</b> Chrysler NEW YORKER [1994-1997] Shock Absorber Mounting	 <small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>ACH13-YOR94F00</b> <b>4582758</b> Chrysler NEW YORKER [1994-1997] Shock Absorber Mounting	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
<b>ACH13-YOR94FZ</b> <b>4582758</b> Chrysler NEW YORKER [ASMCH1005+ABRCH1005] [1994-1997] Shock Absorber Mounting + Bearing [SET]	 <small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	<b>ACH13-PAR91FB</b> Chrysler PARK [1991-1996] Shock Absorber Mounting Bearing Only	 <small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>



# AL LAMSA AL FIDDIYA TRADING L.L.C.

**ALAF**

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHRYSLER

Revision : 2014-November-01

<p><b>ACH14-CAR96F01U</b> <b>4684756AC-M8</b></p> <p>Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [1996]</p> <p>MEP-Shock Absorber Bumper [FR] [8MM]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p><b>ACH14-CAR96F02U</b> <b>4684756AC-M10</b></p> <p>Chrysler CARAVAN 2.2, 2.4, 3.0, 3.3 [1996]</p> <p>MEP-Shock Absorber Bumper [FR] [10MM]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p><b>ACH14-CON94F01U</b> <b>4695755</b></p> <p>Chrysler CONCORD 3.3, 3.5 [1993-1996]</p> <p>MEP-Shock Absorber Bumper [FR]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p><b>ACH20-VOY96E00</b> <b>4228564</b></p> <p>Chrysler Voyager II [GS] [1995-2001]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan II [199</p> <p>Spring Shackle Rubber [RE]</p> <p>ARP Product www.rbi.ae</p>	<p><b>ACH20-VOY96E01</b> <b>4228492</b></p> <p>Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [2001-2007]</p> <p>Spring Shackle Bush [RE]</p> <p>ARP Product www.rbi.ae</p>
<p><b>ACH20-VOY01E00</b> <b>04743040AA</b></p> <p>Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20</p> <p>Spring Shackle Rubber [RE]</p> <p>ARP Product www.rbi.ae</p>	<p><b>ACH20-VOY01E01</b> <b>05006950AA</b></p> <p>Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20</p> <p>Spring Shackle Bush [RE]</p> <p>ARP Product www.rbi.ae</p>






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHRYSLER

Revision : 2014-November-01

<b>ACH21-3C04E00</b> <b>04782892AB</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler 300C [2004]   Dodge Magnum [2004]   Dodge Charger [2004] Stabilizer Shaft Rubber [RE]	
<b>ACH21-3C04F00</b> <b>04782681AB</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler 300C [2004]   Dodge Magnum [2004]   Dodge Charger [2004] Stabilizer Shaft Rubber [FR]	<b>ACH21-3C04F02</b> <b>04782684AB</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler 300C [2004]   Dodge Magnum [2004]   Dodge Challenger [2008]   Dodge Charger [2004] Stabilizer Shaft Rubber [FR]
<b>ACH21-COM06E00</b>  <small>Perfect Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Compass, Patriot [2006-2010] Stabilizer Shaft Rubber [RE]	
<b>ACH21-CON02F00</b> <b>04782302AA</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Concorde Interpid 300M [2002] Stabilizer Shaft Rubber [FR]	
<b>ACH21-NEO00F00</b> <b>05272506AA</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Neon II [2000-2005]   Chrysler Pt Cruiser [2001-2009] Stabilizer Shaft Rubber [FR]	
<b>ACH21-VOY96F00</b> <b>4680000</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [2001-2007] Stabilizer Shaft Rubber [FR]	<b>ACH21-VOY01F00</b> <b>04743024AD</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20 Stabilizer Shaft Rubber [FR]







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHRYSLER

Revision : 2014-November-01

<b>ACH24-NEO00WB</b> <b>04656012AC</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Neon II [2000-2005]   Chrysler Pt Cruiser [2001-2009] Front Lower Arm Bush [FR, Big]	<b>ACH24-NEO00WS</b> <b>#05272236AE</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Neon II [2000-2005]   Chrysler Pt Cruiser [2001-2009] Front Lower Arm Bush [FR, Small]
<b>ACH24-NEO00WBJ</b> <b>#4656010</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Neon II [2000-2005]   Chrysler Pt Cruiser [2001-2009]   Chrysler Voyager II [GS] [1995-2001] Front Lower Arm Ball Joint [FR, LH, RH]	
<b>ACH24-STR04WB</b> <b>04764453AA</b> <small>TN-2014-February-10 Tenacity Product</small>  <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]   Chrysler Sebring Cirrus Stratus R, T [2004] Front Lower Arm Bush [FR, Big]	<b>ACH24-STR04WS</b> <b>04616736</b> <small>TN-2014-February-10 Tenacity Product</small>  <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]   Chrysler Sebring Cirrus Stratus R, T [2004] Front Lower Arm Bush [FR, Small]
<b>ACH24-STR04WL</b> <b>4695116</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]   Chrysler Sebring Cirrus Stratus R, T [2004] Front Lower Arm Bush [FR, Middium]	
<b>ACH24-VOY96WB</b> <b>04743094AA</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20] Front Lower Arm Bush [FR, Big]	<b>ACH24-VOY96WB2</b> <b>04743095AA</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Dodge Caravan III [20] Front Lower Arm Bush
<b>ACH24-VOY96WB3</b> <b>4684548</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Voyager II [GS] [1995-2001]   Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [ Front Lower Arm Bush	<b>ACH24-VOY96WS</b> <b>4680000</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Voyager II [GS] [1995-2001]   Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [ Front Lower Arm Bush [FR, Small]
<b>ACH24-VOY01WBJ</b> <b>#04743376AA</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler Voyager IV [RG] [2001-2007]   Chrysler Voyager III [RG] [1996-2000]   Chrysler Pacifica [20] Front Lower Arm Ball Joint [FR, LH, RH]	









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHRYSLER

Revision : 2014-November-01

<b>ACH25-3C04E01</b> <b>A2013520027</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler 300C [2004]   Chrysler Pacifica [2003-2008]   Dodge Magnum [2004]   Mercedes Benz C-Class [ Rear Suspension Bush	<b>ACH25-3C04E02S</b> <b>#04782561AE</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler 300C [2004]   Dodge Magnum [2004]   Dodge Charger [2004] Rear Suspension Bush
<b>ACH25-STR04E01</b> <b>04764961AA</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]   Chrysler Sebring Cirrus Stratus R, T [2004] Front Upper Arm Bush	<b>ACH25-STR04E02</b> <small>TN-2014-February-10 Tenacity Product</small>  <small>shabbirh@eim.ae 41.50 12.50 www.alafuae.com</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]   Chrysler Sebring Cirrus Stratus R, T [2004] Rear Suspension Bush [RE]
<b>ACH26-STR04E00</b> <b>04616749</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chrysler STRATUS 2.0, 2.4, 2.5 [1995-1999]   Chrysler Sebring Cirrus Stratus R, T [2004] Rear Shock Absorber Bush	
<b>ADO09-CAL06EAZ</b> <b>68032586AF</b> <small>HFC-2014-November-20 HFC Product</small>  <small>shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Dodge Caliber [2006] Insulator Engine [RE]	<b>ADO21-CAL06E00</b> <b>05105108AD</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Dodge Caliber [2006] Stabilizer Shaft Rubber [RE]

