








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-N18EM MB-691490  ARP Product www.rbi.ae www.alafuae.com Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N18, N31, N33, Engine Bushing [RE, M/T] [2WD] [1.8, 2.0, 2.4 Petrol] [2.0 Diesel]	AM09-N18EMZ MB-691490  ASH-2013-July-10 HFC Product, Ashimori Product www.rbi.ae www.alafuae.com Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N18, N31, N33, Insulator Engine [RE, M/T] [2WD] [1.8, 2.0, 2.4 Petrol] [2.0 Diesel]
	AM09-N18EAZ MB-691491  ASH-2013-July-10 HFC Product, Ashimori Product www.rbi.ae www.alafuae.com Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N31, N33, N34 Insulator Engine [RE, A/T] [2WD] [1.8, 2.0, 2.4 Petrol]
	AM09-N33EAZ MB-581311  HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae www.alafuae.com Mitsubishi Chariot, Space Wagon, Grandis [1992-2000] = N33W, N43W Insulator Engine [RE, A/T]
	AM09-N33E2Z MR-581301  HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae www.alafuae.com Mitsubishi Rvr [1992-1997] = N11W, N13W, N21W, N21WG, N23W, N23WG, N28W, N28WG Insulator Engine [RE, A/T]













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-N18FM MB-691500   <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N21, N31, N33,</p> <p>Engine Bushing [FR, A/T, M/T]</p>	AM09-N18FMZ MB-691500  <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N21, N31, N41</p> <p>Insulator Engine [FR, M/T] [2WD, 4WD] [1.8 Petrol]</p>
AM09-N18FA MB-691501   <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N31, N33, N43,</p> <p>Engine Bushing [FR, A/T, M/T]</p>	AM09-N18FAZ MB-691501  <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N31, N11</p> <p>Insulator Engine [FR, A/T] [2WD] [1.8 Petrol]</p>
	AM09-N33FMZ MB-911709  <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N33, N43, N44</p> <p>Insulator Engine [FR, M/T] [2WD, 4WD] [2.0 Petrol]</p>
	AM09-N33FAZ MB-911710  <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N33</p> <p>Insulator Engine [FR, A/T] [2WD] [2.0 Petrol]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-N18RMZ MB-691464</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N21, N31, N33,</p> <p>Insulator Engine [RH, M/T] [2WD, 4WD] [1.8, 2.0, 2.4 Petrol]</p> <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM09-N18RA MB-581330</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N21, N31, N33,</p> <p>Engine Bushing [RH, A/T, M/T] [2WD, 4WD] [1.8, 2.0, 2.4 Petrol]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-N18RAZ MB-581330</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N31, N33, N34</p> <p>Insulator Engine [RH, A/T] [2WD] [1.8, 2.0, 2.4 Petrol]</p> <p>ASH-2014-May-15 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-N18L0 MB-948000</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N18, N33, N34, N38,</p> <p>Engine Bushing [LH, A/T, M/T] [2.0P]</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-N18LZ MB-948000</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N18, N33, N34, N38,</p> <p>Insulator Engine [LH, A/T, M/T] [2.0P]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-N18L2Z MB-949465</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N21, N31, N41</p> <p>Insulator Engine [LH, M/T] [2WD, 4WD] [1.8 P]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-N18L3Z MB-914987</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1992-1997] = N11, N31 [1.8]</p> <p>Insulator Engine [LH, A/T] [2WD, 4WD] [1.8 P]</p> <p>ARD-2014-January-01 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-N84EAZ MR-316651</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1997-2004] = N84</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-N84FAZ MR-316642</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1997-2004] = N84</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-N84LAZ MR-316344</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1997-2004] = N84</p> <p>Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-N84L1Z MR-316269</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1997-2004] = N84</p> <p>Insulator Engine [LH]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-N84RAZ MR-316993</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [1997-2004] = N84</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM09-NA4F MR-594383  Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4 Engine Bushing [FR]	RBI-2008-March-06 RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM09-NA4FZ MR-594377  Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4 Insulator Engine [FR]	Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM09-NA4E MR-594385  Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4 Engine Bushing [RE]	RBI-2008-March-04 RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM09-NA4EZ MR-594379  Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4 Insulator Engine [RE]	HFC-2014-November-20 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM09-NA4L MN-103097  Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4 Engine Bushing [LH]	RBI-2008-March-11 RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM09-NA4LZ MR-995315  Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4 Insulator Engine [LH]	HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
		AM09-NA4RZ MR-594373  Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4 Insulator Engine [RH]	HFC-2014-November-20 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

mitsubishi

Revision : 2014-November-01

	<p>AM09-Z11AFZ</p> <p>MB-581703</p> <p>Mitsubishi 3000GT [1991-1999] = Z11A, Z15A, Z16A..6G72</p> <p>Insulator Engine [FR]</p> <p>TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-Z11AEZ</p> <p>MB-581705</p> <p>Mitsubishi 3000GT [1991-1999] = Z11A, Z15A, Z16A..6G72</p> <p>Insulator Engine [RE]</p> <p>TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-Z11ARZ</p> <p>MB-892449</p> <p>Mitsubishi 3000GT [1991-1999] = Z11A, Z15A, Z16A..6G72</p> <p>Insulator Engine [RH]</p> <p>TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-Z11ALZ</p> <p>MB-870005</p> <p>Mitsubishi 3000GT [1991-1999] = Z11A, Z15A, Z16A..6G72</p> <p>Insulator Engine [LH]</p> <p>TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-02B MB-007161 A156 Engine Bushing [FR]	  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
AM09-02S MB-007156 A156 Engine Bushing [FR, Small]	  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
AM09-02R MB-007183 A156 Engine Bushing [LH, RH]	  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
AM09-02E MB-007162 A156 Engine Bushing [RE]	  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-06E0 MB-309261</p> <p>Galant [1988-1994] = E31, E32, E33</p> <p>Engine Bushing [RE]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-06EAZ MB-309261</p> <p>Galant [1988-1994] = E31, E32, E33</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM09-D21EA MB-581322</p> <p>Eclipse [1990-1994] = D21, D22</p> <p>Engine Bushing [RE, A/T]</p> <p>PFT-2013-June-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-D21EAZ MB-581322</p> <p>Eclipse [1990-1994] = D21, D22</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-06EMZ MB-309260</p> <p>Galant [1988-1994] = E31, E32, E33 Eclipse [90-94] = D21, D22</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-06FAZ MB-309481</p> <p>Galant [1988-1994] = E31, E32, E33 Eclipse [90-94] = D21, D22</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-26 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM09-06FM MB-309504</p> <p>Galant [1988-1994] = E31, E32, E33 Eclipse [90-94] = D21, D22</p> <p>Engine Bushing [FR, M/T]</p> <p>PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-06FMZ MB-309504</p> <p>Galant [1988-1994] = E31, E32, E33 Eclipse [90-94] = D21, D22</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-06L MB-436537</p> <p>Galant [1988-1994] = E33</p> <p>Engine Bushing [LH]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-06LZ MB-436502</p> <p>Galant [1988-1994] = E31, E32, E33</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-06L2Z MB-436501</p> <p>Galant [1988-1994] = E31, E32, E33</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-D21LZ MB-436740</p> <p>Eclipse [1990-1994] = D21, D22</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-D22LZ MB-436741</p> <p>Eclipse [1990-1994] = D21, D22</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

mitsubishi

Revision : 2014-November-01

AM09-06R MB-436553 Galant [1988-1994] = E33 Engine Bushing [RH]	  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	AM09-06RAZ MB-436556 Galant [1988-1994] = E33 Insulator Engine [RH, A/T]	 <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
		AM09-06RMZ MB-436541 Galant [1988-1994] = E33, E33, E38, E39 Insulator Engine [RH, M/T] [2.0]	 <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
		AM09-061RAZ MB-436540 Galant [1988-1994] = E32, E33 Insulator Engine [RH, A/T]	 <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
		AM09-062RAZ MB-436557 Galant [1988-1994] = E32, E33 Insulator Engine [RH, A/T] [2.0]	 <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
		AM09-D21RAZ MB-436744 Eclipse [1990-1994] = D21, D22 Insulator Engine [RH, A/T]	 <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
		AM09-D21RMZ MB-436745 Eclipse [1990-1994] = D21, D22 Insulator Engine [RH, M/T]	 <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM09-07EA MB-911267  Galant [1992-1999] = E54, E55 Engine Bushing [RE, A/T] RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-07EAZ MB-911267  Galant [1992-1995] = E52, E54, E55 Insulator Engine [RE, A/T] [L6] RBI-OLD RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM09-07EM MB-844290  Galant [1992-1999] = E54, E55, E12, E15, E33 Engine Bushing [RE, M/T] RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-07EMZ MB-844290  Galant [1994-1998] = E54, E55 Insulator Engine [RE, M/T] [L6] RBI-OLD RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM09-07E0 MB-911266  Galant [1992-1999] = E52, E54, E55, E56 [2.0] / Eclipse [1994-1999] = D32 Engine Bushing [RE, M/T] ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-07EZ MB-911266  Galant [1992-1999] = E52, E54, E55, E56 [2.0] / Eclipse [1994-1999] = D32 Insulator Engine [RE, M/T] TN-2011-June-03 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM09-071E00 MB-844289  Galant [1994-1999] = E52, E55 Eclipse [1994-1999] = D32 Engine Bushing [RE] PFT-2012-December-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-071EZ MB-844289  Galant [1994-1999] = E52, E55 Eclipse [1994-1999] = D32 Insulator Engine [RE] TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM09-07E4 MR-244286  Galant [1994-1998] = E54, E55 Engine Bushing [RE] ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-07E4Z MR-244286  Galant [1994-1998] = E54, E55 Insulator Engine [RE] ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
	AM09-072EAZ MR-103817  Galant [1993-1998] = E56 Insulator Engine [RE, A/T] [2.4] TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
	AM09-D32EMZ MB-910663  Eclipse [1994-1999] = D32 Insulator Engine [RE, M/T] TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-07FA MB-844276</p>  <p>E54, E55</p> <p>Engine Bushing [FR, A/T]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-07FAZ MB-844276</p>  <p>Galant [92-98] = E52, E54, E55, E57</p> <p>Insulator Engine [FR, A/T]</p>	<p>RBI-OLD RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM09-07FM MB-844274</p>  <p>E54, E55, E12, E15, E33</p> <p>Engine Bushing [FR, M/T]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-07FMZ MB-844274</p>  <p>Galant [92-99] = E52, EE54, E55 / Eclipse [94-99] = D32</p> <p>Insulator Engine [FR, M/T]</p>	<p>RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
		<p>AM09-072FAZ MR-297707</p>  <p>Galant [93-98] = E56</p> <p>Insulator Engine [FR, A/T] [2,4]</p>	<p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-07LA MB-844258</p> <p>E54, E55</p> <p>Engine Bushing [LH, A/T]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-07LAZ MB-844258</p> <p>Galant [92-96] = E54, E55</p> <p>Insulator Engine [LH, A/T]</p>  <p>RBI-OLD RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM09-07LM MR-171324</p> <p>E54, E55</p> <p>Engine Bushing [LH, M/T]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-07LMZ MB-844255</p> <p>Galant [92-98] = E54, E55</p> <p>Insulator Engine [LH, A/T]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-071LZ MB-911271</p> <p>Galant [94-99] = E56 Eclipse [94-99] = D32</p> <p>Insulator Engine [LH]</p>  <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-D32LZ MB-910657</p> <p>Eclipse [94-99] = D32</p> <p>Insulator Engine [LH]</p>  <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-07RM MB-844267 E54, E55  Engine Bushing [RH, A/T, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-07RAZ MB-910201 Galant [1992-1996] = E52, E54, E55  Insulator Engine [RH, A/T]	RBI-2005-March-25 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AM09-07RMZ MB-844267 Galant [1992-1998] = E54, E55  Insulator Engine [RH, M/T]	RBI-2005-March-25 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AM09-07R4Z MB-844268 Galant [1992-1998] = E54, E55  Insulator Engine [RH, M/T]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AM09-071RZ MB-911272 Galant [94-99] = E56 Eclipse [94-99] = D32  Insulator Engine [RH, M/T]	Ashimori Product www.rbi.ae
		AM09-072RAZ MB-844271 Galant [1992-1998] = E54  Insulator Engine [RH, A/T] [2.0]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AM09-073RAZ MR-130007 Galant [1993-1998] = E56  Insulator Engine [RH, A/T] [2.4]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AM09-D32RZ MB-911274 Eclipse [1994-1999] = D32  Insulator Engine [RH]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AM09-D32RAZ MB-910661 Eclipse [1994-1999] = D32  Insulator Engine [RH, A/T]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-EA1FZ MR-198381</p> <p>Galant [96-2006] = EA1, EA2, EA4, EA5</p> <p>Insulator Engine (FR, A/T, M/T)</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AM09-EA2FZ MR-198565</p> <p>Galant [96-2006] = EA1, EA2, EA3, EA6.EA7</p> <p>Insulator Engine (FR, A/T, M/T)</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AM09-EA3FZ MR-333818</p> <p>Galant [96-2006] = EA3 [2.4] Eclipse [99-2005] = D52 [2.4]</p> <p>Insulator Engine (FR, A/T, M/T)</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AM09-EA8FMZ MR-272203</p> <p>Galant [99-2006] = EA8 [3.0] Eclipse [99-2005] = D52, D53 [2.4, 3.0]</p> <p>Insulator Engine (FR, M/T)</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-EA1EAZ MR-198568</p> <p>Galant [96-2006] = EA1, EA2, EA4, EA5</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AM09-EA3EAZ MR-272204</p> <p>Galant [96-2006] = EA3 [2.4] Eclipse [99-2005] = D52 [2.4]</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AM09-EA4EMZ MR-198383</p> <p>Galant [96-2006] = EA4, EA5</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AM09-EA8EAZ MR-272206</p> <p>Galant [99-2006] = EA8 [3.0] Eclipse [99-2005] = D53 [3.0]</p> <p>Insulator Engine [RE, A/T]</p> <p>HFC Product www.rbi.ae</p>
	<p>AM09-D52EMZ MR-272202</p> <p>Eclipse [99-2005] = D52 [2.4]</p> <p>Insulator Engine [RE, M/T]</p> <p>Ashimori Product www.rbi.ae</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	AM09-EA1LAZ MR-198386 Galant [96-2006] = EA1, EA2, E4, EA5 Insulator Engine [LH, A/T]	<small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com
	AM09-EA3LAZ MR-272218 Galant [96-2006] = EA3 [2.4] Eclipse [99-2005] = D52 [2.4] Insulator Engine [LH, A/T]	<small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com
	AM09-EA2LMZ MR-198557 Galant [96-2006] = EA1, EA2, E4, EA5, EA6 Insulator Engine [LH, M/T]	<small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com
	AM09-EA8LAZ MN-101073 Galant [99-2006] = EA8 [3.0] Eclipse [99-2005] = D53 [3.0] Insulator Engine [LH, A/T]	<small>HFC-2014-November-20 HFC Product, Ashimori Product</small> www.rbi.ae
	AM09-D52LMZ MR-272217 Eclipse [99-2005] = D52 [2.4] Insulator Engine [LH, M/T]	<small>HFC-2014-November-20 HFC Product, Ashimori Product</small> www.rbi.ae





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-EA1RZ MR-198543</p> <p>Galant [96-2006] = EA1, EA2</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-EA1R1Z MR-198542</p> <p>Galant [1996-2003] = EA1 [1.8], EA7 [2.0]</p> <p>Insulator Engine [RH]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-EA1R2Z MB-581406</p> <p>Mitsubishi Galant [1996-2003] = EA1A</p> <p>Insulator Engine [RH]</p> <p>HFC-2014-November-20 HFC Product www.rbi.ae</p>
	<p>AM09-EA3RZ MR-272199</p> <p>Galant [96-2006] = EA3 Eclipse [99-2005] = D52 [2.4]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-EA4RZ MR-198377</p> <p>Galant [96-2006] = EA4, EA5</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-EA8RZ MN-101072</p> <p>Galant [99-2006] = EA8 [3.0] Eclipse [99-2005] = D53 [3.0]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae</p>











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-DJ1F0 MR-589152   Galant [2004-2007] = DJ1, DK2 [4 Clinder] Eclipse [2004-2007] = D71, D81 [2.4] Engine Bushing [FR]	AM09-DJ1FZ MR-589152  Galant [2004-2010] = DJ1, DK2 [4 Clinder] Eclipse [2004-2007] = D71, D81 [2.4] Insulator Engine [FR]
	AM09-DJ1EZ MR-234837  Galant [2004-2010] = DJ1, DK2 [4 Clinder] Eclipse [2004-2007] = D71, D81 [2.4] Insulator Engine [RE]
	AM09-DJ1LZ MR-234838  Galant [2004-2010] = DJ1, DK2 [4 Clinder] Eclipse [2004-2007] = D71, D81 [2.4] Insulator Engine [LH]
	AM09-DJ1RZ MR-589843  Galant [2004-2010] = DJ1, DK2 [4 Clinder] Eclipse [2004-2007] = D71, D81 [2.4] Insulator Engine [RH]






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

mitsubishi

AM09-F07EZ AW-323834 <small>Ashimori Product</small> www.rbi.ae Diamante WG [1992-1996] = F07 Insulator Engine [RE]	AM09-F07RZ AW-329292 <small>Ashimori Product</small> www.rbi.ae Diamante WG [1992-1996] = F07 Insulator Engine [RH]
	AM09-F16RZ MR-244457 <small>TN-2010-December-26 Tenacity Product, Ashimori Product</small> shabbirh@eim.ae  Magna / Diamante [1992-2004] = F16A, F38A [3.0, 3.5] www.rbi.ae www.alafuae.com Insulator Engine [RH]
AM09-F36FZ MR-333029 <small>HFC-2014-November-20 HFC Product</small> www.rbi.ae Diamante Wagon [1999-2001] = F36 Insulator Engine [FR] [3.0]	AM09-F36F1Z MB-201691 <small>HFC-2014-November-20 HFC Product</small> www.rbi.ae Diamante Wagon / Sigma [1999-2001] = F36 Insulator Engine [FR]
AM09-F36F2Z MR-244458 <small>Ashimori Product</small> www.rbi.ae Diamante [1997-2003] MT Insulator Engine [FR]	AM09-F36F3Z MR-244847 <small>Ashimori Product</small> www.rbi.ae Diamante [1997-2003] AT Insulator Engine [FR]
AM09-F36EZ MR-197686 <small>Ashimori Product</small> www.rbi.ae Diamante Wagon [1999-2001] = F36 Insulator Engine [RE] [3.0]	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-DG1EAZ MR-102115 <div>ARP Product</div> www.rbi.ae Carisma [1995-2003] = DA Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A Insulator Engine [RE, A/T]	AM09-DG1EMZ MR-102114 <div>ARP Product</div> www.rbi.ae Carisma [1995-2003] = DA Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A Insulator Engine [RE, M/T]
AM09-DG1FAZ MR-333675 <div>ARP Product</div> www.rbi.ae Carisma [1995-2003] = DA Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A Insulator Engine [FR, A/T]	AM09-DG1FMZ MR-197132 <div>ARP Product</div> www.rbi.ae Carisma [1995-2003] = DA Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A Insulator Engine [FR, M/T]
AM09-DG1LAZ MR-131004 <div>ARP Product</div> www.rbi.ae Carisma [1995-2003] = DA Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A Insulator Engine [LH, A/T]	AM09-DG1LMZ MR-197068 <div>ARP Product</div> www.rbi.ae Carisma [1995-2003] = DA Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A Insulator Engine [LH, M/T]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

	<p>AM11-230 MB-307175</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Insulator Engine [RE]</p> <p>RBI-OLD RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM09-23E MB-309269</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Engine Bushing [RE, A/T, M/T]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-23EAZ MB-309694</p> <p>Lancer [1986-1992] = C11, C12</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM09-23EM MB-309695</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Engine Bushing [RE]</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-23EMZ MB-309695</p> <p>Lancer [1986-1992] = C11, C12</p> <p>Insulator Engine [RE, M/T]</p> <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM09-C52EAZ MB-436676</p>  <p>Lancer [1988-1992] = C52, C61, C62</p> <p>Insulator Engine [RE, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM09-C52EM MB-436675</p>  <p>Lancer [1988-1992] = C52, C53, C58, C62, C63, C64, C68</p> <p>Engine Bushing [RE, M/T]</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM09-C52EMZ MB-436675</p> <p>Lancer [1988-1992] = C52, C53, C58, C62, C63, C64, C68</p> <p>Insulator Engine [RE, M/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

mitsubishi

AM09-23F MB-309519  Lancer [1985-1992] = C11, C12 Engine Bushing [FR]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-23FZ MB-309512  Lancer [1985-1992] = C11, C12 Insulator Engine [FR]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM09-23FAZ MB-309995 Lancer [1985-1992] = C11, C12 Insulator Engine [FR, A/T]	ARD-2014-January-01 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM09-23FMZ MB-309996 Lancer [1985-1992] = C11, C12 Insulator Engine [FR, M/T]	ARD-2014-January-01 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-C52FA MB-436699 Lancer [1988-1992] = C52, C61, C62 Engine Bushing [FR, A/T]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-C52FAZ MB-436671 Lancer [1988-1992] = C52, C61, C62 Insulator Engine [FR, A/T]	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-C52FM MB-436670 Lancer [1988-1992] = C52, C53, C58, C62, C63, C64, C68 Engine Bushing [FR, M/T]	PFT-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-C52FMZ MB-436670 Lancer [1988-1992] = C52, C53, C58, C62, C63, C64, C68 Insulator Engine [FR, M/T]	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-240B MB-309998 C12 III BIG, CHAMP 3 Engine Bushing [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-240Z MB-309998  C12 III BIG, CHAMP 3 Insulator Engine [FR]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-23L MB-303046</p> <p>C11</p>  <p>Engine Bushing [LH]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM09-24L MB-436020</p> <p>Lancer [86-92] = C11, C12</p>  <p>Engine Bushing [LH]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM09-24LZ MB-309985</p> <p>Lancer [86-92] = C11, C12</p>  <p>Insulator Engine [LH]</p>
<p>AM09-24LM MB-436022</p> <p>Lancer [86-92] = C11, C12</p>  <p>Engine Bushing [LH]</p>	<p>PFT-2013-October-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM09-24LMZ MB-436022</p> <p>Lancer [86-92] = C11, C12</p> <p>Insulator Engine [LH]</p>
	<p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM09-C53LZ MB-581408</p> <p>Lancer [88-92] = C53, C58, C63, C68</p> <p>Insulator Engine [LH]</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-23R MB-309366</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Engine Bushing [RH]</p>	<p>AM09-23RAZ MB-309990</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Insulator Engine [RH]</p>
<p>AM09-24R MB-436410</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Engine Bushing [RH]</p>	
<p>AM09-23R10 MB-436021</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Engine Bushing [RH]</p>	<p>AM09-23R1Z MB-436868</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Insulator Engine [RH]</p>
	<p>AM09-23R2Z MB-581024</p>  <p>Lancer [1986-1992] = C11, C12</p> <p>Insulator Engine [RH]</p>
	<p>AM09-C52RAZ MB-581029</p>  <p>Lancer [88-92] = C53, C61, C62</p> <p>Insulator Engine [RH, A/T]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-26EA MB-870262 CB1, CB2, CK2, CK5 Engine Bushing [RE, A/T]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-26EAZ MB-691238 Lancer [91-2002] = CA2, CA4, CA5, CB1, CB2, CB3, CB4, CB5, CB8 Insulator Engine [RE, A/T]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM09-26EM MB-891564 CB1, CB2, CK2, CK5 Engine Bushing [RE, M/T]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-26EMZ MB-870012 Lancer [91-2002] = CA1, CA2, CA4, CA5, CB1, CB2, CB3, CB4, CB5, CB8, CD4, CJ1, CJ2, CJ4, CK1, CK2, C Insulator Engine [RE, M/T]	 RBI-OLD RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM09-29EA MR-223674 Lancer [92-2003] = CK1, CK2, CK4, CK5, CJ2, CJ4, CJ5 Engine Bushing [RE, A/T]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-29EAZ MR-223674 Lancer [92-2003] = CK1, CK2, CK4, CK5, CJ2, CJ4, CJ5 Insulator Engine [RE, A/T]	 RBI-2009-May-12 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM09-29EM MR-297257 Lancer [95-2003] = CK1, CK2, CK4, CK5, CJ1, CJ2, CJ4, CJ5 Engine Bushing [RE, M/T]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM09-29EMZ MR-297256 Lancer [95-2003] = CK1, CK2, CK4, CK5, CJ1, CJ2, CJ4, CJ5 Insulator Engine [RE, M/T]	 RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-CS3EA0 MR-554541</p>  <p>Lancer [2001-2006] = CS3, CS5, CV2, CV4, CV5</p> <p>Engine Bushing [RE, A/T]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-CS3EAZ MR-554541</p>  <p>Lancer [2001-2006] = CS3, CS5, CV2, CV4, CV5</p> <p>Insulator Engine [RE, A/T]</p> <p>RBI-2009-July-16 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM09-CS3EM0 MR-519400</p>  <p>Lancer [2000-2007] = CS1, CS2, CS3, CS5</p> <p>Engine Bushing [RE, M/T]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-CS3EMZ MR-519400</p>  <p>Lancer [2000-2007] = CS1, CS2, CS3, CS5</p> <p>Insulator Engine [RE, M/T]</p> <p>RBI-2009-July-16 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-CV2EZ MR-995086</p>  <p>Outlander / Airtrk / Mivec [2001-2006] = CV2</p> <p>Insulator Engine [RE] [2.0] [4WD]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-CV4E1Z MN-100335</p>  <p>Outlander / Airtrk / Mivec [2003-2006] = CV4, CV5</p> <p>Insulator Engine [RE] [2.4] [4WD]</p> <p>TN-2013-July-16 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-CV4E2Z MR-961162</p>  <p>Outlander / Airtrk / Mivec [2001-2003] = CV4, CV5</p> <p>Insulator Engine [RE] [2.4] [4WD]</p> <p>ASH-2014-May-15 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-26FA MB-691236</p> <p>CB1, CB2</p> <p>Engine Bushing [FR, A/T]</p>	<p>AM09-26FAZ MB-691236</p> <p>Lancer [91-2002] = CA2, CA4, CA5, CB1, CB2, CB3, CB4, CB5</p> <p>Insulator Engine [FR, A/T]</p>
<p>AM09-26FM MB-891563</p> <p>CB1, CB2</p> <p>Engine Bushing [FR, M/T]</p>	<p>AM09-26FMZ MB-691235</p> <p>Lancer [91-2002] = CA1, CA2, CA4, CA5, CB1, CB2, CB3, CB4, CB5, CD4, CD5</p> <p>Insulator Engine [FR, M/T]</p>
	<p>AM09-261FAZ MB-844840</p> <p>Lancer [92-1996] = CA2, CB1, CB2, CB5</p> <p>Insulator Engine [FR, A/T]</p>
	<p>AM09-29FAZ MR-131296</p> <p>Lancer [98-2002] = CK5, CJ2, CJ5</p> <p>Insulator Engine [FR, A/T]</p>
	<p>AM09-29FMZ MR-197537</p> <p>Lancer [95-2003] = CK1, CK2, CK4, CK5, CJ1, CJ2, CJ4, CJ5</p> <p>Insulator Engine [FR, M/T]</p>
	<p>AM09-291FMZ MR-197541</p> <p>Lancer [95-2003] = CK1, CK2, CK4, CJ1, CJ2, CJ4</p> <p>Insulator Engine [FR, M/T]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM09-28FA MB-309486  CK2, CK5, CS3, CS5 Engine Bushing [FR, A/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-28FAZ MR-333578  Lancer [95-2002] = CK2, CK5, CS3 Insulator Engine [FR, A/T]	RBI-2005-August-19 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-28FM MR-197519  CK2, CK5, CS3, CS5 Engine Bushing [FR, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-28FMZ MR-333577  Lancer [95-2002] = CK1, CK2, CK4, CK5, CS3, CJ1, CJ2, CJ4, CJ5 Insulator Engine [FR, M/T]	RBI-2005-August-19 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-CS3FM0 MR-554244  CS3 Engine Bushing [FR, M/T]	RBI-2005-December-03 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-CS3FMZ MR-554244  Lancer [2000-2006] = CS1, CS2, CS3, CS6 Insulator Engine [FR, M/T]	RBI-2005-December-03 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-CV2F MR-961324  Outlander / Airtrk / Mivec [2001-2006] = CV2 Engine Bushing	Perfect Product www.rbi.ae 	AM09-CV2FZ MR-961324  Outlander / Airtrk / Mivec [2001-2006] = CV2 Insulator Engine [FR, M/T] [2.0] [4WD]	PFT-2014-May-25 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM09-CV4FZ MN-100289  Outlander / Airtrk / Mivec [2001-2006] = CV2, CV4, CV5 Insulator Engine [FR, A/T] [2.0, 2.4] [2WD, 4WD]	TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM09-CV5FZ MN-100158  Outlander / Airtrk / Mivec [2003-2006] = CV5 Insulator Engine [FR, M/T] [2.4] [4WD]	TN-2010-December-26 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM09-26LR MB-871602  CB1, CB2 Engine Bushing [LH, RH, A/T, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-26LZ MB-691230  Lancer [91-2002] = CA1, CA2, CB1, CB2 [1.5] Insulator Engine [LH, A/T, M/T]	RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM09-264LZ MB-691231  Lancer [91-2002] = CA4, CA5, CB3, CB4 [1.6], CB5, CD4 Insulator Engine [LH]	RBI-2005-December-03 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-28LR MR-244836  Lancer [95-2002] = CK2, CK5 Engine Bushing [LH, RH]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-28LAZ MR-131308  Lancer [95-2002] = CK2, CK4, CK5, CJ2, CJ4, CJ5 Insulator Engine [LH, A/T]	PFT-2012-June-26 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM09-28L3Z MR-244826  Lancer [95-2002] = CK2, CK4, CK5 Insulator Engine [LH, A/T]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM09-28L1Z MR-272063  Lancer [95-2002] = CK1, CK2, CJ1, CJ2 [1.3, 1.5P] Insulator Engine [LH, A/T]	PFT-2014-May-25 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-28L0 MR-244826  Lancer [95-2002] = CK2, CK4, CK5, CJ2, CJ4, CJ5 Engine Bushing [LH]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-28L2Z MR-491885  Lancer [95-2002] = CK2, CK4, CK5, CJ2, CJ4, CJ5 Insulator Engine [LH]	ASH-2012-December-25 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM09-CS3LM0 MR-403861  Lancer [95-2002] = CS3 Engine Bushing [LH, A/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM09-CS3LMZ MR-491557  Lancer [95-2002] = CS1, CS2, CS3, CS6, CS7, CS9, CK4, CK5, CJ4, CJ5 Insulator Engine [LH, M/T]	RBI-2009-December-12 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM09-CS3LA0 MR-491527  CS3, CS5 Engine Bushing [LH, A/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM09-CS3LAZ MR-403670  Lancer [2000-2006] = CS2, CS3 Insulator Engine [LH, A/T]	RBI-2009-July-23 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM09-CS5LAZ MR-491555  Lancer [2000-2003] = CS2, CS5 Insulator Engine [LH, A/T]	RBI-2009-July-16 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM09-CS3L1Z MR-131307  Lancer [95-2002] = CS1, CS2, CS3, CS6, CS7, CS9, CK4, CK5, CJ4, CJ5 Insulator Engine [LH]	TN-2013-July-16 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM09-CS3L3Z MR-403065  CS3 Insulator Engine [LH]	ASH-2013-July-10 HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
		AM09-CS3L4Z MR-297984  CS3 Insulator Engine [LH]	TN-2012-May-14 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM09-CS3L5Z MR-961540  Dion [2000-2004] = CR5W, CR6W, CR9W Lancer [2000-2009] = CS1A, CS3A Insulator Engine [LH, A/T]	Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM09-CV4LAZ MR-961709  Outlander / Airtrk / Mivec [2001-2006] = CV2, CV4, CV5 Insulator Engine [LH, A/T] [2.0, 2.4] [4WD]	TN-2013-November-20 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM09-CV5LMZ MN-100014  Outlander / Airtrk / Mivec [2001-2006] = CV5 Insulator Engine [LH, M/T] [2.4] [4WD]	HFC-2014-November-20 HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-26RAZ MB-691253</p> <p>Lancer [1991-2002] = CA2, CB1, CB2</p> <p>Insulator Engine [RH, A/T]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AM09-26RMZ MB-691251</p> <p>Lancer [1991-2002] = CA1, CA2, CA4, CA5, CB1, CB2, CB3, CB4, CB5</p> <p>Insulator Engine [RH, M/T]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AM09-264RAZ MB-691255</p> <p>Lancer [1991-2002] = CA4, CA5, CB4, CB5</p> <p>Insulator Engine [RH, A/T]</p>	<p>TN-2010-December-01 Tenacity Product, HFC Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AM09-29RZ MR-130551</p> <p>Lancer [1995-2002] = CK4, CK5, CJ4, CJ5</p> <p>Insulator Engine [RH, A/T, M/T]</p>	<p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AM09-29R2Z MR-223925</p> <p>Lancer [1995-2002] = CK4, CK5, CJ4, CJ5</p> <p>Insulator Engine [RH]</p>	<p>PFT-2013-April-30 Perfect Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AM09-29R3Z MR-272780</p> <p>Lancer [1995-2002] = CK4, CK5</p> <p>Insulator Engine [RH, A/T, M/T]</p>	<p>ARD-2014-January-01 ARP Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p> 
	<p>AM09-29R4Z MB-603100</p> <p>Mitsubishi Lancer, Mirage [1995-2000] = CK Mitsubishi Lancer, Mirage [1995-2003] = CJ</p> <p>Insulator Engine [RH]</p>	<p>HFC-2014-November-20 HFC Product</p> <p>www.rbi.ae</p>







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-CSK5R0 MR-223881</p> <p>Lancer [1997] = CK5</p> <p>Engine Bushing [RH]</p>	<p>PFT-2013-October-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AM09-CS5RAZ MR-491479</p> <p>Lancer [2001-2006] = CS1, CS2, CS3, CS5, CS6, CQ2 Dion [2002] = CR5, CR6</p> <p>Insulator Engine [RH, A/T]</p>
<p>AM09-CV4RZ MR-961111</p> <p>Outlander / Airtrek / Mivec [2001-2006] = CV2, CV4, CV5</p> <p>Insulator Engine [RH, A/T] [2.0, 2.4] [4WD]</p>	<p>AM09-CV2RZ MR-491599</p> <p>Outlander / Airtrek / Mivec [2001-2006] = CV2, CV4, CV5</p> <p>Insulator Engine [RH, A/T] [2.0, 2.4] [4WD]</p>











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-L008F0 MN-184058</p>  <p>Lancer [2007-2012] = CY2, CY4 [1.5, 2.0]</p> <p>Engine Bushing [FR, A/T, M/T]</p> <p>RBI-2013-October-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-L008FZ MN-184355</p>  <p>Lancer [2007-2012] = CY2, CY4 [1.5, 2.0]</p> <p>Insulator Engine [FR, A/T, M/T]</p> <p>RBI-2013-October-14 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-CW5FZ MN-101386</p>  <p>Outlander / Airtrek / Mivec [2006-2009] = CW5, CW6</p> <p>Insulator Engine [FR, A/T, M/T] [2.4, 3.0] [2WD, 4WD]</p> <p>TN-2011-July-23 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM09-L008E0 MN-184060</p>  <p>Lancer [2007-2012] = CY2, CY4 [1.5, 2.0] OUTLANDER [2007-2012] = CW6 [3.0]</p> <p>Engine Bushing [RE, A/T, M/T]</p> <p>RBI-2013-March-01 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-L008EZ MN-101387</p>  <p>Lancer [2007-2012] = CY2, CY4 [1.5, 2.0] OUTLANDER [2007-2012] = CW6 [3.0]</p> <p>Insulator Engine [RE, A/T, M/T]</p> <p>TN-2011-July-23 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-CW5EZ MN-101573</p>  <p>Outlander / Airtrek / Mivec [2006-2009] = CW5, CW6</p> <p>Insulator Engine [RE, A/T, M/T] [2.4, 3.0] [4WD]</p> <p>HFC-2014-November-20 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-L008R2Z MN-101441</p> <p></p> <p>Lancer [2007-2012] = CY4 [2.0]</p> <p>Insulator Engine [RH, A/T, M/T] [2WD, 4WD]</p> <p>RBI-2013-December-16 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-L008R2ZZ MN-184372</p> <p>Lancer [2007-2012] = CY4 [2.0] Outlander / Airtrk / Mivec [2006-2009] = CW5 [2.4]</p> <p>Insulator Engine [RH, A/T, M/T] [2WD, 4WD]</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM09-CW6RZZ MN-184296</p> <p>Outlander / Airtrk / Mivec [2006-2009] = CW6</p> <p>Insulator Engine [RH] [3.0] [4WD]</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

	<p>AM09-L008LA1Z MN-184299</p> <p>HFC Product</p> <p>www.rbi.ae</p> <p>Lancer [2007-2012] = CY2 [1.5]</p> <p>Insulator Engine [LH, A/T]</p>
	<p>AM09-L008LA2Z MN-101574</p> <p>RBI-2013-December-16 RBI Product, Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Lancer [2007-2012] = CY4 [2.0] OUTLANDER [2007-2012] = CW5 [2.4]</p> <p>Insulator Engine [LH, A/T]</p>
	<p>AM09-L008LA2ZZ MN-101574</p> <p>ARP Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Lancer [2007-2012] = CY4 [2.0] OUTLANDER [2007-2012] = CW5 [2.4]</p> <p>Insulator Engine [LH, A/T] [2WD]</p>
	<p>AM09-CW6LZ MN-184301</p> <p>ASH-2013-July-10 HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Outlander / Airtrk / Mivec [2006-2009] = CW6</p> <p>Insulator Engine [LH] [3.0] [4WD]</p>
	<p>AM09-CW6LZZ MN-184301</p> <p>ARP Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Outlander / Airtrk / Mivec [2006-2009] = CW6</p> <p>Insulator Engine [LH] [3.0] [4WD]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM09-VAR99E1Z CW-609731</p> <p>Mitsubishi VARICA 1200 [1999-2004]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM09-VAR99F1Z</p> <p>Mitsubishi VARICA 1200 [1999-2004]</p> <p>Insulator Engine</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-VAR99F2Z</p> <p>Mitsubishi VARICA 1100 [1988-1993]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM09-VAR99L1Z</p> <p>Mitsubishi VARICA 1100 [1997]</p> <p>Insulator Engine</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-VAR99R1Z MB-691508</p> <p>Mitsubishi VARICA 1100 [1997]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM09-TOW00R1Z MB-581252</p> <p>Mitsubishi TOWNY</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM09-TOW00R2Z MB-436953</p> <p>Mitsubishi TOWNY [1996]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01








MITSUBISHI

AM10-010 MB-006759  L200 / Triton = K01T [1.6P] ..4G32 A121  Insulator Engine [FR, LH, RH]	AM11-010 MB-006602  A121, A123, GTO  Insulator Engine [RE]
	AM11-020 MB-180256  A156  Insulator Engine [RE]
	AM11-210 MA-152606  A53  Insulator Engine [RE]
AM10-220 MA-152605  A72  Insulator Engine	
AM11-221 MA-180520  A72  Insulator Engine [RE]	AM11-222 MA-180522  A72 5 SPEED  Insulator Engine [RE]



MITSUBISHI

Revision : 2014-November-01

AM10-T120F ME-000030  Canter = T210 Lancer, Colt = T120 Insulator Engine [FR]	PFT-2013-August-20 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM10-T120EZ MT-372604  Canter = T210 Lancer, Colt = T120 Insulator Engine [RE]	ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
	PFT-2013-June-25 Perfect Product shabbirh@eim.ae  Canter = T210 Insulator Engine [RE]	AM10-T121EZ ME-000021  Canter = T210 Insulator Engine [RE]	PFT-2013-June-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM10-C010 ME-011832  Canter = FE111, FE444 Insulator Engine [FR]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM11-C010E ME-011815  Canter = FE111, FE444 Insulator Engine [RE]	ARD-2014-January-01 Perfect Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM10-C011F ME-011807  Canter = FE111, FE444 Insulator Engine [FR]	PFT-2012-June-26 Perfect Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM10-FB511E00 ME-201952  Canter = FB511, FB70A, FB71A [4M40, 4G63] Insulator Engine [RE, LH, RH]	PFT-2012-March-28 Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM10-FC633E00 MC-122542  Canter = FC633 [4G64] Insulator Engine [RE, LH, RH]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM10-FE639F00 ME-017631  Canter = FE639..4D35 Insulator Engine	ARD-2013-August-01 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM10-C012F ME-018993  Canter = 3T [N] ..4D34 Insulator Engine [FR]	ARD-2013-August-01 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM10-C013F MK-332290  Canter [1999-2006] = FB511, FB70A, FB71A Insulator Engine [FR, RH, LH] [4M40]	Ashimori Product www.rbi.ae		



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AR10-FU218 ME-061703  Mitsubishi Fuso [1980] = FV313 Insulator Engine [FR, LH, RH]	AR10-FU218EZ ME-062600  Mitsubishi Fuso [1980] = FV313 Insulator Engine [RE]
AR10-FU215 ME-031962  Mitsubishi Fuso = 215, FN527 Insulator Engine [FR, LH, RH]	AR11-FU527L ME-030948  Mitsubishi Fuso = FN527 Insulator Engine [RE, LH]
AR11-FU527R ME-030949  Mitsubishi Fuso = FN527 Insulator Engine [RE, RH]	AR11-FU528L ME-030970  Mitsubishi Fuso = FN527 Turbo Insulator Engine [RE, LH]
AR11-FU528R ME-030971  Mitsubishi Fuso = FN527 Turbo Insulator Engine [RE, RH]	AR11-FU627L ME-074785  Mitsubishi Fuso = FN627, FN628 Insulator Engine [RE, LH]
AR11-FU215 ME-031365  Mitsubishi Fuso = 215 Insulator Engine [RE, LH, RH]	

Revision : 2014-November-01

MITSUBISHI

AM10-42L MB-006605  L200 / Triton = K14, K64 Stada [2.5] Insulator Engine [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM10-42LZ MB-436773  L200 / Triton [1989-2003] = K22, K32, K33, K35 Insulator Engine [FR, LH]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM10-42R MB-007023  L200 / Triton = K14, K64 Stada [2.5] L200D, GTO Insulator Engine [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM10-T0204 MR-995005  L200 / Triton [2001] [2WD, 4WD] Insulator Engine [FR, LH, RH]	RBI-2007-August-20 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM10-T0204Z MR-995005  L200 / Triton [2001] [2WD, 4WD] Insulator Engine [FR, LH, RH] [With Bracket]	ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM11-420 MB-436365  L200 / Triton [2001] [2WD] = K14 Mitsubishi L200 2.0 2WD [1989-1992] Insulator Engine [RE, A/T]	RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM11-422 MR-267459  L200 / Triton Insulator Engine [RE]	TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM11-T04A MR-992714  Mitsubishi Triton [2006] = KB9T L200 / Triton [2001] Insulator Engine [RE, A/T, 4WD]	RBI-2008-March-11 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM11-T04M MR-992717  Mitsubishi Triton [2006] = KB9T L200 / Triton [2001] Insulator Engine [RE, M/T, 4WD]	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM11-T02M MR-995006  L200 / Triton [2001] [2WD] Insulator Engine [RE, M/T]	ARD-2014-January-01 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM11-T040 MR-992713  Mitsubishi Triton [2006] = KB9T Insulator Engine [RE, A/T, 4WD]	RBI-2013-October-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AM11-KB4TS 3204A005  L200 [2005] = KB4T.. [4WD] Nativa [2008] = KH8W Pajero Sport [2008] = KH8W Pajero, Montero Spo Insulator Engine	PFT-2012-March-28 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 

MITSUBISHI

Revision : 2014-November-01

<p>AM10-62L MB-436833</p> <p>L300 = P15 [2WD]</p> <p>Insulator Engine [FR, LH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM10-62R MB-436832</p> <p>L300 = P15 [2WD]</p> <p>Insulator Engine [FR, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM10-62FZ MB-007038</p> <p>L300 [1984-1994] = P01, P02, P06, P12, P16 [2WD]</p> <p>Insulator Engine [FR, LH, RH]</p>  <p>TN-2011-March-21 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM10-621LZ MB-581191</p> <p>L300 [1992-1999] = P25, P45 [4WD]</p> <p>Insulator Engine [FR, LH]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM10-621RZ MB-581192</p> <p>L300 [1992-1999] = P25, P45 [4WD]</p> <p>Insulator Engine [FR, RH]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM11-62Y MB-436036</p> <p>L300 = P15</p> <p>Engine Bushing [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM11-62YZ MB-436041</p> <p>L300 [1986-1999] = P05, P13, P15</p> <p>Insulator Engine [RE]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM10-62RMZ MB-436342</p> <p>L300 [86-99] = P02, P03, P04, P12, P13, P14</p> <p>Insulator Engine [RH, M/T]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM10-PA3FLR MR-112001 L400 [1995] = PA3, PA4, PB3, PB4, PC3, PD3, PD4 [2WD, 4WD] Insulator Engine [FR, LH, RH]	 <small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.alafuae.com</small>	AM10-PD3ELR MR-112168 L400 [1995] = PD3, PD4, PD5 [4WD] Insulator Engine [RE, LH, RH]	 <small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</small>
AM10-PA3EAZ MR-112164 L400 [1995] = PA3, PA4, PA5, PB4, PB6 [2WD] Insulator Engine [RE, A/T]	 <small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.alafuae.com</small>	AM10-PA3EMZ MR-112163 L400 [1995] = PA3, PA4, PA5, PB4, PB6, PC3, PC5 [2WD] Insulator Engine [RE, M/T]	 <small>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.alafuae.com</small>















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<div>AM10-440</div> <div>MR-151375</div> <div>K64 [2.8]</div> <div>Insulator Engine</div>	<div><div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>		
<div>AM11-440</div> <div>MR-133061</div> <div>K64, Strada [2.5]</div> <div>Insulator Engine [RE]</div>	<div><div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>	<div>AM11-441</div> <div>MR-133062</div> <div>K64, Strada [2.8]</div> <div>Insulator Engine [RE]</div>	<div><div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>
<div>AM11-4X01B</div> <div>MR-133073</div> <div>Pajero = K77 [4WD], Strada</div> <div>Insulator Engine [RE, Big]</div>	<div><div><div>RBI-2005-August-19</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>	<div>AM11-4X01S</div> <div>MR-353470</div> <div>Strada, K77 [4WD]</div> <div>Insulator Engine [RE, Small]</div>	<div><div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>Tenacity Product, HFC Product, Ashimori Product</div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>
<div>AM11-4X03B</div> <div>MB-581627</div> <div>Strada / L200 [1987-1993] = K25</div> <div>Insulator Engine [RE, A/T] [4WD] [2.4]</div>	<div><div><div>Ashimori Product</div><div>www.rbi.ae</div></div><div></div></div>	<div>AM11-4X04B</div> <div>MR-267912</div> <div>Pajero Sport / Montero Sport / Nativa / Challenger / L200 [1999-2006] = K77 [2.8 DIE], K97 [2.8]</div> <div>Insulator Engine [RE, A/T]</div>	<div><div><div>ASH-2013-November-1</div><div>Ashimori Product</div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>
<div>AM11-4X02B</div> <div>MR-133074</div> <div>Pajero = K77 [4WD], Strada</div> <div>Insulator Engine [RE, Big]</div>	<div><div><div>ARP Product</div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>		
<div>AM11-4X05B</div> <div>MR-133072</div> <div>L200 [1997-2005] = K74 [2.5 DIE]</div> <div>Insulator Engine [RE, A/T]</div>	<div><div><div>HFC-2014-November-20</div><div>HFC Product, Ashimori Product</div><div>www.rbi.ae</div></div><div></div></div>	<div>AM11-4X06B</div> <div>MR-133079</div> <div>L200 / Pajero Sport / Nativa / Montero Sport / Challenger [1996-2005] = K76, K96 [3.0]</div> <div>Insulator Engine [RE, M/T]</div>	<div><div><div>HFC-2014-November-2</div><div>HFC Product</div><div>www.rbi.ae</div></div><div></div></div>













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

<p>AM11-L047S MB-260676</p>  <p>Pajero [1986-1989] = L047 L200</p> <p>Insulator Engine [RE, Side]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM11-L047SZ MB-260676</p>  <p>Pajero [1986-1989] = L047 L200</p> <p>Insulator Engine [RE, Side] [With Inner]</p>	<p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM11-L047B MB-260670</p>  <p>Pajero [1986-1989] = L047</p> <p>Insulator Engine [RE]</p>	<p>PFT-2012-March-28 Perfect Product, ARD Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 		
<p>AM10-AL146E MA-581620</p> <p>Pajero [1984-1995] = L146</p> <p>Insulator Engine [RE, A/T]</p>	<p>Ashimori Product www.rbi.ae</p>	<p>AM10-VAR99E2Z MB-006809</p>  <p>L300 [1986-] = L036, L063 Mitsubishi VARICA 1100 [1988-1993]</p> <p>Insulator Engine [RE]</p>	<p>TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 














AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM11-V32B MB-691282</p> <p>Pajero / Montero [1991-2003] = V13, V23, V32, V33, V43, V44</p> <p>Insulator Engine [RE, A/T] [2.5 Diesel] [2.6, 3.0 Petrol]</p>   <p>ARD-2014-January-01 Perfect Product, ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM11-V32M MB-691280</p> <p>Pajero / Montero [1991-2003] = V11, V12, V13, V14, V23, V31, V32, V33, V34, V43</p> <p>Insulator Engine [RE, M/T] [2.5 Diesel] [2.4, 2.6, 3.0 Petrol]</p>   <p>ARD-2013-May-01 ARD Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM11-V32E3 MB-561456</p> <p>Pajero</p> <p>Insulator Engine [RE]</p>   <p>ARD-2014-January-01 Perfect Product, ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM11-V32E4 MB-691281</p> <p>Pajero [1990-1993] = V24, V44</p> <p>Insulator Engine [RE] [2.5 Diesel]</p>   <p>ARD-2013-May-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM11-V32E5 MR-113295</p> <p>Pajero [1997-2003] = V23, V33, V43 [3.0]</p> <p>Insulator Engine [RE]</p>  <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

<p>AM10-V26FL MR-210032</p> <p>Pajero / Montero [1991-2003] = V23, V25, V26, V33, V43, V45, V46</p> <p>Insulator Engine [FR, LH, RH] [3.0, 3.5 Petrol] [2.8 Diesel]</p> <p>ARD-2014-January-01 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM10-V450 MR-132720</p> <p>Pajero / Montero [1991-2003] = V25, V26, V36, V45, V46 [3.5P, 2.8D]</p> <p>Insulator Engine [FR, A/T] [With Two Bolt]</p> <p>RBI-2012-August-06 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM10-V26FR MR-210033</p> <p>Pajero / Montero [1991-2003] = V26, V36, V46</p> <p>Insulator Engine [FR, RH] [2.8 Diesel]</p> <p>ASH-2013-July-10 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
	<p>AM10-V43EZ MR-951304</p> <p>Pajero / Montero [1991-2003] = V25, V33, V43, V45, V46</p> <p>Insulator Engine [RE, A/T] [2.8 Diesel] [3.0, 3.5 Petrol]</p> <p>TN-2011-July-23 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM10-V45E0 MB-922857</p> <p>Pajero / Montero [1993-2000] = V25, V26, V45, V46, V55</p> <p>Engine Bushing [RE]</p> <p>ASH-2013-November-15 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM10-V45EZ MR-133663</p> <p>Pajero / Montero [1993-2000] = V25, V26, V45, V46, V55</p> <p>Insulator Engine [RE]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM10-V46EZ MR-267949</p> <p>Pajero Sport / Nativia [1994-2005] = V26, V46 L200 / Pajero / Montero [1997-2005] = K77, K97</p> <p>Insulator Engine [RE] [2.8 Petrol] [2.8 Diesel]</p> <p>Ashimori Product www.rbi.ae</p>	
<p>AM10-V44EZ MB-951304</p> <p>Mitsubishi Pajero II [1991-2004] = V14W-V55W</p> <p>Insulator Engine [RE, A/T] [2.8 Diesel] [3.0, 3.5 Petrol]</p> <p>TN-2014-August-30 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	



MITSUBISHI

Revision : 2014-November-01

<p>AM10-V75FLR MR-510056</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mitsubishi Pajero III Montero [2000-2006] = V63, V65, V67, V73, V75, V77</p> <p>Insulator Engine [FR, LH, RH]</p>	
<p>AM10-V75ERMZ MR-198012</p> <p>HFC-2014-November-20 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero / Montero [2003-2011] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V86, V93,</p> <p>Insulator Engine [RE, RH, M/T]</p>	<p>AM10-V75ELMZ MR-198013</p> <p>HFC-2014-November-20 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero / Montero [2003-2011] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V86, V93,</p> <p>Insulator Engine [RE, LH, M/T]</p>
	<p>AM10-V75EA1Z MR-448194</p> <p>HFC-2014-November-20 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero / Montero [2003-2011] = V63, V65, V67, V73, V75, V77, V83, V87, V93, V97</p> <p>Insulator Engine [RE, A/T] [3.0, 3.5, 3.8]</p>
<p>AM10-V75H001 MR-132701</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W L200 [1996-2007] = K6#, K7# Pajero III Montero [2000-2006]</p> <p>Insulator Engine [Head Rubber] [RE, UPPER]</p>	<p>AM10-V75H002 MR-132702</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W L200 [1996-2007] = K6#, K7# Pajero III Montero [2000-2006]</p> <p>Insulator Engine [Head Rubber] [FR, LOWER]</p>
<p>AM10-V95FLR MR-554231</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mitsubishi Pajero IV Montero [2006] = V83, V87, V93, V97</p> <p>Insulator Engine [FR, A/T, M/T]</p>	
<p>AM10-K96E00 MR-448559</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero, Montero Sport Challenger [1996-2006] = K94W, K99W</p> <p>Insulator Engine [RE, A/T]</p>	<p>AM10-K96F00 MR-210867</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Nativa [1997-2007] = K94W Pajero, Montero Sport Challenger [1996-2006] = K94W, K99W</p> <p>Insulator Engine [FR, A/T, 6G72]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM10-H51FZ MR-150341  Pajero JR / Mini [1995-1998] = H51, H53, H56, H57, H58 Insulator Engine [FR]	AM10-H51EZ MR-150222  Pajero JR / Mini [1995-1998] = H51, H53, H56, H57, H58 Insulator Engine [RE]
AM10-H76E0 MR-319774  Pajero IO [1998-2004] = H65, H66, H76, H77 Engine Bushing [RE, A/T] [1.6, 1.8, 2.0]	AM10-H76FLR MR-319769  Pajero IO [1998-2004] = H65, H66, H76, H77 Insulator Engine [FR, LH, RH, A/T, M/T] [1.6, 1.8]
AM10-H76E0 MR-319774  Pajero IO [1998-2004] = H65, H66, H76, H77 Engine Bushing [RE, A/T] [1.6, 1.8, 2.0]	AM10-H76EZ MR-319774  Pajero IO [1998-2004] = H65, H66, H76, H77 Insulator Engine [RE, A/T] [1.6, 1.8, 2.0] [With Two Bush]
AM10-H76FL MR-510312  Pajero IO [2001-2005] = H67, H76, H77 Insulator Engine [FR, LH] [1.8, 2.0]	AM10-H76FR MR-510313  Pajero IO [2001-2005] = H67, H76, H77 Insulator Engine [FR, RH] [1.8, 2.0]
AM10-H76E1Z MR-448432  Pajero IO [1998-2000] = H67, H66, H76 Insulator Engine [RE, A/T] [1.6, 1.8]	AM10-H76E2Z MR-448440  Pajero IO [1998-2000] = H66, H76 Insulator Engine [RE, M/T] [1.8]
AM10-H76E3Z MR-491526  Pajero IO [1998-2000] = H65, H76 Insulator Engine [RE, M/T] [1.6]	AM10-H76E3Z MR-491526  Pajero IO [1998-2000] = H65, H76 Insulator Engine [RE, M/T] [1.6]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM13-04F MB-002000</p>  <p>Galant = A121, A173</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-02F MB-109110</p>  <p>Galant = A156</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>AM13-03F MB-109866</p>  <p>Galant = A161</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p>AM13-12F MB-303384</p>  <p>Galant [1983-1990] = E11, E12, E13, E14, E15, E17, E19</p> <p>Shock Absorber Mounting Rubber [FR, LH, RH] [1.6, 1.8, 2.0]</p>	<p>RBI-OLD RBI Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-06F MB-518670</p>  <p>Galant [1989-1994] = E31, E32, E33, E34, E37, E38, E39</p> <p>Shock Absorber Mounting [FR, LH, RH] [1.6, 1.8, 2.0] [2WD, 4WD]</p>	<p>RBI-2007-October-29 RBI Product, Tenacity Product, HFC Product, Ashimori Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-07F MB-864792</p>  <p>Galant [1992-1996] = E52, E53, E54, E57, E64, E72, E74, E77, E84, E55, E56, EA1</p> <p>Shock Absorber Mounting [FR, LH, RH] [1.8, 2.0, 2.4, Diesel] [2WD, 4WD]</p>	<p>AM13-07E00 MB-910186</p>  <p>Galant [1992-1996] = E52, E53, E54, E57, E64, E72, E74, E77, E84, E55, E56, EA1</p> <p>Shock Absorber Mounting [RE, LH, RH] [1.8, 2.0, 2.4, Diesel] [2WD, 4WD]</p>
<p>AM13-D21F00 MB-518141</p>  <p>Eclipse [1989-1994] = D21, D22, D27</p> <p>Shock Absorber Mounting [FR, LH, RH] [1.8, 2.0] [2WD, 4WD]</p>	<p>TN-2010-December-26 Tenacity Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-12EB MB-338618</p>  <p>Galant [1983-1996] = E12, E15, E33, E54</p> <p>Shock Absorber Mounting Rubber [RE, Big]</p>	<p>AM13-12ES MB-242358</p>  <p>Galant [1983-1996] = E12, E15, E33, E54</p> <p>Shock Absorber Mounting Rubber [RE, Small]</p>










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM13-EA1F00 MR-103156</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae  www.alafuae.com</p> <p>Galant [1998-2004] = EA1, EA2, EA3, EA4, EA5, EA6, EA7 [1.8, 2.0, 2.4, 2.5P] [2.0D] Eclipse [1994-</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>AM13-EA1F01 MR-297465</p> <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Galant [1998-2004] = EA3, EA8 [12.4, 3.0P] Eclipse [1994-2004] = D52, D53</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p>AM13-EA1E00 MR-103157</p> <p>TN-2010-December-26 Tenacity Product shabbirh@eim.ae  www.alafuae.com</p> <p>Galant [1998-2004] = EA1, EA2, EA3, EA4, EA5, EA6, EA7 [1.8, 2.0, 2.4, 2.5P] [2.0D] Eclipse [1994-</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>	
<p>AM13-DJ1F00 MR-589432</p> <p>TN-2012-December-31 Tenacity Product shabbirh@eim.ae  www.alafuae.com</p> <p>Galant [2004-2007] = DJ1, DJ3, DJ5, DK2, DK4</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>AM13-DJ1E00 MR-589415</p> <p>TN-2012-December-31 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Galant [2004-2007] = DJ1, DJ3, DJ5, DK2, DK4</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM13-22F MB-002163</p> <p>Lancer = A72</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM13-23F MB-303066</p> <p>Lancer [1983-1985] = C11, C12, C13, C14</p> <p>Shock Absorber Mounting Rubber [FR, LH, RH] [1.3, 1.5, 1.6, 1.8] [2WD]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM13-24F MB-430356</p> <p>Lancer [1986-1992] = C11, C12, C14</p> <p>Shock Absorber Mounting Rubber [FR, LH, RH] [1.3, 1.5, 1.8] [2WD]</p>   <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-C51F00 MB-518798</p> <p>Lancer [1987-1993] = C51, C52, C53, C54, C58, C61, C62, C63, C64, C66, C68, C72, C73, V74, C82, C83</p> <p>Shock Absorber Mounting [FR, LH, RH] [1.3, 1.5, 1.6, 1.8P, 1.8D] [2WD, 4WD]</p>   <p>ARD-2014-January-01 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM13-C51E00 MB-584000</p> <p>Lancer [1987-1993] = C51, C52, C53, C54, C58, C61, C62, C63, C64, C66, C68</p> <p>Shock Absorber Mounting [RE, LH, RH] [1.3, 1.5, 1.6, 1.8P, 1.8D] [2WD, 4WD]</p>   <p>TN-2012-December-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM13-26F MB-808306</p> <p>Lancer [1991-1997] = CA1, CA2, CA3, CA4, CA5, CB1, CB2, CB3, CB4, CB5, CB6, CB7, CB8, CD2, CD3, CD4,</p> <p>Shock Absorber Mounting [FR, LH, RH] [1.3, 1.5, 1.6, 1.8, 2.0P, 2.0D] [2WD, 4WD]</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-27F MR-223294</p> <p>Lancer [1993-2000] = CA1, CA2, CA4, CA5, CB1, CB2</p> <p>Shock Absorber Mounting [FR, LH, RH] [1.3, 1.5] [2WD]</p>   <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM13-28F MR-131420</p> <p>Lancer [1999] = CK2, CK5</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-26EB MR-130230</p> <p>Lancer [1993-2000] = CB1, CB2</p> <p>Shock Absorber Mounting Rubber [RE, Big]</p>   <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM13-26ES MR-130231</p> <p>Lancer [1993-2000] = CB1, CB2</p> <p>Shock Absorber Mounting Rubber [RE, Small]</p>   <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM13-26E MR-910647</p> <p>Lancer [1991-2001] = CA1, CA2, CA4, CA5, CB1, CB2, CB3, CB4, CB5, CB8, CD5, CJ1, CJ2, CJ4, CJ5, CK1,</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>   <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM13-CS3F MR-455018</p> <p>Lancer [1996-2006] = CJ1, CJ2, CJ4, CJ5, CK2, CK4, CK5, CS1, CS2, CS3, CS5, CS6, CS7, CS9, CQ2, CK5</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>AM13-CS5F MR-316457</p> <p>Lancer [1996-2006] = CJ1, CJ2, CJ4, CJ5, CK2, CK4, CK5, CS1, CS2, CS3, CS5, CS6, CS7, CS9, CQ2, CK5</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p>AM13-CS3F00B MR-491447</p> <p>Mitsubishi Airtrek [2001-2005] = CU# Mitsubishi Asx [2010] = GA# Mitsubishi Dion [2000-2004] = C</p> <p>Shock Absorber Mounting Bearing Only [FR]</p>	
<p>AM13-CS901F MR-554860</p> <p>Lancer [1996-2006] = CJ1, CJ2, CJ4, CJ5, CK2, CK4, CK5, CS1, CS2, CS3, CS5, CS6, CS7, CS9, CQ2, CK5,</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	
	<p>AM13-CT902F MR-510138</p> <p>Lancer [2000-2007] = CT9, CP9</p> <p>Shock Absorber Mounting Upper Metal [FR, LH, RH]</p>












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM13-CS3EZ MR-491946</p> <p>Lancer [1996-2006] = CJ1, CJ2, CJ4, CJ5, CK2, CK4, CK5, CS1, CS2, CS3, CS5, CS6, CS7, CS9, CQ2, CK5</p> <p>Shock Absorber Mounting [RE, LH, RH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM13-CS3EZZ MR-491946</p> <p>Lancer [1996-2006] = CJ1, CJ2, CJ4, CJ5, CK2, CK4, CK5, CS1, CS2, CS3, CS5, CS6, CS7, CS9, CQ2, CK5</p> <p>Shock Absorber Mounting [RE, SET]</p> <p>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM13-CS3E00B MR-272946</p> <p>Mitsubishi Airtrek [2001-2005] = CU# Mitsubishi Asx [2010] = GA# Mitsubishi Chariot, Space Wagon</p> <p>Shock Absorber Mounting Bearing Only [RE, Bearing]</p> <p>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM13-CS3ES MR-554369</p> <p>Lancer [1996-2006] = CJ1, CJ2, CJ4, CJ5, CK2, CK4, CK5, CS1, CS2, CS3, CS5, CS6, CS7, CS9, CQ2, CK5</p> <p>Shock Absorber Mounting Rubber [RE, Small]</p> <p>RBI-2009-October-24 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM13-CS3EB MR-554370</p> <p>Lancer [1996-2006] = CJ1, CJ2, CJ4, CJ5, CK2, CK4, CK5, CS1, CS2, CS3, CS5, CS6, CS7, CS9, CQ2, CK5</p> <p>Shock Absorber Mounting Rubber [RE, Big]</p> <p>RBI-2009-October-19 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM13-CW5F00 MN-101372</p> <p>Mitsubishi Lancer [2007] = CY2A, CY3A, CY4A Mitsubishi Outlander [2006-2012] = CW5, CW6</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-2013-November-14 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM13-CW5FZZ MN-101372</p> <p>Mitsubishi Lancer [2007] = CY2A, CY3A, CY4A Mitsubishi Outlander [2006-2012] = CW5, CW6 Mitsubis</p> <p>Shock Absorber Mounting + Bearing [SET] [FR, LH, RH] [With Bearing] [ASMMI1023, ABRMI1001]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM13-DG1F00 MR-316528 ARP Product www.rbi.ae Carisma [1995-2003] = DA Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A Shock Absorber Mounting [FR]	AM13-DG5E00 MR-333564 ARP Product www.rbi.ae Space Star / Carisma [1997-2001] = DG5, DA2 Shock Absorber Mounting [RE, LH, RH] [1.8]
AM13-DA2F00 MR-130519 ARP Product www.rbi.ae Carisma = DA2 Shock Absorber Mounting [FR, LH, RH]	
AM13-N31F00 MB-573617 TN-2010-December-26 Tenacity Product, HFC Product, Ashimori Product www.rbi.ae Space Wagon / Grandis / Nimbus / Savin / Expo [1992-2007] = N11, N13, N18, N21, N23, N28, N31, N33, Shock Absorber Mounting [FR, LH, RH] [1.8, 2.0, 2.4P, 2.0D] [2WD, 4WD]	AM13-N31E00 MB-663202 HFC Product www.rbi.ae Space Wagon / Grandis / Nimbus / Savin / Expo [1992-2007] = N11, N13, N18, N21, N23, N28, N31, N33, Shock Absorber Mounting [RE, LH, RH] [1.8, 2.0, 2.4P, 2.0D] [2WD, 4WD]
AM13-N84F00 MR-272831 TN-2010-December-01 Tenacity Product, HFC Product www.rbi.ae Space Wagon / Grandis / Nimbus / Savin [1997-2004] = N61, N64, N71, N73, N74, N84, N86, N94, N96 Shock Absorber Mounting [FR, LH, RH] [1.8, 2.0, 2.4, 3.0] [2WD, 4WD]	
AM13-NA4ES MR-594438 RBI-2007-May-07 RBI Product www.rbi.ae Space Wagon [2002-2008] = NA4 Shock Absorber Mounting Rubber [RE, Small]	AM13-NA4EB MR-594439 RBI-2007-December-20 RBI Product www.rbi.ae Space Wagon [2002-2008] = NA4 Shock Absorber Mounting Rubber [RE, Big]
AM13-NA4F MR-594347 RBI-2008-October-08 RBI Product, HFC Product www.rbi.ae Space Wagon [2002-2008] = NA4 Shock Absorber Mounting [FR, LH, RH]	
AM13-F07F00 MR-554246 TN-2010-December-01 Tenacity Product, Ashimori Product www.rbi.ae Diamante / Magnum [1992-2004] = F07, F11, F12, F13, F15, F16, F17, F25, F27, F36, F38, S22, S26, S27 Shock Absorber Mounting [FR, LH, RH] [2.0, 2.5, 3.0, 3.5] [2WD, 4WD]	












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM13-V73F0 MR-448170</p> <p>TN-2012-August-06 Tenacity Product, HFC Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero / Montero [2003-2011] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V86, V93,</p> <p>Shock Absorber Mounting [FR, LH, RH] [2.5, 2.8, 3.0, 3.2D, 3.0, 3.5, 3.8P]</p>	
<p>AM13-V73FB01 MR-374546</p> <p>HFC Product, Ashimori Product</p>  <p>www.rbi.ae</p> <p>Pajero / Montero [2003-2011] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V86, V93,</p> <p>Shock Absorber Mounting Rubber [FR, UPR]</p>	<p>AM13-V73FB02 MR-374547</p> <p>Ashimori Product</p>  <p>www.rbi.ae</p> <p>Pajero / Montero [2003-2011] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V86, V93,</p> <p>Shock Absorber Mounting Rubber [FR, LWR]</p>
<p>AM13-T04F00 MR-992326</p> <p>TN-2012-August-06 Tenacity Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Triton = KA4, KA5, KA9, KB4, KB5, KB8, KB9</p> <p>Shock Absorber Mounting [FR, LH, RH] [2.5, 2.8, 3.0, 3.2D, 3.0, 3.5, 3.8P]</p>	
<p>AM13-H76F00 MB-303452</p> <p>TN-2012-December-31 Tenacity Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero IO [1990-2004] = H53, H58, H62, H65, H66, H67, H71, H72, H76, H77, U14, U41, U42, U43, U44</p> <p>Shock Absorber Mounting [FR, LH, RH] [1.6, 1.8, 2.0] [2WD, 4WD]</p>	
<p>AM13-VAR93F00</p> <p>TN-2014-February-10 Tenacity Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mitsubishi VARICA 1100 [1993-1995]</p> <p>Shock Absorber Mounting</p>	
<p>AM13-MAG01F00</p> <p>TN-2014-February-10 Tenacity Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mitsubishi MAGIC 1.6 [2001]</p> <p>Shock Absorber Mounting</p>	







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM14-01B MA-150599 A121   Shock Absorber Bumper [FR, Big Diameter]	AM14-22S MA-150598 A72   Shock Absorber Bumper [FR, Small Diameter]
AM14-06E MB-338684 E12, E15, E33, C12, CB1, CB2   Shock Absorber Bumper [RE]	AM14-U06E0 MB-338684 E12, E15, E33, C12, CB1, CB2   MEP-Shock Absorber Bumper [RE]
AM14-06F MB-349347 E12, E15, E33, E54   Shock Absorber Bumper [FR]	AM14-U06F MB-349347 E12, E15, E33, E54   MEP-Shock Absorber Bumper [FR]
AM14-07F MB-339100 Galant [1988-1994] = E31, E32, E33   Shock Absorber Bumper [FR]	



























AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM14-02F MB-303069  C12, CB2, CB1 Shock Absorber Bumper [FR]  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM14-U02F MB-303069  C12, CB1, CB2 MEP-Shock Absorber Bumper [FR]  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM14-28E0 MB-809285  CK, CB Shock Absorber Bumper [RE]  Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM14-U28E0 MB-809285  CK, CB MEP-Shock Absorber Bumper [RE]  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM14-CS90F MR-961189  CS9 Shock Absorber Bumper [FR]  RBI-2011-April-23 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
AM14-CS3E0 MR-510002  CS3, CS5 Shock Absorber Dust Cover [RE]  RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM14-CS3F0 MR-455020  CS3, CS5 Shock Absorber Dust Cover [FR]  RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM14-CK4F0 MR-403783  Lancer [1997] = CK4, CK5 Shock Absorber Dust Cover [FR]  HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
AM14-CK2F0 MB-349462  Lancer [1997] = CK2, CK4, CK5 Shock Absorber Dust Cover [FR]  ASH-2012-December-25 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM14-CK2E0 MB-809284  Carisma [1995-2003] = DA Fto [1994-1999] = DE2A, DE3A Lancer Evolution [1996-2001] = CN9A Lanc Shock Absorber Dust Cover [RE]  Ashimori Product www.rbi.ae
AM14-06F01 MB-303070  Airtrek [2001-2005] = CU# Carisma [1995-2003] = DA Lancer [2000-2009] = CS1A, CS3A Lancer Stat Shock Absorber Dust Cover [FR]  ARP Product www.rbi.ae	












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM14-NA4E 4060A047  Space Wagon [2002-2008] = NA4 Shock Absorber Bumper [RE]	RBI-2007-October-29 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM14-UNA4E 4060A047  Space Wagon [2002-2008] = NA4 MEP-Shock Absorber Bumper [RE]	RBI-2008-March-17 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM14-NA4FZ MR-272833  Space Wagon [2002-2008] = NA4, N84 Shock Absorber Dust Cover [FR]	Ashimori Product www.rbi.ae		
AM14-NA4F MR-272833  Space Wagon [2002-2008] = NA4, N84 Shock Absorber Dust Cover [FR]	RBI-2008-January-13 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM14-N33F0 MB-349346  Space Wagon [1992] = N31, N33 Shock Absorber Dust Cover [FR]	HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM14-N33E0 MB-663194  Space Wagon [1992] = N31, N33 Shock Absorber Dust Cover [RE]	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM14-V73F0 MR-554120</p> <p>Pajero / Montero [2003-2011] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V86, V93,</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>ASH-2013-July-10 HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM14-H76F0 MR-319786</p> <p>Pajero IO [1998-2004] = H65, H66, H76, H77</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>Perfect Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM14-T04F0 MR-992325</p> <p>Triton / L200 = KB4, KB8 [2.5, 3.2] [16V]</p> <p>Shock Absorber Dust Cover [FR]</p>	<p>ARP Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM14-PG4E MR-418018</p> <p>Pajero Sports</p> <p>Shock Absorber Dust Cover [RE]</p>	<p>RBI-2012-August-25 RBI Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM17-02IZ MB-176164 A156  Drive Shaft Boot [Inner]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-02UZ MB-176162 A156  Drive Shaft Boot [Outer]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM17-06IZ MB-526977 E33 [8V]  Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-06UZ MB-620168 E33 [8V]  Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM17-07IZ MB-526907 E33 [16V]  Drive Shaft Boot [Inner]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-07UZ MB-526905 E33 [16V]  Drive Shaft Boot [Outer]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM17-08IZ MB-937998 E55 [16V]  Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-08UZ MR-222684 E55 [16V]  Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM17-09IZ MB-937307 E54 [24V]  Drive Shaft Boot [Inner]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-09UZ MR-222635 E54 [24V]  Drive Shaft Boot [Outer]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM17-11IZ MB-176861 E11, E12  Drive Shaft Boot [Inner]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-11UZ MB-297351 E11, E12  Drive Shaft Boot [Outer]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM17-15IZ MB-620054 E15  Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-15UZ MB-620053 E15  Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM17-23E MB-110423 C12  Drive Shaft Boot [RE]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM17-23E4 MB-596069 C12 [4WD]  Drive Shaft Boot	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM17-23IZ MB-297454 C11, C12 Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-23UZ MB-175869 C11, C12 Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  
AM17-25IZ MB-298546 C13 Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-25UZ MB-176195 C13 Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  
AM17-CB4IZ MB-297926 Lancer [1991-1996] = C11, C12, CB4 Drive Shaft Boot [Inner]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-CU2IZ MN-156831 Outlander [2002-2006] = CU2W, CU4W, CU5W... [4WD] Drive Shaft Boot [Inner]	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  
AM17-CB1IZ MB-297338 Lancer [1991-1996] = C11, C12, CB1, CB2, CB4 Drive Shaft Boot [Inner]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-CB1UZ MB-297389 Lancer [1991-1996] = C11, C12, CB1, CB2, CB4 Drive Shaft Boot [Outer]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  
AM17-26IZ MB-620876 CB1, CB2, CB4 Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-26UZ MB-837211 CB1, CB2, CB4 Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  
AM17-28IZ MR-195707 CK2, CK5, CS3 Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-28UZ MR-196053 CK2, CK5, CS3 Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  
AM17-CS3IZ MR-276444 CS3, CS5 Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-CS3UZ MR-276442 CS3, CS5 Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  
AM17-CY3IZ 3817A135 Asx [2010] = GA# Galant Fortis, Lancer Evolution [2007] = CY4A, CZ4A Lancer [2007] = CY2A, CY3A, Drive Shaft Boot [Inner]	RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  	AM17-CY3UZ 3817A134 Lancer [2005] = CY3, CY4 Drive Shaft Boot [Outer]	RBI-2013-June-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM17-27IZ MB-886676 <p>Pajero = K77 [4WD] Pajero II [1991-2004] = V14W-V55W Pajero, Montero Sport Challenger [1996-2008]</p> <p>Drive Shaft Boot [Inner]</p>	 <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AM17-27UZ MB-896069 <p>Pajero = K77 [4WD] Pajero II [1991-2004] = V14W-V55W Pajero, Montero Sport Challenger [1996-2008]</p> <p>Drive Shaft Boot [Outer]</p>	 <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
		AM17-4X01UZ MR-232240 <p>K77, Strada [4WD]</p> <p>Drive Shaft Boot [Outer]</p>	 <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
AM17-T04IZ MR-528709 <p>Pajero III Montero [2000-2006] = V65W-V75W Pajero, Montero Sport Challenger [1996-2006] = K94W, K9</p> <p>Drive Shaft Boot [Inner] [4WD]</p>	 <small>RBI-2007-January-05 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AM17-T04UZ 3815A180V <p>Pajero III Montero [2000-2006] = V65W-V75W Pajero, Montero Sport Challenger [1996-2006] = K94W, K9</p> <p>Drive Shaft Boot [Outer] [4WD]</p>	 <small>RBI-2007-September-10 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
AM17-NA4IZ MN-110516 <p>Space Wagon [2002-2008] = NA4</p> <p>Drive Shaft Boot [Inner]</p>	 <small>RBI-2007-August-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
AM17-K57IZ MR-350589 <p>G-Wagon = K57, Magna / Diamante [1999-2005] = F38</p> <p>Drive Shaft Boot [Inner]</p>	 <small>RBI-2009-February-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AM17-K57UZ MR-350588 <p>G-Wagon = K57, Magna / Diamante [1999-2005] = F38</p> <p>Drive Shaft Boot [Outer]</p>	 <small>RBI-2009-February-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>



















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<div>AM18-020Z</div> <div>MB-122136</div> <div>A156</div> <div></div> <div>Steering Gear Boot [LH, RH]</div>	<div><div>RBI-OLD</div><div>RBI Product</div><div>shabbirh@eim.ae</div><div></div><div>www.rbi.ae</div><div>www.alafuae.com</div></div>		
<div>AM18-11LZ</div> <div>MB-266165</div> <div>E11, E15</div> <div></div> <div>Steering Gear Boot [LH]</div>	<div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div></div><div>www.rbi.ae</div><div>www.alafuae.com</div></div>	<div>AM18-11RZ</div> <div>MB-266166</div> <div>E11, E12</div> <div></div> <div>Steering Gear Boot [RH]</div>	<div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div></div><div>www.rbi.ae</div><div>www.alafuae.com</div></div>
<div>AM18-23LZ</div> <div>MB-347364</div> <div>C11, C12</div> <div></div> <div>Steering Gear Boot [LH]</div>	<div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div></div><div>www.rbi.ae</div><div>www.alafuae.com</div></div>	<div>AM18-23RZ</div> <div>MB-347365</div> <div>C11, C12</div> <div></div> <div>Steering Gear Boot [RH]</div>	<div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>shabbirh@eim.ae</div><div></div><div>www.rbi.ae</div><div>www.alafuae.com</div></div>
<div>AM18-26LZ</div> <div>MB-532531</div> <div>CB1, CB2</div> <div></div> <div>Steering Gear Boot [LH]</div>	<div><div>RBI-OLD</div><div>RBI Product</div><div>shabbirh@eim.ae</div><div></div><div>www.rbi.ae</div><div>www.alafuae.com</div></div>	<div>AM18-26RPZ</div> <div>MB-501711</div> <div>E12, E15, E33, E54, CK2, CK4, CB1, CB2, L300</div> <div></div> <div>Steering Gear Boot [RH, Power]</div>	<div><div>RBI-OLD</div><div>RBI Product, Perfect Product</div><div>Ashimori Product</div><div>shabbirh@eim.ae</div><div></div><div>www.rbi.ae</div><div>www.alafuae.com</div></div>









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM18-CS30Z MR-491361</p>  <p>CS3, CS5</p> <p>Steering Gear Boot [LH, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>AM18-CS90Z MR-510406</p>  <p>CS9</p> <p>Steering Gear Boot [LH, RH]</p>
<p>AM18-CY2ALR 4410A328</p>  <p>Asx [2010] = GA# Lancer [2007] = CY2A, CY3A, CY4A</p> <p>Steering Gear Boot</p>	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>AM18-CV5WLR 4410A125</p>  <p>Delica D5 [2006] = CV5W Galant Fortis, Lancer Evolution [2007] = CY4A, CZ4A Lancer [2007] = CY2A</p> <p>Steering Gear Boot</p>















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM18-T02LRZ 4410A179  L200 / Triton [2WD]  Steering Gear Boot [LH, RH] <small>RBI-2008-April-19 RBI Product, Perfect Product shabbirh@eim.ae www.alafuae.com</small>	AM18-T04Z 4410A180  L200 / Triton [4WD]  Steering Gear Boot [RH] <small>RBI-2008-August-15 RBI Product, Perfect Product shabbirh@eim.ae www.alafuae.com</small>
AM18-NA4Z MN-103262  Space Wagon [2002-2008] = NA4  Steering Gear Boot <small>RBI-2008-August-15 RBI Product shabbirh@eim.ae www.alafuae.com</small>	
AM18-V73LZ MR-510271  Pajero [1998-2007] = V73, V78  Steering Gear Boot [LH] <small>RBI-2009-September-30 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.alafuae.com</small>	AM18-V73RZ MR-510272  Pajero [1998-2007] = V73, V78  Steering Gear Boot [RH] <small>RBI-2009-September-30 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.alafuae.com</small>







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM19-T020 MR-992443 L200 / Triton [2WD] Coil Spring Rubber	 <small>RBI-2007-March-13 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AM19-T040 MR-992324 L200 / Triton [4WD] Coil Spring Rubber	 <small>RBI-2009-December-12 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM20-22B MA-180631 A72  Spring Shackle Rubber [FR, Big]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM20-22G MA-471176 A72  Spring Shackle Rubber [RE, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM20-22T MA-126004 A72  Spring Shackle Rubber [RE, Short]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com		
AM20-41B MB-111203 L200 / Triton  Spring Shackle Rubber [Big]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM20-41G MT-111071 L200 / Triton = K14, K64, K77  Spring Shackle Rubber [Long]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM20-41T MT-362394 L200 / Triton = K14, K64, K77  Spring Shackle Rubber [RE, Short]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM20-43F MB-515925 L200 / Triton = K14  Spring Shackle Bush [FR]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM20-44F MR-418960 K64, K67, K77, Strada L200 [1996-2005] = K74T, K75T  Spring Shackle Bush [FR]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com		
ARM20-FE111 MB-025153 FE111  Spring Shackle Rubber	RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	ARM20-FE115 MB-025185 FE111  Spring Shackle Rubber	PFT-2012-December-31 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM20-P15F00 MR-112395 Delica / L300 = P13, P15  Spring Shackle Rubber	ARP Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<div>AM21-010</div> <div>MB-175639</div> <div></div> <div>Galant = A121</div> <div>Stabilizer Shaft Rubber</div>	<div><div>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div><div></div></div>		
<div>AM21-02B</div> <div>MB-176757</div> <div></div> <div>Galant = A156</div> <div>Stabilizer Shaft Rubber [FR] [Big]</div>	<div><div>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div><div></div></div>	<div>AM21-02S</div> <div>MB-176279</div> <div></div> <div>Galant = A156</div> <div>Stabilizer Shaft Rubber [FR] [Small]</div>	<div><div>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div><div></div></div>
<div>AM21-030</div> <div>MB-175638</div> <div></div> <div>Galant = A161</div> <div>Stabilizer Shaft Rubber [FR]</div>	<div><div>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div><div></div></div>	<div>AM21-040</div> <div>MB-175640</div> <div></div> <div>Galant = A173</div> <div>Stabilizer Shaft Rubber</div>	<div><div>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div><div></div></div>
<div>AM21-120</div> <div>MB-303541</div> <div></div> <div>Galant = E12</div> <div>Stabilizer Shaft Rubber</div>	<div><div>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</div><div></div></div>		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-061 MB-573207</p> <p>Galant [1988-1992] = E31, E32, E33 Eclipse [1991] = D21</p> <p>Stabilizer Shaft Rubber [FR] [1.6, 1.8, 2.0] [8V]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM21-062 MB-573054</p> <p>Galant [1988-1992] = E33 Eclipse [1991] = D22</p> <p>Stabilizer Shaft Rubber [FR] [2.0] [16V]</p>	<p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM21-07E MR-297504</p> <p>Galant = E54, E55</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM21-07E03 MR-297507</p> <p>Eclipse [1994-1999] = D32</p> <p>Stabilizer Shaft Rubber [RE] [2.0]</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM21-07F MR-297500</p> <p>Galant = E54, E55</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM21-EA1E MR-223536  Mitsubishi Eclipse Spyder [1999-2005] = D52A, D53A..[USA] Mitsubishi Galant [1996-2003] = EA3A, EA  Stabilizer Shaft Rubber [RE] [1.8, 2.0, 2.0DIE, 2.4, 3.0]	AM21-EA2E MR-272717  Mitsubishi Galant [1996-2003] = EA Mitsubishi Galant [1996-2003] = EA3A, EA8A..[USA]  Stabilizer Shaft Rubber [RE] [2.0, 2.0DIE, 2.4, 2.5, 3.0, 3.8]
AM21-DJ1E MR-297629  Galant [1997-2006] = EA4, EA5, DJ1, DJ3 Eclipse [2003-] DK2  Stabilizer Shaft Rubber [RE] [2.0, 2.5, 2.4, 3.8]	AM21-DJ1E02 MR-589402  Mitsubishi Galant [2006-2012] = DJ1A, DJ3A, DJ5A  Stabilizer Shaft Rubber [RE]
AM21-EA1F MR-244115  Galant [1996-2006] = EA1, EA2, EA3, EA4, EA5, EA6, EA7, EA8  Stabilizer Shaft Rubber [FR] [1.8, 2.0, 2.0DIE, 2.4, 2.5, 3.0]	AM21-EA2F MR-244116  Galant [1996-2005] = EA2, EA3, EA4, EA5, EA6, EA8 Eclipse [2000-2006] = D53  Stabilizer Shaft Rubber [FR] [2.0, 2.4, 2.5, 2.0DIE, 3.0]
AM21-EA5F MR-272646  Galant [1996-2000] = EA5  Stabilizer Shaft Rubber [FR] [2.5]	
AM21-DJ1F MR-589438  Galant [2006-] = DJ1, DJ3  Stabilizer Shaft Rubber [FR] [2.4, 3.8]	AM21-DJ5F MN-101323  Galant [2006-] = DJ5 Eclipse [2003-] = DK2, DK4  Stabilizer Shaft Rubber [FR] [2.4, 3.8]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM21-F07F00 AW-343164 Diamante [1994-1996] = F07W Stabilizer Shaft Rubber [FR]	Ashimori Product www.rbi.ae	AM21-F36F00 AW-343163 Diamante [1997-2003] = F36W Stabilizer Shaft Rubber [FR]	Ashimori Product www.rbi.ae





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-210 MA-150612</p>  <p>Lancer = A53</p> <p>Stabilizer Shaft Rubber [Small Diameter]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM21-220 MA-150610</p>  <p>Lancer = A72</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM21-23F MB-349530</p>  <p>Lancer [1983-1992] = C11, C12</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM21-C11F00 MB-303052</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Lancer [1983-1992] = C11, C12, C14, C18</p> <p>Stabilizer Shaft Rubber [FR] [1.3, 1.5, 1.8]</p>
<p>AM21-C51F00 MB-948522</p> <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Lancer [1992] = C51A, C54A, C61A, C62A, C64A</p> <p>Stabilizer Shaft Rubber [FR] [1.3, 1.5]</p>		
<p>AM21-C51F3 MB-808004</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Lancer [1988-1992] = C51, C52, C54, C61, C62, C64</p> <p>Stabilizer Shaft Rubber [FR] [1.3, 1.5, 1.8DISEL]</p>		<p>AM21-C52F00 MB-808005</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Lancer [1988-1992] = C52, C53, C58, C63, C68</p> <p>Stabilizer Shaft Rubber [FR] [1.5, 1.6, 1.8]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

mitsubishi

Revision : 2014-November-01









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-26E MB-809357</p>  <p>Lancer = CB1, CB2</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>AM21-26F MB-844456</p>  <p>Lancer = CB1, CB2</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p>AM21-CA3F00 MB-844455</p>  <p>Lancer [1993-2000] = CA3A, CB2A, CB3A, CB6A DE3A Pajero IO = H31A, H36A, H31A, H57A</p> <p>Stabilizer Shaft Rubber [FR] [660cc, 1.1, 1.5, 1.6, 2.0] [2WD, 4WD]</p>	<p>AM21-CB1F00 MB-809537</p>  <p>Lancer = CB1, CB2</p> <p>Stabilizer Shaft Rubber [FR]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-28E MR-197475</p> <p>Lancer = CK5, CK2</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM21-28F MR-171441</p> <p>Lancer = CK2, CK5</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM21-29F MR-403082</p> <p>Lancer = CK5 [1999]</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		
<p>AM21-CK4F00 MR-197005</p> <p>Lancer [1995-2000] = CK4</p> <p>Stabilizer Shaft Rubber [FR] [1.6]</p>	<p>RBI-2014-October-21 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		
		<p>AM21-DE2E00 MR-197002</p> <p>Lancer [1997-2000] = CJ4 Mitsubishi FTO [1994-1999] = DE2, DE3</p> <p>Stabilizer Shaft Rubber [RE] [1.6, 1.8, 1.8] [2WD]</p>	<p>RBI-2014-October-21 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
		<p>AM21-CN9F00 MR-491144</p> <p>Lancer Evolution [1996-2001] = CN9, CP9</p> <p>Stabilizer Shaft Rubber [FR] [2.0] [4WD]</p>	<p>RBI-2014-October-21 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM21-CT9E00 MR-491145</p> <p>Lancer Evolution [1996-2001] = CP9 Lancer Evolution [2001-2005] = CT9</p> <p>Stabilizer Shaft Rubber [RE] [2.0] [4WD]</p>	<p>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-CS3F00 MR-403645</p> <p>Lancer = CS3</p> <p>Stabilizer Shaft Rubber [FR]</p>   <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM21-CS5F00 MR-491192</p> <p>Lancer = CS5</p> <p>Stabilizer Shaft Rubber [FR]</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM21-CS901E MR-589637</p> <p>Lancer = CS9</p> <p>Stabilizer Shaft Rubber [RE]</p>   <p>RBI-2009-October-24 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM21-CU2E00 MR-554028</p> <p>Outlander / Airtrek [2001-2005] = CU2, CU4, CU5 Dion [2000-2004] = CR5, CR6, CR9 Lancer [2000-2004]</p> <p>Stabilizer Shaft Rubber [FR] [1.8, 2.0, 2.4]</p>   <p>ASH-2013-November-15 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM21-CU2F00 MR-554095</p> <p>Outlander / Airtrek [2001-2005] = CU2, CU4 Lancer [2001-2001] = CS1, CS3, CS5</p> <p>Stabilizer Shaft Rubber [FR] [1.8, 2.0, 2.4]</p>   <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM21-CU5E00 MR-403775</p> <p>Outlander / Airtrek [2002-2005] = CU2, CU4, CU5...4WD DINGO [1998-2002] = CQ1, CQ2, CQ5 DION [2000-2004]</p> <p>Stabilizer Shaft Rubber [RE] [1.3, 1.5, 1.8, 2.0, 2.4]</p>   <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM21-CU5F00 MN-100250</p> <p>Outlander / Airtrek [2001-2006] = CU2, CU4, CU5...4WD Lancer [2000-2009] = CS1, CS3, CS5, CS6, CS7</p> <p>Stabilizer Shaft Rubber [FR] [1.6, 1.8, 2.0, 2.4]</p>   <p>ASH-2013-November-15 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM21-CY2E00 MN-101395  Lancer [2007] = CY2, CY3, CY4 Asx [2010] = GA#  Stabilizer Shaft Rubber [RE] [1.5]	AM21-CY2F00 4056A049  Lancer [2006] = CY2, CY3, CY4  Stabilizer Shaft Rubber [FR] [1.5]
AM21-CY4E00 4156A004  Lancer [2006] = CY4 Outlander [2006] = CW5  Stabilizer Shaft Rubber [RE] [2.0, 2.4]	AM21-CY4F00 4056A078  Lancer [2006] = CY4  Stabilizer Shaft Rubber [FR] [2.0]
AM21-CW5E00 4156A028  Mitsubishi Outlander [2006-2012] = CW5W Citroen C-Crosser [2007] Peugeot 4007 [2007]  Stabilizer Shaft Rubber [RE] [2.4, 3.0]	AM21-CW5F00 4056A079  Outlander [2006] = CW5, CW6 Asx [2010] = GA# Delica D5 [2006] = CV5  Stabilizer Shaft Rubber [FR] [2.4, 3.0]
AM21-DA1F00 MR-911072  Carisma [1995-2003] = DA1  Stabilizer Shaft Rubber [FR]	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-620 MB-430968</p> <p>Delica / L300 [1986-2004] = P01, P02, P03, P04, P05, P12, P13, P15, P17</p> <p>Stabilizer Shaft Rubber [FR] [1.4, 1.6, 2.0P] [2.5D]</p>	<p>RBI-2012-March-12 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM21-63040 MB-573810</p> <p>Delica / L300 = P25W</p> <p>Stabilizer Shaft Rubber</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM21-63042 MR-150095</p> <p>Delica / L300</p> <p>Stabilizer Shaft Rubber</p>	<p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM21-63041 MR-151285</p> <p>Delica / L300</p> <p>Stabilizer Shaft Rubber</p>
	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AM21-PD4E00 MR-267685</p> <p>Delica / L300 [1994-2002] = PD4W, PD6W, PD8W, PE8W, PF6W, PF8W</p> <p>Stabilizer Shaft Rubber [RE] [2.4, 2.8DIE, 3.0] [4WD]</p>
	<p>RBI-2014-April-18 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-N31F MB-633239</p>  <p>Space Wagon = N31, N33, RVR, N28W</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM21-N84F MR-316227</p>  <p>Space Wagon / Grandis / Nimbus / Savin [1997-2004] = N84</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2014-March-12 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM21-N84E MB-871062</p>  <p>Space Wagon / Grandis / Nimbus / Savin [1997-2004] = N11, N13, N21, N23, N28, N33, N34, N38, N41, N4</p> <p>Stabilizer Shaft Rubber [RE]</p>
<p>AM21-NA4E MN-103392</p>  <p>Space Wagon [2002-2008] = NA4</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-2007-March-13 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM21-NA4F MR-594335</p>  <p>Space Wagon [2002-2008] = NA4</p> <p>Stabilizer Shaft Rubber [FR]</p>



MITSUBISHI

Revision : 2014-November-01

<p>AM21-410 MB-109557</p>  <p>L200 / Triton = K14</p> <p>Stabilizer Shaft Rubber</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM21-411 MB-175534</p> <p>Ashimori Product www.rbi.ae</p> <p>PAJERO / MONTERO = L036, L039, L063, L069</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p>AM21-440 MB-111240</p>  <p>K64, K67</p> <p>Stabilizer Shaft Rubber</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM21-T04F MR-992317</p>  <p>L200 / Triton [4WD]</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-2007-March-24 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM21-450 MR-151326</p>  <p>Pajero = K77 [4WD]</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM22-450 MR-150767</p>  <p>Pajero = K77 [4WD]</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p>AM21-PG4E MB-338594</p>  <p>Pajero / L200 = K94, K96, K97, K99</p> <p>Stabilizer Shaft Rubber [RE]</p>	<p>RBI-2012-March-12 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM21-K67F01 MR-151327</p>  <p>Pajero [1996-2005] = K66T, K72T, K76T, K77T [2WD]</p> <p>Stabilizer Shaft Rubber [FR] [2.0, 2.8DIE, 3.0]</p>	<p>PFT-2012-August-30 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM21-K67F02 MR-519863</p> <p>ASH-2014-May-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Pajero [1999-2005] = K66T, K72T, K76T, K77T [2WD, 4WD]</p> <p>Stabilizer Shaft Rubber [FR] [2.0, 2.8DIE, 3.0]</p>
<p>AM21-K94F01 MR-267649</p>  <p>Mitsubishi PAJERO [1996] Pajero = K93, K94</p> <p>Stabilizer Shaft Rubber [FR] [2.5, 3.0]</p>	<p>TN-2014-August-30 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM21-K96F00 MR-992098</p> <p>HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae</p> <p>Challenger [1998-2001] = K96</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p>AM21-L0470 MB-176442</p>  <p>Pajero [1986-1989] = L047</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-V14F MB-633934</p> <p>Ashimori Product www.rbi.ae</p> <p>Pajero [1993-1996] = V12, V14</p> <p>Stabilizer Shaft Rubber [FR]</p>	
<p>AM21-V24F5 MB-275632</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero [1990-1993] = V24</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>AM21-V24F6 MB-175804</p> <p>PFT-2012-August-30 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p>AM21-V23F MB-573784</p> <p>RBI-2013-December-16 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero [1990-1993] = L141G, L144G, V23C, V23W, V24C, V24V, V24W, V24WG, V34V</p> <p>Stabilizer Shaft Rubber [FR] [2.5, 3.0]</p>	<p>AM21-V23E MR-133706</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mitsubishi Pajero I [1989-1990] = L041G, L144G, L149G Mitsubishi Pajero II [1991-2004] = V14W, V21</p> <p>Stabilizer Shaft Rubber [RE] [2.4, 2.5, 2.8, 3.0, 3.5]</p>
<p>AM21-V43F MB-573783</p> <p>PFT-2012-August-30 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero [1990-1993] = L146G, L149G, V43W, V44W, V44WG</p> <p>Stabilizer Shaft Rubber [FR] [2.5, 3.0]</p>	<p>AM21-V43E MB-338596</p> <p>ASH-2013-July-10 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero [1993-1997] = L046G, L048G, L049G, V43V, V43W, V46V, V46W, V46WG, V47WG</p> <p>Stabilizer Shaft Rubber [RE] [2.0, 2.3, 2.5, 2.8, 3.0]</p>
<p>AM21-V44F MR-150093</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero = V44</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>AM21-V55F00 MR-150092</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mitsubishi Pajero II [1991-2004] = V14W-V55W</p> <p>Stabilizer Shaft Rubber [FR]</p>
<p>AM21-V450 MR-150091</p> <p>RBI-2009-September-05 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero = V45</p> <p>Stabilizer Shaft Rubber [FR]</p>	<p>AM21-V45F MR-150094</p> <p>RBI-2005-August-30 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Pajero = V45</p> <p>Stabilizer Shaft Rubber [FR]</p>














AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-V73E MR-418547</p> <p>Pajero [2001-2007] = V73</p> <p>Stabilizer Shaft Rubber [RE]</p>   <p><small>RBI-2009-September-05 RBI Product, Tenacity Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM21-V73F MR-374520</p> <p>Pajero [2001-2007] = V73</p> <p>Stabilizer Shaft Rubber [FR]</p>   <p><small>RBI-2008-March-19 RBI Product, Perfect Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM21-V75F00 4056A121</p> <p>Mitsubishi Pajero III Montero [2000-2006] = V65W, V75W</p> <p>Stabilizer Shaft Rubber [FR]</p>   <p><small>Perfect Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM21-V76F01 MR-554271</p> <p>Mitsubishi Pajero III Montero = V76</p> <p>Stabilizer Shaft Bush [FR]</p>   <p><small>Perfect Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM21-V87E00 4156A041</p> <p>Mitsubishi Pajero IV Montero [2006] = V87W, V97W</p> <p>Stabilizer Shaft Rubber [RE]</p>  <p><small>HFC-2014-November-20 HFC Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	



AL LAMSA AL FIDDIYA TRADING L.L.C.





ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM21-H76F00 MR-319193</p> <p>Pajero IO [1998-2004] = H61, H65, H66, H71, H76, U61, U62, U63, U64, U65, U66</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>TN-2012-March-06 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	<p>AM21-H76F01 MR-455699</p> <p>Mitsubishi Pajero Pinin, IO [1999-2005] = H61W-H77W</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>TN-2012-March-06 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>
<p>AM21-H76E00 MR-223535</p> <p>Pajero Pinin, IO [1999-2005] = H61W-H77W</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	
<p>AM21-HA1WF00 MR-319183</p> <p>I [AI] [2007] = HA1W, HA3W</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product www.rbi.ae</p>	
<p>AR21-FU215 MB-294604</p> <p>Fuso Truck</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM23-011 MB-109789 A121  Strut Bar Rubber	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM23-01Z MB-109815 A121  Strut Bar Rubber Set [Set]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM23-012 MB-109788 A121  Strut Bar Rubber	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM23-02Y MB-176740 A156  Strut Bar Rubber	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM23-02Z MB-109460 A156  Strut Bar Rubber Set [Set]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM23-041 MB-175617 A173, K64  Strut Bar Rubber [With edge]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM23-04Z MB-175619 A173, K64  Strut Bar Rubber Set [Set]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM23-042 MB-175618 A173, K64  Strut Bar Rubber [With out edge]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM23-221 MB-001766 L200 / Triton A72  Strut Bar Rubber [With edge]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM23-22Z MB-001698 L200 / Triton A72  Strut Bar Rubber Set [Set]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM23-222 MB-001765 L200 / Triton A72  Strut Bar Rubber [With out edge]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM23-431 MB-176371 K14, K64, K67 Strut Bar Rubber [With edge]	  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM23-43Z MB-176373 K14, K64, K67 Strut Bar Rubber Set [Set]	  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM23-432 MB-176372 K14, K64, K67 Strut Bar Rubber [With out edge]	  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
AM23-611 MB-430158 L300, L031, P15V Strut Bar Rubber [With edge]	  RBI-OLD RBI Product, Perfect Product HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM23-61Z MB-175543 L300, L031, P15V Strut Bar Rubber Set [Set]	  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM23-T020 4016A001 L200 / Triton [2WD] Strut Bar Rubber	  RBI-2007-March-24 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM23-T020Z 4016A001 L200 / Triton [2WD] Strut Bar Rubber Set [Set]	  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM23-H75Z MR-465868 Pajero Pinin, IO [1999-2005] = H61, H77 Strut Bar Rubber Set [Set]	  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM24-03W MB-175762 Galant = A156 Front Lower Arm Bush [FR]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM24-04W MB-109786 Galant = A173, A161 Front Lower Arm Bush [FR]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM25-011 MB-003019 Galant = A121 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM25-012 MB-002979 Galant = A121 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM25-013 MB-002990 Galant = A121 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM25-031 MB-111173 Galant = A161 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM25-032 MB-111040 Galant = A161 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM25-033 MB-111041 Galant = A161 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM25-041 MB-110815 Galant = A173 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM25-042 MB-110808 Galant = A173 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AM25-043 MB-110720 Galant = A173 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AM25-044 MB-002998 Galant = A173, A121, A161 Rear Suspension Bush [RE]	 RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM24-12B MB-303680  Galant [1984-1986] = E11, E12, E14 Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM24-12S MB-430311  Galant [1984-1993] = E11, E12, E14, E15, E16, E33 Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM24-15L MB-518094  Galant [1986-1988] = E15, E16 Front Lower Arm Bush [FR, Big, LH]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM24-15R MB-518095  Galant [1986-1988] = E15, E16 Front Lower Arm Bush [FR, Big, RH]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM24-06W MB-518220  Galant [1989-1993] = E33 Eclipse [1989-1994] = D21, D22, D27, E99 Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM24-EA3WB MR-455736  Galant USA [1996-2003] = EA3A, EA8A Front Lower Arm Bush [FR, Big]	PFT-2013-June-25 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM24-EA3WS MR-455737  Galant USA [1996-2003] = EA3A, EA8A Front Lower Arm Bush [FR, Small]	PFT-2013-February-15 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM24-EA8WB MR-554381  Mitsubishi Galant [1996-2003] = EA3A, EA8A... [USA] Front Lower Arm Bush [FR, Big]	PFT-2013-April-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM24-EA8WLZ MR-554381  Galant USA [1996-2003] = EA3A, EA8A Front Lower Arm Bush [Bracket] [FR, Big, LH]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM24-EA8WRZ MR-554382  Galant USA [1996-2003] = EA3A, EA8A Front Lower Arm Bush [Bracket] [FR, Big, RH]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-12LCRZZ MB-430312</p> <p>Galant [1984-1986] = E11, E12, E14</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p> 	<p>AM24-12LCLZZ MB-430311</p> <p>Galant [1984-1986] = E11, E12, E14</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p> 
<p>AM24-06CBR MB-518168</p> <p>Galant [1989-1993] = E33</p> <p>Front Cross Member Arm Bush [FR, RH]</p> 	<p>AM24-06CBL MB-518167</p> <p>Galant [1989-1993] = E33</p> <p>Front Cross Member Arm Bush [FR, LH]</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-07P0 MB-891518</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Upper Arm Bush [FR]</p>	
<p>AM24-07P2Z MB-892320</p> <p>ARP Product www.rbi.ae</p> <p>Galant [1992-1996] = E55A, E75A Galant [1996-2003] = EA Legnum [1996-2002] = EA, EC</p> <p>Front Upper Arm Bush [Bracket] [FR]</p>	
<p>AM24-07UCRZ MB-912506</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>AM24-07UCLZ MB-912505</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]</p>
<p>AM24-07WG MB-808556</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Lower Arm Bush [FR, Small] [Inner Height = 54mm]</p>	
<p>AM24-07WCR1ZZ MB-912510</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Complete Lateral Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>AM24-07WCL1ZZ MB-912509</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Complete Lateral Arm [FR, LH] [With Ball Joint & 2 Bush]</p>
<p>AM24-07WT MR-296296</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Lower Arm Bush [FR, Small] [Inner Height = 50mm]</p>	<p>AM24-07W5 MB-808775</p> <p>PFT-2012-June-26 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Lower Arm Bush [FR]</p>
<p>AM24-07WC2ZZ MR-296296</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2, EA3, EA4, EA5, EA7 Eclipse = D32</p> <p>Front Complete Lateral Arm [FR, LH, RH] [With Ball Joint & 2 Bush]</p>	








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-07WB MR-296319</p>  <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2 Eclipse = D32</p> <p>Front Lower Arm Bush [FR, Big]</p> <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM24-07LCR1Z MB-912512</p>  <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2 Eclipse = D32</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 1 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM24-07LCL1Z MB-912511</p>  <p>Galant [1994-1999] = E52, E54, E55, E56, E57, EA1, EA2 Eclipse = D32</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 1 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-EA6LCRZ MR-554376</p> <p>ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Galant [2002-2005] = EA6, EA8 Eclipse [2002-2005] = D53</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>AM24-EA6LCLZ MR-554375</p> <p>ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Galant [2002-2005] = EA6, EA8 Eclipse [2002-2005] = D53</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p>
<p>AM24-DJ1WB MN-184123</p> <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Galant / Grunder [2004] = DJ1, DJ3, DJ5, DK2, DK4</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>AM24-DJ1WS MN-184138</p> <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Galant / Grunder [2004] = DJ1, DJ3, DJ5, DK2, DK4</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>AM24-F36WB AW-343831</p> <p>PFT-2013-April-30 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</p> <p>Sigma / Magna / Diamante [1995-2005] = F31, F34, F36, F41, F46, F47</p> <p>Front Lower Arm Bush [FR, Big]</p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM25-12EB MB-242367 Galant = E12, E15 Rear Suspension Bush [RE, Big]	  RBI-OLD RBI Product, Perfect Product www.rbi.ae www.alafuae.com	AM25-12ES MB-242332 Galant = E12, E15 Rear Suspension Bush [RE, Small]	  RBI-OLD RBI Product, Perfect Product www.rbi.ae www.alafuae.com
AM25-12FB MB-303626 Galant = E12, E15, E33 Rear Suspension Bush [RE] [FR, Big]	  RBI-OLD RBI Product, Perfect Product www.rbi.ae www.alafuae.com	AM25-12FS MB-303628 Galant = E12, E33, E15 Rear Suspension Bush [RE] [FR, Small]	  RBI-OLD RBI Product, Perfect Product www.rbi.ae www.alafuae.com
AM25-06EB MB-515500 Galant = E33 Rear Suspension Bush [RE, Big]	  RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product www.rbi.ae www.alafuae.com	AM25-06ES MB-584084 Galant [1988-1992] = E33, E38A, E39A Lancer Station Wagon [1992-2002] = CB#W Lancer, Colt [1988- Rear Suspension Bush [RE, Small]	  RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product www.rbi.ae www.alafuae.com
AM25-06E03 MB-809566 Lancer Station Wagon [1992-2002] = CB#W Libero, Libero Cargo [1992-2002] = CB#W Rear Suspension Bush	  PFT-2014-November-15 Perfect Product www.rbi.ae www.alafuae.com		
AM25-07EB MB-864736 Galant = E54, E55 Rear Suspension Bush [RE, Big]	  RBI-OLD RBI Product, Perfect Product www.rbi.ae www.alafuae.com	AM25-07EB2 MB-864731 Galant [1992-1996] = E55A, E75A Galant USA [1996-2003] = EA3A, EA8A Rear Suspension Bush [RE, Big]	  PFT-2012-June-26 Perfect Product www.rbi.ae www.alafuae.com
AM26-120 MB-303650 E12, E15, E33, E54 Suspension Rubber [FR]	  RBI-OLD RBI Product www.rbi.ae www.alafuae.com		



MITSUBISHI

Revision : 2014-November-01

<p>AM25-07ES MR-223673</p> <p>Galant [1994-1999] = E54, E55, EA1, EA2 Lancer = CB1, CB2, CK2, CK5</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-07E2B MR-223651</p> <p>Galant [1992-1996] = E55A, E75A Galant [1996-2003] = EA Galant USA [1996-2003] = EA3A, EA8A</p> <p>Rear Suspension Bush [RE, Big]</p> <p>PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM25-07EU2Z MR-102013</p> <p>Galant [1992-1999] = E54, E55, EA1, EA2</p> <p>Rear Complete Upper Arm [RE] [With 2 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM25-07E0 MB-809170</p> <p>Galant = E54, E55</p> <p>Rear Suspension Bush [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-07E02 MR-131913</p> <p>Galant [1996-2003] = EA</p> <p>Rear Suspension Bush [RE]</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM25-EA3E01 MR-223229</p> <p>Galant USA [1996-2003] = EA3A, EA8A Galant [1992-1996] = E55A, E75A Galant [1996-2003] = EA</p> <p>Rear Suspension Bush [RE]</p>  <p>PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM25-07EAR1Z MB-912516</p> <p>Galant [1992-1996] = E54, E55, EA1, EA2</p> <p>Rear Complete Assist Arm [RE, RH] [With Ball Joint & 1 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-07EAL1Z MB-912515</p> <p>Galant [1992-1996] = E54, E55, EA1, EA2</p> <p>Rear Complete Assist Arm [RE, LH] [With Ball Joint & 1 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM25-DJ1E01 MR-589485 Galant [2006] = DJ1A, DJ3A, DJ5A Eclipse USA [2006] = DK2A, DK4A Endeavor [2003] = D71W, D81W Rear Suspension Bush [RE]	 PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM25-DJ1E02 MR-589493 Galant [2006] = DJ1A, DJ3A, DJ5A Rear Suspension Bush [RE]	 PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM25-DJ1E03 4113A050 Galant [2006] = DJ1A, DJ3A, DJ5A Eclipse USA [2006] = DK2A, DK4A Endeavor [2003] = D71W, D81W Rear Suspension Bush [RE]	 PFT-2013-March-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM25-DJ1E04 4110A033 Galant [2006] = DJ1A, DJ3A, DJ5A Eclipse USA [2006] = DK2A, DK4A Endeavor [2003] = D71W, D81W Rear Suspension Bush [RE]	 PFT-2013-March-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM25-DJ1E05 4110A033 Galant [2006] = DJ1A, DJ3A, DJ5A Eclipse USA [2006] = DK2A, DK4A Endeavor [2003] = D71W, D81W Rear Suspension Bush [RE]	 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
AM25-DJ1E06B MR-589460 Galant [2006] = DJ1A, DJ3A, DJ5A Rear Upper Arm Bush [RE, Big]	 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM25-DJ1E06S MR-589459S Galant [2006] = DJ1A, DJ3A, DJ5A Front Upper Arm Bush [RE, Small]	 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM24-21W MB-001620  Lancer = A53, 16L  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR]	AM24-22W MB-001621  Lancer = A72, A121  RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR]
AM24-23R MB-518393  Lancer / Colt / Mirage [1988-1992] = C11, C12 Upto C50  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Big, RH]	AM24-23L MB-518392  Lancer / Colt / Mirage [1988-1992] = C11, C12 Upto C50  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Big, LH]
AM24-24S MB-303787  Lancer / Colt / Mirage [1988-1992] = C11, C12 Upto C50  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Small] [Small Diameter]	AM24-25S MB-430385  Lancer / Colt / Mirage [1988-1992] = C11, C12 Upto C50  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Small] [Big Diameter]
AM24-25S02 MB-573524  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Lancer / Colt [1988-1995] = C51A, C77A Front Lower Arm Bush [FR, Small]	
AM24-23LCR2Z MB-518807  HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Lancer / Colt / Mirage [1986-1988] Front Complete Lower Arm [FR, RH] [With Ball Joint & 1 Bush]	AM24-23LCL2Z MB-518806  HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Lancer / Colt / Mirage [1986-1988] Front Complete Lower Arm [FR, LH] [With Ball Joint & 1 Bush]













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM26-23FB MB-349419 Lancer = C11 Suspension Rubber [FR, Big]	  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	AM26-23FS MB-176667 Lancer = C11 Suspension Rubber [FR, Small]	  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
AM26-23RB MB-515143 Lancer = C11 Suspension Rubber [RE, Big]	  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	AM26-23RS MB-515142 Lancer = C11 Suspension Rubber [RE, Small]	  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-26R MB-808910</p> <p>Lancer / Colt / Mirage / Veryca [1993-1996] = CB1, CB2, CK2, CK5</p> <p>Front Lower Arm Bush [FR, Big, RH]</p>	<p>AM24-26L MB-808909</p> <p>Lancer / Colt / Mirage / Veryca [1993-1996] = CB1, CB2, CK2, CK5</p> <p>Front Lower Arm Bush [FR, Big, LH]</p>
<p>AM24-26S MR-130983</p> <p>Lancer / Colt / Mirage / Veryca [1993-1996] = CB1, CB2, CK2, CK5</p> <p>Front Lower Arm Bush [FR, Small]</p>	
<p>AM24-26LCR2Z MR-241342</p> <p>Lancer / Colt / Mirage / Veryca [1995-2003] = CB1, CB2, CK2, CK5</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>AM24-26LCL2Z MR-241341</p> <p>Lancer / Colt / Mirage / Veryca [1995-2003] = CB1, CB2, CK2, CK5</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

mitsubishi













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

AM24-CS3WB MR-403441  Mitsubishi Lancer [2000-2009] = CS1A, CS3A Mitsubishi Outlander [2002-2006] = CU2W, CU4W, CU5W..[4] Front Lower Arm Bush [FR, Big]	AM24-CS3WT MR-403441T  Mitsubishi Lancer [2000-2009] = CS1A, CS3A Mitsubishi Outlander [2002-2006] = CU2W, CU4W, CU5W..[4] Front Lower Arm Bush [FR, Big]
AM24-CS3WS MR-403440  Lancer / Cedia [2000-2006] = CS1, CS2, CS3, CS3, CS5, CS6, CS7, CS9 Outlander / Airtrek / Mivec [20] Front Lower Arm Bush [FR, Small]	AM24-CU2WS 4013A129  Outlander [2002-2006] = CU2W, CU5W Airtrek [2001-2005] = CU2W, CU4W, CU5W Front Lower Arm Bush [FR, Small]
AM24-CS3LCR1Z MR-403420  Lancer / Cedia [2003-2006] = CS3, CS5 Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	AM24-CS3LCL1Z MR-403419  Lancer / Cedia [2003-2006] = CS3, CS5 Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]
AM24-CS3LCR2Z MR-961392  Outlander [2003-2006] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	AM24-CS3LCL2Z MR-961391  Outlander [2003-2006] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM24-CY4WB MN-184133  Lancer [2006-2010] = CY2, CY4 Outlander [2006-2009] = CW5, CW6  Front Lower Arm Bush [FR, Big]	AM24-CY4WS MN-125871  Lancer [2006-2010] = CY2, CY4 Outlander [2006-2009] = CW5, CW6  Front Lower Arm Bush [FR, Small]
AM24-CY4LCR1Z 4013A150  Lancer / Cedia / COLT [2004] = Z32, Z34, Z36, Z39A Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	AM24-CY4LCL1Z 4013A135  Lancer / Cedia / COLT [2004] = Z32, Z34, Z36, Z39A Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]
AM24-CY4LCR3Z 4013A010  Lancer / FORTIS / OUTLANDER [2008] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	AM24-CY4LCL3Z 4013A009  Lancer / FORTIS / OUTLANDER [2008] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]
AM24-CS9LCR3Z 4013A273  Lancer [2008] = CS9 Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	AM24-CS9LCL3Z 4013A272  Lancer [2008] = CS9 Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : http://www.rbi.ae http://www.alafuae.com

Revision : 2014-November-01

MITSUBISHI

AM25-28B MR-102014  Lancer = CB1, CB2, CK2, CK5 Rear Suspension Bush [RE, Big]	RBI-OLD RBI Product, Perfect Product, HFC Product, shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM25-28B2 MB-809222  Carisma [1995-2003] = DA Lancer / Mirage [1995-2000] = CK Space Star [1998-2004] = DG1A, DG3A, D Rear Suspension Bush [RE]	PFT-2012-March-28 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM25-290 MR-403464  Lancer / Cedia = CB1, CB2, CS3, CS5, CK2, CK5 Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM25-26ES MR-102012  Lancer / Cedia = CB1, CB2, CS3, CS5, CK2, CK5 Rear Suspension Bush [RE, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM25-CS301 MR-491911  Lancer / Cedia = CB1, CB2, CS3, CS5, CK2, CK5 Rear Suspension Bush [RE, Small]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM25-CS302 MR-403485  Lancer = CS3, CS5, Cedia Rear Suspension Bush [RE]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM25-28EAR1Z MR-809221  Mirage [1993-1994] Rear Complete Upper Arm [RE, RH] [With 2 Bush]	HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM25-28EAR1Z MR-809220  Mirage [1993-1994] Rear Complete Upper Arm [RE, LH] [With 2 Bush]	HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM25-28EAR2Z MB-809223  Mirage [1993-1994] Rear Complete Suspension Arm [RE, RH] [With 2 Bush]	HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM25-28EAR2Z MB-809222  Mirage [1993-1994] Rear Complete Suspension Arm [RE, LH] [With 2 Bush]	HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM25-CS3EAR1Z MR-130480  Carisma [1997-2002] Rear Complete Upper Arm [RE, RH] [With 2 Bush]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM25-CS3EAR1Z MR-130479  Carisma [1997-2002] Rear Complete Upper Arm [RE, LH] [With 2 Bush]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		AM25-CS3EA3Z MR-491911  Lancer [2002-2006] Rear Complete Upper Arm [RE, LH, RH] [With 2 Bush]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com



MITSUBISHI

Revision : 2014-November-01

AM25-CS901G MN-100086 Lancer / CEDIA / Outlander [2001-2006] = CS3, CS9, CS5, CS6, CS7, CT9, CN9, CP9, CU2, CU4, CU5 Rear Suspension Bush [RE, Big]	RBI-2009-May-04 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM25-CS901GZ MN-100086 Lancer = CS9, CEDIA Rear Complete Suspension Arm [RE, LH, RH]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM25-CS901T MN-100109 Lancer = CS9, CEDIA Rear Suspension Bush [RE, Big]	RBI-2009-May-04 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM25-CS901S MN-100109 Lancer = CS9, CEDIA Rear Suspension Bush [RE, Small]	RBI-2009-June-09 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM25-CS901TZ MN-100109 Lancer = CS9, CEDIA Rear Complete Suspension Arm [RE, LH, RH]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM25-26EB MB-809262 Lancer = CB1, CB2, CK2, CK5 Rear Suspension Bush [RE, Big]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM25-CS30B MR-519127 Lancer = CS3, CS5, Cedia Rear Suspension Bush [RE, Big]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM25-Z32E01 4120A002 Colt [2002] = Z21A, Z22A, Z23A, Z24A, Z25A, Z26A, Z27A, Z28A Colt [2004] = Z32A, Z34A, Z36A, Z37A, Rear Suspension Bush [RE, Big]	Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM25-CY4AE01 4120A125 Mitsubishi Lancer [2007] = CY2A, CY3A, CY4A Rear Suspension Bush [RE, Big]	RBI-2014-July-14 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM25-CY4E02 4110A012 Mitsubishi Lancer [2007] = CY2A, CY3A, CY4A Rear Suspension Bush [RE]	PFT-2014-January-14 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM25-CY4E05 4113A011AA Mitsubishi Galant Fortis, Lancer Evolution [2007] = CY4A, CZ4A Rear Lower Arm Bush [RE]	TN-2014-May-05 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM25-CW5WE00 MN-101430 Mitsubishi Outlander [2006-2012] = CW5W Rear Suspension Bush [RE, Big]	PFT-2013-August-20 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM26-26E MB-891463</p> <p>Lancer = CB1, CB4, CK2</p> <p>Bushing Sway</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM26-26FB MB-844446</p> <p>Lancer = CB1, CB2</p> <p>Suspension Rubber [FR, Big]</p>   <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM26-26FS MB-844445</p> <p>Lancer = CB1, CB2</p> <p>Suspension Rubber [FR, Small]</p>   <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM26-CK2FB MR-198875</p> <p>Lancer [1997] = CK2, CK5, CK4</p> <p>Suspension Rubber [FR, Big]</p>  <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM26-CK2FS MR-198876</p> <p>Lancer [1997] = CK2, CK5, CK4</p> <p>Suspension Rubber [FR, Small]</p>  <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>














AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM24-N31WL MB-633003 Space Wagon [1991-2000] = N31, N33 Chariot / Space Wagon Grandis [1992-2000] = N33W, N43W RVR [1] Front Lower Arm Bush [FR, Big, LH] 	AM24-N31WR MB-633004 Space Wagon [1991-2000] = N31, N33 Chariot / Space Wagon Grandis [1992-2000] = N33W, N43W RVR [1] Front Lower Arm Bush [FR, Big, RH] 
AM24-N31WS MB-633002 Space Wagon [1991-2000] = N31, N33 Chariot / Space Wagon Grandis [1992-2000] = N33W, N43W Front Lower Arm Bush [FR, Small] 	AM24-N11WS MB-831555 RVR [1992-1997] = N11W, N13W, N21W, N21WG, N23W, N23WG, N28W, N28WG Front Lower Arm Bush [FR, Small] 
AM24-N84WB MR-316074 Space Wagon / Grandis / Nimbus / Savin [1997-2004] = N84 Front Lower Arm Bush [FR, Big] 	AM24-N84WS MR-589033 Space Wagon / Grandis / Nimbus / Savin [1997-2004] = N84 Front Lower Arm Bush [FR, Small] 
AM24-N84WBJ MR-316053 Mitsubishi Chariot, Space Wagon, Grandis [1997-2003] = N84W, N94W Mitsubishi Rvr [1997-2002] = N61 Front Lower Arm Ball Joint [FR, LH, RH] 	
AM24-N84LCRZ MR-589034 Space Wagon / Grandis / Nimbus / Savin [1997-2004] = N84 Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush] 	AM24-N84LCLZ MR-589033 Space Wagon / Grandis / Nimbus / Savin [1997-2004] = N84 Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush] 





AL LAMSA AL FIDDIYA TRADING L.L.C.







ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-NA4WB MR-594320</p> <p>Space Wagon [2002-2008] = NA4</p> <p>Front Lower Arm Bush [FR, Big]</p>   <p>RBI-2008-March-04 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM24-NA4WS MR-594325</p> <p>Space Wagon [2002-2008] = NA4</p> <p>Front Lower Arm Bush [FR, Small]</p>   <p>RBI-2007-May-07 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM24-NA4LCRZ 4013A236</p> <p>Space Wagon [2002-2008] = NA4</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM24-NA4LCLZ 4013A235</p> <p>Space Wagon [2002-2008] = NA4</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



MITSUBISHI

Revision : 2014-November-01

AM25-N2100 MB-515563  Space Wagon = N21W, N41W, N43W Rear Suspension Bush [RE]	RBI-2006-June-05 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM25-N61E01 MR-369082 Pajero / Montero Sport Challenger [1996-2006] = K94W, K99W RVR [1997-2002] = N61W, N64W, N64WG, N7 Rear Suspension Bush [RE]	PFT-2012-November-07 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM25-N61E02 MR-297054 Chariot / Space Wagon Grandis [1997-2003] = N84W, N94W RVR [1997-2002] = N61W, N64W, N64WG, N71W, Rear Suspension Bush [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM25-N61E03 MR-333422 Chariot / Space Wagon Grandis [1997-2003] = N84W, N94W RVR [1997-2002] = N61W, N64W, N64WG, N71W, Rear Suspension Bush [RE]	HFC-2014-November-20 HFC Product www.rbi.ae
AM25-N61E04 4125A020 Chariot / Space Wagon / Space Runner / Grandis / RVR [1991-2009] = N11, N13, N18, N21, N23, N28, N33 Rear Lower Arm Bush [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM25-N61E05 MR-316027 Chariot / Space Wagon Grandis [1997-2003] = N84W, N94W RVR [1997-2002] = N61W, N64W, N64WG, N71W, Rear Suspension Bush [RE]	Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM25-N61E06 MR-316028 Chariot / Space Wagon Grandis [1997-2003] = N84W, N94W RVR [1997-2002] = N61W, N64W, N64WG, N71W, Rear Suspension Bush [RE]	Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM25-NA4E01 MN-103500 Grandis [2003-2009] = NA4W, NA8W Rear Suspension Bush [RE]	PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM26-N31FB MB-808747 Space Wagon [1991-2000] = N31, N33 Suspension Rubber [FR, Big]	RBI-2006-May-01 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM26-N31FS MB-808748 Space Wagon [1991-2000] = N31, N33 Suspension Rubber [FR, Small]	RBI-2006-May-01 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-44P MB-430462</p> <p>L200 / Triton [1983-1994] Pajero = K64, K14, Strada</p> <p>Front Upper Arm Bush [FR]</p>	<p>AM24-45P MR-124880</p> <p>Pajero [1983-2000] = K77 [4WD], Strada [4WD]</p> <p>Front Upper Arm Bush [FR]</p>







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-41W MB-109529</p>  <p>L200 / Triton [1983-1994]</p> <p>Front Lower Arm Bush [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM24-43W MB-109528</p>  <p>Pajero = K14</p> <p>Front Lower Arm Bush [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM24-45WB MB-109662</p>  <p>Pajero [1983-2000] = K77 [4WD], Strada [4WD]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM24-K77W MB-633870</p>  <p>Pajero = K77 [4WD], Strada, Montero [1995-1996]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM24-41LC1RZZ MB-109513</p>  <p>L200 / Triton [1983-1994]</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>HFC Product shabbirh@eim.ae www.alafuae.com</p> 











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM24-T02P 4010A017  L200 / Triton [2WD] Front Upper Arm Bush [FR]	RBI-2007-May-28 RBI Product, Perfect Product, shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AM24-T04P 4010A013  L200 / Triton [4WD] Front Upper Arm Bush [FR]	RBI-2007-April-03 RBI Product, Perfect Product, Ashimori Product, shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AM24-V75P MR-519398  Pajero [1995-2004] = V45, V75 [3.5] Front Upper Arm Bush [FR]	RBI-2009-August-04 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AM24-V75PLZ 4010A037 ARP Product www.rbi.ae Mitsubishi Pajero III Montero [2000-2006] = V65W, V75W Mitsubishi Pajero IV Montero [2006] = V87W, Front Complete Upper Arm [FR, LH]		AM24-V75PRZ 4010A038 ARP Product www.rbi.ae Mitsubishi Pajero III Montero [2000-2006] = V65W, V75W Mitsubishi Pajero IV Montero [2006] = V87W, Front Complete Upper Arm [FR, RH]	
AM24-T04UC2RZ 4010A014 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  L200 / Triton [4WD] [2006] = KB4T Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]		AM24-T04UC2LZ 4010A013 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  L200 / Triton [4WD] [2006] = KB4T Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]	





AL LAMSA AL FIDDIYA TRADING L.L.C.








ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-T02W MR-992410</p>  <p>L200 / Triton [2WD]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2007-June-18 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM24-T04W MR-992256</p>  <p>L200 / Triton [4WD]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2007-March-24 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM24-V75WB MR-510417</p>  <p>Pajero [2001-2004] = V75 [3.5]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2009-August-04 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM24-V75WS MR-510417</p>  <p>Pajero [2001-2004] = V75 [3.5]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-2009-July-14 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

<p>AM25-450 MR-374327</p> <p>Pajero = K77 [4WD], Strada</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM25-K57E MR-267949</p> <p>G-Wagon = K57</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2008-October-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM25-V43E MB-631492</p> <p>Pajero [1995-1999] = V43, V45</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2007-May-28 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM25-V45E MR-112891</p> <p>Pajero [1995-1999] = V43, V45</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2007-May-07 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM25-PG40 MR-210731</p> <p>Pajero / Montero Sport Challenger [1996-2006] = K94W, K99W Pajero / Montero Sport Challenger [2008]</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2012-April-26 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM25-PG4E 4113A085</p> <p>Pajero / Montero Sport Challenger [1996-2006] = K94W, K99W Pajero / Montero Sport Challenger [2008]</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2012-April-05 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM25-V45E4 MR-374677</p> <p>Pajero</p> <p>Rear Suspension Bush [RE]</p>	<p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  		



MITSUBISHI

Revision : 2014-November-01

<p>AM25-V73E MR-374575</p>  <p>Pajero [1999] = V65W, V63W, V73</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2009-November-28 RBI Product, Perfect Product, HFC Product, Ashimori Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM25-V736 MR-374574</p>  <p>Pajero [1999] = V65W, V63W, V73</p> <p>Rear Suspension Bush [RE]</p>	<p>PFT-2012-March-28 Perfect Product, HFC Product, Ashimori Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-V736B MR-992363</p>  <p>L200 [2005] = KB4T Nativia [2008] = KH8W Pajero Sport [2008] = KH8W Pajero / Montero Sport Chal</p> <p>Rear Suspension Bush [RE]</p>
<p>AM25-V730 MR-554076</p>  <p>Pajero [1999] = V65W, V63W, V73</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2010-January-29 RBI Product, HFC Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<p>AM25-V731 MR-418671</p>  <p>Pajero [1999-2004] = V65W, V63W, V73, V75, V78</p> <p>Rear Suspension Bush [RE]</p>
<p>AM25-V75E MR-510418</p>  <p>Mitsubishi Pajero III Montero [2000-2006] = V65W, V75W Mitsubishi Pajero IV Montero [2006] = V87W,</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2008-July-11 RBI Product, Perfect Product, Tenacity Product, HFC Product</p>  <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM25-V750E MR-374672</p>  <p>Pajero [2001-2004] = V75 [3.5]</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2009-November-03 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<p>AM25-V750E2 MR-990882</p>  <p>Pajero III Montero [2000-2006] = V65W, V75W Pajero III Montero [2000-2006] = V75W Pajero IV Mont</p> <p>Rear Suspension Bush [RE]</p>
<p>AM25-V758AB 3770A015B</p>  <p>Pajero III Montero [2000-2006] = V65W, V75W Pajero III Montero [2000-2006] = V75W Pajero IV Mont</p> <p>Rear Suspension Bush [RE, Big]</p>	<p>PFT-2014-May-25 Perfect Product, HFC Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<p>AM25-V758AS 3770A015S</p>  <p>Pajero III Montero [2000-2006] = V65W, V75W Pajero III Montero [2000-2006] = V75W Pajero IV Mont</p> <p>Rear Suspension Bush [RE, Small]</p>
<p>AM25-V75E00 MR-374674</p>  <p>Pajero [1999-] = V65, V68, V75, V78</p> <p>Rear Suspension Bush [RE]</p>	<p>PFT-2013-March-10 Perfect Product, HFC Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<p>AM25-V75E02 MR-210418</p>  <p>Mitsubishi Pajero III Montero [2000-2006] = V65W, V75W Mitsubishi Pajero IV Montero [2006] = V87W,</p> <p>Rear Suspension Bush [RE]</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

mitsubishi

Revision : 2014-November-01

<p>AM26-V43E MB-809388</p> <p>Pajero [1992-1998] = V43</p> <p>Rear Suspension Bush [RE]</p>   <p>RBI-2007-October-22 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM26-V454 MB-584166</p> <p>Pajero [V6]</p> <p>Bushing Sway [RE]</p>   <p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-V458 MB-633900</p> <p>Pajero II [1991-1999] = V14W-V55W Pajero II [1991-2004] = V14W-V55W</p> <p>Rear Shock Absorber Bush [FR]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-V7200E MR-519399</p> <p>Pajero [1995-2004] = V45, V73, V75 [3.5]</p> <p>Rear Upper Arm Bush [RE]</p>   <p>PFT-2013-June-25 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-H76WB MR-210222</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77 EK-Series [2001-2004] = H81W Minicab / Minicab T</p> <p>Front Lower Arm Bush (FR, Big)</p> <p><small>PFT-2014-March-25 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AM24-H76BJ 54503-22A00</p> <p>Hyundai Accent 11, Blue [2011] .. [USA] Hyundai Accent, Excel [1994-1999] Hyundai Accent, Verna</p> <p>Front Lower Arm Ball Joint (FR, LH, RH)</p> <p><small>Tenacity Product www.rbi.ae</small></p>
<p>AM25-H76E1 MR-353951</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77</p> <p>Rear Suspension Bush (RE)</p> <p><small>PFT-2012-March-28 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AM25-H76E2 MR-418807</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77</p> <p>Rear Suspension Bush (RE)</p> <p><small>PFT-2012-March-28 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p>AM25-H76E3 MR-223791</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77</p> <p>Rear Suspension Bush (RE)</p> <p><small>PFT-2012-March-28 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	
<p>AM25-H76E05 MR-353961</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77 I [AI] [2007] = HA1W, HA3W</p> <p>Rear Suspension Bush (RE)</p> <p><small>PFT-2012-November-07 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AM25-H76E06 MR-448439</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77 I [AI] [2007] = HA1W, HA3W</p> <p>Rear Suspension Bush (RE)</p> <p><small>PFT-2012-November-07 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>



MITSUBISHI

Revision : 2014-November-01

<p>AM25-H76E07 MR-223792</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2012-August-30 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-H76E08 MR-510327</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2013-March-10 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-H76E09 MR-418404</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77 Pajero JR [1995-1998] = H57</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2012-December-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-H76E10 MB-672106</p> <p>Pajero IO [1998-2005] = H61, H65, H66, H76, H77 Pajero JR [1995-1998] = H57 Pajero MINI [1994] =</p> <p>Rear Suspension Bush [RE]</p> <p>ASH-2013-July-10 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-H76E11 MR-151935</p> <p>Pajero MINI [1994] = H51A, H53A, H56A, H58A</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-H76E12 MR-151936</p> <p>Pajero MINI [1994] = H51A, H53A, H56A, H58A</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2012-November-07 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-H76E13 MB-339157</p> <p>Pajero MINI [1994] = H51A, H53A, H56A, H58A</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM25-H76E14 MR-272768</p> <p>Pajero IO [1998-2000] = H65, H66, H76</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM25-H51E01 MR-210670</p> <p>Pajero MINI [1994-1995] = H51, H56, H57</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-H51E02 MR-267543</p> <p>Pajero MINI [1995-2003] = H51, H53, H56, H57, H58</p> <p>Rear Suspension Bush [RE]</p> <p>PFT-2013-April-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-HA1WE01 4113A029</p> <p>I [AI] [2007] = HA1W, HA3W</p> <p>Rear Suspension Bush [RE]</p> <p>ARP Product www.rbi.ae</p>	<p>AM25-HA1WE02 4113A028</p> <p>I [AI] [2007] = HA1W, HA3W</p> <p>Rear Suspension Bush [RE]</p> <p>ARP Product www.rbi.ae</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI


Revision : 2014-November-01

AM26-T040

MR-992320

L200 / Triton [4WD] [2006] = KB4T

Front Shock Absorber Bush [FR]



RBI-2012-January-06
RBI Product, Perfect Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com




AM26-T020

MR-992435

L200 / Triton [2WD] [2006]

Front Shock Absorber Bush [FR]



RBI-2012-May-09
RBI Product, Perfect Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-621P00 MB-430201</p> <p>L300 / Delica = P15V</p> <p>Front Upper Arm Bush [FR]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM24-62PB MB-430200</p> <p>L300 / Delica = P15V</p> <p>Front Upper Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AM24-621UC3RZ MB-598546</p> <p>L300 / Delica [1986-1994] [2WD] [2500]</p> <p>Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM24-621UC3LZ MB-598545</p> <p>L300 / Delica [1986-1994] [2WD] [2500]</p> <p>Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]</p>	<p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM24-61W

MB-109936

L300 / Delica = L031

Front Lower Arm Bush [FR, Small]



RBI-OLD
RBI Product, Perfect Product,
Ashimori Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com



AM24-62W

MR-319537

L300 / Delica = P15V

Front Lower Arm Bush [FR]



RBI-OLD
RBI Product, Perfect Product,
HFC Product, Ashimori
Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM24-PD4PS MB-672031 Delica [1994-2004] = PD4W, PD6W, PD8W Rosa [1997] = BG642 Front Upper Arm Bush [FR, Small]	AM24-PD4PB MB-672030 Delica [1994-2004] = PD4W, PD6W, PD8W Rosa [1997] = BG642 Front Upper Arm Bush [FR, Big]
AM24-PA4WB MR-112709 Delica Space Gear, Cargo [1994-2006] = PA, PB, PC Delica Truck [1994-1999] = P02T, P05T, P13T, P15 Front Lower Arm Bush [FR, Big]	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM25-63040 MR-112710</p> <p>L300 / Delica = PD#, PF [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-63041 MR-112711</p> <p>L300 / Delica = PD#, PF [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-63042 MB-430960</p> <p>L300 / Delica = P25W [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-63043 MB-633070</p> <p>L300 / Delica = P25W [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-PD4E01 MB-951814</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W Delica Space Gear / Cargo [1994-2006] = PA, PB, PC L400 Sp</p> <p>Rear Suspension Bush [RE]</p>	<p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-PD4E02 MB-951813</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W Delica Space Gear / Cargo [1994-2006] = PA, PB, PC L400 Sp</p> <p>Rear Suspension Bush [RE]</p>	<p>Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-PD4E03 MB-951815</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W Delica Space Gear / Cargo [1994-2006] = PA, PB, PC L400 Sp</p> <p>Rear Suspension Bush [RE]</p>	<p>ASH-2013-July-10 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-PD4E04 MR-210480</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W Delica Space Gear / Cargo [1994-2006] = PA, PB, PC L400 Sp</p> <p>Rear Suspension Bush [RE]</p>	<p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM25-PD4E05 MR-151760</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W Delica Space Gear / Cargo [1994-2006] = PA, PB, PC L400 Sp</p> <p>Rear Suspension Bush [RE]</p>	<p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>		
<p>AM25-630 MB-951444</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W Delica Space Gear / Cargo [1994-2006] = PA, PB, PC L400 Sp</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2006-May-25 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM25-631 MB-951445</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W Delica Space Gear / Cargo [1994-2006] = PA, PB, PC L400 Sp</p> <p>Rear Suspension Bush [RE]</p>	<p>RBI-2006-June-05 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM24-T210W00 MT-141213</p> <p>Mitsubishi L300 [1986] = P0#, P1#, P2#, P45V, L03# Mitsubishi L300 [1986] = P15V</p> <p>Front Lower Arm Bush [FR]</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM25-DG5E00 MR-911439</p> <p>Space Star / Carisma [1997-2001] = DG5A, DA2A</p> <p>Rear Suspension Bush [RE]</p>	<p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM24-FB70P MK-335060</p> <p>Canter [2003] = FB70AB</p> <p>Front Upper Arm Bush [FR]</p>	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM24-FG30P MB-161668</p> <p>Ashimori Product www.rbi.ae</p> <p>CANTER = FG3#, FG5# [4WD]</p> <p>Front Upper Arm Bush [FR]</p>
<p>AM24-FB70WB MK-335141</p> <p>Canter [2003] = FB70AB</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2013-October-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM24-FB70WS MK-335140</p> <p>PFT-2013-October-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Canter [2003] = FB70AB</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>AM25-CD8E01 MB-891644</p> <p>Libero [1992-2000] = CD8W [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM25-CD8E02 MB-892298</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Libero [1992-2000] = CD8W [4WD]</p> <p>Rear Suspension Bush [RE]</p>
<p>AM25-CD8E03 MB-948295</p> <p>Libero [1992-2000] = CD8W [4WD]</p> <p>Rear Suspension Bush [RE]</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

mitsubishi

Revision : 2014-November-01

AM24-VAR93WB  Mitsubishi VARICA [1992-1997] Front Lower Arm Bush [FR, Big]	AM24-VAR93WS  Mitsubishi VARICA [1998-2000] Front Lower Arm Bush [FR, Small]













MITSUBISHI

Revision : 2014-November-01

<p>AM27-210 MB-001626</p> <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant = A53</p> <p>Stabilizer Link [FR, LH, RH]</p>	
<p>AM27-E38F00 MB-584467</p> <p>PFT-2014-January-01 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant / Eterna [1988-1992] = E38A, E39A Diamante [1990-1994] = F11A, F12A, F13A, F15A, F17A, F25A</p> <p>Link Assy [FR, LH, RH]</p>	<p>AM27-E38F0 4056A039</p> <p>RBI-2013-July-19 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant / Eterna [1988-1992] = E38A, E39A Diamante [1990-1994] = F11A, F12A, F13A, F15A, F17A, F25A</p> <p>Link Assy [FR, LH, RH]</p>
<p>AM27-07F MB-892981</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant / Eterna [1992-2000] = E54, E55, E56A, E70, E88, D2A, EC7A</p> <p>Link Assy [FR, LH, RH]</p>	<p>AM27-07E MB-892982</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant / Eterna [1987-2000] = E33, E52, E53, E54, E55, EA1A</p> <p>Link Assy [RE, LH, RH]</p>
<p>AM27-EA3FL MR-297333</p> <p>RBI-2013-March-01 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant USA [1996-2003] = EA3A, EA8A</p> <p>Link Assy [FR, LH]</p>	<p>AM27-EA3FR MR-333763</p> <p>RBI-2013-March-01 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant USA [1996-2003] = EA3A, EA8A</p> <p>Link Assy [FR, RH]</p>
	<p>AM27-EA3E00 MR-333762</p> <p>TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant USA [1996-2003] = EA3A, EA8A Diamante [1990-1994] = F11A, F12A, F13A, F15A, F17A, F25A, F27</p> <p>Link Assy [RE, LH, RH]</p>
<p>AM27-DJ1E00 MR-589336</p> <p>RBI-2013-February-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [2006] = DJ1A, DJ3A, DJ5A Eclipse USA [2006] = DK2A, DK4A Endeavor [2003] = D71W, D81W</p> <p>Link Assy [RE, LH, RH]</p>	<p>AM27-DJ1F00 MR-589437</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Galant [2006] = DJ1A, DJ3A, DJ5A Eclipse USA [2006] = DK2A, DK4A</p> <p>Link Assy [FR, LH, RH]</p>
<p>AM27-D71E00 MR-589337</p> <p>ARP Product www.rbi.ae</p> <p>Endeavor [2003] = D71W, D81W</p> <p>Link Assy [RE, LH, RH]</p>	

MITSUBISHI

Revision : 2014-November-01

<p>AM27-230 MB-241974</p> <p>Lancer / Cedia [1991-1996] = C11, CB1, CB2</p> <p>Stabilizer Link [FR, LH, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-CB1E00 MR-954888</p> <p>Mitsubishi Lancer Station Wagon [1992-2002] = CB#W Mitsubishi Lancer, Colt [1991-1995] = CA, CB </p> <p>Stabilizer Link [RE]</p>  <p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-26E MB-809354</p> <p>Lancer / Cedia [1991-1996] = CB1, CB2, CB4, DE3A, CA4A, CB4A, CC4A, CG4A, CK4K, CD5A, CM5A, CD9A, CE</p> <p>Link Assy [RE, LH, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM27-CK200 MR-954887</p> <p>Lancer / Cedia / Mirage [1995-2009] = CK2, CK4, CK5, CS3, CS5, CS, CJ, CK Airtrek [2001-2005] = CU</p> <p>Stabilizer Link [FR, LH, RH]</p>  <p>TN-2014-February-10 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-28E MB-860011</p> <p>Lancer / Cedia [1997-2001] = CK2, CK5</p> <p>Stabilizer Link [RE, LH, RH]</p>  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-CS3F 4056A040</p> <p>Lancer / Cedia [2000-2006] = CS3</p> <p>Link Assy [FR, LH, RH]</p>  <p>RBI-2013-March-14 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM27-CS9F MR-319147</p> <p>Lancer / Cedia [2000-2006] = CS3, CS9 OUTLANDER [2002-2006] = CU2W, CU5W AIRTREK [2001-2005] = C</p> <p>Link Assy [FR, LH, RH]</p>  <p>ASH-2014-May-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-CS9E 4056A037</p> <p>Lancer / Cedia [2000-2006] = CS3, CS9</p> <p>Link Assy [RE, LH, RH]</p>  <p>RBI-2008-June-05 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-CT9AEL MB-856476</p> <p>Lancer Evolution [2001-2005] = CT9A</p> <p>Link Assy [RE, LH]</p>  <p>Ashimori Product www.rbi.ae</p>	<p>AM27-CT9AER MB-856475</p> <p>Lancer Evolution [2001-2005] = CT9A</p> <p>Link Assy [RE, RH]</p>  <p>Ashimori Product www.rbi.ae</p>
<p>AM27-CU2WFL MR-316368</p> <p>Outlander [2002-2006] = CU2W, CU4W, CU5W.. [4WD]</p> <p>Link Assy [RE, LH]</p>  <p>TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-CU2WFR MR-316369</p> <p>Outlander [2002-2006] = CU2W, CU4W, CU5W.. [4WD]</p> <p>Link Assy [RE, RH]</p>  <p>TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM27-CY2EL 4156A014</p> <p>Lancer / Cedia [2007-2011] = CY2A, CY3A, CY4A OUTLANDER [2006] = CW# DELICA [2006] = D5 CV5W A</p> <p>Link Assy [RE, LH]</p>	<p>AM27-CY2ER MN-184194</p> <p>Lancer / Cedia [2007-2011] = CY2A, CY3A, CY4A OUTLANDER [2006] = CW# DELICA [2006] = D5 CV5W A</p> <p>Link Assy [RE, RH]</p>
<p>AM27-CY2FLR MN-101368</p> <p>Lancer / Cedia [2007-2011] = CY2A, CY3A, CY4A OUTLANDER [2006] = CW5, CW6</p> <p>Link Assy [FR, LH, RH]</p>	
<p>AM27-Z21F00 4056A050</p> <p>Mitsubishi Colt [2002] = Z21A, Z22A, Z23A, Z24A, Z25A, Z26A, Z27A, Z28A</p> <p>Stabilizer Link [FR, LH, RH]</p>	
<p>AM27-Z32E00 4056A052</p> <p>Colt [2004] = Z32A, Z34A, Z36A, Z37A, Z38A, Z39A Ford Focus I [1998-2005] = CAK</p> <p>Link Assy [RE, LH, RH]</p>	






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

mitsubishi

Revision : 2014-November-01

<p>AM27-DG1F00 MR-392730</p> <p>SPACE STAR / CARISMA [1995-2004] = DG1A, DG3A, DG4A, DG5A</p> <p>Stabilizer Link [FR, LH, RH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM27-DG1E00 MR-465000</p> <p>Mitsubishi Carisma [1995-2003] = DA Mitsubishi Space Star [1998-2004] = DG1A, DG3A, DG4A, DG5A V</p> <p>Link Assy [RE, LH, RH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM27-DA1F00 MR-272116</p> <p>Carisma [1995-2003] = DA1</p> <p>Link Assy [FR, LH, RH]</p> <p>RBI-2014-September-04 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
























AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM27-N31FL MB-672370  Chariot, Space Wagon, Grandis [1992-2000] = N31W, N33W, N43W Rvr [1992-1997] = N11W, N13W, N21W, N Link Assy [FR, LH]	RBI-OLD RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM27-N31FR MB-808076  Chariot, Space Wagon, Grandis [1992-2000] = N31W, N33W, N43W Rvr [1992-1997] = N11W, N13W, N21W, N Link Assy [FR, RH]	RBI-OLD RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM27-N50FL 4056A034  Space Wagon [1997-2002] = N50 Link Assy [FR, LH]	RBI-2013-March-01 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM27-N50FR 4056A035  Space Wagon [1997-2002] = N50 Link Assy [FR, RH]	RBI-2013-February-19 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM27-N84FL MR-316435  Chariot, Space Wagon, Grandis [1997-2003] = N84W, N94W Link Assy [FR, LH]	ASH-2013-November-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM27-N84FR MR-316436  Chariot, Space Wagon, Grandis [1997-2003] = N84W, N94W Link Assy [RE, RH]	ASH-2013-November-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM27-N84E00 MR-316437  Chariot, Space Wagon, Grandis [1997-2003] = N84W, N94W Link Assy [RE]	Ashimori Product www.rbi.ae		
AM27-NA4FL MR-594339  Grandis, Space Wagon [2002-2009] = NA4W, NA8W Link Assy [FR, LH]	RBI-2006-May-01 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM27-NA4FR MR-594340  Grandis, Space Wagon [2002-2009] = NA4W, NA8W Link Assy [FR, RH] [2 Heads]	RBI-2006-May-01 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM27-220 MB-241429  Space Wagon [2002-2008] = NA4 A72 A173 Stabilizer Link [RE]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		

















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM27-410 MB-527168</p> <p>L200 / Triton = E12, K14</p> <p>Stabilizer Link</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM27-T04FL MR-992309</p> <p>L200 / Triton [4WD] [2005] = KB4T</p> <p>Link Assy [FR, LH] [2 Heads]</p>   <p>RBI-2006-July-25 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-T04FR MR-992310</p> <p>L200 / Triton [4WD] [2005] = KB4T</p> <p>Link Assy [FR, RH]</p>   <p>RBI-2006-July-25 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-PA4F00 MR-132707</p> <p>L400 / SPACE GEAR / DELICA [1994-2006] = PA3W, PA4W, PD4W, PD5W DELICA TRUCK [1994-2006] = P02T, P</p> <p>Link Assy [FR, LH, RH]</p>   <p>RBI-2013-May-28 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-PD4F00 MR-150705</p> <p>L400 / SPACE GEAR / DELICA [1994-2004] = PD4W, PD5W, PD6W, PD8W</p> <p>Link Assy [FR, LH, RH]</p>   <p>RBI-2013-July-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-PA4E00 MB-185476</p> <p>L400 / SPACE GEAR / DELICA [1994-2006] = PA3W, PA4W, PD4W, PD5W, PD6W, PD8W PAJERO I [1989-1990] =</p> <p>Link Assy [RE, LH, RH]</p>   <p>RBI-2013-May-28 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	



REVISION : 2014-NOVEMBER-01

MITSUBISHI

<p>AM27-440 MB-598097</p> <p>Mitsubishi Strada [1993-1997-1999] = K34T, K74T Mitsubishi Strada 2500 [1996] = K64T..4D56 [Diesel]</p> <p>Stabilizer Link</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM27-K57F00 MR-990044</p> <p>Pajero, Strada / G-Wagon [2002] = K54, K57</p> <p>Stabilizer Link [FR]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-STR001 33440011</p> <p>Pajero, Strada</p> <p>Stabilizer Link</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-V14F00 MB-831039</p> <p>Pajero II [1991-2004] = V14W-V55W</p> <p>Stabilizer Link [FR, LH, RH]</p> <p>HFC Product www.rbi.ae</p>	
<p>AM27-V40FL MB-267877</p> <p>Pajero / Montero [1991-1999] = V21, V23, V24, V25, V26, V43, V44, V45, V46, V47, P25</p> <p>Link Assy [FR, RH]</p> <p>PFT-2012-August-30 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-V40FR MB-267876</p> <p>Pajero / Montero [1991-1999] = V21, V23, V24, V25, V26, V43, V44, V45, V46, V47, P25</p> <p>Link Assy [FR, RH]</p> <p>PFT-2012-August-30 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-V43FL MR-132552</p> <p>Pajero / Montero [1991-1999] = V21, V23, V24, V25, V26, V43, V44, V45, V46, V47, P25</p> <p>Link Assy [FR, RH]</p> <p>PFT-2012-August-30 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-V43FR MR-132551</p> <p>Pajero / Montero [1991-1999] = V21, V23, V24, V25, V26, V43, V44, V45, V46, V47, P25</p> <p>Link Assy [FR, RH]</p> <p>PFT-2012-August-30 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AM27-V43E00 4056A138</p> <p>Pajero II / Montero [1991-2004] = V14W TO V55W, V43, V45</p> <p>Stabilizer Link [RE, LH, RH]</p> <p>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-V45F MB-633926</p> <p>Pajero II / Montero [1991-2004] = V14W TO V55W, V43, V45</p> <p>Link Assy [FR, LH, RH]</p> <p>RBI-2009-June-09 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-V45E00 MB-598098</p> <p>Pajero II / Montero [1991-2004] = V14W TO V55W, V43, V45 Pajero I [1989-1990] = L041G-L149G Paje</p> <p>Stabilizer Link [RE, LH, RH]</p> <p>ASH-2013-November-15 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM27-K94F00 MR-267643</p> <p>Pajero / Montero Sport Challenger [1996-2006] = K94W, K99W Nativa [1997-2007] = K94W L200 [1996-</p> <p>Stabilizer Link [FR, LH, RH]</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM27-K94E00 MR-344624</p> <p>Pajero / Montero Sport Challenger [1996-2006] = K94W, K99W Nativa [1997-2007] = K94W</p> <p>Stabilizer Link [RE, LH, RH]</p> <p>PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>

MITSUBISHI

Revision : 2014-November-01

AM27-V73FL MR-374521  Pajero / Montero [1999-2010] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V98 Link Assy [FR, LH] [2.5DIE, 2.8DIE, 3.0, 3.2DIE, 3.5, 3.8]	AM27-V73FR MR-374522  Pajero / Montero [1999-2010] = V63, V64, V65, V66, V67, V68, V73, V74, V75, V76, V77, V78, V98 Link Assy [FR, RH] [2.5DIE, 2.8DIE, 3.0, 3.2DIE, 3.5, 3.8]
AM27-V93FL 4056A133  Pajero / Montero [2008-2011] = V73, V77, V83, V87, V88, V93, V96, V97, V98 Link Assy [FR, LH] [2.8DIE, 3.0, 3.2DIE, 3.8]	AM27-V93FR 4056A134  Pajero / Montero [2008-2011] = V73, V77, V83, V87, V88, V93, V96, V97, V98 Link Assy [FR, RH] [2.8DIE, 3.0, 3.2DIE, 3.8]
AM27-V97FL MR-992191  Pajero / Montero [2008-2011] = V73, V77, V83, V87, V88, V93, V96, V97, V98 Link Assy [FR, LH] [2.8DIE, 3.0, 3.2DIE, 3.8]	AM27-V97FR MR-992192  Pajero / Montero [2008-2011] = V73, V77, V83, V87, V88, V93, V96, V97, V98 Link Assy [FR, RH] [2.8DIE, 3.0, 3.2DIE, 3.8]
AM27-V73EL MR-418052  Pajero / Montero [1999-2010] = V65, V63, V68, V73, V75, V78, V75, V98 Link Assy [RE, LH]	AM27-V73ER MR-418053  Pajero / Montero [1999-2010] = V65, V63, V68, V73, V75, V78, V75, V98 Link Assy [RE, RH]
AM27-H77E00 MR-510319  Pajero IO / Pajero PININ [1999-2005] = H61W-H77W Link Assy [RE, LH, RH]	
AM27-HA1WFL 4056A065  Mitsubishi I [AI] [2007] = HA1W, HA3W Link Assy [FR, LH]	AM27-HA1WFR 4056A066  Mitsubishi I [AI] [2007] = HA1W, HA3W Link Assy [FR, RH]



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM28-41E MB-111253</p> <p>L200 / Triton = K14, K64</p> <p>Bumper Bound [RE]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  	<p>AM28-L047W MB-831096</p> <p>Strada [1996-2002] = K54, K57, K77 [2.5, 2.8D] [4D56, 4M40] [4WD] Pajero L047</p> <p>Bumper Bound [Lower]</p>	<p>RBI-2012-August-25 RBI Product, HFC Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  
<p>AM28-41P MB-185502</p> <p>L200 / Triton = K14, K64, K67</p> <p>Bumper Bound [Upper]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  		
<p>AM28-41L MB-185995</p> <p>L200 / Triton = K14, K64</p> <p>Bumper Bound [Lower, LH]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  	<p>AM28-41R MB-185996</p> <p>L200 / Triton = K14, K64</p> <p>Bumper Bound [Lower, RH]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  
<p>AM28-42FP MB-109688</p> <p>L200 / Triton MITSUBISHI STORM 2000-2004</p> <p>Bumper Bound [FR, Upper]</p>	<p>PFT-2012-June-26 Perfect Product, Ashimori Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  	<p>AM28-42L MB-185978</p> <p>L200 / Triton MITSUBISHI STORM 2000-2004</p> <p>Bumper Bound [Lower]</p>	<p>PFT-2012-August-30 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  
<p>AM28-61L MB-109915</p> <p>L300</p> <p>Bumper Bound [Lower, LH]</p>	<p>ARD-2014-January-01 ARD Product, HFC Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  	<p>AM28-61R MB-109916</p> <p>L300</p> <p>Bumper Bound [Lower, RH]</p>	<p>ARD-2014-January-01 ARD Product, HFC Product shabbirh@eim.ae</p> <p>www.rbi.ae www.alafuae.com</p>  





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM28-T02E MR-319973  L200 / Triton [2WD] Bumper Bound [RE]	RBI-2007-December-07 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM28-T02P 4055A006T  L200 / Triton [2WD] Bumper Bound	RBI-2008-February-12 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM28-T02R 4055A010  L200 / Triton [2WD] Bumper Bound [Lower, RH]	RBI-2011-June-04 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM28-T02L 4055A009  L200 / Triton [2WD] Bumper Bound [Lower, LH]	RBI-2011-June-04 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM28-T04E MR-992642  L200 / Triton [4WD] Bumper Bound [RE]	RBI-2007-November-15 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM28-T04P 4055A007T  L200 / Triton [4WD] Bumper Bound	RBI-2008-March-04 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM28-T04W 4055A008T  L200 / Triton [4WD] Bumper Bound [Lower]	RBI-2010-November-02 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM28-PG4E0 MR-584148  Pajero Sports Bumper Bound [RE]	RBI-2012-August-25 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM28-FE111FL MB-025453  Mitsubishi Canter = FE111, FE444, FE449 Bumper Bound [FR, LH]	ARD-2014-January-01 HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AM28-FE111FR MB-025454  Mitsubishi Canter = FE111, FE444, FE449 Bumper Bound [FR, RH]	ARD-2014-January-01 HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AM28-FE112F MB-025162  Mitsubishi Canter = FE111, FE444, FE449 Bumper Bound [FR]	ARD-2014-January-01 ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AM28-FB51100 MC-110180  Canter FB511 Bumper Bound [FR]	Ashimori Product www.rbi.ae		






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM28-0001 MB-025007</p> <p>Mitsubishi</p> <p>Bumper Bound</p>   <p>PFT-2012-March-28 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM28-0002 MB-025008</p> <p>Mitsubishi</p> <p>Bumper Bound</p>   <p>PFT-2012-March-28 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM28-0003 MB-161571</p> <p>Mitsubishi</p> <p>Bumper Bound</p>   <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM28-0004 MB-025126</p> <p>Mitsubishi</p> <p>Bumper Bound</p>   <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM28-0005 MB-185781</p> <p>Mitsubishi Pajero, L200 [4wd]</p> <p>Bumper Bound</p>   <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM28-0009 MR-113271</p> <p>L200 / Triton</p> <p>Bumper Bound</p>   <p>PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM28-K64001 MB-908639</p> <p>Strada [1996-2002] = K54, K57, K77 [2.5, 2.8D] [4D56, 4M40] [4WD]</p> <p>Bumper Bound Hood</p>   <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM28-FN21500 17255-57500</p> <p>Mitsubishi Fuso = FN215</p> <p>Bumper Bound</p>   <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM28-T21000 MT-104718</p> <p>Mitsubishi Canter = T210 [4DR5]</p> <p>Bumper Bound</p>   <p>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM29-CU2E00 MR-953922 Outlander [2002-2006] = CU2W, CU4W, CU5W.. [4WD] Airtrek [2001-2005] = CU# Center Bearing [RE]	HFC-2014-November-20 HFC Product, Ashimori Product  shabbirh@eim.ae www.rbi.ae www.alafuae.com	AM29-CU2F00 MR-953919 Outlander [2002-2006] = CU2W, CU4W, CU5W.. [4WD] Airtrek [2001-2005] = CU# Center Bearing [FR]	HFC-2014-November-20 HFC Product, Ashimori Product  shabbirh@eim.ae www.rbi.ae www.alafuae.com
AM29-CW5G01 3401A022 Citroen C-Crosser [2007] Mitsubishi Asx [2010] = GA# Mitsubishi Outlander [2006-2012] = CW5W P Center Bearing	ARP Product  www.rbi.ae	AM29-CK00 MN-171430 Mitsubishi Lancer, Mirage [1995-2000] = CK Center Bearing	RBI-2014-July-14 RBI Product  www.rbi.ae
AM29-N33G01 MB-505495 Chariot, Space Wagon, Grandis [1992-2000] = N33W, N43W Diamante [1990-1994] = F11A, F12A, F13A, F1 Center Bearing	ARP Product  shabbirh@eim.ae www.rbi.ae www.alafuae.com		
AM29-N84G01 MR-196669 Chariot, Space Wagon, Grandis [1997-2003] = N84W, N94W Rvr [1997-2002] = N61W, N64W, N64WG, N71W, Center Bearing	ARP Product www.rbi.ae		
AM29-PA3G01 MR-165252 Delica Space Gear, Cargo [1994-2006] = PA, PB, PC L400 [1994-2002] = PA3W, PA4W Center Bearing	ARP Product www.rbi.ae		



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM29-430 MB-154080</p>  <p>L200 / Triton = K14</p> <p>Center Bearing</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM29-440RU MB-154199</p>  <p>Strada, K67, K64</p> <p>Center Bearing Rubber</p>	<p>AM29-440 MB-154199</p>  <p>Mitsubishi L200 [1996-2007] = K6#, K7# Mitsubishi Strada [1997-1999] = K74T</p> <p>Center Bearing [2WD]</p>
<p>AM29-450 MR-223119</p>  <p>Mitsubishi L200 [1996-2007] = K6#, K7# Mitsubishi Strada [1997-1999] = K74T</p> <p>Center Bearing [4WD]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM29-K5400 MB-154279</p>  <p>Strada [2002] = K54 [2.5D] [4D56]</p> <p>Center Bearing</p>	<p>AM29-K5700 MB-154285</p>  <p>Strada [2002] = K57 [2.8D] [4M40]</p> <p>Center Bearing</p>
<p>AM29-T0204 MR-580647</p>  <p>L200 / Triton [2WD, 4WD]</p> <p>Center Bearing [2WD, 4WD]</p>	<p>RBI-2012-October-15 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM29-FE111OBE MB-000076  Mitsubishi Canter [1986] = FE211, FE111, FE444, FE449 [Old Model] [4D30] Center Bearing [Bearing Only]	AM29-FE111OM MB-000076  Mitsubishi Canter [1986] = FE211, FE111, FE444, FE449 [Old Model] [4D30] Center Bearing Rubber
AM29-FE111OZ MB-000076  Mitsubishi Canter [1986] = FE211, FE111, FE444, FE449 [Old Model] [4D30] Center Bearing	AM29-FE111OZZ MB-000076  Mitsubishi Canter [1986] = FE211, FE111, FE444, FE449 [Old Model] [4D30] Center Bearing
AM29-FE111NBE MB-563204  Mitsubishi Canter [1986] = FE111, FE444, FE449 [New Model] [4D32] Center Bearing [Bearing Only]	AM29-FE111NM MB-563204  Mitsubishi Canter [1986] = FE111, FE444, FE449 [New Model] [4D32] Center Bearing Rubber
AM29-FE111NZ MB-563204  Mitsubishi Canter [1986] = FE111, FE444, FE449 [New Model] [4D32] Center Bearing	
AM29-FE111OM1 MB-000079  Mitsubishi Canter [1986] = FE111, FE444, FE449 [New Model] [4D32] Center Bearing Metal	AM29-FE111OM2 MB-000080  Mitsubishi Canter [1986] = FE211, FE111, FE444, FE449 [Old Model] [4D30] Center Bearing Metal





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

mitsubishi

Revision : 2014-November-01

<p>AM29-T210Z MT-119504</p> <p>Mitsubishi Canter = T210 [4DR5]</p> <p>Center Bearing</p>	<p>PFT-2012-November-07 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM29-FN21500 12019-28000</p> <p>Mitsubishi Fuso = FN215</p> <p>Center Bearing</p>	<p>PFT-2012-December-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM29-FN52700 MC-802792</p> <p>Mitsubishi Fuso = FN527</p> <p>Center Bearing</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM31-270 MB-252113</p> <p>Pajero</p> <p>Exhaust Pipe Support</p>   <p>RBI-OLD RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AM31-C11F001 MB-252856</p> <p>Lancer Champ [1991] = C11A, C12A</p> <p>Exhaust Pipe Support Rubber [1.3, 1.5]</p>  <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM31-C12F001 MB-376363</p> <p>Lancer Champ [1991] = C12A</p> <p>Exhaust Pipe Support Rubber [1.3, 1.5]</p>  <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM31-CB1001 MB-906121</p> <p>Lancer / Cedia [1991-1997] = C11, CB1, CB2, CB4, CK2, CK4, CK5</p> <p>Exhaust Pipe Support Rubber</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM31-CB1002 MB-906124</p> <p>Lancer / Cedia [1991-1997] = C11, CB1, CB2, CB4</p> <p>Exhaust Pipe Support Rubber</p>  <p>ARD-2014-January-01 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM31-CB1003 MB-906128</p> <p>Lancer / Cedia [1991-1997] = C11, CB1, CB2, CB4, CK2, CK4, CK5</p> <p>Exhaust Pipe Support Rubber</p>  <p>Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM31-CS3F00 MR-529673</p> <p>Lancer / Cedia [2000] = CS2</p> <p>Exhaust Pipe Support</p>  <p>ARD-2014-January-01 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM31-CK2001 MB-612366</p> <p>Lancer / Cedia [1997] = CK2, CK4, CK5</p> <p>Exhaust Pipe Support Rubber</p>  <p>ARP Product www.rbi.ae</p>	<p>AM31-CK2002 MB-925829</p> <p>Lancer / Cedia [1997] = CK2, CK4, CK5</p> <p>Exhaust Pipe Support Rubber</p>  <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AM31-E33001 MB-376954</p> <p>Galant [1988-1994] = E31, E33</p> <p>Exhaust Pipe Support Rubber</p>  <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AM31-E0001 MB-329646</p> <p>Mitsubishi</p> <p>Exhaust Pipe Support Rubber</p>  <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

<p>AM31-K64001 MR-419581</p> <p>Strada / G-Wagon [1996-2002] = K54, K64, K77 [2.5, 2.8D] [2WD, 4WD] [4D56, 4M40]</p> <p>Exhaust Pipe Support Rubber</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM31-K64002 MR-419582</p> <p>Strada / G-Wagon [1996-2002] = K54, K64, K77 [2.5, 2.8D] [2WD, 4WD] [4D56, 4M40]</p> <p>Exhaust Pipe Support Rubber</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM31-K64003 MR-514615</p> <p>Strada / G-Wagon [1996-2002] = K54, K64, K77 [2.5, 2.8D] [2WD, 4WD] [4D56, 4M40]</p> <p>Exhaust Pipe Support Rubber</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM31-K64004 MB-431175</p> <p>Strada / G-Wagon [1996-2002] = K54, K64, K77 [2.5, 2.8D] [2WD, 4WD] [4D56, 4M40] Cyclone / L200 [1]</p> <p>Exhaust Pipe Support Rubber</p> <p>ARD-2014-January-01 ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM31-K64005 MB-612304</p> <p>Strada / G-Wagon [1996-2002] = K54, K64, K77 [2.5, 2.8D] [2WD, 4WD] [4D56, 4M40]</p> <p>Exhaust Pipe Support Rubber</p> <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AM31-T02001 1577A018</p> <p>L200 / Triton = KA4, KB4, KB8 [16V] [2.5, 3.2] [2WD, 4WD]</p> <p>Exhaust Pipe Support Rubber</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AM31-T02002 MR-431633</p> <p>L200 / Triton = KA4, KB4, KB8 [16V] [2.5, 3.2] [2WD, 4WD]</p> <p>Exhaust Pipe Support Rubber</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM31-V14E00 MB-868783</p> <p>Pajero II [1991-2004] = V14W-V55W</p> <p>Exhaust Pipe Support</p> <p>HFC-2014-November-20 HFC Product www.rbi.ae</p>	
<p>AM19-804 MB-150651</p> <p>A72, A121</p> <p>Repair Kit</p> <p>RBI-OLD RBI Product www.rbi.ae</p> 	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MITSUBISHI

<p>AM38-020 MB-076715</p> <p>A156</p> <p>Grommet Steering Rack</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	
<p>AM38-23L MB-288983</p> <p>C11</p> <p>Grommet Steering Rack [LH]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM38-23R MB-266705</p> <p>C11, CB1, CB2, CK2</p> <p>Grommet Steering Rack [RH]</p>
<p>AM38-26L MB-910968</p> <p>CB1, CB2</p> <p>Grommet Steering Rack [LH]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM38-CS3L MR-491363</p> <p>CS3, CS5</p> <p>Grommet Steering Rack [LH]</p>
<p>AM38-CS301 MR-403503</p> <p>Mitsubishi Lancer [2000-2009] = CS1A, CS3A Mitsubishi Galant Fortis, Lancer Evolution [2007] = CY4</p> <p>Grommet Steering Rack Bush</p>	<p>RBI-2010-June-18 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM38-CS302B MN-101388</p> <p>Mitsubishi Galant Fortis, Lancer Evolution [2007] = CY4A, CZ4A Mitsubishi Lancer [2007] = CY2A, CY</p> <p>Grommet Steering Rack</p>
<p>AM38-E3301 MB-315228</p> <p>Galant [1988-1994] = E31, E32, E33</p> <p>Grommet Steering Rack</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	
<p>AM38-T020 4410A184</p> <p>L200 / Triton [2WD]</p> <p>Grommet Steering Rack</p>	<p>RBI-2007-March-03 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM38-T040 4410A185</p> <p>L200 / Triton [4WD]</p> <p>Grommet Steering Rack</p>
<p>AM38-T0204 4410A166</p> <p>Mitsubishi Triton [2006] = KB9T</p> <p>Grommet Steering Rack Bush [2WD, 4WD]</p>	<p>RBI-2014-October-21 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	
<p>AM38-NA400 4410A102</p> <p>Space Wagon / Grandis / Nimbus / Space Runner / Expo / RVR / Savin [2002-2008] = NA4</p> <p>Grommet Steering Rack Bush</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AM38-V75S00 MR-223335</p> <p>Mitsubishi Pajero III Montero [2000-2006] = V65W, V75W Mitsubishi Pajero IV Montero [2006] = V87W,</p> <p>Grommet Steering Rack Bush</p>



MITSUBISHI

Revision : 2014-November-01

<p>AM41-CY4001 3517A003</p> <p>ASX [2010] = GA# Delica D5 [2006] = CV5W Lancer [2007] = CY# Lancer [2007] = CY3A, CY4A Outl</p> <p>Rear Differential Bushing</p>	<p>PFT-2012-November-07 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM41-CU4001 MN-100065</p> <p>Outlander [2002-2006] = CU2W, CU5W Airtrek [2001-2005] = CU2W, CU4W, CU5W</p> <p>Rear Differential Bushing</p>	<p>PFT-2012-December-31 Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM41-CU4002 MR-961407</p> <p>Outlander [2002-2006] = CU2W, CU5W Airtrek [2001-2005] = CU2W, CU4W, CU5W</p> <p>Rear Differential Bushing</p>
<p>AM41-CU4002LZ MR-961407</p> <p>Outlander [2002-2006] = CU2W, CU4W, CU5W.. [4WD]</p> <p>Rear Differential Mounting [LH]</p>	<p>HFC Product, Ashimori Product www.rbi.ae</p>  <p>AM41-CU4002RZ MR-961408</p> <p>Outlander [2002-2006] = CU2W, CU4W, CU5W.. [4WD]</p> <p>Rear Differential Mounting [RH]</p>
<p>AM41-PD4E00 MB-951655</p> <p>Delica [1994-2004] = PD4W, PD6W, PD8W L400 Space Gear [1994-2001] = PD4W, PD5W</p> <p>Rear Differential Mounting [RE]</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM41-V75001 MR-554075</p> <p>Pajero III Montero [2000-2006] = V65W, V75W Pajero IV Montero [2006] = V87W, V97W</p> <p>Rear Differential Bushing [RE]</p>	<p>PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AM41-V75002 MR-374877</p> <p>Pajero III Montero [2000-2006] = V65W, V75W Pajero IV Montero [2006] = V87W, V97W</p> <p>Rear Differential Bushing [RE]</p>
<p>AM40-E5501 MB-871921</p> <p>Galant [1992-1996] = E55A, E75A Galant [1996-2003] = EA</p> <p>Rubber Body Bush</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM40-K5730 MB-275630</p> <p>K57</p> <p>Rubber Body Mounting</p>	<p>RBI-2012-May-31 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AM40-V430 MB-675984</p> <p>Pajero [1995-1999] = V43</p> <p>Rubber Body Mounting</p>	<p>RBI-2012-August-06 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MITSUBISHI

Revision : 2014-November-01

AM90-FE111 MB-390261 Mitsubishi Canter = FE111, FE444, FE449 Air Hose Pipe	<p>ARD-2014-January-01 ARD Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	
AM90-T0400 1505A041 L200 / Triton = KB8T [3.2] [16V] [4WD] Air Hose Pipe	<p>ARP Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<p>Perfect Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>
AM90-K640T MR-127413 Strada [1996-2002] = K64 [2.5D] [4D56] Air Hose Pipe	<p>ARP Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<p>ARP Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>
AM90-K640S MR-127413 Strada [1996-2002] = K64 [2.5D] [4D56] Air Hose Pipe	<p>ARP Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	
AM90-K0401 MD-106179 Cyclone / L200 [1988] = K04T [2.5D] [4D56] Air Hose Pipe	<p>ARP Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>	<p>ARP Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>
AM90-K0402 MB-060646 Cyclone / L200 [1988] = K04T, K14 [2.5D] [4D56] Air Hose Pipe		<p>ARP Product shabbirh@eim.ae</p>  <p>www.rbi.ae www.alafuae.com</p>

