











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

	<p>AD09-33FZ B092-39-050</p> <p>Mazda 323 [1983-1988]</p> <p>Insulator Engine [FR, M/T] [1.3, 1.5, 1.6 Petrol]</p> <p>   </p> <p> <small>TN-2011-July-23 Perfect Product, Tenacity Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
	<p>AD09-33FAZ B180-39-050</p> <p>Mazda 323 [1983-1988]</p> <p>Insulator Engine [FR, A/T] [1.6 Petrol, Diesel]</p> <p>   </p> <p> <small>TN-2011-July-23 Tenacity Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
	<p>AD09-33F5Z B001-39-050</p> <p>Mazda 323 [1986-1989]</p> <p>Insulator Engine [FR]</p> <p>   </p> <p> <small>PFT-2012-June-26 Perfect Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
	<p>AD09-33F6Z B037-39-050</p> <p>Mazda 323 [1986-1989]</p> <p>Insulator Engine [FR]</p> <p>   </p> <p> <small>Perfect Product, HFC Product, Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com </p>
<p>AD09-04F00 H380-39-040</p> <p>Mazda 929 [1991-1996] = HD</p> <p>Insulator Engine</p> <p> <small>HFC Product</small> www.rbi.ae </p>	







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

	<p>AD09-33LMZ B092-39-040</p> <p>Mazda 323 [1983-1988]</p> <p>Insulator Engine [LH, M/T] [1.3, 1.5, 1.6 Petrol]</p> <p> PERFECT RUBBER PARTS</p> <p>PFT-2013-April-30 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AD09-33L0Z B001-39-070</p> <p>Mazda 323 [1983-1988]</p> <p>Insulator Engine [LH]</p> <p> PERFECT RUBBER PARTS</p> <p>Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD09-33R00 B001-39-060  Mazda 323 [1983-1988] Engine Bushing [RH]	<p>PFT-2012-December-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	AD09-33R0Z B001-39-060  Mazda 323 [1983-1988] Insulator Engine [RH]	<p>PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
		AD09-33RM1Z B092-39-060 <p>Ashimori Product www.rbi.ae</p> Mazda 323 [1983-1988] Insulator Engine [RH, M/T] [1.3, 1.5 Petrol]	
		AD09-33RAZ B182-39-060  Mazda 323 [1983-1988] Insulator Engine [RH, A/T] [1.6 Petrol, Diesel]	<p>TN-2011-July-23 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD09-36E BR74-39-040 Mazda 323 [1989-1993] Engine Bushing [RE]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD09-36EZ BR74-39-040 Mazda 323 [1989-1993] Insulator Engine [RE]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD09-36F B455-39-050 Mazda 323 [1989-1993] Engine Bushing [FR]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD09-36FZ B455-39-050 Mazda 323 [1989-1993] Insulator Engine [FR]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD09-36L B455-39-100 Mazda 323 [1989-1993] Engine Bushing [LH]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD09-36LZ B455-39-100 Mazda 323 [1989-1993] Insulator Engine [LH]	RBI-2006-March-15 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD09-36R B455-39-060 Mazda 323 [1989-1993] Engine Bushing [RH]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD09-36RZ B455-39-060 Mazda 323 [1989-1993] Insulator Engine [RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AD09-36RAZ BA55-39-060 Mazda 323 [1989-1993] Insulator Engine [RH]	TN-2011-June-03 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 



Revision : 2014-November-01

MAZDA | FORD

AD09-37EA BC1D-39-040 Mazda 323 [1994-1997] Engine Bushing [RE, A/T, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-37EAZ BC1D-39-040 Mazda 323 [1994-1997] Insulator Engine [RE, A/T, M/T]	RBI-2006-August-14 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-37FA BC1G-39-050 Mazda 323 [1994-1997] Engine Bushing [FR, A/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-37FAZ BC1G-39-050 Mazda 323 [1994-1997] Insulator Engine [FR, A/T]	RBI-2005-December-03 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-37FM BC1D-39-050 Mazda 323 [1994-1997] Engine Bushing [FR, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-37FMZ BC1D-39-050 Mazda 323 [1994-1997] Insulator Engine [FR, M/T]	RBI-2005-December-03 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-37LA BC1D-39-100 Mazda 323 [1994-1997] Engine Bushing [LH, A/T, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-37LAZ BC1D-39-100 Mazda 323 [1994-1998] = BA Insulator Engine [LH, A/T]	PFT-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AD09-37LMZ BC1E-39-100 Mazda 323 [1994-1998] = BA Insulator Engine [LH, M/T]	RBI-2006-April-04 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AD09-37RZ BC1F-39-060 Mazda 323 [1994-1997] Insulator Engine [RH, A/T, M/T] [1.5, 1.8]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
		AD09-37R2Z BC1D-39-060 Mazda 323 [1994-1998] = BA Mazda 323F [1994-1998] = BA Insulator Engine [RH]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD09-A00E BJ0N-39-040  Mazda 323 [1998-2002] Engine Bushing [RE]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD09-A00EZ BJ0N-39-040  Mazda 323 [1998-2002] Insulator Engine [RE, A/T, M/T] [1.8]	RBI-2006-December-18 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD09-A00EAZ B25G-39-040  Mazda 323 [1998-2002] Insulator Engine [RE, A/T] [1.6]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD09-A00EMZ B25F-39-040  Mazda 323 [1998-2002] Insulator Engine [RE, M/T] [1.6]	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD09-A00F B25D-39-050  Mazda 323 [1998-2002] Engine Bushing [FR]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD09-A00FZ B25D-39-050  Mazda 323 [1998-2002] Insulator Engine [FR]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com



Revision : 2014-November-01

MAZDA | FORD

AD09-A00LM B25D-39-070  Mazda 323 [1998-2002] Engine Bushing [LH, A/T, M/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD09-A00LMZ B25D-39-070  Mazda 323 [1998-2002] Insulator Engine [LH, M/T]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		AD09-A00LAZ B25E-39-070  Mazda 323 [1998-2002] Insulator Engine [LH, A/T]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD09-A00RS B25D-39-06Y  Mazda 323 [1998-2002] Engine Bushing [RH, Small] [1.5, 1.6]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD09-A00RSWZ B25D-39-06Y  Mazda 323 [1998-2002] Insulator Engine [RH] [1.5, 1.6] [With Out Screw]	ARD-2014-January-01 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		AD09-A00RSZ B25D-39-06Y  Mazda 323 [1998-2002] Insulator Engine [RH] [1.5, 1.6] [With Screw]	TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD09-A00RB BJ0N-39-06Y  Mazda 323 [1998-2002] Engine Bushing [RH, Big] [1.8]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD09-A00RBWZ BJ0N-39-06Y  Mazda 323 [1998-2002] Insulator Engine [RH] [1.8] [With Out Screw]	ARD-2014-January-01 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		AD09-A00RBZ BJ0N-39-06Y  Mazda 323 [1998-2002] Insulator Engine [RH] [1.8] [With Screw]	TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com

Revision : 2014-November-01

MAZDA | FORD

<p>AFO09-FOC98E1Z 98AB-6P082AH</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Insulator Engine [RE, 2.0, 2.3]</p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AFO09-FOC98E2Z 1094591</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Insulator Engine [RE]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AFO09-FOC98L1Z 1S4Z-7M121AA</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Insulator Engine [LH, 2.0]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AFO09-FOC98R1Z YS4Z-6038BA</p> <p>Ford Focus I [1998-2005] = CAK Ford Transit Connect [2002] = TC7</p> <p>Insulator Engine [RH, 2.0]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AFO09-FOC98R2Z 1112025</p> <p>Ford Focus I [1998-2005] = CAK Ford Transit Connect [2002] = TC7</p> <p>Insulator Engine [RH]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AFO09-FOC98R3Z 98AB-6038CH</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Insulator Engine [RH, 1.4, 1.6]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AFO09-FOC98R4Z 1139257</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Insulator Engine [RH]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AFO09-FOC98R5Z YS4Z-6038FA</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Insulator Engine [RH, 2.3]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

	<p>AD09-MZ3EZ BP4S-39-040</p> <p>Mazda 3 [2003]</p> <p>Insulator Engine [RE, 1.3, 1.6, 2.0, 2.3]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AD09-MZ3E2B BP4K-39-010</p> <p>Mazda 3 [2003-2008] = BK Mazda 3 [2009] = BL Mazda 5 [2005-2010] = CR Mazda Biente [2008] = CC</p> <p>Engine Bushing [RE]</p> <p>ARP Product www.rbi.ae</p>	<p>AD09-MZ3E2Z BP4N-39-010</p> <p>Mazda 3 [2003-2008] = BK Mazda 3 [2009] = BL 5 [2005-2010] = CR Biente [2008] = CCEFW Premac</p> <p>Insulator Engine [RE]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD09-MZ3E3Z BP4K-39-010</p> <p>Mazda 3 [2003-2008] = BK Mazda 3 [2009] = BL 5 [2005-2010] = CR Biente [2008] = CCEFW Premac</p> <p>Insulator Engine [RE]</p> <p>HFC-2014-November-20 HFC Product www.rbi.ae</p>	<p>AD09-MZ3E4Z BP4S-39-010</p> <p>Mazda 3 [2003-2008] = BK</p> <p>Insulator Engine [RE]</p> <p>HFC-2014-November-20 HFC Product www.rbi.ae</p>
<p>AFO09-FOC04E1Z 1522138</p> <p>Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Focus II [2004-2008] Ford Kuga</p> <p>Insulator Engine [RE]</p> <p>ARP Product www.rbi.ae</p>	
<p>AFO09-FOC04CLZ 1326988</p> <p>Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo</p> <p>Insulator Engine [Center, LH]</p> <p>ARP Product www.rbi.ae</p>	<p>AFO09-FOC04CRZ 1355621</p> <p>Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo</p> <p>Insulator Engine [Center, RH]</p> <p>ARP Product www.rbi.ae</p>



Revision : 2014-November-01

MAZDA | FORD

AD09-MZ3LZ BP4N-39-070  Mazda 3 [2003] Insulator Engine [LH, 1.3, 1.6, 2.0, 2.3]	
AD09-MZ3L3Z BFF4-39-070  Mazda 3 [2003-2008] = BK Insulator Engine [LH]	AD09-MZ3L4Z BP4S-39-070  Mazda 3 [2003-2008] = BK Insulator Engine [LH]
AFO09-FOC04L1Z 3M51-7M121  Ford Focus II [2004-2008] Insulator Engine [LH, A/T, M/T, 1.8, 2.0]	AFO09-FOC04L2Z 1437544  Ford Focus [2008-2011] = CB4 Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Insulator Engine [LH]
AD09-MZ3RSZ BP4K-39-060  Mazda 3 [2003] Insulator Engine [RH] [1.3, 1.6]	AD09-MZ3RBZ BP4S-39-060  Mazda 3 [2003] Insulator Engine [RH] [2.0, 2.3]
AD09-MZ3R3Z BBM4-39-060  Mazda 3 [2003] Insulator Engine [RH]	AD09-MZ310RBZ B38M-39-060  Mazda 3 [2009] = BL Insulator Engine [RH]
AD09-MZ3R5Z BFF4-39-060  Mazda 3 [2003-2008] = BK Insulator Engine [RH]	AD09-MZ3R6Z BFF7-39-060  Mazda 3 [2003-2008] = BK Insulator Engine [RH]
AFO09-FOC04R1Z 5S4Z-6038CA  Ford Focus II [2004-2008] Insulator Engine [RH, 2.0]	AFO09-FOC04R2Z 1430067  Ford Focus [2008-2011] = CB4 Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Foc Insulator Engine [RH]
AFO09-FOC04R4Z 1430066  Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo Insulator Engine [RH]	

MAZDA | FORD

Revision : 2014-November-01

<p>AD09-12187FEZ KK391-39-050</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 121 [1987-1990] = DA Metro</p> <p>Insulator Engine [FR, RE]</p>	
<p>AD09-DEM1FZ D201-39-050</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Demio [1998-2002]</p> <p>Insulator Engine [FR]</p>	<p>AD09-DEM1EZ D201-39-040</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Demio [1998-2002]</p> <p>Insulator Engine [RE]</p>
	<p>AD09-DEM1RZ DC22-39-060</p> <p>ARP Product www.rbi.ae</p> <p>Demio [1998-2002]</p> <p>Insulator Engine [RH]</p>
<p>AD09-MZ203EZ DD32-39-040</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5</p> <p>Insulator Engine [RE]</p>	<p>AD09-DEM2EAZ D354-39-040</p> <p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5</p> <p>Insulator Engine [RE, A/T]</p>
<p>AD09-DEM2R0 D350-39-060</p> <p>TN-2013-November-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5</p> <p>Insulator Engine [RH] [With Out Bracket]</p>	<p>AD09-DEM2RZ D350-39-060</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5</p> <p>Insulator Engine [RH] [With Bracket]</p>
<p>AD09-MZ203RZ DD32-39-060</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5</p> <p>Insulator Engine [RH, M/T]</p>	<p>AFO09-FIE02RZ 1313587</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford Fiesta [2008] = CB1 Ford Fiesta V [2001-2008] = JH Ford Fiesta, Fusion [2001-2008] = CBK</p> <p>Insulator Engine [RH, M/T]</p>
<p>AD09-MZ203LZ DD32-39-070</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5</p> <p>Insulator Engine [LH]</p>	<p>AD09-DEM2LZ D350-39-070</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5</p> <p>Insulator Engine [LH]</p>














AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : http://www.rbi.ae http://www.alafuae.com

MAZDA | FORD

Revision : 2014-November-01

AD09-MZ207EAZ D652-39-040  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [RE, A/T]	AD09-MZ207EMZ D651-39-04XD  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [RE, M/T]
AD09-MZ207E3Z DG80-39-040  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [RE]	AD09-MZ207E4Z DG81-39-040  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [RE]
AD09-MZ207L1Z D652-39-070  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [LH, A/T, 1.5]	AD09-MZ207LMZ D651-39-070  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [LH, M/T]
AD09-MZ207L3Z DG80-39-070  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [LH]	AD09-MZ207L4Z DG81-39-070  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [LH]
AD09-MZ207R1Z D652-39-060  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [RH]	AD09-MZ207R1ZZ D652-39-060  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [Bracket only] [RH, A/T]
AD09-MZ207RMZZ D651-39-060  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [Bracket only] [RH, M/T]	AD09-MZ207R3ZZ DG80-39-060  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [Bracket only] [RH]
AD09-MZ207R4ZZ DG81-39-060  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [Bracket only] [RH]	
AD09-MZ207C1Z DG80-39-080  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [Center]	AD09-MZ207C2Z DG81-39-080  Mazda 2 [2007] = DE Mazda Demio [2007] = DE Insulator Engine [Center]









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD09-CX707E0Z EH46-39-040A  Mazda CX-7 [2006] = ER Insulator Engine [RE]	
AD09-CX707L0Z EH46-39-070B  Mazda CX-7 [2006] = ER Insulator Engine [LH]	AD09-CX707R0Z EG21-39-060  Mazda CX-7 [2006] = ER Insulator Engine [RH]
AD09-CX907E0Z TDY0-39-04X  Mazda CX-9 [2007-2013] = TB Insulator Engine	













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD10-62E G030-39-040  Mazda 626 [1983-1986] Insulator Engine [RE]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD10-62F G076-39-050  Mazda 626 [1983-1986] Insulator Engine [FR]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
		AD10-62LZ G030-39-070  Mazda 626 [1983-1986] Insulator Engine [LH]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD10-62R G032-39-060  Mazda 626 [1983-1986] Insulator Engine [RH]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

	<p>AD09-631EAZ GM02-39-040</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [RE, A/T..3-Speed]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-63EMZ GJ21-39-040</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [RE, M/T..4-Speed]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-63EAZ GJ23-39-040</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [RE, A/T..4-Speed]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-631EMZ GJ25-39-040</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [RE, M/T..3-Speed]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-63FAZ GJ23-39-050</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-63FMZ GJ21-39-050</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

	<p>AD09-63RAZ GJ27-39-060</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [RH, A/T]</p>	<p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AD09-63RMZ GJ21-39-060</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [RH, M/T]</p>	<p>TN-2010-December-01 Tenacity Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AD09-63LAZ GJ23-39-070</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [LH, A/T..4-Speed]</p>	<p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AD09-63LMZ GJ21-39-070</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [LH, M/T]</p>	<p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  
	<p>AD09-631LAZ GJ91-39-070</p> <p>Mazda 626 [1987-1991]</p> <p>Insulator Engine [LH, A/T]</p>	<p>TN-2010-December-01 Tenacity Product</p> <p>shabbirh@eim.ae</p> <p>www.rbi.ae</p> <p>www.alafuae.com</p>  







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD09-MPV1F1Z LA01-39-040 Mazda MPV [1989-1994] Insulator Engine [FR, LH, RH, A/T, M/T] [2WD, 4WD] [3.0]	HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae	
	HFC-2014-November-20 ARD Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD09-MPV1FZ LA27-39-040 Mazda MPV [1995-1999] Insulator Engine [FR, LH, RH, A/T, M/T]
	Ashimori Product www.rbi.ae	AD09-MPV1E2Z LA12-39-340 Mazda MPV [1993-1994] Insulator Engine [RE, A/T, M/T] [4WD] [2.6]
AD09-MPV1EZ LA01-39-340 Mazda MPV [1989-1999] Insulator Engine [RE, A/T, M/T] [2WD, 4WD] [3.0]	ARD-2014-May-05 ARD Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	



Revision : 2014-November-01

MAZDA | FORD

AD11-64A GA2G-39-100  Mazda 626 [1991-1996] Insulator Engine [RE, A/T]  RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD11-64M GA2E-39-100  Mazda 626 [1991-1996] Insulator Engine [RE, M/T]  RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-64EA GA2C-39-040  Mazda 626 [1991-1996] Engine Bushing [RE, A/T]  RBI-OLD RBI Product, Perfect Product, shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-64EAZ GA2C-39-040  Mazda 626 [1991-1996] Insulator Engine [RE, A/T] [1.8, 2.0, 2.5] [With Clip]  RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-64EZ KB31-39-040  Mazda 626 [1991-1996] Insulator Engine [RE, A/T] [1.8, 2.0, 2.5] [With Out Clip]  TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-64EA5Z GD7G-39-040  Mazda 626 [1991-1996] Insulator Engine [RE]  TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-64EM GA2A-39-040  Mazda 626 [1991-1996] Engine Bushing [RE, M/T]  RBI-OLD RBI Product, Perfect Product, shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-64EMZ GA2A-39-040  Mazda 626 [1991-2001] Insulator Engine [RE, A/T, M/T] [1.8, 2.0, 2.5] [With Out Clip]  RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-65EMZ GA2H-39-040  Mazda 626 [1991-2001] Insulator Engine [RE, A/T, M/T] [1.8, 2.0, 2.5] [With Out Clip]  TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD09-65EAZ GG2P-39-040  Mazda 626 [1997-2001] Insulator Engine [RE, A/T, M/T] [1.8, 2.0, 2.5] [With Clip]  TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
	AD09-MPV2EZ LD47-39-040  Mazda MPV [1999-2006] Insulator Engine [RE, A/T, M/T]  Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD09-MPV2E3Z L081-39-040  MPV [2000-2003] Insulator Engine [RE] Ashimori Product www.rbi.ae	



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD09-64FA GA2C-39-050</p> <p>Mazda 626 [1991-1996]</p> <p>Engine Bushing [FR, A/T]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>AD09-64FAZ GA2C-39-050</p> <p>Mazda 626 [1991-1996]</p> <p>Insulator Engine [FR, A/T]</p> <p>RBI-2007-June-04 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AD09-65FAZ KB31-39-050</p> <p>Mazda 626 [1996-2001]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD09-64FM GA2A-39-050</p> <p>Mazda 626 [1991-1996]</p> <p>Engine Bushing [FR, M/T]</p>	<p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>AD09-64FMZ GA2A-39-050</p> <p>Mazda 626 [1991-1996]</p> <p>Insulator Engine [FR, M/T]</p> <p>RBI-2007-June-18 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AD09-65FMZ GE6T-39-050</p> <p>Mazda 626 [1996-2001]</p> <p>Insulator Engine [FR, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AD09-MPV2FAZ LC62-39-050</p> <p>Mazda MPV [1999-2006]</p> <p>Insulator Engine [FR, A/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

	<p>AD09-64LZ KB31-39-070</p> <p>Mazda 626 [1991-1996]</p> <p>Insulator Engine [LH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AD09-64LM GE4T-39-070</p> <p>Mazda 626 [1997-2001]</p> <p>Engine Bushing [LH, M/T]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AD09-64LMZ GJ2A-39-070</p> <p>Mazda 626 [1991-2001]</p> <p>Insulator Engine [LH, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AD09-64LA GE6T-39-070</p> <p>Mazda 626 [1997-2001]</p> <p>Engine Bushing [LH, A/T]</p> <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AD09-64LAZ GE6T-39-070</p> <p>Mazda 626 [1991-2001]</p> <p>Insulator Engine [LH, A/T]</p> <p>RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
	<p>AD09-65LAZ GG2P-39-070</p> <p>Mazda 626 [1997-2001]</p> <p>Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AD09-64LA2 GA2A-39-070</p> <p>Mazda MPV [1999-2006] = LW MX-6 [1991-1996] = GE Xedos-6 [1992-1998] = CA</p> <p>Engine Bushing [LH]</p> <p>PFT-2012-December-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AD09-MPV2LAZ LC62-39-070</p> <p>Mazda MPV [1999-2006]</p> <p>Insulator Engine [LH, A/T]</p> <p>Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

	<p>AD09-64RZ GA2A-39-060</p> <p>Mazda 626 [1991-1996]</p> <p>Insulator Engine [RH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD09-65RA G15C-39-060</p> <p>Mazda 626 [1997-2001]</p> <p>Engine Bushing [RH, A/T]</p> <p>PFT-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AD09-65RAZ GG2A-39-060</p> <p>Mazda 626 [1997-2001]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-65RZ G15C-39-060</p> <p>Mazda 626 [1997-2001]</p> <p>Insulator Engine [RH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-MPV2RAZ LC62-39-060</p> <p>Mazda MPV [1999-2006]</p> <p>Insulator Engine [RH, A/T]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-MPV2RM1Z L1Y7-39-060</p> <p>Mazda MPV [2002-2006]</p> <p>Insulator Engine [RH, M/T] [2.3] [Petrol]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
	<p>AD09-MPV2RMZ L081-39-060</p> <p>Mazda MPV [1999-2002]</p> <p>Insulator Engine [RH, M/T]</p> <p>Ashimori Product www.rbi.ae</p>



Revision : 2014-November-01

MAZDA | FORD

AD09-66RAZ GJ6G-39-060  Mazda 6 [2002-2006] Insulator Engine [RH, A/T]	AD09-66RMZ GK2E-39-060  Mazda 6 [2002-2006] Insulator Engine [RH, M/T]
AD09-66LA GJ6G-39-070  Mazda 6 [2002-2006] Engine Bushing [LH, A/T]	AD09-66LAZ GJ6G-39-070  Mazda 6 [2002-2006] Insulator Engine [LH, A/T]
AD09-66EZ GJ6A-39-040  Mazda 6 [2002-2006] [2.0] Insulator Engine [RE, A/T, M/T]	AD09-66E2Z GJ6G-39-04X  Mazda 6 [2002-2006] [2.5] Insulator Engine [RE, A/T, M/T]
AD09-66E3Z GK2C-39-040  Mazda 6 [2002-2006] [3.0] Insulator Engine [RE, A/T, M/T]	
AD09-67EAZ GS1G-39-040  Mazda 6 [2007-2013] = GH Mazda 6 Wagon [2007-2013] = GH Insulator Engine [RE, A/T, M/T]	AD09-67E2Z GS1D-39-04X  Mazda 6 [2007-2013] = GH Mazda 6 Wagon [2007-2013] = GH Insulator Engine [RE]
	AD09-67RAZ GS1G-39-060  Mazda 6 [2007-2013] = GH Mazda 6 Wagon [2007-2013] = GH Insulator Engine [RH, A/T]
	AD09-67LAZ GS2P-39-070  Mazda 6 [2007-2013] = GH Mazda 6 Wagon [2007-2013] = GH Insulator Engine [LH, A/T]












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD09-T10F0 EC01-39-054  Ford Escape [2000-2002] Mazda Tribute [2000-2002] Engine Bushing [FR]	AD09-T10EZ EC02-39-040  Ford Escape [2000-2002] Mazda Tribute [2000-2002] Insulator Engine [RE]
AD09-T10LZ EC01-39-070  Ford Escape [2000-2002] Mazda Tribute [2000-2002] Insulator Engine [LH]	AD09-T10RZ EC01-39-060  Ford Escape [2000-2002] Mazda Tribute [2000-2002] Insulator Engine [RH]
	AD09-T20FZ E181-39-050  Ford Escape [2003-2007] Mazda Tribute [2003-2007] Insulator Engine [FR] [2.3]
	AD09-T20EZ E181-39-040  Ford Escape [2003-2007] Mazda Tribute [2003-2007] [2WD] Insulator Engine [RE] [2.3]
	AD09-T24EZ E182-39-040  Ford Escape [2003-2007] Mazda Tribute [2003-2007] [4WD] Insulator Engine [RE] [2.3]
AD09-T20LZ E181-39-070  Ford Escape [2003-2007] Mazda Tribute [2003-2007] Insulator Engine [LH] [2.3]	AD09-T20RZ E181-39-060  Ford Escape [2003-2007] Mazda Tribute [2003-2007] Insulator Engine [RH] [2.3]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD09-FES93E1Z MD061-39-040</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine [RE, 1.3, 1.5]</p>	<p>AD09-FES93E2Z MD002-39-040</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine [RE, M/T]</p>
<p>AD09-FES93E3Z MD012-39-040</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine [RE, A/T]</p>	
<p>AD09-FES93F1Z MD012-39-060</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine [FR, A/T]</p>	<p>AD09-FES93F2Z KK390-39-060</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine [FR]</p>
<p>AD09-FES93L1Z MD002-39-050</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine [FR, LH]</p>	<p>AD09-FES93L2Z</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine [FR, LH, 1.3]</p>
<p>AD09-FES93R1Z 96FB-7M-121AJ</p> <p>Ford Festiva [1993–2000] = WB, WD, WF Ford Aspire [1993–2000] = WB, WD, WF KIA Avella [1998-1999]</p> <p>Insulator Engine</p>	

Revision : 2014-November-01

MAZDA | FORD

<p>AFO09-ALT89E1Z</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford ALTEZZ [1989-1999]</p> <p>Insulator Engine [RE]</p>	
<p>AFO09-FAL94FLR</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>EL-6039C</p> <p>Ford FALCON AULEF, EL 6CY&V8 [1994-2002]</p> <p>Insulator Engine [FR, LH, RH]</p>	<p>AFO09-FAL95FLR</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>1R23-6B032AA</p> <p>Ford FALCON 6CY [1995-2001]</p> <p>Insulator Engine [FR, LH, RH]</p>
<p>AFO09-FAL08EZ</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Falcon FG 4.0L [6CYL]</p> <p>Insulator Engine [RE]</p>	
<p>AFO09-KA97E1Z</p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>2S55-7M124AB</p> <p>Ford KA [1997-2007]</p> <p>Insulator Engine [RE]</p>	
<p>AFO09-PRO89F1Z</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford PRONTO = [1989-1999]</p> <p>Insulator Engine [FR, 1.0]</p>	
<p>AFO09-SIE87E1Z</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford SIERRA = [1987]</p> <p>Insulator Engine [RE, 1.8, 2.0]</p>	<p>AFO09-SIE87F1Z</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford SIERRA = [1987]</p> <p>Insulator Engine [FR, 1.8, 2.0]</p>
<p>AFO09-TAU96F1Z</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>YF1Z-6068AB</p> <p>Ford Taurus III [1996-1999]</p> <p>Insulator Engine [3.0 V6]</p>	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO09-MON92E1Z 97BB-6P095  Ford Mondeo [1992-2000] = FD Insulator Engine [RE, A/T, 2.0]	AFO09-MON92E2Z 97BB-6P082  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Insulator Engine [RE, A/T, 2.0]
AFO09-MON92F1Z 93BB-6P081  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Insulator Engine [FR, A/T, 2.0]	AFO09-MON92F2Z 97BB-6P081  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Insulator Engine [FR, A/T, 2.0]
AFO09-MON92L1Z  Ford Mondeo [1992-2000] = FD Insulator Engine [LH, M/T, 2.0]	AFO09-MON92L2Z 93BB-7M124  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Insulator Engine [LH, A/T, 2.0]
AFO09-MON92R1Z 93BB-6P079  Ford Mondeo [1992-2000] = FD Insulator Engine [RH]	AFO09-MON92R2Z 97BB-6F012AD  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Insulator Engine
AFO09-MON92R3Z 1S71-6F012BC  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Insulator Engine [RH, Hydraulic]	











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AFO09-MON00E1Z 1S71-6P082BF  Ford Mondeo [2000-2007] = GE Insulator Engine [RE, AT]	AFO09-MON00E2Z 98BB-6P090  Ford Mondeo [2000-2007] = GE Insulator Engine
AFO09-MON00F1Z 1123542  Ford Mondeo [2000-2007] = GE Insulator Engine	
AFO09-MON00L1Z 1S71-7M122EB  Ford Mondeo [2000-2007] = GE Insulator Engine [LH]	AFO09-MON00R1Z 1S71-6F012AD  Ford Mondeo [2000-2007] = GE Insulator Engine [RH, Hydraulic]
AFO09-MON07R1Z 1376874  Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200 Insulator Engine	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AFO09-TRA00E1Z 1330122 <div>ARP Product</div> www.rbi.ae FFord Transit [2000-2006] = FA, FB, FC, FD, FM, FN, FZ, FY Ford Transit [2006] = TT9 Insulator Engine [RE]	AFO09-TRA00FLR 4571417 <div>ARP Product</div> www.rbi.ae Ford Transit [2000-2006] = FA, FB, FC, FD, FM, FN, FZ, FY Ford Transit [2006] = TT9 Insulator Engine [FR, LH, RH]
AFO09-TRA00L1Z 4520000 <div>ARP Product</div> www.rbi.ae Ford Transit [2000-2006] = FA, FB, FC, FD, FM, FN, FZ, FY Ford Transit [2006] = TT9 Insulator Engine [LH]	
AFO09-TRA94FLZ 95VB-6B032BD <div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> Ford Transit [1994-2000] = E Insulator Engine [FR, LH]	AFO09-TRA94FRZ 95VB-6038BF <div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae</div> <div>www.rbi.ae</div> <div>www.alafuae.com</div> Ford Transit [1994-2000] = E Insulator Engine [FR, RH]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD







Revision : 2014-November-01

AD10-010 0370-39-040  Mazda 808 Insulator Engine [FR]	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	
AD10-410 0259-39-040  M1200 Insulator Engine [FR]	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	
AD11-410 0259-39-340  M1200, M1300, M1600, Magnum Insulator Engine [RE]	 <small>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD11-410Z 0259-39-340  M1200 Insulator Engine [RE, Bracket]
AD10-42L 0317-39-050  M1300, M1400 Insulator Engine [FR, LH]	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD10-42R 0317-39-040  M1300, M1400 Insulator Engine [FR, RH]
AD10-43L 0223-39-090  M1600 Insulator Engine [FR, LH]	 <small>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD10-43R 0223-39-060  M1600 Insulator Engine [FR, RH]
AD10-440 UA01-39-340  B2200 Insulator Engine [FR]	 <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	











Revision : 2014-November-01

MAZDA | FORD

<p>AD10-E200LR S083-39-040</p>  <p>Mazda = E2000, E2200 [1987-2002] [Petrol+Diesel]</p> <p>Insulator Engine [FR, LH, RH]</p> <p><small>RBI-2007-December-18 RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AD10-E201LR H115-39-040</p>  <p>Mazda</p> <p>Insulator Engine</p> <p><small>PFT-2014-January-14 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p>AD10-B250FLR S10H-39-040</p>  <p>B1800 [1996] B2200 [1996] B2500 [2002] B2500, B2600 [1996] = UF BT-50 [2006]</p> <p>Insulator Engine [FR]</p> <p><small>PFT-2014-January-14 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	
<p>AD10-E200E S083-39-340</p>  <p>Mazda = E2000, E2200 [1987-1998] [Petrol]</p> <p>Insulator Engine [RE]</p> <p><small>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	
<p>AD10-E201E SG42-39-340</p>  <p>Mazda = E2000, E2200 [1987-1998] [Diesel]</p> <p>Insulator Engine [RE]</p> <p><small>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AD10-E202E S47R-39-34Y</p>  <p>Mazda = E2000, E2200 [1999-2002] [Petrol]</p> <p>Insulator Engine [RE]</p> <p><small>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>

MAZDA | FORD

Revision : 2014-November-01

<p>AD10-450 UB39-39-040</p> <p>Mazda = B1600, B1800, B2000, B2200, B2500, B2600, B2900 [1985-2002] Magnum, Fighter</p> <p>Insulator Engine [FR] [2WD] [Petrol, Diesel]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD10-B260F UC86-39-040</p> <p>Mazda = B1600, B1800, B2000, B2200, B2500, B2600, B2900 [1985-2002] Magnum, Fighter</p> <p>Insulator Engine [FR] [4WD] [Petrol]</p>  <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AD10-BT50LR UR58-39-040</p> <p>Mazda = BT50 [2006] [2WD, 4WD]</p> <p>Insulator Engine [FR] [2WD, 4WD] [Petrol]</p>  <p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD11-4XB UH74-39-34X</p> <p>Mazda = B2200, B2500, B2600, B2900 [1999-2002] Fighter, Ranger Mazda = BT50 [2006] [4WD]</p> <p>Insulator Engine [RE] [4WD] [Diesel]</p>  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD11-4XS UH74-39-33X</p> <p>Mazda = B1600, B1800, B2000, B2200, B2500, B2600, B2900 [1985-1998] Magnum, Fighter</p> <p>Insulator Engine [RE] [4WD] [Petrol]</p>  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD11-2XM UH71-39-340</p> <p>Mazda = B2200, B2500, B2600, B2900 [1999-2002] Fighter, Ranger Mazda = BT50 [2006] [2WD]</p> <p>Insulator Engine [RE, M/T] [2 WD]</p>  <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD11-2XA UH72-39-340</p> <p>Mazda = B2200, B2500, B2600, B2900 [1999-2002] Fighter, Ranger Mazda = BT50 [2006] [2WD]</p> <p>Insulator Engine [RE, A/T] [2 WD]</p>  <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD10-B260E UB39-39-340</p> <p>Mazda = B1600, B1800, B2000, B2200, B2500, B2600, B2900 [1985-1998] Magnum, Fighter</p> <p>Insulator Engine [RE] [2WD] [Petrol, Diesel]</p>  <p>TN-2010-December-26 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD10-405 0185-39-040</p> <p>Mazda Titan Truck [1984-2005] = T2000, T2500, T2600, T3000, T3500, T4100</p> <p>Insulator Engine [FR]</p>	<p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD10-T3K1FZ W023-39-040</p> <p>Mazda Titan Truck [1984-1992] = T2000, T2500, T2600, T3000, T3500</p> <p>Insulator Engine [FR]</p>	<p>PFT-2012-August-30 Perfect Product, Tenacity Product, ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AD10-T3K1EZ W023-39-340</p> <p>Mazda Titan Truck [1984-2005] = T2000, T2500, T2600, T3000, T3500, T4100</p> <p>Insulator Engine [RE]</p>
<p>AD10-T4100FZ T410-39-040</p> <p>Mazda Truck [1984-2000] = T4100</p> <p>Insulator Engine [FR]</p>	<p>ARD-2013-May-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AD10-T4600FZ T460-39-040</p> <p>Mazda Truck [1984-2000] = T4600</p> <p>Insulator Engine [FR]</p>
<p>AD10-00001 0000-39-340</p> <p>MAZDA</p> <p>Insulator Engine [RE]</p>	<p>ARD-2013-May-01 ARD Product www.rbi.ae</p> 







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD13-01F 0866-34-390</p> <p>Mazda 323 Mazda 808</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AD13-02F00 H001-34-380</p> <p>Mazda 929 [1982-1987] Mazda 929 [1986-1991] = HC Mazda 808</p> <p>Shock Absorber Mounting [FR]</p>	<p>Ashimori Product www.rbi.ae</p>
<p>AD13-04E00 H380-28-380</p> <p>Mazda 929 [1991-1996] = HD</p> <p>Shock Absorber Mounting</p>	<p>AD13-04F00 H380-34-380</p> <p>Mazda 929 [1991-1996] = HD</p> <p>Shock Absorber Mounting [FR]</p>
<p>AD13-12190E00 1E00-28-012</p> <p>Mazda 121 [1990-1996] = DB</p> <p>Shock Absorber Mounting [RE]</p>	<p>AD13-12190F00 1E00-34-390</p> <p>Mazda 121 [1990-1996] = DB</p> <p>Shock Absorber Mounting [FR]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01









MAZDA | FORD

AD13-33F B001-34-390  Mazda 323 [1985-1988] Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD13-33E B001-28-390  Mazda 323 [1985-1988] Shock Absorber Mounting [RE, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD13-36F B455-34-380  Mazda 323 [1989-1993] 4 Door Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD13-36E B455-28-390  Mazda 323 [1989-1993] 4, 5 Door Shock Absorber Mounting [RE, LH, RH]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD13-36FB B455-34-38XB Mazda 323 [1989-1994] = BG Mazda 323 [1994-1998] = BA Mazda 323F [1994-1998] = BA Mazda 626 [1 Shock Absorber Mounting Bearing Only	ARP Product www.rbi.ae	AD13-36FZ B455-34-390  Mazda GOLDLASER 1.6, 1.8 [ASMMA1003+ABRMA1002] [1990-1996] Shock Absorber Mounting + Bearing [SET]	Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD13-35F B481-34-380  Mazda 323 [1989-1993] 4 Door Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD13-38F B01C-34-380  Mazda 323 [1994-1997] LANTIS ASTINA Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD13-38EL BC1D-28-390  Mazda 323 [1994-1997] Shock Absorber Mounting [RE, LH]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD13-38ER BC1D-28-380  Mazda 323 [1994-1997] Shock Absorber Mounting [RE, RH]	TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com



Revision : 2014-November-01

MAZDA | FORD

<p>AD13-A00F CB01-34-380</p>  <p>Mazda 323 [1998-2002]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p><small>RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AD13-A00FZ B25D-34-380</p>  <p>Mazda TIERRA 1.6, 1.8 [ASMMA1008+ABRMA1003] [1998]</p> <p>Shock Absorber Mounting + Bearing [SET] [FR]</p> <p><small>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p>AD13-A01F BL8P-34-380</p>  <p>Mazda 323 [1998-2002]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p><small>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AD13-A00FB B25D-34-38X</p>  <p>Mazda 323 [1998-2004] = BJ Mazda Familia [1998-2004] = BJ Mazda Premacy [1999-2005] = CP</p> <p>Shock Absorber Mounting Bearing Only</p> <p><small>ARP Product www.rbi.ae</small></p>
<p>AD13-A00EL B25D-28-390</p>  <p>Mazda 323 [1998-2002] 4 Door</p> <p>Shock Absorber Mounting [RE, LH]</p> <p><small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AD13-A00ER B25D-28-380</p>  <p>Mazda 323 [1998-2002] 4 Door</p> <p>Shock Absorber Mounting [RE, RH]</p> <p><small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>
<p>AD13-A01EL BJ3D-28-390</p>  <p>Mazda 323 [1998-2002] 5 Door</p> <p>Shock Absorber Mounting [RE, LH]</p> <p><small>TN-2013-March-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	<p>AD13-A01ER BJ3D-28-380</p>  <p>Mazda 323 [1998-2002] 5 Door</p> <p>Shock Absorber Mounting [RE, RH]</p> <p><small>TN-2013-March-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>

Revision : 2014-November-01

MAZDA | FORD

AD13-61F 8173-34-380  Mazda 626 [1980-1985] Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Tenacity Product  www.rbi.ae www.alafuae.com	AD13-62F G030-34-390  Mazda 626 [1985-1986] Shock Absorber Mounting [FR, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product  www.rbi.ae www.alafuae.com
AD13-62EL G030-28-390  Mazda 626 [1985-1986] Shock Absorber Mounting [RE, LH]	RBI-OLD RBI Product, Tenacity Product, Ashimori Product  www.rbi.ae www.alafuae.com	AD13-62ER G030-28-380  Mazda 626 [1985-1986] Shock Absorber Mounting [RE, RH]	RBI-OLD RBI Product, Tenacity Product  www.rbi.ae www.alafuae.com
AD13-63F GJ21-34-380  Mazda 626 [1987-1990] Shock Absorber Mounting [FR, LH, RH, M/T]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com	AD13-63FA GN64-34-380  Mazda 626 [1987-1990] Shock Absorber Mounting [FR, LH, RH, A/T]	TN-2010-December-01 Tenacity Product  www.rbi.ae www.alafuae.com
AD13-63E GJ21-28-380  Mazda 626 [1987-1990] Shock Absorber Mounting [RE, LH, RH]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com		
AD13-632F GJ23-34-380  Mazda 626 [1987-1990] Shock Absorber Mounting [FR, LH, RH]	TN-2011-June-03 Tenacity Product, HFC Product  www.rbi.ae www.alafuae.com	AD13-632E GJ23-28-380  Mazda 626 [1987-1990] Shock Absorber Mounting [RE, LH, RH]	Ashimori Product  www.rbi.ae www.alafuae.com
AD13-63FB GJ21-34-38X  Mazda 626 [1987-1990] Shock Absorber Mounting Bearing Only [FR]	Tenacity Product  www.rbi.ae www.alafuae.com	AD13-63FZ GN64-34-380  Mazda 626 [1987-1990] Shock Absorber Mounting + Bearing [SET] [FR]	Tenacity Product  www.rbi.ae www.alafuae.com

MAZDA | FORD

Revision : 2014-November-01

<p>AD13-64F GA5R-34-380</p>  <p>Mazda 626 [1991-1996]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD13-65F GE4T-34-380</p>  <p>Mazda 626 [1997-2001] 4Door</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD13-64FB GA2A-34-38X</p>  <p>Mazda 323F [1994-1998] = BA Mazda 626 [1991-1997] = GE Mazda 626 [1997-2002] = GF Mazda MX-6 [</p> <p>Shock Absorber Mounting Bearing Only [FR]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD13-64FB2 GA5R-34-38X</p>  <p>Mazda 323F [1994-1998] = BA Mazda 626 [1991-1997] = GE Mazda 626 [1997-2002] = GF Mazda MX-6 [</p> <p>Shock Absorber Mounting Bearing Only [FR, 1.80, 2.0]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD13-64FZ GA2A-34-380</p>  <p>Mazda TELSTAR 1.8, 2.0 [ASMMA1017+ABRMA1002] [1993-1996]</p> <p>Shock Absorber Mounting + Bearing [SET] [FR]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD13-65FB GE4T-34-38X</p>  <p>Mazda 626 [1997-2001] 4Door</p> <p>Shock Absorber Mounting Bearing Only [FR]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD13-64UEL GA2A-28-390</p>  <p>Mazda 626 [1991-1996] USA Make</p> <p>Shock Absorber Mounting [RE, LH]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD13-64UER GA2A-28-380</p>  <p>Mazda 626 [1991-1996] USA Make</p> <p>Shock Absorber Mounting [RE, RH]</p> <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD13-65EL GE4T-28-390</p>  <p>Mazda 626 [1991-2001] 4Door JPN Make</p> <p>Shock Absorber Mounting [RE, LH]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD13-65ER GE4T-28-380</p>  <p>Mazda 626 [1991-2001] 4Door JPN Make</p> <p>Shock Absorber Mounting [RE, RH]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD13-651EL GG2E-28-390</p>  <p>Mazda 626 [1997-2001] 5Door</p> <p>Shock Absorber Mounting [RE, LH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD13-651ER GG2E-28-380</p>  <p>Mazda 626 [1997-2001] 5Door</p> <p>Shock Absorber Mounting [RE, RH]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>

Revision : 2014-November-01

MAZDA | FORD

<p>AD13-66F GM6A-34-380</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 6 [2002-2008] = GG Mazda 6 MPS [2005-2007] = GG Mazda 6 Wagon [2002-2008] = GY</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	
<p>AD13-66F02 GJ6E-34-380</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 6 [2002-2008] = GG Mazda 6 MPS [2005-2007] = GG Mazda 6 Wagon [2002-2008] = GY</p> <p>Shock Absorber Mounting [FR]</p>	<p>AD13-66FB GJ6E-34-38X</p> <p>ARP Product www.rbi.ae</p> <p>Mazda 6 [2002-2008] = GG Mazda 6 MPS [2005-2007] = GG Mazda 6 Wagon [2002-2008] = GY Mazda Ate</p> <p>Shock Absorber Mounting Bearing Only [FR]</p>
<p>AD13-67F GS1D-34-380</p> <p>TN-2013-July-16 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda 6 [2007]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	
<p>AD13-T20F00 EC01-34-380</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Escape [2000-2007] Ford Tribute</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>AD13-T20F E112-34-390</p> <p>RBI-2012-August-06 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Escape [2000-2007] Ford Tribute</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>
<p>AD13-T200 E112-28-775</p> <p>RBI-2008-April-08 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Escape [2000-2007] Ford Tribute</p> <p>Shock Absorber Mounting Rubber [RE, LH, RH]</p>	
<p>AD13-T20F0Z EC01-34-380</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford ESCAPE 2.0, 2.3, 3.0 [ASMFO1028+ABRFO1001] [2001-2007]</p> <p>Shock Absorber Mounting + Bearing [SET] [FR]</p>	<p>AD13-T20FB1 EC01-34-38X</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Mazda Tribute [2000-2007] = EP Ford Escape [2000-2007] Ford Maverick [2006-2009] = TM7</p> <p>Shock Absorber Mounting Bearing Only [FR, 2.0, 2.3, 3.0]</p>
<p>AD13-T28FB E112-34-38X</p> <p>ARP Product www.rbi.ae</p> <p>Ford Escape [2008] Ford Escape [2007] Mazda 626 [1997-2002] = GF Mazda 626 Wagon [1997-2002] =</p> <p>Shock Absorber Mounting Bearing Only [FR]</p>	



MAZDA | FORD

Revision : 2014-November-01

AD13-MZ3F BP4L-34-380  Mazda 3 [2003-2008] = BK Shock Absorber Mounting [FR, LH, RH]  RBI-2009-August-31 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD13-MZ3FB B39D-34-38X  Mazda 3 [2003-2008] = BK Shock Absorber Mounting Bearing Only [FR, LH, RH]  Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD13-MZ3FZ BP4K-34-380K  Mazda 3 [2003-2008] = BK Shock Absorber Mounting + Bearing [SET] [FR, LH, RH]  Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	
AD13-MZ3E BP4K-28-380  Mazda 3 [2003-2008] = BK Shock Absorber Mounting [RE, LH, RH]  TN-2013-March-31 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD13-MZ505E00 1300459  Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo Shock Absorber Mounting [RE, LH, RH]  TN-2013-March-31 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD13-MZ203E00 DL33-28-390  Mazda 2 [2003-2007] = DY Shock Absorber Mounting Rubber [RE]  RBI-2013-July-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD13-MZ303E01 BP4L-28-390  Mazda 3 [2003-2008] = BK Shock Absorber Mounting Rubber [RE]  RBI-2013-July-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD13-MZ203F00 2S65-3K155CB  Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5 Ford Fie Shock Absorber Mounting  TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD13-MZ203F01 D350-34-380  Mazda 2 [2003-2007] = DY Demio [2002-2007] = DY3, DY5 Verisa [2004] = DC5 Ford Fiesta V [2001- Shock Absorber Mounting [FR, LH, RH]  TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD13-MZ203FB 1146152  Ford Fiesta IV [1995-2002] = JA, JB Ford Fiesta, Fusion [2001-2008] = CBK Mazda 2 [2003-2007] = Shock Absorber Mounting Bearing Only  ARP Product www.rbi.ae	
AD13-MZ207F00 D651-34-380  Mazda 2 [2007] = DE Demio [2007] = DE Shock Absorber Mounting [FR, LH, RH]  RBI-2013-November-14 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD13-MZ207FB D651-34-38XA  Ford Fiesta [2008] = CB1 Mazda 2 [2007] = DE Mazda Demio [2007] = DE Shock Absorber Mounting Bearing Only  ARP Product www.rbi.ae

Revision : 2014-November-01

MAZDA | FORD

AD13-MPV90F00 LB82-34-380 MPV [1990-1999] = LV Shock Absorber Mounting [FR]	HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD13-MPVF00 LD47-34-380 Mazda MPV [1999-2003] Shock Absorber Mounting [FR, LH, RH]	TN-2016-December-01 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD13-MPV2FZ LD47-34-380 Mazda MPV [ASMMMA1022+ABRMA1003] [1999-2003] Shock Absorber Mounting + Bearing [SET]	Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD13-DEM1FZ D101-34-390 Demio [1998-2002] Shock Absorber Mounting [FR, LH, RH]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD13-CX707F00 TD11-34-380 CX-7 [2006] = ER CX-9 [2007] = TB Shock Absorber Mounting [FR, LH, RH]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD13-CX707FB L208-34-38X Mazda CX-7 [2006] = ER Mazda CX-9 [2007] = TB Shock Absorber Mounting Bearing Only	ARP Product www.rbi.ae
AD13-S10HF00 S10H-34-380 Bongo Friendee [1995-2005] = SG# Shock Absorber Mounting [FR]	ARP Product www.rbi.ae		
AD13-FES93E00 MD107-28-775 Ford FESTIVA 1.3, 1.5 [1993-1995] Shock Absorber Mounting	TN-2014-February-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD13-FES93F00 MD001-34-380 Ford FESTIVA 1.3, 1.5 [1993-1995] Shock Absorber Mounting	TN-2014-February-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AFO13-COU90F00</p> <p>Ford COUGAR [1990-1997]</p> <p>Shock Absorber Mounting [FR]</p> 	
<p>AFO13-EST85F00 F23Z-18183A</p> <p>Ford ESCORT [1985-1990]</p> <p>Shock Absorber Mounting</p> 	<p>AFO13-EST85FZ F23Z-18183AK</p> <p>Ford ESCORT [ASMFO1029+ABRFO1003] [1985-1990]</p> <p>Shock Absorber Mounting + Bearing [SET]</p> 
<p>AFO13-FOC98F00 YS4Z-3A197AA</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Shock Absorber Mounting</p> 	<p>AFO13-FOC98FB YS4Z-18198-AAA</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Shock Absorber Mounting Bearing Only</p> 
<p>AFO13-FOC98FZ YS4Z-3A197AAK</p> <p>Ford Focus I [1998-2005] = CAK</p> <p>Shock Absorber Mounting + Bearing [SET] [FR] [ASMFO1030+ABRFO1005]</p> 	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO13-MON92E00 F5RZ-18198A <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD</p> <p>Shock Absorber Mounting [RE, 2.0]</p>	AFO13-MON92F00 F5RZ-18198B <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD</p> <p>Shock Absorber Mounting [FR, 2.0]</p>
AFO13-MON00E00 1303625 <p>ARP Product www.rbi.ae</p> <p>Ford Mondeo [2000-2007] = GE</p> <p>Shock Absorber Mounting [RE]</p>	AFO13-MON00FB 1115177 <p>ARP Product www.rbi.ae</p> <p>Ford Mondeo [2000-2007] = GE Ford Transit Connect [2002] = TC7</p> <p>Shock Absorber Mounting Bearing Only</p>
AFO13-MON07E00 1440000 <p>ARP Product www.rbi.ae</p> <p>Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo XC60 [2009]</p> <p>Shock Absorber Mounting [RE]</p>	AFO13-MON07FB 1465258 <p>ARP Product www.rbi.ae</p> <p>Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Land Rover Freelander II [2006] Volvo</p> <p>Shock Absorber Mounting Bearing Only</p>
AFO13-PRO00F00 <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford PRONTO 1.0 [2000]</p> <p>Shock Absorber Mounting</p>	AFO13-PRO00F01 <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford PRONTO 800</p> <p>Shock Absorber Mounting</p>
AFO13-PRO00F02 <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford PRZ PRONTO</p> <p>Shock Absorber Mounting</p>	
AFO13-SAB86E00 E6DZ-18192A <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford SABLE 3.0 [1986-1992]</p> <p>Shock Absorber Mounting</p>	AFO13-SAB86F00 E6DZ-18183A <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford SABLE 3.0 [1986-1992]</p> <p>Shock Absorber Mounting</p>
AFO13-SAB96F00 <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford SABLE [1996-2007]</p> <p>Shock Absorber Mounting</p>	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AFO13-TAU96FB</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford Taurus III [1996-1999] Ford Taurus IV [2000-2007]</p> <p>Shock Absorber Mounting Bearing Only</p>	
<p>AFO13-TEM84FB</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford TEMPO [1984-1994]</p> <p>Shock Absorber Mounting Bearing Only</p>	
<p>AFO13-TOP83E00</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford TOPAZ [1983-1994]</p> <p>Shock Absorber Mounting [RE]</p>	
<p>AFO13-TRA00F00 4710000</p> <p>ARP Product www.rbi.ae</p> <p>Ford Transit [2000-2006] = FY</p> <p>Shock Absorber Mounting [FR]</p>	<p>AFO13-TRA00FB 1103725</p> <p>ARP Product www.rbi.ae</p> <p>Ford Cougar [1998-2000] = MC Ford Transit [2000-2006] = FY</p> <p>Shock Absorber Mounting Bearing Only</p>
<p>AFO13-TRA06F00 1377973</p> <p>ARP Product www.rbi.ae</p> <p>Ford Transit [2006] = TT9</p> <p>Shock Absorber Mounting [FR]</p>	<p>AFO13-TRA06FB 1377929</p> <p>ARP Product www.rbi.ae</p> <p>Ford Transit [2006] = TT9</p> <p>Shock Absorber Mounting Bearing Only</p>
<p>AFO13-WIN94F00 F58Z-18183A</p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford WINDSTAR [1994-2003]</p> <p>Shock Absorber Mounting</p>	













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01















MAZDA | FORD

AD14-33E B001-28-111  Mazda 323 [1985-1991] = BF Shock Absorber Dust Cover [RE]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com	AD14-33F B001-34-111  Mazda 323 [1985-1991] = BF Shock Absorber Dust Cover [FR]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com
AD14-36E B455-28-111  Mazda 323 [1994-1998] = BA Shock Absorber Dust Cover [RE]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com	AD14-36F B455-34-111  Mazda 323 [1994-1998] = BA Shock Absorber Dust Cover [FR]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com
AD14-35F00 B481-34-015 Ashimori Product www.rbi.ae Mazda 323 [1989-1994] = BG Mazda 323 [1994-1998] = BA Mazda Lantis [1996-1999] Shock Absorber Dust Cover [FR]			
AD14-38F01U B01C-34-111 ARP Product www.rbi.ae Mazda 323 [1994-1998] = BA Mazda 323F [1994-1998] = BA Mazda Bongo Friendee [1995-2005] = SG# Shock Absorber Bumper [FR]			



Revision : 2014-November-01

MAZDA | FORD

AD14-A00F1 C100-34-0A5  Mazda 323 [2000] Shock Absorber Dust Cover [FR]	RBI-2006-May-01 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	
AD14-A00F C100-34-111  Mazda 323 [1995-2000] Shock Absorber Bumper [FR]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD14-A00FU C100-34-111  Mazda 323 [1995-2000] MEP-Shock Absorber Bumper [FR]
AD14-A00E1 B01C-28-0A5  Mazda 323 [1995-2000] Shock Absorber Dust Cover [RE]	RBI-2006-May-01 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	
AD14-A00E B25D-28-111  Mazda 323 [2000] Shock Absorber Bumper [RE]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD14-A00EU B25D-28-111  Mazda 323 [1995-2000] MEP-Shock Absorber Bumper [RE]
AD14-A00E02U C100-28-111  Protege [1999-2003] Shock Absorber Bumper [RE]	Ashimori Product www.rbi.ae	
AD14-MPV1F00 LA01-34-111  MPV [1990-1999] = LV Shock Absorber Dust Cover	ARP Product www.rbi.ae	AD14-MPV2E01U LC70-28-111  MPV [1999-2006] = LW Shock Absorber Bumper [RE]
AD14-MPV2F00 LC62-34-015  MPV [1999-2006] = LW Shock Absorber Dust Cover	ARP Product www.rbi.ae	AD14-MPV2F01U LC62-34-111  MPV [1999-2006] = LW Shock Absorber Bumper [FR]

Revision : 2014-November-01

MAZDA | FORD

<p>AD14-MZ3F0 BP4K-34-0A5</p> <p>Mazda 3 [2003]</p> <p>Shock Absorber Dust Cover [FR]</p>  <p>RBI-2008-March-17 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD14-MZ3F BP4K-34-111</p> <p>Mazda 3 [2003]</p> <p>Shock Absorber Bumper [FR]</p>  <p>RBI-2008-February-02 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD14-MZ3FU BP4K-34-111</p> <p>Mazda 3 [2003]</p> <p>MEP-Shock Absorber Bumper [FR]</p>  <p>RBI-2008-October-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD14-MZ3F01U BR5G-34-111A</p> <p>Mazda 3 [2003-2008] = BK Mazda 3 [2009] = BL Mazda Axela [2003-2009]</p> <p>MEP-Shock Absorber Bumper [FR]</p> <p>ARP Product www.rbi.ae</p>	
<p>AD14-MZ3E0 3N61-5K-570</p> <p>Mazda 3 [2003-2008] = BK</p> <p>Shock Absorber Dust Cover [RE]</p>  <p>RBI-2014-March-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD14-MZ3E BP4K-28-1B0</p> <p>Mazda 3 [2003]</p> <p>Shock Absorber Bumper [RE]</p>  <p>RBI-2007-December-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD14-MZ309E01U 1321003</p> <p>Ford C-max [2003-2007] = CAP Ford Focus [2008-2011] = CB4 Ford Focus II [2004-2008] Mazda 3 [2]</p> <p>MEP-Shock Absorber Bumper [RE]</p> <p>ARP Product www.rbi.ae</p>	<p>AD14-MZ309F01U BBM2-34-111</p> <p>Mazda 3 [2009] = BL</p> <p>MEP-Shock Absorber Bumper [FR]</p> <p>ARP Product www.rbi.ae</p>









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD14-MZ203E01 DL33-28-1A1  Mazda 2 [2003-2007] = DY Fiesta 5D Shock Absorber Dust Cover [RE]	RBI-2013-October-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD14-MZ203F00 D350-34-0A5 ARP Product Mazda 2 [2003-2007] = DY Demio [2002-2007] = DY3, DY5 Verisa [2004] = DC5 Ford Fiesta V [2001- www.rbi.ae Shock Absorber Dust Cover [FR]	
AD14-MZ203F01U D350-34-111 Mazda 2 [2003-2007] = DY Demio [2002-2007] = DY3, DY5 MEP-Shock Absorber Bumper [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD14-MZ203F02U 1146129 ARP Product Ford Fiesta V [2001-2008] = JH Ford Fiesta, Fusion [2001-2008] = CBK Ford Fusion [2002] = JU www.rbi.ae MEP-Shock Absorber Bumper [FR]	
AD14-DEM1E1 D201-28-015 Demio [1998-2002] Shock Absorber Dust Cover [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD14-DEM1E2U DC20-28-111 ARP Product Demio [1998-2002] Shock Absorber Bumper [RE]	shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD14-DEM1F1 D101-34-111 Demio [1998-2002] Shock Absorber Dust Cover [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AD14-MZ207F00 D651-34-012 Mazda 2 [2007] = DE Demio [2007] = DE Shock Absorber Dust Cover [FR]	ARP Product www.rbi.ae 	AD14-MZ207F01 D651-34-111 RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  Mazda 2 [2007] = DE Demio [2007] = DE Shock Absorber Bumper [FR]	
AD14-MZ207E01U #DF71-28-70XB Mazda 2 [2007] = DE Mazda Demio [2007] = DE MEP-Shock Absorber Bumper [RE]	ARP Product www.rbi.ae 		
AD14-MZ505E01U CC43-28-910 Mazda 5 [2005-2010] = CR Mazda Biente [2008] = CCEFW MEP-Shock Absorber Bumper [RE]	ARP Product www.rbi.ae 		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD14-02F00 H001-34-111 <small>Ashimori Product</small> www.rbi.ae Mazda 929 [1982-1987] Mazda 929 [1986-1991] = HC Mazda 808 Shock Absorber Dust Cover [FR]	
AD14-62F00 G030-34-111 <small>Ashimori Product</small> www.rbi.ae Mazda 626 [1985-1988] = GC Shock Absorber Bumper [FR]	
AD14-63E00 GJ21-28-015 <small>Ashimori Product</small> www.rbi.ae Mazda 626 [1988-1992] = GD Shock Absorber Dust Cover [RE]	AD14-63E01 GJ21-28-111 <small>Ashimori Product</small> www.rbi.ae Mazda 626 [1988-1992] = GD Shock Absorber Bumper [RE]
AD14-63F00 GJ21-34-015 <small>Ashimori Product</small> www.rbi.ae Mazda 626 [1988-1992] = GD Mazda 626 [1991-1997] = GE Mazda Xedos-6 [1992-1998] = CA Shock Absorber Dust Cover [FR]	











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD14-64E GA2A-28-111  Mazda 626 [1991-1997] = GE Mazda 626 [1991-1997] = GE..[USA] Shock Absorber Bumper [RE]	AD14-64E02 GA2A-28-0A5  Mazda 626 [1991-1997] = GE Mazda 626 [1991-1997] = GE..[USA] Lantis [1996-1999] Shock Absorber Dust Cover [RE]
AD14-64EU GA2A-28-111  Mazda 626 MEP-Shock Absorber Bumper [RE]	AD14-65E01U GE4T-28-111  626 [1997-2002] = GF MEP-Shock Absorber Bumper [RE]
AD14-64F GA2A-34-111  Mazda 626 Shock Absorber Bumper [FR]	AD14-64FU GA2A-34-111  Mazda 626 MEP-Shock Absorber Bumper [FR]
AD14-65F00 GE4T-34-015  626 [1997-2002] = GF 626 Wagon [1997-2002] = GW Shock Absorber Dust Cover	AD14-65F01U GE4V-34-111  626 [1997-2002] = GF 626 Wagon [1997-2002] = GW MEP-Shock Absorber Bumper [FR]













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD14-66E01U GJ6A-28-1A0 Mazda 6 [2002-2006] Shock Absorber Bumper [RE]	 <small>Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD14-66F00 GJ6A-34-012 Mazda 6 [2002-2006] Shock Absorber Dust Cover [FR]	 <small>ARP Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD14-66F01 GJ6A-34-111 Mazda 6 [2002-2006] Shock Absorber Bumper [FR]	 <small>ASH-2013-November-15 Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD14-66F01U GJ6A-34-111 Mazda 6 [2002-2006] MEP-Shock Absorber Bumper [FR]	 <small>ASH-2013-July-10 Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD14-66F02 GJ6A-34-015 Mazda 6 [2002-2007] = GG Mazda 6 MPS [2005] = GG Mazda 6 Wagon [2002-2007] = GY Atenza [2002-2 Shock Absorber Dust Cover	 <small>ARP Product</small> www.rbi.ae		
AD14-67F00 GS1D-34-012 Mazda 6 [2007] = GH Mazda 6 Wagon [2007] = GH Shock Absorber Dust Cover [FR]	 <small>ARP Product</small> www.rbi.ae	AD14-67F01 GS1D-34-111 Mazda 6 [2007] = GH Mazda 6 Wagon [2007] = GH Shock Absorber Bumper Bound [FR]	 <small>ARP Product</small> www.rbi.ae
AD14-CX707F01U L206-34-111 CX-7 [2006] = ER CX-9 [2007] = TB Shock Absorber Bumper [FR]	 <small>ARP Product</small> www.rbi.ae		



Revision : 2014-November-01

MAZDA | FORD

AD14-T20E E112-28-1A0  Escape [2000-2007] Ford Tribute Shock Absorber Bumper [RE]	RBI-2008-February-25 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD14-T20EU E112-28-1A0  Escape [2000-2007] Ford Tribute MEP-Shock Absorber Bumper [RE]	RBI-2008-December-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD14-T20F E112-34-111  Escape [2000-2007] Ford Tribute Shock Absorber Bumper [FR]	RBI-2008-February-25 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD14-T20F02 EC01-34-0A5  Tribute [2000-2007] = EP Shock Absorber Dust Cover	ARP Product www.rbi.ae
AD14-T20F1 E112-34-0A5  Escape [2000-2007] Ford Tribute Shock Absorber Dust Cover [FR]	RBI-2009-January-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD14-T20FU E112-34-111  Escape [2000-2007] Ford Tribute MEP-Shock Absorber Bumper [FR]	RBI-2008-October-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD14-T20FU03 EC01-34-111  Tribute [2000-2007] = EP Shock Absorber Bumper [FR]	ARP Product www.rbi.ae		
AD14-XDS1E00 T001-28-111  Mazda Xedos-9 / Milenia TA [1993-2000] Shock Absorber Dust Cover [RE]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD14-XDS1F00 T001-34-111  Mazda Xedos-9 / Milenia TA [1993-2000] Shock Absorber Dust Cover [FR]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO14-FOC11F01 1710056 <div>ARP Product</div> www.rbi.ae Ford Focus III [2011] = CB8 MEP-Shock Absorber Bumper [FR]	
AFO14-MON00E01 1151390 <div>ARP Product</div> www.rbi.ae Ford Mondeo [2000-2007] = GE MEP-Shock Absorber Bumper [RE]	
AFO14-MON00F00 1110000 <div>ARP Product</div> www.rbi.ae Ford Mondeo [1996-2000] = GD Ford Mondeo [2000-2007] = GE Ford Transit Connect [2002] = TC7 Shock Absorber Dust Cover [FR]	AFO14-MON00F01 1307842 <div>ARP Product</div> www.rbi.ae Ford Mondeo [2000-2007] = GE MEP-Shock Absorber Bumper [FR]
AFO14-TRA00F01 4040000 <div>ARP Product</div> www.rbi.ae Ford Transit [2000-2006] = FY MEP-Shock Absorber Bumper [FR]	
AFO14-TRA06F00 1434150 <div>ARP Product</div> www.rbi.ae Ford Transit [2006] = TT9 Shock Absorber Dust Cover [FR]	AFO14-TRA06F01 1383523 <div>ARP Product</div> www.rbi.ae Ford Transit [2006] = TT9 MEP-Shock Absorber Bumper [FR]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD17-31IZ F001-22-540  Mazda 323 Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD17-31UZ F001-22-530  Mazda 323 Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD17-36IZ F024-22-540  Mazda 323 [1992] Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD17-36UZ F024-22-530  Mazda 323 [1992] Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD17-37IZ F061-22-540  Mazda 323 [1995-2000] Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD17-37UZ F069-22-530  Mazda 323 [1995-2000] ASTINA Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD17-61IZ G001-22-540  Mazda 626 Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD17-61UZ G001-22-530  Mazda 626 Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD17-64IZ G560-22-540  Mazda 626 Drive Shaft Boot [Inner, A/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD17-64UZ G560-22-530  Mazda 626 Drive Shaft Boot [Outer, A/T]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD17-A00UB FA21-22-530  Mazda 323 Drive Shaft Boot [Outer] [1.8, 2.0]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD17-A00UZ FA50-22-530  Mazda 323 [2000] Drive Shaft Boot [Outer] [1.6, 1.8]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD17-MZ3I0 FG02-22-540 Mazda 3 [2003] Drive Shaft Boot [Inner, A/T] [1.6]	  <small>RBI-2007-August-20 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD17-MZ3IM FG01-22-540 Mazda 3 [2003] Drive Shaft Boot [Inner, M/T] [1.6]	  <small>RBI-2007-September-10 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
AD17-MZ3IZ GG25-22-540 Mazda 3 [2003] Drive Shaft Boot [Inner]	  <small>RBI-2007-August-01 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD17-MZ3UZ GG25-22-530 Mazda 3 [2003] Drive Shaft Boot [Outer]	  <small>RBI-2007-August-01 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
AD17-MZ2IA FA81-22-540 Mazda 2 Fiesta [2003-2007] Drive Shaft Boot [Inner, A/T]	  <small>RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD17-MZ2UA FA81-22-530 Mazda 2 Fiesta [2003-2007] Drive Shaft Boot [Outer, A/T]	  <small>RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
AD17-MZ2IM FD80-22-540 Mazda 2 Fiesta [2003-2007] Drive Shaft Boot [Inner, A/T]	  <small>RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD17-MZ2UM FD80-22-530 Mazda 2 Fiesta [2003-2007] Drive Shaft Boot [Outer, A/T]	  <small>RBI-2013-June-15 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD17-T20IZ GD29-22-540 Escape Ford Tribute Drive Shaft Boot [Inner, RE]	RBI-2009-January-07 RBI Product www.rbi.ae 	AD17-T20UE GD29-22-530 Escape Ford Tribute Drive Shaft Boot [Outer, RE]	RBI-2009-January-16 RBI Product www.rbi.ae 
AD17-T20IF YL8Z-3A331-AA Escape Ford Tribute Drive Shaft Boot [Inner, FR]	RBI-2009-November-24 RBI Product www.rbi.ae 	AD17-T20UF GG15-22-530 Escape Ford Tribute Drive Shaft Boot [Outer, FR]	RBI-2009-January-07 RBI Product www.rbi.ae 
AD17-T23IZ GP06-22-540 Escape Ford Tribute Drive Shaft Boot [Inner] [2,3]	RBI-2010-March-16 RBI Product www.rbi.ae 	AD17-T23UZ GA35-22-530 Escape Ford Tribute Drive Shaft Boot [Outer] [2,3]	RBI-2010-March-16 RBI Product www.rbi.ae 
AD17-CX707IZ GP27-22-540 CX-7 [2006] = ER CX-9 [2007] = TB Drive Shaft Boot [Inner]	ARP Product www.rbi.ae		
AD17-4X1IZ M080-22-540 Fighter, Ford Ranger Drive Shaft Boot [Inner]	RBI-OLD RBI Product, Perfect Product www.rbi.ae 	AD17-4X1UZ M080-22-530 Fighter, Ford Ranger Drive Shaft Boot [Outer]	RBI-OLD RBI Product, Perfect Product www.rbi.ae 
AD17-BT54I PP01-22-540 Mazda BT-50 [2006-2011] = UN Drive Shaft Boot [Inner, 4WD]	RBI-2014-March-12 RBI Product www.rbi.ae 	AD17-BT54U PP01-22-530 Mazda BT-50 [2006-2011] = UN Drive Shaft Boot [Outer]	RBI-2014-July-14 RBI Product www.rbi.ae





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO17-FOC04I1Z 1451975 <div>ARP Product</div> Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo www.rbi.ae Drive Shaft Boot [Inner]	AFO17-FOC04I2Z #4371796 <div>ARP Product</div> Ford Focus II [2004-2008] Ford Transit Connect [2002] = TC7 www.rbi.ae Drive Shaft Boot [Inner]
AFO17-FOC04UZ #1345655 <div>ARP Product</div> Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo www.rbi.ae Drive Shaft Boot [Outer]	
AFO17-FOC08IZ 1550000 <div>ARP Product</div> Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Focus Cabriolet [2006-2011] = CA5 www.rbi.ae Drive Shaft Boot [Inner]	
AFO17-MON07I1Z #1504139 <div>ARP Product</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 www.rbi.ae Drive Shaft Boot [Inner]	AFO17-MON07I2Z #1417222 <div>ARP Product</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 www.rbi.ae Drive Shaft Boot [Inner]
AFO17-MON07I3Z 1450000 <div>ARP Product</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 www.rbi.ae Drive Shaft Boot [Inner]	
AFO17-MON07U1Z #1459740 <div>ARP Product</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 www.rbi.ae Drive Shaft Boot [Outer]	AFO17-MON07U2Z #1504137 <div>ARP Product</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Ford Transit Connect [2002] = TC7 Ope www.rbi.ae Drive Shaft Boot [Outer]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD18-31LZ B001-32-118  Mazda 323 Steering Gear Boot [LH]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD18-31RZ B001-32-125  Mazda 323 Steering Gear Boot [RH]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD18-36PZ B456-32-125  Mazda 323 Steering Gear Boot [Power] [2.0]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD18-61Z G030-32-125  Mazda 626 Steering Gear Boot [LH, RH]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD18-62PZ H002-32-125  Mazda 626 Steering Gear Boot [Power]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD18-640 GA2A-32-125  Mazda 626 Steering Gear Boot	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD18-A000 GJ25-32-125  Mazda 626 Steering Gear Boot	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD18-MZ30Z BP4L-32-12XM00  Mazda 3 [2003] Steering Gear Boot	RBI-2008-August-15 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD18-MZ20Z D651-32-12X  Mazda 2 Fiesta [2011-2013] Steering Gear Boot [FR, LH, RH]	RBI-2013-June-15 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD18-T20Z E112-32-F0Y  Escape Ford Tribute Steering Gear Boot	RBI-2009-January-24 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AFO18-MON07FLR 1433372 <small>ARP Product</small> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Land Rover Freelander II [2006] Volvo Steering Gear Boot www.rbi.ae	
AFO18-TRA00FL 4602027 <small>ARP Product</small> Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2006] = TT9 Steering Gear Boot [FR, LH] www.rbi.ae	AFO18-TRA00FR 4600000 <small>ARP Product</small> Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2006] = TT9 Steering Gear Boot [FR, RH] www.rbi.ae





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD20-01B 0866-28-333  Mazda 808 Spring Shackle Rubber [FR, Big]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD20-01G 0866-28-353  Mazda 808 Spring Shackle Rubber [Long, RE]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD20-01T 0866-28-343  Mazda 808 Spring Shackle Rubber [RE, Short]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com		
AD20-02B 0443-28-333  Mazda 929 Spring Shackle Rubber [Big]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD20-02G 1011-28-353  Mazda 929 Spring Shackle Rubber [Long, RE]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD20-02T 0443-28-343  Mazda 929 M1200, M1300, M1400 Spring Shackle Rubber [RE, Short]	RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com		
AD20-430 3874-28-330  Magnum, B1600, Fighter Mazda B2200 [1996] Mazda B2500 [2002] Mazda B2500, B2600 [1996] = UF Spring Shackle Bush [FR]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD20-45G UB39-28-333  Magnum, Fighter Spring Shackle Rubber [Long, RE]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AD20-45T UB40-28-333  Magnum, Fighter Spring Shackle Rubber [RE, Short]	RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com		
AD20-E270E01 S083-28-444  Mazda E2700 Spring Shackle Rubber	PFT-2014-October-15 Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD20-E270E02 S085-28-444  Mazda E2700 Spring Shackle Rubber	PFT-2014-October-15 Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD20-BT52F UR58-28-450  Mazda = BT50 [2006] [2WD, 4WD] Spring Shackle Bush [FR]	RBI-2009-May-13 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com	AD20-BT50F01 UH71-28-450  Mazda BT-50 [2006] Spring Shackle Bush [FR]	PFT-2012-June-26 Perfect Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com
AFO20-TRA00E01 4055743 ARP Product www.rbi.ae Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2000-2006] = FY Spring Shackle Bush [RE]		AFO20-TRA06E01 1420171 ARP Product www.rbi.ae Ford Transit [2006] = TT9 Spring Shackle Bush [RE]	
AFO20-TRA06E02 1431018 ARP Product www.rbi.ae Ford Transit [2006] = TT9 Spring Shackle Bush [RE]		AFO20-TRA06E03 1430000 ARP Product www.rbi.ae Ford Transit [2006] = TT9 Spring Shackle Bush [RE]	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD21-04E00 H380-28-156 Mazda 929 [1991-1996] = HD Stabilizer Shaft Rubber	AD21-04F00 H380-34-156 Mazda 929 [1991-1996] = HD Stabilizer Shaft Rubber
AD21-330 B029-34-156 Mazda 323 [1985-1988] Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Ashimori Product  www.rbi.ae www.alafuae.com
AD21-36F B459-34-156 Mazda 323 [1989-1993] Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, HFC Product  www.rbi.ae www.alafuae.com
AD21-37F BC1D-34-156 Mazda 323 [1994-1997] Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Tenacity Product, Ashimori Product  www.rbi.ae www.alafuae.com
AD21-A00F B26R-34-156 Mazda 323 [1998-2002] Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com
AD21-37E G564-28-156 Mazda 323 [1994-2002] Stabilizer Shaft Rubber [RE]	RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com



Revision : 2014-November-01

MAZDA | FORD

<p>AD21-MZ3F BP4K-34-156</p> <p>Mazda 3 [2003-2006]</p> <p>Stabilizer Shaft Rubber [FR] [1.3, 1.6, 2.0]</p>  <p>RBI-2008-February-19 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD21-MZ3E BP4K-28-156</p> <p>Mazda 3 [2003-2006]</p> <p>Stabilizer Shaft Rubber [RE] [1.3, 1.6, 2.0]</p>  <p>RBI-2008-February-12 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD21-MZ303F2 CC29-34-156</p> <p>Mazda 3 [2003-2008] = BK Mazda 5 [2005-2010] = CR Axela [2003-2009] Biente [2008] = CCEFW</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD21-MZ02F DL33-34-156</p> <p>Mazda 2 [2003-2007] = DY Fiesta 5D</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-2013-February-08 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD21-MZ020F DN21-34-156</p> <p>Mazda 2 [2003-2007] = DY Fiesta 4D</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>RBI-2013-May-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD21-MZ207F00 DF71-34-156</p> <p>Mazda 2 [2007] = DE Demio [2007] = DE</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>PFT-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD21-MZ207F01 D651-34-156</p> <p>Mazda 2 [2007] = DE Demio [2007] = DE</p> <p>Stabilizer Shaft Rubber [FR]</p>  <p>PFT-2014-January-01 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD21-MZ505E00 C243-28-156</p> <p>Mazda 5 [2005-2010] = CR Premacy [2005-2010] = CREW, CR3W</p> <p>Stabilizer Shaft Rubber [RE]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD21-62F G041-34-156  Mazda 626 [1985-1990] Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD21-62E G067-28-156  Mazda 626 [1987-1990] Mazda 323 [1985-1988] Stabilizer Shaft Rubber [RE]	RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD21-64F GA2B-34-156  Mazda 626 [1991-1996] Stabilizer Shaft Rubber [FR]	RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD21-64E GA2A-28-156  Mazda 626 [1991-1996] Stabilizer Shaft Rubber [RE]	RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD21-65F GE4T-34-156  Mazda 626 [1997-2001] Stabilizer Shaft Rubber [FR]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD21-65E GE4T-28-156  Mazda 626 [1997-2001] Mazda 323 [1998-2002] Stabilizer Shaft Rubber [RE]	ASH-2012-December-25 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD21-66F00 GJ6A-34-156  Mazda 6 [2002-2006] Stabilizer Shaft Rubber [FR]	RBI-2014-March-12 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD21-66E00 GJ6A-28-156  Mazda 6 [2002-2006] Stabilizer Shaft Rubber [RE]	RBI-2014-July-14 RBI Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD21-67F00 GS1D-34-15Y  Mazda 6 [2008-2013] = GH Mazda 6 Wagon [2008-2013] = GH Stabilizer Shaft Rubber [FR]	ARP Product www.rbi.ae 	AD21-67E00 GS1D-28-156  Mazda 6 [2007] Stabilizer Shaft Rubber [RE]	RBI-2014-July-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD21-MPVF LC62-34-156  Mazda MPV [1999-2003] Stabilizer Shaft Rubber [FR]	TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD21-010 1881-34-156  Mazda 808  Stabilizer Shaft Rubber [Small Diameter]	AD21-020 0305-34-156  Mazda 929  Stabilizer Shaft Rubber [Big Diameter]
AD21-430 0603-34-156  B1600  Stabilizer Shaft Rubber	AD21-440 UA01-34-156  B2200  Stabilizer Shaft Rubber
AD21-450 UB71-34-156  Magnum, Fighter  Stabilizer Shaft Rubber	AD21-4X1F UH74-34-156  Fighter, Ford Ranger [4WD]  Stabilizer Shaft Rubber [FR]
AD21-E200F S083-34-156  Mazda = E2000, E2200 [1987-1998] [2WD]  Stabilizer Shaft Rubber [FR]	AD21-E201F S113-34-156  Mazda = E2000, E2200 [1987-1998] [2WD]  Stabilizer Shaft Rubber [FR]
AD21-F14F 1410-34-156  M1400  Stabilizer Shaft Rubber [FR]	



Revision : 2014-November-01

MAZDA | FORD

AD21-BT52F UR58-34-156 Mazda = BT50 [2006] [2WD] Stabilizer Shaft Rubber [FR]	RBI-2009-April-08 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD21-BT52E UR58-28-156 Mazda = BT50 [2006] [2WD] Stabilizer Shaft Rubber [RE]	RBI-2009-May-04 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD21-BT54F UP20-34-156 Mazda = BT50 [2006] [4WD] Stabilizer Shaft Rubber [FR]	RBI-2009-April-07 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD21-BT54E UR61-28-156 Mazda = BT50 [2006] [4WD] Stabilizer Shaft Rubber [RE]	RBI-2009-May-02 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD21-T10F E112-34-156 Escape Ford Tribute Stabilizer Shaft Bush [FR]	RBI-2009-July-29 RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD21-T10F2 EC01-34-156 Mazda Tribute [2000-2007] = EP Escape Ford Tribute Stabilizer Shaft Bush [FR]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD21-T10F5 EF92-34-156 Tribute [2000-2007] = EP Ford Maverick [2000-2006] = TM1 Ford Maverick [2006-2009] = TM7 Stabilizer Shaft Rubber [FR]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD21-DEM1F00 D107-34-156 Demio [1998-2002] Stabilizer Shaft Rubber [FR]	TN-2014-February-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD21-DEM2F00 D350-34-156 Demio [2002-2007] = DY3, DY5 Stabilizer Shaft Rubber [FR]	TN-2014-February-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD21-CX707E00 EG21-28-156 CX-7 [2006] = ER CX-9 [2007] = TB Stabilizer Shaft Rubber [RE]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD21-CX707F00 EG21-34-156B Mazda CX-7 [2006] = ER Stabilizer Shaft Rubber [FR]	ARP Product www.rbi.ae




AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD21-S10HE00 S10H-28-156 Bongo Friendee [1995-2005] = SG# Stabilizer Shaft Rubber [RE]  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD21-S10HF00 S10H-34-156 Bongo Friendee [1995-2005] = SG# Stabilizer Shaft Rubber [FR] ARP Product www.rbi.ae
AD21-T35E00 W015-34-913 Mazda Titan Truck = T3000, T3500 Stabilizer Shaft Rubber [RE] ARP Product www.rbi.ae	







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD21-FES93F00 KKY01-34-156  Ford FESTIVA 1.3, 1.5 [1993-1995]  Stabilizer Shaft Rubber	
AFO21-FOC98F00 1073217 ARP Product www.rbi.ae Ford Focus I [1998-2005] = CAK Volvo S40 II [2004] Volvo V50 [2004] Stabilizer Shaft Rubber [FR]	
AFO21-FOC04E00 1345913 ARP Product www.rbi.ae Ford C-max [2003-2007] = CAP Ford Focus [2008-2011] = CB4 Ford Focus II [2004-2008] Stabilizer Shaft Rubber [RE]	AFO21-FOC04F00 1305960 ARP Product www.rbi.ae Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo Stabilizer Shaft Rubber [FR]
AFO21-FOC04F01 1348231 ARP Product www.rbi.ae Ford C-max [2003-2007] = CAP Ford Focus II [2004-2008] Stabilizer Shaft Rubber [FR]	
AFO21-TRA00E00 4041490 ARP Product www.rbi.ae Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2006] = TT9 Stabilizer Shaft Rubber [RE]	AFO21-TRA00F00 4671720 ARP Product www.rbi.ae Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2006] = TT9 Stabilizer Shaft Rubber [FR]
AFO21-TRA00F01 4040000 ARP Product www.rbi.ae Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Stabilizer Shaft Rubber [FR]	













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO21-MON92E00 93BB-4A037EA  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Stabilizer Shaft Rubber [RE, 2.0]	AFO21-MON92E01 93BB-4A037AC  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Stabilizer Shaft Rubber [RE, 2.0]
AFO21-MON92F00 93BB-5484AB  Ford Mondeo [1992-2000] = FD Ford Mondeo [1996-2000] = GD Stabilizer Shaft Rubber [FR, 2.0]	
AFO21-MON00E00 1124418  Ford Mondeo [2000-2007] = GE Stabilizer Shaft Rubber [RE]	AFO21-MON00F00 1118695  Ford Mondeo [2000-2007] = GE Stabilizer Shaft Rubber [FR]
AFO21-MON07E00 1581670  Ford Focus II [2008-2011] = CB4 Ford Mondeo [2007] = CA2 Volvo S60 II [2010] Volvo S80 II [200]	AFO21-MON07F00 1478582  Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S80 II [2007] Volvo V70 III [20]
AFO21-EXP02F00 4L2Z5484DA  Ford Explorer III [2002-2010] Stabilizer Shaft Rubber [FR]	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD23-01Y 1393-34-156</p>  <p>Mazda 808 Mazda 929</p> <p>Strut Bar Rubber</p>	<p>AD23-33Y 8565-34-153</p>  <p>Mazda 323</p> <p>Strut Bar Rubber</p>
<p>AD23-45Y UB39-34-136</p>  <p>Magnum, Fighter</p> <p>Strut Bar Rubber</p>	<p>AD23-45Z UB39-34-136</p>  <p>Magnum, Fighter</p> <p>Strut Bar Rubber Set [Set]</p>
<p>AD23-E200Y S083-34-136</p>  <p>Mazda = E2000, E2200 [1987-1998] [2WD]</p> <p>Strut Bar Rubber</p>	
<p>AD23-102Y H001-34-136</p>  <p>Mazda 929 [1982-1987] Mazda 929 [1986-1991] = HC Mazda 808</p> <p>Strut Bar Rubber</p>	<p>AD23-61Y 8173-34-136</p>  <p>Mazda 626 [1980-1985]</p> <p>Strut Bar Rubber</p>
<p>AD23-FES93F00 MD001-34-153</p>  <p>Mazda FESTIVE [1993]</p> <p>Strut Bar Rubber</p>	
<p>AFO23-TAU90F01 4616383</p>  <p>Chrysler Concorde Interpid 300M [2002] Ford Taurus II [1990-1995] Ford Taurus III [1996-1999]</p> <p>Strut Bar Rubber</p>	<p>AFO23-TAU90F02 4620000</p>  <p>Chrysler Concorde Interpid 300M [2002] Ford Taurus II [1990-1995] Ford Taurus III [1996-1999]</p> <p>Strut Bar Rubber</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD24-33WB

B001-34-460

Mazda 323 [1979-1989]

Front Lower Arm Bush [FR, Big]



RBI-OLD
RBI Product, Perfect Product,
Tenacity Product, Ashimori
Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com

AD24-32WS

B210-34-470

Mazda 323 [1979-1989]

Front Lower Arm Bush [FR, Small]



RBI-OLD
RBI Product, Perfect Product,
Tenacity Product, HFC
Product, Ashimori Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com

AD24-33WS

B001-34-470

Mazda 323 [1979-1989]

Front Lower Arm Bush [FR, Small]



RBI-OLD
RBI Product, Perfect Product,
HFC Product, Ashimori
Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD25-33Z B001-28-SET</p> <p>Mazda 323 [1983-1989]</p> <p>Rear Suspension Bush [Set] [RE] [Set 12 Pcs.]</p> <p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD25-33E1B B092-28-600</p> <p>Mazda 323 [1983-1989]</p> <p>Rear Suspension Bush [RE, Big, Link-01]</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD25-33E1S B092-28-600</p> <p>Mazda 323 [1983-1989]</p> <p>Rear Suspension Bush [RE, Small, Link-01]</p> <p>Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>PERFECT RUBBER PARTS</p>
<p>AD25-33E1C B092-28-600</p> <p>Mazda 323 [1985-1989]</p> <p>Rear Complete Suspension Arm [RE, RH, LH] [Arm#, 1] [With 2 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD25-33E2B B092-28-500</p> <p>Mazda 323 [1983-1989]</p> <p>Rear Suspension Bush [RE, Big, Link-02]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD25-33E2S B092-28-500</p> <p>Mazda 323 [1983-1989]</p> <p>Rear Suspension Bush [RE, Small, Link-02]</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD25-33E2CR B092-28-500</p> <p>Mazda 323 [1985-1989]</p> <p>Rear Complete Suspension Arm [RE, RH] [Arm#, 2] [With 2 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD25-33E3B B092-28-200</p> <p>Mazda 323 [1985-1989]</p> <p>Rear Suspension Bush [RE, Big, Link-03]</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.









ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD24-37B B455-34-46X</p> <p>Mazda 323 [1989-1997]</p> <p>Front Lower Arm Bush [FR, Big]</p>   <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD24-37S B459-34-470</p> <p>Mazda 323 [1989-1994]</p> <p>Front Lower Arm Bush [FR, Small]</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD24-37BLZ B455-34-46Y</p> <p>Mazda 323 [1989-1997]</p> <p>Front Lower Arm Bush [Bracket] [FR, Big, LH] [1.6, 1.5]</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD24-37BRZ B455-34-46X</p> <p>Mazda 323 [1989-1997]</p> <p>Front Lower Arm Bush [Bracket] [FR, Big, RH] [1.6, 1.5]</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD24-38WB BC1F-34-46Y  Mazda 323 [1994-1997] Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-38WS BC1D-34-470  Mazda 323 [1994-1997] Front Lower Arm Bush [FR, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD24-38BLZ BC1F-34-46Y  Mazda 323, MX3 [1994-1997] Front Lower Arm Bush [Bracket] [FR, Big, LH] [1.7, 1.8]	RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-38BRZ BC1F-34-46X  Mazda 323, MX3 [1994-1997] Front Lower Arm Bush [Bracket] [FR, Big, RH] [1.7, 1.8]	RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com





















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD25-37B B455-28-200  Mazda 323 [1989-1998] Rear Suspension Bush [RE, Big]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-37S B455-28-200  Mazda 323 [1989-1998] Rear Suspension Bush [RE, Small]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD25-37L B455-28-620  Mazda 323 [1989-1998] Rear Suspension Bush [RE] [LH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD25-37RG B455-28-600  Mazda 323 [1989-1998] Rear Suspension Bush [RE] [RH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-37RT B455-28-630  Mazda 323 [1989-1998] Rear Suspension Bush [RE] [RH]	RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD25-37E1C BR70-28-600  Mazda 323 [1989-1995] Rear Complete Suspension Arm [RE, RH, LH] [Arm#, 1] [With 2 Bush]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD25-37E2CR BR70-28-620  Mazda 323 [1989-1995] Rear Complete Suspension Arm [RE, RH] [Arm#, 2] [With 2 Bush]	Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-37E2CL BR70-28-630  Mazda 323 [1989-1995] Rear Complete Suspension Arm [RE, LH] [Arm#, 2] [With 2 Bush]	Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD25-360 B455-39-830  Mazda 323 [1992-1995] Suspension Rubber [RE]	RBI-2008-February-02 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
	AD25-362 B092-39-811  Mazda 323 [1992-1995] Suspension Rubber [FR]
AD25-361 B455-39-820  Mazda 323 [1992-1995] LANTIS Suspension Rubber [RE]	RBI-2008-April-19 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD26-330 B001-39-811  Mazda 323 Suspension Rubber [RE]	RBI-OLD RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD24-A00B B25D-34-460</p>  <p>Mazda 323 [1998-2002]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2010-April-27 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product www.rbi.ae www.alafuae.com</p>  <p>AD24-A00WBJ B25D-34-3BJ</p> <p>ARP Product</p> <p>Mazda 323 [1998-2004] = BJ KIA Clarus [1996] = K9A Mazda 626 [1991-1997] = GE Mazda 626 [1997-]</p> <p>www.rbi.ae</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<p>AD24-A00S B25D-34-470</p>  <p>Mazda 323 [1998-2002]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product www.rbi.ae www.alafuae.com</p>  <p>AD24-A01S B28V-34-470</p> <p>PFT-2012-June-26 Perfect Product, Tenacity Product www.rbi.ae www.alafuae.com</p>  <p>Mazda 323 [1998-2002]</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>AD24-A00LCRZZ B25D-34-300</p>  <p>Mazda 323 [1998-2002]</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AD24-A00LCLZZ B25D-34-350</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Mazda 323 [1998-2002]</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p>










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD25-A00E3 BJ3D-28-600  Mazda 323 [1998-2002] Rear Suspension Bush [RE, Big, Link-02]	AD25-A00E4 BJ3D-28-600  Mazda 323 [1998-2002] Rear Suspension Bush [RE, Small, Link-02]
AD25-A00E5 BJ3D-28-620  Mazda 323 [1998-2002] Rear Suspension Bush [RE, Big, Link-03]	AD25-A00E6 BJ3D-28-620  Mazda 323 [1998-2002] Rear Suspension Bush [RE, Small, Link-03]
AD25-A00E7S BL8D-28-201  Mazda 323 [1998-2004] = BJ Mazda Familia [1998-2004] = BJ Mazda Premacy [1999-2005] = CP Rear Suspension Bush [RE, Small]	AD25-A00E7B BL8D-28-202  Mazda 323 [1998-2004] = BJ Mazda Familia [1998-2004] = BJ Mazda Premacy [1999-2005] = CP Rear Suspension Bush [RE, Big]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD24-MZ2WS D350-34-350</p> <p>Mazda 2 [2003-2007] = DY Mazda 2 [2003-2007] = DY Mazda Demio [2002] = DY3, DY5 Mazda Demio [2]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>AD24-MZ203WS DL33-34-470</p> <p>Mazda 2 [2003-2007] = DY Fiesta 5D</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>AD24-MZ2WB D350-34-300</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5 Ford Fie</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>AD24-MZ203WB DL33-34-460</p> <p>Mazda 2 [2003-2007] = DY</p> <p>Front Lower Arm Bush [FR, Big]</p>
<p>AD24-MZ2WBZ D350-34-300</p> <p>Mazda 2 [2003-2007] = DY Mazda Demio [2002-2007] = DY3, DY5 Mazda Verisa [2004] = DC5 Ford Fie</p> <p>Front Lower Arm Bush [Bracket] [FR, LH, RH]</p>	<p>AD24-MZ2WBJ D350-34-3BJ</p> <p>Ford Fiesta V [2001-2008] = JH Ford Fiesta, Fusion [2001-2008] = CBK Ford Fusion [2002] = JU M</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<p>AD24-MZ203LCLZZ DD32-34-350</p> <p>Mazda 2 [2003-2007]</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p>	<p>AD24-MZ203LCRZZ DD32-34-300</p> <p>Mazda 2 [2003-2007]</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p>












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD24-MZ207WB D651-34-300  Mazda 2 [2007] = DE Demio [2007] = DE  Front Lower Arm Bush [FR, Big]	AD24-MZ207WS D651-34-470  Mazda 2 [2007] = DE Demio [2007] = DE Ford Fiesta [2008] = CB1  Front Lower Arm Bush [FR, Small]
AD24-MZ207WBJ D651-34-3BJ  Ford Fiesta [2008] = CB1 Mazda 2 [2007] = DE Mazda Demio [2007] = DE Front Lower Arm Ball Joint [FR, LH, RH]	
AD24-MZ207LCLZZ D651-34-350  Mazda 2 [2007-2011] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	AD24-MZ207LCRZZ D651-34-300  Mazda 2 [2007-2011] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]



Revision : 2014-November-01

MAZDA | FORD

<div>AD24-MZ3WS</div> <div>B32H-34-350</div> <div></div> <div>Mazda 3 & 5 [2003-2010]</div> <div>Front Lower Arm Bush [FR, Small]</div>	<div>RBI-2007-August-20 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div>	<div>AD24-MZ303WBJ</div> <div>B32H-34-3BJ</div> <div>ARP Product</div> <div>Mazda 3 [2003-2008] = BK Mazda 3 [2009] = BL Mazda 5 [2005-2010] = CR Mazda Axela [2003-2009]</div> <div>www.rbi.ae</div> <div>Front Lower Arm Ball Joint [FR, LH, RH]</div>
<div>AD24-MZ3WB</div> <div>B32H-34-350</div> <div></div> <div>Mazda 3 & 5 [2003-2010]</div> <div>Front Lower Arm Bush [FR, Big]</div>	<div>RBI-2009-March-04 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div>	<div>AD24-MZ3WZ</div> <div>B32H-34-350</div> <div>Tenacity Product, Ashimori Product</div> <div>Mazda 3 & 5 [2003-2010]</div> <div>www.rbi.ae</div> <div>Front Lower Arm Bush [Bracket] [FR, Big]</div>
<div>AD24-MZ3LCRZZ</div> <div>B32H-34-300</div> <div>HFC Product</div> <div>Mazda 3 & 5 [2003-2010]</div> <div>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</div>	<div>shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div>	<div>AD24-MZ3LCLZZ</div> <div>B32H-34-350</div> <div>HFC Product</div> <div>Mazda 3 & 5 [2003-2010]</div> <div>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</div>
<div>AD24-MZ309WS</div> <div>BBM2-34-350</div> <div></div> <div>Mazda 3 [2009] = BL Ford C-max [2003-2007] = CAP Ford C-max [2006] = CB3 Ford Focus [2008-2011]</div> <div>Front Lower Arm Bush [FR, Small]</div>	<div>PFT-2014-January-14 Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div>	
<div>AD24-MZ309WLZ</div> <div>BBM2-34-350</div> <div></div> <div>Mazda 3 [2009] = BL</div> <div>Front Lower Arm Bush [Bracket] [FR, LH] [Big]</div>	<div>TN-2014-February-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com</div>	<div>AD24-MZ309WRZ</div> <div>BBM2-34-300</div> <div>Tenacity Product</div> <div>Mazda 3 [2009] = BL</div> <div>Front Lower Arm Bush [Bracket] [FR, RH] [Big]</div>
<div>AD24-MZ309LCLZZ</div> <div>B39D-34-350</div> <div>ARP Product</div> <div>Mazda 3 [2009] = BL</div> <div>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</div>	<div>www.rbi.ae</div>	<div>AD24-MZ309LCRZZ</div> <div>B39D-34-300</div> <div>ARP Product</div> <div>Mazda 3 [2009] = BL</div> <div>Front Complete Lower Arm [FR, RH]</div>

Revision : 2014-November-01

MAZDA | FORD

AD25-MZ301 BP4K-28-200  Mazda 3 [2003-2010] Rear Suspension Bush [RE] [1] [2 Pcs/Car]	RBI-2008-February-19 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	
AD25-MZ303 BP4K-28-C10  Mazda 3 [2003-2010] Rear Suspension Bush [RE] [3] [2 Pcs/Car]	RBI-2008-February-28 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-MZ303EZ BP4K-28-C10 ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com Mazda 3 [2003-2010] Rear Complete Suspension Arm [RE] [Arm#, 3] [With 2 Bush]
AD25-MZ304 BP4K-28-500  Mazda 3 [2003-2010] Rear Suspension Bush [RE] [4] [2 Pcs/Car]	RBI-2008-March-17 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	
AD25-MZ302 BP4K-28-300  Mazda 3 [2003-2010] Rear Suspension Bush [RE, Big] [Link-02] [2 Pcs/Car]	RBI-2008-February-19 RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-MZ305 BP4K-28-300  Mazda 3 [2003-2010] Rear Suspension Bush [RE, Small] [Link-02] [2 Pcs/Car]
AD25-MZ304ZZ BP4K-28-500  Mazda 3 [2005-2006] Rear Complete Suspension Arm [RE]	Ashimori Product www.rbi.ae	
AD25-MZ203E01 DD32-28-460  Mazda 2 [2003-2007] = DY Ford Fiesta V [2001-2008] = JH Ford Fiesta, Fusion [2001-2008] = CBK Rear Suspension Bush [RE]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-MZ207E01 D651-28-460  Mazda 2 [2007] = DE Demio [2007] = DE Rear Suspension Bush [RE]
AD26-MZ3E BRY0-28-910  Mazda 3 [2003] Front Shock Absorber Bush [RE]	RBI-2013-April-27 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD26-MZ2E DL33-28-70FX  Mazda 2 [2003-2007] = DY Fiesta 5D Front Shock Absorber Bush [RE]
AD26-MZ505B00 CC29-28-910  Mazda 5 [2005-2010] = CR Bianta [2008] = CCEFW Rear Shock Absorber Bush [RE]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD24-61W 8173-34-460</p> <p>Mazda 626 [1980-1985]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD24-62W G030-34-460</p> <p>Mazda 626 [1983-1987]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD24-63WB GJ21-34-460</p> <p>Mazda 626 [1987-1990]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD24-63LCRZZ GJ22-34-300</p> <p>Mazda 626 [1987-1990]</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p>	<p>AD24-63WS KA10-34-470</p> <p>Mazda 626 [1987-1990]</p> <p>Front Lower Arm Bush [FR, Small]</p>



Revision : 2014-November-01

MAZDA | FORD

AD25-62ZZ G030-28-SET  Mazda 626 [1985-1986]  Rear Suspension Bush [Set] [RE] [Set 12 Pcs.]	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	AD25-63ZZ GJ21-28-SET  Mazda 626 [1987-1990]  Rear Suspension Bush [Set] [RE] [Set 12 Pcs.]	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
AD25-62E3S G030-28-300  Mazda 626 [1983-1987]  Rear Suspension Bush [RE, Small]	<p>PFT-2012-March-28 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	AD25-62E3B G030-28-300  Mazda 626 [1983-1987]  Rear Suspension Bush [RE, Big]	<p>PFT-2012-March-28 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
AD25-62E3C G030-28-300  Mazda 626 [1983-1987]  Rear Complete Suspension Arm [RE, RH, LH] [Arm#, 3] [With 2 Bush]	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 		
AD25-6444 G376-28-200  Mazda 626 [1987-1990]  Rear Suspension Bush [RE, Small]	<p>RBI-2009-February-18 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	AD25-6442 G376-28-200  Mazda 626 [1987-1990]  Rear Suspension Bush [RE, Big]	<p>RBI-2009-February-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 

Revision : 2014-November-01

MAZDA | FORD

<p>AD25-6445 G211-28-620</p> <p>Mazda 626 [1983-1990]</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>RBI-2009-March-04 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
	<p>AD25-62E1B G030-28-600</p> <p>Mazda 626 [1983-1987]</p> <p>Rear Suspension Bush [RE, Big]</p>  <p>PFT-2012-March-28 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AD25-62E2B G030-28-500</p> <p>Mazda 626 [1983-1987]</p> <p>Rear Suspension Bush [RE, Big]</p>  <p>PFT-2012-March-28 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD25-6443R G211-28-601</p> <p>Mazda 626 [1988-1992] = GD</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD25-6443 G211-28-620</p> <p>Mazda 626 [1987-1990]</p> <p>Rear Suspension Bush [RE, Big]</p>  <p>RBI-2009-February-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD25-62E1C G030-28-600</p> <p>Mazda 626 [1983-1987]</p> <p>Rear Complete Suspension Arm [RE, RH, LH] [Arm#, 1] [With 2 Bush]</p>  <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD25-62E2CR G030-28-500</p> <p>Mazda 626 [1983-1987]</p> <p>Rear Complete Suspension Arm [RE, RH] [Arm#, 2] [With 2 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD25-62E2CL G030-28-550</p> <p>Mazda 626 [1983-1987]</p> <p>Rear Complete Suspension Arm [RE, LH] [Arm#, 2] [With 2 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD25-63E2CR G211-28-620</p> <p>Mazda 626 [1987-1990]</p> <p>Rear Complete Suspension Arm [RE, RH] [Arm#, 2] [With 2 Bush]</p>  <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	

Revision : 2014-November-01

MAZDA | FORD

AD24-64WB GA2A-34-46X  Mazda 626 [1991-1996] Front Lower Arm Bush [FR, Big]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-64WS GA2B-34-470  Mazda 626 [1991-1997] Front Lower Arm Bush [FR, Small, 1.8, 2.0]	RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD24-64WLZ GA2A-34-46Y  Mazda 626 [1991-1996] Front Lower Arm Bush [Bracket] [FR, Big, LH]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-64WRZ GA2A-34-46X  Mazda 626 [1991-1996] Front Lower Arm Bush [Bracket] [FR, Big, RH]	TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD24-65WB GE4T-34-46X  Mazda 626 [1997-2002] = GF Front Lower Arm Bush [FR, Big]	PFT-2014-May-28 Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-65WS GE4T-34-470  Mazda 626 [1997-2002] = GF Front Lower Arm Bush [FR, Small]	PFT-2012-November-07 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD24-65WLZ GE4T-34-46Y  Mazda 626 [1997-2002] Front Lower Arm Bush [Bracket] [FR, Big, LH]	TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-65WRZ GE4T-34-46X  Mazda 626 [1997-2002] Front Lower Arm Bush [Bracket] [FR, Big, RH]	TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD24-651LCRZZ GE4T-34-300  Mazda 626 [1997-2002] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD24-651LCLZZ GE4T-34-350  Mazda 626 [1997-2002] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com























AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD25-64ZZ GA2A-28-SET  Mazda 626 [1991-1996] Rear Suspension Bush [Set] [RE] [Set 12 Pcs.]	PFT-2014-August-31 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-65ZZ GE4T-28-SET  Mazda 626 [1997-2001] Rear Suspension Bush [Set] [RE] [Set 12 Pcs.]	PFT-2014-August-31 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD25-64E1B GA2A-28-601  Mazda 626 [1991-2001] Rear Suspension Bush [RE, Big]	PFT-2014-November-15 Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-64E1S GA2A-28-602  Mazda 626 [1991-1996] Rear Suspension Bush [RE, Small]	ASH-2013-July-10 Perfect Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD25-64E1BM GA2A-28-603  Mazda 626 [1991-1996] Rear Suspension Bush [RE, Metal, Big]	ASH-2013-November-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-64E1SM GA2A-28-604  Mazda 626 [1991-1996] Rear Suspension Bush [RE, Metal, Small]	ASH-2013-November-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
		AD25-65E1S GE4T-28-602  Mazda 626 [1997-2001] Rear Suspension Bush [RE, Small]	Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD25-64E1CR GA2A-28-600  Mazda 626 [1991-1996] Rear Complete Suspension Arm [RE, RH] [Arm#, 1] [With 2 Bush]	Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD25-64E1CL GA2A-28-60X  Mazda 626 [1991-1996] Rear Complete Suspension Arm [RE, LH] [Arm#, 1] [With 2 Bush]	ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD25-65E1Z GE4T-28-600  Mazda 626 [1997-2001] Rear Complete Suspension Arm [RE, LH, RH] [Arm#, 1] [With 2 Bush]	Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		



















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD25-64E2B GA2A-28-621  Mazda 626 [1991-1996] Mazda 626 [1997-2001] Rear Suspension Bush [RE, Big]	<small>ASH-2012-December-25 Perfect Product, Ashimori Product</small>  www.rbi.ae www.alafuae.com	AD25-64E2S GA2A-28-620  Mazda 626 [1991-1996] Rear Suspension Bush [RE, Small]	<small>PFT-2012-June-26 Perfect Product, Ashimori Product</small>  www.rbi.ae www.alafuae.com
AD25-64E2BM GA2A-28-623  Mazda 626 [1991-1996] Mazda 626 [1997-2001] Rear Suspension Bush [RE, Metal, Big]	<small>ASH-2014-May-15 Ashimori Product</small>  www.rbi.ae www.alafuae.com	AD25-64E2SM GA2A-28-624  Mazda 626 [1991-1996] Rear Suspension Bush [RE, Metal, Small]	<small>ASH-2013-November-15 Ashimori Product</small>  www.rbi.ae www.alafuae.com
		AD25-65E2S GE4T-28-622  Mazda 626 [1997-2001] Rear Suspension Bush [RE, Small]	<small>Perfect Product</small>  www.rbi.ae www.alafuae.com
AD25-64E2Z GA2A-28-620  Mazda 626 [1991-1996] Rear Complete Suspension Arm [RE, LH, RH] [Arm#, 2] [With 2 Bush]	<small>Ashimori Product</small>  www.rbi.ae www.alafuae.com		
AD25-65E2Z GE4T-28-620  Mazda 626 [1997-2001] Rear Complete Suspension Arm [RE, LH, RH] [Arm#, 2] [With 2 Bush]	<small>Ashimori Product</small>  www.rbi.ae www.alafuae.com		





AL LAMSA AL FIDDIYA TRADING L.L.C.




ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01














MAZDA | FORD

<p>AD25-6441 GA5R-28-200</p> <p>Mazda 626 [1991-2001]</p> <p>Rear Suspension Bush [RE, Big]</p>  <p>RBI-2009-February-12 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD25-6440 GA5R-28-200</p> <p>Mazda 626 [1991-2001]</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>RBI-2009-February-12 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
	<p>AD25-6440E2 G516-28-200</p> <p>Mazda 626 [1991-2001]</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>PFT-2014-November-15 Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>AD25-64E3C GA5R-28-200</p> <p>Mazda 626 [1991-1996]</p> <p>Rear Complete Suspension Arm [RE, RH, LH] [Arm#, 3] [With 2 Bush]</p> <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>AD25-65E3CR GE4T-28-200</p> <p>Mazda 626 [1997-2001]</p> <p>Rear Complete Suspension Arm [RE, RH] [Arm#, 3] [With 2 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>AD25-65E3CL GE4T-28-250</p> <p>Mazda 626 [1997-2001]</p> <p>Rear Complete Suspension Arm [RE, LH] [Arm#, 3] [With 2 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



Revision : 2014-November-01

MAZDA | FORD

AD24-66P GJ6A-34-200  Mazda 6 [2002-2006] Front Upper Arm Bush [FR, Big]	PFT-2012-June-26 Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-66PBJ GJ6A-34-2BJ ARP Product Mazda 6 [2002-2008] = GG Mazda 6 [2008-2013] = GH Mazda 6 MPS [2005-2007] = GG Mazda 6 Wagon [2002-2006] Front Upper Arm Ball Joint [FR, LH, RH]	www.rbi.ae
AD24-66WB GJ6A-34-460  Mazda 6 [2002-2006] Front Lower Arm Bush [FR, Big]	TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD24-66WS GJ6A-34-470  Mazda 6 [2002-2006] Front Lower Arm Bush [FR, Small, 1]	PFT-2012-June-26 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD24-66W0 GJ6A-34-710  Mazda 6 [2002-2006] Front Lower Arm Bush [FR, Center]	PFT-2012-June-26 Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD24-66UCRZZ GJ6A-34-200  Mazda 6 [2002-2006] Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD24-66UCLZZ GJ6A-34-250  Mazda 6 [2002-2006] Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD24-66LCUZZ GJ6A-34-300  Mazda 6 [2002-2006] Front Complete Lower Arm [FR, LH, RH] [With Ball Joint & 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
AD24-66LCRZ GJ6A-34-J00  Mazda 6 [2002-2006] Front Complete Lower Arm [FR, RH] [With Ball Joint & 1 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD24-66LCLZ GJ6A-34-J50  Mazda 6 [2002-2006] Front Complete Lower Arm [FR, LH] [With Ball Joint & 1 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com

MAZDA | FORD

Revision : 2014-November-01

<div>AD25-66011</div> <div>GJ6A-28-450</div> <div>Mazda 6 [2002-2006]</div> <div>Rear Suspension Bush [RE] [4 Pcs/Car]</div>	<div>PFT-2012-June-26 Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>		
<div>AD25-6602B</div> <div>GJ6A-28-500</div> <div>Mazda 6 [2002-2006]</div> <div>Rear Suspension Bush [RE] [4 Pcs/Car]</div>	<div>PFT-2012-August-30 Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>	<div>AD25-6602BZ</div> <div>GJ6A-28-500</div> <div>Mazda 6 [2002-2006]</div> <div>Rear Complete Suspension Link [RE]</div>	<div>Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>
<div>AD25-6603B</div> <div>G21D-28-500</div> <div>Mazda 6 MPS [2005] = GG Mazda 6 Wagon [2002-2007] = GY Atenza [2002-2007] = GG</div> <div>Rear Suspension Bush [RE] [4 Pcs/Car]</div>	<div>PFT-2012-August-30 Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>	<div>AD25-6603BZ</div> <div>G21D-28-500</div> <div>Mazda 6 MPS [2005] = GG Mazda 6 Wagon [2002-2007] = GY Atenza [2002-2007] = GG</div> <div>Rear Complete Suspension Link [RE]</div>	<div>Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>
<div>AD25-6603</div> <div>GJ6A-28-200</div> <div>Mazda 6 [2002-2006]</div> <div>Rear Suspension Bush [RE] [2 Pcs/Car]</div>	<div>Perfect Product, HFC Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>	<div>AD25-66032</div> <div>G26A-28-200</div> <div>Mazda 6 [2002-2006]</div> <div>Rear Suspension Bush [RE] [2 Pcs/Car]</div>	<div>Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>
<div>AD25-6604</div> <div>G26A-28-300</div> <div>Mazda 6 [2002-2006]</div> <div>Rear Suspension Bush [RE] [4 Pcs/Car]</div>	<div>PFT-2012-December-31 Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>	<div>AD25-6605</div> <div>GJ6A-28-890</div> <div>Mazda 6 [2002-2007] = GG Mazda 6 Wagon GY [2002-2007] Mazda Atenza [2002-2007] = GG</div> <div>Rear Suspension Bush [RE]</div>	<div>ARP Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>
<div>AD25-66061</div> <div>GJ6A-28-89X</div> <div>Mazda 6 [2002-2007] = GG Mazda 6 MPS [2005] = GG Mazda 6 Wagon GY [2002-2007] Mazda Atenza [20</div> <div>Rear Suspension Bush [RE]</div>	<div>ARP Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>	<div>AD25-66062</div> <div>GJ6A-28-89Y</div> <div>Mazda 6 [2002-2007] = GG Mazda 6 MPS [2005] = GG Mazda 6 Wagon GY [2002-2007] Mazda Atenza [20</div> <div>Rear Suspension Bush [RE]</div>	<div>ARP Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>
<div>AD25-6606R</div> <div>GJ6A-28-860</div> <div>Mazda 6 [2002-2007] = GG Mazda 6 Wagon GY [2002-2007] Mazda Atenza [2002-2007] = GG</div> <div>Rear Suspension Bush [RE]</div>	<div>ARP Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>	<div>AD25-6606L</div> <div>GJ6A-28-86X</div> <div>Mazda 6 [2002-2007] = GG Mazda 6 Wagon GY [2002-2007] Mazda Atenza [2002-2007] = GG</div> <div>Rear Suspension Bush [RE]</div>	<div>ARP Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>







Revision : 2014-November-01

MAZDA | FORD

AD24-67PB GS1D-34-200  Mazda 6 [2007-2011] Front Upper Arm Bush [FR, Big]	PFT-2012-June-26 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD24-67PS GS1D-34-200  Mazda 6 [2002-2008] = GG Front Upper Arm Bush [FR]	TN-2014-May-05 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD24-67PLZ GS1D-34-200 Mazda 6 [2007-2011] Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD24-67PRZ GS1D-34-250 Mazda 6 [2007-2011] Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]	ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD24-67WC GS1D-34-710  Mazda 6 [2007-2011] Front Lower Arm Bush [FR, Center]	PFT-2012-June-26 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AD24-67WS GS1D-34-300  Mazda 6 [2007-2011] Front Lower Arm Bush [FR, Small]	TN-2014-June-15 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD24-67WB GS1D-34-300  Mazda 6 [2007-2011] Front Lower Arm Bush [FR, Big]	RBI-2014-February-04 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD24-67WBLZ GS1D-34-350  Mazda 6 [2007-2011] Front Lower Arm Bush [Bracket] [Bracket] [FR, Big, LH]	RBI-2014-July-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD24-67WBRZ GS1D-34-300  Mazda 6 [2007-2011] Front Lower Arm Bush [Bracket] [Bracket] [FR, Big, RH]	RBI-2014-July-14 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 

Revision : 2014-November-01

MAZDA | FORD

<div>AD25-67011</div> <div>GS1D-28-450</div> <div>Mazda 6 [2007-2011] = GH</div> <div>Rear Suspension Bush [RE] [4 Pcs/Car]</div>	<div><div>PFT-2014-March-25 Perfect Product, Tenacity Product</div><div><div>shabbirh@eim.ae</div><div>40.00</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>	
<div>AD25-6702B</div> <div>GS1D-28-501</div> <div>Mazda 6 [2007-2011] = GH</div> <div>Rear Suspension Bush [RE, Big Hole, 2 Pcs/Car]</div>	<div><div>PFT-2013-August-20 Perfect Product, Tenacity Product</div><div><div>shabbirh@eim.ae</div><div>40.00</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>	<div><div>AD25-6702S</div><div>GS1D-28-500</div><div>Mazda 6 [2007-2011] = GH</div><div>Rear Suspension Bush [RE, Small Hole, 2 Pcs/Car]</div></div> <div><div>PFT-2012-August-3 Perfect Product, Tenacity Product</div><div><div>shabbirh@eim.ae</div><div>40.00</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>
<div>AD25-6702BZZ</div> <div>GS1D-28-500</div> <div>Mazda 6 [2007] = GH Mazda 6 Wagon [2007] = GH</div> <div>Rear Complete Arm [RE]</div>	<div><div>ARP Product</div><div><div>www.rbi.ae</div></div></div>	
<div>AD25-6703</div> <div>GS1D-28-200</div> <div>Mazda 6 [2007-2011] = GH</div> <div>Rear Suspension Bush [RE] [2 Pcs/Car]</div>	<div><div>PFT-2014-March-25 Perfect Product, Tenacity Product</div><div><div>shabbirh@eim.ae</div><div>70.00</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>	
<div>AD25-6704</div> <div>GS1D-28-301</div> <div>Mazda 6 [2007-2011] = GH</div> <div>Rear Suspension Bush [RE, Big]</div>	<div><div>PFT-2013-October-10 Perfect Product, Tenacity Product</div><div><div>shabbirh@eim.ae</div><div>44.10</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>	
<div>AD25-6705</div> <div>GS1D-26-11X</div> <div>Mazda 6 [2007] = GH Mazda 6 Wagon [2007] = GH</div> <div>Rear Suspension Bush [RE]</div>	<div><div>PFT-2014-August-31 Perfect Product</div><div><div>shabbirh@eim.ae</div><div>www.rbi.ae</div><div>www.alafuae.com</div></div><div></div></div>	



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD24-CX91WS TD11-34-350</p> <p>PERFECT RUBBER PARTS</p> <p>Mazda CX-9 TB [2007]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD24-CX71WS EG21-34-350</p> <p>PERFECT RUBBER PARTS</p> <p>Mazda CX-7 [2006] = ER</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AD24-CX71WB EG21-34-300</p> <p>PERFECT RUBBER PARTS</p> <p>Mazda CX-7 [2006] = ER Mazda CX-9 TB [2007]</p> <p>Front Lower Arm Bush [FR, Big]</p>
<p>AD24-CX707WBJ EG21-34-300</p> <p>PERFECT RUBBER PARTS</p> <p>Mazda CX-7 [2006] = ER Mazda CX-9 [2007] = TB</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	<p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AD24-CX71WBZ EG21-34-300</p> <p>PERFECT RUBBER PARTS</p> <p>Mazda CX-7 [2006] = ER Mazda CX-9 TB [2007]</p> <p>Front Lower Arm Bush [FR, Big, Bracket]</p>






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD25-CX707E01S EG21-28-302 Mazda CX-7 [2006] = ER Rear Suspension Bush [RE, Small]	 AD25-CX707E01B EG21-28-301 Mazda CX-7 [2006] = ER Rear Suspension Bush [RE, Big]
AD25-CX707E02 EG25-28-69X Mazda CX-7 [2006] = ER Mazda 6 MPS [2005] = GG Mazda Atenza [2002-2007] = GG Rear Suspension Bush [RE]	 AD25-CX71E03 EG21-28-200 CX-7 [2006] = ER Rear Suspension Bush [RE]
AD25-CX71E04 EG25-28-68X CX-7 [2006] = ER Rear Suspension Bush [RE, Differential]	
AD25-CX707E05 #EG21-28-910E Mazda CX-7 [2006-2012] = ER Rear Shock Absorber Bush	
	AD25-CX907E01Z TD11-28-500 CX-9 [2007] = TB Rear Complete Suspension Arm [RE]
AD25-CX91E02 TD11-28-200 CX-9 [2007] = TB Rear Suspension Bush [RE]	 AD25-CX91E03 TD11-28-C10 CX-9 [2007] = TB Rear Suspension Bush [RE]
AD25-CX91E04 TD11-28-300 CX-9 [2007] = TB Rear Suspension Bush [RE]	 AD25-CX91E05 L214-28-68X CX-9 [2007] = TB Rear Suspension Bush [RE, Differential]











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD24-MPV1PBZ LA01-34-230</p> <p>Mazda MPV LV [1990-1999]</p> <p>Front Upper Arm Bush [Bracket] [FR, Big, Bracket]</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD24-MPV1PS LA01-34-300</p> <p>Mazda MPV LV [1990-1999]</p> <p>Front Upper Arm Bush [FR, Small]</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD24-MPV1WB LA12-34-300</p> <p>Mazda MPV [1990-1999] = LV</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AD24-MPV1WS LA12-34-460</p> <p>Mazda MPV [1990-1999] = LV</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>ASH-2013-July-10 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD25-MPV1E1Z LC03-28-320</p> <p>MPV [1990-1999] = LV</p> <p>Rear Complete Suspension Arm</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AD25-MPV1E2Z L022-28-210</p> <p>MPV [1990-1999] = LV</p> <p>Rear Complete Suspension Arm</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD24-MPVWB LC62-34-460</p> <p>Mazda MPV [1999-2003]</p> <p>Front Lower Arm Bush [FR, Big]</p> <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	<p>AD24-MPVWS LC62-34-470</p> <p>Mazda MPV [1999-2003]</p> <p>Front Lower Arm Bush [FR, Small, 2.5]</p> <p>PFT-2012-November-07 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  
<p>AD24-MPV2LCRZZ LC62-34-300</p> <p>Mazda MPV [1999-2003]</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AD24-MPV2LCLZZ LC62-34-350</p> <p>Mazda MPV [1999-2003]</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AD25-MPV2E01 LC62-28-460</p> <p>Mazda MPV LW [1999-2006] Mazda MPV [2003-2006] = LW3W</p> <p>Rear Suspension Bush [RE]</p> <p>RBI-2013-November-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD24-DEM1WB D201-34-460</p> <p>Demio [1998-2002]</p> <p>Front Lower Arm Bush [FR, Big]</p> <p><small>PFT-2012-August-30 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>PERFECT RUBBER PARTS</p>	<p>AD24-DEM1RU D001-34-153</p> <p>Demio [1998-2002]</p> <p>Front Lower Arm Rubber [FR]</p> <p><small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>TENACITY</p>
<p>AD24-DEM1WBZ D201-34-300</p> <p>Demio [1998-2002]</p> <p>Front Complete Lower Arm [FR, LH, RH] [With Ball Joint & 2 Bush]</p> <p><small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	
<p>AD25-DEM1WB DC20-28-460</p> <p>Demio [1998-2002]</p> <p>Rear Suspension Bush [RE, Big, Lower]</p> <p><small>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> <p>PERFECT RUBBER PARTS</p>	
<p>AD25-DEM2WB D350-28-460</p> <p>Demio [2002-2007] = DY3, DY5</p> <p>Rear Suspension Bush [RE, Big, Lower]</p> <p><small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD24-XDS1PB T001-34-D00   Mazda Xedos-9 / Milenia TA [1993-2000] Front Upper Arm Bush [FR, Upper]	AD24-XDS1PS T001-34-42Y  Mazda Xedos-9 / Milenia TA [1993-2000] Front Lower Center Arm Bush [FR, Center]
AD24-XDS1PS2 T001-34-42Y  Mazda Xedos-9 / Milenia TA [1993-2000] Front Lower Center Arm Bush [FR, Center]	AD24-XDS1PS3 T001-34-42Y  Mazda Xedos-9 / Milenia TA [1993-2000] Front Lower Center Arm Bush [FR, Center]
AD24-XDS1WB T001-34-460   Mazda Xedos-9 / Milenia TA [1993-2000] Front Lower Arm Bush [FR, Big, Lower]	AD24-XDS1WS T001-34-710   Mazda Xedos-9 / Milenia TA [1993-2000] Front Lower Arm Bush [FR, Small, Lower]
AD25-XDS1WB T001-28-460  Mazda Xedos-9 / Milenia TA [1993-2000] Rear Lower Arm Bush [RE, Big, Lower]	AD25-XDS1WS T001-28-710  Mazda Xedos-9 / Milenia TA [1993-2000] Rear Lower Arm Bush [RE, Small, Lower]

Revision : 2014-November-01

MAZDA | FORD

AD24-T20WS2 EC01-34-470  Mazda Tribute [2001-2004] Ford Escape  Front Lower Arm Bush [FR, Small] [2,3]	AD24-T20WS E112-34-350  Mazda Tribute [2001-2004] Ford Escape  Front Lower Arm Bush [FR, Small, 2,3]
AD24-T20WB E112-34-350  Mazda Tribute [2001-2004] Ford Escape  Front Lower Arm Bush [FR, Big] [2,3]	AD24-T20WBJ E112-34-3BJ  Ford Escape [2000-2007] Ford Maverick [2000-2006] = TM1 Ford Maverick [2006-2009] = TM7 Ford E Front Lower Arm Ball Joint [FR, LH, RH]
AD24-T22WB EF91-34-460  Mazda Tribute [2000-2007] = EP  Front Lower Arm Bush [FR, Big]	AD24-T22WS EF91-34-470  Mazda Tribute [2000-2007] = EP  Front Upper Arm Bush [FR, Small]
AD24-T20LCRZZ EC01-34-300  Mazda Tribute [2001-2004] Ford Escape Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]	AD24-T20LCLZZ EC01-34-350  Mazda Tribute [2001-2004] Ford Escape Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]
AD25-T20E E112-28-460  Mazda Tribute [2000-2007] = EP Ford Escape [2000-2007] Ford Maverick [2000-2006] = TM1 Ford Ma  Rear Suspension Bush [RE] [2,3]	AD25-T200E EC01-28-690  Mazda Tribute [2000-2007] = EP Ford Escape [2000-2007] Ford Maverick [2000-2006] = TM1 Ford Ma  Rear Suspension Bush [RE]
AD25-T20E1CLZ EC01-28-650  Mazda Tribute [2000-2007] = EP Ford Escape [2000-2007] Ford Maverick [2000-2006] = TM1 Ford Ma Rear Complete Suspension Arm [RE, LH] [With Ball Joint & 1 Bush]	AD25-T20E1CRZ EC01-28-600  Mazda Tribute [2000-2007] = EP Ford Escape [2000-2007] Ford Maverick [2000-2006] = TM1 Ford Ma Rear Complete Suspension Arm [RE, RH] [With Ball Joint & 1 Bush]
AD25-T20E2CLZ EF91-28-550  Mazda Tribute [2000-2007] = EP Ford Escape [2000-2007] Ford Maverick [2000-2006] = TM1 Ford Ma Rear Complete Suspension Arm [RE, LH] [With Ball Joint & 1 Bush]	AD25-T20E2CRZ EF91-28-500  Mazda Tribute [2000-2007] = EP Ford Escape [2000-2007] Ford Maverick [2000-2006] = TM1 Ford Ma Rear Complete Suspension Arm [RE, RH] [With Ball Joint & 1 Bush]



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD24-E200W S24A-34-470</p> <p>Mazda = E2000, E2200 [1987-1998] KIA = K2700, HI2406</p> <p>Front Lower Arm Bush [FR, Big]</p>  <p>RBI-2009-December-12 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AD24-E201W S083-34-820</p> <p>Mazda = E2000, E2200 [1987-1998]</p> <p>Front Lower Arm Bush [FR, Big]</p>  <p>PFT-2012-June-26 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AKA24-K27PB S083-34-830</p> <p>Mazda = E2000, E2200 [1987-1998] KIA = K2700 / HI2403</p> <p>Front Upper Arm Bush [FR, Big]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>AKA24-K27PS S083-34-840</p> <p>Mazda = E2000, E2200 [1987-1998] KIA = K2700 / HI2403</p> <p>Front Upper Arm Bush [FR, Small]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>AKA24-K27W 0K63B-34-820</p> <p>K2700</p> <p>Front Lower Arm Bush [FR, Big]</p>  <p>RBI-2006-October-07 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD24-S10HWS S10H-34-470  Mazda Bongo Friendee [1995-2005] = SG# Mazda Friendee / Freda [1995] = SGL, SGR Front Lower Arm Bush [FR, Small]	AD24-S10HWP S10H-34-460  Mazda Bongo Friendee [1995-2005] = SG# Mazda Friendee / Freda [1995] = SGL, SGR Front Lower Arm Bush [FR, Big]
AD24-S10HWPJ #S10H-34-300A  Mazda Bongo Friendee [1995-2005] = SG# Front Lower Arm Ball Joint [FR, LH, RH]	
AD25-S10HE01 S10H-28-660  Mazda Bongo Friendee [1995-2005] = SG# Mazda Friendee / Freda [1995] = SGL, SGR Rear Suspension Bush [RE]	
AD25-S10HE02B S10H-28-652  Bongo Friendee [1995-2005] = SG# Rear Suspension Bush [RE, Big]	AD25-S10HE02S S10H-28-651  Bongo Friendee [1995-2005] = SG# Rear Suspension Bush [RE, Small]
AD25-S10HE03Z S10H-28-210  Bongo Friendee [1995-2005] = SG# Rear Complete Suspension Arm	









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD24-01W 0866-34-460 Mazda 808 Mazda 929 Front Lower Arm Bush [FR]	  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD24-02W H001-34-460 Mazda 929 [1982-1987] Mazda 929 [1986-1991] = HC Mazda 808 Front Lower Arm Bush [FR]	  RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD24-13W 0317-34-460  M1300  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Lower Arm Bush [FR]	AD24-41W 0662-34-460  M1200, M1300  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Lower Arm Bush [FR]
AD24-12W 0259-34-460  M1200  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Lower Arm Bush [FR]	
AD24-43W 1243-34-460  M1600, B1600  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Lower Arm Bush [FR]	AD24-44W UA01-34-820  B2200  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Lower Arm Bush [FR]
AD24-41XP UH71-34-470  Fighter, Ford Ranger [4WD]  <small>RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Upper Arm Bush [FR]	AD24-41XW UH74-34-450  Fighter, Ford Ranger [4WD]  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Lower Arm Bush [FR]
AD24-45W UB39-34-460  Mazda = B1600, B2000, B2200, B2600 [1985-1991]  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Front Lower Arm Bush [FR]	








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AD24-BT50W UR56-34-470</p> <p> PERFECT RUBBER PARTS</p> <p>Mazda BT50</p> <p>Front Upper Arm Bush [FR]</p>	<p>AD24-BT50PBJ UH71-34-540</p> <p></p> <p>Mazda BT-50 [2006] Ford Ranger [2002-2007] = EQ Ford Ranger [2006-2009] = ET Ford Ranger [2009]</p> <p>Front Upper Arm Ball Joint [FR, LH, RH]</p>
<p>AD24-BT50WBJ UR61-34-550</p> <p></p> <p>Mazda BT-50 [2006] Ford Everest [2006] = EU Ford Everest [2009] = EP Ford Ranger [2006-2009] =</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD24-T35WS 0559-34-330</p> <p>Mazda Titan Truck = T3000, T3500</p> <p>Spring Shackle Bush [FR, Small]</p>	<p>AD24-T35WD 0680-34-330</p> <p>Mazda Titan Truck = T3000, T3500</p> <p>Spring Shackle Bush [FR, Big]</p>
<p>AD24-T35WB 0680-28-330</p> <p>Mazda Titan Truck = T3000, T3500</p> <p>Spring Shackle Bush [RE, Big]</p>	
<p>AD24-T35PBJ W628-34-540</p> <p>Mazda Titan Truck T3000, T3500</p> <p>Front Upper Arm Ball Joint [FR, LH, RH]</p>	<p>AD24-T35WBJ W628-34-550</p> <p>Mazda Titan Truck T3000, T3500</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

	<p>AD24-FES93WS</p> <p>KY01-34-460</p> <p>Mazda FESTIVA [1993]</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>Tenacity Product</p> <p>shabbirh@eim.ae</p> <p>29.00</p> <p>www.alafuae.com</p> <p>10.20</p> <p>www.4989fuae.com</p>







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO24-FOC98WBJ #1073214 <div>ARP Product</div> www.rbi.ae Ford Focus I [1998-2005] = CAK Front Lower Arm Ball Joint [FR, LH, RH]	
AFO24-FOC98WBZ #1073214 <div>ARP Product</div> shabbirh@eim.ae  www.rbi.ae www.alafuae.com Ford Focus I [1998-2005] = CAK Front Lower Arm Bush [FR, Big]	AFO24-FOC98WS 1060000 <div>ARP Product</div> shabbirh@eim.ae  www.rbi.ae www.alafuae.com Ford Focus I [1998-2005] = CAK Front Lower Arm Bush [FR, Small]
AFO24-FOC04WBJ 1470000 <div>ARP Product</div> www.rbi.ae Ford C-max [2006-2010] = CB3 Ford Focus II [2004-2008] Volvo C30 [2007] Volvo C70 [2006] Vol Front Lower Arm Ball Joint [FR, LH, RH]	AFO24-FOC04WBJ2 1234382 <div>ARP Product</div> www.rbi.ae Ford C-max [2003-2007] = CAP Ford Focus II [2004-2008] Volvo S40 II [2004] Volvo V50 [2004] Front Lower Arm Ball Joint [FR, LH, RH]
AFO24-FOC04LCLZZ 1234375 <div>ARP Product</div> www.rbi.ae Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo Front Complete Lower Arm [FR, LH]	AFO24-FOC04LCRZZ 1230000 <div>ARP Product</div> www.rbi.ae Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo Front Complete Lower Arm [FR, RH]
AFO25-FOC98E01 1061666 <div>ARP Product</div> www.rbi.ae Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus II [2008-2011] = CB4 Ford Rear Suspension Bush	
AFO25-FOC04E01 #1306901 <div>ARP Product</div> www.rbi.ae Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo Rear Suspension Bush	AFO25-FOC04E02 1448127 <div>ARP Product</div> www.rbi.ae Ford C-max [2003-2007] = CAP Ford Focus II [2004-2008] Ford Kuga [2008] = CBV Rear Complete Suspension Arm [RE]





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO24-MON92WB

93BB-3063AA

Ford MONDEO 2.0 [1993]

Front Lower Arm Bush [FR, Big]



AFO24-MON92WB2

1023058

Mazda MONDEO [1993-1999]

Front Lower Arm Rubber



AFO24-MON92WS

Ford MONDEO 2.0 [1993]

Front Lower Arm Bush [FR, Small]



AFO24-MON92WS2

93BB-5K-566AC

Ford MONDEO [1993-1995]

Front Lower Arm Bush















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO24-MON00WB 1311417BA  Ford Mondeo [2000-2007] = GE Front Lower Arm Bush [FR, Big]	AFO24-MON00WS 1311417BB  Ford Mondeo [2000-2007] = GE Front Lower Arm Bush [FR, Small]
AFO24-MON00WBJ #1149802  Ford Mondeo [2000-2007] = GE Front Lower Arm Ball Joint [FR, LH, RH]	
AFO25-MON00E01 1400000  Ford Mondeo [2000-2007] = GE Rear Suspension Bush	AFO25-MON00E02 #1202267  Ford Mondeo [2000-2007] = GE Rear Suspension Bush
AFO25-MON00E03 #1117857  Ford Kuga [2008] = CBV Ford Mondeo [2000-2007] = GE Rear Suspension Bush	AFO25-MON00E04 1404976  Ford Mondeo [2000-2007] = GE Rear Suspension Bush
AFO25-MON00E05 #1214290  Ford Mondeo [2000-2007] = GE Rear Suspension Bush	AFO25-MON00E06 #1206474  Ford Mondeo [2000-2007] = GE Rear Suspension Bush
AFO25-MON00E07 #1202267  Ford Mondeo [2000-2007] = GE Rear Suspension Bush	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO24-MON07WB 1405584 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200] Front Lower Arm Bush [FR, Big]	AFO24-MON07WBJ #1435745 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S80 II [2007] Volvo V70 III [20] Front Lower Arm Ball Joint [FR, LH, RH]
AFO24-MON07WL #1435745 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S80 II [2007] Volvo V70 III [20] Front Lower Arm Bush	AFO24-MON07WS #1435745 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S80 II [2007] Volvo V70 III [20] Front Lower Arm Bush [FR, Small]
AFO25-MON07E01 #1469125 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200] Rear Suspension Bush	AFO25-MON07E03 1440000 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200] Rear Suspension Bush
AFO25-MON07E04 #1377449 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200] Rear Suspension Bush	AFO25-MON07E05 #1377406 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200] Rear Suspension Bush
AFO25-MON07E06 1437191 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Rear Suspension Bush	AFO25-MON07E07 #1457609 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Ford Galaxy [2006] Volvo S80 II [2007] Rear Suspension Bush
AFO25-MON07E08 #1469125 <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200] Rear Suspension Bush	
AFO25-MON07E2Z 6G915K743XAD <div>ARP Product</div> <div>www.rbi.ae</div> Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [2010] Volvo S80 II [200] Rear Complete Suspension Arm [RE]	





AL LAMSA AL FIDDIYA TRADING L.L.C.










ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AFO24-TAU96WB F8DZ-3079-AABA Ford Taurus III [1996-1999] Front Lower Arm Bush [FR, Big] [12mm]		AFO24-TAU96WB2 F8DZ-3078-AABA Ford Taurus III [1996-1999] Front Lower Arm Bush [Big] [14mm]	
AFO24-TAU96WS F8DZ-3078-AABB Ford Taurus III [1996-1999] Front Lower Arm Rubber [FR, Small]			
AFO24-TRA00WB 4540787 Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2000-2006] = FY Ford Transit [200]		AFO24-TRA00WBJ 1420000 Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2000-2006] = FY Ford Transit [200]	
AFO24-TRA00WS 4130000 Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2006] = TT9		AFO24-TRA02WS 4370000 Ford Transit Connect [2002] = TC7	
AFO26-TRA00E1 1517518 Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2006] = TT9		AFO26-TRA00E2 1520000 Ford Transit [2000] = FA, FB, FC, FD, FM, FN, FZ Ford Transit [2006] = TT9	












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD27-260 G030-34-157  Mazda 626  Stabilizer Link <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD27-320 B097-34-158  Mazda 323  Stabilizer Link <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
AD27-330 B029-34-159  Mazda 323  Stabilizer Link <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	AD27-350 B459-34-158  ASTINA  Stabilizer Link <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
AD27-430 UB39-34-154  B1600, B2200, Magnum, Fighter  Stabilizer Link <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	



Revision : 2014-November-01

MAZDA | FORD

AD27-MPVF00 LC70-34-170  Mazda MPV [1999-2006] Link Assy [FR, LH, RH] [2 Heads]	RBI-2013-June-19 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	
AD27-33FL GA2A-34-170  Mazda 323 [1994-1997] Mazda 626 [1991-2001] Link Assy [FR, LH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-33FR GA2A-34-150  Mazda 323 [1994-1997] Mazda 626 [1991-2001] Link Assy [FR, RH]
AD27-35E BC1D-28-170  Mazda 323 [1994-1997] ASTINA Link Assy [RE, LH, RH]	RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	
AD27-64E GA2C-28-170  Mazda 626 [1991-1996] Link Assy [RE, LH, RH]	RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-65E GE4T-28-170  Mazda 626 [1997-2001] Link Assy [RE, LH, RH]
AD27-A00F B26R-34-170  Mazda 323 [1998-2002] 4 Door Link Assy [FR, LH, RH] [2 Heads]	RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-A00E B26R-28-170  Mazda 323 [1998-2002] 4 Door Link Assy [RE, LH, RH] [2 Heads]
AD27-A01F LC62-34-170  Mazda 323 [1998-2002] 5 Door Link Assy [FR, LH, RH]	RBI-2007-May-04 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-A01E B30H-28-170  Mazda 323 [1998-2002] 5 Door Link Assy [RE, LH, RH]



AL LAMSA AL FIDDIYA TRADING L.L.C.













ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD27-66FL GJ6A-34-170  Mazda 6 [2002-2006] Link Assy [FR, LH]	RBI-2007-May-19 RBI Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-66FR GJ6A-34-150  Mazda 6 [2002-2006] Link Assy [FR, RH]	RBI-2007-May-16 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD27-66E0 GJ6A-28-170  Mazda 6 [2002-2006] Link Assy [RE, LH, RH]	RBI-2007-June-29 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		
AD27-MZ6FL GS1D-34-170  Mazda 6 [2007] Link Assy [FR, LH]	RBI-2012-August-25 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-MZ6FR GS1D-34-150  Mazda 6 [2007] Link Assy [FR, RH]	RBI-2012-August-25 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD27-MZ6E GS1D-28-170  Mazda 6 [2007] Link Assy [RE, LH, RH]	RBI-2012-August-25 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD27-MZ3F BP4K-34-170  Mazda 3 [2003] Link Assy [FR, LH, RH]	RBI-2007-May-19 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-MZ3E BP4K-28-170  Mazda 3 [2003] Link Assy [RE, LH, RH] [2 Heads]	RBI-2008-October-15 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD27-T1FL E181-34-170  Ford Escape Mazda Tribute Link Assy [FR, LH] [2.3]	RBI-2009-July-29 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-T1FR E181-34-150  Ford Escape Mazda Tribute Link Assy [FR, RH]	RBI-2009-April-07 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD27-T2FLR E112-34-150  Ford Escape Mazda Tribute Link Assy [FR, LH, RH]	RBI-2007-June-18 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-T0FLR EF91-34-150  Ford Escape Mazda Tribute [2001] Link Assy [FR, LH, RH]	PFT-2014-October-15 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD27-BT52E UR58-28-170  Mazda = BT50 [2006] [2WD] Link Assy [RE, LH, RH]	RBI-2009-July-31 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	AD27-BT54E UR61-28-170  Mazda = BT50 [2006] [4WD] Link Assy [RE, LH, RH]	RBI-2009-July-31 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com
AD27-BT5000 UR58-28-170  Mazda = BT50 [2006] [2WD, 4WD] Rear Suspension Bush [RE]	ARD-2014-January-01 Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com		







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD27-XDS1FL T001-34-17X  Mazda Xedos-9 / Milenia TA [1993-2000] Link Assy [FR, LH]	RBI-2013-November-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD27-XDS1FR T001-34-170  Mazda Xedos-9 / Milenia TA [1993-2000] Link Assy [FR, RH]	RBI-2013-December-16 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD27-XDS1E T001-28-170  Mazda Xedos-9 / Milenia TA [1993-2000] Link Assy [RE, LH, RH]	RBI-2013-July-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		
AD27-RDAF00 S10H-34-150  Mazda BONGO FRIENDEE [1995-2005] Mazda FRIENDEE / FREDA [1995] Link Assy [FR, LH, RH]	RBI-2013-June-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 	AD27-RDAE00 S10H-28-170  Mazda BONGO FRIENDEE [1995-2005] Mazda FRIENDEE / FREDA [1995] Link Assy [RE, LH, RH]	RBI-2013-July-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 
AD27-MZ21F00 D350-34-170  Mazda 2 [2003-2007] Mazda DEMIO [2002-2007] Mazda VERISA [2004] FORD FIESTA [2001-2008] FORD Link Assy [FR, LH, RH]	PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AD27-CX91FL TD11-34-170 CX-9 [2007] Link Assy [FR, LH]	  RBI-2014-July-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD27-CX91FR TD11-34-150 CX-9 [2007] Link Assy [FR, RH]	  RBI-2014-July-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD27-CX91E00 L206-28-170 CX-9 [2007] Link Assy [RE, LH, RH]	  RBI-2013-April-27 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
AD27-RX81FL F151-34-170 RX-8 [2003-2008] CX-7 [2007] [RE, LH] Link Assy [FR, LH]	  RBI-2013-July-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD27-RX81FR F151-34-150 RX-8 [2003-2008] CX-7 [2007] [RE, RH] Link Assy [FR, RH]	  RBI-2013-November-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD27-RX81E00 F151-28-170 RX-8 [2003-2008] Link Assy [RE, LH, RH]	  RBI-2013-September-02 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
AD27-RX81E01 F151-28-150 RX8 [2004-2006] Link Assy [RE]	  Ashimori Product www.rbi.ae		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

AFO27-FOC04E00 1500000 <small>ARP Product</small> www.rbi.ae Ford C-max [2003-2007] = CAP Ford C-max [2006-2010] = CB3 Ford Focus [2008-2011] = CB4 Ford Fo Link Assy [RE]	AFO27-FOC11E00 1714891 <small>ARP Product</small> www.rbi.ae Ford C-max Grand [2010] = CB9 Ford Focus III [2011] = CB8 Link Assy [RE]
AFO27-MON96F00 1004018 <small>ARP Product</small> www.rbi.ae Ford Cougar [1998-2000] = MC Ford Escort [1995-2001] = FA Ford Fiesta IV [1995-2002] = JA, JB Link Assy	
AFO27-MON00E00 1130000 <small>ARP Product</small> www.rbi.ae Ford Mondeo [2000-2007] = GE Link Assy [RE]	AFO27-MON07E00 1380000 <small>ARP Product</small> www.rbi.ae Ford Kuga [2008] = CBV Ford Mondeo [2007] = CA2 Ford S-max, Galaxy [2006] = CA1 Volvo S60 II [Link Assy [RE]
AFO27-TRA00F00 3736028 <small>ARP Product</small> www.rbi.ae Ford Transit [2000-2006] = FY Link Assy	AFO27-TRA02E00 1330000 <small>ARP Product</small> www.rbi.ae Ford Transit Connect [2002] = TC7 Link Assy [RE]
AFO27-TRA06E00 4709303 <small>ARP Product</small> www.rbi.ae Ford Transit [2006] = TT9 Link Assy [RE]	







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD28-45P UB40-34-121  Magnum, Fighter  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Bumper Bound [Upper]	AD28-45W UB39-34-110  Magnum, Fighter Ford Ranger [4WD], Fighter  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Bumper Bound [Lower]
AD28-45XE S083-34-110  Mazda = E2000, E2200 [1987-1998] Magnum Fighter  <small>ARD-2014-January-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Bumper Bound [FR]	
AD28-41XP UH74-34-120  Ford Ranger [4WD], Fighter  <small>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Bumper Bound [Upper]	
AD28-BT54E UH74-28-111  Mazda = BT50 [2006] [4WD]  <small>RBI-2009-June-09 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Bumper Bound [RE]	AD28-BT52E UR58-28-1A1  Mazda = BT50 [2006] [2WD]  <small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Bumper Bound [RE]





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD29-4X0 SA02-25-310 Fighter [2WD] Center Bearing	 RBI-OLD RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD29-410 0755-25-300 M1200, B2200 Center Bearing	 RBI-OLD RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae
AD29-450 P030-25-310 Magnum Center Bearing	 RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD29-460 P047-25-310 THUNDER Center Bearing	 RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD29-4X4 SA52-25-310 FIGTHER, Ranger [4WD] Center Bearing	 RBI-2007-April-03 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com		
AD29-BT540 SA68-25-300 Mazda = BT50 [2006] [4WD] Center Bearing	 RBI-2012-January-27 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com	AD29-BT520 SA12-25-300 Mazda = BT50 [2006] [2WD] Center Bearing	 RBI-2011-November-11 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com
AD29-4X300 SA04-25-310 Mazda FIGTHER, Ranger Center Bearing	 HFC Product www.rbi.ae		
AD29-CX706F00 #PH01-25-100 Mazda CX-7 [2006] = ER Center Bearing	 ARP Product www.rbi.ae	AD29-CX706F02 #PH01-25-100 Mazda CX-7 [2006] = ER Center Bearing	 ARP Product www.rbi.ae
AD29-CX907F00 #KG03-25-100C Mazda CX-9 [2007-2013] = TB Center Bearing	 ARP Product www.rbi.ae	AD29-CX907F02 #KG03-25-100C Mazda CX-9 [2007-2013] = TB Center Bearing	 ARP Product www.rbi.ae





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

MAZDA | FORD

Revision : 2014-November-01

<p>AFO29-FAL94B01</p>  <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford FALCON BA</p> <p>Rear Suspension Coupling Kit</p>	<p>AFO29-FAL94C01</p>  <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford FALCON BA, BF</p> <p>Center Bearing</p>
<p>AFO29-FAL04C01</p>  <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford FALCON BA, BF [2004]</p> <p>Center Bearing</p>	
<p>AFO29-FAL04C02 BAF4800A</p>  <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 30.00</p> <p>Falcon BA/BF 4.0L [6CYL, 30MM]</p> <p>Center Bearing</p>	<p>AFO29-FAL04C03</p>  <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com 35.00</p> <p>Falcon BF/FG [V8, 35MM]</p> <p>Center Bearing</p>
<p>AFO29-FAL02B01</p>  <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Falcon BF, Falcon Series II, Falcon FG [2002]</p> <p>Rear Suspension Coupling Kit</p>	
<p>AFO29-TRA94C01 99VB-4826AB</p>  <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Ford TRANSIT [1994-2000]</p> <p>Center Bearing</p>	<p>AFO29-TRA06C01 4104708</p>  <p>ARP Product www.rbi.ae</p> <p>Ford Transit [2000-2006] = FY Ford Transit [2006] = TT9</p> <p>Center Bearing</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD38-37L B456-32-124  Mazda 323 [1995] Grommet Steering Rack [LH]	RBI-OLD RBI Product, Ashimori Product  www.rbi.ae www.alafuae.com	AD38-38MR B455-32-123  Mazda 323 [1995] Grommet Steering Rack [RH, M/T]	RBI-OLD RBI Product, Ashimori Product  www.rbi.ae www.alafuae.com
AD38-38PR B595-32-123  Mazda 323 [1995] [Power] Grommet Steering Rack [RH]	RBI-OLD RBI Product, Ashimori Product  www.rbi.ae www.alafuae.com	AD38-38B B455-32-124  Mazda 323 [1995] Grommet Steering Rack	ASH-2013-November-15 Ashimori Product  www.rbi.ae www.alafuae.com
AD38-A00B B25D-32-123  Mazda 323 [1998-2002] = BJ Mazda 323 [1998-2004] = BJ Mazda Premacy [1999-2005] = CP Grommet Steering Rack Bush	ARP Product  www.rbi.ae www.alafuae.com	AD38-A00M B25D-32-124  Mazda 323 [1998-2002] Grommet Steering Rack	ARP Product  www.rbi.ae www.alafuae.com
AD38-MZ300B BP4L-32-123  Mazda 3 [2003] = BK Mazda 3 [2003-2008] = BK Mazda 5 [2005] = CR Mazda Axela [2003-2009] Maz Grommet Steering Rack Bush	PFT-2014-August-31 Perfect Product  www.rbi.ae www.alafuae.com		



MAZDA | FORD

Revision : 2014-November-01

AD38-64L GA2A-32-124  Mazda 626  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack [LH]	AD38-64R GA2A-32-123  Mazda 626  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack [RH]
AD38-66B01 GJ8A-32-123  Mazda 6 [2002-2007] = GG Mazda 6 Wagon [2002-2007] = GY  PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack Bush	AD38-66B02 G31A-32-123  Mazda 6 [2002-2007] = GG Mazda 6 Wagon [2002-2007] = GY CX-7 [2006] = ER  PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack Bush
AD38-66B03 GJ6A-32-123  Mazda 6 [2002-2007] = GG Mazda 6 Wagon [2002-2007] = GY  PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack Bush	
AD38-67B01 G33S-32-124  Mazda 6 [2007] = GH  PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack Bush	AD38-67B02 GDK6-32-123  Mazda 6 [2007] = GH Mazda 6 Wagon [2007] = GH  PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack Bush
AD38-67B03 G33S-32-123  Mazda 6 [2007] = GH Mazda 6 Wagon [2007] = GH  PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Grommet Steering Rack Bush	
AD38-T20S E112-32-123  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Ford Escape [2000-2007] Mazda Tribute [2001] = EP Grommet Steering Rack Bush	
AFO38-FOC04LR1 1251934  ARP Product www.rbi.ae Ford C-max [2006-2010] = CB3 Ford Focus II [2004-2008] Ford Kuga [2008] = CBV Grommet Steering Rack Bush	AFO38-TRA06G01 1370000  ARP Product www.rbi.ae Ford Transit [2006] = TT9 Grommet Steering Rack



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

AD41-T20DE00 EC01-28-690 ARP Product www.rbi.ae Tribute [2000-2007] = EP Front Differential Mounting	AD41-T20DE02 EC01-28-68X ARP Product www.rbi.ae Tribute [2000-2007] = EP Front Differential Mounting
AD41-66001 GP9A-28-68X PFT-2014-August-31 Perfect Product www.rbi.ae www.alafuae.com Mazda 6 MPS [2005] = GG Atenza [2002-2007] = GG Rear Differential Bushing [RE]	AD41-67RA001 B6DG-15-202 ARP Product www.rbi.ae Mazda 6 [2002-2008] = GG Mazda 6 [2008-2013] = GH Mazda 6 MPS [2005-2007] = GG Mazda 6 Wagon [
AD41-41X01 UH74-39-540 RBI-OLD RBI Product www.rbi.ae www.alafuae.com FIGTHER, Ranger [4WD] Rear Differential Mounting [With 1 edge]	AD41-41X02 UH74-39-550 RBI-OLD RBI Product www.rbi.ae www.alafuae.com FIGTHER, Ranger [4WD] Rear Differential Mounting
AD41-41X03 UH74-39-560 RBI-OLD RBI Product www.rbi.ae www.alafuae.com FIGTHER, Ranger [4WD] Rear Differential Mounting [With 2 edge]	
AD41-T3K1EZ1 W023-39-340-1 ARD-2014-January-01 ARD Product www.rbi.ae www.alafuae.com Mazda Titan Truck [1984-2005] = T2000, T2500, T2600, T3000, T3500, T4100 Radiator Mounting	AD41-T3K1EZ2 W023-39-340-2 ARD-2014-January-01 ARD Product www.rbi.ae www.alafuae.com Mazda Titan Truck [1984-2005] = T2000, T2500, T2600, T3000, T3500, T4100 Radiator Mounting
AD41-T3K1EZ3 W023-39-340-3 ARD-2014-January-01 ARD Product www.rbi.ae www.alafuae.com Mazda Titan Truck [1984-2005] = T2000, T2500, T2600, T3000, T3500, T4100 Radiator Mounting	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

MAZDA | FORD

<p>AD90-T35001 SEA2-13-247 Mazda T3000 Air Hose Pipe</p>	<p>Tenacity Product shabbirh@eim.ae  www.alafuae.com</p>	
<p>AD90-FES93AHP1 KB359-13-221 Ford FESTIVA 1.3, 1.5 [1993-1995] Air Hose Pipe</p>	<p>Tenacity Product shabbirh@eim.ae  www.alafuae.com</p>	
<p>AD90-T20AHP1 L336-13-221C Ford ESCAPE 2.3 [2001-2005] Air Hose Pipe</p>	<p>Tenacity Product shabbirh@eim.ae  www.alafuae.com</p>	

