






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<p>AC09-AV03E1Z</p> <p>96535402</p> <p>Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008]</p> <p>Insulator Engine</p>	<p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AC09-AV03L1Z</p> <p>96535505</p> <p>Chevrolet Aveo [2003-2008] = T200</p> <p>Insulator Engine [LH, 1.6]</p>	<p>TN-2014-May-05 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>AC09-AV03R1Z</p> <p>96535510</p> <p>Chevrolet Aveo [2003-2008] = T200</p> <p>Insulator Engine [RH, 1.6]</p>	<p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF


P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

AC09-CAV1R1Z



Chevrolet CAVALIER 2.2 [1985-1992]

Insulator Engine





# AL LAMSA AL FIDDIYA TRADING L.L.C.





ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<p>AC09-COR2R1H</p> <p></p> <p>Chevrolet CORSICA 2.2</p> <p>Insulator Engine</p> <p><small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> 	
<p>AC09-COR2R2H</p> <p></p> <p>Chevrolet CORSICA 2.2</p> <p>Insulator Engine</p> <p><small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> 	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC09-LA97E1Z</b> <b>682561</b> <small>ARP Product</small> Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF   Daewoo Nexia New [2009] Insulator Engine	<a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AC09-LA97L1Z</b> <b>90300000</b> <small>ARP Product</small> Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF   Daewoo Nexia New [2009] Insulator Engine	<a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AC09-LA97R1Z</b> <b>684195</b> <small>HFC Product</small> Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF   Daewoo Nexia New [2009] Insulator Engine [RH]	<a href="http://www.rbi.ae">www.rbi.ae</a>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<p>AC09-MA98F1Z 96300000</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chevrolet Matiz, Spark [1998-2005] = M100</p> <p>Insulator Engine</p>	
<p>AC09-OP03E1Z 96550261</p> <p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Insulator Engine [RE]</p>	<p>AC09-OP03F1Z 96436399</p> <p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Insulator Engine [FR]</p>
<p>AC09-OP03L1Z 96550234</p> <p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Insulator Engine [LH]</p>	<p>AC09-OP03R1Z 96550227</p> <p>TN-2014-May-05 Tenacity Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Insulator Engine [RH]</p>









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

Revision : 2014-November-01

## CHEVROLET

<p>AC09-S10E1Z</p> <p></p> <p>Chevrolet S10 PICKUP [1995-2003]</p> <p>Insulator Engine</p>	<p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p>AC09-S10F1Z</p> <p>15967994</p> <p></p> <p>Chevrolet S10 PICKUP [1995-2003]</p> <p>Insulator Engine</p>	<p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC13-AV03E00</b> <b>96456713</b> HFC Product Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] Shock Absorber Mounting  <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AC13-AV03F00</b> <b>96535011</b> Tenacity Product, HFC Product Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] Shock Absorber Mounting [FR, LH, RH]  <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AC13-AV03FB</b> <b>96535010</b> Tenacity Product Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] Shock Absorber Mounting Bearing Only [FR, LH, RH]  <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AC13-AV03FZ</b> <b>96653239K</b> Tenacity Product Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] Shock Absorber Mounting + Bearing [SET] [FR, LH, RH]  <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AC13-CA07FB</b> <b>4806308</b> ARP Product Chevrolet Captiva [2007] = C100   Opel Antara [2006] Shock Absorber Mounting Bearing Only  <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AC13-COR2FLR</b> <b>17981101</b> TN-2014-February-10 Tenacity Product Chevrolet CORSICA 2.0 Shock Absorber Mounting  <a href="http://www.alafuae.com">www.alafuae.com</a>	
<b>AC13-LA97F00</b> <b>96200000</b> ARP Product Chevrolet Lanos [1997-2002] = T100   Chevrolet Nubira [1997-1999] = J100 Shock Absorber Mounting  <a href="http://www.rbi.ae">www.rbi.ae</a>	
<b>AC13-LA97FL</b> <b>96444919</b> ARP Product Chevrolet Lanos [1997-2002] = T100 Shock Absorber Mounting [FR, LH]  <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AC13-LA97FR</b> <b>96400000</b> ARP Product Chevrolet Lanos [1997-2002] = T100 Shock Absorber Mounting [FR, RH]  <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AC13-LE98F00</b> <b>96200000</b> ARP Product Chevrolet Leganza [1998-2002] = V100 Shock Absorber Mounting  <a href="http://www.rbi.ae">www.rbi.ae</a>	<b>AC13-LE98FB</b> <b>94500000</b> ARP Product Chevrolet Leganza [1998-2002] = V100 Shock Absorber Mounting Bearing Only  <a href="http://www.rbi.ae">www.rbi.ae</a>









# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC13-MA98F00</b> <b>96568585</b> <div>ARP Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> Chevrolet Matiz, Spark [1998-2005] = M100 Shock Absorber Mounting	<b>AC13-MA98FB</b> <b>96528088</b> <div>ARP Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> Chevrolet Matiz, Spark [1998-2005] = M100 Shock Absorber Mounting Bearing Only
<b>AC13-MAL2E00</b> <div>TN-2014-February-10 Tenacity Product</div> <div>shabbirh@eim.ae</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <div><a href="http://www.alafuae.com">www.alafuae.com</a></div>  Chevrolet MALIBU [1997-2003] Shock Absorber Mounting	
<b>AC13-OP03E00</b> <b>96457360</b> <div>TN-2014-May-05 Tenacity Product, HFC Product</div> <div>shabbirh@eim.ae</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <div><a href="http://www.alafuae.com">www.alafuae.com</a></div>  Chevrolet Lacetti, Optra [2003-2008] = J200 Shock Absorber Mounting	<b>AC13-OP03F00</b> <b>93731583</b> <div>TN-2014-May-05 Tenacity Product, HFC Product</div> <div>shabbirh@eim.ae</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <div><a href="http://www.alafuae.com">www.alafuae.com</a></div>  Chevrolet Lacetti, Optra [2003-2008] = J200 Shock Absorber Mounting
<b>AC13-OP03FB</b> <b>94535236</b> <div>ARP Product</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> Chevrolet Lacetti, Optra [2003-2008] = J200 Shock Absorber Mounting Bearing Only	
<b>AC13-TRA2F00</b> <div>TN-2014-February-10 Tenacity Product</div> <div>shabbirh@eim.ae</div> <div><a href="http://www.rbi.ae">www.rbi.ae</a></div> <div><a href="http://www.alafuae.com">www.alafuae.com</a></div>  Chevrolet TRACKER [1999-2003] Shock Absorber Mounting	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC14-AV03F00U</b> <b>96535006</b> <small>ARP Product</small> Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] <a href="http://www.rbi.ae">www.rbi.ae</a> MEP-Shock Absorber Bumper [FR]	<b>AC14-AV03F01</b> <b>96535008</b> <small>ARP Product</small> Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] <a href="http://www.rbi.ae">www.rbi.ae</a> Shock Absorber Dust Cover
<b>AC14-CA07E00U</b> <b>#4804652</b> <small>ARP Product</small> Chevrolet Captiva [2007] = C100   Opel Antara [2006] <a href="http://www.rbi.ae">www.rbi.ae</a> MEP-Shock Absorber Bumper [RE]	<b>AC14-CA07F00U</b> <b>4810000</b> <small>ARP Product</small> Chevrolet Captiva [2007] = C100   Opel Antara [2006] <a href="http://www.rbi.ae">www.rbi.ae</a> MEP-Shock Absorber Bumper [FR]
<b>AC14-EP03E00U</b> <b>96400000</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> MEP-Shock Absorber Bumper [RE]	<b>AC14-EP03F00U</b> <b>96328543</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250 <a href="http://www.rbi.ae">www.rbi.ae</a> MEP-Shock Absorber Bumper [FR]
<b>AC14-EP03F01</b> <b>96328566</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Shock Absorber Dust Cover	
<b>AC14-LA97F00</b> <b>90142884</b> <small>ARP Product</small> Chevrolet Lanos [1997-2002] = T100   Chevrolet Nubira [1997-1999] = J100   Daewoo Nexia 1500I [1995- <a href="http://www.rbi.ae">www.rbi.ae</a> Shock Absorber Bumper Bound [FR]	<b>AC14-LA97F01</b> <b>96133096</b> <small>ARP Product</small> Chevrolet Lanos [1997-2002] = T100   Chevrolet Nubira [1997-1999] = J100   Daewoo Nexia 1500I [1995- <a href="http://www.rbi.ae">www.rbi.ae</a> Shock Absorber Dust Cover
<b>AC14-LE98F00U</b> <b>96225882</b> <small>ARP Product</small> Chevrolet Leganza [1998-2002] = V100 <a href="http://www.rbi.ae">www.rbi.ae</a> MEP-Shock Absorber Bumper [FR]	<b>AC14-LE98F01</b> <b>96200000</b> <small>ARP Product</small> Chevrolet Leganza [1998-2002] = V100 <a href="http://www.rbi.ae">www.rbi.ae</a> Shock Absorber Dust Cover [FR]
<b>AC14-LE98F02U</b> <b>344402</b> <small>ARP Product</small> Chevrolet Leganza [1998-2002] = V100   Opel Astra [1991-1998] = F <a href="http://www.rbi.ae">www.rbi.ae</a> MEP-Shock Absorber Bumper [FR]	







# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

AC14-MA98E01 96318363 ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Matiz, Spark [1998-2005] = M100 Shock Absorber Bumper Bound [RE]	
AC14-OP03E00U 96549918 ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 MEP-Shock Absorber Bumper [RE]	AC14-OP03E01 96600000 ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 Shock Absorber Dust Cover [RE]
AC14-OP03F00U 96400000  RBI-OLD RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 MEP-Shock Absorber Bumper [FR]	AC14-OP03F01 96498780 ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 Shock Absorber Dust Cover [FR]
AC14-OP03F02U 96549925  RBI-OLD RBI Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 MEP-Shock Absorber Bumper [FR]	






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC17-AV03I1Z</b> <b>96500000</b>  Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Epica [2003-2006] Drive Shaft Boot [Inner]	<b>AC17-AV03I2Z</b> <b>96500000</b> ARP Product Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Lacetti, Optra [20 Drive Shaft Boot [Inner]
<b>AC17-AV03O1Z</b> <b>96245309</b> ARP Product Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] Drive Shaft Boot [Outer]	
<b>AC17-CA07IZ</b> <b>#4804590</b> ARP Product Chevrolet Captiva [2007] = C100   Opel Antara [2006] Drive Shaft Boot [Inner]	
<b>AC17-LA97OZ</b> <b>510434</b> ARP Product Chevrolet Lanos [1997-2002] = T100   Chevrolet Leganza [1998-2002] = V100   Chevrolet Nubira [1997-1 Drive Shaft Boot [Outer]	
<b>AC18-CA07LR</b> <b>4800000</b> ARP Product Chevrolet Captiva [2007] = C100   Opel Antara [2006] Steering Gear Boot	
<b>AC20-AV03001</b> <b>96456715</b> ARP Product Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Kalos [2003-2008] Shock Absorber Grommet Rubber	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC21-AV03F00</b> <b>96653351</b> <small>ARP Product</small> <b>www.rbi.ae</b> Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Aveo [2009] = T250 Stabilizer Shaft Rubber [FR]	
<b>AC21-CA07E00</b> <b>4810000</b> <small>ARP Product</small> <b>www.rbi.ae</b> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Stabilizer Shaft Rubber [RE]	<b>AC21-CA07F00</b> <b>4810000</b> <small>RBI-OLD RBI Product</small> <b>www.rbi.ae</b> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Stabilizer Shaft Rubber [FR]
<b>AC21-EP03E00</b> <b>96500000</b> <small>ARP Product</small> <b>www.rbi.ae</b> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = Stabilizer Shaft Rubber [RE]	<b>AC21-EP03F00</b> <b>96859498</b> <small>ARP Product</small> <b>www.rbi.ae</b> Chevrolet Epica [2007] = V250 Stabilizer Shaft Rubber [FR]
<b>AC21-LA97F00</b> <b>96444469</b> <small>ARP Product</small> <b>www.rbi.ae</b> Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF Stabilizer Shaft Rubber [FR]	
<b>AC21-MA98F00</b> <b>96300000</b> <small>ARP Product</small> <b>www.rbi.ae</b> Chevrolet Matiz, Spark [1998-2005] = M100 Stabilizer Shaft Rubber [FR]	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC21-OP03E00</b> <b>96500000</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 Stabilizer Shaft Rubber [RE]	<b>AC21-OP03E01</b> <b>96500000</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 Stabilizer Shaft Rubber [RE]
<b>AC21-OP03F00</b> <b>96474040</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 Stabilizer Shaft Rubber [FR]	<b>AC21-OP03F01</b> <b>96839850</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200   Chevrolet Vivant [2000-2008] = U100 Stabilizer Shaft Rubber [FR]
<b>AC21-OP03F02</b> <b>96800000</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Lacetti, Optra [2003-2008] = J200 Stabilizer Shaft Rubber [FR]	
<b>AC21-TA00F00</b> <b>96500000</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Tacuma, Rezzo [2000-2008] = U100   Chevrolet Vivant [2000-2008] = U100 Stabilizer Shaft Rubber [FR]	






# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC24-AV03DEB</b> <b>96535069</b> <small>ARP Product</small> Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Aveo [2009] = T250 <a href="http://www.rbi.ae">www.rbi.ae</a> Front Lower Arm Bush	<b>AC24-AV03DES</b> <b>96535066</b> <small>ARP Product</small> Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Aveo [2009] = T250 <a href="http://www.rbi.ae">www.rbi.ae</a> Front Lower Arm Bush
<b>AC24-AV03WB</b> <b>96653381</b> <small>Perfect Product</small>  Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Aveo [2009] = T250 <a href="http://www.rbi.ae">www.rbi.ae</a> Front Lower Arm Bush [FR, Big]	<b>AC24-AV03WS</b> <b>96535087</b> <small>ARP Product</small> Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Aveo [2009] = T250 <a href="http://www.rbi.ae">www.rbi.ae</a> Front Lower Arm Bush [FR, Small]
<b>AC25-AV03E01</b> <b>96495468</b> <small>ARP Product</small> Chevrolet Aveo [2003-2008] = T200   Chevrolet Aveo [2006-2008] = T250   Chevrolet Aveo [2009] = T250 <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Suspension Bush	
<b>AC26-AV03E00</b> <b>96500000</b> <small>ARP Product</small> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Aveo [2003-2008] = T200 Rear Shock Absorber Bush	








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC24-CA07WS</b> <b>96626237</b>  Chevrolet Captiva [2007] = C100   Opel Antara [2006] Front Lower Arm Bush [FR, Small]	RBI-2013-October-14 RBI Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AC24-CA07W2S</b> <b>4806300</b>  Chevrolet Captiva [2007] = C100   Opel Antara [2006] Front Lower Arm Bush [FR, Small]	PFT-2014-January-01 Perfect Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>
<b>AC24-CA07WB</b> <b>96809676</b>  Chevrolet Captiva [2007] = C100   Opel Antara [2006] Front Lower Arm Bush [FR, Big]	RBI-2013-December-16 RBI Product  <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a>	<b>AC24-CA07WBZ</b> <b>96809676</b>  Chevrolet Captiva [2007] = C100   Opel Antara [2006] Front Lower Arm Bush [Bracket] [FR, Big, LH, RH]	Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AC24-CA07WBJ</b> <b>4813823</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Front Lower Arm Ball Joint [FR, LH, RH]			
<b>AC24-CA07LCLZZ</b> <b>4810831</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Front Complete Lower Arm [FR, LH]		<b>AC24-CA07LCRZZ</b> <b>4812870</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Front Complete Lower Arm [FR, RH]	
<b>AC25-CA07E1B</b> <b>96626481</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Suspension Bush		<b>AC25-CA07E2B</b> <b>96626425B</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Suspension Bush [RE, Big]	
<b>AC25-CA07E2S</b> <b>96626425S</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Suspension Bush [RE, Small]		<b>AC25-CA07E2Z</b> <b>4804807</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Complete Suspension Arm [RE]	
<b>AC25-CA07E3B</b> <b>96626433B</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Suspension Bush		<b>AC25-CA07E3S</b> <b>96626434S</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Suspension Bush	
<b>AC25-CA07E4</b> <b>96626409</b> ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Suspension Bush			





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

AC24-CR09WB 13334021  Chevrolet Cruze [2009] = J300   Opel Insignia [2009]   Opel Astra [2010] = J  Front Lower Arm Bush [FR, Big]	AC24-CR09WS 13334022  Chevrolet Cruze [2009] = J300   Opel Insignia [2009]   Opel Astra [2010] = J  Front Lower Arm Bush [FR, Small]








# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC24-EP03WB</b> <b>96388640</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Front Lower Arm Bush [FR, Big]	<b>AC24-EP03WS</b> <b>96328434</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Front Lower Arm Bush [FR, Small]
<b>AC25-EP03E1BJ</b> <b>96440010</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Lower Arm Ball Joint [RE, LH, RH]	
<b>AC25-EP03E1L</b> <b>96440010</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Upper Arm Bush	<b>AC25-EP03E1M</b> <b>96440010</b> <small>ARP Product</small>  Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a> Rear Upper Arm Bush
<b>AC25-EP03E2</b> <b>96450022</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Suspension Bush	<b>AC25-EP03E3</b> <b>96440032</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AC25-EP03E4</b> <b>96440041</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Suspension Bush	<b>AC25-EP03E5</b> <b>96440044</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AC25-EP03E6BL</b> <b>96440024</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Suspension Bush	<b>AC25-EP03E6BM</b> <b>96440024</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a>
<b>AC25-EP03E6S</b> <b>96440024</b> <small>ARP Product</small> Chevrolet Epica [2003-2006] = V200   Chevrolet Epica [2007] = V250   Chevrolet Evanda [2003-2006] = <a href="http://www.rbi.ae">www.rbi.ae</a> Rear Suspension Bush	













# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC24-LA97WB</b> <b>90235040</b>  <b>Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF   Daewoo Nexia New [2009]</b> <b>Front Lower Arm Bush [FR, Big]</b>	<b>AC24-LA97WS</b> <b>90335966</b>  <b>Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF   Daewoo Nexia New [2009]</b> <b>Front Lower Arm Bush [FR, Small]</b>
<b>AC25-LA97E1B</b> <b>90189050</b>  <b>Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF   Opel Kadett [1984-1991]</b> <b>Rear Suspension Bush</b>	<b>AC25-LA97E1S</b> <b>90189050</b>  <b>Chevrolet Lanos [1997-2002] = T100   Daewoo Nexia 1500I [1995-2009] = G15MF   Daewoo Nexia New [2009]</b> <b>Rear Suspension Bush</b>
<b>AC24-LE98WB</b> <b>96213131</b>  <b>Chevrolet Leganza [1998-2002] = V100</b> <b>Front Lower Arm Bush [FR, Big]</b>	<b>AC24-LE98WS</b> <b>96213130</b>  <b>Chevrolet Leganza [1998-2002] = V100</b> <b>Front Lower Arm Bush [FR, Small]</b>
<b>AC24-NU99WB</b> <b>96300622</b>  <b>Chevrolet Nubira [1999-2003] = J150</b> <b>Front Lower Arm Bush [FR, Big]</b>	
<b>AC26-NU97E00</b> <b>96308617</b>  <b>Chevrolet Nubira [1997-1999] = J100   Chevrolet Nubira [1999-2003] = J150</b> <b>Rear Shock Absorber Bush</b>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<p><b>AC24-OP03WB1</b> <b>96431044</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200   Chevrolet Tacuma, Rezzo [2000-2008] = U100   Chevrolet</p> <p>Front Lower Arm Bush</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	<p><b>AC24-OP03WB2</b> <b>96391856</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Front Lower Arm Bush</p> <p>TN-2014-May-05 RBI Product, Perfect Product, Tenacity Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AC24-OP03WS</b> <b>96378346</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200   Chevrolet Tacuma, Rezzo [2000-2008] = U100   Chevrolet</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>TN-2014-May-05 RBI Product, Tenacity Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AC24-OP03WBJ</b> <b>96490218</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>
<p><b>AC25-OP03E1B</b> <b>96497058</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Rear Suspension Bush [RE]</p> <p>RBI-2013-September-02 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AC25-OP03E1S</b> <b>96550055</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Rear Suspension Bush [RE]</p> <p>RBI-2013-September-02 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AC25-OP03E2B</b> <b>96550066</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Suspension Rubber Bush</p> <p>RBI-2013-October-14 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>	<p><b>AC25-OP03E2S</b> <b>96550064</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Suspension Rubber Bush</p> <p>RBI-2013-October-14 RBI Product <a href="http://shabbirh@eim.ae">shabbirh@eim.ae</a> <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p>
<p><b>AC25-OP03E2Z</b> <b>96550057</b></p> <p>Chevrolet Lacetti, Optra [2003-2008] = J200</p> <p>Rear Complete Suspension Arm</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	
<p><b>AC25-TA00E01</b> <b>96261123</b></p> <p>Chevrolet Tacuma, Rezzo [2000-2008] = U100   Chevrolet Vivant [2000-2008] = U100</p> <p>Rear Suspension Bush</p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<p><b>AC27-CA07E00</b> <b>4804642</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chevrolet Captiva [2007] = C100   Opel Antara [2006]</p> <p>Link Assy [RE]</p>	
<p><b>AC27-CA07FL</b> <b>95488870</b></p> <p>RBI-2014-February-04 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chevrolet Captiva [2007] = C100</p> <p>Link Assy [FR, LH]</p>	<p><b>AC27-CA07FR</b> <b>95488871</b></p> <p>RBI-2014-February-04 RBI Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chevrolet Captiva [2007] = C100</p> <p>Link Assy [FR, RH]</p>
<p><b>AC27-CA07FL2</b> <b>4810000</b></p> <p>PFT-2014-January-01 Perfect Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chevrolet Captiva [2007] = C100   Opel Antara [2006]</p> <p>Link Assy [FR, LH]</p>	<p><b>AC27-CA07FR2</b> <b>4806305</b></p> <p>PFT-2014-January-01 Perfect Product shabbirh@eim.ae <a href="http://www.rbi.ae">www.rbi.ae</a> <a href="http://www.alafuae.com">www.alafuae.com</a></p> <p>Chevrolet Captiva [2007] = C100   Opel Antara [2006]</p> <p>Link Assy [FR, RH]</p>
<p><b>AC27-CR09F00</b> <b>350614</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chevrolet Cruze [2009] = J300   Chevrolet Malibu [2012]   Chevrolet Orlando [2011]   Chevrolet Volt</p> <p>Link Assy</p>	
<p><b>AC27-EP03FL</b> <b>96600000</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chevrolet Epica [2007] = V250</p> <p>Link Assy [FR, LH]</p>	<p><b>AC27-EP03FR</b> <b>96639905</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chevrolet Epica [2007] = V250</p> <p>Link Assy [FR, RH]</p>
<p><b>AC27-LA97F00</b> <b>2875013</b></p> <p>ARP Product <a href="http://www.rbi.ae">www.rbi.ae</a></p> <p>Chevrolet Lanos [1997-2002] = T100   Daewoo Espero [1991-1999] = KLEJ   Daewoo Nexia 1500I [1995-200]</p> <p>Link Assy</p>	





# AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

## CHEVROLET

Revision : 2014-November-01

<b>AC29-CA07001</b> <b>#0446073</b> <div>ARP Product</div> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Center Bearing	
<b>AC30-CA07E00</b> <b>96626073</b> <div>ARP Product</div> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Cylinder Piston [RE]	<b>AC30-CA07F00</b> <b>96600000</b> <div>ARP Product</div> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Cylinder Piston [FR]
<b>AC38-CA0700B</b> <b>4800000</b> <div>ARP Product</div> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Grommet Steering Rack	<b>AC38-CA0700S</b> <b>4803242</b> <div>ARP Product</div> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Grommet Steering Rack
<b>AC41-CA07B01</b> <b>4810000</b> <div>ARP Product</div> <a href="http://www.rbi.ae">www.rbi.ae</a> Chevrolet Captiva [2007] = C100   Opel Antara [2006] Rear Differential Bushing	

