















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : http://www.rbi.ae http://www.alafuae.com

Revision : 2014-November-01

SUZUKI

ASU10-BA95E1Z 11720-60G50 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Insulator Engine  www.rbi.ae	ASU10-BA95E2Z 11710-62G10 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Insulator Engine [RE, A/T] [1.6, 1.8]  www.rbi.ae www.alafuae.com
ASU10-BA95F1Z 11720-62G10 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Cultus [1995-2001] = Insulator Engine [FR]  www.rbi.ae www.alafuae.com	
ASU10-BA95L1Z 11620-62G01 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Cultus [1995-2001] = Insulator Engine [LH]  www.rbi.ae	ASU10-BA95R1Z 11610-60G10 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Cultus [1995-2001] = Insulator Engine [RH]  www.rbi.ae
ASU10-CA01FLR 11610-60K00 Suzuki Carry, Every [1999-2005] = GA413 Insulator Engine  www.rbi.ae www.alafuae.com	ASU10-CA01RZ 11630-60H00 Suzuki Carry, Every [1999-2005] = GA413 Insulator Engine  www.rbi.ae www.alafuae.com
ASU10-LA01E1Z 11710-54G01 Suzuki Aerio, Liana [2006] = RH423 Suzuki Liana [2001-2008] = RH413, RH416, RH418 Insulator Engine  www.rbi.ae	ASU10-LA01F1Z 11720-54G10 Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Liana [2001-2008] = R Insulator Engine  www.rbi.ae www.alafuae.com
ASU10-LA01F2Z 11720-62G00 Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Baleno, Esteem [1995- Insulator Engine  www.rbi.ae	ASU10-LA01L1Z 11620-54G00 Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Liana [2001-2008] = R Insulator Engine  www.rbi.ae
	ASU10-SK41FLR 11610-60C01 Suzuki Carry / Super Carry [1988-] = SK410 Insulator Engine [FR]  www.rbi.ae www.alafuae.com



SUZUKI

Revision : 2014-November-01

<p>ASU10-SL02E1Z 11710-78F11 Suzuki SOLIO 1.3 [2002] Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>ASU10-SL02L1Z 11620-78F00 Suzuki SOLIO 1.3 [2002] Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU10-SL02R1Z 11610-79C00 Suzuki SOLIO 1.3 [2002] Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>ASU10-SW89E1Z 11710-60B20 Suzuki SWIFT 1.3 [1989-2001] Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU10-SW89F1Z 11910-60B20 Suzuki SWIFT 1.3 [1989-2001] Insulator Engine [FR]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>ASU10-SW89L1Z 11620-71C10 Suzuki SWIFT 1.3 [1989-2001] Insulator Engine [LH]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU10-SW89R1Z 11610-71C10 Suzuki SWIFT [1989-2001] Insulator Engine [RH]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>ASU10-SW05E1Z 11710-63J30 Suzuki SWIFT [2005] Insulator Engine [RE] [1.5 Petrol]</p> <p>TN-2013-September-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>ASU10-SW05L1Z 11620-63J00 Suzuki SWIFT 1.5 [2005] Insulator Engine</p> <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU10-SW05R1Z 11610-62J00 Insulator Engine [RH]</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>ASU10-SX406EZ 11710-79J10 Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 Insulator Engine</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU10-SX406FZ 11720-79J00 Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 Insulator Engine</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>ASU10-SX406LZ 11620-79J00 Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 Insulator Engine [LH]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU10-SX406RZ 11610-79J00 Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 Insulator Engine [RH]</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU10-VT1F0 11610-80010 Suzuki Sidekick [1996-1998] = SE416 Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [198  Insulator Engine [FR] [Without Bracket]	ASU10-VT1F2 17610-80000 Suzuki Sidekick [1996-1998] = SE416 Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [198  Insulator Engine [FR] [Without Bracket]
ASU10-VT1F2Z 17610-80000 Suzuki Sidekick [1996-1998] = SE416 Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [198  Insulator Engine [FR] [With Bracket]	ASU10-VT1F3Z 11610-56B00 Suzuki Jimny [1998] = SN413 Suzuki Samurai [1985-1995] = SJ413 Suzuki Sidekick [1996-1998] = SE4  Insulator Engine
ASU10-VT1F4Z 11610-58B00 Suzuki Sidekick [1996-1998] = SE416 Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [198  Insulator Engine	ASU10-VT1F5Z 11610-58B01 Suzuki SIDEKICK 1.6 [1991-1998]  Insulator Engine
ASU10-VT1F6 11610-80000 Suzuki SAMURAI  Insulator Engine [FR] [Without Bracket]	ASU10-VT1F6Z 11610-8A000 Suzuki SAMURAI  Insulator Engine [FR] [With Bracket]
ASU10-VT1FZ 11610-80020 Suzuki Sidekick [1996-1998] = SE416 Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [198  Insulator Engine [FR] [With Bracket]	










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU10-VT1E3 11710-80010  Suzuki Caribbean SJ413 Insulator Engine (RE)	RBI-2013-May-28 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com	ASU10-VT1E4 11710-81A00 HFC Product www.rbi.ae Suzuki Jimny [1998] = SN413 Insulator Engine	
ASU10-VT1E5 11710-76J00 ARP Product www.rbi.ae Suzuki Jimny [1998] = SN413 Insulator Engine		ASU10-VT1EZ 11710-60A00 TN-2014-February-10 Tenacity Product, ARD Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Insulator Engine (RE, A/T)	
ASU10-VT1R1Z 11910-57B01 TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com Suzuki SIDEKICK 1.6 [1989-1998] Insulator Engine		ASU10-VT1R2Z 11910-60A03 TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com Suzuki SAMURAI 1.6 [1989-1998] Insulator Engine	










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU10-VT2E1Z 11710-65D00 <small>ARP Product</small> Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Insulator Engine	ASU10-VT2E2Z 11710-77E11 <small>ARP Product</small> Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Suzuki X90 [1996-1998] = SZ416 Insulator Engine
ASU10-VT2F1Z 11610-67D00 <small>ARP Product</small>  Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Insulator Engine	ASU10-VT2F2Z 11610-65D00 <small>HFC-2014-November-20 HFC Product</small>  Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Insulator Engine
ASU10-VT2F3Z 11610-77AE0 <small>TN-2014-February-10 Tenacity Product</small>  Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Insulator Engine [FR, 1.8]	
ASU10-VT3E1Z 11710-65J00 <small>ARP Product</small>  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Insulator Engine	ASU10-VT3F1Z 11610-65J01 <small>ARP Product</small>  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Insulator Engine





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

<p>ASU13-CU95E00 41910-50G00</p> <p>Suzuki CULTUS 1.3 [1991-1997] Suzuki Cultus [1995-2001] = SY415</p> <p>Shock Absorber Mounting [RE, LH, RH] [1.3]</p>	<p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU13-LA01F00 41710-60G10</p> <p>Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Cultus [1995-2001] =</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>	<p>ASU13-LA01FB 41742-60G00</p> <p>ARP Product</p> <p>Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Baleno, Esteem [1995-]</p> <p>Shock Absorber Mounting Bearing Only</p> <p>www.rbi.ae</p>
<p>ASU13-LA01FZ 41710-60G10K</p> <p>Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Cultus [1995-2001] =</p> <p>Shock Absorber Mounting + Bearing [SET] [FR, LH, RH]</p>	<p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU13-LA06F00 41710-54G10</p> <p>Suzuki Aerio, Liana [2006] = RH423</p> <p>Shock Absorber Mounting</p>	<p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU13-SW89F00 41710-50G00</p> <p>Suzuki SWIFT [1989-2001]</p> <p>Shock Absorber Mounting</p>	<p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>ASU13-SW93F00 41710-60B00</p> <p>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Suzuki Swift [1993-2003] = SF413, SF416</p> <p>Shock Absorber Mounting [FR]</p>
<p>ASU13-SW05F00 41710-51K00</p> <p>ARP Product www.rbi.ae</p> <p>Opel Agila [2008] = B Suzuki Splash [2008] Suzuki Swift [2003] = RS413, RS415, RS416</p> <p>Shock Absorber Mounting</p>	
<p>ASU13-SX406F00 41710-79J01</p> <p>ARP Product www.rbi.ae</p> <p>Suzuki SX4 [2006] = RW415, RW416, RW419, RW420</p> <p>Shock Absorber Mounting</p>	











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU13-VT1E00 41710-82000 Suzuki Vitara [1989-1998] = SE413, SE416 Shock Absorber Mounting	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	ASU13-VT1F00 41810-60A00 Suzuki ESCUDO 1.6 [1990-1999] Shock Absorber Mounting	 <small>TN-2014-February-10 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
ASU13-VT2F00 41810-65D11 Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Shock Absorber Mounting [FR, LH, RH]	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>	ASU13-VT2F01 41810-65DTN Suzuki GRAND VITARA XL-7 2.7 JA627 [2001-2006] Shock Absorber Mounting [FR, LH, RH]	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>
ASU13-VT3F00 41810-65J00 Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Shock Absorber Mounting [FR, LH, RH]	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		
ASU13-WG04F00 41710-80G10 Suzuki Wagon R+ [2004] = RC410E27, RC413E35 Shock Absorber Mounting	 <small>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>		





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU14-SW93F00 41931-54G00 <small>ARP Product</small> www.rbi.ae Suzuki Aerio, Liana [2006] = RH423 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, Shock Absorber Dust Cover	
ASU14-SX406F01 42111-79J00 <small>ARP Product</small> www.rbi.ae Suzuki Aerio, Liana [2006] = RH423 Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 MEP-Shock Absorber Bumper [FR, LH, RH]	
ASU14-VT2F00 41850-65D00 <small>ARP Product</small> www.rbi.ae Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Shock Absorber Dust Cover [FR, LH, RH]	
ASU14-VT3F00 41931-65J00 <small>ARP Product</small> www.rbi.ae Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Shock Absorber Dust Cover [FR, LH, RH]	ASU14-VT3F01 42111-65J00 <small>ARP Product</small> www.rbi.ae Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 MEP-Shock Absorber Bumper [FR, LH, RH]
ASU14-WG04F00 42111-70B11 <small>ARP Product</small> www.rbi.ae Mazda Laputa [1999-2006] = HP11, HP21 Suzuki Alto [1998-2004] = HA12, HA22 Suzuki KEI [1998-2009] Shock Absorber Dust Cover	










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU18-VT2001 48571-65D00 <small>ARP Product</small> Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Steering Gear Boot	ASU18-VT3001 48571-65J00 <small>ARP Product</small> Suzuki Grand Vitara, Escudo [2006] = JB416, www.rbi.ae JB420, JB627 Steering Gear Boot
ASU20-VT1E00 09305-13002  Suzuki Samurai [1985-1995] = SJ413  <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small> Spring Shackle Rubber [RE, Small]	ASU20-VT1F00 41331-62020  Suzuki Samurai [1985-1995] = SJ413  <small>RBI-OLD RBI Product, Perfect Product www.rbi.ae</small> Spring Shackle Rubber [FR, BIG]
ASU20-VT1F02 20031-50390  Suzuki Samurai [1985-1995] = SJ413 <small>Perfect Product www.rbi.ae</small> Spring Shackle Bush [RE]	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU21-LA01E00 46641-60G10 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Baleno, Esteem [1995- www.rbi.ae Stabilizer Shaft Rubber [RE]	ASU21-LA01F00 46641-54G10 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Liana [2001-2008] = RH413, RH416, RH418 www.rbi.ae Stabilizer Shaft Rubber [RE]
ASU21-LA06F00 42431-59J00 <small>ARP Product</small> Suzuki Aerio, Liana [2006] = RH423 www.rbi.ae Stabilizer Shaft Rubber [FR]	
ASU21-SW05F00 42431-63J10 <small>ARP Product</small> Opel Agila [2008] = B Suzuki Swift [2003] = RS413, RS415, RS416 www.rbi.ae Stabilizer Shaft Rubber [FR]	ASU21-SW93F00 42431-70C00 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, S www.rbi.ae Stabilizer Shaft Rubber [FR]
ASU21-SX406F00 42431-79J00 <small>ARP Product</small> Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 www.rbi.ae Stabilizer Shaft Rubber [FR]	ASU21-SX406F02 42431-80J00 <small>ARP Product</small> Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 www.rbi.ae Stabilizer Shaft Rubber [FR]










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU21-VT1F00 42412-60A00 <div>ARP Product</div> www.rbi.ae Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [1989-1998] = SE413, SE416 Suzuki Vitara Stabilizer Shaft Rubber [FR]	
ASU21-VT2F00 42412-65D00 <div>ARP Product</div>  www.rbi.ae www.alafuae.com Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Stabilizer Shaft Rubber [FR]	ASU21-VT2F02 42412-66D00 <div>ARP Product</div> www.rbi.ae Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Stabilizer Shaft Rubber [FR]
ASU21-VT2F03 42412-82A00 <div>ARP Product</div> www.rbi.ae Suzuki Jimny [1998] = SN413 Stabilizer Shaft Rubber [FR]	
ASU21-VT3F00 42412-65J00 <div>ARP Product</div>  www.rbi.ae www.alafuae.com Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Stabilizer Shaft Rubber [FR]	ASU21-VT3F02 42412-65J02 <div>ARP Product</div>  www.rbi.ae www.alafuae.com Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Stabilizer Shaft Rubber [FR]
ASU21-WG04F00 42431-70B42 <div>TN-2014-February-10 Tenacity Product</div>  www.rbi.ae www.alafuae.com Suzuki Alto [1998-2004] = HA12, HA22 Suzuki Wagon R+ [1999] = MA63S Suzuki Wagon R+ [2004] = RC4 Stabilizer Shaft Rubber [FR]	
ASU23-HA12F01 42451-76G00 <div>TN-2014-February-10 Tenacity Product</div>  www.rbi.ae www.alafuae.com Suzuki Alto [1998-2004] = HA12, HA22 Suzuki Wagon R+ [1999] = MA63S Suzuki Wagon R+ [2004] = RC4 Strut Bar Rubber	



SUZUKI

Revision : 2014-November-01

<p>ASU24-BA95LCLZZ 45202-63G01</p> <p>Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Cultus [1995-2001] =</p> <p>Front Complete Lower Arm [FR, LH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU24-BA95LCRZZ 45201-63G01</p> <p>Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Cultus [1995-2001] =</p> <p>Front Complete Lower Arm [FR, RH]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>ASU24-CP91PB 45200-80F00</p> <p>Suzuki Cappuccino [1991-1997] = SX306</p> <p>Front Upper Arm Bush</p> <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>ASU24-GA413WB 09319-12046</p> <p>Suzuki Carry, Every [1999-2005] = GA413</p> <p>Spring Shackle Bush [RE]</p> <p>TN-2013-November-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	
<p>ASU24-LA01LCL2ZZ 45202-54G01</p> <p>Suzuki Aerio [2002-2005] = RH420 Suzuki Liana [2001-2008] = RH413, RH416, RH418</p> <p>Front Complete Lower Arm [FR, LH]</p> <p>ARP Product www.rbi.ae</p>	<p>ASU24-LA01LCLZZ 45202-59J00</p> <p>Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Liana [2001-2008] = R</p> <p>Front Complete Lower Arm [FR, LH]</p> <p>HFC Product www.rbi.ae</p>
<p>ASU24-LA01LCR2ZZ 45201-54G01</p> <p>Suzuki Aerio [2002-2005] = RH420 Suzuki Liana [2001-2008] = RH413, RH416, RH418</p> <p>Front Complete Lower Arm [FR, RH]</p> <p>ARP Product www.rbi.ae</p>	<p>ASU24-LA01LCRZZ 45201-59J00</p> <p>Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Liana [2001-2008] = R</p> <p>Front Complete Lower Arm [FR, RH]</p> <p>HFC Product www.rbi.ae</p>
<p>ASU24-LA06WB 45540-54G00</p> <p>Suzuki Aerio, Liana [2006] = RH423</p> <p>Front Lower Arm Bush [FR, Big]</p> <p>PFT-2014-November-15 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	<p>ASU24-LA06WS 45500-50810</p> <p>Suzuki Aerio, Liana [2006] = RH423</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>
<p>ASU24-RG413WS 09319-10030</p> <p>Suzuki Ignis [2003-2008] = RG413, RG415 Suzuki KEI [1998-2009] = RE306 Suzuki Wagon R+ [1999] =</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU25-LA01E01 46110-54G60 <small>ARP Product</small> Chrysler Sebring Cirrus Stratus R, T [2004] www.rbi.ae Chrysler Sebring II [2006] Honda Odyssey III, Shuttle Rear Suspension Bush	ASU25-LA01E02 46200-54G10 <small>ARP Product</small> Suzuki Aerio, Liana [2006] = RH423 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, www.rbi.ae Rear Suspension Bush
ASU25-LA01E02LZ 46200-54G20 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Liana [2001-2008] = R www.rbi.ae Rear Complete Suspension Arm [RE, LH]	ASU25-LA01E02RZ 46200-54G10 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Aerio, Liana [2006] = RH423 Suzuki Liana [2001-2008] = R www.rbi.ae Rear Complete Suspension Arm [RE, RH]
ASU25-LA01E03 46110-54G60 <small>ARP Product</small> Suzuki Aerio, Liana [2006] = RH423 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, www.rbi.ae Rear Suspension Bush	



SUZUKI

Revision : 2014-November-01

<p>ASU24-SW89WB 45540-60G10</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Suzuki SWIFT [1989-2001]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>ASU24-SW89WS 45540-60R00</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Suzuki SWIFT [1989-1994]</p> <p>Front Lower Arm Bush [FR, Small]</p>
	<p>ASU24-SW89WS2 45530-60B00</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Suzuki SWIFT [1989-1994]</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>ASU24-SW93WB 46420-60E00</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Suzuki SWIFT [1994-2001]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>ASU24-SW93WS 45530-50G00</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Suzuki SWIFT [1994-2001]</p> <p>Front Lower Arm Bush [FR, Small]</p>
	<p>ASU24-SW93WS2 45500-50800</p> <p>Perfect Product www.rbi.ae</p> <p>Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, SY419 Suzuki Swift [1993-2003] = S</p> <p>Front Lower Arm Bush [FR, Small]</p>
<p>ASU24-SW05WB 45201-62J00</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Suzuki SWIFT [2005]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>ASU24-SW05WBJ 45201-63J00</p> <p>ARP Product www.rbi.ae</p> <p>Opel Agila [2008] = B Suzuki Splash [2008] Suzuki Swift [2003] = RS413, RS415, RS416</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p>
<p>ASU24-SW05WS 45261-79J00</p> <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Opel Agila [2008] = B Suzuki Splash [2008] Suzuki Swift [2003] = RS413, RS415, RS416 Suzuki SX</p> <p>Front Lower Arm Bush [FR, Small]</p>	
<p>ASU24-SW05LCLZZ 45202-63J00</p> <p>ARP Product www.rbi.ae</p> <p>Opel Agila [2008] = B Suzuki Splash [2008] Suzuki Swift [2003] = RS413, RS415, RS416</p> <p>Front Complete Lower Arm [FR, LH]</p>	<p>ASU24-SW05LCRZZ 45201-63J00</p> <p>ARP Product www.rbi.ae</p> <p>Opel Agila [2008] = B Suzuki Splash [2008] Suzuki Swift [2003] = RS413, RS415, RS416</p> <p>Front Complete Lower Arm [FR, RH]</p>
<p>ASU25-SW05E01 46221-63J00</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Suzuki Splash [2008] Suzuki Swift [2003] = RS413, RS415, RS416</p> <p>Rear Suspension Bush</p>	



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU24-SX406LCLZZ 45202-54L00 <div>ARP Product</div> www.rbi.ae Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 Front Complete Lower Arm [FR, LH]	ASU24-SX406LCRZZ 45201-54L00 <div>ARP Product</div> www.rbi.ae Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 Front Complete Lower Arm [FR, RH]
ASU25-SX406E01 46221-79J00 <div>HFC Product</div> www.rbi.ae Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 Rear Suspension Bush	
ASU24-WG04WB 46201-86G00 <div>ARP Product</div> www.rbi.ae Suzuki Ignis [2003-2008] = RG413, RG415 Suzuki Wagon R+ [2004] = RC410E27, RC413E35 Front Lower Arm Bush [FR, Big]	





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

<p>ASU24-VT1BD01 48750-60A00</p> <p>Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [1989-1998] = SE413, SE416 Suzuki Vitara</p> <p>Front Lower Arm Bush</p>	<p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU24-VT1E1 09319-12043</p> <p>Suzuki Vetra ESCUDO [1.6] [1990-1999] Suzuki Ignis [2003-2008] = RG413, RG415 Suzuki Jimny [19]</p> <p>Front Lower Arm Bush [FR, Small]</p>	<p>ARD-2013-May-01 ARD Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>ASU24-VT1E2 09319-12045</p> <p>Suzuki Vetra ESCUDO [1.6] [1990-1999]</p> <p>Front Upper Arm Bush [FR, Small]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU24-VT1E3 09319-12023</p> <p>Suzuki Caribbean SJ413</p> <p>Spring Shackle Bush [FR]</p>	<p>RBI-2013-May-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU24-VT1PB 09319-12044</p> <p>Suzuki Vetra ESCUDO [1.6] [1990-1999]</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>TN-2012-May-14 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>ASU24-VT1PS 09319-14007</p> <p>Suzuki Sidekick Sport [1996-1998] = SV418 Suzuki Vitara [1989-1998] = SE413, SE416 Suzuki X90 [1</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU24-VT1WB 09319-12047</p> <p>Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>TN-2014-August-30 Tenacity Product, ARD Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU24-SF310 45540-60B02</p> <p>Suzuki Swift, Cultus [2001-2003] = SF310 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416,</p> <p>Front Lower Arm Bush [FR, Big]</p>	<p>RBI-2013-May-28 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>ASU24-SF311 45530-70C00</p> <p>Suzuki Swift, Cultus [2001-2003] = SF310 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416,</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>RBI-2013-June-15 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU24-VT2WB 45262-65D01  Suzuki Vetra [1998-2006] Front Lower Arm Bush [FR, Big]	ASU24-VT2WS 45261-65D01  Suzuki Vetra [1998-2006] Front Lower Arm Bush [FR, Small]
ASU24-VT2LCLZZ 45202-65D00  Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]	ASU24-VT2LCRZZ 45201-65D00  Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, www.rbi.ae SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

<p>ASU24-VT3BD01 46911-65J00</p> <p>Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627</p> <p>Front Suspension Body Bush</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>ASU24-VT3WB 45262-65J12</p> <p>Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627</p> <p>Front Lower Arm Bush [FR, Big]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	<p>ASU24-VT3WS 45261-65J12</p> <p>Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627</p> <p>Front Lower Arm Bush [FR, Small]</p> <p>TN-2013-November-20 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 
<p>ASU24-VT3WL 27553-66J01</p> <p>Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627</p> <p>Front Lower Arm Bush</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> 	
<p>ASU24-VT3LCLZZ 45202-65J00</p> <p>Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p> <p>ARP Product www.rbi.ae</p>	<p>ASU24-VT3LCRZZ 45201-65J00</p> <p>Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p> <p>ARP Product www.rbi.ae</p>





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU25-VT3E02 46331-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Suspension Bush	ASU25-VT3E03 46122-65J00  Hyundai Azera [2006] = TG Hyundai Grandeur [2005] = TG Hyundai Sonata [2005-2010] = NF Suzuki Rear Suspension Bush
ASU25-VT3E04B 46121-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Suspension Bush	ASU25-VT3E04S 46110-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Suspension Bush
ASU25-VT3E05 46371-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Suspension Bush	ASU25-VT3E05Z 46305-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Complete Suspension Arm
ASU25-VT3UB 46231-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Upper Arm Bush [RE, Small]	
ASU25-VT3UCLZZ 46202-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Complete Upper Arm [RE, LH]	ASU25-VT3UCRZZ 46201-65J00  Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 Rear Complete Upper Arm [RE, RH]
ASU25-VT3E06 #46201-65D00  Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL Rear Suspension Bush	ASU25-VT3E07 #46300-52D00  Suzuki Grand Vitara, Grand Escudo XL-7 [2001-2006] = JA627 Ssang Yong New Actyon, Korando C [2010- Rear Suspension Bush





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

SUZUKI

Revision : 2014-November-01

ASU27-BA95EL 46640-80F00 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, S www.rbi.ae Link Assy [RE, LH]	ASU27-BA95ER 46630-80F00 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, S www.rbi.ae Link Assy [RE, RH]
ASU27-CA01F00 42420-61J00  <small>RBI-OLD RBI Product</small> www.rbi.ae Suzuki Carry, Every [1999-2005] = GA413 Link Assy [FR]	
ASU27-SW05F00 350616 <small>ARP Product</small> Alfa Romeo Mito [2008] BMW Mini [2000-2008] = R50, R52, R53 BMW Mini [2005] = R55, R56, R57, R58 www.rbi.ae Link Assy	ASU27-SW93F00 09320-10024 <small>ARP Product</small> Suzuki Aerio [2002-2005] = RH420 Suzuki Baleno, Esteem [1995-2001] = SY413, SY415, SY416, SY418, S www.rbi.ae Link Assy
ASU27-VT2F00 09320-10024 <small>ARP Product</small> Suzuki Grand Vitara, Escudo [1998-2006] = SQ416, SQ420, SQ625 Suzuki Grand Vitara, Grand Escudo XL www.rbi.ae Link Assy [FR, LH, RH]	ASU27-VT3F00 42420-65J00 <small>ARP Product</small> Suzuki Grand Vitara, Escudo [2006] = JB416, JB420, JB627 shabbirh@eim.ae www.rbi.ae www.alafuae.com Link Assy [FR, LH, RH]
ASU41-SX406001 27550-63J00 <small>ARP Product</small> Suzuki Swift [2003] = RS413, RS415, RS416 Suzuki SX4 [2006] = RW415, RW416, RW419, RW420 www.rbi.ae Front Differential Mounting	

