

HONDA

Revision : 2014-November-01

| | | | |
|--|---|---|---|
| AO09-088RB 50836-SA0-981 Accord [1988] Engine Bushing [RH, Big] |  RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-088S 50834-SA0-010 Accord [1988] Engine Bushing [RH, Small] |  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-0880 50811-SA5-000 Accord [1980-1983] Insulator Engine |  RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO10-088F 50811-SE0-000 Accord [1988] Insulator Engine [FR, RE] |  RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-088L 50821-SE0-931 Accord [1988] Insulator Engine [LH] |  RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-088FAZ 50810-SE0-J31 Accord [1988] Insulator Engine [FR, M/T] |  TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-088FMZ 50810-SE0-A02 Accord [1988] Insulator Engine [FR, A/T] |  TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-088FU 50815-SA5-000 Accord [1988] Insulator Engine [FR, Upper] |  Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| | | | |
| | | | |
| | | | |

HONDA

Revision : 2014-November-01

| | | | |
|---|--|---|---|
| AO09-090FB 50830-SM4-981 Accord [1990-1997] [LXI] Engine Bushing [FR, A/T, M/T] [Big] | RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO09-090FZ 50830-SM4-020 Accord [1990-1997] [LXI] Insulator Engine [FR, A/T, M/T] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com |
| AO09-090FS 50830-SM4-981 Accord [1990-1997] [LXI] Engine Bushing [FR, A/T, M/T] [Small] | RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| AO10-090FM 50814-SF1-010 Accord [1990-1993] Insulator Engine [FR, A/T, M/T] | RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO10-PL4FZ 50814-SS0-980 Prelude [1992-1996] Insulator Engine [FR, A/T, M/T] | Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO10-094FA 50840-SV4-980 Accord [1994-1997] Odyssey [1995-1999] Insulator Engine [FR, A/T] | RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO10-094FM 50840-SV4-000 Accord [1994-1997] Odyssey [1995-1999] Insulator Engine [FR, M/T] | RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO10-090EZ 50810-SM4-000 Accord [1990-1993] Insulator Engine [RE, A/T, M/T] | TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO10-090EMZ 50810-SS0-000 Accord [1990-1994] Prelude [1992-1996] Insulator Engine [RE, A/T, M/T] | TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com |
| AO10-090ELZ 50810-SM4-J02 Accord [1990-1997] Insulator Engine [RE, LH, A/T, M/T] | ASH-2012-December-25 HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO10-090ERZ 50810-SV4-J82 Accord [1990-1997] Odyssey [1995-1999] Insulator Engine [RE, RH, A/T, M/T] | TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| | | | |
| | | | |

HONDA

Revision : 2014-November-01

| | |
|--|--|
| <p>AO10-090R 50805-SM4-020</p> <p>Accord [1990-1993]</p> <p>Insulator Engine [RH, A/T, M/T]</p>  <p>RBI-2005-February-15 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-090RMZ 50806-SS0-982</p> <p>Accord [1990-1994] [2.0, 2.2]</p> <p>Insulator Engine [RH]</p>  <p>Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-PL4RAZ 50805-SS0-980</p> <p>Prelude [1992-1993]</p> <p>Insulator Engine [RH, A/T]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-PL4RMZ 50806-SS0-000</p> <p>Prelude [1992-1996]</p> <p>Insulator Engine [RH, M/T]</p>  <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-094RA 50806-SV4-980</p> <p>Accord [1994-1997] Odyssey [1995-1999] Prelude [1993-1996]</p> <p>Insulator Engine [RH, A/T]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-094RM 50806-SV4-000</p> <p>Accord [1994-1997] Odyssey [1995-1999]</p> <p>Insulator Engine [RH, M/T]</p>  <p>RBI-2005-August-19 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| <p>AO10-090L 50820-SM4-020</p> <p>Accord [1990-1993]</p> <p>Insulator Engine [LH, A/T, M/T]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-094L 50820-SV4-J01</p> <p>Accord [1994-1997] Odyssey [1995-1999]</p> <p>Insulator Engine [LH, A/T, M/T]</p>  <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | <p>AO10-PL4LZ 50820-SS0-J01</p> <p>Prelude [1992-1996]</p> <p>Insulator Engine [LH, A/T, M/T]</p>  <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |




AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|--|--|
| AO10-095FZ 50800-SV7-A01 Accord [1994-1997] V6 [3.0] Insulator Engine [FR] | <small>Ashimori Product</small> www.rbi.ae | AO10-095EZ 50810-SV7-A01 Accord [1994-1997] V6 [3.0] Insulator Engine [RE] | <small>Ashimori Product</small> shabbirh@eim.ae www.rbi.ae www.alafuae.com  |
| | | AO10-095LZ 50805-SV7-A00 Accord [1994-1997] V6 [3.0], Integra Insulator Engine [LH] | <small>Ashimori Product</small> www.rbi.ae |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|--|
| <p>AO10-098FZ 50840-S84-A80</p> <p>Accord [1998]</p> <p>Insulator Engine [FR, A/T, M/T]</p> <p><small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO10-099FZ 50840-S0A-981</p> <p>Honda Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Honda Torneo [1997-2002] = CF3, CF4, CF5, CL1,</p> <p>Insulator Engine [FR, A/T, M/T]</p> <p><small>TN-2013-September-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> |
| <p>AO10-099F2Z 50840-S1A-E00</p> <p>Honda Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Honda Torneo [1997-2002] = CF3, CF4, CF5, CL1,</p> <p>Insulator Engine [FR, A/T, M/T]</p> <p><small>Perfect Product www.rbi.ae</small></p> | |
| <p>AO10-098EM 50810-S84-A00</p> <p>Accord [1998]</p> <p>Insulator Engine [RE, M/T]</p> <p><small>RBI-2005-February-15 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO10-098EMZ 50810-S84-A00</p> <p>Accord [1998]</p> <p>Insulator Engine [RE, M/T] [With Top]</p> <p><small>Ashimori Product www.rbi.ae</small></p> |
| | <p>AO10-098EAZ 50810-S84-A84</p> <p>Accord [1998-2002]</p> <p>Insulator Engine [RE, A/T]</p> <p><small>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| | <p>AO10-098LZ 50821-S84-A01</p> <p>Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Odyssey, Shuttle [1999-2003] = RA6, RA7, RA8, RA9 T</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p> |
| | |
| <p>AO09-098RMZ 50805-S84-A01</p> <p>Accord [1998-2002] [1.8, 2.0, 2.2]</p> <p>Insulator Engine [RH, M/T]</p> <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO10-099RA 50805-S84-A80</p> <p>Accord [1998]</p> <p>Insulator Engine [RH, A/T]</p> <p>TN-2011-October-12 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-098RA 50806-S0A-980</p> <p>Accord [1999-2002]</p> <p>Insulator Engine [RH, A/T]</p> <p>RBI-2005-January-11 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO10-098F3Z 50810-S87-A81</p> <p>Accord [1998-2002] V6 [3.0]</p> <p>Insulator Engine [FR]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-098E3Z 50815-S87-A81</p> <p>Accord [1998-2002] V6 [3.0]</p> <p>Insulator Engine [RE]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-300FZ 50800-S0X-A02</p> <p>Odyssey [2000-2004]</p> <p>Insulator Engine [FR]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| | <p>AO10-300EZ 50810-S0X-A00</p> <p>Odyssey [2000-2004]</p> <p>Insulator Engine [RE]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-098L3Z 50820-S87-A81</p> <p>Accord [1998-2002] V6 [3.0]</p> <p>Insulator Engine [LH]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-098L4Z 50821-S0A-003</p> <p>Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Odyssey, Shuttle [1999-2003] = RA6, RA7, RA8, RA9 T</p> <p>Insulator Engine [LH, A/T]</p> <p>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-300LZ 50820-S0X-A01</p> <p>Odyssey [2000-2004]</p> <p>Insulator Engine [LH]</p> <p>TN-2011-July-23 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO10-098CRZ 50806-S87-A80</p> <p>Accord [1998-2002] V6 [3.0] Odyssey [2000-2004]</p> <p>Insulator Engine [Center, RH]</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-098CLZ 50805-S87-A80</p> <p>Honda Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Honda Avancier [1999-2003] = TA1, TA2, TA3, TA4</p> <p>Insulator Engine [Center, LH, 3.0]</p> <p>TN-2014-February-10 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|---|--|
| | | AO10-OD02E1Z 50830-SFE-350 Odyssey 2.4L [2002-2003] Insulator Engine [RE] | HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae |
| | | AO10-305E3Z 50810-SFE-020 Honda Odyssey II, Shuttle [1999-2003] = RA6, RA7, RA8, RA9 Honda Odyssey III, Shuttle [2003-2008] Insulator Engine [RE, 2.4] | HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae |
| | | AO10-OD02L1Z 50820-SFE-J00 Odyssey 2.4L [2002-2003] Insulator Engine [LH] | HFC Product, Ashimori Product www.rbi.ae |
| | | AO10-OD02R1Z 50850-SFE-003 Odyssey [2002-2003] 2.4l Insulator Engine [RH] | HFC Product, Ashimori Product www.rbi.ae |
| AO10-STP01F1Z 50840-S7S-980 Honda Step WGN [2001-2005] = RF3-RF8 Insulator Engine [FR] | HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | | |
| AO10-STP01E1Z 50810-S7S-003 Honda Step WGN [2001-2005] = RF3-RF8 Insulator Engine [RE] | HFC-2014-November-20 HFC Product www.rbi.ae | AO10-STP01E2Z 50810-SLJ-003 Honda Step WGN [2001-2005] = RF3-RF8 Insulator Engine [RE] | HFC Product www.rbi.ae |
| AO10-STP01L1Z 50805-S7S-033 Honda Step WGN [2001-2005] = RF3-RF8 Insulator Engine [LH] | ARP Product shabbirh@eim.ae  www.alafuae.com | AO10-STP01L2Z 50805-SLJ-013 Honda Step WGN [2001-2005] = RF3-RF8 Insulator Engine [LH] | HFC-2014-November-20 HFC Product www.rbi.ae |
| AO10-STP01R1Z 50821-S7S-033 Honda Step WGN [2001-2005] = RF3-RF8 Insulator Engine [RH] | ARP Product shabbirh@eim.ae  www.alafuae.com | AO10-STP01R2Z 50820-SLJ-100 Honda Step WGN [2001-2005] = RF3-RF8 Insulator Engine [RH] | HFC-2014-November-20 HFC Product www.rbi.ae |



HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO10-003F0 50830-SDA-A02</p> <p>Accord [2003-2008] Odyssey [2005-2010]</p> <p>Insulator Engine [FR, A/T, M/T]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-003E0 50810-SDA-A02</p> <p>Accord [2003-2008]</p> <p>Insulator Engine [RE, A/T, M/T]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>AO10-003E1 50810-SDB-A02</p> <p>HFC-2014-November-20 HFC Product www.rbi.ae</p> <p>ACCORD [2003]</p> <p>Insulator Engine [RE, AT]</p> |
| <p>AO10-305EZ 50810-SHJ-A62</p> <p>Honda Odyssey II, Shuttle [1999-2003] = RA6, RA7, RA8, RA9 Honda Odyssey III, Shuttle [2003-2008]</p> <p>Insulator Engine [RE, A/T]</p> | <p>HFC Product www.rbi.ae</p> <p>AO10-305EZ 50810-SFE-030</p> <p>HFC-2014-November-20 HFC Product, Ashimori Product www.rbi.ae</p> <p>Honda Odyssey II, Shuttle [1999-2003] = RA6, RA7, RA8, RA9 Honda Odyssey III, Shuttle [2003-2008]</p> <p>Insulator Engine [RE, A/T]</p> |
| <p>AO10-003R0 50820-SDA-A01</p> <p>Accord [2003-2008]</p> <p>Insulator Engine [RH, A/T, M/T]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>AO10-305RZ 50820-SHJ-A03</p> <p>HFC Product www.rbi.ae</p> <p>Honda Odyssey II, Shuttle [1999-2003] = RA6, RA7, RA8, RA9 Honda Odyssey III, Shuttle [2003-2008]</p> <p>Insulator Engine [RH, A/T]</p> |
| <p>AO10-003L0 50870-SDA-A02</p> <p>Accord [2003-2008]</p> <p>Insulator Engine [LH, A/T, M/T]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>AO10-003L1 50870-SDB-A02</p> <p>Accord [2003-2008]</p> <p>Insulator Engine [LH, A/T, M/T]</p> |
| | |
| | |
| | |









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|--|
| | |
| AO10-003CFA 50850-SDA-A00 Accord [2003-2008] Insulator Engine [Center, FR, A/T] |  <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO10-003CFM 50850-SDB-A00 Accord [2003-2008] Insulator Engine [Center, FR, M/T] |  <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO10-003CEA 50860-SDA-A02 Accord [2003-2008] Insulator Engine [Center, RE, A/T] |  <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO10-003CEM 50860-SDB-A01 Accord [2003-2008] Insulator Engine [Center, RE, M/T] |  <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO24-003ELZ 50285-SDA-A01 Honda Accord [2002-2008] = CL, CN, CM Honda Accord Wagon, Tourer [2002-2008] = CM Honda Inspire Front Cross Member Arm Bush |  <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO24-003ERZ 50280-SDA-A01 Honda Accord [2002-2008] = CL, CN, CM Honda Accord Wagon, Tourer [2002-2008] = CM Honda Inspire Front Cross Member Arm Bush |  <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |
| | |
| | |













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|--|---|
| AO10-MRV03EZ 50810-S3V-A01 MR-V [2003-2008] Insulator Engine [RE] |  HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-MRV03FZ 50800-S3V-A81 MR-V [2003-2008] Pilot [2002-2008] = YF1 Insulator Engine [FR] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-MRV03RZ 50820-S3V-A82 MR-V [2003-2008] Insulator Engine [RH] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-MRV03R2Z 50820-STW-A00 MR-V / Honda Pilot [2007] Insulator Engine |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-MRV03CEZ 50806-S3V-A01 MR-V [2003-2008] Insulator Engine [Center, RE] |  TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-MRV03CFZ 50805-S3V-A81 Honda MR-V [2003-2008] Insulator Engine [Center, FR] |  TN-2014-February-10 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-MRV03CE3Z 50806-S3V-000 Honda Acura MDX [2001-2006] = YD1 Honda MR-V [2003-2008] Honda Pilot [2002-2008] = YF1 Insulator Engine [Center, RE, A/T] |  ARP Product www.rbi.ae | AO10-MRV03CF3Z 50805-S3V-010 Honda Acura MDX [2001-2006] = YD1 Honda MR-V [2003-2008] Honda Pilot [2002-2008] = YF1 Insulator Engine [Bracket only] [Center, FR, A/T] |  HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |
| | | | |
| | | | |
| | | | |






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO10-009E1Z 50810-TA2-H01</p> <p>Accord [2008-2013] [2.0]</p> <p>Insulator Engine [RE, A/T, M/T]</p> | <p>ASH-2013-November-15 HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO10-008E0 50810-TA0-A01</p> <p>Accord [2008-2013] [2.4]</p> <p>Insulator Engine [RE, A/T, M/T]</p> | <p>RBI-2011-April-11, RBI-2011-May-07 RBI Product, Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO10-009E3Z 50810-TA1-A01</p> <p>Accord [2008-2013] [3.5]</p> <p>Insulator Engine [RE, A/T, M/T]</p> | <p>ARP Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO10-009F1Z 50830-TA2-H01</p> <p>Accord [2008-2013] [2.0]</p> <p>Insulator Engine [FR, A/T, M/T]</p> | <p>ARD-2014-January-01 HFC Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO10-009F2Z 50830-TA0-A01</p> <p>Accord [2008-2013] [2.4]</p> <p>Insulator Engine [FR, A/T, M/T]</p> | <p>TN-2010-December-26 Tenacity Product, HFC Product, Ashimori Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO10-009F3Z 50830-TA1-A01</p> <p>Accord [2008-2013] [3.5]</p> <p>Insulator Engine [FR, A/T, M/T]</p> | <p>ARD-2014-January-01 ARP Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | |
| | |












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| <p>AO10-009R1Z 50820-TA2-H01</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Accord [2008-2013] [2.0]</p> <p>Insulator Engine [RH, A/T, M/T]</p> | |
| <p>AO10-009R2Z 50820-TA0-A11</p> <p>TN-2014-February-10 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Accord [2008-2013] [2.4]</p> <p>Insulator Engine [RH, A/T, M/T]</p> | |
| <p>AO10-009R3Z 50820-TA1-A01</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Accord [2008-2013] [3.5]</p> <p>Insulator Engine [RH, A/T, M/T]</p> | |
| <p>AO10-009L1ZZ 50870-TA2-H02</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Accord [2008-2013] [2.0]</p> <p>Insulator Engine [LH, A/T, M/T]</p> | |
| <p>AO10-009L2ZZ 50870-TA0-A03</p> <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Accord [2008-2013] [2.4]</p> <p>Insulator Engine [LH, A/T, M/T]</p> | <p>AO10-009L2Z 50870-TA0-A03</p> <p>TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Accord [2008-2013] [2.4]</p> <p>Insulator Engine [LH, A/T, M/T]</p> |
| <p>AO10-009L3ZZ 50870-TA1-A01</p> <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>Accord [2008-2013] [3.5]</p> <p>Insulator Engine [LH, A/T, M/T]</p> | |
| | |
| | |











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|--|
| | <p>AO10-008L0 50850-TA2-H02</p> <p>Accord [2008-2013] [2.0]</p> <p>Insulator Engine [Center, A/T]</p>  <p>RBI-2011-December-12 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO10-009C2M 50851-TA0-A11</p> <p>Accord [2008-2013] [2.4]</p> <p>Insulator Engine [Center, M/T]</p> | <p>AO10-008L1 50850-TA0-A01</p> <p>Accord [2008-2013] [2.4]</p> <p>Insulator Engine [Center, A/T]</p>  <p>RBI-2012-January-06 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO10-008L 50851-TA1-A01</p> <p>Accord [2008-2013] [3.5]</p> <p>Insulator Engine [Center, A/T]</p>  <p>RBI-2011-July-02 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| | |
| | |
| | |
| | |
| | |






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | |
|--|---|---|
| AO10-IN91FZ 50840-SK7-010  Integra [1991-1993] Insulator Engine [FR, A/T, M/T] | <small>Perfect Product, Ashimori Product</small> www.rbi.ae | |
| AO10-IN91LZ 50821-SK7-010 Integra [1991] Insulator Engine [LH, A/T, M/T] | <small>Ashimori Product</small> www.rbi.ae | |
| | AO10-IN92RAZ 50805-SK7-981 Integra [1991-1993] Insulator Engine [RH, A/T] | <small>Ashimori Product</small> www.rbi.ae |
| | | |
| | | |
| | | |
| | | |
| | | |



HONDA

Revision : 2014-November-01

| | | | |
|---|---|---|--|
| AO10-286FA 50841-SH3-984 Civic [1988-1991] Insulator Engine [FR, A/T] | RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-286FM 50840-SH3-000 Civic [1988-1991] Insulator Engine [FR, M/T] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO09-286EA 50810-SH3-985 Civic [1988-1991] Engine Bushing [RE, A/T] | RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-286EAZ 50810-SH3-985 Civic [1988-1991] Insulator Engine [RE, A/T] | RBI-2006-February-09 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO09-286EM 50810-SH3-040 Civic [1988-1991] Engine Bushing [RE, M/T] | RBI-2007-February-26 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-286EMZ 50810-SH3-040 Civic [1988-1991] Insulator Engine [RE, M/T] | RBI-2007-February-26 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-288L0 50821-SH3-040 Civic [1988-1991] Insulator Engine [LH, A/T, M/T] | RBI-2007-February-13 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO10-286RA 50805-SH3-983 Civic [1988-1991] Insulator Engine [RH, A/T] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-286RM 50805-SH3-020 Civic [1988-1991] Insulator Engine [RH, M/T] | TN-2010-December-01 Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-286R3Z 50805-SH3-N11 Civic SR4 VTEC [AT] Insulator Engine [RH] | Ashimori Product www.rbi.ae | | |
| | | | |
| | | | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO10-292FL 50842-SR3-030</p> <p>Civic [1992-2000] CRV [1997-2001] Integra [1994-2001]</p> <p>Insulator Engine [FR, LH, A/T, M/T]</p> | <p>AO10-292FR 50841-SR3-030</p> <p>Civic [1992-2000] CRV [1997-2001] Integra [1994-2001]</p> <p>Insulator Engine [FR, RH, A/T, M/T]</p> |
| <p>AO10-496FL 50842-ST0-N10</p> <p>Civic [1996-2000] CRV [1997-2001] Integra [1994-2001]</p> <p>Insulator Engine [FR, LH, M/T]</p> | <p>AO10-496FR 50841-ST0-N10</p> <p>Civic [1996-2000] CRV [1997-2001] Integra [1994-2001]</p> <p>Insulator Engine [FR, RH, M/T]</p> |
| <p>AO10-292E 50810-SR3-030</p> <p>Civic [1992-2000] CRV [1997-2001] Integra [1994-2001]</p> <p>Insulator Engine [RE, A/T, M/T]</p> | |
| | |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | |
|---|---|
| | <p>AO10-292LMZ 50821-SR3-020</p> <p>Civic [1992]</p> <p>Insulator Engine [LH, M/T]</p> <p>TENACITY</p> <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | <p>AO09-292LZ 50820-SR3-J03</p> <p>Civic [1988-1995] City Honda K6 CIVIC 1.6 [1992-1996]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO09-292L 50820-SR3-003</p> <p>Civic [1992-1995] Accord [1998] City</p> <p>Engine Bushing [LH, A/T, M/T]</p> <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO09-292LAZ 50820-SR3-003</p> <p>Civic [1992-1995] [V-TEC]</p> <p>Insulator Engine [LH, A/T]</p> <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO09-292L3Z 50820-SR3-J11</p> <p>Honda K6 CIVIC 1.6 [1992-1996]</p> <p>Insulator Engine</p> <p>TN-2014-February-10 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO10-296L0 50820-S04-013</p> <p>Civic [1996-2000]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>RBI-2006-February-09 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-496L0 50820-S10-004</p> <p>CRV [1997-2001]</p> <p>Insulator Engine [LH, A/T, M/T] [Hydraulic-With Bracket]</p> <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-IN94LZ 50820-ST7-003</p> <p>Integra [1994-2001]</p> <p>Insulator Engine [LH, A/T, M/T]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| | |
| | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO10-292RM 50805-SR3-010</p>  <p>Civic [1992-1993] Integra [1994-2001]</p> <p>Insulator Engine [RH, M/T]</p> | <p>AO10-292RAV 50805-SR3-981</p>  <p>Civic [1992-1995] [V-TEC] Integra [1994-2001]</p> <p>Insulator Engine [RH, A/T]</p> |
| <p>AO10-292RA 50805-SR3-951</p>  <p>Civic [1992-1995]</p> <p>Insulator Engine [RH, A/T]</p> | <p>AO10-294RA 50805-SR3-A81</p>  <p>Civic [1994-1995]</p> <p>Insulator Engine [RH, A/T]</p> |
| <p>AO10-296R 50805-S04-000</p>  <p>Civic [1996-2000] CRV [1997-2001] City</p> <p>Insulator Engine [RH, A/T, M/T]</p> | <p>AO10-296RC 50805-S04-990</p>  <p>Civic [1996-2000] [CVT]</p> <p>Insulator Engine [RH]</p> |
| | |
| | |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|--|---|---|---|
| AO10-201FA 50840-S5A-990 Civic [2001-2005] Insulator Engine [FR, A/T] | RBI-2006-February-09 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-201FM 50840-S5A-010 Civic [2001-2005] Insulator Engine [FR, M/T, L7] | RBI-2011-May-07 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-201F7 50840-S6M-010 Honda Civic, Civic Ferio [2000-2006] = ES1, ES2, ES3 Honda Civic [2001-2006] = EU, EP, ES Insulator Engine [FR, 1.7 Petrol] | TN-2013-November-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO10-201EA 50810-S5A-992 Civic [2001-2005] Insulator Engine [RE, A/T] | RBI-2009-August-15 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-201EM 50810-S5A-013 Civic [2001-2005] Insulator Engine [RE, M/T] | RBI-2009-August-21 RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-203E0 50810-S7C-981 Civic [2003] Insulator Engine [RE] | TN-2012-March-06 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| | | AO09-201RZ 50805-S5A-033 Civic [2001-2005] Insulator Engine [RH, A/T, M/T] | RBI-2010-May-22 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-YH2R0Z 50821-SCV-A02 Element [2003-2005] = YH2 Insulator Engine [FR, RH] | ARP Product www.rbi.ae | | |
| AO10-201L1 50820-S5A-A08 Civic [2001-2005] Insulator Engine [LH] | TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-201L0 50827-S5A-003 Civic [2001-2005] Insulator Engine [LH] | TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-YH2L0Z 50815-SCV-A82 Element [2003-2005] = YH2 Insulator Engine [FR, LH] | ARP Product www.rbi.ae | | |











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO10-402FA 50840-S7C-980</p> <p>CRV [2002-2006]</p> <p>Insulator Engine [FR, A/T]</p>   | <p>AO10-402FM 50840-S7C-000</p> <p>CRV [2002-2006]</p> <p>Insulator Engine [FR, M/T]</p> <p>HFC Product</p> <p>www.rbi.ae</p> |
| <p>AO10-402EA 50810-S7D-003</p> <p>CRV [2002-2006]</p> <p>Insulator Engine [RE, A/T, M/T]</p>   | |
| <p>AO10-402R0 50821-S9A-023</p> <p>CRV [2002-2006]</p> <p>Insulator Engine [RH, A/T, M/T]</p>   | <p>AO10-402RM 50821-S5B-003</p> <p>CRV [2002-2006], Intregra [2001-2006]</p> <p>Insulator Engine [RH, M/T]</p> <p>TN-2013-September-10 Product, Tenacity Product, HFC Product</p> <p>www.rbi.ae</p> |
| <p>AO10-402LA 50805-S9A-983</p> <p>Honda CR-V [2001-2006] = RD4, RD5, RD6, RD7, RD9</p> <p>Insulator Engine [LH, A/T]</p>   | <p>AO10-402LM 50805-S9A-023</p> <p>Honda CR-V [2001-2006] = RD4, RD5, RD6, RD7, RD9</p> <p>Insulator Engine [LH, M/T]</p> <p>HFC Product</p> <p>www.rbi.ae</p> |
| <p>AO10-402L2M 50805-S9A-013</p> <p>Honda CR-V [2001-2006] = RD4, RD5, RD6, RD7, RD9</p> <p>Insulator Engine [LH, M/T]</p> <p>HFC Product</p> <p>www.rbi.ae</p> | <p>AO10-402L3M 50805-S7C-013</p> <p>Honda Civic [2001-2006] = EU, EP, ES Honda Civic, Civic Ferio [2000-2006] = ES1, ES2, ES3</p> <p>Insulator Engine [LH, M/T, 1.7]</p> <p>Tenacity Product</p> <p>www.rbi.ae</p> |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | |
|---|---|
| AO10-206F0W0 50820-SVA-A05 Ashimori Product www.rbi.ae Civic [2006-2010] [1.8] Insulator Engine [FR, A/T, M/T] [Without Aluminum] | AO10-206F0 50820-SVA-A05 TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Civic [2006-2010] [1.8] Insulator Engine [FR, A/T, M/T] [With Aluminum] |
| AO10-206F2W0 50820-SNG-J02 ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Civic [2006-2010] [2.0] Insulator Engine [FR, A/T, M/T] [Without Aluminum] | AO10-206F2 50820-SNG-J02 TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Civic [2006-2010] [2.0] Insulator Engine [FR, A/T, M/T] [With Aluminum] |
| AO10-407FB 50820-SWE-T51 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com CRV [2007-2011] Insulator Engine [FR, A/T, M/T] [Without Aluminum] | AO10-407F0 50820-SWE-T01 TN-2012-March-06 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com CRV [2007-2011] Insulator Engine [FR, A/T, M/T] [With Aluminum] |
| | AO10-407F1 50820-SWE-T51 TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com CRV [2007-2011] Insulator Engine [FR, A/T, M/T] [With Aluminum] |
| | AO10-407F2 50820-SWG-T51 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com CRV [2007-2011] Insulator Engine [FR, A/T, M/T] [With Aluminum] |
| AO10-206L0 50850-SNA-A82 TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Civic [2006-2010] Insulator Engine [LH, A/T, M/T] | |
| AO10-407LM 50850-SWC-E02 HFC Product www.rbi.ae CRV [2007-2011] Insulator Engine [LH, M/T] | AO10-407LAZ 50850-SWA-A81 TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com CRV [2007-2011] Insulator Engine [LH, A/T, M/T] |
| | |

HONDA

Revision : 2014-November-01

| | |
|--|--|
| <p>AO10-2060 50890-SNA-A81 Civic [2006-2010] Insulator Engine [RE, A/T] [1.8]</p>   <p>RBI-2011-August-23 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-206E 50890-SNG-982 Civic [2006-2010] Insulator Engine [RE, A/T] [2.0]</p>   <p>RBI-2011-January-26 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-407EAZ 50890-SWA-A81 CRV [2007-2011] Insulator Engine [RE, A/T] [2.4]</p>   <p>RBI-2014-October-21 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-206EMZ 50890-SNA-A02 Civic [2006-2010] CRV [2007-2011] Insulator Engine [RE, M/T]</p>   <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-206R0 50880-SNA-A82 Civic [2006-2010] Insulator Engine [RH, A/T] [1.8]</p>   <p>RBI-2011-November-18 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-206R 50880-SNG-981 Civic [2006-2010] Insulator Engine [RH, A/T] [2.0]</p>   <p>RBI-2011-September-24 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-407R1Z 50880-SWA-A81 CRV [2007-2011] Insulator Engine [RH, A/T] [2.4]</p>   <p>TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO10-407R2Z 50880-SWC-E81 CRV [2007-2011] Insulator Engine [RH, A/T] [2.0]</p>   <p>RBI-2014-May-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO10-206RMZ 50880-SNA-A02 Civic [2006-2010] CRV [2007-2011] Insulator Engine [RH, M/T]</p>   <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| | |
| | |
| | |

HONDA

Revision : 2014-November-01

| | | | |
|---|---|--|--|
| AO10-301FA 50840-SX8-T51 City [2001] Insulator Engine [FR, A/T] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-301F0 50840-SX8-T01 City [2001] Insulator Engine [FR, A/T, M/T] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO09-301EA 50810-SX8-T50 City [2001] Engine Bushing [RE, A/T] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-301EAZ 50810-SX8-T50 City [2001] Insulator Engine [RE, A/T] | RBI-2009-October-19 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-303RA 50821-SAA-013 City [2003-2007] Jazz / FIT [2002-2008] Insulator Engine [RH, A/T] | RBI-2009-September-30 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-303RM 50826-SEL-E01 City [2003-2007] Jazz / FIT [2002-2008] Insulator Engine [RH, M/T] | RBI-2009-October-07 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO09-303FM 50840-SAA-003 City [2003-2007] Jazz / FIT [2002-2008] Engine Bushing [FR, M/T] | RBI-2005-March-19 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-303FMZ 50840-SAA-003 City [2003-2007] Jazz / FIT [2002-2008] Insulator Engine [FR, M/T] | RBI-2008-June-14 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO09-303L0 50805-SAA-982 City [2003-2007] Jazz / FIT [2002-2008] Engine Bushing [LH, A/T, M/T] | ARP Product www.rbi.ae | AO09-303LAZ 50805-SAA-982 City [2003-2007] Jazz / FIT [2002-2008] Insulator Engine [LH, A/T] | RBI-2010-May-22 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-303EM 50810-SEL-T01 City [2003-2007] Jazz / FIT [2002-2008] Insulator Engine [RE, A/T, M/T] | TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-303LMZ 50805-SAA-013 City [2003-2007] Jazz / FIT [2002-2008] Insulator Engine [LH, M/T] | RBI-2010-June-03 RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO10-303EA 50810-SAA-982 City [2003-2007] Jazz / FIT [2002-2008] Insulator Engine [RE, A/T, M/T] | TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO10-303E4Z 50810-SCD-003 Honda Airwave [2005] = GJ1, GJ2 Honda Jazz/FIT [2002-2008] = GD# Honda Mobilio [2001- 2008] = GB1 Insulator Engine [RE] | HFC-2014-November-20 Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| AO09-309EAZ 50890-TF0-981  City [2008-2012] Jazz / FIT [2009-2013] Insulator Engine [RE, A/T]  shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-309EMZ 50890-TF0-911  City [2008-2012] Jazz / FIT [2009-2013] Insulator Engine [RE, M/T]  shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO09-309LZ 50822-TF0-J02  City [2008-2012] Jazz / FIT [2009-2013] Insulator Engine [LH, A/T, M/T]  shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-309L2Z 50822-TG0-T02  City [2008-2012] Jazz / FIT [2009-2013] Insulator Engine [LH, A/T, M/T]  shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO09-309RAZ 50850-TG0-T03  City [2008-2012] Jazz / FIT [2009-2013] Insulator Engine [RH, A/T]  shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO09-309RMZ 50850-TG0-T12  City [2008-2012] Jazz / FIT [2009-2013] Insulator Engine [RH, M/T]  shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | |
| | |
| | |
| | |
| | |
| | |














AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| AO09-HR99EAZ 50810-S2H-991  Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4 Insulator Engine [RE, A/T] | AO09-HR99FLAZ 50842-S2H-990  Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4 Insulator Engine [FR, LH, A/T] |
| AO09-HR99FLMZ 50842-S2H-000  HR-V [1998-2005] = GH1, GH2, GH3, GH4 Insulator Engine [FR, LH, M/T] | |
| AO09-HR99FRMZ 50841-SR0-003  Honda Civic Coupe [1993-1995] = EJ1 Honda Civic CR-X Delsol [1992-1998] = EG1, EG2, EJ4 Honda Ci Insulator Engine [FR, RH, M/T] | |
| AO09-HR99LAZ 50820-S2H-J91  Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4 Insulator Engine [LH, A/T] | AO09-HR99RAZ 50805-S2H-991  Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4 Insulator Engine [RH, A/T] |
| AO09-LG96EZ 50810-S50-980  Honda Logo [1996-2001] = GA3, GA5 Honda Capa [1998-2002] = GA4, GA6 Insulator Engine [RE] | |
| AO09-LG96LZ 50820-S50-J91  Honda Logo [1996-2001] = GA3, GA5 Insulator Engine [LH] | AO09-LG96RZ 50805-S50-010  Honda Logo [1996-2001] = GA3, GA5 Honda Capa [1998-2002] = GA4, GA6 Insulator Engine [RH] |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO13-284F 51920-SB2-004</p> <p>Civic [1984-1991]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> | <p>AO13-288F 51675-SR0-004</p> <p>Civic [1988-2000] S2000 [2000-2009] CR-X [1988-1991] DEL SOL [1993-1997] INTEGRA [1998-2001]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> |
| <p>AO13-292F 51675-S10-004</p> <p>Civic [1992-2000] CRV [1997-2001]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> | <p>AO13-292E 52675-SH3-024</p> <p>Civic [1992-2000] CRV [1997-2001]</p> <p>Shock Absorber Mounting [RE, LH, RH] [With Rubber Set]</p> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | |
|--|--|
| <p>AO13-201FLR 51920-S5H-T02</p> <p>Civic [2001-2002] CRV [2002-2006]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO13-2011FL 51925-S5A-014</p> <p>Civic [2001-2002] CRV [2002-2006]</p> <p>Shock Absorber Mounting [FR, LH]</p>  <p>TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO13-2011FR 51920-S5A-014</p> <p>Civic [2001-2002] CRV [2002-2006]</p> <p>Shock Absorber Mounting [FR, RH]</p>  <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO13-2012FLR 51920-S5A-750</p> <p>Civic [2002-2005] CRV [2002-2006]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>TN-2010-December-01 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO13-2012FL 51925-S5A-751</p> <p>Civic [2002-2005] CRV [2002-2006]</p> <p>Shock Absorber Mounting [FR, LH]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO13-2012FR 51920-S5A-751</p> <p>Civic [2002-2005] CRV [2002-2006]</p> <p>Shock Absorber Mounting [FR, RH]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO13-201F01 51929-S5A-014</p> <p>Honda CIVIC [2002-2006]</p> <p>Shock Absorber Mounting</p>  <p>TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO13-201EZ 52675-S5H-T01</p> <p>Civic [2001-2005] CRV [2002-2006]</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO13-201E 52631-S5A-004</p> <p>Civic [2001-2005]</p> <p>Shock Absorber Mounting Rubber [RE]</p>  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |

HONDA

Revision : 2014-November-01

| | | | |
|--|--|---|---|
| AO13-206F 51920-SNA-013  Civic [2006-2010] Shock Absorber Mounting [FR, LH, RH] | RBI-2013-June-15 RBI Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO13-206F0 51920-SNA-023  Civic [2006-2010] Shock Absorber Mounting [FR, LH, RH] | ASH-2013-July-10 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO13-206F2 51920-SMG-E01 Civic FK [2006-2012] Shock Absorber Mounting [FR, LH, RH] | ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO13-206F3 51920-SVB-A03  Civic [2006-2010] Shock Absorber Mounting [FR, LH, RH] | TN-2013-September-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO13-206F3Z 51920-SVB-A03  Civic [2006-2010] Shock Absorber Mounting + Bearing [SET] [FR, LH, RH] [With Bearing] | TN-2013-September-10 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| AO13-206FB 51726-SNA-013  Honda Civic FD [2006-2012] Shock Absorber Mounting Bearing Only [FR, LH, RH] [With Bearing] | TN-2014-February-10 Tenacity Product, HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| AO13-206E1 52631-SNA-A12 Honda Civic FD [2006-2012] Shock Absorber Mounting Rubber [RE, LH, RH] | ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO13-206E2 52631-SNA-A22 Honda Civic FD [2006-2012] Shock Absorber Mounting Rubber [RE, LH, RH] | ASH-2014-May-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO13-206E3 52691-SNA-A01 Civic [2006-2010] Shock Absorber Mounting Rubber [RE, LH, RH] | ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO13-206E4 52748-SNA-A02 Civic [2006-2010] Shock Absorber Mounting Rubber [RE, LH, RH] | Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO13-206EZ 52631-SNA-A12  Honda Civic FD [2006-2012] Shock Absorber Mounting Rubber [Set] [RE, SET] | TN-2014-May-05 Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| | | | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA


Revision : 2014-November-01

| | |
|--|--|
| <p>AO13-407F0 51920-SWA-A01</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> | <p>AO13-407E0 52675-SWA-A02</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Shock Absorber Mounting [RE, LH, RH]</p> |
| <p>AO13-407FB 51726-STK-A01</p> <p>Honda CR-V [2007] = RE3, RE4</p> <p>Shock Absorber Mounting Bearing Only</p> | <p>AO13-407FZ 51920-SWA-A01</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Shock Absorber Mounting + Bearing [SET] [FR, LH, RH]+ [Brearing]</p> |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|---|--|---|--|
| <p>AO13-088E 52725-SB2-013</p> <p>Accord [1988-1990] Civic [1988-1990]</p> <p>Shock Absorber Mounting Rubber [RE]</p> | <p>RBI-OLD RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   | <p>AO13-088F 51631-SB0-003</p> <p>Accord [1988-1990] Honda [1998-2002] = S84 Civic [1988-1990] CRV [1997-2001]</p> <p>Shock Absorber Mounting Rubber [FR]</p> | <p>RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   |
| <p>AO13-090F 51675-SM4-004</p> <p>Accord [1990-1993] Odyssey [1995-1999]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   | | |
| <p>AO13-090E 52675-SM4-004</p> <p>Accord [1990-1997]</p> <p>Shock Absorber Mounting [RE, LH, RH]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   | | |
| <p>AO13-098F0 51675-S84-A01</p> <p>Accord [1998-2003]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   | | |
| <p>AO13-003F0 51675-SDA-A01</p> <p>Accord [2003-2008]</p> <p>Shock Absorber Mounting [FR]</p> | <p>TN-2014-August-30 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   | | |
| <p>AO13-098E0 52675-S84-A01</p> <p>Accord [1998-2008]</p> <p>Shock Absorber Mounting [RE]</p> | <p>HFC-2014-November-20 HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   | <p>AO13-0980 51631-SV7-004</p> <p>Accord [1998-2003]</p> <p>Shock Absorber Mounting Rubber [FR, RE]</p> | <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   |
| | | | |
| | | | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO13-009F1 51675-TA0-A11</p> <p>Accord [2008-2013] [2.0]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO13-009F2L 51676-TC0-T01</p> <p>Accord [2008-2013] [2.4, 3.5]</p> <p>Shock Absorber Mounting [FR, LH]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO13-009F2R 51675-TC0-T01</p> <p>Accord [2008-2013] [2.4, 3.5]</p> <p>Shock Absorber Mounting [FR, RH]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO13-009E 52675-TA0-A01</p> <p>Accord [2008-2013] [2.0, 2.4, 3.5]</p> <p>Shock Absorber Mounting [RE, LH, RH]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| | |
| <p>AO13-300F0 51920-S0X-A02</p> <p>Odyssey [2000-2004] MDX [2001-2006]</p> <p>Shock Absorber Mounting [FR, LH, RH]</p>  <p>TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO13-ACA01FB 51726-S3V-A01</p> <p>Honda Acura MDX [2001-2006] = YD1 Honda Civic GX [1999] = EN1, EN2 Honda Civic, Civic Ferio [200</p> <p>Shock Absorber Mounting Bearing Only</p>  <p>ARP Product www.rbi.ae</p> | <p>AO13-ACA07FB 51726-SJC-A03</p> <p>Honda Acura MDX [2007] = YD2</p> <p>Shock Absorber Mounting Bearing Only</p>  <p>ARP Product www.rbi.ae</p> |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|--|---|
| AO13-301E 52678-SX8-T01  City [1996-2002] Shock Absorber Mounting [RE, LH, RH] | RBI-OLD RBI Product, Tenacity Product, Ashimori Product  www.rbi.ae www.alafuae.com | AO13-301F 51920-SX8-T01  City [1996-2002] Shock Absorber Mounting [FR, LH, RH] | RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com |
| AO13-303F0 51920-SAA-015  City [2003-2007-2012] Jazz / FIT [2002-2008-2013] Shock Absorber Mounting Rubber [FR, LH, RH] | RBI-2005-October-12 RBI Product, Perfect Product, HFC Product, Ashimori Product  www.rbi.ae www.alafuae.com | | |
| AO13-303F1 51925-SAA-005  City [2003-2007] Jazz / FIT [2002-2008] Shock Absorber Mounting Rubber [FR, LH, RH] | ARD-2014-January-01 ARP Product  www.rbi.ae www.alafuae.com | AO13-303F2 51688-SEL-T01  City [2003-2007] Jazz / FIT [2002-2008] Shock Absorber Mounting [FR, LH, RH] | ARP Product  www.rbi.ae www.alafuae.com |
| AO13-303F3 51688-SCC-004  City [2003-2007] Jazz / FIT [2002-2008] Shock Absorber Mounting Rubber [FR, LH, RH] | TN-2013-September-10 Tenacity Product  www.rbi.ae www.alafuae.com | AO13-303F4 51726-SFA-005  City [2003-2007] Jazz / FIT [2002-2008] Shock Absorber Mounting Bearing Only [FR, LH, RH] | TN-2013-September-10 Tenacity Product  www.rbi.ae www.alafuae.com |
| AO13-303FZ 51688-SCC-004  City [2003-2007] Jazz / FIT [2002-2008] Shock Absorber Mounting + Bearing [SET] [FR, LH, RH] | TN-2013-September-10 Tenacity Product  www.rbi.ae www.alafuae.com | | |
| AO13-304F0 51920-TG0-T01  City [2008-2012] Jazz / FIT [2009-2013] Shock Absorber Mounting Rubber [FR, LH, RH] | HFC-2014-November-20 HFC Product  www.rbi.ae www.alafuae.com | AO13-304F1 51925-TG0-T01  City [2008-2012] Jazz / FIT [2009-2013] Shock Absorber Mounting Rubber [FR, LH, RH] | ARP Product  www.rbi.ae www.alafuae.com |
| AO13-304E 52725-TG0-T01  City [2008-2012] Jazz / FIT [2009-2013] Shock Absorber Mounting Rubber [RE, LH, RH] | RBI-2010-September-07 RBI Product  www.rbi.ae www.alafuae.com | | |
| AO13-STP01FB1 51726-SK3-003 Honda Concerto [1988-1992] = MA1, MA2, MA3 Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4 Honda S-M Shock Absorber Mounting Bearing Only | ARP Product www.rbi.ae | AO13-STP01FB2 51726-S7S-J01 Step WGN [2001-2005] = RF3-RF8 Shock Absorber Mounting Bearing Only | ARP Product www.rbi.ae |



HONDA

Revision : 2014-November-01

| | | | |
|--|--|--|--|
| AO14-098F 51722-S84-A01 Honda Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Honda Avancier [1999-2003] = TA1, TA2, TA3, TA4 Shock Absorber Dust Cover [FR] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-003E 52688-S0A-004 Honda Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Honda Accord [2002-2008] = CL, CN, CM Honda I Shock Absorber Dust Cover [RE] | RBI-2005-April-22 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-003F 51688-SDA-A01 Honda Accord [2002-2008] = CL, CN, CM Honda Accord [2008-2012] = CU2 Honda Accord Tourer [2008-2] | RBI-2009-March-24 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO14-090F 51722-SM4-003 Accord [1990-1993] Shock Absorber Bumper [FR] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-U090F 51722-SM4-003 Accord [1990-1993] MEP-Shock Absorber Bumper [FR] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-090E 52722-SM4-961 Accord [1990-1998-2002] Civic [1992-2000] Odyssey [1995-1999] Shock Absorber Bumper [RE] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-U090E 52722-SM4-961 Accord [1990-1998-2002] Civic [1992-2000] Odyssey [1995-1999] MEP-Shock Absorber Bumper [RE] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-094E 52722-SM4-013 Accord [1990-1998-2002] Civic [1992-2000] Odyssey [1995-1999] Shock Absorber Bumper [RE] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-U094E 52722-SM4-013 Accord [1990-1998-2002] Civic [1992-2000] Odyssey [1995-1999] MEP-Shock Absorber Bumper [RE] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-094F 51722-SV4-004 Accord [1994-1999] Odyssey [1995-1999] Shock Absorber Bumper [FR] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-U094F 51722-SV4-004 Accord [1994-1999] Odyssey [1995-1999] MEP-Shock Absorber Bumper [FR] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-003EI 52722-SDA-A01 Accord [1998-2008] Shock Absorber Bumper [RE] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-U003E 52722-SDA-A01 Accord [1998-2008] MEP-Shock Absorber Bumper [RE] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | |
|---|--|---|
| AO14-201F0 51722-S5A-014  Civic [2001-2005] Shock Absorber Dust Cover [FR] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | |
| AO14-206FR 51402-SNL-T02 Civic [2006-2010] Shock Absorber Dust Cover [FR, RH] [1.8, 2.0, A/T, M/T] | ASH-2013-November-15 Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO14-206FL 51403-SNL-T02 Civic [2006-2010] Shock Absorber Dust Cover [FR, LH] [1.8, 2.0, A/T, M/T] |
| | | |
| AO14-292E 52722-SR3-003 Civic [1992-2000] Shock Absorber Bumper [RE] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO14-U292E 52722-SR3-003 Civic [1992-2000] MEP-Shock Absorber Bumper [RE] |
| AO14-292F 51722-SS0-004 Civic [1992-1996] Accord [2003-2010] PRELUDE Shock Absorber Bumper [FR] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO14-U292F 51722-SS0-004 Civic [1992-1996] Accord [2003-2010] PRELUDE MEP-Shock Absorber Bumper [FR] |
| AO14-296E 52722-SN4-003 Civic [1996-2001] City [1998-2002] Shock Absorber Bumper [RE] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO14-U296E 52722-SN4-003 Civic [1996-2001] City [1998-2002] MEP-Shock Absorber Bumper [RE] |
| AO14-201 52722-S5A-004 Civic [2001-2005] Shock Absorber Bumper [RE] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO14-U2001 52722-S5A-004 Civic [2001-2005] MEP-Shock Absorber Bumper [RE] |
| AO14-206F 51722-SNA-904 Civic [2006-2010] Shock Absorber Bumper [FR] | RBI-2008-November-27 RBI Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO14-U206F 51722-SNA-904 Civic [2006-2010] MEP-Shock Absorber Bumper [FR] |





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|--|
| | |
| | |
| AO14-496E 52722-SS0-003  CRV [1997-2001]  Shock Absorber Bumper [RE] | AO14-U496E 52722-SS0-003  CRV [1997-2001]  MEP-Shock Absorber Bumper [RE] |
| AO14-40F 51722-S10-004  CRV [1997-2001]  Shock Absorber Bumper [FR] | AO14-U40F 51722-S10-004  CRV [1997-2001]  MEP-Shock Absorber Bumper [FR] |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO14-402F 51722-S7A-014</p> <p>Honda Civic [2001-2006] = EU, EP, ES Honda Civic GX [1999] = EN1, EN2 Honda CR-V [2001-2006] = R</p> <p>Shock Absorber Dust Cover [FR]</p>  <p>RBI-2005-March-31 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| <p>AO14-402E 52722-S9A-014</p> <p>CRV [2002-2006]</p> <p>Shock Absorber Bumper [RE]</p>  <p>RBI-2005-September-23 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | <p>AO14-U402 52722-S9A-014</p> <p>CRV [2002-2006]</p> <p>MEP-Shock Absorber Bumper [RE]</p>  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO14-407FR 51402-STK-A02</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Shock Absorber Dust Cover [FR, RH] [2.0]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | <p>AO14-407FL 51403-STK-A01</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Shock Absorber Dust Cover [FR, LH] [2.0]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO14-407F 51722-SWE-T01</p> <p>CRV [2007-2011]</p> <p>Shock Absorber Bumper [FR]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| <p>AO14-407E 52722-SWA-A01</p> <p>CRV [2007-2011]</p> <p>Shock Absorber Bumper [RE]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|---|---|---|--|
| AO14-301F 51722-SX8-T01 City [1996-2002] Shock Absorber Dust Cover [FR] | RBI-2009-March-24 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-303F 51722-SEL-T01 City [2003-2007] Jazz / FIT [2002-2008] Shock Absorber Dust Cover [FR] | RBI-2005-April-27 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-303F00 51722-SAA-E02D Jazz / FIT [2002-2008] Shock Absorber Bumper [FR] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-U303F00 51722-SAA-E02B Jazz / FIT [2002-2008] MEP-Shock Absorber Bumper [FR] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-305F 51686-TG0-T01 City [2008-2012] Jazz / FIT [2009-2013] Shock Absorber Dust Cover [FR] | RBI-2011-March-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO14-304F 51722-TF0-014 City [2008-2012] Jazz / FIT [2009-2013] Shock Absorber Bumper [FR] | RBI-2010-October-27 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO14-U304F 51722-TF0-014 City [2008-2012] Jazz / FIT [2009-2013] MEP-Shock Absorber Bumper [FR] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO14-ACA01F00 51722-S3V-A01 Acura MDX [2001-2006] = YD1 MR-V [2003-2008] Pilot [2002-2008] = YF1 Shock Absorber Dust Cover [FR] | ARP Product www.rbi.ae | | |
| AO14-STP01F00 51722-S7S-J01 Step WGN [2001-2005] = RF3-RF8 Shock Absorber Dust Cover [FR] | ARP Product www.rbi.ae | AO14-STP01F02 51722-S7T-J02 Step WGN [2001-2005] = RF3-RF8 Shock Absorber Dust Cover [FR] | ARP Product www.rbi.ae |
| AO14-STP01E00 52687-SX0-003 Odyssey, Shuttle [1994-1999] = RA1, RA2, RA3, RA4, RA5 S-MX [1996-2002] = RH1, RH2 Step WGN [199 Shock Absorber Dust Cover | ARP Product www.rbi.ae | AO14-STP01E02 52722-SX1-003 Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Accord [2002-2008] = CL, CN, CM Inspire [1995- 1998] MEP-Shock Absorber Bumper [RE] | ARP Product www.rbi.ae |
| | | | |

HONDA

Revision : 2014-November-01

| | | | |
|---|--|---|--|
| AO17-084IL 44326-SB0-300 Accord [1984] Drive Shaft Boot [Inner, LH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-084UL 44324-SB0-310 Accord [1984] Drive Shaft Boot [Outer, LH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO17-084IR 44325-SB0-300 Accord [1984] Drive Shaft Boot [Inner, RH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-084UR 44323-SB0-310 Accord [1984] Drive Shaft Boot [Outer, RH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO17-086IL 44315-SD2-003 Accord [1986-1989] Drive Shaft Boot [Inner, LH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-086UL 44333-SD2-003 Accord [1986-1989] Drive Shaft Boot [Outer, LH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO17-086IR 44315-SB2-980 Accord [1986-1989] Drive Shaft Boot [Inner, RH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-086UR 44333-SB2-980 Accord [1986-1989] Drive Shaft Boot [Outer, RH] |  <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO17-090IZ 44315-SM4-003 Accord [1990] Drive Shaft Boot [Inner] |  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-090UZ 44333-SM4-003 Accord [1990] Drive Shaft Boot [Outer] |  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO17-098IZ 44315-SM1-A000 Accord [1996-1998] Drive Shaft Boot [Inner] |  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-098UZ 44333-S84-A01 Accord [1996-1998] Drive Shaft Boot [Outer] |  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO17-003IZ 44315-SDE-T01 Accord [2003-2008] Drive Shaft Boot [Inner] |  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-003UZ 44333-SDE-T01 Accord [2003-2008] Drive Shaft Boot [Outer] |  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO17-008IZ 44315-SDF-T01 Accord [2008] [3.5] Drive Shaft Boot [Inner] |  <p>RBI-2012-May-31 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO17-008UZ 44333-SDF-T01 Accord [2008] [3.5] Drive Shaft Boot [Outer] |  <p>RBI-2012-May-31 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |




AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|---|--|---|
| AO17-286IZ 44315-SA2-300 Civic [1986-1989] Drive Shaft Boot [Inner] |   RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.rbi.ae | AO17-286UZ 44333-SA2-310 Civic [1986-1989] Drive Shaft Boot [Outer] |   RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae |
| AO17-292IZ 44315-SR3-003 Civic [1992] Drive Shaft Boot [Inner] |   RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae | AO17-292UZ 44333-SR3-013 Civic [1992] Drive Shaft Boot [Outer] |   RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae |
| AO17-296IZ 44315-S04-0030 Civic [1996] Drive Shaft Boot [Inner] |   RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.rbi.ae | AO17-296UZ 44333-S04-0130 Civic [1996] Drive Shaft Boot [Outer] |   RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae |
| AO17-201IZ 44017-S5D-A01 Civic [2001-2005] Drive Shaft Boot [Inner, LH] |   RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae | AO17-201IR 44017-S5D-A11 Civic [2001-2005] Drive Shaft Boot [Inner, RH] |   RBI-2005-August-19 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae |
| AO17-201UZ 44018-S5D-A010 Civic [2001-2005] Drive Shaft Boot [Outer] |   RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.rbi.ae | | |
| AO17-206UZ 44333-SEL-T01 Civic [2006-2010] Drive Shaft Boot [Outer] [L&R] |   RBI-2009-April-07 RBI Product shabbirh@eim.ae www.rbi.ae www.rbi.ae | | |
| | | | |
| | | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|---|--|--|
| AO17-496EI 42315-S10-000 CRV [1997-2001] Drive Shaft Boot [Inner, RE] |   | AO17-496EU 42333-SR7-J21 CRV [1997-2001] Drive Shaft Boot [Outer, RE] |   |
| AO17-496FU 44333-S0A-003 CRV [1997-2001] Drive Shaft Boot [Outer, FR] |   | | |
| AO17-402E 42315-S71-003 CRV [2002-2006] Drive Shaft Boot [Outer] [RE] |   | | |
| AO17-402FI 44315-S0K-J02 CRV [2002-2006] Drive Shaft Boot [Inner, FR] |   | AO17-402FU 44333-SX0-C02 CRV [2002-2006] Drive Shaft Boot [Outer, FR] |   |
| | | | |
| | | | |
| | | | |
| | | | |










AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|---|---|
| AO17-303IZ 44315-SEL-T01 City [2003-2007] Jazz / FIT [2002-2008] Drive Shaft Boot [Inner] |  | AO17-303UZ 44333-S04-N01 City [2003-2007] Jazz / FIT [2002-2008] Drive Shaft Boot [Outer] |  |
| | | AO17-304UZ 44333-TF0-003 City [2008-2012] Jazz / FIT [2009-2013] Drive Shaft Boot [Outer] |  |
| AO17-ACA01IZ 42017-STK-A01 Honda Acura MDX [2001-2006] = YD1 Honda Pilot [2009] = YF4 Drive Shaft Boot [Inner] |  | AO17-STP01UZ 44018-S9A-000 Accord [2002-2008] = CL, CN, CM CR-V [2001-2006] = RD4, RD5, RD6, RD7, RD9 Inspire [2003-2007] = Drive Shaft Boot [Outer] |  |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO18-0869 53534-SE0-A52</p>  <p>Accord [1986-1989]</p> <p>Steering Gear Boot [Power]</p> | <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.alafuae.com</p> |
| <p>AO18-0903 53534-SD4-000</p>  <p>Accord [1990-1994]</p> <p>Steering Gear Boot [Power]</p> | <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.alafuae.com</p> |
| <p>AO18-094L 53534-SV4-003</p>  <p>Accord [1995-1997]</p> <p>Steering Gear Boot [LH]</p> | <p>AO18-094R 53534-SV4-N01</p>  <p>Accord [1995-1997]</p> <p>Steering Gear Boot [RH]</p> |
| <p>AO18-0980 53534-S84-A01</p>  <p>Accord [1998]</p> <p>Steering Gear Boot [LH, RH]</p> | <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.alafuae.com</p> |
| | |
| <p>AO18-0030 53534-SEA-G02</p> <p>Accord [2003-2008]</p> <p>Steering Gear Boot [LH, RH]</p> | <p>ARP Product www.rbi.ae</p> |
| <p>AO18-008Z 53534-TA0-A02</p>  <p>Accord [2008-2013]</p> <p>Steering Gear Boot [LH, RH]</p> | <p>RBI-2012-January-27 RBI Product shabbirh@eim.ae  www.alafuae.com</p> |
| | |

















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA
















Revision : 2014-November-01

| | | | |
|--|---|---|--|
| AO18-2880 53534-SA5-951  Civic [1988-1990] Steering Gear Boot [Power] | RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae  www.alafuae.com | AO18-2925 53534-SR3-N52  Civic [1992-1995] Steering Gear Boot [Power] | RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.alafuae.com |
| AO18-296Z 53534-SR3-N62  Civic [1996] Steering Gear Boot [Power] | RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae  www.alafuae.com | AO18-201S 06537-S5A-H01  Civic [2001-2005] Steering Gear Boot [Small] | RBI-OLD RBI Product shabbirh@eim.ae  www.alafuae.com |
| AO18-206RZ 53534-SNA-A01  Civic [2006-2010] Steering Gear Boot [RH] | RBI-2009-May-13 RBI Product shabbirh@eim.ae  www.alafuae.com | AO18-206LZ 53535-SNA-A01  Civic [2006-2010] Steering Gear Boot [LH] | RBI-2009-May-23 RBI Product shabbirh@eim.ae  www.alafuae.com |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |



HONDA

Revision : 2014-November-01

| | |
|--|---|
| AO18-4020 53536-S9A-003  CRV [2002-2006] Steering Gear Boot  RBI-2005-June-29 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO18-407F00 53534-SMA-003  CR-V [2007] = RE3, RE4 Steering Gear Boot  ARP Product www.rbi.ae | |
| AO18-301L 53537-SH3-J00  City [1996-2002] Steering Gear Boot [LH]  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO18-301LP 53534-ST0-013  City [1996-2002] Steering Gear Boot [LH, Power]  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO18-301R 53537-SH3-000  City [1996-2002] Steering Gear Boot [RH]  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO18-303L 53534-SEL-003  City [2003-2007] Jazz / FIT [2002-2008] Steering Gear Boot [LH]  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO18-303R 53535-SEL-003  City [2003-2007] Jazz / FIT [2002-2008] Steering Gear Boot [RH]  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO18-304L 53534-TF0-003  City [2008-2012] Jazz / FIT [2009-2013] Steering Gear Boot [LH]  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| | |
| | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|--|--|
| AO21-086F 51316-SE0-000  Accord [1986-1989] Stabilizer Shaft Rubber [FR] |  RBI-OLD RBI Product, Ashimori Product www.rbi.ae www.alafuae.com | AO21-086E 52315-SE0-000  Accord [1986-1989] Stabilizer Shaft Rubber [RE] |  RBI-OLD RBI Product www.rbi.ae www.alafuae.com |
| AO21-090F 51306-SM4-010  Accord [1990-1993] Stabilizer Shaft Rubber [FR] |  RBI-OLD RBI Product, Tenacity Product, Ashimori Product www.rbi.ae www.alafuae.com | AO21-090E 52315-SJ4-000  Accord [1990-1993] Stabilizer Shaft Rubber [RE] |  RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product www.rbi.ae www.alafuae.com |
| AO21-094F 51306-SV4-000  Accord [1994-1997] Stabilizer Shaft Rubber [FR] |  RBI-OLD RBI Product, Tenacity Product, HFC Product www.rbi.ae www.alafuae.com | AO21-0941F 51306-SM4-961  Accord [1994-1997] Stabilizer Shaft Rubber [FR] |  TN-2010-December-01 Tenacity Product, Ashimori Product www.rbi.ae www.alafuae.com |
| AO21-094E 52315-SR3-900  Accord [1994-1997] Civic [1992-1995] Stabilizer Shaft Rubber [RE] |  RBI-OLD RBI Product, Tenacity Product www.rbi.ae www.alafuae.com | | |
| AO21-098F 51306-S84-A01  Accord [1998-2002] Stabilizer Shaft Rubber [FR] |  RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product www.rbi.ae www.alafuae.com | AO21-098E 52306-S84-A01  Accord [1998-2002] Stabilizer Shaft Rubber [RE] |  RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product www.rbi.ae www.alafuae.com |
| | | | |
| | | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|--|--|--|
| AO21-003F 51306-SDA-A03 Accord [2003-2008] Stabilizer Shaft Rubber [FR] |  <p>RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO21-003E 52306-SDA-A01 Accord [2003-2008] Stabilizer Shaft Rubber [RE] |  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO21-008F 51306-TA0-A01 Accord [2008] Stabilizer Shaft Rubber [FR] |  <p>RBI-2010-October-27 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO21-008E 52306-TA0-A02 Accord [2008] Stabilizer Shaft Rubber [RE] [2.0, 2.4] |  <p>RBI-2010-October-01 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO21-009FL 51307-TL0-G01 Accord [2008-2013] Stabilizer Shaft Rubber [FR] [LH] |  <p>RBI-2014-July-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO21-009FR 51306-TL0-G01 Accord [2008-2013] Stabilizer Shaft Rubber [FR] [RH] |  <p>RBI-2014-July-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| AO21-009E 52306-TA1-A02 Accord [2008-2013] Stabilizer Shaft Rubber [RE] [3.5] |  <p>RBI-2010-October-27 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | | |
| | | | |
| AO21-PL1E 52315-SS0-010 Prelude Stabilizer Shaft Rubber [RE] |  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | | |
| | | | |
| | | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | |
|--|---|--|
| AO21-282F 51315-SA0-000 Civic [1982-1983] Stabilizer Shaft Rubber [FR] |  Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| | AO21-285F 51315-SB4-000 Civic [1984-1987] Stabilizer Shaft Rubber [FR] |  ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO21-286F 51316-SH3-J00 Civic [1986-1991] Stabilizer Shaft Rubber [FR] |  RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO21-292F 51306-SR3-010 Civic [1992-1995] Stabilizer Shaft Rubber [FR] |  RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |  RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO21-2922F 51306-SR3-J00 Civic [1992-1995] Stabilizer Shaft Rubber [FR] |  TN-2010-December-01 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |  TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO21-296F 51306-S04-003 Civic [1996-2000] Stabilizer Shaft Rubber [FR] |  RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO21-296E 52315-S04-N00 Civic [1996-2000] Stabilizer Shaft Rubber [RE] |  TN-2010-December-01 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |  TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|--|---|---|
| AO21-201F 51306-S5A-003 Civic [2001] Stabilizer Shaft Rubber [FR] | <div><div>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> | | |
| AO21-203F 51306-S5A-A11 Civic [2002] Stabilizer Shaft Rubber [FR] | <div><div>RBI-2008-September-26 RBI Product, Perfect Product, Tenacity Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> | AO21-201E 52306-S5A-003 Civic [2002] Stabilizer Shaft Rubber [RE] | <div><div>RBI-OLD RBI Product, Perfect Product, Ashimori Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> |
| AO21-202F 51306-S5J-003 Civic Sedan Stabilizer Shaft Rubber [FR] | <div><div>RBI-2013-June-15 RBI Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> | AO21-202F0 51306-S5J-801 Civic [2002] Sedan, 5Door Stabilizer Shaft Rubber [FR] | <div><div>RBI-2013-June-19 RBI Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> |
| AO21-202F1 51306-SNJ-P00 Honda Civic [2001-2006] = EU, EP, ES Honda Civic, Civic Ferio [2000-2006] = ES1, ES2, ES3 Stabilizer Shaft Rubber [FR] [5 Doors] | <div><div>RBI-2013-July-19 RBI Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> | | |
| AO21-204F 51306-S5A-801 Civic [2003-2005] Stabilizer Shaft Rubber [FR] | <div><div>RBI-2010-November-03 RBI Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> | AO21-204E 52306-S5A-801 Civic [2003-2005] Stabilizer Shaft Rubber [RE] | <div><div>ARD-2014-January-01 ARP Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> |
| AO21-205F 51306-S5G-801 Civic [2005] [2.0] Stabilizer Shaft Rubber [FR] | <div><div>RBI-2010-November-03 RBI Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> | AO21-205E 52306-S5A-E01 Civic [2003-2005] Stabilizer Shaft Rubber [RE] | <div><div>ARD-2014-January-01 ARP Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> |
| AO21-YH2E00 52306-SCV-000 Element [2003-2005] = YH2 Stabilizer Shaft Rubber [RE] | <div><div>ARP Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> | AO21-YH2F00 51306-SCV-000 Element [2003-2005] = YH2 Stabilizer Shaft Rubber [FR] | <div><div>ARP Product</div><div></div><div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div></div> |
| | | | |









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| AO21-206F 51306-SNA-A02  Civic [2006-2010] Stabilizer Shaft Rubber [FR] | AO21-206E 52306-SNG-J01  Civic [2006-2010] Stabilizer Shaft Rubber [RE] |
| AO21-206FL 51307-SMG-E11  Civic FK [2006-2012] Stabilizer Shaft Rubber [FR] [LH] | AO21-206FR 51306-SMG-E11  Civic FK [2006-2012] Stabilizer Shaft Rubber [FR] [RH] |
| | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| <p>AO21-301F 51306-SX8-T00 City [1996-2002] Stabilizer Shaft Rubber [FR]</p>   <p>RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO21-303F 51306-SEL-T01 City [2003-2007] Jazz / FIT [2002-2008] Stabilizer Shaft Rubber [FR]</p>   <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO21-303E 52315-SEL-000 City [2003-2007] Jazz / FIT [2002-2008] Stabilizer Shaft Rubber [RE]</p>   <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO21-3033F 51306-SAA-J01 City [2006-2008] Stabilizer Shaft Rubber [FR]</p>   <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO21-304F 51306-TM0-003 City [2008-2012] Jazz / FIT [2009-2013] Stabilizer Shaft Rubber [FR]</p>   <p>RBI-2010-September-07 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO21-304E 52315-TM0-T01 City [2008-2012] Jazz / FIT [2009-2013] Stabilizer Shaft Rubber [RE]</p>   <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO21-305F 51306-TF0-003 Honda City [2009-2013] Honda Jazz, Fit [2009-2013] = GE# Stabilizer Shaft Rubber [FR]</p>   <p>RBI-2010-October-01 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO21-40E 52315-S10-023</p>  <p>CRV [1997-2001]</p> <p>Stabilizer Shaft Rubber [RE]</p> | <p>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO21-41E 52315-S10-A01</p>  <p>CRV [1997-2006]</p> <p>Stabilizer Shaft Rubber [RE]</p> | <p>RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AO21-41F 51306-S04-N01</p>  <p>Civic [1996-2000] CRV [1997-2001]</p> <p>Stabilizer Shaft Rubber [FR]</p> |
| <p>AO21-402E 52306-S9A-005</p>  <p>CRV [2002-2006]</p> <p>Stabilizer Shaft Rubber [RE]</p> | <p>RBI-2005-March-05 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AO21-402F 51306-S7B-014</p>  <p>CRV [2002-2006]</p> <p>Stabilizer Shaft Rubber [FR]</p> |
| <p>AO21-407FR 51306-SWW-P51</p>  <p>CRV [2007-2009]</p> <p>Stabilizer Shaft Rubber [FR] [RH]</p> | <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AO21-407FL 51307-SWW-P51</p> <p>CRV [2007-2009]</p> <p>Stabilizer Shaft Rubber [FR] [LH]</p> |
| <p>AO21-407F00 51306-SWA-A01</p>  <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Stabilizer Shaft Rubber [FR]</p> | <p>PFT-2014-May-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AO21-407E00 52306-SWA-A01</p>  <p>CRV [2007-2011]</p> <p>Stabilizer Shaft Rubber [RE]</p> |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO21-OD1F00 51306-SW3-J01</p> <p>Odyssey [1999-2003]</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>TN-2012-August-06 Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO21-OD1E00 52315-S3N-901</p> <p>Odyssey [1999-2003]</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO21-OD2F00 51306-S0X-A01</p> <p>Odyssey [2000-2004]</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO21-OD3F00 51306-S3V-A00</p> <p>Odyssey [2005-2010]</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO21-OD3E01 52306-SFE-901</p> <p>Odyssey, Shuttle [2003-2008] = RB1, RB2</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>ARP Product www.rbi.ae</p> |
| <p>AO21-HR99F00 51306-S2H-003</p> <p>Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO21-HR99F02 51306-S2H-023</p> <p>Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product www.rbi.ae</p> |
| <p>AO21-HR99F03 51306-S2J-951</p> <p>Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Stabilizer Shaft Rubber [FR]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO21-HR99E00 52315-S2H-003</p> <p>Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO21-HR99E02 52315-S2H-013</p> <p>Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Stabilizer Shaft Rubber [RE]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA










Revision : 2014-November-01

| | |
|--|---|
| AO21-ACA01E00 52306-S3V-A00 <small>ARP Product</small> www.rbi.ae Acura MDX [2001-2006] = YD1 MR-V [2003-2008] Pilot [2002-2008] = YF1 Pilot [2009] = YF4 Stabilizer Shaft Rubber [RE] | |
| AO21-ACA07E01 52306-STX-A01 <small>ARP Product</small> www.rbi.ae Acura MDX [2007] = YD2 Stabilizer Shaft Rubber [RE] | AO21-ACA07E02 52306-STX-A11 <small>ARP Product</small> www.rbi.ae Acura MDX [2007] = YD2 Stabilizer Shaft Rubber [RE] |
| AO21-ACA07F00 51306-STX-A12 <small>ARP Product</small> www.rbi.ae Honda Acura MDX [2007] = YD2 Honda Odyssey IV, Shuttle [2008-2011] = RB3, RB4 Stabilizer Shaft Rubber [FR] | AO21-ACA07F01 51306-SZA-A02 <small>ARP Product</small> www.rbi.ae Acura MDX [2007] = YD2 Pilot [2009] = YF4 Stabilizer Shaft Rubber [FR] |
| AO21-STP96F00 51306-S47-003 <small>ARP Product</small>  www.rbi.ae www.alafuae.com S-MX [1996-2002] = RH1, RH2 Step WGN [1996-2001] = RF1, RF2 Stabilizer Shaft Rubber [FR] | AO21-STP01F00 51306-S7S-003 <small>ARP Product</small> www.rbi.ae Step WGN [2001-2005] = RF3-RF8 Stabilizer Shaft Rubber [FR] |
| AO21-STP05F00 51306-SLJ-902 <small>ARP Product</small>  www.rbi.ae www.alafuae.com Step WGN [2005-2009] = RG1, RG2, RG3, RG4 Stabilizer Shaft Rubber [FR] | |
| AO21-STM00E00 52306-S7C-004 <small>Ashimori Product</small> www.rbi.ae Honda Stream [2000-2006] = RN1-RN5 Stabilizer Shaft Rubber [RE] | |
| AO21-ELY04F00 51306-SZ3-G01 <small>ARP Product</small>  www.rbi.ae www.alafuae.com Honda Elysion [2004] = RR1, RR2, RR3, RR4, RR5, RR6 Honda Legend [1996-2004] = KA9 Honda Legend Stabilizer Shaft Rubber [FR] | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|---|---|---|---|
| AO23-086IY 51380-SE0-003 Accord [1986-1989] Strut Bar Rubber [Inner] |  RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO23-086Z 51390-SE0-003 Accord [1986-1989] Strut Bar Rubber Set [Set] |  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO23-086UY 51390-SE0-003 Accord [1986-1989] Strut Bar Rubber [Outer] |  RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO23-090BY 51391-SM4-013 Accord [1990-1998] Strut Bar Rubber [Big] |  RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO23-090Z 51391-SM4-013 Accord [1990-1998] Strut Bar Rubber Set [Set] |  RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO23-090SY 51381-SM4-013 Accord [1990-1998] Strut Bar Rubber [Small] |  RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO23-090Z2 51728-SR3-003 Honda CIVIC, ACCORD [1990-2005] Shock Absorber Mounting |  TN-2014-February-10 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO23-094BY 51391-SX0-013 Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Accord [2002-2008] = CL, CN, CM Ascot [1993-1997] = Strut Bar Arm Bush [FR] |  ARP Product www.rbi.ae | AO23-094SY 51381-SX0-013 Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Ascot [1993-1997] = CE4, CE5 Avancier [1999-2003] = Strut Bar Arm Bush [FR] |  ARP Product www.rbi.ae |
| | | AO23-098B2 51381-S1A-E01 Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Torneo [1997-2002] = CF3, CF4, CF5, CL1, CL3 Strut Bar Arm Bush [FR] |  ARP Product www.rbi.ae |
| AO23-098B3 51391-S1A-E01 Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Torneo [1997-2002] = CF3, CF4, CF5, CL1, CL3 Strut Bar Arm Bush [FR] |  ARP Product www.rbi.ae | | |







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|--|---|---|
| AO23-286Y 51395-SH3-003 Civic [1986-1992] Strut Bar Rubber |   <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | AO23-286Z 51395-SH3-003 Civic [1986-1992] Honda CIVIC, ACCORD [1990-2005] Strut Bar Rubber Set [Set] |   <p>RBI-OLD RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA


Revision : 2014-November-01

AO24-086P0

51458-SB0-000

Accord [1986-1989]

Front Upper Arm Bush Axile [FR]




AO24-086P

51455-SB0-003

Accord [1986-1989]

Front Upper Arm Bush [FR]



AO24-086UCRZ

51459-SE0-000

Accord [1986-1989]

Front Complete Upper Arm [FR, RH] [With Ball Joint & 1 Bush]



AO24-088WB

51810-SE0-003

Accord [1976-1987]

Front Lower Arm Bush [FR, Big]





AL LAMSA AL FIDDIYA TRADING L.L.C.





ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| <p>AO25-088B 52384-SE0-G02</p>  <p>Accord [1986-1987]</p> <p>Rear Suspension Bush [RE, Big]</p> | <p>AO25-088S 52365-SE0-003</p>  <p>Accord [1986-1987]</p> <p>Rear Suspension Bush [RE, Small]</p> |
| <p>AO25-089B 52384-SE0-023</p>  <p>Accord [1987]</p> <p>Rear Suspension Bush [RE, Big]</p> | |
| <p>AO26-086B 50836-689-000</p>  <p>Accord [1987]</p> <p>Front Shock Absorber Bush [Big]</p> | |
| | |
| | |
| | |
| | |
| | |



















HONDA

Revision : 2014-November-01

| | | | |
|--|---|---|--|
| AO24-090P 51450-SM4-023  Accord [1989-2002] Front Upper Arm Bush [FR] | RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  | AO24-090PZ 51450-SM4-023  Accord [1990-1998] = CB1, CB3, CB7, CC, CD, CE Inspire [1992-1998] = CC2, CC3, UA1, UA2, UA3 Ody Front Upper Arm Bush [Bracket] [FR] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-098P 51460-S86-K00  Accord [1989-2002] Front Upper Arm Bush [FR] | RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  | | |
| AO24-090UCRZ 51450-SM4-A03  Accord [1989-1993] Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-090UCLZ 51460-SM4-A03  Accord [1989-1993] Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-094UCRZ 51450-SV4-000  Accord [1994-1998] Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush] | HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-094UCLZ 51460-SV4-000  Accord [1994-1998] Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush] | HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |
| | | | |
| AO24-098UCRZ 51450-S84-A01  Accord [1998-2002] Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush] | HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-098UCLZ 51460-S84-A01  Accord [1998-2002] Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush] | HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |

HONDA

Revision : 2014-November-01

| | | | |
|---|--|---|---|
| AO24-090WB 51810-SM4-004  Accord [1987-2002] Odyssey [1995-1999] Front Lower Arm Bush [FR, Big] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO24-090WS 51393-SM4-013  Accord [1987-1993] Front Lower Arm Bush [FR, Small] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO24-094WS 51393-SL5-013  Accord [1994-2002] = CF3, CF4, CF5, CL1, CL3 Odyssey [1995-1999] Front Lower Arm Bush [FR, Small] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| AO24-090LCRZ 51355-SM4-040  Accord [1990-1993] Front Complete Lower Arm [FR, RH] [With 2 Bush] | Ashimori Product shabbirh@eim.ae  www.alafuae.com | AO24-090LCLZ 51365-SM4-040  Accord [1990-1993] Front Complete Lower Arm [FR, LH] [With 2 Bush] | Ashimori Product shabbirh@eim.ae  www.alafuae.com |
| AO24-094LCRZ 51355-SV4-000  Accord [1994-1998] Front Complete Lower Arm [FR, RH] [With 2 Bush] | Ashimori Product shabbirh@eim.ae  www.alafuae.com | | |
| AO24-098LCRZ 51355-S84-A00  Accord [1998-2002] Front Complete Lower Arm [FR, RH] [With 2 Bush] | HFC Product shabbirh@eim.ae  www.alafuae.com | | |
| AO24-OD99WB 51391-S0X-A02  Honda Odyssey II, Shuttle [1999-2003] = RA6, RA7, RA8, RA9 Front Lower Arm Bush [FR, Big] | PFT-2013-October-10 Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| | | | |









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| <p>AO24-003P0 51460-SDA-A01</p> <p>Accord [2003-2013] Odyssey [2005-2007]</p> <p>Front Upper Arm Bush [FR]</p>   <p>RBI-2008-February-02 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO24-003UCRZ 51450-SDA-A01</p> <p>Accord [2003-2008]</p> <p>Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]</p>  <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO24-003UCLZ 51460-SDA-A01</p> <p>Accord [2003-2008]</p> <p>Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]</p>  <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| <p>AO24-008UCRZ 51510-TA0-A03</p> <p>Accord [2008-2013]</p> <p>Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]</p>  <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO24-008UCLZ 51520-TA0-A03</p> <p>Accord [2008-2013]</p> <p>Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]</p>  <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|---|--|--|---|
| AO24-003WB 51391-SDA-A03  Accord [2003-2008] Front Lower Arm Bush [FR, Big] | RBI-2005-January-27 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-003WS 51393-SDA-A02  Accord [2003-2008] Front Lower Arm Bush [FR, Small] | RBI-2005-February-15 RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-008WB 51391-TA0-A01  Accord [2008-2013] Front Lower Arm Bush [FR, Big] | RBI-2011-April-23 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-008WS 51392-TA0-A01  Accord [2008-2013] Front Lower Arm Bush [FR, Small] | PFT-2012-March-28 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-307WB 51391-SFE-003  Honda Odyssey, Shuttle [2003-2008] = RB1, RB2 Honda Odyssey, Shuttle [2008] = RB3, RB4 Honda Cro Front Lower Arm Bush [FR, Big] | TN-2012-August-06 Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO24-ACA01DEB 50230-S3V-A01  Honda Acura MDX [2001-2006] = YD1 Honda MR-V [2003-2008] Honda Pilot [2009] = YF4 Front Cross Member Arm Bush | ARP Product www.rbi.ae | | |
| AO24-ACA01WB 51391-S3V-A01  Honda Acura MDX [2001-2006] = YD1 Honda Lagreat [1999-2004] = RL1 Honda MR-V [2003- 2008] Honda Front Lower Arm Bush [FR, Big] | PFT-2013-October-10 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-ACA01WS 51392-S3V-A01  Honda Acura MDX [2001-2006] = YD1 Honda Lagreat [1999-2004] = RL1 Honda MR-V [2003- 2008] Honda Front Lower Arm Bush [FR, Small] | PFT-2013-October-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-ACA01WBJ #51350-S3V-A03  Honda Acura MDX [2001-2006] = YD1 Honda MR-V [2003-2008] Honda Pilot [2009] = YF4 Front Lower Arm Ball Joint [FR, LH, RH] | ARP Product www.rbi.ae | | |
| AO24-ACA07WS 51392-STX-A07  Honda Acura MDX [2007] = YD2 Honda Pilot [2009] = YF4 Front Lower Arm Bush [FR, Small] | PFT-2013-March-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO24-ACA07WB 51391-STX-A07  Honda Acura MDX [2007] = YD2 Honda Pilot [2009] = YF4 Front Lower Arm Bush [FR, Big] | PFT-2013-October-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-ACA07WBJ #51350-STX-A07  Honda Acura MDX [2007] = YD2 Honda Pilot [2009] = YF4 Front Lower Arm Ball Joint [FR, LH, RH] | ARP Product www.rbi.ae |

HONDA

Revision : 2014-November-01

| | | | |
|---|--|--|---|
| AO24-003LCRZ 51350-SDA-A03 Accord [2003-2008] Front Complete Lower Arm [FR, RH] [With 3 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-003LCLZ 51360-SDA-A03 Accord [2003-2008] Front Complete Lower Arm [FR, LH] [With 3 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-008L1CRZ 51350-TA0-A00 Accord [2008-2013] Front Complete Lower Arm [FR, RH] [With 3 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-008L1CLZ 51360-TA0-A00 Accord [2008-2013] Front Complete Lower Arm [FR, LH] [With 3 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-007WB 51391-SHJ-A01 Odyssey [2003] Front Lower Arm Bush [FR, Big] | PFT-2014-May-25 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO24-OD07WB 51391-SHJ-A05 Honda Odyssey III, Shuttle [2003-2008] = RB1, RB2 Front Lower Arm Bush [FR, Big] | PFT-2014-November-15 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-OD07WS 51392-SHJ-A05 Odyssey [2007-2011] Honda Odyssey III, Shuttle [2003-2008] = RB1, RB2 Front Lower Arm Bush [FR, Small] | Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |
| | | | |







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| AO25-089E00 52390-SE0-003 ARP Product www.rbi.ae Accord [1986-1989] Rear Suspension Bush [RE] | |
| AO25-090 52393-SM4-004  RBI Product, Perfect Product, Ashmori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com Accord [1990-1997] Rear Upper Arm Bush [RE] | |
| | |
| AO25-094UARZ 52390-SM4-033 HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com Accord [1994-1997] Rear Complete Upper Arm [RE, RH] [With Ball Joint & 1 Bush] | AO25-094UALZ 52400-SM4-033 HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com Accord [1994-1997] Rear Complete Upper Arm [RE, LH] [With Ball Joint & 1 Bush] |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.










ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA










Revision : 2014-November-01

| | |
|---|--|
| <p>AO25-090G 52366-SM4-005</p> <p>Accord [1990-1998]</p> <p>Rear Suspension Bush [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | <p>AO25-090S 52365-SM4-005</p> <p>Accord [1990-2002]</p> <p>Rear Suspension Bush [RE]</p>  <p>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | |
| | |
| | |
| <p>AO25-090SS 52371-SM4-010</p> <p>Accord [1990-1998]</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | <p>AO25-090S3 52371-SL5-000</p> <p>Honda Accord [1994-1998] = CC, CD, CE Honda Ascot [1993-1997] = CE4, CE5 Honda Vigor [1989-1995]</p> <p>Rear Suspension Bush</p>  <p>Perfect Product www.rbi.ae</p> |
| <p>AO25-094B 52371-SM4-010</p> <p>Accord [1994-1998] = CC, CD, CE Inspire [1992-1995] = CC2, CC3 Odyssey / Shuttle [1994-1999] = R</p> <p>Rear Suspension Bush [RE, Big]</p>  <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|---|--|---|---|
| <div>AO25-098S</div> <div>52390-S84-A01</div> <div></div> <div>Accord [1998-2008] = CL, CN, CM</div> <div>Rear Suspension Bush [RE, Small]</div> | <div>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> | | |
| <div>AO25-098UAZ</div> <div>52390-S84-A01</div> <div>Accord [1998-2003]</div> <div>Rear Complete Upper Arm [RE, RH, LH] [With Ball Joint & 1 Bush]</div> | <div>Ashimori Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> | <div>AO25-003UAZ</div> <div>52390-SDA-A01</div> <div>Accord [2003-2008]</div> <div>Rear Complete Upper Arm [RE, RH, LH] [With Ball Joint & 1 Bush]</div> | <div>HFC Product, Ashimori Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> |
| <div>AO25-0980</div> <div>52360-S86-K01</div> <div>Accord [1998-2008] = CF3, CF4, CF5, CL1, CL3, CL, CN, CM</div> <div>Rear Suspension Bush [RE, Small]</div> | <div>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> | <div>AO25-0980B0</div> <div>52350-S1A-E00</div> <div>Accord [1998-2008] = CF3, CF4, CF5, CL1, CL3, CL, CN, CM CRV [2007] = RE3, RE4</div> <div>Rear Suspension Bush [RE, Big]</div> | <div>ARP Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> |
| <div>AO25-098CAZ</div> <div>52360-S84-A01</div> <div>Accord [1998-2003]</div> <div>Rear Complete Suspension Arm [RE, RH, LH] [Link With 2 Bush]</div> | <div>ARP Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> | <div>AO25-003CAZ</div> <div>52360-SDA-A00</div> <div>Accord [2003-2008]</div> <div>Rear Complete Suspension Arm [RE, RH, LH] [Link With 2 Bush]</div> | <div>HFC Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> |
| | | <div>AO25-003LAZ</div> <div>52350-SDA-A00</div> <div>Accord [2003-2008]</div> <div>Rear Complete Suspension Arm [RE, RH, LH] [Link With 2 Bush]</div> | <div>HFC Product shabbirh@eim.ae</div> <div></div> <div>www.rbi.ae www.alafuae.com</div> |
| | | | |
| | | | |
| | | | |

HONDA

Revision : 2014-November-01

| | | |
|--|---|---|
| AO25-098B 52380-S84-A01  Accord [1998-2008] = CL, CN, CM Rear Suspension Bush [RE, Big] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| | | AO25-003LEAZ 52380-SEA-000 ARP Product www.rbi.ae Accord [2003-2008] Rear Complete Leading Arm [RE, LH, RH] [With 1 Bush] |
| AO25-098TARZ 52370-S86-K50 Accord [1998-2002] Rear Complete Trailing Arm [RE, RH] [With 1 Bush] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-098TALZ 52375-S86-K50 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Accord [1998-2002] Rear Complete Trailing Arm [RE, LH] [With 1 Bush] |
| AO25-003TARZ 52370-SEA-E00 Accord [2003-2008] Rear Complete Suspension Arm [RE, RH] [With 1 Bush] | ARP Product www.rbi.ae | AO25-003TALZ 52375-SEA-E00 ARP Product www.rbi.ae Accord [2003-2008] Rear Complete Suspension Arm [RE, LH] [With 1 Bush] |
| AO25-003E5B 52368-S3N-003 Accord [2002-2008] = CL, CN, CM Odyssey / Shuttle [1999-2003] = RA6, RA7, RA8, RA9 Rear Suspension Bush [RE, Big] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO24-003E6B 50260-SEA-E01 Accord [2002-2008] = CL, CN, CM Elysion [2004] = RR1, RR2, RR3, RR4, RR5, RR6 Front Cross Member Arm Bush [RE, Big] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-003E6S 50270-SEA-E01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Accord [2002-2008] = CL, CN, CM Elysion [2004] = RR1, RR2, RR3, RR4, RR5, RR6 Odyssey / Shuttle Front Cross Member Arm Bush [RE, Small] |
| AO25-LE00E0 52365-SP0-003 Legend Acura [1991] = KA7, KA8 Rear Suspension Bush [RE] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| | | |











HONDA

Revision : 2014-November-01

| | |
|--|--|
| AO25-ACA01E1 52367-S0X-003 Acura MDX [2001-2006] = YD1 Lagreat [1999-2004] = RL1 MR-V [2003-2008] Odyssey / Shuttle [2003] Rear Suspension Bush [RE]  PFT-2013-February-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-ACA01E2 52345-S0X-A01 Acura MDX [2001-2006] = YD1 Lagreat [1999-2004] = RL1 MR-V [2003-2008] Odyssey / Shuttle [1999] Rear Suspension Bush [RE]  PFT-2013-March-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-ACA01E3 52371-S3V-A00 Acura MDX [2001-2006] = YD1 MR-V [2003-2008] Rear Suspension Bush  Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO25-ACA07E1B 52345-STX-A01B Acura MDX [2007] = YD2 Pilot [2009] = YF4 Rear Suspension Bush  Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-ACA07E1S 52345-STX-A01S Acura MDX [2007] = YD2 Pilot [2009] = YF4 Rear Suspension Bush  Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-ACA07E1Z 52345-STX-A01 Acura MDX [2007] = YD2 Pilot [2009] = YF4 Rear Complete Arm [RE]  ARP Product www.rbi.ae | |
| AO25-ACA07E2 52350-STX-A00B Acura MDX [2007] = YD2 Pilot [2009] = YF4 Rear Suspension Bush  PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-ACA07E3 52210-STX-A02 Acura MDX [2007] = YD2 Pilot [2009] = YF4 Rear Suspension Bush  PFT-2013-August-20 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-ACA07E4 52371-SHJ-A01 Acura MDX [2007] = YD2 Odyssey, Shuttle [2003-2008] = RB1, RB2 Odyssey, Shuttle [2008] = RB3, RB Rear Suspension Bush [RE]  PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO25-ACA07E5Z 52390-STX-A01 Acura MDX [2007] = YD2 Pilot [2009] = YF4 Rear Complete Arm [RE]  ARP Product www.rbi.ae | |
| | |

HONDA

Revision : 2014-November-01

| | |
|--|---|
| AO25-OD94E01 52350-S9V-A0S Odyssey / Shuttle [1994-2003] = RA1, RA2, RA3, RA4, RA5, RA6, RA7, RA8, RA9 S-MX [1996-2002] = RH1 Rear Suspension Bush  PFT-2013-October-10 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-OD94E02 52390-S7S-003 Odyssey / Shuttle [1994-2003] = RA1, RA2, RA3, RA4, RA5, RA6, RA7, RA8, RA9 S-MX [1996-2002] = RH1 Rear Suspension Bush  PFT-2013-August-20 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-OD94E03 52345-SX0-000 Odyssey / Shuttle [1994-1999] = RA1, RA2, RA3, RA4, RA5 S-MX [1996-2002] = RH1, RH2 Step Wagon [] Rear Suspension Bush  ASH-2013-July-10 Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO25-OD94E04 52384-SM4-000 Odyssey [1994-1998] Rear Suspension Bush [RE]  PFT-2012-March-28 Perfect Product, Ashimori Product www.rbi.ae | |
| AO25-OD94E03Z 52345-SX0-900 Odyssey, Shuttle [1994-1999] = RA1, RA2, RA3, RA4, RA5 S-MX [1996-2002] = RH1, RH2 Step WGN [199] Rear Complete Suspension Arm [RE]  ARP Product www.rbi.ae | AO25-OD94E05Z 52306-SE0-000 Accord [1994-1997] = SV4, Odyssey [1995-1998] Rear Complete Suspension Arm [RE]  Ashimori Product www.rbi.ae |
| AO25-OD03E00 52365-SFE-004 Odyssey / Shuttle [2003-2008] = RB1, RB2 Edix [2004] = BE1, BE2, BE3, BE4 FR-V [2004-2009] = BE5 Rear Suspension Bush  PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |
| AO26-090E 52622-SM4-003 Accord [1990-1998] Rear Shock Absorber Bush [RE]  RBI-OLD RBI Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO26-098E 52622-S84-A01 Accord [1998-2002] Rear Shock Absorber Bush [RE]  RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO26-LE01E 52622-SP0-003 Legend Acura [1991] = KA7, KA8 Accord [2002-2008] = CL, CN, CM Legend [1990-1996] = KA7, KA8 Rear Shock Absorber Bush [RE]  ASH-2012-December-25 HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | |







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO25-003S2 52210-SEA-E03</p> <p>Accord [2002-2008] = CL, CN, CM</p> <p>Rear Suspension Bush [RE, Small]</p> | <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO25-008S 52215-TC0-T00</p> <p>Accord [2008-2013] = CU2</p> <p>Rear Suspension Bush [RE, Small]</p> | <p>RBI-2010-December-24 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AO25-008B 52215-TC0-T00</p> <p>Accord [2008-2013]</p> <p>Rear Suspension Bush [RE, Big]</p> |
| <p>AO25-0080 52215-TC0-T00</p> <p>Accord [2008-2013]</p> <p>Rear Suspension Bush [RE] [Middium]</p> | <p>RBI-2011-February-02 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | |
| <p>AO25-008LARZ 52350-TA0-A00</p> <p>Accord [2008-2013]</p> <p>Rear Complete Lower Arm [RE, LH, RH] [With 1 Bush]</p> | <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>AO25-008LALZ 52355-TA0-J00</p> <p>Accord [2008-2013]</p> <p>Rear Complete Lower Arm [RE, LH] [With 1 Bush]</p> |
| | |
| | |
| | |












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO25-008TB 52370-TA0-A00</p> <p>Accord [2008-2013]</p> <p>Rear Suspension Bush [RE, Big]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO25-008TARZ 52370-TA0-A00</p> <p>Accord [2008-2013]</p> <p>Rear Complete Trailing Arm [RE, RH] [With 1 Bush]</p>  <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO25-008TALZ 52375-TA0-A00</p> <p>Accord [2008-2013]</p> <p>Rear Complete Trailing Arm [RE, LH] [With 1 Bush]</p>  <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO25-0083S 52340-TA0-A00</p> <p>Accord [2008-2013] = CU2</p> <p>Rear Suspension Bush [RE, Small]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO25-0083B 52340-TA0-A00</p> <p>Accord [2008-2013] = CU2</p> <p>Rear Suspension Bush [RE, Big]</p>  <p>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO25-008CARZ 52340-TA0-A00</p> <p>Accord [2008-2013]</p> <p>Rear Complete Suspension Arm [RE, RH] [With 2 Bush]</p>  <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO25-008CALZ 52345-TA0-A00</p> <p>Accord [2008-2013]</p> <p>Rear Complete Suspension Arm [RE, LH] [With 2 Bush]</p>  <p>HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO25-008P 52520-TA0-A02  Accord [2008-2013] Front Upper Arm Bush [RE]</p> | <p>RBI-2011-January-26 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO25-008UARZ 52510-TA0-A02 Accord [2008-2013] Rear Complete Upper Arm [RE, RH] [With Ball Joint & 2 Bush]</p> | <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO26-003E 52622-SDA-A01 Accord [2003-2008] Rear Shock Absorber Bush [RE]</p> | <p>RBI-2005-March-05 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | <p>AO25-008UALZ 52520-TA0-A02 Accord [2008-2013] Rear Complete Upper Arm [RE, LH] [With Ball Joint & 2 Bush]</p> |
| | <p>HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | <p>AO26-003E2 52622-SEA-014 Accord [2003-2008] = CL, CN, CM Rear Shock Absorber Bush [RE]</p> |
| | <p>PFT-2012-December-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO24-284W00 51396-SB2-003</p> <p>Civic [1984-1987] = EW2 Ballade [1983-1987] = AJ, AK</p> <p>Front Lower Arm Bush</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO24-286P 51455-SH3-005</p> <p>Civic [1986-1991]</p> <p>Front Upper Arm Bush [FR]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO24-287P 51455-SH3-0B5</p> <p>Civic [1986-1991]</p> <p>Front Upper Arm Bush [FR]</p>  <p>TENACITY TN-2012-August-06 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO24-288UCRZ 51450-SH3-010</p> <p>Civic [1988-1991]</p> <p>Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO24-288UCLZ 51460-SH3-010</p> <p>Civic [1988-1991]</p> <p>Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO24-286WB 51810-SH3-004</p> <p>Civic [1986-1992]</p> <p>Front Lower Arm Bush [FR, Big]</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO24-286WS 51393-SH3-003</p> <p>Accord [1982-1989] Civic [1986-1991]</p> <p>Front Lower Arm Bush [FR, Small]</p>  <p>RBI-OLD RBI Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| <p>AO24-292P 51455-SR3-004</p>  <p>Civic [1992-1997]</p> <p>Front Upper Arm Bush [FR]</p> | <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO24-292UCRZ 51450-SR3-013</p>  <p>Civic [1992-1994]</p> <p>Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush]</p> | <p>HFC Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>HFC Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO24-292WB 51391-SR3-0040</p>  <p>Civic [1992-1997]</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>RBI-OLD RBI Product, Perfect Product, shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO24-292WBRZ 51395-SR3-N02</p>  <p>Civic [1992-1997]</p> <p>Front Lower Arm Bush [Bracket] [FR, Big, RH]</p> | <p>TN-2010-December-01 Tenacity Product, HFC Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  <p>TN-2010-December-01 Tenacity Product</p> <p>shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|--|---|--|--|
| AO24-296PL 51460-S04-023 Civic [1996-2000] CRV [1997-2001] Front Upper Arm Bush [FR] | <div>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   | | |
| AO24-296UCRZ 51450-S04-023 Civic [1996-2001] Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush] | <div>Ashimori Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   | AO24-296UCLZ 51460-S04-023 Civic [1996-2001] Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush] | <div>ARP Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   |
| AO24-497UCRZ 51450-S10-020 CRV [1997-2001] Front Complete Upper Arm [FR, RH] [With Ball Joint & 2 Bush] | <div>HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   | AO24-497UCLZ 51460-S10-020 CRV [1997-2001] Front Complete Upper Arm [FR, LH] [With Ball Joint & 2 Bush] | <div>HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   |
| AO24-296WB 51391-S04-005 Civic [1996-2000] CRV [1997-2001] Front Lower Arm Bush [FR, Big] | <div>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   | AO24-296WLS 51360-S04-G00S Civic [1996-2000] CRV [1997-2001] Front Lower Arm Bush [FR, Small] | <div>RBI-OLD RBI Product, Perfect Product, Tenacity Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   |
| AO24-296L 51360-S04-G00M Civic [1996-2000] CRV [1997-2001] Front Lower Arm Bush [FR] [Middium] | <div>RBI-OLD RBI Product, Perfect Product, Tenacity Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   | | |
| | | | |
| AO24-497LCRZ 51350-S10-A00 CRV [1997-2001] Front Complete Lower Arm [FR, RH] [With 3 Bush] | <div>HFC Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   | AO24-497LCLZ 51360-S10-A00 CRV [1997-2001] Front Complete Lower Arm [FR, LH] [With 3 Bush] | <div>HFC Product</div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div>   |
| | | | |

HONDA

Revision : 2014-November-01

| | | | |
|--|--|---|---|
| AO25-2880 52395-SH3-004 Civic [1988-2000] CRV [1997-2001] Rear Suspension Bush [RE, Small] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO25-288SX 52393-SR3-004 Honda Civic [1988-2000] = EJ9, EK1, EK3, EK4 Rear Suspension Bush [RE, Big] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO25-292UCRZ 52390-SR0-A00 Civic [1988-2000] CRV [1997-2001] Rear Complete Upper Arm [RE, RH] [With 2 Bush] | HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO25-292UCLZ 52400-SR0-A00 Civic [1988-2000] CRV [1997-2001] Rear Complete Upper Arm [RE, LH] [With 2 Bush] | HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO25-288B 52365-SH3-014 Civic [1988-1995] Rear Suspension Bush [RE, Big] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| AO25-296S 52350-S04-000 Civic [1988-2000] CRV [1997-2001] Rear Suspension Bush [RE, Small] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO25-296L 52350-S04-000 Civic [1996-2000] CRV [1997-2001] Civic CR-X Delsol [1992-1998] = EG1, EG2, EJ4 Civic / Civic Rear Suspension Bush [RE, Big] | RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO25-295E1S 52622-ST3-E01 Civic / Civic Ferio [1995-2001] = EK#, EJ9 Rear Suspension Bush [RE, Small] | ARP Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | AO25-295E1B 52365-SK7-A02 Civic Coupe [1993-1995] = EJ1 Civic CR-X Delsol [1992-1998] = EG1, EG2, EJ4 Civic / Civic CRX [1 Rear Suspension Bush [RE, Big] | HFC Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com |
| AO25-296LCZ 52350-S04-000 Civic [1996-2000] Rear Complete Lower Arm [RE, LH, RH] [With 2 Bush] | HFC Product, Ashimori Product shabbirh@eim.ae  www.rbi.ae www.alafuae.com | | |
| | | | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

ALAF

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

AO25-497SX

52393-SH3-004

Honda CR-V [1997-2001] = RD1, RD2

Rear Suspension Bush [RE, Big]

PFT-2012-June-26
Perfect Product
shabbirh@eim.ae
www.rbi.ae
www.alafuae.com



PERFECT
RUBBER PARTS







AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO25-288S 52343-SK7-003</p>  <p>Civic [1988-2000] CRV [1997-2001]</p> <p>Rear Suspension Bush [RE, Small]</p> | <p>RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | |
| | <p>AO25-296CAZ 52341-S04-000</p> <p>HFC Product, Ashimori Product www.rbi.ae</p> <p>Civic [1996-2000] CRV [1997-2001]</p> <p>Rear Complete Compensator Arm [RE, LH, RH] [With 2 Bush]</p> |
| | |
| | |
| | |
| | |
| | |




















AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| AO25-288BX 52371-SH3-G70  Civic [1988-1996]  Rear Suspension Bush [RE, Big] | AO25-292B 52370-SH3-G70  Civic [1988-1996]  Rear Suspension Bush [RE, Big] |
| AO25-293B 52385-SR3-000  Civic [1988-1996]  Rear Suspension Bush [RE, Big] | AO25-298B 52385-SK7-N02  Civic [1998] Integra [1992]  Rear Suspension Bush [RE, Big] |
| AO25-288TARZ 52370-SH3-G03  Civic [1988-1991]  Rear Complete Trailing Arm [RE, RH] | AO25-288TALZ 52371-SH3-G03  Civic [1988-1991] Rear Complete Trailing Arm [RE, LH] |
| | |
| | |
| | |
| | |
| AO26-286S 50836-634-000  Civic [1986]  Front Shock Absorber Bush [Small] | AO26-292E 52622-SR3-003  Civic [1988-1992] CRV [1997-2001]  Rear Shock Absorber Bush [RE] |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|--|
| <p>AO24-201WB 51391-S5A-024</p> <p>Honda Civic, Civic Ferio [2000-2006] = ES1, ES2, ES3 Honda CR-V [2001-2006] = RD4, RD5, RD6, RD7,</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>AO24-201WS 51392-S5A-004</p> <p>Civic [2001-2005] CRV [2002-2006]</p> <p>Front Lower Arm Bush [FR, Small]</p> |
| <p>AO24-202WB 51391-S9A-003</p> <p>Honda Civic [2001-2006] = EU, EP, ES</p> <p>Front Lower Arm Bush [FR, Big]</p> | |
| <p>AO24-YH2WB 51391-SCV-A01</p> <p>Element [2003-2005] = YH2</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>AO24-YH2WS 51392-SCV-A01</p> <p>Element [2003-2005] = YH2</p> <p>Front Lower Arm Bush [FR, Small]</p> |
| <p>AO24-201LCRZ 51350-S5A-030</p> <p>Civic [2001-2005]</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p> | <p>AO24-201LCLZ 51360-S5A-030</p> <p>Civic [2001-2005]</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p> |
| <p>AO24-402LCRZ 51350-S9A-A01</p> <p>CRV [2002-2006]</p> <p>Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush]</p> | <p>AO24-402LCLZ 51360-S9A-A01</p> <p>CRV [2002-2006]</p> <p>Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush]</p> |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO25-2014 52390-S5H-000</p> <p>Civic [2001-2005] = EU, EP, ES Integra [2001-2006] = DC5</p> <p>Front Upper Arm Bush [RE] [Upper Assy-01]</p>  <p>RBI-2008-March-17 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO25-2014C1ZZ 52390-S5H-000</p> <p>Civic [2001-2005]</p> <p>Rear Complete Suspension Arm [RE] [Upper Assy-01]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO25-2014C2ZZ 52390-S5H-980</p> <p>Civic [2001-2005]</p> <p>Rear Complete Suspension Arm [RE] [Upper Assy-01]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO25-203E 52390-S5H-810</p> <p>Civic [2003]</p> <p>Rear Suspension Bush [RE] [Upper Assy-01]</p>  <p>RBI-2009-August-29 RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO25-2030 52365-S5A-802</p> <p>Civic [2003]</p> <p>Rear Suspension Bush [RE]</p>  <p>RBI-2013-April-27 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO25-203EC1ZZ 52390-S5H-810</p> <p>Civic [2003]</p> <p>Rear Complete Suspension Arm [RE] [Upper Assy-01]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO25-203EC2ZZ 52390-S5H-800</p> <p>Civic [2003]</p> <p>Rear Complete Suspension Arm [RE] [Upper Assy-01]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO25-2012C1ZZ 52390-S7A-000</p> <p>Civic [2001-2005]</p> <p>Rear Complete Suspension Arm [RE] [Upper Assy-01]</p>  <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | |
| <p>AO25-2012C2RZZ 52390-S9A-981</p> <p>CRV [2002-2006]</p> <p>Rear Complete Suspension Arm [RE, RH] [Upper Assy-01]</p>  <p>Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> | <p>AO25-2012C2LZZ 52400-S9A-981</p> <p>CRV [2002-2006]</p> <p>Rear Complete Suspension Arm [RE, RH] [Upper Assy-01]</p>  <p>Ashimori Product www.rbi.ae</p> |
| | |
| | |






AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|--|---|---|
| <div>AO25-2012</div> <div>52395-S5A-004</div> <div></div> <div>Civic [2001-2005] CRV [2002-2006]</div> <div>Rear Suspension Bush [RE] [Upper Knuckle]</div> | <div>RBI-OLD RBI Product, Perfect Product, Ashimori Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> | | |
| <div>AO25-2010</div> <div>52365-S5A-024</div> <div></div> <div>Civic [2001-2005] CRV [2002-2006]</div> <div>Rear Suspension Bush [RE, Small Diameter] [Lower Knuckle]</div> | <div>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> | <div>AO25-2011</div> <div>52366-S5A-024</div> <div></div> <div>Civic [2001-2005] CRV [2002-2006]</div> <div>Rear Suspension Bush [RE, Big Diameter] [Lower Knuckle]</div> | <div>RBI-OLD RBI Product, Perfect Product, HFC Product, Ashimori Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> |
| <div>AO25-2013</div> <div>52364-S5A-004</div> <div></div> <div>Civic [2001-2005] CRV [2002-2006]</div> <div>Rear Suspension Bush [RE, Small] [Trailing Arm]</div> | <div>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> | <div>AO25-2013B</div> <div>52370-S5A-A50</div> <div></div> <div>Civic [2001-2006] = EU, EP, ES CRV [2001-2006] = RD4, RD5, RD6, RD7, RD9</div> <div>Rear Suspension Bush [RE, Big] [Trailing Arm]</div> | <div>ARP Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> |
| | | <div>AO25-2015</div> <div>52371-S5A-030</div> <div></div> <div>Civic [2001-2005] CRV [2002-2006]</div> <div>Rear Suspension Bush [RE, Big] [Trailing Arm]</div> | <div>RBI-2008-October-22 RBI Product, Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> |
| | | | |
| | | | |
| <div>AO25-40211</div> <div>50711-S9A-000</div> <div></div> <div>CRV [2002]</div> <div>Rear Suspension Bush [RE]</div> | <div>RBI-2005-April-22 RBI Product, Perfect Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> | | |
| <div>AO26-201E</div> <div>52622-S5A-004</div> <div></div> <div>Civic [2001-2005]</div> <div>Front Shock Absorber Bush [RE]</div> | <div>RBI-OLD RBI Product, Ashimori Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> | <div>AO26-402E</div> <div>52622-S7A-014</div> <div></div> <div>CRV [2002-2006]</div> <div>Rear Shock Absorber Bush [RE]</div> | <div>RBI-2005-March-19 RBI Product, Ashimori Product</div> <div></div> <div>shabbirh@eim.ae www.rbi.ae www.alafuae.com</div> |



HONDA

Revision : 2014-November-01

| | | | |
|---|--|--|---|
| AO24-206WB 51391-SNA-903  Honda Civic FD [2006-2012] Front Lower Arm Bush [FR, Big] | RBI-2010-March-03 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-206WS 51392-SNA-903  Civic [2006-2010] Front Lower Arm Bush [FR, Small] | RBI-2010-February-16 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-206L1CRZ 51350-SNA-903  Civic [2006-2010] Front Complete Lower Arm [FR, RH] [With 2 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-206L1CLZ 51360-SNA-903  Civic [2006-2010] Front Complete Lower Arm [FR, LH] [With 2 Bush] | HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |
| | | | |
| AO24-206WB2 51395-SMG-E03  Civic FK [2006-2012] Front Lower Arm Bush [FR, Big] | PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-206WS2 50280-SMG-E01  Civic FK [2006-2012] Front Lower Arm Bush [FR, Small] | PFT-2014-November-15 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-206WB2LZ 51396-SMG-E03  Civic FK [2006-2012] Front Lower Arm Bush [Bracket] [FR, LH] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-206WB2RZ 51395-SMG-E03  Civic FK [2006-2012] Front Lower Arm Bush [Bracket] [FR, RH] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |
| | | | |
















HONDA

Revision : 2014-November-01

| | | | |
|---|---|--|---|
| AO25-206B 52400-SNA-900  Civic [2006-2010] Front Upper Arm Bush [RE, Big] [Upper Assy-01] | RBI-2009-February-12 RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae 40.20 www.rbi.ae 136.60 www.alafuae.com | AO25-206S 52400-SNA-900  Civic [2006-2010] Front Upper Arm Bush [RE, Small] [Upper Assy-01] | RBI-2009-March-26 RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-206E1RCZZ 52390-SNA-900  Civic [2006-2010] Rear Complete Upper Arm [RE, RH] [Link With 2 Bush] [Upper Assy-01] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-206E1LCZZ 52400-SNA-900  Civic [2006-2010] Rear Complete Upper Arm [RE, LH] [Link With 2 Bush] [Upper Assy-01] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-206E2B 52370-SNA-904  Civic [2006-2010] Rear Suspension Bush [RE, Big] [Trailing Arm] | TN-2014-June-15 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-206E2S 52370-SNA-A04  Civic [2006-2010] Rear Suspension Bush [RE, Small] [Trailing Arm] | PFT-2013-April-30 Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-206E3B 52210-SNA-A00  Civic [2006-2010] Crossroad [1993-1998] = RT1, RT2, RT3, RT4 Stream [2006] = RN6-RN9 Rear Suspension Bush [RE, Big] [Lower Knuckle] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-206E3S 52210-SNA-A00  Civic [2006-2010] Rear Suspension Bush [RE, Small] [Lower Knuckle] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-206E4 42100-SMG-E05  Civic [2006-2010] Rear Suspension Bush [RE] | PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO26-206E00 52622-SMG-E01  Civic FK [2006] Rear Shock Absorber Bush [RE] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |

HONDA

Revision : 2014-November-01

| | |
|---|---|
| AO24-407WB 51350-SWA-E01  CRV [2007-2011] = RE3, RE4  RBI-2011-May-24, RBI-2011-November-11 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Big] | AO24-407WS 51350-SWA-E01  CRV [2007-2011]  RBI-2011-May-24 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [FR, Small] |
| AO24-407WBJ 51350-SWA-E01  CRV [2007-2011]  Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Ball Joint [FR, LH, RH] | AO24-407WBJ2 51220-STK-A01  Honda CR-V [2007] = RE3, RE4  Tenacity Product www.rbi.ae Front Lower Arm Ball Joint [FR, LH, RH] |
| AO24-407WBRZ 51395-SWA-E01  CRV [2007-2011]  Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [Bracket] [FR, RH] | AO24-407WBLZ 51396-SWA-E01  CRV [2007-2011]  Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Lower Arm Bush [Bracket] [FR, LH] |
| AO24-407L1CRZ 51350-SWA-E01  CRV [2007-2011] [2.0]  HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush] | AO24-407L1CLZ 51360-SWA-E01  CRV [2007-2011] [2.0]  HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush] |
| | |
| | |
| | |
| | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| | <p>AO25-407E1CZZ 52390-SWA-A00</p> <p>CRV [2007-2011]</p> <p>Rear Complete Upper Arm [RE, LH, RH] [Link With 1 Bush] [Upper Assy-01]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO25-407E2S 52370-SWA-J01S</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Rear Suspension Bush [RE, Small] [Trailing Arm]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | <p>AO25-407E2B 52370-SWA-J01B</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Rear Suspension Bush [RE, Small] [Trailing Arm]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO25-407E2S2 52371-SWA-J01S</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Rear Suspension Bush [RE, Small] [Trailing Arm]</p> <p>RBI-2014-October-21 RBI Product www.rbi.ae</p>  | |
| <p>AO25-407E2RCZZ 52370-SWA-A01</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Rear Complete Upper Arm [RE, RH] [Link With 2 Bush] [Trailing Arm]</p> <p>HFC Product www.rbi.ae</p> | <p>AO25-407E2LCZZ 52371-SWA-A01</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Rear Complete Upper Arm [RE, LH] [Link With 2 Bush] [Trailing Arm]</p> <p>HFC Product www.rbi.ae</p> |
| <p>AO25-407E3B 52210-SWA-A0B</p> <p>CRV [2007-2011]</p> <p>Rear Suspension Bush [RE, Big] [Lower Knuckle]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | <p>AO25-407E3S 52210-SWA-A0S</p> <p>CRV [2007-2011]</p> <p>Rear Suspension Bush [RE, Small] [Lower Knuckle]</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO25-407E4S 52215-SWE-T00S</p> <p>Honda CR-V [2007-2012] = RE3, RE4</p> <p>Rear Suspension Bush</p> <p>RBI-2014-September-04 RBI Product www.rbi.ae</p>  | |
| | |
| | |













AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|---|--|--|
| AO24-301WI 51360-SX8-T02 City [1996-2002] = [LI] Front Lower Arm Bush [FR, Big] |  RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-301WU 51360-SX8-T01 Honda City LI [1996-2003] Front Lower Arm Bush [FR, Small] |  RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-301LCRZ 51350-SX8-T01 City [1996-2002] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-301LCLZ 51360-SX8-T01 City [1996-2002] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-302WB 51391-SEL-T01 City [2003-2007] Jazz / FIT [2002-2008] Front Lower Arm Bush [FR, Big] |  RBI-2008-March-04 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-302WS 51392-SEL-T01 City [2003-2007] Jazz / FIT [2002-2008] = GD# Mobilio [2001-2008] = GB1, GB2 Mobilio Spike [20] Front Lower Arm Bush [FR, Small] |  RBI-2007-December-07 RBI Product, Perfect Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO24-302LCRZ 51350-SAE-T01 City [2003-2007] Jazz / FIT [2002-2008] Front Complete Lower Arm [FR, RH] [With Ball Joint & 2 Bush] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO24-302LCLZ 51360-SAE-T01 City [2003-2007] Jazz / FIT [2002-2008] Front Complete Lower Arm [FR, LH] [With Ball Joint & 2 Bush] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |
| | | | |
| | | | |
| | | | |











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| <p>AO24-304WB 51360-TG0-T02</p> <p>City [2008-2012] Jazz / FIT [2009-2013]</p> <p>Front Lower Arm Bush [FR, Big]</p>   | <p>AO24-304WS 51360-TG0-T02</p> <p>City [2008-2012] Jazz / FIT [2009-2013]</p> <p>Front Lower Arm Bush [FR, Small]</p>   |
| <p>AO24-304WBRZ 51350-TG0-T02</p> <p>City [2008-2012] Jazz / FIT [2009-2013]</p> <p>Front Lower Arm Bush [Bracket] [FR, RH]</p>  | <p>AO24-304WBLZ 51360-TG0-T02</p> <p>City [2008-2012] Jazz / FIT [2009-2013]</p> <p>Front Lower Arm Bush [Bracket] [FR, LH]</p>  |
| | |
| | |
| | |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|---|---|--|
| AO25-3010 52370-SX8-T00 City [1996-2002] Rear Suspension Bush [RE] |  RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO25-301S 52350-SX8-T00 City [1996-2002] Rear Suspension Bush [RE] |  RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO25-301SZZ 52360-SX8-T00 City [1996-2002] Rear Complete Suspension Arm [RE] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO25-302E 52384-SAE-T00 City [2003-2007] Jazz / FIT [2002-2008] = GD# Rear Suspension Bush [RE] |  RBI-2009-May-23 RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO26-303E 52622-SAA-005 City [2003-2007] Jazz / FIT [2002-2008] Rear Shock Absorber Bush [RE] |  RBI-2005-March-05 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO25-304E0 52385-TG0-T14 City [2008-2012] Jazz / FIT [2009-2013] Rear Suspension Bush [RE] |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO26-304E5 52622-TG0-T01 City [2008-2012] Jazz / FIT [2009-2013] Front Shock Absorber Bush [RE] |  ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| | | | |
| | | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO24-HR99WB 51391-S2H-013</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>AO24-HR99WS 51392-S2H-013</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Front Lower Arm Bush [FR, Small]</p> |
| <p>AO25-HR99E01 52385-S50-004</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4 Capa [1998-2002] = GA4, GA6 Life [1998-2003] = JB1, JB2</p> <p>Rear Suspension Bush [RE]</p> | |
| <p>AO25-HR99E02 52362-SF4-003</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4 City [1988-1994] = GA1, GA2 Capa [1998-2002] = GA4, GA6</p> <p>Rear Suspension Bush [RE]</p> | <p>AO25-HR99E03 52361-SF4-003</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4 Capa [1998-2002] = GA4, GA6 City [1988-1994] = GA1, GA2</p> <p>Rear Suspension Bush [RE]</p> |
| <p>AO25-HR99E04 52370-S2H-000</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4 Capa [1998-2002] = GA4, GA6 Logo [1996-2001] = GA3, GA5</p> <p>Rear Suspension Bush [RE]</p> | <p>AO25-HR99E05 52361-S2K-004</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4 Life [1998-2003] = JB1, JB2 Life [2003-2008] = JB5, JB6, J</p> <p>Rear Suspension Bush [RE]</p> |
| <p>AO25-HRV04E01 52390-SJF-000</p> <p>FR-V [2004-2009] = BE5 Integra [2001-2006] = DC5 Crossroad [1993-1998] = RT1, RT2, RT3, RT4 Ed</p> <p>Front Upper Arm Bush [RE]</p> | <p>AO25-HRV04E02 52364-SJF-004</p> <p>FR-V [2004-2009] = BE5 Edix [2004] = BE1, BE2, BE3, BE4</p> <p>Rear Suspension Bush [RE]</p> |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|--|
| <p>AO24-STM06WB 51391-SMA-030</p> <p>PFT-2014-March-25 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda Stream [2006] = RN6-RN9</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>AO24-STM06WS 51392-SMA-030</p> <p>PFT-2013-August-20 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda Stream [2006] = RN6-RN9</p> <p>Front Lower Arm Bush [FR, Small]</p> |
| <p>AO24-STM06WBJ #51350-SMA-030</p> <p>ARP Product www.rbi.ae</p> <p>Honda Stream [2006] = RN6-RN9</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p> | |
| <p>AO24-LIF03WB 51391-SFA-013</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda Life [2003-2008] = JB5, JB6, JB7, JB8 Honda Zest [2006] = JE1, JE2</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>AO24-LIF03WS 51392-SFA-013</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda Life [2003-2008] = JB5, JB6, JB7, JB8 Honda Zest [2006] = JE1, JE2</p> <p>Front Lower Arm Bush [FR, Small]</p> |
| | |
| <p>AO24-AIR05WB 51391-SLA-023</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda Airwave [2005-2010] = GJ1, GJ2 Honda Partner [2005-2010] = GJ3, GJ4</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>AO24-AIR05WS 51392-SLA-023</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda Airwave [2005-2010] = GJ1, GJ2 Honda Partner [2005-2010] = GJ3, GJ4</p> <p>Front Lower Arm Bush [FR, Small]</p> |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO24-STP96WBJ #51350-S47-013</p> <p>ARP Product</p> <p>Honda S-MX [1996-2002] = RH1, RH2 Honda Step WGN [1996-2001] = RF1, RF2 Honda Step WGN [2001-200]</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p> | |
| <p>AO24-STP05WB 51391-SLJ-013</p> <p>PFT-2014-January-14 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Step WGN [2005-2009] = RG1, RG2, RG3, RG4</p> <p>Front Lower Arm Bush [FR, Big]</p> | <p>AO24-STP05WS 51392-SLJ-013</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Step WGN [2005-2009] = RG1, RG2, RG3, RG4</p> <p>Front Lower Arm Bush [FR, Small]</p> |
| <p>AO24-STP05WBJ 51350-S2H-013</p> <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda City [2003-2008] Honda City ZX [2004] Honda HR-V [1998-2005] = GH1, GH2, GH3, GH4 Honda</p> <p>Front Lower Arm Ball Joint [FR, LH, RH]</p> | |
| <p>AO25-STP96EBJ #52390-S7S-003</p> <p>ARP Product www.rbi.ae</p> <p>Honda Accord [2002-2008] = CL, CN, CM Honda Accord Tourer [2008] = CW Honda Accord Wagon, Tourer</p> <p>Rear Arm Ball Joint [RE, LH, RH]</p> | |
| <p>AO24-RGE05WS 51392-SJC-A00</p> <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> <p>Honda Ridgeline [2005]</p> <p>Front Lower Arm Bush [FR, Small]</p> | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO26-0031 50361-SDB-A02</p> <p>Accord [2003-2008]</p> <p>Rear Shock Absorber Rubber [RE, FR]</p> | <p>AO26-0032 50371-SDB-A02</p> <p>Accord [2003-2008]</p> <p>Rear Shock Absorber Rubber [RE, RE]</p> |
| <p>AO26-0033 50271-SDA-A01</p> <p>Accord [2003-2008]</p> <p>Rear Shock Absorber Rubber [RE][FR]</p> | <p>AO26-0034 50261-SDA-A02</p> <p>Accord [2003-2008]</p> <p>Rear Shock Absorber Rubber [RE, FR]</p> |
| <p>AO26-40213 50713-SH9-010</p> <p>CRV [2002-2006]</p> <p>Rear Shock Absorber Rubber [RE]</p> | <p>AO26-084 51303-SA5-014</p> <p>Accord Civic</p> <p>Bushing Sway</p> |
| | |
| | |
| | |
| | |
| | |











AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO27-090 90112-SM4-020</p> <p>Accord [1990-1996]</p> <p>Stabilizer Link</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p> | <p>AO27-286 90112-SE0-000</p> <p>Civic [1986-1992]</p> <p>Stabilizer Link</p>   <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product shabbirh@eim.ae www.alafuae.com</p> |
| <p>AO27-300 90112-SX8-000</p> <p>Accord [1988] City</p> <p>Stabilizer Link</p>   <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.alafuae.com</p> | |
| | |
| | |
| | |
| | |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|--|---|--|---|
| AO27-098EL 52325-S84-A01 Accord [1997-2008] = CF3, CF4, CF5 INSPIRE [1998] = UA4, UA5 ACURA TL [2004] Accord Hybrid [20] Link Assy [RE, LH] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-098ER 52320-S84-A01 Accord [1997-2008] = CF3, CF4, CF5 INSPIRE [1998] = UA4, UA5 ACURA TL [2004] Accord Hybrid [20] Link Assy [RE, RH] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-098FL 51321-S84-A01 Accord [1997-2002] = CF3, CF4, CF5 INSPIRE [1998] = UA4, UA5 Link Assy [FR, LH] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-098FR 51320-S84-A01 Accord [1997-2002] = CF3, CF4, CF5 INSPIRE [1998] = UA4, UA5 Link Assy [FR, RH] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-003FL 51321-SDA-A05 Accord [2003-2008] = CL7 Link Assy [FR, LH] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-003FR 51320-SDA-A05 Accord [2003-2008] = CL7 Link Assy [FR, RH] | RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-002FL 51321-SEA-E01 Accord [2002-2008] = CL, CN, CM Link Assy [FR, LH] | RBI-2013-November-14 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-002FR 51320-SEA-E01 Accord [2002-2008] = CL, CN, CM Link Assy [FR, RH] | RBI-2013-July-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-008FL 51325-TA0-A01 Accord [2008-2013] Link Assy [FR, LH] | RBI-2010-May-22 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-008FR 51320-TA0-A01 Accord [2008-2013] Link Assy [FR, RH] | RBI-2010-October-27 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-008EL 52325-TA0-A01 Accord [2008-2013] Link Assy [RE, LH] | RBI-2010-October-01 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-008ER 52320-TA0-A01 Accord [2008-2013] Link Assy [RE, RH] | RBI-2010-October-01 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| | | | |
| | | | |

HONDA

Revision : 2014-November-01

| | | |
|---|---|--|
| <p>AO27-300E 52320-S3N-013</p>  <p>Odyssey [2000-2004]</p> <p>Link Assy [RE, LH, RH]</p> | <p>RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| <p>AO27-OD1F 51320-S0X-A02</p>  <p>Odyssey [2000-2004]</p> <p>Link Assy [FR, LH, RH]</p> | <p>RBI-2013-May-28 RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| <p>AO27-OD2F 51320-SHJ-A02</p>  <p>Odyssey [2005-2010]</p> <p>Link Assy [FR, LH, RH]</p> | <p>RBI-2013-May-28 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| <p>AO27-INS98EL 52325-SFY-J01</p>  <p>Honda Inspire [1998-2003] = UA4, UA5</p> <p>Link Assy [RE, LH]</p> | <p>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | <p>AO27-INS98ER 52320-SFY-J01</p>  <p>Honda Inspire [1998-2003] = UA4, UA5</p> <p>Link Assy [RE, RH]</p> |
| <p>AO27-IN00F 51320-ST7-003</p>  <p>Integra Civic [1992-1997] = EG4, EG6, EG7, EG8, EG9, EH1, EJ3</p> <p>Link Assy [FR, LH, RH]</p> | <p>RBI-2009-December-12 RBI Product, Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| <p>AO27-LE00F 51320-SP0-003</p>  <p>Legend Acura [1991] = KA7, KA8</p> <p>Link Assy [FR, LH, RH]</p> | <p>RBI-2009-December-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  | |
| | | |
| | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|--|
| <p>AO27-296 51320-S04-003</p> <p>Civic [1995-2001] = EK3, EK4 CRV [1995-2001] = RD1, RD2</p> <p>Link Assy [FR, LH, RH]</p> | <p>RBI-OLD RBI Product, Perfect Product, Tenacity Product, HFC Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>   |
| <p>AO27-296EL 52321-S04-003</p> <p>Civic [1995-2000] = EK4</p> <p>Link Assy [RE, LH]</p> | <p>AO27-296ER 52320-S04-003</p> <p>Civic [1995-2000] = EK4</p> <p>Link Assy [RE, RH]</p> |
| <p>AO27-41EL 52321-S10-003</p> <p>CRV [1995-2001] = RD1, RD2</p> <p>Link Assy [RE, LH]</p> | <p>AO27-41ER 52320-S10-003</p> <p>CRV [1995-2001] = RD1, RD2</p> <p>Link Assy [RE, RH]</p> |
| | |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA



















Revision : 2014-November-01

| | |
|---|---|
| <p>AO27-201FL 51321-S5A-003</p> <p>Civic [2001-2005] = RD4, RD5 CRV [2002-2006] = RD4, RD5</p> <p>Link Assy [FR, LH]</p> <p><small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO27-201FR 51320-S5A-003</p> <p>Civic [2001-2005] = RD4, RD5 CRV [2002-2006] = RD4, RD5</p> <p>Link Assy [FR, RH]</p> <p><small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> |
| <p>AO27-201EL 52321-S5A-013</p> <p>Civic [2001-2005] = EU3, ES3</p> <p>Link Assy [RE, LH]</p> <p><small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO27-201ER 52320-S5A-013</p> <p>Civic [2001-2005] = EU3, ES3</p> <p>Link Assy [RE, RH]</p> <p><small>RBI-OLD RBI Product, Perfect Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> |
| <p>AO27-202EL 52321-S5T-J01</p> <p>Civic [2001-2006] = EU, EP, ES</p> <p>Link Assy [RE, LH]</p> <p><small>ARP Product www.rbi.ae</small></p> | <p>AO27-202ER 52320-S5T-J01</p> <p>Civic [2001-2006] = EU, EP, ES</p> <p>Link Assy [RE, RH]</p> <p><small>ARP Product www.rbi.ae</small></p> |
| <p>AO27-402EL 52321-S9A-003</p> <p>CRV [2002-2006] = RD4, RD5</p> <p>Link Assy [RE, LH]</p> <p><small>RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO27-402ER 52320-S9A-003</p> <p>CRV [2002-2006] = RD4, RD5</p> <p>Link Assy [RE, RH]</p> <p><small>RBI-OLD RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> |
| <p>AO27-YH2EL 52321-SCV-A00</p> <p>Element [2003-2005] = YH2</p> <p>Link Assy [RE, LH]</p> <p><small>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO27-YH2ER 52320-SCV-A00</p> <p>Element [2003-2005] = YH2</p> <p>Link Assy [RE, RH]</p> <p><small>Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> |
| | |
| | |
| | |



HONDA

Revision : 2014-November-01

| | | | |
|--|---|--|--|
| AO27-206FL 51321-SNA-A02 Civic [2006-2010] = FD1, FD3 Civic COUPE / SEDAN [2006] = DX, EX, LX Civic Hybird Link Assy [FR, LH] | RBI-2008-July-31 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae   www.alafuae.com | AO27-206FR 51320-SNA-A02 Civic [2006-2010] = FD1, FD3 Civic COUPE / SEDAN [2006] = DX, EX, LX Civic Hybird Link Assy [FR, RH] | RBI-2008-July-31 RBI Product, Tenacity Product, Ashimori Product shabbirh@eim.ae   www.alafuae.com |
| AO27-206EL 52321-SNL-T01 Civic [2006-2010] Link Assy [RE, LH] | RBI-2008-September-13 RBI Product shabbirh@eim.ae   www.alafuae.com | AO27-206ER 52320-SNL-T01 Civic [2006-2010] Link Assy [RE, RH] | RBI-2008-August-27 RBI Product shabbirh@eim.ae   www.alafuae.com |
| AO27-205EL 52321-SNA-A01 Civic [2006-2010] Link Assy [RE, LH] | RBI-2014-April-18 RBI Product, Tenacity Product shabbirh@eim.ae   www.alafuae.com | AO27-205ER 52320-SNA-A01 Civic [2006-2010] Link Assy [RE, RH] | RBI-2014-April-18 RBI Product, Tenacity Product shabbirh@eim.ae   www.alafuae.com |
| AO27-407F0 51320-STK-A01 CRV [2007-2011] Link Assy [FR, LH, RH] | RBI-2011-November-11 RBI Product, Tenacity Product shabbirh@eim.ae   www.alafuae.com | | |
| AO27-407EL 52321-SWA-A01 CRV [2007-2011] Link Assy [RE, LH] | RBI-2011-September-24 RBI Product, Tenacity Product shabbirh@eim.ae   www.alafuae.com | AO27-407ER 52320-SWA-A01 CRV [2007-2011] Link Assy [RE, RH] | RBI-2011-September-24 RBI Product, Tenacity Product shabbirh@eim.ae   www.alafuae.com |
| | | | |
| | | | |
| | | | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|--|
| <p>AO27-301E 52325-SX8-T30</p> <p>City [1996-2002]</p> <p>Link Assy [RE, LH, RH]</p> | <p>RBI-2009-March-07 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p> |
| <p>AO27-303FL 51321-SEL-T01</p> <p>City [2003-2007] = GD6, GD7, GD8, GD9 FIT ARIA [2002-2004] = GD6, GD7, GD8, GD9 FIT [2002-2004]</p> <p>Link Assy [FR, LH]</p> | <p>AO27-303FR 51320-SEL-T01</p> <p>City [2003-2007] = GD6, GD7, GD8, GD9 FIT ARIA [2002-2004] = GD6, GD7, GD8, GD9 FIT [2002-2004]</p> <p>Link Assy [FR, RH]</p> |
| <p>AO27-205FL 51321-SAE-T01</p> <p>City [2006-2008] Jazz / FIT [2005-2008]</p> <p>Link Assy [FR, LH]</p> | <p>AO27-205FR 51320-SAE-T01</p> <p>City [2006-2008] Jazz / FIT [2005-2008]</p> <p>Link Assy [FR, RH] [2 Heads]</p> |
| <p>AO27-304F 51320-TG0-T01</p> <p>City [2008-2012] Jazz / FIT [2009-2013]</p> <p>Link Assy [FR, LH, RH]</p> | |
| | |
| | |
| | |
| | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|---|---|
| AO27-HR99FL 51321-S2H-003 HR-V [1998-2005] = GH1, GH2, GH3, GH4 Link Assy [FR, LH] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-HR99FR 51320-S2H-003 HR-V [1998-2005] = GH1, GH2, GH3, GH4 Link Assy [FR, RH] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-HR99EL 52321-S2H-003 HR-V [1998-2005] = GH1, GH2, GH3, GH4 Link Assy [RE, LH] | TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-HR99ER 52320-S2H-003 HR-V [1998-2005] = GH1, GH2, GH3, GH4 Link Assy [RE, RH] | TN-2014-February-10 Tenacity Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-ACA01EL 52325-S3V-013 Acura MDX [2001-2006] = YD1 MR-V [2003-2008] Pilot [2002-2008] = YF1 Pilot [2009] = YF4 Link Assy [RE, LH] | ARP Product www.rbi.ae | AO27-ACA01ER 52320-S3V-013 Acura MDX [2001-2006] = YD1 MR-V [2003-2008] Pilot [2002-2008] = YF1 Pilot [2009] = YF4 Link Assy [RE, RH] | ARP Product www.rbi.ae |
| AO27-ACA07EL 52325-STX-A01 Acura MDX [2007] = YD2 Pilot [2009] = YF4 Link Assy [RE, LH] | ARP Product www.rbi.ae | AO27-ACA07ER 52320-STX-A01 Acura MDX [2007] = YD2 Pilot [2009] = YF4 Link Assy [RE, RH] | ARP Product www.rbi.ae |
| AO27-AIR05FL 51321-SLA-003 Honda Airwave [2005] = GJ1, GJ2 Honda Partner [2005] = GJ3, GJ4 Link Assy | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO27-AIR05FR 51320-SLA-003 Honda Airwave [2005] = GJ1, GJ2 Honda Partner [2005] = GJ3, GJ4 Link Assy [FR, RH] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO27-STP96F00 51311-S47-000 S-MX [1996-2002] = RH1, RH2 Step WGN [1996- 2001] = RF1, RF2 Link Assy [FR] | ARP Product www.rbi.ae | AO27-STP01F00 51320-S7S-003 Step WGN [2001-2005] = RF3-RF8 Hyundai Elantra [2006] = HD Hyundai I30 [2007] KIA Ceed [2006] Link Assy [FR] | ARP Product www.rbi.ae |
| | | | |
| | | | |












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|---|---|
| <p>AO29-496G 40520-S10-003</p>  <p>Honda CR-V [1997-2001] = RD1, RD2</p> <p>Center Bearing</p> | <p>RBI-2009-June-12 RBI Product, Perfect Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO29-402T 40100-S9A-J01</p>  <p>Honda CR-V [2001-2006] = RD4, RD5, RD6, RD7, RD9 Honda Edix [2004] = BE1, BE2, BE3, BE4</p> <p>Center Bearing</p> | <p>RBI-2009-June-12 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO29-407G01 40100-SXS-A01</p>  <p>Honda CR-V [2007] = RE3, RE4</p> <p>Center Bearing</p> | <p>PFT-2013-August-20 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| <p>AO29-292G01 40520-SR7-J01</p> <p>Civic, Civic Ferio [1991-1995] = EG#, EH1, EJ3 Civic, Civic Ferio [1995-2001] = EK#, EJ9 Domani</p> <p>Center Bearing</p> | <p>ARP Product www.rbi.ae</p> |
| <p>AO29-HR99G01 40100-S2H-003</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4</p> <p>Center Bearing</p> | <p>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</p>  |
| | |
| | |
| | |



AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | |
|--|---|
| <p>AO41-401E 50721-SH9-901</p> <p>CRV [1996-2001]</p> <p>Rear Differential Mounting [RE]</p> <p><small>PFT-2014-August-31 Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO41-401F00 50716-SR7-J00</p> <p><small>ARP Product</small></p> <p>Civic, Civic Ferio [1995-2001] = EK#, EJ9 CR-V [1997-2001] = RD1, RD2 Domani [1997-2000] = MB3,</p> <p>Front Differential Mounting</p> <p><small>www.rbi.ae</small></p> |
| <p>AO41-402E 50721-S5C-003</p> <p>CRV [2002-2006]</p> <p>Rear Differential Mounting [RE]</p> <p><small>RBI-2010-July-19 RBI Product, HFC Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | <p>AO41-402F00 50716-S9A-000</p> <p><small>HFC Product</small></p> <p>CR-V [2001-2006] = RD4, RD5, RD6, RD7, RD9</p> <p>Front Differential Mounting</p> <p><small>www.rbi.ae</small></p> |
| <p>AO41-HR99E1 50711-S2H-000</p> <p>HR-V [1998-2005] = GH1, GH2, GH3, GH4 Capa [1998-2002] = GA4, GA6 Logo [1996-2001] = GA3, GA5</p> <p>Rear Differential Mounting [RE]</p> <p><small>ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small></p> | |
| <p>AO41-ACA01E00 50712-S3V-A01</p> <p>Honda Acura MDX [2001-2006] = YD1 Honda MR-V [2003-2008] Honda Pilot [2002-2008] = YF1</p> <p>Rear Differential Bushing [RE]</p> <p><small>ARP Product www.rbi.ae</small></p> | <p>AO41-ACA01E02 50721-S3V-A01</p> <p><small>ARP Product</small></p> <p>Honda Acura MDX [2001-2006] = YD1 Honda MR-V [2003-2008] Honda Pilot [2002-2008] = YF1</p> <p>Rear Differential Bushing [RE]</p> <p><small>www.rbi.ae</small></p> |
| <p>AO41-ACA01E03 50728-S3V-A01</p> <p>Honda Acura MDX [2001-2006] = YD1 Honda MR-V [2003-2008] Honda Pilot [2002-2008] = YF1</p> <p>Rear Differential Bushing [RE]</p> <p><small>ARP Product www.rbi.ae</small></p> | |
| <p>AO41-STP05E00 50711-SAB-000</p> <p>Honda Airwave [2005] = GJ1, GJ2 Honda Jazz, Fit [2002-2008] = GD# Honda Mobilio [2001-2008] = GB</p> <p>Rear Differential Mounting</p> <p><small>ARP Product www.rbi.ae</small></p> | |
| | |
| | |









AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|---|--|--|
| AO31-29200 18215-671-000  Civic [1992-2000] Exhaust Pipe Support | <small>RBI-OLD RBI Product, Perfect Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>  | AO31-206E00 18215-SNA-A31  Civic [2006] Exhaust Pipe Support Rubber | <small>ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>  |
| AO31-098F 18215-S84-A11  Accord [1998-2002] Exhaust Pipe Support [FR] | <small>TN-2011-March-21 Tenacity Product shabbirh@eim.ae www.rbi.ae www.alafuae.com</small>  | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |












AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|---|---|--|
| AO38-088L 53436-SE0-950  Accord [1988] Grommet Steering Rack [LH] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | AO38-088R 53435-SE0-950  Accord [1988] Grommet Steering Rack [RH] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com |
| AO38-090Z 53436-SM4-000  Accord [1990-1993] Grommet Steering Rack | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | AO38-094Z 53436-SV4-000  Accord [1994-1998] [SET] Grommet Steering Rack | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com |
| AO38-098L 53436-S84-A01  Accord [1998] Grommet Steering Rack [LH] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | AO38-098R 53685-S84-A01  Accord [1998-2002] Grommet Steering Rack Bush [RH] | RBI-OLD RBI Product, Perfect Product, Ashimori Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com |
| AO38-098B1 53685-S0A-003 Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Accord [2002-2008] = CL, CN, CM Torneo [1997-2002] Grommet Steering Rack Bush | ARP Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | AO38-098B2 53685-S0A-J00 Accord [1998-2002] = CF3, CF4, CF5, CL1, CL3 Accord [2002-2008] = CL, CN, CM Torneo [1997-2002] Grommet Steering Rack Bush | ARP Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com |
| AO38-OD99E 53685-S0X-A01  Odyssey / Shuttle [1999-2008] = RA6, RA7, RA8, RA9, RB1, RB2 Lagreat [1999-2004] = RL1 Grommet Steering Rack Bush | ARP Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | | |
| AO38-003R 53685-S3N-013  Accord [2002-2008] = CL, CN, CM Inspire [2003-2007] = UC1 Odyssey / Shuttle [1999-2003] = RA6, R Grommet Steering Rack Bush [RH] | ARP Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | | |
| AO38-008L 53436-TA0-A01  Accord [2008] Grommet Steering Rack [LH] | RBI-2010-August-18 RBI Product shabbirh@eim.ae www.rbi.ae  www.alafuae.com | | |
| | | | |








AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|---|---|--|---|
| AO38-286Z 53436-SH3-000  Civic [1986-1991] Grommet Steering Rack | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  | AO38-288PZ 53436-SH3-950  Civic [1988-1992] Grommet Steering Rack [Power] | RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  |
| AO38-296PZ 53436-S04-J51  Civic [1996] Grommet Steering Rack [Power] | RBI-OLD RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  | | |
| | | AO38-201R00 53010-S5S-000  Civic [2001-2006] = EU, EP, ES Grommet Steering Rack Bush | ARP Product www.rbi.ae |
| AO38-206L 53436-SNB-J01  Civic [2006-2010] Grommet Steering Rack [LH] | RBI-2008-September-02 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  | AO38-206R 53685-SMG-E01  Civic [2006-2010] Grommet Steering Rack Bush [RH] | RBI-2008-December-12 RBI Product, Tenacity Product shabbirh@eim.ae 27.50 www.rbi.ae 29.20 www.alafuae.com  |
| AO38-206L0 53436-SNA-A01  Civic [2006-2010] [HPS] Grommet Steering Rack [LH] | RBI-2009-December-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  | | |
| AO38-401Z 53436-S10-010  CRV [1996-2001] Grommet Steering Rack [Set] | RBI-2005-May-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  | AO38-402Z 53436-S9A-000  CRV [2002-2006] Grommet Steering Rack [Set] | RBI-2005-May-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  |
| | | AO38-402S 53685-S5A-000  CRV [2002-2006] Grommet Steering Rack [Small] | ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com  |
| | | | |





AL LAMSA AL FIDDIYA TRADING L.L.C.

P.O.Box 35703 Dubai , U.A.E., TEL: +9714-2249141 , FAX: +9714-2249142, MOB:+971-50-6453924

E-mail : shabbirh@eim.ae , Web Site : <http://www.rbi.ae> <http://www.alafuae.com>

HONDA

Revision : 2014-November-01

| | | | |
|--|--|--|--|
| AO38-301PZ 53436-SX8-T50 City [1996-2002] Grommet Steering Rack [Power] |  RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO38-301Z 53436-SX8-T00 City [1996-2002] [POWER, SET] Grommet Steering Rack [Power] |  RBI-OLD RBI Product, Ashimori Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO38-303L 53436-SEL-003 City [2003-2007] Jazz / FIT [2002-2008] Grommet Steering Rack [LH] |  RBI-2005-April-08 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO38-303R 53685-SCC-003 City [2003-2007] Jazz / FIT [2002-2008] Grommet Steering Rack Bush [RH] |  RBI-2005-August-19 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO38-303B 53010-SEY-000 City [2003-2007] Jazz / FIT [2002-2008] Grommet Steering Rack Bush |  ARD-2014-January-01 ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |
| AO26-304L 53685-TF0-003 City [2008-2012] Jazz / FIT [2009-2013] Grommet Steering Rack Bush [LH] |  RBI-2011-January-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | AO26-3040 53684-TF0-003 City [2008-2012] Jazz / FIT [2009-2013] Grommet Steering Rack Bush [RH] |  RBI-2011-January-12 RBI Product shabbirh@eim.ae www.rbi.ae www.alafuae.com |
| AO26-304R 53686-TF0-003 City [2008-2012] Jazz / FIT [2009-2013] Grommet Steering Rack Bush |  ARP Product shabbirh@eim.ae www.rbi.ae www.alafuae.com | | |

